

Card No.: G/n-1

Ward (Part): G north-V

CS No.: F.P 1360

Plot Area: 1941.48 sq.m.

B U Area: 3214.00 sq.m.

Date: February, 2005

Record by: Gauri J, Uma P


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Seth

Ref.: G.M. Jain Hostel



1.0	Denomination					
1.1	Name of Premises	Seth G.M. Jain Hos	stel			
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 th century	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Off Jagannath Bhat	ankar Marg			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Taramati Sureshbhai Parekh				
3.2	Past	Chinubhai Manibhai Patel, Rameshbhai Manibhai Patel, Jainbhai Manibhai Patel, Gautambhai Manibhai Patel				hai
3.3	Status	Trust				
4.0	Use					
4.1	Present	Hostel				
4.2	Past	Hostel				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Located on western side of Elphinstone station below Elphinstone bridge.			one	
5.2	Architectural Description	Neo-classical style structure with sloping roof and high gables with human figures as the Pinnacles. The entrance has a short porch with a balcony above, topped by a pediment supported by decorative stone columns with floral capitals. Long and short work at the corner of the building.				ch
5.3	Intrinsic		remaining buildings of the Colonial perio		el area which has	Neo-
5.4	Value Classification	A(arc), B(des), B(u	u)	Recom	mended Grade	IIΒ
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Balck Basalt stone	plinth in coursed as	hlar ma	sonry	
7.2	Walls	Stone walls in cours	sed ashlar masonry			
7.3	Floor	Wooden joist flooring	ng			
7.4	Stairs	Access denied				
7.5	Openings	Rectangular openir	igs with wooden frai	mes an	d glazed shutter	
7.6	Roofing	Sloping roof with M	angalore tiles and w	vooden	trusses	

7.7	Articulation	The entrance has a short porch with a balcony above topped by a pediment supported by decorative stone columns with floral capitals. Long and short work at the corner of the building.				
7.8	Finishes	Coursed ashlar masor	nry externally			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value			
7.10	Compound / Fence / Gate	High stone compound	wall in random rubble	masonry		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Central open space				
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, good natural lighting				
8.2	Ventilation	Natural and artificial, g	good natural ventilation			
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not provided				
8.7	Other (HVAC / BMS / Security Systems)	Not provided				
9.0	Condition					
9.1	Plinth	Good (No settlement or cracks observed)				
9.2	Walls	Good (No dampness or cracks observed)				
9.3	Floor	Good (No sagging observed)				
9.4	Stairs	Access denied				
9.5	Openings	Good (Wooden memb	pers in good condition)			
9.6	Roofing	Good (No leakage obs	served)			
9.7	Articulation & Finishes	Good (Well maintaine	d)			
9.8	Services	Good (Drainage pipes	need no replacement)			
9.9	Outbuildings	Fair				
9.10	Overall condition	Fair	Maintenance level	Good		
10.0	Transformation					
10.1	Form	No transformation				
10.2	Structure	No transformation				
10.3	Articulation & Finishes	No transformation				
11.0	DP Remarks / Perceived Threats	North boundary touch Development Plan. (D	es the Special Industria P.P.)	al Zone on proposed		
12.0	Additional Notes / References /	Documents: C.S. shee	ets, D.P. Sheets, Eiche	r City Maps - Mumbai		

Seth G.M. Jain Hostel



View from Elphinstone railway station



Rectangular double height windows



Decorative roof gable



Roof profile of the hostel



Seth G.M. Jain Hostel

Right side elevation and Left side elevation not seen due to proximity of adjoining buildings



Card No.: G/n-2

Ward (Part): G north-V

CS No.: 1419

Plot Area: 778.43 sq.m

B U Area: 727.26 sq.m

Date: February, 2005

Record by: Gauri J, Tanvi O


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\

Ref.: Green Villa



1.0	Denomination					
1.1	Name of Premises	Green Villa				
1.2	Earlier Name	Not applicable				
1.3	Built in	Mid 20 th century	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Bhawani Shankar I	Marg			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Bai Adul Natal				
3.2	Past	Governor of Bombay, Narayan Waman Tare, Jagannath Waman Tare, Govind Sahadeo				
3.3	Status	Tenanted				
4.0	Use	•				
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Located on Bhawani Shankar Marg which has a series of similar houses near Dadar station.				lar
5.2	Architectural Description	Vernacular style house which stands prominently on the road due to its decorative carved, red coloured wooden brackets supporting the roof. It also has a high plinth which is in coursed ashlar masonry contrasting with the plastered walls above. The external wooden staircase leading to the first floor is also one of the characteristics of such modest houses.				
5.3	Intrinsic	This is one of the formal Marg which belong community.				kar
5.4	Value Classification	A(arc), A(cul)		Recom	nmended Grade	III
6.0	Topography			•		<u> </u>
6.1	Floors	G + 1				
7.0	Construction	•				
7.1	Plinth	160 cms high Stone	e plinth in coursed	ashlar n	nasonry	
7.2	Walls	Load bearing brick	walls			
7.3	Floor	Wooden joist floorii	ng			
7.4	Stairs	Wooden stairs with	decorative railing	and bal	uster	

11.0		Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			
	DP Remarks / Perceived Threats	None			
10.3	Articulation & Finishes	No transformation			
10.2	Structure	No transformation			
10.1	Form	Grills and hoardings added later.			
10.0	Transformation				
9.10	Overall condition	Good Maintenance level Good			
9.9	Outbuildings	Good			
9.8	Services	Good (No leakage observed)			
9.7	Articulation & Finishes	Good (Well maintained)			
9.6	Roofing	Good (No leakage observed)			
9.5	Openings	Good (Wooden members in good condition)			
9.4	Stairs	Good (Sagging of a few wooden treads seen)			
9.3	Floor	Good (No sagging observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.1	Plinth	Good (No settlement or cracks observed)			
9.0	Condition	1			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
8.6	Fire precaution	Not provided			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.4	Water Supply	MCGM			
8.3	Electricity	BEST			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.1	Lighting	Natural and artificial, good natural lighting			
8.0	Services & Utilities				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space and marginal side open spaces			
7.10	Compound / Fence / Gate	Not provided			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.8	Finishes	brackets supporting the chajjas. The plinth has coursed ashlar masonry and the brackets are recently painted in bright red oil paint. Externally sand faced finish plaster and internally cement plastered			
7.7	Articulation	wooden trusses The façade shows minimal articulation with decorative wooden			
7.6	Openings Roofing	Segmental arched opening double window having wooden frames and glazed shutters Sloping roof with Mangalore tiles and decorative eaves with			

Green Villa



View from Bhawani Shankar Marg



Oil painted carved wooden brackets



Decorative cast iron railing



Decorative eaves



Card No.: G/n-3

Ward (Part): G north-V

CS No.: 1430

Plot Area: 290.97 sq.m.

B U Area: 300.00 sq.m.

Date: February, 2005

Record by: Gauri J, Swapnil B


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\P'Alex

Ref.: D'Souza Bungalow



Penomination Itame of Premises Itarlier Name Italian I	P'Alex D'Souza Bur Not applicable 1881 Bhawani Shankar M Not applicable Government of Born B.C. Vaity, Rusi Pho Gandhy Tenanted	Extension Date (i		1977				
carlier Name suilt in access Main subsidiary Dwnership Pattern Present Past	Not applicable 1881 Bhawani Shankar M Not applicable Government of Bom B.C. Vaity, Rusi Phe Gandhy	Extension Date (i		1977				
Access Main Subsidiary Dwnership Pattern Present Past	Bhawani Shankar M Not applicable Government of Bom B.C. Vaity, Rusi Phe Gandhy	Marg		1977				
Access Main Subsidiary Dwnership Pattern Present Past	Bhawani Shankar M Not applicable Government of Born B.C. Vaity, Rusi Phe Gandhy	Marg		1977				
Main Subsidiary Dwnership Pattern Present Past Status	Government of Bom B.C. Vaity, Rusi Phe Gandhy	nbay	nv. Kersi					
Subsidiary Dwnership Pattern Present Past Status	Government of Bom B.C. Vaity, Rusi Phe Gandhy	nbay	nv. Kersi					
Ownership Pattern Present Past Status	Government of Bom B.C. Vaity, Rusi Phe Gandhy		nv. Kersi					
resent rast status	B.C. Vaity, Rusi Pho Gandhy		nv. Kersi					
rast status	B.C. Vaity, Rusi Pho Gandhy		ıv. Kersi					
itatus Use	Gandhy	erozshah Gamadh	ıv. Kersi					
lse	Tenanted		,	B.C. Vaity, Rusi Pherozshah Gamadhy, Kersi Gamadhy, Homy Gandhy				
resent	Residential, Commercial							
ast	Residential, Commercial							
Isage	Regular residential, commercial use							
Significance & Value Classification								
ownscape (Natural / Manmade)	Located off Bhawani Shankar Marg and maintains the skyline of the internal road.				of the			
rchitectural Description	One of the more elaborate houses that exist on the road in Vernacular style. It has a wooden external staircase which forms a feature of the structure due to its bold triangular form comprising of the two flights converging in to one landing. The entrance porch and the balcony above are supported by slender wooden columns. The wooden handrails, railings, trellis work and wooden louvres add an exquisite quality to the house. The lowrise sloping roof covers the entire structure only punctured by the balcony roof. Uniform sized window openings topped with segmental arched nitches are in two parts, panelled shutters in the lower part and and glazed shutters on							
ntrinsic					ker			
alue Classification	A(arc), A(cul)		Recom	mended Grade	Ш			
opography			ul.					
loors								
Construction		90 cms high stone plinth						
	90 cms high stone p	olinth	90 cms high stone plinth Load bearing brick walls					
'a	pography pors	the balcony above a wooden handrails, rexquisite quality to tentire structure only window openings to parts, panelled shut the upper part. This is one of the ference Road which belongs community. Alue Classification A(arc), A(cul) Apography G+1	the balcony above aresupported by sl wooden handrails, railings, trellis work exquisite quality to the house. The low entire structure only punctured by the window openings topped with segment parts, panelled shutters in the lower parts, panelled shutters in the lower parts, panelled shutters in the lower parts and which belongs to the Catholic of community. This is one of the few remaining bung Road which belongs to the Catholic of community. A(arc), A(cul) A(arc), A(cul) Appography Ons G+1	the balcony above aresupported by slender wooden handrails, railings, trellis work and wo exquisite quality to the house. The lowrise slopentire structure only punctured by the balcony window openings topped with segmental archiparts, panelled shutters in the lower part and a the upper part. This is one of the few remaining bungalows or Road which belongs to the Catholic or East In community. A(arc), A(cul) Recompography Ors G+1	the balcony above aresupported by slender wooden columns. wooden handrails, railings, trellis work and wooden louvres ad exquisite quality to the house. The lowrise sloping roof covers entire structure only punctured by the balcony roof. Uniform six window openings topped with segmental arched nitches are in parts, panelled shutters in the lower part and and glazed shutter the upper part. This is one of the few remaining bungalows on Bhawani Shanl Road which belongs to the Catholic or East Indian Christian community. A(arc), A(cul) Recommended Grade pography Figure 1 Recommended Grade postruction			

9.6 9.7 9.8 9.9 9.10 10.0 10.1 10.2 10.3 11.0	Walls Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings Overall condition Transformation Form Structure Articulation & Finishes DP Remarks / Perceived Threats	Good (No dampness or cracks observed) Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition) Good (No leakage observed) Good Good (Drainage pipes need no replacement) Good Good Maintenance level Good No transformation No transformation Plot in Residential Zone on proposed Development Plan. (D.P.)			
9.7 9.8 9.9 9.10 10.0 10.1	Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings Overall condition Transformation Form Structure	Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition) Good (No leakage observed) Good Good (Drainage pipes need no replacement) Good Good Maintenance level Good No transformation No transformation			
9.7 9.8 9.9 9.10 10.0	Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings Overall condition Transformation Form	Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition) Good (No leakage observed) Good Good (Drainage pipes need no replacement) Good Good Maintenance level Good No transformation			
9.7 9.8 9.9 9.10 10.0	Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings Overall condition Transformation	Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition) Good (No leakage observed) Good Good (Drainage pipes need no replacement) Good Good Maintenance level Good			
9.7 9.8 9.9 9.10	Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings Overall condition	Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition) Good (No leakage observed) Good Good (Drainage pipes need no replacement) Good			
9.7 9.8 9.9	Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings	Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition) Good (No leakage observed) Good Good (Drainage pipes need no replacement) Good			
9.7 9.8	Floor Stairs Openings Roofing Articulation & Finishes Services	Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition) Good (No leakage observed) Good Good (Drainage pipes need no replacement)			
9.7	Floor Stairs Openings Roofing Articulation & Finishes	Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition) Good (No leakage observed) Good			
	Floor Stairs Openings Roofing	Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition) Good (No leakage observed)			
9.6	Floor Stairs Openings	Good (No sagging observed) Good (Wooden members in good condition) Good (Wooden members in good condition)			
	Floor Stairs	Good (No sagging observed) Good (Wooden members in good condition)			
9.5	Floor	Good (No sagging observed)			
9.4					
9.3	Walls	Good (No dampness or cracks observed)			
9.2					
9.1	Plinth	Good (No settlement or cracks observed)			
9.0	Condition				
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
8.6	Fire precaution	Not provided			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.4	Water Supply	MCGM			
8.3	Electricity	BEST STATE OF THE			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.1	Lighting	Natural and artificial, good natural lighting			
8.0	Services & Utilities				
7.10	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not provided			
7.10	Compound / Fence / Gate	Not provided			
7.8 7.9	Interiors (Movable & Immovable)	Internally and externally cement plastered and painted Interiors, not of heritage value			
7.7	Finishes	wooden eaves fascia. The façade shows minimal articulation.			
7.6	Roofing Articulation	Sloping roof with Mangalore tile with wooden plain eaves and wooden trusses The wooden staircase has simple balusters. The roof has plain			
7.5	Openings	Segmental arched simple windows with wooden frames and glaz double shutters			
7.4	Stairs	Wooden straight flight stairs with wooden balusters			
7.3	Floor	Wooden joist flooring with brick bat coba			

P'Alex D'Souza Bungalow



View from an internal lane off Bhawani Shankar Marg



External straight flight staircase



Projecting balcony with simple balusters



View of the front façade



Trellis work for balcony



Card No.: G/n-4

Ward (Part): G north-V

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Gauri J, Arti S

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\30,
Ref.: Tom's Cottage



1.0	Denomination						
1.1	Name of Premises	30, Tom's Cottage					
1.2	Earlier Name	Not applicable					
1.3	Built in	1932	Extension Date (if	f any)	Not applicable		
2.0	Access						
2.1	Main	Bhawani Shankar N	Marg				
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	Not available					
3.2	Past	Not available					
3.3	Status	Ownership	Ownership				
4.0	Use						
4.1	Present	Residential					
4.2	Past	Residential					
4.3	Usage	Regular residential use					
5.0	Significance & Value Classification						
5.1	Townscape (Natural / Manmade)	Located on a small plot on Bhawani Shankar Marg near Dadar station.				r	
5.2	Architectural Description	Low rise vernacular style structure with entrance porch, sloping roof with Mangalore tile having decorative wooden eaves board. Its distinct feature is the sloping roof in two levels extending to the central length of the house punctured by the porch. The entire plot is elevated by 90 cms. Above the footpath level which helps to attain a right architectural scale to the house.					
5.3	Intrinsic	One of the few rem road.	aining houses in th	nis typolo	ogy existing on the	his	
5.4	Value Classification	A(arc), F		Recom	mended Grade	III	
6.0	Topography						
6.1	Floors	G + 1					
7.0	Construction						
7.1	Plinth	Approx. 160 cms h	igh plastered stone	plinth			
7.2	Walls	Load bearing brick	walls				
7.3	Floor	Wooden joist flooring	ng				
7.4	Stairs	Access denied					
7.5	Openings	Rectangular openir	ng with wooden fran	mes and	glazed shutters	3	

12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai			
11.0	DP Remarks / Perceived Threats	None			
10.3	Articulation & Finishes	No transformation			
10.2	Structure	No transformation			
10.1	Form	No transformation			
10.0	Transformation				
9.10	Overall condition	Good Maintenance level Good			
9.9	Outbuildings	Good			
9.8	Services	Good (No leakage observed)			
9.7	Articulation & Finishes	Good (Well maintained)			
9.6	Roofing	Good (No leakage observed and Mangalore tiles need no replacement)			
9.5	Openings	Good (Wooden members in good condition)			
9.4	Stairs	Access denied			
9.3	Floor	Good			
9.2	Walls	Good (No dampness or cracks observed)			
9.1	Plinth	Good (No settlement or cracks observed)			
9.0	Condition	1			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
8.6	Fire precaution	Not provided			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.4	Water Supply	MCGM			
8.3	Electricity	BEST			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.1	Lighting	Natural and artificial, good natural lighting			
8.0	Services & Utilities				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal open foreground with Shahbad tiles			
7.10	Compound / Fence / Gate	Plastered brick compound wall			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.8	Finishes	Internally and externally plastered and painted			
7.7	Articulation	The structure has minimal ornamentation on the façade. But it has decoratively carved eaves fascia. The entrance porch has wooden carved pinnacle above.			
7.6	Roofing	Sloping roof with Mangalore tiles, decorative eaves on ground fl porch and plain eaves on the top floor.			

30, Tom's Cottage



Front elevation



Detail of eaves



Roof detail of the entrance porch



Card No.: G/n-5

Ward (Part): G north-V

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Gauri J, Tanvi O

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Nazreth House



1.0	Denomination						
1.1	Name of Premises	Nazreth House					
1.2	Earlier Name	Not applicable					
1.3	Built in	Mid 20 th century	Extension Date (i	f any)	Not applicable		
2.0	Access						
2.1	Main	Bhawani Shankar	Marg				
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	Not available					
3.2	Past	Not available					
3.3	Status	Tenanted	Tenanted				
4.0	Use						
4.1	Present	Residential					
4.2	Past	Residential					
4.3	Usage	Regular residential use					
5.0	Significance & Value Classification						
5.1	Townscape (Natural / Manmade)	Located off Bhawani Shankar Marg and maintains the skyline of the internal road.				of the	
5.2	Architectural Description	character given by eaves board is cor an elegant and a la staircase. Unlike the stretch of a weather which is supported.	Vernacular style bungalow creates interest due to its sprawling character given by a large low rise roof enhanced by a decorative eaves board is commonly seen in the bungalows of this road. It has an elegant and a large balcony on the first floor and a wooden staircase. Unlike the other bungalows on this road, it shows a long stretch of a weather shade above the large entrance verandah which is supported by slender wooden columns and is approached by a wide flight of steps which is its unique feature.				
5.3	Intrinsic	One of the few ren	naining houses in th	nis typol	logy existing on th	nis	
5.4	Value Classification	A(arc), B(des)		Recon	nmended Grade	Ш	
6.0	Topography						
6.1	Floors	G + 1					
7.0	Construction	·					
7.1	Plinth	Stone plinth in cou	ırsed ashlar masonı	ry			
7.2	Walls	Load bearing brick	walls				
7.3	Floor	Wooden joist floor	ings				
	I						

7.5	Openings	Rectangular wooden frame shutters and a weather shade in stained glass			
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses			
7.7	Articulation	Simple wooden balustrades and decorative wooden eaves board. The weather shade covering the entire balcony along its length is in stainrd glass. Not much articulation is seen on the façade			
7.8	Finishes	Internally and externally plastered and painted			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Not provided			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Large front open space with landscaping done and marginal side open spaces			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, fair natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Fair (No dampness or cracks observed)			
9.3	Floor	Fair (No sagging observed)			
9.4	Stairs	Fair (Wooden members need maintenance)			
9.5	Openings	Fair (Wooden members in good condition)			
9.6	Roofing	Good (To be checked for leakage if any)			
9.7	Articulation & Finishes	Fair (Needs maintenance)			
9.8	Services	Fair (Drainage pipes need maintenance)			
9.9	Outbuildings	Fair			
9.10	Overall condition	Fair Maintenance level Fair			
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai			

Nazreth House



View from Bhawani Shanker Road



Prominent eaves fascia



View onstructed due to tree plantation



Balcony having simple wooden balusters




Wooden trellis work



Decrative wooden eaves fascia

Right side elevation not seen due to proximity of adjoining buildings



Card No.: G/n-6

Ward (Part): G north-IV

CS No.: F.P. No. 309

Plot Area: 260.03 sq.m.

B U Area: 351.004 sq.m.

Date: February, 2005


Record by: Gauri J, Arti S

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Ref.: Goregaonkar Premises



1.0	Denomination						
1.1	Name of Premises	Goregaonkar Prem	nises				
1.2	Earlier Name	Not applicable					
1.3	Built in	Mid 20 th century	Extension Date (i	f any)	Not applicable		
2.0	Access						
2.1	Main	S. K. Bole Marg					
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	Not available	Not available				
3.2	Past	Not available	Not available				
3.3	Status	Tenanted					
4.0	Use						
4.1	Present	Residential					
4.2	Past	Residential					
4.3	Usage	Regular residential use					
5.0	Significance & Value Classification						
5.1	Townscape (Natural / Manmade)	Located on a plot on S.K Bole Marg near Dadar station.					
5.2	Architectural Description	school. The long st the premises. Thes intervals. The pren and the other structures storeyed structures	A Vernacular settlement at Dadar is located near Antonio D'silva school. The long stretch of wooden balconies is a distinct feature of the premises. These balconies are supported by wooden posts at intervals. The premises include two buildings which form a chawl and the other structures in the premises are two small ground storeyed structures. The railings for the G + 2 structures are decorative wooden balusters.				
5.3	Intrinsic	This Maharashtriar area.	n settlement gives g	glimpses	of chawls in Da	dar	
5.4	Value Classification	A(arc), G(grp)		Recom	mended Grade	III	
6.0	Topography						
6.1	Floors	G + 2					
7.0	Construction						
7.1	Plinth	60 cms high Kurla	Basalt stone plinth				
7.2	Walls	Brick masonry wall	s				
7.3	Floor	Wooden joist floor	with brick bat coba				
7.4	Stairs	Straight flight wood	den decorative railir	ng balus	ter		
	<u> </u>						

12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai				
11.0	DP Remarks / Perceived Threats	None				
10.3	Articulation & Finishes	No transformation				
10.2	Structure	No transformation				
10.1	Form	No transformation				
10.0	Transformation					
9.10	Overall condition	Fair Maintenance level Fair				
9.9	Outbuildings	Fair				
9.8	Services	Fair (Drainage pipes need maintenance)				
9.7	Articulation & Finishes	Fair (Needs maintanance)				
9.6	Roofing	Fair (Leakage observed at a few places)				
9.5	Openings	Fair (Wooden members in good condition)				
9.4	Stairs	Fair (Wooden members in good condition)				
9.3	Floor	Fair (Sagging observed at a few places)				
9.2	Walls	Fair (Needs plastering and painting)				
9.1	Plinth	Fair (No settlement of the plinth observed but the cracks are seen at a few places)				
9.0	Condition					
8.7	Other (HVAC / BMS / Security Systems)	Not provided				
8.6	Fire precaution	Not provided				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.4	Water Supply	MCGM				
8.3	Electricity	BEST				
8.2	Ventilation	Natural and artificial, good natural ventilation				
8.1	Lighting	Natural and artificial, good natural lighting				
8.0	Services & Utilities	<u> </u>				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space, marginal side open space				
7.10	Compound / Fence / Gate	Plastered brick wall				
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value				
7.8	Finishes	Internally and externally cement plastered and painted				
7.7	Articulation	Cornice band is seen at second floor level. The long balconies are interrupted by simple wooden post. These balconies have decorative wooden balusters.				
7.6	Roofing	Slopingroof with Mangalore tiles, plain eaves, wooden trusses, wooden purlin supported by decorative brackets.				

Goregaonkar Premises



View of one of the buildings of the premises



Plain façade of the structure facing S.K Bole road



G + 1 structure with lean to roof on the ground floor



View from interiors of the premises



View of the out buildings



Wooden dog legged propped with bamboos







Avenue created by the two buildings of the premises



Long stretch of balconies used as common corridors



Card No.: G/n-7

Ward (Part): G north-IV

CS No.: F.P. 10

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Gauri J, Arti S

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ **Ref.:** Narayan Smriti



1.0	Denomination					
1.1	Name of Premises	Narayan Smriti				
1.2	Earlier Name	Not applicable				
1.3	Built in	Mid 20 th century	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Chhabildas Road				
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential, Commercial				
4.2	Past	Residential, Commercial				
4.3	Usage	Regular residential,	commercial use			
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	An imposing structuadjoining Dadar sta		usy com	mercial street	
5.2	Architectural Description	G + 2 sprawling struprojecting bays on a pediments at the to Mangalore tiled slow wooden railings. The projecting bays.	the façade that are p. Large balconies ping and character	finished are covi ized by a	I with elaborate ered with extend a long row of ve	rtical
5.3	Intrinsic	A sprawling structu Dadar.	re stands out in a c	commerc	cially busy area	of
5.4	Value Classification	A(arc), F, E		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Black basalt stone	plinth in coursed as	shlar ma	sonry	
7.2	Walls	Bricks masonry walls				
7.3	Floor	RCC floor slab				
7.4	Stairs	Wooden dog legger railing balusters	d stairs with decora	ative woo	oden newel pos	t,
7.5	Openings	Rectangular openir	ng with wooden frai	med glaz	zed shutters	

7.6	Roofing	Sloping roof with Mangalore tiles and teak wood trusses		
7.7	Articulation	The structure has pediments on the top of every bay. This bay projects alternatively on the front façade. The pediments also bear decorative floral motifs on their tympanum.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not provided		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	Good		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement seen but needs maintenance)		
9.2	Walls	Fair (To be maintained to avoid leakage during rains)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Sagging observed in wooden treads)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Needs maintenance)		
9.7	Articulation & Finishes	Fair (Needs maintenance)		
9.8	Services	Fair (Drainage pipes need to be replaced)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Hoardings, grills and sliding windows added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumba		
	1			

Narayan Smriti



View of the façade from Chabildas Road



Triangular parapet wall




Triangular parapet wall with decorative motifs



Balconies with simple balusters



Façade obstructed by street furniture (lamp post)



7.7	Articulation	It has minimal articulation on the façade. The balconies project at first, second and third floor levels. The railings used for the balconies have C.I railings.			
7.8	Finishes	Internally and external	lly cement plastered an	nd painted	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value		
7.10	Compound / Fence / Gate	Not provided			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front and marginal side open space			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, g	good natural lighting		
8.2	Ventilation	Natural and artificial, g	good natural ventilation		
8.3	Electricity	BEST	BEST		
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Fair (No settlement or cracks observed but needs maintanance)			
9.2	Walls	Fair (Needs plastering	and painting)		
9.3	Floor	Fair (No sagging obse	rved)		
9.4	Stairs	Fair (Wooden membe	rs in good condition)		
9.5	Openings	Good (Wooden memb	ers in good condition)		
9.6	Roofing	Fair (Leakage observe	ed at a few places)		
9.7	Articulation & Finishes	Fair (Well maintained)			
9.8	Services	Fair (Drainage pipes n	need no replacement)		
9.9	Outbuildings	Fair			
9.10	Overall condition	Fair	Maintenance level	Fair	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Under Urban Renewel Scheme on proposed Development Plan. (D.P.)			
12.0	Additional Notes / References / Documents Available	Documents: C.S. shee	ets, D.P. Sheets, Eiche	r City Maps - Mumbai	

Sitaram Prasad Building



View from Ranade Road Extension




Floral motifs with fluted pilasters for the entrance porch



Projecting balcony



Decorative cast iron railing



Card No.: G/n-9

Ward (Part): G north-IV

CS No.: 1691

Plot Area: 429.21 sq.m.

B U Area: 1454.56 sq.m.

Date: February, 2005

Record by: Gauri J, Anup S


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Park

Ref.: View



1.0	Denomination						
1.1	Name of Premises	Park View					
1.2	Earlier Name	Not applicable					
1.3	Built in	1936	Extension Date (if any)	Not applicable			
2.0	Access			·			
2.1	Main	H. Parelkar Marg					
2.2	Subsidiary	H. M Patil Marg					
3.0	Ownership Pattern						
3.1	Present	Ramakant					
3.2	Past	Jankibai Ramchandra Karnik, Chandrakant Ramchandra Karnik, James Richard Karnik					
3.3	Status	Tenanted					
4.0	Use	•					
4.1	Present	Residential					
4.2	Past	Residential					
4.3	Usage	Regular residential	use				
5.0	Significance & Value Classification						
5.1	Townscape (Natural / Manmade)	Typical corner build	ding plot at Shivaji Park.				
5.2	Architectural Description	due to its corner poterrace level. The care supported by re	It in Indo-Saracenic style osition and the decorative chajjas of the other balcorectangular RCC columns onies have a decorative of	parapet wall at the nies are prominent with a decorative	e : and		
5.3	Intrinsic		cated in an area belongino Shivaji park neighbourhoo		l		
5.4	Value Classification	A(arc), I(sce)	Reco	mmended Grade	III		
6.0	Topography						
6.1	Floors	G + 3					
7.0	Construction						
7.1	Plinth	Plastered masonry plinth					
7.2	Walls	Brick walls					
7.3	Floor	RCC floor slab					
7.4	Stairs	Openwell RCC staircase					
7.5	Openings	Rectangular Openi	ng with wooden frames a	nd glazed shutter.			
7.6	Roofing	Flat roof terrace					
۸ طویادو	r Associates Architects	25		\\/l	G north		

7.7	Articulation	It has features like concrete jali for parapet walls of the balconies. These balconies are supported by columns with decorative capitals. The terrace parapet wall has a decorative profile. Internally and externally cement plastered and painted			
7.8	Finishes	Internally and external	lly cement plastered ar	nd painted	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value		
7.10	Compound / Fence / Gate	Plastered brick wall			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front and side open space			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, g	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness of	or cracks observed)		
9.3	Floor	Good (No sagging obs	served)		
9.4	Stairs	Fair (Wooden membe	rs in good condition)		
9.5	Openings	Good (Wooden memb	pers in good condition)		
9.6	Roofing	Good (No leakage obs	served)		
9.7	Articulation & Finishes	Fair (Needs maintana	nce)		
9.8	Services	Fair (Well maintained)			
9.9	Outbuildings	Fair			
9.10	Overall condition	Fair	Maintenance level	Fair	
10.0	Transformation				
10.1	Form	Hoardings, sliding win	dows and grills added	later.	
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			

Park View



View from Senapati Bapat Chowk





Projecting balconies supported by reinforced columns



Prominent projecting chajjas on every floor



Decorative parapet wall



Common	Ref.	No.:
--------	------	------

Card No.: G/n-10

Ward (Part): G north-IV

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Gauri J, Arti S

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Shastri Building



1.0	Denomination					
1.1	Name of Premises	Shastri Building				
1.2	Earlier Name	Not applicable				
1.3	Built in	Mid 20 th century	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	P. L. Kale Guruji Ma	arg			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Burma shell oil storage and distribution company, India				
3.2	Past	Dr. N.A. Purandare				
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Commercial				
4.2	Past	Commercial				
4.3	Usage	Regular commercia	l use			
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	This corner building is one of the major				which
5.2	Architectural Description	Structure located in Maharashtrian local Corinthian columns around. The buildin decorative motifs.	lity. It looks interest . The window open	ting due iings ha	to the coupled ve simple architr	
5.3	Intrinsic	One of the few build Maharashtrian com		which I	has a majority of	f
5.4	Value Classification	A(arc), A(his)		Recom	mended Grade	Ш
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Plastered stone plin	nth			
7.2	Walls	Brick walls				
7.3	Floor	Wooden joist flooring with brick bat coba				
7.4	Stairs	Openwell wooden staircase with wooden balustrade				
7.5	Openings	Segmental arched of wooden frames and		angular	windows with	
7.6	Roofing	Flat roof terrace				

7.7	Articulation	It has features like coupled Corinthian columns. The window openings have simple architraves around. The façade also has decorative motifs.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front and marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Fair (Needs plastering and painting)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Good (Wooden members in good condition)		
9.6	Roofing	Fair (Leakage observed at a few places)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need no replacement)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Hoardings, sliding windows and grill added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Shastri Building



View from P.L Kale Guruji Marg



Decorative consoles below the pediment



Decorative concrete jali at the parapet level



Neoclassical coupled columns



Card No.: G/n-11

Ward (Part): G north-IV

CS No.: 1660

Plot Area: 519.23 sq.m.

B U Area: 1125.00 sq.m.

Date: February, 2005


Record by: Gauri J, Swapnil B

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Kitte Ref.: Bhandari Building



1.0	Denomination						
1.1	Name of Premises	Kitte Bhandari Buile	ding				
1.2	Earlier Name	Not applicable					
1.3	Built in	1937	Extension Date (if	any)	Not applicable		
2.0	Access						
2.1	Main	N.M Gokhale Road	l (North)				
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	Rao Bahadur Sitaram, Keshav Bole Vitthal, Devji Kangutkar, Tukaram Mahadeo Varekar (Trust of Kitte Bhandari)					
3.2	Past	Trust of Kitte Bhan	Trust of Kitte Bhandari				
3.3	Status	Tenanted					
4.0	Use						
4.1	Present	Residential, Commercial					
4.2	Past	Residential, Comm	ercial				
4.3	Usage	Regular residential	, commercial use				
5.0	Significance & Value Classification	n					
5.1	Townscape (Natural / Manmade)		ltural building loated orth-South arterial re		khale road, whic	h is	
5.2	Architectural Description	coursed ashlar magarchitraves in mala	minent due to its ma sonry.the windows h d stone. The façade cting bands around.	nave sin e has se	nple rectangular		
5.3	Intrinsic		ng is a multipurpose opulation of the are		nich only caters t	o the	
5.4	Value Classification	A(arc), A(cul), B(ut	ı)	Recom	mended Grade	II B	
6.0	Topography		·				
6.1	Floors	G + 3					
7.0	Construction	•					
7.1	Plinth	Malad stone claddi	ng in coursed ashla	r masoı	nry plinth		
7.2	Walls	Brick walls					
7.3	Floor	RCC floor slab					
7.4	Stairs	Quarter turn RCC s wooden newel pos	staircase with woode t	en clado	ding and a decor	rative	
7.5	Openings		ings on2nd floor rec s are seen on the re			S	

Articulation Finishes	Stone bands around w	uindows of 1 st and 2 nd fl			
Finishes	Stone bands around windows of 1 st and 2 nd floor				
Tillisties	Malad stone cladding and painted.	externally and internally	y cement plastered		
Interiors (Movable & Immovable)	Interiors, not of heritag	ge value			
Compound / Fence / Gate	Not provided				
Curtilage / Unbuilt Space / Out Buildings / Landscape	No front and marginal	No front and marginal side open space			
Services & Utilities					
Lighting	Natural and artificial, g	Natural and artificial, good natural lighting			
Ventilation	Natural and artificial, good natural ventilation				
Electricity	BEST				
Water Supply	мссм				
Drainage (Plumbing and Sanitation)	MCGM				
Fire precaution	Not provided				
Other (HVAC / BMS / Security Systems)	Not provided				
Condition					
Plinth	Good (No settlement or cracks observed)				
Walls	Good (No dampness of	or cracks observed)			
Floor	Good (No sagging obs	served)			
Stairs	Good (Wooden memb	ers in good condition)			
Openings	Good (Wooden memb	ers in good condition)			
Roofing	Good (No leakage obs	served)			
Articulation & Finishes	Good (Well maintained	d)			
Services	Good (Drainage pipes	need no replacement)			
Outbuildings	Good				
Overall condition	Good	Maintenance level	Good		
Transformation					
Form	Hoardings added later	·			
Structure	No transformation				
Articulation & Finishes	No transformation				
DP Remarks / Perceived Threats	Plot reserved for Public housing on proposed Development Plan. (D.P.)				
Additional Notes / References / Documents Available	Documents: C.S. shee	ets, D.P. Sheets, Eicher	r City Maps - Mumbai		
	Compound / Fence / Gate Curtilage / Unbuilt Space / Out Buildings / Landscape Services & Utilities Lighting Ventilation Electricity Water Supply Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems) Condition Plinth Walls Floor Stairs Openings Roofing Articulation & Finishes Services Outbuildings Overall condition Transformation Form Structure Articulation & Finishes DP Remarks / Perceived Threats	Compound / Fence / Gate Curtilage / Unbuilt Space / Out Buildings / Landscape Services & Utilities Lighting Ventilation Electricity BEST Water Supply Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems) Condition Plinth Good (No settlement of Good (No sagging obstairs Floor Good (Wooden membore) Openings Roofing Articulation & Finishes Good (Wooden membore) Good (Wooden membore	Compound / Fence / Gate Curtilage / Unbuilt Space / Out Buildings / Landscape Services & Utilities Lighting Natural and artificial, good natural lighting Ventilation Not provided Not good natural lighting Ventilation Electricity BEST Water Supply MCGM Drainage (Plumbing and Sanitation) Fire precaution Other (HVAC / BMS / Security Systems) Condition Plinth Good (No settlement or cracks observed) Walls Good (No sagging observed) Stairs Good (No sagging observed) Stairs Good (Wooden members in good condition) Openings Good (Wooden members in good condition) Roofing Good (Wolden members in good condition) Roofing Good (Wolden members in good condition) Services Good (Well maintained) Services Good (Well maintained) Services Good (Well maintained) Transformation Form Hoardings added later. Structure No transformation Articulation & Finishes No transformation Plot reserved for Public housing on proposed (D.P.) Additional Notes / References / Documents: C.S. sheets, D.P. Sheets, Eichelen		

Kitte Bhandari Building



View from N.M Gokhale Road



Malad stone cladded façade



Semicircular opening with simple architrave



Card No.: G/n-12

Ward (Part): G north III-IV

CS No.: 1530, 1566

Plot Area: 77119.58 sq.m.

B U Area: Not applicable

Date: January, 2005

Record by: Gauri J, Tanvi O


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\

Ref.: Shivaji Park



1.0	Denomination						
1.1	Name of Premises	Shivaji Park					
1.2	Earlier Name	Not applicable					
1.3	Built in	Early 20 th century	Extension Date (i	f any)	Not applicable		
2.0	Access						
2.1	Main	Bounded by N.C Ke and Veer Savarkar				North)	
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	Mumbai Municipal Mumbai	Mumbai Municipal Park, The Municipal Corporation of city of Mumbai				
3.2	Past	Mumbai Municipal Park, The Municipal Corporation of city of Mumbai					
3.3	Status	MCGM owned	MCGM owned				
4.0	Use						
4.1	Present	Playground					
4.2	Past	Playground					
4.3	Usage	Regular recreations	al use				
5.0	Significance & Value Classification	n					
5.1	Townscape (Natural / Manmade)	Located in Dadar a which is one of the				west	
5.2	Architectural Description	This playground sp Most of the part unwhereas the other a extense of land is b hall, two gymkhana	der the Shivaji Parl area is used for ou oordered by trees. ⁻	k Gymkl tdoor ar	nana has lawns eas. This huge		
5.3	Intrinsic	Place of Socio-culti	ural and political si	gnifican	ce.		
5.4	Value Classification	J, C(seh)		Recom	mended Grade	II A	
6.0	Topography						
6.1	Floors	Not applicable					
7.0	Construction						
7.1	Plinth	Not applicable					
7.2	Walls	Not applicable					
7.3	Floor	Not applicable					
7.4	Stairs	Not applicable					
7.5	Openings	Not applicable					

7.6	Roofing	Not applicable			
7.7	Articulation	Not applicable			
7.8	Finishes	Not applicable			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate		oound wall but has a co		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Large open space with	n partly lawned areas		
8.0	Services & Utilities				
8.1	Lighting	Not applicable			
8.2	Ventilation	Not applicable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Fair			
9.9	Outbuildings	Good			
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plot reserved as Plays	ground on proposed De	evelopment Plan. (D.P.)	
12.0	Additional Notes / References / Documents Available	History: The plots in Shivaji Park vicinity were laid out by the Bombay Improvement Trust during 1930's. The land was owned and developed by B.I.T. The newly laid out plots were leased out by 1937. The Shivaji Park, a large central open space played a major role in the planning. Buildings were constructed along U-shaped plan around the Shivaji Park in Art-Deco style, a contemporary style of the period and formed a good avenue with Ground plus two development. The majority of flats were and still are owned by upper middle class Maharashtrian population. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			









Card No.: G/n-13

Ward (Part): G north III-IV

CS No.: Not applicable

Plot Area: Not applicable

B U Area: Not applicable

Date: January, 2005


Record by: Gauri J, Tanvi O

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Shivaji Park Precinct



1.0	Denomination					
1.1	Name of Premises	Shivaji Park Precin	Shivaji Park Precinct			
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	Not applicable	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Not applicable				
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not applicable				
3.2	Past	Not applicable				
3.3	Status	Not applicable				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Reglar residential u	ise			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Located in Dadar a	rea bordering the S	Shivaji F	ark ground.	
5.2	Architectural Description	Most of the buildings of this precinct are in Art Deco style. There are small bungalows and buildings in low scale showing similarity in proportions. The whole precinct shows concentric planning where the neucleus is the huge ground. Most of the Art Deco features exhibited by the buildings are the rounded balconies and grooves on the façade.				
5.3	Intrinsic	One of the old neig occupied by Mahar			n and Dadar mos	stly
5.4	Value Classification	A(arc), C(seh), G(g	rp)	Recom	mended Grade	III
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Not applicable				
7.2	Walls	Not applicable				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				
7.5	Openings	Not applicable				
7.6	Roofing	Not applicable				

7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Not applicable		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not applicable		
8.0	Services & Utilities			
8.1	Lighting	Not applicable		
8.2	Ventilation	Not applicable		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not applicable		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Not applicable		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Not applicable		
9.9	Outbuildings	Not applicable		
9.10	Overall condition	Not applicable Maintenance level Not applicable		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Not applicable		
12.0	Additional Notes / References / Documents Available	History: The plots in Shivaji Park vicinity were laid out by the Bombay Improvement Trust during 1930's. The land was owned and developed by B.I.T. The newly laid out plots were leased out by 1937. The Shivaji Park, a large central open space played a major role in the planning. Buildings were constructed along U-shaped plan around the Shivaji Park in Art-Deco style, a contemporary style of the period and formed a good avenue with Ground plus two development. The majority of flats were and still are owned by upper middle class Maharashtrian population. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Shivaji Park Precinct







Typical balcony detail





Building facing Veer Savarkar Marg





Card No.: G/n-13a

Ward (Part): G north-III

CS No.: 1886, 1887, 1888

Plot Area: 1935.16 sq.m.

B U Area: 4387.50 sq.m.

Date: February, 2005

Record by: Gauri J, Ojas P


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Hari

Ref.: Niwas



1.0	Denomination					
1.1	Name of Premises	Hari Niwas (Shivaji Park Precint)				
1.2	Earlier Name	Not applicable				
1.3	Built in	1937	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Lady Jamshetji Mar	g			
2.2	Subsidiary	Shivaji Park Road N	No. 2			
3.0	Ownership Pattern					
3.1	Present	Jethalal Kanji Chau Chauhan, Deepa Je		al Chau	lhan, Jyoti Jethala	al
3.2	Past	Madhavji Raja Chauhan, Keshavji Kanti Chauhan, Puri bai Kanji Chauhan, Uma Keshavji Chauhan, Bharat Keshavji Chauhan, Ajay Keshavji Chauhan, Damodar Kanji Chauhan, Taraben Damodar Chauhan, Sonali Damodar Chauhan, Hina Damodar Chauhan, Darshan Damodar Chauhan, Naina Damodar Chauhan				
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential, Comm	ercial			
4.2	Past	Residential, Comm	ercial			
4.3	Usage	Regular residential,	commercial use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located on a corne the major North-So		nshetji I	Marg which is one	e of
5.2	Architectural Description	G + 4 Art deco building located in Shivaji park vicinity facing Lady Jamshetji Marg. It has features like rounded balconies at the corner and columns supporting them. The terrace has an interesting elliptical roof on the portion which defines the junction of the roads in a typical Art deco style.				
5.3	Intrinsic	The building houses modest size tenements for middle class Marathi speaking tenants in Shivaji Park area.				
5.4	Value Classification	I(sce), A(arc)		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 4				
7.0	Construction					
7.1	Plinth	Plastered masonry	plinth			
7.2	Walls	Brick walls				
7.3	Floor	RCC floor slab				

7.4	Stairs	Dog legged RCC staircase		
7.5	Openings	Rectangular Opening with wooden frames and glazed shutters		
7.6	Roofing	Flat roof terrace		
7.7	Articulation	It has features like rounded balconies at the corner and columns supporting them. The terrace has an interesting elliptical roof on the portion which defines the junction of the roads in a typical Art decostyle.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space and marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Fair (No settlement or cracks observed but needs maintanance)		
9.2	Walls	Fair (Needs plastering and painting)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Leakage observed at a few places)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Hoardings, grills and sliding windows added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Hari Niwas



View from the junction near Shivaji Park





View from Lady Jamshetji Marg



Decorative terrace parapet wall



Corner terrace has a flat roof supported by reinforced columns



Card No.: G/n-14

Ward (Part): G north-III

CS No.: 1985

Plot Area: 743.96

B U Area: 2235 sq.m.

Date: February, 2005


Record by: Gauri J, Ojas P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Swastik House



1.0	Denomination					
1.1	Name of Premises	Swastik House				
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	1930	Extension Date (if	f any)	Not applicable	
2.0	Access					
2.1	Main	Taikalwadi Marg				
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Trust				
4.0	Use					
4.1	Present	Institutional	Institutional			
4.2	Past	Institutional				
4.3	Usage	Regular institutiona	Regular institutional use			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	One of the school b	ouildings located ne	ear Shiva	aji Park.	
5.2	Architectural Description	This building has Indo Saracenic style. It is prominent due to the Moorish arches which are used on the bays at intervals. The long common corridors are accentuated with concrete jalis at every floor. The structure gains importance because it is a school building in one of the residential areas of Matunga.				
5.3	Intrinsic	An important public	building due to its	location	in a residential	area.
5.4	Value Classification	A(arc), I(sce)		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 3				
7.0	Construction					
7.1	Plinth	Plastered masonry	plinth			
7.2	Walls	Brick walls				
7.3	Floor	RCC floor slab	RCC floor slab			
7.4	Stairs	Straight flight RCC	Straight flight RCC staircase with wooden cladded members			
7.5	Openings	Rectangular openin	ngs with wooden fra	ames an	d glazed shutter	s
7.6	Roofing	Flat roof terrace				

7.7	Articulation	The façade has Moorish arches and concrete jali at the parapet wal level. The columns at intervals for the common corridors have grooves and decorative capitals.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value	
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal side open sp	ace	
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, g	good natural lighting	
8.2	Ventilation	Natural and artificial, g	good natural ventilation	
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement or	cracks observed)	
9.2	Walls	Fair (Needs plastering	and painting)	
9.3	Floor	Fair (No sagging obse	erved)	
9.4	Stairs	Fair (Wooden membe	rs in good condition)	
9.5	Openings	Fair (Wooden membe	rs in good condition)	
9.6	Roofing	Fair (Leakages observ	ved at few places)	
9.7	Articulation & Finishes	Fair (Plastered elemer	nts need maintenance)	
9.8	Services	Fair (Drainage pipes n	need maintenance)	
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair	Maintenance level	Fair
10.0	Transformation			
10.1	Form	Hoardings added later	on the façade.	
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. shee	ets, D.P. Sheets, Eiche	r City Maps - Mumbai

Swastik House



View from Taikalwadi Road





Decorative arches in between grooved pilasters



Ground floor has commercial sinages



Decorative concrete jali at parapet level



Right side elevation and Left side elevation not seen due to proximity of adjoining buildings



Card No.: G/n-15

Ward (Part): G north-III

CS No.: 5/521, 3/523

Plot Area: 700.66 sq.m.

B U Area: 1020.00 sq.m.

Date: February, 2005

Record by: Gauri J, Tanvi O


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Gurudwara Khalsa


Sabha



1.0	Denomination			
1.1	Name of Premises	Gurudwara Khalsa Sabha		
1.2	Earlier Name	Not applicable		
1.3	Built in	1947-48 Extension Date (if any) Not applicable		
2.0	Access			
2.1	Main	Gopi Tank Road		
2.2	Subsidiary	City light Cinema Road		
3.0	Ownership Pattern			
3.1	Present	Khalsa Sabha , Bombay (Matunga Gurudwara)		
3.2	Past	Khalsa Sabha , Bombay (Matunga Gurudwara)		
3.3	Status	Tenanted		
4.0	Use			
4.1	Present	Religious		
4.2	Past	Religious		
4.3	Usage	Regular religious place		
5.0	Significance & Value Classification	on		
5.1	Townscape (Natural / Manmade)	This imposing structure is a local landmark, off Lady Jamshetji Marg, which is one of the main arterial roads.		
5.2	Architectural Description	G + 2 building functioning as a Gurudwara and a school is built in Indo-Sarsanic style. It has a prominent dome on the terrace, chhatris on the entrance gate and a very prominent balcony with ornamental brackets having a Bengal style roof supported by decorative columns. Although it has the school building in its premises it is not included in the fresh listing since it has no heritage value.		
5.3	Intrinsic	Gurudwara is a worship place place for the Sikh community. This is a post independent structure located in a non Sikh neighbourhood.		
5.4	Value Classification	A(cul), B(uu), C(seh), E Recommended Grade II B		
6.0	Topography	<u> </u>		
6.1	Floors	G + 2		
7.0	Construction			
7.1	Plinth	Plastered masonry plinth		
7.2	Walls	Brick walls		
7.3	Floor	RCC floor slab		
7.4	Stairs	RCC dog legged staircase		

12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		
11.0	DP Remarks / Perceived Threats	Plot reserved for Public hall and Students hostel on proposed Development Plan. (D.P.)		
10.3	Articulation & Finishes	No transformation		
10.2	Structure	Renovated over the period of time.		
10.1	Form	No transformation		
10.0	Transformation			
9.10	Overall condition	Good Maintenance level Good		
9.9	Outbuildings	Good		
9.8	Services	Good (No leakage observed)		
9.7	Articulation & Finishes	Good (Well maintained)		
9.6	Roofing	Good (No leakage observed)		
9.5	Openings	Good (Wooden members in good condition)		
9.4	Stairs	Good (Well maintained)		
9.3	Floor	Good (No sagging observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.1	Plinth	Good (No settlement or cracks observed)		
9.0	Condition			
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
8.6	Fire precaution	Not provided		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.4	Water Supply	MCGM		
8.3	Electricity	BEST		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.1	Lighting	Natural and artificial, good natural lighting		
8.0	Services & Utilities			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front and marginal side open space		
7.10	Compound / Fence / Gate	Plastered brick wall		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.8	Finishes	Internally and externally Cement plastered and Painted		
7.7	Articulation	The entrance gate is highly ornamental having features like decorative chhatris above. The projecting balconies on the first flow have a Bengal roof, the dome on the top also has small decorative.		
7.6	Roofing	Balcony on the first floor has a Bengal roof and flat roof terrace above		
	Openings			

Gurudwara Khalsa Sabha



View from Gopi Tank Marg



Projecting balcony with decorative Bengal roof above



View of the façade



Dome above the Gurudwara



Dining hall



Prayer hall



The Holy granth

Right side elevation and Left side elevation not seen due to proximity of adjoining buildings



Card No.: G/n-16

Ward (Part): G north-III

CS No.: 540 (F.P 158 B)

Plot Area: 3025.11 sq.m.

B U Area: 1272.72 sq.m.

Date: February, 2005


Record by: Gauri J, Arti S

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ **Ref.:** Govardhan Baug



1.0	Denomination					
1.1	Name of Premises	Govardhan Baug				
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 th century	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Manmala Tank Roa	ad			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Khanderao Ramrao	o Shirodkar			
3.2	Past	Khanderao Ramrao	o Shirodkar			
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential	Residential			
4.3	Usage	Regular residential	Regular residential use			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Located in a interior	or plot off ManmalaT	Tank Ro	oad.	
5.2	Architectural Description	Vernacular style structure which lend a chawl like character to the area. This area mostly belongs to the marathi speaking population. The peculiar character of the structure is that it has two elevated bays topped by a sloping roof and between these two bays is a long stretch of common corridors interrupted by slender wooden columns. It has a central archway which leads to the staircase. The elevated bays have floral motifs on the gables.				
5.3	Intrinsic	The structure is a coneighbourhood.	chawl which is house	ed in ar	n old Maharashtr	ian
5.4	Value Classification	A(arc), E		Recom	mended Grade	III
6.0	Topography	•				
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Black Basalt stone	plinth in coursed as	hlar ma	asonry	
7.2	Walls	Brick walls				
7.3	Floor	Wooden joist floori	ng			
7.4	Stairs	Open well Wooden	Open well Wooden staircase with decorative balustrade			
7.5	Openings	Rectangular openir	ng with wooden fran	nes and	d glazed shutters	;
7.6			Rectangular opening with wooden frames and glazed shutters Sloping roof with Mangalore tiles and wooden trusses			

7.7	Articulation	The structure has features like decorative semi circular arches with decorative floral motifs around it. Cornice bands are seen at all floor levels. The gables have decorative floral motifs at the top. The long stretch of balconies have slender wooden columns at intervals which break the monotony.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space, marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement observed but cracks seen at some places)		
9.2	Walls	Fair (Dampness seen at few places)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Leakage observed at a few places)		
9.7	Articulation & Finishes	Fair (Needs maintenance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Hoardings added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Govardhan Baug



View from Manmala Tank Road



Decorative floral motifs on the gable wall



Decorative cast iron railing



View of the elevated bay



Semicircular arch with floral motifs above



Card No.: G/n-17

Ward (Part): G north-III

CS No.: F.P 131

Plot Area: 32165.81 sq.m.

B U Area: 96497.43 sq.m.

Date: February, 2005

Record by: Gauri J, Ojas P


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\David
Ref.: Sasoon Reformatory

school



		301001
1.0	Denomination	
1.1	Name of Premises	David Sasoon Reformatory school
1.2	Earlier Name	Not applicable
1.3	Built in	Early 20 th century Extension Date (if any) Not applicable
2.0	Access	
2.1	Main	Takandas Kataria Marg
2.2	Subsidiary	Senapati Bapat Marg (Tulsi Pipe Road)
3.0	Ownership Pattern	
3.1	Present	Government of Maharashtra, David Sasoon Industrial School
3.2	Past	Government of Maharashtra, David Sasoon Industrial School
3.3	Status	Government
4.0	Use	
4.1	Present	Reformatory school
4.2	Past	Reformatory school
4.3	Usage	Reformatory school
5.0	Significance & Value Classifica	tion
5.1	Townscape (Natural / Manmade)	A huge plot located near Matunga station bounded by Senapati Bapat Marg on the east, Takandas Kataria Marg on the north and Manmala Tank road on the west.
5.2	Architectural Description	This is a combination Vernacular style and Neo classical architecture. The façade facing the interiors is plastered and the façade facing Senapati Bapat Marg is in Black Basalt stoneand coursed ashlar masonry. The windows have simple stone architraves painted in blue. The ground floor has semicircular windows and the upper floors have segmental arched windows. The corner edges of the building have long and short work. The sloping roof is supported by decorative wooden brackets.
5.3	Intrinsic	Important corner building which caters to a particular cause of a Remand home.
5.4	Value Classification	A(arc), B(uu), B(des), I(sce) Recommended Grade II B
6.0	Topography	
6.1	Floors	G + 2
7.0	Construction	
7.1	Plinth	Black Basalt stone plinth in coursed ashlar masonry
7.2	Walls	Brick walls
7.3	Floor	Wooden joist flooring

7.4	Stairs	Openwell wooden staircase		
7.5	Openings	Arched openings with wooden frames and glazed shutter.		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	The windows have simple stone architraves painted in blue. The ground floor has semicircular windows and the upper floors have segmental arched windows. The corner edges of the building have long and short work. The sloping roof is supported by decorative wooden brackets.		
7.8	Finishes	West façade cladded with Basalt stone		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	High stone wall in random rubble masonry		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Structure has a playground inside		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Good (Wooden members in good condition)		
9.5	Openings	Good (Wooden members in good condition)		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Good (Well maintained)		
9.8	Services	Good (Drainage pipes need no replacement)		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	West and South boundaries of the plot touch the Industrial School on proposed Development Plan. (D.P.)		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai		

David Sasoon Reformatory School



Façade facing Matunga railway station



Black Basalt with highlighted arches and long and short work at the corner edges of the building




Plain façade with semicircular cut outs



Semicircular arcade on the ground floor



Façade facing the playground



Name inscribed on a marble plaque




Playground

















Card No.: G/n-18

Ward (Part): G north-III

CS No.: F.P 522

Plot Area: 306.28 sq.m.

B U Area: 562.50 sq.m.

Date: February, 2005


Record by: Gauri J, Ojas P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ **Ref.:** Manekbai Building



1.0	Denomination					
1.1	Name of Premises	Manekbai Building				
1.2	Earlier Name	Not applicable				
1.3	Built in	Mid 20 th century	Extension Date (i	if any)	Not applicable	
2.0	Access					
2.1	Main	Takandas Kataria I	Marg			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Bombay Electric Si	upply & Trensway (Compan	ıy	
3.2	Past	Bombay Electric Si	upply & Trensway (Compan	y	
3.3	Status	Tenanted				
4.0	Use	·				
4.1	Present	Residential	Residential			
4.2	Past	Residential	Residential			
4.3	Usage	Regular residential	Regular residential use			
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)		Located near Matunga station adjacent to David Sassoon Reformatory School.			
5.2	Architectural Description	looks interesting be on either sides and other. These balco decoratively carved floor level defines t	This Vernacular style structure located off Senapati Bapat Marg looks interesting because of the two elevated bays with sloping roof on either sides and a balcony block flanking from one bay to the other. These balconies are supported by wooden posts having decoratively carved wooden brackets. The cornice band at the first floor level defines the separation between the floors. The ground floor has an arcade of semicircular arches.			
5.3	Intrinsic	This structure gains multipurpose hall w community and the	hich can be used b	by the pe	eople of any	
5.4	Value Classification	A(arc), A(cul), E		Recom	nmended Grade	III
6.0	Topography					
6.0 6.1	Topography Floors	G + 1				
		G + 1				
6.1	Floors	G + 1 Plastered masonry	plinth			
6.1 7.0	Floors Construction		plinth			
6.1 7.0 7.1	Floors Construction Plinth	Plastered masonry	plinth			

7.5	Openings	Rectangular Opening with wooden frames and glazed shutter		
7.6	Roofing	Slopping roof Mangalore tiles with wooden trusses		
7.7	Articulation	The balconies are supported by wooden posts having decoratively carved wooden brackets. The cornice band at the first floor level defines the separation between the floors. The ground floor has an arcade of semicircular arches.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Brick compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement of the plinth seen but needs maintanance)		
9.2	Walls	Fair (Needs plastering and painting)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Leakage observed at a few places)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Manekbai Building



View from Takandas Kataria Marg





Semicircular arcade on the ground floor





Decorative wooden posts and carved brackets



Plain eaves fascia



Cornice band supported by decorative corbels



View towards Senapati Bapat Marg



Cill of the parapet has a moulding

Right side elevation and Left side elevation not seen due to proximity of adjoining buildings



Card No.: G/n-19

Ward (Part): G north - III

CS No.: F.P 265

Plot Area: 3911.40 sq.m.

B U Area: 4727.25 sq.m.

Date: February, 2005


Record by: Gauri J., Ojas P

Review by: Neera Adarkar

Internal: As above

External: As above


Photo T-IV-Gn:\Ward Gn\
Ref.: Manik Niwas



1.0	Denomination					
1.1	Name of Premises	Manik Niwas				
1.2	Earlier Name	Not applicable				
1.3	Built in	Mid 20 th century	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Takandas Kataria Ma	arg			
2.2	Subsidiary	Senapati Bapat Marg (Tulsi Pipe Road)				
3.0	Ownership Pattern					
3.1	Present	Bombay Municipal C	Corporation			
3.2	Past	Dhirabhai Bhirubhai,	Natwarlal Bhirubh	nai, Gul	abbhai Morrarji	
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located near Matung the fly-over.	ga Station off Sen	apati Ba	apat Marg seen f	from
5.2	Architectural Description	This Vernacular style structure has a modest roof profile with two bays elevated on the either sides of the structure with a sloping roof. The roof has a simple profile and the gables have decorative floral motifs. The balconies stretching from one end of the bay to the other have wooden posts at the intervals to break the monotony. The windows have simple architraves around and floor bands are projecting at all floor levels.				
5.3	Intrinsic	This Vernacular strue of Mahim.	cture is located in	one of	the old neighbou	irhood
5.4	Value Classification	A(arc), B(des)		Recom	mended Grade	Ш
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Plastered stone plint	h			
7.2	Walls	Load bearing brick w	alls			
7.3	Floor	Wooden joist flooring	9			
7.4	Stairs	Wooden dog legged	staircase with sim	nple woo	oden balustrade	
7.5	Openings	Rectangular opening	gs with wooden fra	mes an	d glazed shutter	,
	•	•				

7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	The façade has features like decorative floral motifs on the gables. Projecting bands at all floor levels. The balconies stretching from one end of the bay to the other have wooden posts at the intervals to break the monotony.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Front open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement or cracks observed)		
9.2	Walls	Fair (Needs plastering and painting)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Leakage observed at a few places)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Chajjas and grills added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai		

Manik Niwas



View from Matunga flyover



One of the bays with the gable elevated above





Front elevation



Card No.: G/n-20

Ward (Part): G north-III

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005

Record by: Gauri J, Tanvi O

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Anand Bhavan



			Aliana Dhavan				
1.0	Denomination						
1.1	Name of Premises		Anand Bhavan				
1.2	Earlier Name		Not applicable				
1.3	Built in		Mid 20 th century	Extension Date (if any)	Not applicable	
2.0	Access						
2.1	Main		Takandas Kataria I	Marg			
2.2	Subsidiary		Not applicable				
3.0	Ownership Pattern						
3.1	Present		Not available				
3.2	Past		Not available				
3.3	Status		Tenanted				
4.0	Use						
4.1	Present		Residential, Comm	nercial			
4.2	Past		Residential, Commercial				
4.3	Usage		Regular residential, commercial use				
5.0	Significance & Value Class	ification	1				
5.1	Townscape (Natural / Manma	ade)	Located off Lady Jamshetji Marg, which is one of the major North-South arterial roads.				
5.2	Architectural Description		This Vernacular style structure maintains the skyline of the road due to its modest scale and proportions. The roof profile and the projecting balconies with decorative C.I railings give it a perfect Vernacular look. The roof profile is further enhanced with a decorative eaves fascia. The segmental openings are seen on the façade.				
5.3	Intrinsic		A low profile mode	rate building in a b	usy marl	ket of Matunga.	
5.4	Value Classification		A(arc), A(cul)		Recom	mended Grade	III
6.0	Topography						
6.1	Floors		G + 1				
7.0	Construction						
7.1	Plinth		Plastered masonry	plinth			
7.2	Walls		Brick walls				
7.3	Floor		RCC floor slab				
7.4	Stairs		Openwell wooden staircase with decorative wooden balusters				
7.5	Openings		Segmental arched glazed shutter and				d
_							

7.7	Articulation	The projecting balconies have decorative C.I railings. The windows have simple architraves around. The roof has decorative wooden eaves fascia. The façade shows minimal articulation.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement of the plinth observed but cracks seen at few places)		
9.2	Walls	Fair (Needs plastering and painting)		
9.3	Floor	Fair (No sagging observed but needs maintanance)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Leakage observed at few places)		
9.7	Articulation & Finishes	Fair		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Hoardings, grills and sliding windows added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Anand Bhavan



View from Takandas Kataria Marg



View of the projecting balcony



Balcony supported by wooden posts



Decorative cast iron railing



Decorative eaves fascia



Card No.: G/n-21

Ward (Part): G north-III

CS No.: F.P 263

Plot Area: 1925.59 sq.m.

B U Area: 4363.60 sq.m.

Date: February, 2005


Record by: Gauri J, Ojas P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Dalmiya Building



1.0	Denomination					
1.1	Name of Premises	Dalmiya Building				
1.2	Earlier Name	Not applicable				
1.3	Built in	1918	Extension Date (if	any)	Not applicable	
2.0	Access				•	
2.1	Main	Takandas Kataria I	Takandas Kataria Marg			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Proladrai Ramjidas	3			
3.2	Past	Harikishandas Ran Ramkuvar	nbhagat, Umarsingl	n Shivm	nukhrai, Dubhcha	ınd
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential	Residential			
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	า				
5.1	Townscape (Natural / Manmade)	Located on a plot, major North-South	off Lady Jamshetji I arterial roads.	Marg, w	hich is one of the)
5.2	Architectural Description	style. The central s the ground floor an the façade has a sl corridors. The cent sides of the arches parapet level. This	combination of Verretaircase bay has feat a shouldered arch of loping roof with Markral bay has decorated. These arches have central bay continued the eaves board less	atures I on the t ngalore ive pilas e a sim es abov	ike Moorish archehird floor. The restiles and long consters on the either ple balustrade at	es on st of mmon er t the
5.3	Intrinsic	One of the building occupied by Gujara	s located in a Mara	thi spea	aking area but	
5.4	Value Classification	A(arc)		Recom	nmended Grade	III
6.0	Topography					
6.1	Floors	G + 3				
7.0	Construction					
7.1	Plinth	Plastered stone pli	nth			
7.2	Walls	Brick walls				
7.3	Floor	RCC floor slab				
7.4	Stairs	Dog legged woode	n staircase with ded	corative	balustrade.	

7.5	Openings	Rectangular Opening with wooden framed glazed shutters		
7.6	Roofing	Slopping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	The central staircase bay has features like Moorish arches on the ground floor and shouldered arch on the third floor. The rest of the façade has a sloping roof with Mangalore tiles and long common corridors. The central bay has decorative pilasters on the either sides of the arches. These arches have a simple balustrade at the parapet level.		
7.8	Finishes	Internally and externally Cement plastered and Painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Brick compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement of the plinth observed but needs maintanance)		
9.2	Walls	Fair (Needs plastering and painting)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Leakage observed at few places)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Grills and sliding windows added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Dalmiya Building



Front elevation



Moorish arch for the staircase bay



Staircase bay with different decorative Mughal arches



Decorative architraves around the doors of the verandah



Shouldered arch for the staircase bay



Decorative motifs above the entrance arch



Card No.: G/n-22

Ward (Part): G north-III

CS No.: 529

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Gauri J, Uma P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\KashiRef.: Vishweshwar Mandir



1.0	Denomination					
1.1	Name of Premises	Kashi Vishweshwar Mandir				
1.2	Earlier Name	Not applicable				
1.3	Built in	1783 (Sthapana) Extension Date (if any) Not applicable				
2.0	Access					
2.1	Main	Takandas Kataria Marg				
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present Not available					
3.2	Past	Not available				
3.3	Status	Trust				
4.0	Use					
4.1	Present Religious					
4.2	Past Religious					
4.3	Usage Regular religious use					
5.0	Significance & Value Classification	on .				
5.1	Townscape (Natural / Manmade)	Located off Lady Jamshetji Marg next to the crowded City Light market.				
5.2	Architectural Description	A low profile temple has a Vernacular style with a sloping roof and decorative eaves fascia. The stepped profile of the staircase is an interesting feature of the temple. The windows and doors of the ground floor are segmental whereas the openings on the first floor are rectangular. Moulded architraves are seen around all the openings. Cornice bands are seen at first floor level.				
5.3	Intrinsic	It is one of the oldest temples of the neighbourhood used mostly by Marathi speaking population.				
5.4	Value Classification	A(arc), A(cul), B(uu), C(seh),E Recommended Grade				
6.0	Topography					
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	Plastered stone plinth				
7.2	Walls	Brick load bearing walls				
7.3	Floor	Wooden joist flooring with brick bat coba				
7.4	Stairs	Straight flight wooden staircase				

7.5	Openings	The windows and doors of the ground floor are segmental whereas the openings on the first floor are rectangular with wooden frames and glazed shutter.		
7.6	Roofing	Sloping Mangalore tile with wooden trusses		
7.7	Articulation	The stepped profile of the staircase is an interesting feature of the temple. The windows and doors of the ground floor are segmental whereas the openings on the first floor are rectangular. Moulded architraves are seen around all the openings. Cornice bands are seen at first floor level.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered Brick wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Front open space adequate and marginal side open spaces		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Good (Well maintained)		
9.5	Openings	Good (Wooden members in good condition)		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Good (Well maintained)		
9.8	Services	Good (Drainage pipes need no replacement)		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	Recently partly painted.		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Kashi Vishweshwar Mandir



View from Takandas Kataria Marg





Stepped profile of the external staircase



Kashi Vishweshwar Mandir



Decorative pilasters on the façade



Decorative pinnacle of the temple



Shopline on the ground floor



Right side elevation and Left side elevation not seen due to proximity of adjoining buildings



Card No.: G/n-23

Ward (Part): G north-III

CS No.: 2/634

Plot Area: 531.78 sq.m.

B U Area: 1155.00 sq.m.

Date: February, 2005


Record by: Gauri J., Ojas P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ **Ref.:** Bamboli Niwas



1.0	Denomination					
1.1	Name of Premises	Bamboli Niwas				
1.2	Earlier Name	Not applicable				
1.3	Built in	1936	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Lady Jamshetji Mai	·g			
2.2	Subsidiary	Sitaram Ravji Alias	Sitaram Ravji Alias S. Keer Marg			
3.0	Ownership Pattern					
3.1	Present	Madhav Atmaram F	Pandit , Milind Mad	hukar P	andit	
3.2	Past	Madhav Atmaram F	Pandit , Milind Mad	hukar P	andit	
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential, Commercial				
4.2	Past	Residential				
4.3	Usage	Regular residential, commercial use				
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located on a corne North South road.	r plot on Lady Jam	ıshetji M	arg, which is a n	najor
5.2	Architectural Description	This G + 3 building is one of the many Art deco buildings on this major road in Mahim. This building is owned by Pandit family originally migrated from a village Bamboli in Goa and hence the name. The central portion of the façade responds to the corner in a true Art deco vocabulary. It is covered with an elliptical flat roof and is accentuated with projecting columns which terminate above the entrance in the horizontal band with zig zag linear decoration in plaster.				
5.3	Intrinsic	The central portion Deco vocabulary.	of the façade resp	onds to	the corner in a tr	ue Art
5.4	Value Classification	A(arc), I(sce)		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Plastered masonry	plinth			
7.2	Walls	Brick walls				
7.3	Floor	RCC floor slab				
7.4	Stairs	Wooden with M S b	palusters, wooden i	railing		

7.5	Openings	Rectangular Opening with wooden framed glazed shutters		
7.6	Roofing	Flat roof terrace		
7.7	Articulation	The central portion of the façade responds to the corner in a true Art deco vocabulary. It is covered with an elliptical flat roof and is accentuated with projecting columns which terminate above the entrance in the horizontal band with zig zag linear decoration in plaster.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space, marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Fair (No settlement or cracks observed but needs maintanance)		
9.2	Walls	Fair (Needs plastering and painting)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (No leakage observed)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Hoardings, grills and sliding windows added later		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Bamboli Niwas



View from Lady Jamshetji Marg



Art Deco corner building



Staircase bay with a elliptical roof



Nameplate





Elevation from Lady Jamshetji Marg



Shopline on the ground floor



Common	Ref.	No.	:
--------	------	-----	---

Card No.: G/n-24

Ward (Part): G north-III

CS No.: F.P 107

Plot Area: 565.68 sq.m.

B U Area: 1050.00 sq.m.

Date: February, 2005


Record by: Gauri J, Uma P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Parvati Niwas



1.0	Denomination					
1.1	Name of Premises	Parvati Niwas				
1.2	Earlier Name	Not applicable				
1.3	Built in	1930	Extension Date (if a	any)	Not applicable	
2.0	Access					
2.1	Main	Lady Jamshetji Mar	g			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Madhav Martand K	orde, Shripad Marta	nd Kord	de	
3.2	Past		na Korde, Laxman F arad Laxman Korde		shna Korde, Ana	ant
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential, Commercial				
4.2	Past	Residential, Commercial				
4.3	Usage	Regular residential,	commercial use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	One of the only remaining typology of buildings on Lady Jamshetji Marg which is one of the major North-South arterial roads.				
5.2	Architectural Description	Vernacular style modest building with long wooden balconies covered with a sloping roof and hence breaking the monotony of RCC buildings bordering the west side of Lady Jamshetji Marg. The structure has minimal articulation on the façade. The chajjas are supported by RCC brackets.				
5.3	Intrinsic	The only remaining occupied by Marath	typology of building	s on thi	is road is being	
5.4	Value Classification	A(cul), G(grp)	F	Recomr	mended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Plastered masonry	plinth			
7.2	Walls	Brick walls				
7.3	Floor	RCC floor slab				
7.4	Stairs	Straight flight Wooden staircase				
7.5	Openings	Segmental arched wooden frames and	windows with rectand d glazed shutters	gular d	ouble shutters h	naving

7.6	Roofing	Flat roof terrace partially sloping roof with Mangalore tiles		
7.7	Articulation	The structure has features like projecting balconies with RCC criss cross pattern jalis. The terrace parapet wall has decorative motifs. The chajjas are supported by simple RCC brackets.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space, marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	мссм		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units at some places		
9.0	Condition			
9.1	Plinth	Fair (No settlement or cracks observed but needs maintanance)		
9.2	Walls	Fair (Needs plastering and painting)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Leakages observed at few places)		
9.7	Articulation & Finishes	Fair (Needs maintenance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Hoardings, grills and sliding windows added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Parvati Niwas



View from Lady Jamshetji Marg



Decorative wooden brackets supporting the roof



Front elevation



Projecting balcony on the 1st floor



Roof profile



Commercial banners on the ground floor

CONT 1.3		0	D-(N-			
			on Ref. No.:			
	A Park III	Card N			14	-, -, l
		`	Part): G north-III		759 KUNNA	TH I
		CS No.			Hous	E 3 7591
<u>.</u> T		Plot Ar	ea: 434.97 sq.m.			
		B U Ar	ea: 720.00 sq.m.			
		Date: F	ebruary, 2005		SITALADEVI	TEMPLE
		Record	l by : Gauri J, Tanvi C)		KOAD
		Review	by: Neera Adarkar		,	
		Interna	II: As above		1979 1980	
		Extern	al: As above			
		Photo Ref.:	T-IV-Gn:\Ward Gn\ Kunnath House			1 1 1
1.0	Denomination					
1.1	Name of Premises	_	Kunnath House			
1.2	Earlier Name		Not applicable			
1.3	Built in		1944	Exte	nsion Date (if any)	Not applicable
2.0	Access					
2.1	Main		Sitaladevi Temple R	Road ((East)	
2.2	Subsidiary		Not applicable			
3.0	Ownership Pattern					
3.1	Present		Kunnath Balkrishna	Nair		
3.2	Past		Kunnath Balkrishna Nair			
3.3	Status		Tenanted			
4.0	Use					
4.1	Present		Residential			
4.2	Past		Residential			
4.3	Usage		Regular residential use			
5.0	Significance & Value Class	ification	1 -			
5.1	Townscape (Natural / Manma		Structure located or			next to its junction with or North-South arterial
			roads.	ج, wii		o. Holai Godii ditellal
5.2	Architectural Description		style. It has balconic externally has a 10f	es cur t high	ved at the corners. S	ngular band around it,
5.3	Intrinsic		Art Deco building of community.	the n	nid 20 th century occu	pied by Catholic
5.4	Value Classification		A(arc), A(cul)		Recom	nmended Grade III
6.0	Topography					
6.1	Floors		G + 2			
7.0	Construction					
7.1	Plinth		Plastered masonry	plinth		
7.2	Walls		Brick walls			
7.3	Floor		RCC floor slab			
7.4	Stairs		Openwell wooden s	tairca	se	
7.5	Openings		Rectangular Openin	ng witl	n wooden frames an	d glazed shutter.
7.6	Roofing		Flat roof terrace			
			•			

7.7	Articulation	Windows of staircase block at landing has projecting bands Staircase block externally has a 10ft high window with a rectangular band around it, there are V shaped Grooves on top and bottom of the window.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement or cracks observed but plaster chipped off at a few places)		
9.2	Walls	Fair (Needs plastering and painting)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Leakage observed at few places)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Grills and sliding windows added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot under Residential Zone on proposed Development Plan. (D.P.)		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Kunnath House



View from Sitladevi Temple Road



Art Deco style V shaped grooves on the façade



Grooved bands at the entrance



Rounded balcony



View of the compound wall

Right side elevation and Left side elevation not seen due to proximity of adjoining buildings



Card No.: G/n-26

Ward (Part): G north-III

CS No.: 1/765, 1A/765

Plot Area: 596.99 sq.m.

B U Area: 1940.25 sq.m.

Date: February, 2005


Record by: Gauri J, Ojas P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ **Ref.:** Ferriera Mansion



1.0	Denomination					
1.1	Name of Premises	Ferriera Mansion	Ferriera Mansion			
1.2	Earlier Name	Not applicable	Not applicable			
1.3	Built in	1937	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Sitaladevi Temple	Road (East)			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Emlyn Ferreira				
3.2	Past	Emlyn Ferreira				
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residentia	ıl use			
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)		Long stretch of a building block along Sitladevi Temple road off Senapati Bapat Marg which is one of the major North-South arterial roads.			
5.2	Architectural Description	building looks pro typical rounded ba the building look n building is highligh	This Art Deco building occupies a long stretch of the road. This building looks prominent because it is neatly maintained. It has typical rounded balconies at the corners of the building which make the building look more impressive. The staircase block of the building is highlighted with typical coloured Art Deco bands. The façade has grooved bands.			
5.3	Intrinsic	This building was Catholic neighbou	owned by a Catholic rhood of Mahim.	c family	and belongs to a	n old
5.4	Value Classification	G(grp), A(arc), I(s	ce)	Recon	nmended Grade	Ш
6.0	Topography					
6.1	Floors	G + 4				
7.0	Construction					
7.1	Plinth	Plastered masonr	y plinth			
7.2	Walls	Brick walls				
7.3	Floor	RCC floor slab				
7.4	Stairs	Dog legged RCC	staircase			
7.5	Openings		Rectangular opening with wooden frames and glazed shutters			

12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			
11.0	DP Remarks / Perceived Threats	Plot under Residential Zone on proposed Development Plan. (D.P.)			
10.3	Articulation & Finishes	No transformation			
10.2	Structure	No transformation			
10.1	Form	Grills and sliding wind	ows added later.		
10.0	Transformation				
9.10	Overall condition	Good	Maintenance level	Good	
9.9	Outbuildings	Good			
9.8	Services	Good (Drainage pipes	need no replacement)		
9.7	Articulation & Finishes	Good (Well maintaine			
9.6	Roofing	Good (No leakage ob	served)		
9.5	Openings	Good (Wooden memb	pers in good condition)		
9.4	Stairs	Good (Well maintaine	d)		
9.3	Floor	Good (No sagging ob	served)		
9.2	Walls	Good (No dampness	or cracks observed)		
9.1	Plinth	Good (No settlement	or cracks observed)		
9.0	Condition				
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units			
8.6	Fire precaution	Not provided			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.4	Water Supply	MCGM			
8.3	Electricity	BEST			
8.2	Ventilation	Natural and artificial, o	good natural ventilation		
8.1	Lighting	Natural and artificial, o	good natural lighting		
8.0	Buildings / Landscape Services & Utilities				
7.11	Curtilage / Unbuilt Space / Out	Marginal side open sp	aces		
7.10	Compound / Fence / Gate	Plastered brick wall			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value		
7.8	Finishes	Internally and externa	Internally and externally cement plastered and painted		
7.7	Articulation	It has features like rounded balconies with grooved bands. The staircase block is highlighted with coloured bands in Art Deco style.			
7.6	Roofing	Flat roof terrace			

Ferriera Mansion



View from the junction



Typical Art Deco highlighted staircase block



View of the corner building



View from Sitladevi Temple Road



Front façade



Cast iron spiral staircase



Rear view



Side profile of the building



Chajjas continue with the rounded balconies





Card No.: G/n-27

Ward (Part): G north-III

CS No.: 687

Plot Area: 131.27 sq.m.

B U Area: 210.032 sq.m.

Date: February, 2005


Record by: Gauri J, Arti S

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Julekha House



1.0	Denomination			
1.1	Name of Premises	Julekha House		
1.2	Earlier Name	Not applicable		
1.3	Built in	Mid 20 th century Extension Date (if any) Not applicable		
2.0	Access			
2.1	Main	Veer Savarkar Marg (Cadelll Road)		
2.2	Subsidiary	Not applicable		
3.0	Ownership Pattern			
3.1	Present	Not available		
3.2	Past	Not available		
3.3	Status	Tenanted		
4.0	Use			
4.1	Present	Residential, Commercial		
4.2	Past	Residential		
4.3	Usage	Regular residential, commercial use		
5.0	Significance & Value Classification	ו		
5.1	Townscape (Natural / Manmade)	Located on the western side of Veer Savarkar Marg which is one of the major North-South arterial roads and also facing the sea.		
5.2	Architectural Description	G + 3 sea facing building stands prominent due to its unique features like decorative projecting balconies. It also has simple rectangular rustication with highly decorative architraves for the windows. The building is located in a comparatively low rise area. It had moulded cornice bands above the windows and decorative motif band runs above it. The balconies projecting on 1 st and 2 nd floor are supported by decorative brackets.		
5.3	Intrinsic	The sea facing building bears highly decorative architraves around the windows.		
5.4	Value Classification	A(arc), F Recommended Grade		
6.0	Topography			
6.1	Floors	G + 3		
7.0	Construction			
7.1	Plinth	30 cms high black basalt stone plinth in coursed ashlar masonry		
7.2	Walls	Brick walls		
7.3	Floor	RCC floor slab		
7.4	Stairs	RCC dog legged staircase with a wooden decorative newel post		
	·			

12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai		
11.0	DP Remarks / Perceived Threats	Affected by road widening on proposed Development Plan. (D.P.)		
10.3	Articulation & Finishes	Painting done on few bays on façade.		
10.2	Structure	No transformation		
10.1	Form	Hoardings added later.		
10.0	Transformation			
9.10	Overall condition	Fair Maintenance level Fair		
9.9	Outbuildings	Fair		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.7	Articulation & Finishes	Fair (Needs maintenance)		
9.6	Roofing	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.4	Stairs	Good (Well maintained)		
9.3	Floor	Fair (No sagging observed)		
9.2	Walls	Fair (Needs plastering and painting)		
9.1	Plinth	Fair (No settlement or cracks observed but still needs maintenance)		
9.0	Condition			
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
8.6	Fire precaution	Not provided		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.4	Water Supply	MCGM		
8.3	Electricity	BEST		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.1	Lighting	Natural and artificial, good natural lighting		
8.0	Services & Utilities			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space, marginal side open space		
7.10	Compound / Fence / Gate	Not provided		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.8	Finishes	Internally and externally cement plastered and painted		
7.7	Articulation	It has simple rectangular rustication with highly decorative architraves for the windows. It had moulded cornice bands above the windows and decorative motif band runs above it. The balconies projecting on 1 st and 2 nd floor are supported by decorative brackets.		
7.6	Roofing	Flat roof terrace		
7.5	Openings	Rectangular openings with wooden frames and glazed shutter and a stained glass weather shade		



View from Veer Savarkar Marg



Decorative floral motifs in stucco work above the architrave



Simple motifs and mouldings on the façade



Projecting balconies on the façade



Sloping roof chajja for the projecting balconies



Common	Ref.	No.
--------	------	-----

Card No.: G/n-28

Ward (Part): G north-III

CS No.: 960

Plot Area: 880.90 sq.m.

B U Area: 727.26 sq.m.

Date: February, 2005


Record by: Gauri J, Uma P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Ref.: Radha Krishna Mandir



1.0	Denomination				
1.1	Name of Premises	Radha Krishna Mandir			
1.2	Earlier Name	Pathare Prabhu Gurudwara			
1.3	Built in	Early 20 th century Extension Date	(if any)	1929	
2.0	Access			•	
2.1	Main	Veer Savarkar Marg (Cadelll Road)			
2.2	Subsidiary	Not applicable			
3.0	Ownership Pattern				
3.1	Present	Rao Saheb Balaram Mothabai Rane	9		
3.2	Past	Gajanan Vinayak Valkar, Anandrao Sadhivrao, Khanderao Krishnanath		Kothare, Balaji Ga	anpat
3.3	Status	Trust			
4.0	Use				
4.1	Present	Religious			
4.2	Past	Temple			
4.3	Usage	Regular Religious use			
5.0	Significance & Value Classification	1			
5.1	Townscape (Natural / Manmade)	Located on a small rectangular plot abutting Veer Savarkar Marg which is one of the major North-South arterial roads.			
5.2	Architectural Description	This temple is located in one of the old neighbourhoods of Mahim. The building is important due to its religious use. It has features like segmental openings on the ground floor and segmental arched openings on the first floor. The parapet wall at the terrace level has decorative balustrade and above it are some decorative idols of the temple.			
5.3	Intrinsic	Building having religious importance).		
5.4	Value Classification	A(cul), B(uu), C(seh)	Recom	nmended Grade	III
6.0	Topography				
6.1	Floors	G + 1			
7.0	Construction				
7.1	Plinth	Plastered stone plinth			
7.2	Walls	Brick walls			
7.3	Floor	Wooden joist flooring			
7.4	Stairs	Straight flight wooden staircase with simple balustrade			
7.5	Openings	Rectangular opening with wooden for	ramed and	d glazed shutters	
7.6	Roofing	Partly sloping mangalore tile roof ar	nd partly fl	at roof terrace	
۸ ما م سا ، م ،	Associates Architects	86		14/	G north

7.7	Articulation	Grooved pilasters at corners, opening have architraves around them terrace parapet wall has decorative idols of Hindu Gods. Ground floor has semi circular arches.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	The internal shrine of the God		
7.10	Compound / Fence / Gate	Not provided		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No marginal side and front open spaces		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement or cracks observed but needs maintanance)		
9.2	Walls	Fair (No dampness or cracks observed)		
9.3	Floor	Fair (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Fair (Leakage observed at a few places)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need no replacement)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	Not transformation		
10.2	Structure	Marble flooring done later on, collapsible gulls added at entrance.		
10.3	Articulation & Finishes	Not transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Notes: Belongs to Pathare Prabhu Charitable Trust. Needs plastering Hindu (Sadhu) idols on verge of chipping. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Radha Krishna Mandir



View from Veer Savarkar Marg



Radha Krishna Mandir



Collapsible grills seen on the ground floor



Decorative concrete jali at the terrace parapet



Double height windows



Decorative idols of God above the terrace parapet level



Common	Ref.	No.:
--------	------	------

Card No.: G/n-29

Ward (Part): G north-I

CS No.: 936

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Gauri J, Uma P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ **Ref.:** Bungalow No. 4



1.0	Denomination					
1.1	Name of Premises	Bungalow No. 4				
1.2	Earlier Name	Zyeed House				
1.3	Built in	1931	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Veer Savarkar Mar	g (Cadelll Road)			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available	Not available			
3.3	Status	Ownership				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification	า				
5.1	Townscape (Natural / Manmade)	Located in a very o Dargah.	ld neighbourhood o	f Mahin	n close to Mahim	1
5.2	Architectural Description	Vernacular style structure having a very interesting roof profile with the central bay projecting out of the structure and the balconies on the either sides of this bay cantilever out in the same profile as that of the bay. The roof appears in two levels one above the other. The bay and the balconies resemble due to the the decorative C.I railing. The central bay also has wooden louvred window at the ground floor level.				
5.3	Intrinsic	Bungalow located i Mohammedian com	n the interiors of Manmunity.	ahim wh	nich belongs to th	ne
5.4	Value Classification	A(arc), A(cul)		Recom	nmended Grade	Ш
6.0	Topography					
6.1	Floors	G + 1				
7.0	Construction	•				
7.1	Plinth	Plastered stone plin	nth			
7.2	Walls	Load bearing brick	wall			
7.3	Floor	Wooden joist flooring	ng			
7.4	Stairs	Straight flight wood	en staircase with si	mple ba	alusters	

12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		
11.0	DP Remarks / Perceived Threats	None		
10.3	Articulation & Finishes	Recently painted.		
10.2	Structure	No transformation		
10.1	Form	No transformation		
10.0	Transformation			
9.10	Overall condition	Good Maintenance level Good		
9.9	Outbuildings	Good		
9.8	Services	Good		
9.7	Articulation & Finishes	Good (Well maintained)		
9.6	Roofing	Good (Leakage observed at a few place)		
9.5	Openings	Good (Wooden members in good condition)		
9.4	Stairs	Good (Wooden members in good condition)		
9.3	Floor	Good (No sagging observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.1	Plinth	Good (No settlement or cracks observed)		
9.0	Condition			
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
8.6	Fire precaution	Not provided		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.4	Water Supply	MCGM		
8.3	Electricity	BEST		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.1	Lighting	Natural and artificial, fair natural lighting		
8.0	Services & Utilities			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal side open space provided		
7.10	Compound / Fence / Gate	Plastered brick wall with decorative cast iron railing		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.8	Finishes	Internally and externally cement plastered and painted		
7.7	Articulation	The balconies have decorative C.I railing. The ground floor openings have wooden louvred windows. The balconies are cantilevered at both the ends of the structures. The central bay has a wooden pinnacle at the roof top.		
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		



Front elevation



A huge commercial banner stands at the left side of the building





Decorative entrance cast iron Gate



Cantilevered balcony with a sloping roof



Compound wall with decorative cast iron railing



Card No.: G/n-30

Ward (Part): G north-I

CS No.: 738

Plot Area: 5396.00 sq.m.

B U Area: 1939.38 sq.m.

Date: February, 2005


Record by: Gauri J, Ojas P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Rogay Cottage



1.0	Denomination					
1.1	Name of Premises	Rogay Cottage				
1.2	Earlier Name	Not applicable				
1.3	Built in	1938	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Balamiya Lane				
2.2	Subsidiary	Veer Savarkar Mar	g (Cadelll Road)			
3.0	Ownership Pattern					
3.1	Present	Municipal Corporation of City of Bombay				
3.2	Past	Municipal Corporat	ion of City of Bomb	oay		
3.3	Status	Not available				
4.0	Use					
4.1	Present	Residential, Commercial				
4.2	Past	Residential, Commercial				
4.3	Usage	Regular residential and commercial use				
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	Located on a corne	er plot opposite Ma	him Dar	gah.	
5.2	Architectural Description	This building has Neo-classical features on the façade. The façade has segmental arched windows with moulded architraves and decorative key stones. The central bay of the façade has a semicular pediment on the first floor and a triangular pediment on the first floor. The parapet wall of the building has decorative balustrade in a continuous band with simple pilasters breaking the monotony. Cornice bands are seen at all floor levels. Long and short work seen at the corner edges of the building.				
5.3	Intrinsic	Corner building loc Mahim near Mahim		of old ne	eighbourhood of	
5.4	Value Classification	A(arc), B(des), I(sc	e), F	Recom	nmended Grade	III
6.0						
6.1	Topography					
	Topography Floors	G + 1				
7.0		G+1				
	Floors	G + 1 Stone plinth in cour	rsed ashlar mason	ry		
7.0	Floors Construction		rsed ashlar mason	ry		
7.0 7.1	Floors Construction Plinth	Stone plinth in cour	rsed ashlar mason	ry		

7.5	Openings	Segmental arched operations	enings with wooden fra	mes and glazed	
7.6	Roofing	Pitched roof with Man	galore tiles		
7.7	Articulation	The façade has segmental arched windows with moulded architraves and deorative key stones. The central bay of the façade has a semicular pediment on the first floor and a triangular pedimen on the first floor. The parapet wall of the building has decorative balustrade in a continuous band with simple pilasters breaking the monotony. Cornice bands are seen at all floor levels. Long and short work seen at the corner edges of the building.			
7.8	Finishes	Internally and externa	lly cement plastered an	nd painted.	
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Not provided			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No marginal and side open spaces provided			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, fair natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Air-conditioning window units at some places			
9.0	Condition				
9.1	Plinth	Good (No settlement	or cracks observed)		
9.2	Walls	Good (No dampness	or cracks observed)		
9.3	Floor	Good (No sagging obs	served)		
9.4	Stairs	Good (Wooden memb	pers in good condition)		
9.5	Openings	Good (Wooden memb	pers in good condition)		
9.6	Roofing	Good (No leakage obs	served)		
9.7	Articulation & Finishes	Good (Well maintaine	d)		
9.8	Services	Good (Drainage pipes	need no replacement)		
9.9	Outbuildings	Good		_	
9.10	Overall condition	Good	Maintenance level	Good	
10.0	Transformation				
10.1	Form	Commercial signboard	d on ground floor.		
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	Plot under Residentia	Zone on proposed De	velopment Plan. (D.P.)	
12.0	Additional Notes / References / Documents Available	Documents: C.S. shee	ets, D.P. Sheets, Eiche	r City Maps – Mumbai	

Rogay Cottage



View from Veer Savarkar Marg



Neo-classical details on the façade



Windows have decorative architraves with key stones



View of the whole façade





Card No.: G/n-31a

Ward (Part): G north-I

CS No.: 1080, 1083

Plot Area: 4411.41 sq.m

B U Area: 6727.26 sq.m

Date: February, 2005

Record by: Gauri J, Ojas P


Review by: Neera Adarkar

Internal: As Above

External: As Above

Photo Photography denied

Ref.:



1.0	Denomination					
1.1	Name of Premises	Maqdum Mohamma	ad Mahimi Dargah	(Shrine))	
1.2	Earlier Name	Not applicable				
1.3	Built in	1431	Extension Date (if	any)	1970	
2.0	Access					
2.1	Main	Veer Savarkar Mar	g (Cadell Road)			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Suleman Haji Ali M Noorali Mohommad of Haji Kasim Agbo	d Ahmed, Hussain A			
3.2	Past	Syed Abdul Kadri Al Edroos, Trustees of Pir Magalum Saheb Charitable Trust, Dawood Haji Ali Mohommad				
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Shrine				
4.2	Past	Religious				
4.3	Usage	Regular religious us	se			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	A landmark monum shore on west of Ve North-South arteria	eer Savarkar Marg			
5.2	Architectural Description	Internally there two tombs are plain with retained but have u plastering and mair	n no articulation. Th ndergone several c	ne shap	es of these tomb	s are
5.3	Intrinsic	Originally built in 14 th century, this Dargah is one of the oldest structures in Mumbai and is of high cultural and historical importance. The structure is however modified many times in the last 4 centuries and is closely surrounded with a dense settlement evolved over years. For these reasons the core shrine is graded I and the surrounding buildings are graded II A instead of I.				
5.4	Value Classification	A(cul), A(his), B(pe	r)	Recom	mended Grade	I
6.0	Topography					
6.1	Floors	Ground storeyed				
7.0	Construction					
7.1	Plinth	Plastered stone plir	nth			
7.2	Walls	Not applicable				

7.3	Floor	Not applicable		
7.4	Stairs	Not applicable		
7.5	Openings	Not applicable		
7.6	Roofing	Not applicable		
7.7	Articulation	The tombs and the shrine are relatively plain and bear no articulation.		
7.8	Finishes	Externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Tombs of the Saint and his mother		
7.10	Compound / Fence / Gate	Not applicable		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	None		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (Recently plastered showing no cracks)		
9.2	Walls	Not applicable		
9.3	Floor	Not applicable		
9.4	Stairs	Access denied		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Not applicable		
9.8	Services	Good (Well maintained)		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	Repaired and enlarged in 1674 and 1748. In 1952, 1 st floor was added and in 1970, was extended up to 3 rd floor.		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	History: Ali Bin Ahmed, later known as Maqdum Mohammed Mahimi, was born on the island of Mahim in the 14 th Century. It is said that Ali Bin Ahmed received Sainthood because of his mother. The Saint lived up on a small islet at Mahim and his fame spread during his lifetime. After his death the shrine was erected around his tomb to honour him. His mother's tomb lies just besides his. The shape of the shrine has not altered much but has undergone several changes. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai		



Card No.: G/n-31b

Ward (Part): G north-I

CS No.: 1068

Plot Area: Not available

B U Area: Not available

Date: February, 2005

Record by: GauriJ, Ojas P


Review by: Neera Adarkar

Internal: As Above

External: As Above

Photo T-IV-Gn:\Ward Gn\
Ref.: Maqdum Mohammad

Maqdum Mohammad Mahimi Dargah



1.0	Denomination					
1.1	Name of Premises	Maqdum Mohamm	ad Mahimi Dargah	(Comple	ex)	
1.2	Earlier Name	Not applicable				
1.3	Built in	1431	Extension Date (i	if any)	1970	
2.0	Access					
2.1	Main	Veer Savarkar Mar	g (Cadell Road)			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern	•				
3.1	Present	Suleman Haji Ali M Noorali Mohommad of Haji Kasim Agbo	d Ahmed, Hussain			
3.2	Past	Syed Abdul Kadri Al Edroos, Trustees of Pir Magalum Saheb Charitable Trust, Dawood Haji Ali Mohommad				
3.3	Status	Tenanted				
4.0	Use					
4.1	Present	Dargah				
4.2	Past	Religious				
4.3	Usage	Regular Religious	ıse			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	A landmark monum shore on west of Von North-South arteria	eer Savarkar Marg			
5.2	Architectural Description	Entrance Gate has identity. It has four dargah is topped w with small chhatris. his mother. These	brick domes with c ith a huge dome a Internally there tw	decorativ nd has for o tombs	re pinnacles. The our minars cappe Saint Maqdum a	main ed
5.3	Intrinsic	Originally built in 14 th century, this Dargah is one of the oldest structures in Mumbai and is of high cultural and historical importance. The structure is however modified many times in the last 4 centuries and is closely surrounded with a dense settlements evolved over years. For these reasons the core shrine is graded I and the surrounding buildings are graded IIA instead of I.				
5.4	Value Classification	A(arc), A(cul), A(his	s), B(per)	Recom	mended Grade	II A
6.0	Topography					
6.1	Floors	G + 3				
7.0	Construction					
7.1	Plinth	Plastered stone plin	nth			

Walls	Brick Masonry walls		
Floor	RCC floor slab		
Stairs	Access denied		
Openings	Semicircular and Moor glazed shutters	rish arched openings w	rith wooden frames and
Roofing	Brick dome		
Articulation		rance gate with decora ntral dome is topped by	tive stucco work on the y metal pinnacle.
Finishes	Internally and external	ly cement plastered an	d painted.
Interiors (Movable & Immovable)	Tombs of the Saint and	d his mother	
0 Compound / Fence / Gate	Plastered brick compo	und wall	
1 Curtilage / Unbuilt Space / Out Buildings / Landscape	None		
Services & Utilities			
Lighting	Natural and artificial, g	ood natural lighting	
Ventilation	Natural and artificial, g	ood natural ventilation	
Electricity	BEST		
Water Supply	MCGM		
Drainage (Plumbing and Sanitation)	MCGM		
Fire precaution	Not provided		
Other (HVAC / BMS / Security Systems)	Not provided		
Condition			
Plinth	Good (Recently plaste	red showing no cracks)
Walls	Good (No leakage or o	cracks)	
Floor	Good (No deflection in	floor)	
Stairs	Access denied		
Openings	Good (Wooden memb	ers in good condition)	
Roofing	Good (No leakage obs	served)	
Articulation & Finishes	Good (Well maintained	d)	
Services	Good (Well maintained	d)	
Outbuildings	Good		
0 Overall condition	Good	Maintenance level	Good
0 Transformation			
1 Form	No transformation		
2 Structure	Repaired and enlarged added and in 1970, wa	d in 1674 and 1748. In as extended up to 3 rd flo	1952, 1 st floor was oor.
3 Articulation & Finishes	No transformation		
0 DP Remarks / Perceived Threats	None		
Additional Notes / References / Documents Available	History: Ali Bin Ahmed, later known as Maqdum Mohammed Mahimi, was born on the island of Mahim in the 14 th Century. It is said that Ali Bin Ahmed received Sainthood because of his mother. The Saint lived up on a small islet at Mahim and his fame spread during his lifetime. After his death the shrine was erected around his tomb to honour him. His mother's tomb lies just besides his. The shape of the shrine has not altered much but has undergone several changes.		
		shape of the shrine ha several changes.	shape of the shrine has not altered much but

Maqdum Mohammad Mahimi Dargah




View of the entrance gate



Main dome of the dargah



Shop line along the road



View of the internal façade



Four chattris above the gate



Maqdum Mohammad Mahimi





Decorative mouldings around the entrance arch to the Dargah




Common Ref. No.:	
Card No.: G/n-32	>1
Ward (Part): G north-III	-
CS No. : 972	F
Plot Area: 648.28 sq.m.	

B U Area: 1090.50 sq.m. Date: February, 2005 Record by: Gauri J, Arti S

Review by: Neera Adarkar

Internal: As above External: As above

Photo T-IV-Gn:\Ward Gn\H. H. Ref.: Khoja Aga Khan Jamat Khana




1.0	Denomination					
1.1	Name of Premises	H. H. Khoja Aga Kha	n Jamat Khana			
1.2	Earlier Name	Not applicable				
1.3	Built in	Mid 20 th century	Extension Date (if	any) Not ap	plicable	
2.0	Access			·		
2.1	Main	Sant Gadge Maharaj	Marg			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Trust	Trust			
4.0	Use					
4.1	Present	Religious, Residential				
4.2	Past	Religious, Residential				
4.3	Usage	Regular residential a	Regular residential as well as religious use			
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Located along the corner following curve profile at junction with shops on frontage.				
5.2	Architectural Description	Vernacular style building on corner following a curve of the road profile though appears to be a non ornamental and plain façade from the road side, internally it has a paved court with balconies overlooking it. The balconies and entrance area have carved CI grills. Balconies have been supported on CI pillars with floral capitals. Shrine is located in South West corner in the building court.				
5.3	Intrinsic	Corner building havir	ng religious import	ance.		
5.4	Value Classification	B(per), C(seh), D(bio), E	Recommended	d Grade	III
6.0	Topography					•
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	Black Basalt stone p	linth			
7.2	Walls	Load bearing brick w	all			
7.3	Floor	Jack arch flooring				
7.4	Stairs	Straight flight woode	n staircase			
7.5	Openings	Rectangular wooden	openings with full	y glazed shutte	ers	
7.6	Roofing	Flat roof terrace				
Adarka	r Associates, Architects	100			Ward	G nortl

12.0	Additional Notes / References / Documents Available	Notes: Tree growth on façade, structure damaged due to lines of water from pipes. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		
11.0	DP Remarks / Perceived Threats	Marked by Town Plan (D.P.)	ning Scheme on propo	sed Development Plan.
10.3	Articulation & Finishes	No transformation		
10.2	Structure	No transformation		
10.1	Form	Box type signboards for added later.	or shops, chajjas on M	S brackets, box grills
10.0	Transformation			
9.10	Overall condition	Fair	Maintenance level	Fair
9.9	Outbuildings	Fair		
9.8	Services	Poor (Drainage pipes	need maintenance)	
9.7	Articulation & Finishes	Fair (Needs maintana	nce)	
9.6	Roofing	Fair (Leakage observe	ed at a few places)	
9.5	Openings	Fair (Wooden membe	rs in good condition)	
9.4	Stairs	Fair (Wooden membe	rs in good condition)	
9.3	Floor	Fair (No sagging obse	rved but needs mainta	nance)
9.2	Walls	Fair (No dampness or	cracks observed)	
9.1	Plinth	Fair (No settlement or	cracks observed but n	eeds maintanance)
9.0	Condition			
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
8.6	Fire precaution	Not provided		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.4	Water Supply	MCGM		
8.3	Electricity	BEST		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.1	Lighting	Natural and artificial, g	good natural lighting	
8.0	Services & Utilities			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Central paved open sp	pace used as a gatheri	ng space for worship
7.10	Compound / Fence / Gate	Not provided		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value	
7.8	Finishes	Internally and external	ly cement plastered ar	nd painted
7.7	Articulation	Central courtyard with CI columns with floral capitals, Moorish ar on windows on first floor, cornice bands at first floor level.		

H. H. Khoja Aga Khan Jamat Khana



External façade



Mughal arch in stucco work for the entrance



Internal shrine of the premises



Internal view



Card No.: G/n-33

Ward (Part): G north-III

CS No.: F.P 398

Plot Area: 450.67 sq.m.

B U Area: 1118.16 sq.m.

Date: February, 2005


Record by: Gauri J, Uma P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ **Ref.:** Bungalow No. 3



1						
1.0	Denomination					
1.1	Name of Premises	Bungalow No. 3				
1.2	Earlier Name	Not applicable				
1.3	Built in	Late 19 th century	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	D. S. Raje Marg	D. S. Raje Marg			
2.2	Subsidiary	Bhagoji Keer Marg	Bhagoji Keer Marg			
3.0	Ownership Pattern					
3.1	Present	Andrian Joseph He	Andrian Joseph Hengriqes, Lewis Family Trust, A.P Lewis Trust			st
3.2	Past	Andrian Joseph He	Andrian Joseph Hengriqes, Lewis Family Trust, A.P Lewis Trust			st
3.3	Status	Trust	Trust			
4.0	Use					
4.1	Present	Religious, Residen	tial			
4.2	Past	Religious, Residential				
4.3	Usage	Regular residential use				
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Located on a sharp triangular plot off Lady Jamshetji Marg which is one of the major North-South arterial roads.				
5.2	Architectural Description	G + 2 Vernacular style modest bungalow which represents a typology of bungalows seen in the older neighbourhood between Dadar to Bandra mostly belonging to the Catholic or East Indian Christian community. The most interesting feature of this house is the balcony supported by the slender timber posts covered by a well balanced sloping roof in an interesting profile with a decorative fascia and finished with Mangalore tiles. The intricate C.I. railing of the balcony gives the entire structure an exquisite character. Remaining part of the building has a plain façade in sharp contrast to the balcony structure.				
5.3	Intrinsic	This bungalow reprinciple of the control of the con	ween Dadar to Bar	ndra mo		
5.4	Value Classification	B(per), C(seh), E		Recom	nmended Grade	III
6.0	Topography			<u>'</u>		
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	Black Basalt stone	plinth in coursed a	shlar ma	asonry	
7.2	Walls	Load bearing brick walls				
7.3	Floor	Wooden joist flooring				
	1	1				

12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		
11.0	DP Remarks / Perceived Threats	Located in a General Residential zone on proposed Development Plan. (D.P.)		
10.3	Articulation & Finishes	No transformation		
10.2	Structure	No transformation		
10.1	Form	The flooring has changed and added later. The area below the balcony is enclosed subsequently.		
10.0	Transformation			
9.10	Overall condition	Fair-Poor	Maintenance level	Fair
9.9	Outbuildings	Fair		
9.8	Services	Fair (Drainage pipes need to be replaced)		
9.7	Articulation & Finishes	Fair (Needs maintenance)		
9.6	Roofing	Fair (No leakage observed)		
9.5	Openings	Fair (Wooden members in good condition)		
9.4	Stairs	Fair (Wooden membe	rs need maintenance)	
9.3	Floor	Fair (No sagging observed)		
9.2	Walls	Fair (Needs plastering and painting)		
9.1	Plinth	Fair (No settlement of the plinth observed but needs maintenance)		
9.0	Condition			
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
8.6	Fire precaution	Not provided		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.4	Water Supply	MCGM		
8.3	Electricity	BEST		
8.2	Ventilation	Natural and artificial, g	good natural ventilation	
8.1	Lighting	Natural and artificial, f	air natural lighting	
8.0	Services & Utilities			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	The front open space has been landscaped and there are marginal side open spaces provided		and there are marginal
7.10	Compound / Fence / Gate	Plastered brick wall		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value	
7.8	Finishes	Rectangular wooden openings with wooden frames and glazed shutters		rames and glazed
7.7	Articulation	Straight flight wooden staircase with simple wooden balustrade		vooden balustrade
7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		n trusses
7.5	Openings	Rectangular opening wooden frames and glazed shutter		zed shutter
7.4	Stairs	Straight flight wooden	staircase with plain rail	ling

Bungalow No. 3



View from D.S Raje Marg





Pitched roof for the projecting balcony



Decorative cast iron railing



Internal straight flight staircase



Wooden joist flooring









Wooden king post truss

Right side elevation and Left side elevation not seen due to proximity of adjoining buildings



Cal	mm	n	Ref.	No	
COL		IOH	Rei.	INO	-:

Card No.: G/n-34

Ward (Part): G north-I

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005

Record by: Gauri J, Uma P


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Belle

Ref.: View



1.0	Denomination				
1.1	Name of Premises	Belle View			
1.2	Earlier Name	Not applicable			
1.3	Built in	Mid 20 th century Extension D	Date (if any)	Not applicable	
2.0	Access			•	
2.1	Main	Lady Jamshetji Marg			
2.2	Subsidiary	Balamiya Lane			
3.0	Ownership Pattern				
3.1	Present	Not available	Not available		
3.2	Past	Not available			
3.3	Status	Tenanted			
4.0	Use				
4.1	Present	Residential			
4.2	Past	Residential			
4.3	Usage	Regular residential use			
5.0	Significance & Value Classificatio	icance & Value Classification			
5.1	Townscape (Natural / Manmade)	Located on a plot facing Lady Jamshetji Marg which is one of the major North-South arterial roads.			
5.2	Architectural Description	G+ 3 structures with corners of building the form of bay windows. Staircase block has small sloping roof at the top, small rectangular painted motifs appear at top, bottom and either sides of the windows. Coloured projecting bands seen at every floor and lintel level.			
5.3	Intrinsic	This is one of the many Art Deco	o buildings or	the major road i	n
5.4	Value Classification	A(arc), I(sce)	Recon	nmended Grade	Ш
6.0	Topography		·		
6.1	Floors	G+3			
7.0	Construction				
7.1	Plinth	30 cms high plastered stone plin	nth		
7.2	Walls	23 cms thick brick wall			
7.3	Floor	RCC floor slab			
7.4	Stairs	Dog legged wooden staircase			
7.5	Openings	Rectangular openings with wooden frames and glazed shutter and stained glass ventilator			
7.6	Roofing	Flat roof terrace			
Adarka	r Associates. Architects	106		Ward	G north

7.7	Articulation	Small rectangular painted motifs appear at top, bottom and either side of the windows. Coloured projecting bands seen at every floor and lintel level.		
7.8	Finishes	Externally sand faced finish plaster and internally plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Side compound wall in random rubble masonry		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space, marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement or cracks observed)		
9.2	Walls	Fair (No dampness or cracks observed)		
9.3	Floor	Fair (No sagging observed but needs maintanance)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition but glazings need to be replaced)		
9.6	Roofing	Fair (No leakage observed Mangalore tiles need to be replaced)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai		

Belle View



Front elevation



Front façade



Rectangular windows







View from Lady Jamshetji Marg



Simple motifs on the façade



Triangular element above the entrance





Card No.: G/n-35

Ward (Part): G north-I

CS No.: F.P 614

Plot Area: 428.65 sq.m.

B U Area: 720.00 sq.m.

Date: February, 2005


Record by: Gauri J, Tanvi O

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Hearts Ease



1.0	Denomination					
1.1	Name of Premises	Hearts Ease				
1.2	Earlier Name	Not applicable				
1.3	Built in	1925	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Lady Jamshetji Mar	rg			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Milton Lobo, Raymond Lobo, Austen Lobo, Dr. Max Saldhana				
3.2	Past	Milton Lobo, Raymo	ond Lobo, Austen L	obo, Dr	. Max Saldhana	
3.3	Status	Ownership				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located in the older Marg near St. Mich		of Mahin	n on Lady Jamsł	netji
5.2	Architectural Description	This G + 1 bungalow forms a part of Catholic neighbourhood in Mahim in the early 20 th century. The bungalow follows a particular style of that period in relation to the scale and hence follows the typology of all the similar bungalows of the neighbourhood. The roof profile and the wooden balcony separates it from the adjoining buildings on Lady Jamshetji Marg.				
5.3	Intrinsic	One of the few bun- neighbourhood of N		nains in	the oldest	
5.4	Value Classification	A(arc), B(per)		Recom	mended Grade	Ш
6.0	Topography					
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	90 cms high stone	plinth in ashlar mas	sonry		
7.2	Walls	23 cms thick load b	earing brick walls			
7.3	Floor	Wooden joist flooring	ng			
7.4	Stairs	Dog legged wooder	n staircase with sim	ple woo	oden balustrade	
7.5	Openings	Rectangular openin	ngs in wooden fram	es and	stained glass wii	ndow

7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	It has features like decorative stained glass window panes and decorative motifs on the façade. The projecting balcony is supported by decorative bracketed columns.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Brick compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space. Marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Fair (Wooden members in good condition)		
9.5	Openings	Fair (Wooden members in good condition)		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Fair (Needs maintanance)		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumba		

Hearts Ease



View from Lady Jamshetji Marg



Prominent wooden weather sheds in stained glass





The balcony requires maintenance

Left side elevation not seen due to proximity of adjoining buildings



View obstructed by vegetation



Floral motifs on the gable with the name in stucco work



The maroon colour of the façade highlights the structure



Decorative cast iron brackets



Card No.: G/n-36

Ward (Part): G north-I

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: January, 2005

Record by: Gauri J, Tanvi O


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\

Ref.: Ramos



1.0	Denomination					
1.1	Name of Premises	Ramos				
1.2	Earlier Name	Not applicable				
1.3	Built in	1745	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Off Lady Jamshedji	Cross Road No. 1			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available	Not available			
3.3	Status	Ownership				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Residential				
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located in the inter	iors of Mahim near	r Holy C	ross Chapel.	
5.2	Architectural Description	This Vernacular style small bungalow is one of the oldest bungalows of the neighbourhood. It is a very simple structure in terms of articulation. The façade bears no ornamentation. It has simple sloping roof in Mangalore tiles supported by wooden trusses. It also has a verandah on the external side.				
5.3	Intrinsic	Important building i neighbourhoods of		and loca	ation in the oldes	st
5.4	Value Classification	B(per)		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	Ground floor				
7.0	Construction					
7.1	Plinth	Plastered stone plir	nth			
7.2	Walls	Brick masonry walls	5			
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				
7.5	Openings	Rectangular openir	ngs with wooden fra	ames ar	nd glazed shutter	
7.6	Roofing	Simple sloping roof trusses	with Mangalore tile	es supp	orted by wooder	1

12.0	Additional Notes / References /	None Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		
11.0	DP Remarks / Perceived Threats			
10.2	Articulation & Finishes	No transformation		
10.1	Structure	No transformation		
10.1	Form	No transformation		
10.0	Transformation	1. 55.	atoriarioo iovoi	1. 551
9.10	Overall condition	Poor	Maintenance level	Poor
9.8	Outbuildings	Fair	uio iiiiaDilaliUII)	
9.7	Services	Poor (Stopped due to	the inhabitation)	
9.6	Roofing Articulation & Finishes	Fair (Leakage observe	eu at iew piaces)	
9.5	Openings	Fair (Wooden membe	· · · · · · · · · · · · · · · · · · ·	
9.4	Stairs	Not applicable	ro in good condition)	
9.3	Floor	Not applicable		
9.2	Walls	Fair (Needs plastering	g and painting)	
9.1	Plinth	,	cracks observed but n	eeds maintanance)
9.0	Condition	I		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
8.6	Fire precaution	Not provided		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.4	Water Supply	MCGM		
8.3	Electricity	BEST		
8.2	Ventilation	Natural and artificial, f	air natural ventilation	
8.1	Lighting	Natural and artificial, f	air natural lighting	
8.0	Services & Utilities			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	None		
7.10	Compound / Fence / Gate	It has an M.S entrance gate		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritag	ge value	
7.8	Finishes	Internally and externa	lly plastered and painte	ed
7.7	Articulation	The façade bears no ornamentation Internally and externally plastered and painted		

Ramos



View of the entire bungalow



Date encrypted on the wall



Verandah on the external side of the bungalow



Card No.: G/n-37

Ward (Part): G north-I

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005


Record by: Gauri J, Uma P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ **Ref.:** Silvan Mansion



1.0	Denomination					
1.1	Name of Premises	Silvan Mansion				
1.2	Earlier Name	Not applicable				
1.3	Built in	1934	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Lady Jamshedji Cro	oss Road No. 2			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available	Not available			
3.3	Status	Tenanted				
4.0	Jse					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification	l				
5.1	Townscape (Natural / Manmade)	Located on a plot of streetscape.	ff Lady Jamshetji N	larg and	d responds to the)
5.2	Architectural Description	It is a G + 2 sprawling structure. The façade is marked with three projecting bays rising higher than the remaining façade sandwitched between them. The recessed portions are the balconies notionally divided in to three parts with vertical twin members. The parapet of the balconies is composed of intricate concrete grill in criss cross pattern. The balconies are provided with stained glass ventilators. The projecting bays have sloping roofs that rise above the roof of the remaining structure.				
5.3	Intrinsic	This sprawling struc	cture forms a part o	of old Ma	ahim neighbourh	ood.
5.4	Value Classification	A(cul), A(arc)		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 2				
7.0	Construction					
7.1	Plinth	60 cms high plaster	ed stone plinth			
7.2	Walls	15 cms thick brick v	valls			
7.3	Floor	Wooden joist flooring	ng			
7.4	Stairs	Straight flight wood	en staircase			
7.5	Openings	Rectangular window	ws with teak wood t	frames	and glazed shutt	ers

7.6	Roofing	Sloping roof with Mangalore tiles and wooden trusses		
7.7	Articulation	The façade is marked with three projecting bays rising higher than the remaining façade sandwitched between them. The recessed portions are the balconies notionally divided in to three parts with vertical twin members. The parapet of the balconies is composed of intricate concrete grill in criss cross pattern.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Plastered brick wall with piers		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal front open space and landscaped side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
8.7	Other (HVAC / BMS / Security Systems)	Window air-conditioning units added at some places		
9.0	Condition			
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good (No sagging observed)		
9.4	Stairs	Good (Wooden members in good condition)		
9.5	Openings	Good (Wooden members in good condition)		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Good (Well maintained)		
9.8	Services	Good (Drainage pipes need no replacement)		
9.9	Outbuildings	Good		
9.10	Overall condition	Good Maintenance level Good		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
	DP Remarks / Perceived Threats	None		
11.0				

Silvan Mansion



View from Lady Jamshedji Cross Road No. 2



View of the façade



View of the side façade



Criss cross concrete jali at the parapet





Right side elevation not seen due to proximity of adjoining buildings



Common	Ref. No.
--------	----------

Card No.: G/n-38

Ward (Part): G north-I

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: February, 2005

Record by: Gauri J, Swapnil B


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Holy

Ref.: Cross Chapel



1.0	Denomination					
1.1	Name of Premises	Holy Cross Chapel				
1.2	Earlier Name	Not applicable				
1.3	Built in	1934	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Lady Jamshedji Cr	oss Road No. 1			
2.2	Subsidiary	St. Michael's Scho	St. Michael's School Road			
3.0	Ownership Pattern					
3.1	Present	Not available				
3.2	Past	Not available				
3.3	Status	Trust				
4.0	Use					
4.1	Present	Religious				
4.2	Past	Religious				
4.3	Usage	Regular religious u	se			
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)		which leads to an ich is one of the ma			
5.2	Architectural Description	ornamentation. Ho the top on which the	is a modest structo wever it has a care e cross is supporte opening. It has an ic	fully arti d. The p	culated wall profi olain façade is m	ile on arked
5.3	Intrinsic	Situated on one of	the oldest catholic	neighbo	ourhoods of Mahi	m.
5.4	Value Classification	A(cul), B(per), C(se	eh), A(his)	Recom	mended Grade	III
6.0	Topography					
6.1	Floors	Ground floor				
7.0	Construction					
7.1	Plinth	30 cms high plastered stone plinth				
7.2	Walls	30 cms thick brick wall				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable	Not applicable			
7.5	Openings	Semi circular arche	ed opening with C.I	grill		
7.6	Roofing	Flat roof terrace				


7.7	Articulation				
7.8	Finishes	Internally and externa	lly cement plastered a	nd painted	
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage	ge value		
7.10	Compound / Fence / Gate	Brick compound wall			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space, marginal side open space			
8.0	Services & Utilities				
8.1	Lighting	Good natural lighting			
8.2	Ventilation	Not applicable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not provided			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Fair (No settlement or	cracks observed)		
9.2	Walls	Fair (Needs plastering	and painting)		
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Fair			
9.6	Roofing	Fair (No leakage obse	erved)		
9.7	Articulation & Finishes	Fair			
9.8	Services	Not applicable			
9.9	Outbuildings	Fair			
9.10	Overall condition	Fair	Maintenance level	Fair	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP Remarks / Perceived Threats	None			
12.0	Additional Notes / References / Documents Available	Documents: C.S. shee	ets, D.P. Sheets, Eiche	er City Maps - Mumbai	

Holy Cross Chapel



View from Lady Jamshedji Cross Road No. 1





Plaque



Card No.: G/n-39

Ward (Part): G north-I

CS No.: F.P 621

Plot Area: 5212.20 sq.m.

B U Area: 10188.20 sq.m.

Date: February, 2005


Record by: Gauri J, Uma P

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Nitya Ref.: Sahay Mata Niwas



1.0	Denomination					
1.1	Name of Premises	Nitya Sahay Mata N	Niwas			
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 th century	Extension Date (if	f any)	Not applicable	
2.0	Access					
2.1	Main	St. Michael School	Marg			
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	The Vicar & Warde	ns of the Church of	f St Mich	nael	
3.2	Past	The Vicar & Wardens of the Church of St Michael				
3.3	Status	Ownership				
4.0	Use					
4.1	Present	Residential				
4.2	Past	Residential				
4.3	Usage	Regular residential	use			
5.0	Significance & Value Classification					
5.1	Townscape (Natural / Manmade)	Low rise precinct si neighbourhood of N		mshetji N	Marg in old	
5.2	Architectural Description	This is a modest Vernacular precinct with low roof profiles. These structures in the precinct bear no ornamentation on the façade but its mere exsistance give the glimpses of the old neighbourhood of Mahim. Most of these houses have an external straight flight staircase covered with a sloping Mangalore tile roof.				
5.3	Intrinsic	One of the oldest C identity.	atholic neighbourh	oods of	Mahim still retai	ns its
5.4	Value Classification	G(grp)		Recom	mended Grade	III
6.0	Topography					
6.1	Floors	G + 1				
7.0	Construction					
7.1	Plinth	45 cms high stone	plinth in coursed as	shlar ma	sonry	
7.2	Walls	15 cms thick brick v	wall			
7.3	Floor	Wooden joist flooring	ng with brick bat co	ba		
7.4	Stairs	Straight flight wood	en staircase			
7.5	Openings	Rectangular openin	ngs with aluminium	framed	glazed window	
7.6	Roofing	Slopping roof with I	Mangalore tiles and	d woode	n trusses	

7.8 7.9 7.10	Articulation Finishes Interiors (Movable & Immovable) Compound / Fence / Gate Curtilage / Unbuilt Space / Out	,	lly cement plastered an	d painted
7.9 7.10	Interiors (Movable & Immovable) Compound / Fence / Gate	,	•	d painted
7.10	Compound / Fence / Gate	Interiors, not of heritag		
	·	Interiors, not of heritage value		
7.11	Curtilage / Unbuilt Space / Out	Plastered brick compo	pund	
	Buildings / Landscape	Marginal side open space		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, f	air natural ventilation	
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not provided		
	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (Cracks seen at few places)		
9.2	Walls	Fair (Needs plastering	and painting)	
9.3	Floor	Fair (No sagging obse	erved but needs maintar	nance)
9.4	Stairs	Fair (Wooden membe	rs in good condition)	
9.5	Openings	Fair (Needs maintana	nce)	
9.6	Roofing	Fair (Leakages observ	ved at few places)	
9.7	Articulation & Finishes	Fair		
9.8	Services	Fair (Drainage pipes r	need maintenance)	
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair	Maintenance level	Fair
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	None		
	Additional Notes / References / Documents Available	Documents: C.S. shee	ets, D.P. Sheets, Eicher	City Maps - Mumbai

Nitya Sahay Mata Niwas



View from St.Michael's School Marg







Entrance gate



Plain façade



Overhead water tank



External staircase covered with a roof



Rear façade





Card No.: G/n-40

Ward (Part): G north-I

CS No.: 4325 / 20

Plot Area: Not available

B U Area: Not applicable

Date: February, 2005

Record by: Gauri J, Uma P


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\St.Ref.: Michael's Church

Cemetery



		Genetary		
1.0	Denomination			
1.1	Name of Premises	St. Michael's Church Cemetery		
1.2	Earlier Name	Not applicable		
1.3	Built in	1925 Extension Date (if any) Not applicable		
2.0	Access			
2.1	Main	Lady Jamshetji Marg		
2.2	Subsidiary	Mori Road		
3.0	Ownership Pattern			
3.1	Present	Not available		
3.2	Past	Not available		
3.3	Status	Trust		
4.0	Use			
4.1	Present	Religious		
4.2	Past	Religious		
4.3	Usage	Regular religious use		
5.0	Significance & Value Classificati	on		
5.1	Townscape (Natural / Manmade)	Located on a corner plot at a prominent junction of Lady Jamshetji Marg and Mori Road which is just behind the popular St. Michael's Church which is used by majority of Catholic population in Mahim.		
5.2	Architectural Description	It is one of the oldest part of St. Michael's Church earlier known as "Novina" of the earlier 20 th century used by the Catholic population residing in oldest parts of Mahim. The cremation ground existed even before the Novina wooden staircase built. The ground is enclosed with a brick compound wall which flushes with the North façade of the Church.		
5.3	Intrinsic	Locted in old parts of Mahim in a neighbourhood belonging to the Catholic population.		
5.4	Value Classification	A(his), A(cul), B(per), C(seh), E Recommended Grade II A		
6.0	Topography			
6.1	Floors	Ground floor		
7.0	Construction			
7.1	Plinth	Not applicable		
7.2	Walls	Not applicable		
7.3	Floor	Not applicable		
7.4	Stairs	Not applicable		

12.0	Additional Notes / References / Documents Available	Documents: C.S. she	ets, D.P. Sheets, Eiche	er City Maps - Mumbai	
11.0	DP Remarks / Perceived Threats	Plot is demarcated by Plan. (D.P.)	y Secondary school on	proposed Development	
10.3	Articulation & Finishes	No transformation			
10.2	Structure	No transformation			
10.1	Form	No transformation			
10.0	Transformation				
9.10	Overall condition	Good	Maintenance level	Good	
9.9	Outbuildings	Good			
9.8	Services	Good			
9.7	Articulation & Finishes	Not applicable			
9.6	Roofing	Not applicable			
9.5	Openings	Not applicable			
9.4	Stairs	Not applicable			
9.3	Floor	Not applicable			
9.2	Walls	Not applicable			
9.1	Plinth	Not applicable			
9.0	Condition				
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
8.6	Fire precaution	Not provided			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.4	Water Supply	MCGM			
8.3	Electricity	BEST			
8.2	Ventilation	Natural and artificial,	good natural ventilatior	າ	
8.1	Lighting	Natural and artificial,	good natural lighting		
8.0	Services & Utilities				
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	No front open space.	No front open space. Large side open space with landscaping.		
7.10	Compound / Fence / Gate	RCC compound wall	with column projecting	at intervals	
7.9	Interiors (Movable & Immovable)	The burial ground has graves with modest ornamentation on them.			
7.8	Finishes	Not applicable			
7.7	Articulation	Not applicable			
7.6	Roofing	Not applicable			
7.5	Openings	Not applicable			

St. Michael's Church Cemetery



View from Mori Road



Statue of Mother Mary




View of the graves



View of the bell tower below which the statue of Mother Mary stands



Plaques on which the names of the dead are inscribed



Card No.: G/n-41

Ward (Part): G north-II

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: January, 2005

Record by: Gauri J, Tanvi O


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Kala

Ref.: Killa



1.0	Denomination					
1.1	Name of Premises	Kala Killa				
1.2	Earlier Name	Reva Fort				
1.3	Built in	1737	Extension Date (if	any)	Not applicable	
2.0	Access				•	
2.1	Main	Dharavi Link Road				
2.2	Subsidiary	Not applicable				
3.0	Ownership Pattern					
3.1	Present	Directorate of Arch	neology, Maharashtr	a		
3.2	Past	British Governmen	ıt			
3.3	Status	Directorate of Arch	neology, Maharashtr	a		
4.0	Use	•				
4.1	Present	Vacant, in ruins				
4.2	Past	Defence				
4.3	Usage	Vacent, in ruins				
5.0	Significance & Value Classification	n				
5.1	Townscape (Natural / Manmade)	BEST bus depot a	Located in Dharavi, a big neighbourhood of slums near the Dharavi BEST bus depot and Mithi River. The fort was constructed on the southern side of the Mahim creek.			
5.2	Architectural Description	some corners near Part of the bastion the most prominen formal gateway as down. It has a ston	The fort is constructed in Black Basalt random rubble masonry with some corners near the bastion constructed in dressed Malad stone. Part of the bastion forming a corner avenue, though in ruins forms the most prominent part of the fort. The fort does not have any formal gateway as such. The plateau on the top has steps to go down. It has a stone plaque in Malad stone. Fort wall on the southeastern side is completely encroached upon by the slums.			
5.3	Intrinsic	One of the eleven old forts in Mumbai of which only eight remain today. It was built by the first Governer of Bombay Gerald Aungier in the 1670s. It was part of the larger Bombay Castle which was also used for the watch tower. Guarding the territory against the Portuguese occupied Salsette island. It is a State Protected Monument.				
5.4	Value Classification	Graded B by DOA, A(arc), A(his), B(de E, F, H(tec)		Recom	nmended Grade	I
6.0	Topography					<u> </u>
6.1	Floors	Not applicable				
7.0	Construction	•				
7.0	Jonoti dottori					

7.2	Walls	Load bearing walls in Black Basalt stone coursed masonry			
7.3	Floor	Not applicable			
7.4	Stairs	Black Basalt stone stra	Black Basalt stone straight flight staircase		
7.5	Openings	Not applicable			
7.6	Roofing	Not applicable			
7.7	Articulation	Plaque in Malad stone			
7.8	Finishes	Black Basalt stone couplaque	ursed masonry constru	ction with Malad stone	
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Not applicable			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Unpaved open space	around, pat encroache	d by slums.	
8.0	Services & Utilities				
8.1	Lighting	Good natural lighting of inside the staircase ch	on fort, Poor natural and amber	d no artificial lighting	
8.2	Ventilation	Good natural ventilation	on, no ventilation in the	staircase chamber	
8.3	Electricity	Not applicable			
8.4	Water Supply	Not applicable			
8.5	Drainage (Plumbing and Sanitation)	Not applicable			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Fair (No settlement or by Moss)	cracks observed on pli	inth, part plint attacked	
9.2	Walls		f the walls broken, tree d due to deep roots of		
9.3	Floor	Not applicable			
9.4	Stairs	Extremly Poor (Stairca being not under use)	ase chamber damaged	due to attack of water	
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Fair (Stone plaque und	der fair state)		
9.8	Services	Not applicable			
9.9	Outbuildings	Poor (Encroached by sthe south-estern fort w		with hutments touching	
9.10	Overall condition	Extremly Poor	Maintenance level	Extremly Poor	
10.0	Transformation				
10.1	Form	Most of the structure b	oroken, fort in ruins.		
10.2	Structure	Most of the structure b	oroken, fort in ruins.		
10.3	Articulation & Finishes	Most of the structure b	oroken, fort in ruins.		
11.0	DP Remarks / Perceived Threats	Marked as Reva Fort	on proposed Developm	nent Plan. (D.P.)	
12.0	Additional Notes / References / Documents Available	Marked as Reva Fort on proposed Development Plan. (D.P.) History: Kala Killa is a small fort located near Dharavi BEST bus depot. It was built in the year 1737 by Governor John Horn. Today in a bad state, ladders can be used to climb up; from above there are steps to go down. The most mysterious feature of the fort is the absence of gate. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			




Plaque stating the construction year 1737



Side walls of the fort, now in ruins



Random rubble masonry in broken condition



Slums and tree growth on the south-eastern walls of the fort



Malad stone dressed masonry for the corner junction





Fort wall in Black Basalt random rubble masonry



Card No.: G/n-42

Ward (Part): G north-I

CS No.: FP No. 567, 567A

Plot Area: 4075.28 sq.m.

B U Area: 4075.28 sq.m.

Date: February, 2005

Record by: Gauri J, Uma P


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Mahim Sunni Muslim

Cemetery



1.1 Name of Premises Mahim Sunni Muslim Cemetery 1.2 Earlier Name Not applicable 1.3 Built in 1908 Extension Date (if any) Not applicable 2.0 Access 2.1 Main Off Miya Mohd. Chottani Road 2.2 Subsidiary Not applicable				
1.3 Built in 1908 Extension Date (if any) Not app 2.0 Access 2.1 Main Off Miya Mohd. Chottani Road				
2.0 Access 2.1 Main Off Miya Mohd. Chottani Road	Not applicable			
2.1 Main Off Miya Mohd. Chottani Road	icable			
2.2 Subsidiary Not applicable	Off Miya Mohd. Chottani Road			
7.2 Gaboliary	Not applicable			
3.0 Ownership Pattern				
	Mohammed Haji Ahmed Aagbotwala, Ibrahim Dadamiya Khandwani, Haji Ebrahim Haji Abdulla Oomere, Hajibhai Ismail Ghanji, Sayeed Abdul Haqeum, Kadri Oomar Osman			
3.2 Past Mahim Sunni Muslim Kabristan trust	Mahim Sunni Muslim Kabristan trust			
3.3 Status Trust				
4.0 Use				
4.1 Present Cemetery				
4.2 Past Cemetery				
4.3 Usage Regular religious use				
5.0 Significance & Value Classification				
5.1 Townscape (Natural / Manmade) Located in the old Mahim neighbourhood near Mahim s	tation.			
	This burial ground is one of the oldest in the Mahim neighbourhood. This ground is used by the Muslim community in Mahim. Two of the graves have brick domes with floral motifs (Kabar), two small kabars are plastered with lime mortar, the dome has a base of Kamalak motif. The space is solely used for burial purpose and hence the space is slowly falling short.			
graves have brick domes with floral motifs (Kabar), two are plastered with lime mortar, the dome has a base of				
graves have brick domes with floral motifs (Kabar), two are plastered with lime mortar, the dome has a base of motif. The space is solely used for burial purpose and h	ence the			
graves have brick domes with floral motifs (Kabar), two are plastered with lime mortar, the dome has a base of motif. The space is solely used for burial purpose and h space is slowly falling short. 5.3 Intrinsic This burial ground of the early 20 th century is used by the space is slowly falling short.	ne Muslim			
graves have brick domes with floral motifs (Kabar), two are plastered with lime mortar, the dome has a base of motif. The space is solely used for burial purpose and h space is slowly falling short. 5.3 Intrinsic This burial ground of the early 20 th century is used by the community of the old neighbourhood.	ne Muslim			
graves have brick domes with floral motifs (Kabar), two are plastered with lime mortar, the dome has a base of motif. The space is solely used for burial purpose and his space is slowly falling short. 5.3 Intrinsic This burial ground of the early 20 th century is used by the community of the old neighbourhood. 5.4 Value Classification A(cul), B(per), B(uu), J, E Recommended	ne Muslim			
graves have brick domes with floral motifs (Kabar), two are plastered with lime mortar, the dome has a base of motif. The space is solely used for burial purpose and his space is slowly falling short. 5.3 Intrinsic This burial ground of the early 20 th century is used by the community of the old neighbourhood. 5.4 Value Classification A(cul), B(per), B(uu), J, E Recommended (Cul), B(per), B(uu),	ne Muslim			
graves have brick domes with floral motifs (Kabar), two are plastered with lime mortar, the dome has a base of motif. The space is solely used for burial purpose and his space is slowly falling short. 5.3 Intrinsic This burial ground of the early 20 th century is used by the community of the old neighbourhood. 5.4 Value Classification A(cul), B(per), B(uu), J, E Recommended (Color) 6.0 Topography 6.1 Floors Ground floor	ne Muslim			
graves have brick domes with floral motifs (Kabar), two are plastered with lime mortar, the dome has a base of motif. The space is solely used for burial purpose and respace is slowly falling short. 5.3 Intrinsic This burial ground of the early 20 th century is used by the community of the old neighbourhood. 5.4 Value Classification A(cul), B(per), B(uu), J, E Recommended and the community of the old neighbourhood. 6.0 Topography 6.1 Floors Ground floor 7.0 Construction	ne Muslim			
graves have brick domes with floral motifs (Kabar), two are plastered with lime mortar, the dome has a base of motif. The space is solely used for burial purpose and his space is slowly falling short. 5.3 Intrinsic This burial ground of the early 20 th century is used by the community of the old neighbourhood. 5.4 Value Classification A(cul), B(per), B(uu), J, E Recommended (Construction) 6.0 Topography 6.1 Floors Ground floor 7.0 Construction 7.1 Plinth Not applicable	ne Muslim			

7.5	Openings	Not applicable
7.6	Roofing	Not applicable
7.7	Articulation	Not applicable
7.8	Finishes	Not applicable
7.9	Interiors (Movable & Immovable)	Not applicable
7.10	Compound / Fence / Gate	Stone wall in random rubble masonry
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not applicable
8.0	Services & Utilities	
8.1	Lighting	Not applicable
8.2	Ventilation	Not applicable
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and Sanitation)	MCGM
8.6	Fire precaution	Not applicable
8.7	Other (HVAC / BMS / Security Systems)	Not applicable
9.0	Condition	
9.1	Plinth	Not applicable
9.2	Walls	Not applicable
9.3	Floor	Not applicable
9.4	Stairs	Not applicable
9.5	Openings	Not applicable
9.6	Roofing	Not applicable
9.7	Articulation & Finishes	Not applicable
9.8	Services	Not applicable
9.9	Outbuildings	Not applicable
9.10	Overall condition	Fair Maintenance level Fair
10.0	Transformation	
10.1	Form	Not applicable
10.2	Structure	Not applicable
10.3	Articulation & Finishes	Not applicable
11.0	DP Remarks / Perceived Threats	Plot reserved as a cremation ground on proposed Development Plan. (D.P.)
12.0	Additional Notes / References / Documents Available	Notes: MCGM Plot leased in 1936, Approx. 950 graves, too small to meet the present needs. No facility for mourners. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai


Mahim Sunni Muslim Cemetry








One of the graves of the cemetery




The road abutting the the cemetery



Decorative kabar with Kamalaka motif



Quarters for the care takers



Straight flight wooden staircase with simple balusters

Rectangular openings with wooden frames and glazed shutters

7.4

7.5

Stairs

Openings

12.0	Additional Notes / References / Documents Available	Documents: C.S. she	ets, D.P. Sheets, Eiche	er City Maps - Mumbai	
11.0	DP Remarks / Perceived Threats	None			
10.3	Articulation & Finishes	Recently painted.			
10.2	Structure	No transformation			
10.1	Form	No transformation			
10.0	Transformation				
9.10	Overall condition	Good	Maintenance level	Good	
9.9	Outbuildings	Good			
9.8	Services	Good			
9.7	Articulation & Finishes	Good (Well maintaine	d)		
9.6	Roofing	Good (No leakage ob	served)		
9.5	Openings	Good (Wooden memb	pers in good condition)		
9.4	Stairs	Good (Wooden memb	pers in good condition)		
9.3	Floor	Good (No sagging ob	served)		
9.2	Walls	Good (No dampness	or cracks observed)		
9.1	Plinth	Good (No settlement	or cracks observed)		
9.0	Condition	<u>1</u>			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
8.6	Fire precaution	Not provided			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.4	Water Supply	MCGM			
8.3	Electricity	BEST			
8.2	Ventilation		good natural ventilation	1	
8.1	Lighting	Natural and artificial, fair natural lighting			
8.0	Buildings / Landscape Services & Utilities				
7.11	Curtilage / Unbuilt Space / Out	No front open space.	Marginal side open spa	ace provided.	
7.10	Compound / Fence / Gate	M S fencing is provide	ed		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.8	Finishes	Internally and externally cement plastered and painted			
7.7	Articulation	The bungalow has an external staircase covered with a Mangalore tile roof. The parapet walls of the first floor balconies have RCC jali The roof has an interesting profile.			

Marianella



View from Miya Mohd. Chottani cross Road





Plain façade of the structure gives it a modest look



Downtake pipes from the gutter



Front elevation



View of the side façade



Card No.: G/n-44

Ward (Part): G north-V

CS No.: Not available

Plot Area: Not available

B U Area: Not available

Date: January, 2006

Record by: Gauri J, Deepti S


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\Sane

Ref.: Guruji Park



1.0	Denomination						
1.1	Name of Premises	Sane Guruji Park	Sane Guruji Park				
1.2	Earlier Name	Nardulla Tank Maid	an				
1.3	Built in	Early 20 th century	Extension Date (it	f any)	Not applicable		
2.0	Access						
2.1	Main	Kakasaheb Gadgil I	Kakasaheb Gadgil Marg				
2.2	Subsidiary	Sayani Road	Sayani Road				
3.0	Ownership Pattern						
3.1	Present	MCGM					
3.2	Past	MCGM					
3.3	Status	MCGM					
4.0	Use						
4.1	Present	Recreational Groun	Recreational Ground				
4.2	Past	Recreational Groun	Recreational Ground				
4.3	Usage	Recreational Groun	d				
5.0	Significance & Value Classification	on					
5.1	Townscape (Natural / Manmade)	Temple abutting the	This large open space is located next to the popular Siddhivinayak Temple abutting the Veer Savarkar Road on the west boundary, which is one of the major North-South arterial roads.				
5.2	Architectural Description	This large piece of I ground is used as a some exhibitions ar the schools for recre	maidan but is also nd political function	o genera s. The g	Ily rented out for	r	
5.3	Intrinsic	Earlier social and political meetings used to take place on the ground.					
F 4		grouna.					
5.4	Value Classification	J, C(seh)		Recom	mended Grade	II B	
6.0	Value Classification Topography			Recom	mended Grade	IIΒ	
-	1			Recomi	mended Grade	II B	
6.0	Topography	J, C(seh)		Recomi	mended Grade	ΙΙΒ	
6.0 6.1	Topography Floors	J, C(seh)		Recomi	mended Grade	II B	
6.0 6.1 7.0	Topography Floors Construction	J, C(seh) Not applicable		Recomi	mended Grade	II B	
6.0 6.1 7.0 7.1	Topography Floors Construction Plinth	J, C(seh) Not applicable Not applicable		Recomi	mended Grade	II B	
6.0 6.1 7.0 7.1 7.2	Topography Floors Construction Plinth Walls	J, C(seh) Not applicable Not applicable Not applicable		Recomi	mended Grade	II B	
6.0 6.1 7.0 7.1 7.2 7.3	Topography Floors Construction Plinth Walls Floor	J, C(seh) Not applicable Not applicable Not applicable Not applicable		Recomi	mended Grade	II B	

7.7	Articulation	Not applicable			
7.8	Finishes	Not applicable			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	M.S. fencing on the b	oundary		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Huge open space with	h no paving		
8.0	Services & Utilities				
8.1	Lighting	Not applicable			
8.2	Ventilation	Not applicable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Good			
9.9	Outbuildings	Not applicable			
9.10	Overall condition	Fair	Maintenance level	Fair	
10.0	Transformation				
10.1	Form	Not applicable			
10.2	Structure	Not applicable			
10.3	Articulation & Finishes	Not applicable			
11.0	DP Remarks / Perceived Threats	Plot demarketed as G	Garden on proposed De	evelopment Plan. (D.P.)	
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			

Sane Guruji Park









Located at a very commanding location on Veer Savarkar Marg with its rear side facing the sea, this mill does not posses the grandeur in terms of scale of structures, materials used or even the architectural features. The highlights of this mill are the guest rooms with beautiful landscape in front facing the large stretch of sea. These guest rooms are still in use and thus well maintained. There are two water bodies within the small plot. The mill has a plain brick chimney. The mill has a lot of open space right from the entrance area till the end. The structures in the mill follow the vernacular vocabulary. The mill produces finished cloth out of the cotton from bale. The entire process involves various activities, step by step working and categorization. The mill is divided in various departments. Preparatory department consists of mixing, carding, blow room, combing sub departments. These are located on ground floor close to each other. Production of thread for weaving takes place in the Ring spinning department. Chimney and boiler room is attached to this largest structure in mill having large machinery. The winding department consisting mainly of lady employees involved beaming of thread from small reels along with categorization and sizing. The beams with wrapped thread are then sent to where the cloth was woven on looms. All the handlooms were replaced by power looms during 1975-77. The structure consists of a large hall with north light roof trusses and a looms lined up in series. The cloth produced in weaving department is then taken to the processing department where the cloth is made ready for dispatch after dyeing, printing and finishing. The mill has densely wooded areas with very old trees, some of them even planted at the time of construction. The lake supplies water to the automatic fire sprinklers in various departments to be used in case of fire hazards.



Card No.: G/n-45

Ward (Part): G north-IV

CS No.: Not available

Plot Area: 48414.00 sq.m.

B U Area: Not applicable

Date: January, 2005

Record by: Swapnil B, Gauri J


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\India Ref.: United Mills No. 6

Compound



1.0	Denomination	•			
1.1	Name of Premises	India United Mills No. 6 Compo	ound		
1.2	Earlier Name	India United dye works			
1.3	Built in	1888 Extension	Date (if any)	Not applicable	
2.0	Access				
2.1	Main	Veer Savarkar Marg (Cadell R	oad)		
2.2	Subsidiary	Suryawanshi Kshatriya Sabha	griha Marg		
3.0	Ownership Pattern				
3.1	Present	National Textile Corporation (N	N.T.C.)		
3.2	Past	Private			
3.3	Status	Ownership (Government)			
4.0	Use				
4.1	Present	Partly used, Textile mill			
4.2	Past	Textile mill, industrial			
4.3	Usage	Partly used,Textile mill			
5.0	Significance & Value Classification	1			
5.1	Townscape (Natural / Manmade)	This mill is located on an extremely prime location along the Dadar chowpaty on the Shivaji Park sea-front. The mill land is located on Veer Savarkar Marg, one of the major North-South arterial roads of Mumbai. The entire land enjoys a sea view and is the only N.T.C. mill land in Mumbai facing the sea.			
5.2	Architectural Description	The entire mill land has a large open space facing the sea with Vernacular low rise and modest structures without much ornamentation. The premises have a maintained lawn for the guest housie facing the sea.			
5.3	Intrinsic	One of the only mills to have a structures in this mill work on t			
5.4	Value Classification	A(arc), A(his), B(per), B(uu), C H(tec), G(grp)	(seh), Recon	nmended Grade	II B
6.0	Topography		·		
6.1	Floors	Not applicable			
7.0	Construction				
7.1	Plinth	Not applicable			
7.2	Walls	Not applicable			
7.3	Floor	Not applicable			

7.4	Stairs	Not applicable	
7.5	Openings	Not applicable	
7.6	Roofing	Not applicable	
7.7	Articulation	Not applicable	
7.8	Finishes	Not applicable	
7.9	Interiors (Movable & Immovable)	Not applicable	
7.10	Compound / Fence / Gate	Plastered brick compound wall	
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Partly wooded unpaved open space in between the structures	
8.0	Services & Utilities		
8.1	Lighting	Natural and artificial, fair natural lighting	
8.2	Ventilation	Natural and artificial, fair natural ventilation	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and Sanitation)	MCGM	
8.6	Fire precaution	Automatic fire sprinkler system for some structures	
8.7	Other (HVAC / BMS / Security Systems)	Not applicable	
9.0	Condition		
9.1	Plinth	Not applicable	
9.2	Walls	Not applicable	
9.3	Floor	Not applicable	
9.4	Stairs	Not applicable	
9.5	Openings	Not applicable	
9.6	Roofing	Not applicable	
9.7	Articulation & Finishes	Not applicable	
9.8	Services	Fair	
9.9	Outbuildings	Fair	
9.10	Overall condition	Fair Maintenance level Fair	
10.0	Transformation		
10.1	Form	Not applicable	
10.2	Structure	Not applicable	
10.3	Articulation & Finishes	Not applicable	
11.0	DP Remarks / Perceived Threats	Plot demarcated as I-3, special industrial zone on proposed Development Plan (D.P.)	
12.0	Additional Notes / References / Documents Available		



Low rise modest structure of Guest House facing the sea



Natural lake in the mill premises



Sea facing verandah of the Guest House



Brick Masonry Chimney with Boiler Room



Capital of M.S. piller supporting the roof



Internal view of the Weaving Shed



View of Guest House



Card No.: G/n-45a

Ward (Part): G north-IV

CS No.: Not available

Plot Area: 48414.00 sq.m.

B U Area: 1100.00 sq.m.

Date: January, 2005

Record by: Swapnil B, Gauri J


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ Ref.:

Folding and Finishing department, India United Mills No. 6



Ward G north

		iville red. o
1.0	Denomination	
1.1	Name of Premises	Folding and Finishing department, India United Mills No. 6
1.2	Earlier Name	India United dye works
1.3	Built in	1888 Extension Date (if any) Not applicable
2.0	Access	
2.1	Main	Veer Savarkar Marg (Cadell Road)
2.2	Subsidiary	Suryawanshi Kshatriya Sabhagriha Marg
3.0	Ownership Pattern	
3.1	Present	National Textile Corporation (N.T.C.)
3.2	Past	Private
3.3	Status	Ownership
4.0	Use	
4.1	Present	Folding, industrial
4.2	Past	Folding, industrial
4.3	Usage	Frequent industrial use
5.0	Significance & Value Classificat	ion
5.1	Townscape (Natural / Manmade)	Low rise structure situated at the centre of the plot besides the reservoir. This mill is located on an extremely prime location along the Dadar chowpaty on the Shivaji Park sea-front. The mill land is located on Veer Savarkar Marg. The entire land enjoys a sea view and is the only N.T.C. mill land in Mumbai facing the sea.
5.2	Architectural Description	Modest low rise structure following the Vernacular architectural character. The façade has not much ornamentation and is characterized by segmental arched openings. Visible from the sea side due to North light roof trusses.
5.3	Intrinsic	Earlier the department was used for both Finishing and Folding of the processed cotton spindle but now only the Folding department works.
5.4	Value Classification	A(arc), A(his), B(uu), C(seh), I(sce), Recommended Grade H(tec)
6.0	Topography	
6.1	Floors	Ground floor
7.0	Construction	
7.1	Plinth	Black Basalt stone plinth in coursed ashlar masonry
7.2	Walls	23 cms thick brick wall
7.3	Floor	Shahabad tiles used for flooring

7.4	Stairs	Not applicable		
7.5	Openings	Rectangular, wooden segmental arched windows with wooden frames and glazed shutter		
7.6	Roofing	North light roof with wooden trusses		
7.7	Articulation	Not applicable		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value		
7.10	Compound / Fence / Gate	Not applicable		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Marginal side open spaces		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Automatic fire sprinkler system		
8.7	Other (HVAC / BMS / Security Systems)	Not provided		
9.0	Condition			
9.1	Plinth	Fair (No settlement or cracks observed but needs maintanance)		
9.2	Walls	Fair (Dampness observed at a few places)		
9.3	Floor	Fair		
9.4	Stairs	Not applicable		
9.5	Openings	Fair		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Fair		
9.8	Services	Fair (Drainage pipes need maintenance)		
9.9	Outbuildings	Fair		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot demarcated as I-3, special industrial zone on proposed Development Plan (D.P.)		
12.0	Additional Notes / References / Documents Available	History: The India united group has seen many changes in the management since its inception. The group which was founded by E.D.Sasson was run till 1943 when it was sold to m/s Agarwal & co., and managed by their board of directors from 1943 to 1958 and again from 1963 to 1965. Then management was given to the authorized controller appointed by government for the period of 1958-1963 and again for the period of 1965-1970 and from 1970. The same was managed from 1970-1974 by the Maharashtra state textile corporation Ltd. as authorized controller and nationalized with effect from 1st April 1974. N.T.C. (north) ltd. was registered on 10th October 1947 and N.T.C. Ltd. (holding company) transferred 11 mill units on 13th march 1975 to this corporation. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai		

Folding and Finishing department, India United Mills No. 6



View of Plain façade with North light truss





Internal view of Foliding and Finishing Department



View of elongated façade of the Folding and Finshing Deapartment



Card No.: G/n-45b

Ward (Part): G north-IV

CS No.: Not available

Plot Area: 48414.00 sq.m.

B U Area: 180.00 sq.m.

Date: January, 2005

Record by: Swapnil B, Gauri J

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Guest house, India

United Mills No. 6



1.0	Denomination					
1.1	Name of Premises	Guest house, India United Mills No. 6				
1.2	Earlier Name	India United dye works				
1.3	Built in	Early 20 th century Extension Date (if	any) Not applicable			
2.0	Access					
2.1	Main	Veer Savarkar Marg (Cadell Road)				
2.2	Subsidiary	Suryawanshi Kshatriya Sabhagriha Ma	arg			
3.0	Ownership Pattern					
3.1	Present	National Textile Corporation (N.T.C.)				
3.2	Past	Private				
3.3	Status	Ownership				
4.0	Use					
4.1	Present	Guest house (in use)				
4.2	Past	Guest house (in use)				
4.3	Usage	Occasional residential use				
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Structure located almost touching the shore line. This mill is located on an extremely prime location along the Dadar chowpaty on the Shivaji Park sea-front. The mill land is located on Veer Savarkar Marg, one of the major north-south arterial roads of Mumbai. The entire land enjoys a sea view and is the only N.T.C. mill land in Mumbai facing the sea.				
5.2	Architectural Description	Vernacular style low rise structure which is sprawling in its form. The verandah of the structure is enclosed by a porch supported by wooden posts covered by Mangalore tiles. There is a rear open space used as a drying yard.				
5.3	Intrinsic	The structure is maily used for receiving	ng the N.T.C officers.			
5.4	Value Classification	A(arc), B(des), I(sce), J	Recommended Grade II B			
6.0	Topography					
6.1	Floors	Ground floor				
7.0	Construction					
7.1	Plinth	Black Basalt stone plinth in coursed as	shlar masonry			
7.2	Walls	Brick load bearing walls				
7.3	Floor	Shahabad tiles used for flooring				
7.4	Stairs	Not applicable				

7.5	Openings	Simple rectangular openings with wooden frames and glazed shutter			
7.6	Roofing	Sloping roof with Mangalore tiles supported by wooden trusses			
7.7	Articulation	The façade does not bear any articulation			
7.8	Finishes	Internally and externally cement plastered and painted			
7.9	Interiors (Movable & Immovable)	Interiors, not of heritage value			
7.10	Compound / Fence / Gate	Not applicable			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Large front open space with lawns			
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, good natural lighting			
8.2	Ventilation	Natural and artificial, good natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Has a small water natural reservoir, sprinkler hydrant			
8.7	Other (HVAC / BMS / Security Systems)	Not provided			
9.0	Condition				
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (Well maintained)			
9.4	Stairs	Not applicable			
9.5	Openings	Good			
9.6	Roofing	Good (Well maintained)			
9.7	Articulation & Finishes	Good			
9.8	Services	Good (Drainage pipes need no replacement)			
9.9	Outbuildings	Good			
9.10	Overall condition	Good Maintenance level Good			
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	Cladding done on internal walls.			
11.0	DP Remarks / Perceived Threats	Plot demarcated as I-3, special industrial zone on proposed Development Plan (D.P.)			
12.0	Additional Notes / References / Documents Available	History: The India united group has seen many changes in the management since its inception. The group which was founded by E.D.Sasson was run till 1943 when it was sold to m/s Agarwal & co., and managed by their board of directors from 1943 to 1958 and again from 1963 to 1965. As the group was found to be working unsatisfactorily after 1950, an investigation was carried out in the year 1953 and management was given to the authorized controller appointed by government for the period of 1958-1963 and again for the period of 1965-1970. The same was managed from 1970. The same was managed from 1970-1974 by the Maharashtra state textile corporation Ltd. As authorized controller and nationalized with effect from 1st April 1974. N.T.C. (north) ltd. was registered on 10th October 1947 and N.T.C. Ltd. (holding company) transferred 11 mill units on 13th march 1975 to this corporation. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps - Mumbai			

Guest house, India United Mills No. 6



View of the sprawling structure of Guest House with landscape in front



Large porch with Mangalore tiled sloping roof and landscape give ambience of a bungalow



Front elevation showing the sea facing verandah



Elongated façade of the guest house



Play of Mangalore tiled sloping roofs with different profiles add to the modest façade



Internal corridor facing the sea

Right side elevation and Left side elevation not seen due to proximity of adjoining buildings



Card No.: G/n-45c

Ward (Part): G north-IV

CS No.: Not available

Plot Area: 48414.00 sq.m.

B U Area: 70.00 sq.m

Date: January, 2005


Record by: Swapnil B, Gauri J

Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ Ref.: Chimney, India United Mills No. 6



1.0	Denomination					
1.1	Name of Premises	Chimney, India United Mills No. 6				
1.2	Earlier Name	India United dye works				
1.3	Built in	Early 20 th century	Extension Date (i	f any)	Not applicable	
2.0	Access					
2.1	Main	Veer Savarkar Mar	g (Cadell Road)			
2.2	Subsidiary	Suryawanshi Kshat	triya Sabhagriha M	larg		
3.0	Ownership Pattern					
3.1	Present	National Textile Co	rporation (N.T.C.)			
3.2	Past	National Textile Co	rporation (N.T.C.)			
3.3	Status	Ownership (Govern	nment)			
4.0	Use					
4.1	Present	Vacant, Not in use				
4.2	Past	Chimney				
4.3	Usage	Vacant, Not in use				
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	This mill is located on an extremely prime location along the Dadar chowpaty on the Shivaji Park sea-front. The mill land is located on Veer Savarkar Marg, one of the major north-south arterial roads of Mumbai. The entire land enjoys a sea view and is the only N.T.C. mill land in Mumbai facing the sea.				
5.2	Architectural Description	Chimney constructed in brick masonry with not much ornamentation except for circular bands at top level.the structure is attached with the boiler house which is the department already closed down. The chimney is constructed during the Colonial period.				
5.3	Intrinsic	Earlier used for the the tallest structure			ticles and appare	ently
5.4	Value Classification	A(arc), B(des), B(u	u), I(sce)	Recom	nmended Grade	II B
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Plastered masonry plinth				
7.2	Walls	Load bearing brick masonry walls				
7.3	Floor	Not applicable				

7.4	Staire	Not applicable		
7.4	Stairs Openings	Not applicable Not applicable		
7.6	Roofing	Not applicable Not applicable		
7.7	Articulation	Not applicable		
7.8	Finishes	Not applicable		
7.9	Interiors (Movable & Immovable)	Not applicable		
7.10	Compound / Fence / Gate	Plastered brick compound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Unpaved open space around		
8.0	Services & Utilities			
8.1	Lighting	Natural and artificial, fair natural lighting		
8.2	Ventilation	Natural and artificial, fair natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and Sanitation)	MCGM		
8.6	Fire precaution	Not applicable		
8.7	Other (HVAC / BMS / Security Systems)	Not applicable		
9.0	Condition			
9.1	Plinth	Good (No cracks observed)		
9.2	Walls	Fair (Plastered chipped off at many places)		
9.3	Floor	Not applicable		
9.4	Stairs	Not applicable		
9.5	Openings	Not applicable		
9.6	Roofing	Not applicable		
9.7	Articulation & Finishes	Fair		
9.8	Services	Poor (Completely shut down)		
9.9	Outbuildings	Fair (Needs immediate clean-up)		
9.10	Overall condition	Fair Maintenance level Fair		
10.0	Transformation			
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0	DP Remarks / Perceived Threats	Plot demarcated for I-3, special industrial zone on proposed Development Plan		
12.0	Additional Notes / References / Documents Available	History: The India united group has seen many changes in the management since its inception. The group which was founded by E.D.Sasson was run till 1943 when it was sold to m/s Agarwal & co., and managed by their board of directors from 1943 to 1958 and again from 1963 to 1965. As the group was found to be working unsatisfactorily after 1950, an investigation was carried out in the year 1953 and management was given to the authorized controller appointed by government for the period of 1958-1963 and again for the period of 1965-1970. The same was managed from 1970. The same was managed from 1970-1974 by the Maharashtra state textile corporation Ltd. As authorized controller and nationalized with effect from 1st April 1974. N.T.C. (north) ltd. was registered on 10th October 1947 and N.T.C. Ltd. (holding company) transferred 11 mill units on 13th march 1975 to this corporation. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai, Charles Correa committee report on N.T.C. mills of Mumbai		

Chimney, India United Mills No. 6



View of brick masonry chimney with boiler room



Brick masonry chimney with horizontal bands at the top portion

Kohinoor Mills No. 3 (Now demolished except for Chimney)

The mill land is located at a very prime location in the midst of a residential and commercial neighbourhood. The mill is now demolished except for the chimney. The mill produced finished cloth out of the cotton from bale. The entire process involves various activities, step by step working and categorization. The mill is divided in various departments. Preparatory department consists of mixing, carding, blow room, combing sub departments. These are located on ground floor close to each other. Production of thread for weaving takes place in the Ring spinning department. Chimney and boiler room is attached to this largest structure in mill having large machinery. The winding department consisting mainly of lady employees involved beaming of thread from small reels along with categorization and sizing. The beams with wrapped thread are then sent to where the cloth was woven on looms. All the handlooms were replaced by power looms during 1975-77. The structure consists of a large hall with north light roof trusses and a looms lined up in series. The cloth produced in weaving department is then taken to the processing department where the cloth is made ready for dispatch after dyeing, printing and finishing. The mill has densely wooded areas with very old trees, some of them even planted at the time of construction. The lake supplies water to the automatic fire sprinklers in various departments to be used in case of fire hazards.



Card No.: G/n-46

Ward (Part): G north-IV

CS No.: Not available

Plot Area: 20492.00 sq.m.

B U Area: 18879.00 sq.m.

Date: January, 2005

Record by: Swapnil B, Ojas P


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ **Ref.:** Kohinoor Mills No. 3

compound



		compound					
1.0	Denomination						
1.1	Name of Premises	Kohinoor Mills No. 3 compound (Now demolished except for Chimney)					
1.2	Earlier Name	Not applicable	Not applicable				
1.3	Built in	Early 20 th century Extension Date (if any) Not applicable					
2.0	Access						
2.1	Main	N. C. Kelkar Marg					
2.2	Subsidiary	Lady Jamshedji Road					
3.0	Ownership Pattern						
3.1	Present	National Textile Corporation (N.T.C.)					
3.2	Past	National Textile Corporation (N.T.C.)					
3.3	Status	Ownership (Government)					
4.0	Use						
4.1	Present	Vacant, Not in use					
4.2	Past	Processing unit					
4.3	Usage	Vacant, Not in use					
5.0	Significance & Value Classif	cation					
5.1	Townscape (Natural / Manmac	Located on a strategic location in at junction of Lady Jamshedj Road and N. C. Kelkar Marg at Dadar. One of the prime commercial areas in Mumbai.					
5.2	Architectural Description	style. The structures were located along the avenue formed by	The mill land consisted of 18 structures constructed in Vernacular style. The structures were located along the avenue formed by screen printing, rope alley and screen printing office structures. The building had fairly ornamental character.				
5.3	Intrinsic	The Mill land is locatede in the midst of the residential and	One of the mils of The Kohinoor group, later handed over to N.T.C. The Mill land is locatede in the midst of the residential and commercial neighbourhood with its north-east wall abuting a mill				
5.4	Value Classification	A(arc), A(his), B(des), B(uu), C(she), Recommended Grade H(tec)	IIΒ				
6.0	Topography						
6.1	Floors	Not applicable					
7.0	Construction						
7.1	Plinth	Not applicable					
7.2	Walls	Not applicable					
		Not applicable					

7.4	Stairs	Not applicable			
7.5	Openings	Not applicable			
7.6	Roofing	Not applicable	Not applicable		
7.7	Articulation	Not applicable			
7.8	Finishes	Not applicable			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Plastered brick compo	ound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Not applicable			
8.0	Services & Utilities				
8.1	Lighting	Not applicable			
8.2	Ventilation	Not applicable			
8.3	Electricity	Not applicable			
8.4	Water Supply	Not applicable			
8.5	Drainage (Plumbing and Sanitation)	Not applicable			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Not applicable			
9.9	Outbuildings	Not applicable			
9.10	Overall condition	Not applicable	Maintenance level	Not applicable	
10.0	Transformation				
10.1	Form	Demolished			
10.2	Structure	Demolished			
10.3	Articulation & Finishes	Demolished			
11.0	DP Remarks / Perceived Threats	Plot demarcated for I-3, special industrial zone on proposed Development Plan			
12.0	Additional Notes / References / Documents Available		ets, D.P. Sheets, Eiche littee report on N.T.C.	er City Maps – Mumbai, mills of Mumbai	



Avenue formed by Screen Printing and Rope Alley



View of Chimney from the mill premises



Vernacular style façade with horizontal bands & segmental windows



View of Screen Printing and Rope Alley



View of Auto loom shed and Chimney



Tower of Screen Printing department



External staircase to folding department



View towards entrance



Card No.: G/n-46a

Ward (Part): G north-IV

CS No.: Not available

Plot Area: 52408.00 sq.m.

B U Area: 65.00 sq.m.

Date: January, 2005

Record by: Swapnil B, Ojas P


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\
Ref.: Chimney, Kohinoor Mills


No. 3



1.0	Denomination					
1.1	Name of Premises	Chimney, Kohinoor Mills No. 3				
1.2	Earlier Name	Not applicable				
1.3	Built in	Early 20 th century	Extension Date (if	any)	Not applicable	
2.0	Access					
2.1	Main	Lady Jamshedji Ro	ad			
2.2	Subsidiary	N. C. Kelkar Marg				
3.0	Ownership Pattern					
3.1	Present	National Textile Co	rporation (N.T.C.)			
3.2	Past	Not available				
3.3	Status	Ownership (Govern	ment)			
4.0	Use					
4.1	Present	Vacant, Not in use				
4.2	Past	Chimney				
4.3	Usage	Vacant, Not in use				
5.0	Significance & Value Classification	1				
5.1	Townscape (Natural / Manmade)	Located on a strate Road and N. C. Kel commercial areas in	kar Marg at Dadar.			ji
5.2	Architectural Description		Chimney constructed in brick masonry with not much ornamentation except for circular bands at top level.			
5.3	Intrinsic	Chimney is the tallest and most prominent structure in the mill premises. Chimney is characterized by its height which was constructed above the general height of buildings so as to release the polluted gasses above the level of habitat. The Chimney is located next to Boiler, Blow Room and Carding department, departments from which a lot of polluting gasses are emitted.				
5.4	Value Classification	A(arc), B(des), B(ut	u), I(sce)	Recom	mended Grade	II B
6.0	Topography					
6.1	Floors	Not applicable				
7.0	Construction					
7.1	Plinth	Plastered stone plin	nth			
7.2	Walls	Load bearing brick masonry				
7.3	Floor	Not applicable				
7.4	Stairs	Not applicable				

7.5	Openings	Not applicable	Not applicable			
7.6	Roofing	Not applicable				
7.7	Articulation	Not applicable				
7.8	Finishes	Not applicable				
7.9	Interiors (Movable & Immovable)	Not applicable				
7.10	Compound / Fence / Gate	Plastered brick compo	ound wall			
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Unpaved open space	around with vegetation	1		
8.0	Services & Utilities					
8.1	Lighting	Natural and artificial, f	air natural lighting			
8.2	Ventilation	Natural and artificial, f	air natural ventilation			
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing and Sanitation)	MCGM				
8.6	Fire precaution	Not applicable				
8.7	Other (HVAC / BMS / Security Systems)	Not applicable				
9.0	Condition					
9.1	Plinth	Good (No cracks observed)				
9.2	Walls	Fair (Tree growth obswalls)	Fair (Tree growth observed on external façade, cracks seen on the walls)			
9.3	Floor	Not applicable				
9.4	Stairs	Not applicable				
9.5	Openings	Not applicable				
9.6	Roofing	Not applicable				
9.7	Articulation & Finishes	Not applicable				
9.8	Services	Poor (Completely shu	t down)			
9.9	Outbuildings	Fair (Needs immediate	e clean-up)			
9.10	Overall condition	Fair	Maintenance level	Fair		
10.0	Transformation					
10.1	Form	No transformation				
10.2	Structure	No transformation				
10.3	Articulation & Finishes	Tree growth on façade	e			
11.0	DP Remarks / Perceived Threats	Plot demarcated for I-3, special industrial zone on proposed Development Plan. (D. P.)				
12.0	Additional Notes / References / Documents Available	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai, Charles Correa committee report on N.T.C. mills of Mumbai				

Chimney, Kohinoor Mills No. 3




View of Brick Masonry Chimney with horizontal bands



Plaster chipped off and tree growth on façade of chimney

Elphinstone Mills (Now demolished)

The mill land is located on Senapati Bapat Marg (Tulsi Pipe Road), a road on which most of the private and N.T.C. textile mill lands in Mumbai are located. The entire mill land is now demolished. The mill had vernacular style structure in brick masonry. The most striking feature whereas was the lake located just next to the front entrance wall facing Senapati Bapat Marg unlike other mills. The mill produced finished cloth out of the cotton from bale. The entire process involves various activities, step by step working and categorization. The mill is divided in various departments. Preparatory department consists of mixing, carding, blow room, combing sub departments. These are located on ground floor close to each other. Production of thread for weaving takes place in the Ring spinning department. Chimney and boiler room is attached to this largest structure in mill having large machinery. The winding department consisting mainly of lady employees involved beaming of thread from small reels along with categorization and sizing. The beams with wrapped thread are then sent to where the cloth was woven on looms. All the handlooms were replaced by power looms during 1975-77. The structure consists of a large hall with north light roof trusses and a looms lined up in series. The cloth produced in weaving department is then taken to the processing department where the cloth is made ready for dispatch after dyeing, printing and finishing. The mill has densely wooded areas with very old trees, some of them even planted at the time of construction. The lake supplies water to the automatic fire sprinklers in various departments to be used in case of fire hazards.



Card No.: G/n-47

Ward (Part): G north-V

CS No.: Not available

Plot Area: 34382.93 sq.m.

B U Area: Not applicable

Date: January, 2005

Record by: Swapnil B, Ojas P


Review by: Neera Adarkar

Internal: As above

External: As above

Photo T-IV-Gn:\Ward Gn\ Ref.: Elphinstone Mills

Compound



1.0	Denomination						
1.1	Name of Premises	Elphinstone Mills Compound (Now Demolished)					
1.2	Earlier Name	Not applicable	Not applicable				
1.3	Built in	Early 20 th century Extension Date (if any) Not applicable				
2.0	Access						
2.1	Main	Senapati Bapat Marg (Tulsi Pipe Roa	id)				
2.2	Subsidiary	Not applicable					
3.0	Ownership Pattern						
3.1	Present	National Textile Corporation (N.T.C.)					
3.2	Past	Bhawan Haribhai, Motilal Kalyanji					
3.3	Status	Ownership (Government)					
4.0	Use						
4.1	Present	Vacant, Not in use					
4.2	Past	Processing unit					
4.3	Usage	Vacant, Not in use					
5.0	Significance & Value Classification	on					
5.1	Townscape (Natural / Manmade)		The mill is located at the junction of Jagannathrao Bhatankar Marg, which is one of the major North-South arterial roads in Mumbai.				
5.2	Architectural Description	It is a combination of Vernacular style architecture. It has features like segment the floors. The terrace parapet wall has projecting cornice band.	nental arched openings of	n all			
5.3	Intrinsic	The mil land is located in the midst of N.T.C. mill lands, most of which now builders in the form of residential tower	demolished and develop	ed by			
5.4	Value Classification	A(arc), B(des), B(uu), I(sce)	Recommended Grade	II B			
6.0	Topography						
6.1	Floors	Not applicable					
7.0	Construction						
7.1	Plinth	Not applicable					
7.2	Walls	Not applicable					
7.3	Floor	Not applicable					
7.4	Stairs	Not applicable					
7.5	Openings	Not applicable					
7.6	Roofing	Not applicable					
Adarka	r Associates, Architects	160	Ward	d G nort			

7.7	Articulation	Not applicable			
7.8	Finishes	Not applicable			
7.9	Interiors (Movable & Immovable)	Not applicable			
7.10	Compound / Fence / Gate	Plastered brick compo	ound wall		
7.11	Curtilage / Unbuilt Space / Out Buildings / Landscape	Unpaved open space	around with vegetation		
8.0	Services & Utilities				
8.1	Lighting	Natural and artificial, fa	air natural lighting		
8.2	Ventilation	Natural and artificial, f	air natural ventilation		
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and Sanitation)	MCGM			
8.6	Fire precaution	Not applicable			
8.7	Other (HVAC / BMS / Security Systems)	Not applicable			
9.0	Condition				
9.1	Plinth	Not applicable			
9.2	Walls	Not applicable			
9.3	Floor	Not applicable			
9.4	Stairs	Not applicable			
9.5	Openings	Not applicable			
9.6	Roofing	Not applicable			
9.7	Articulation & Finishes	Not applicable			
9.8	Services	Not applicable			
9.9	Outbuildings	Not applicable			
9.10	Overall condition	Fair	Maintenance level	Fair	
10.0	Transformation				
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	Tree growth on façade	e		
11.0	DP Remarks / Perceived Threats	Plot demarcated for I-3, special industrial zone on proposed Development Plan			
12.0	Additional Notes / References / Documents Available	History: In 1935 it was owned by Bhawan Haribhai, Motilal Kalyanji and in 1983 it was handed over to the National Textile Corporation. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai,			
			ittee report on N.T.C. r		

tone Mills Compound (Now Demolished)



View of Production Department and Chimney



Lake facing Senapati Bapat Marg



Brick masonry Chimney with base having cornice band



View of Blow Room and Mixing Department and lake in the foreground



Vernacular style elongated façade of Card Department



Internal view of Card Department



View of Weaving Shed



M.S. bridge connecting two structures



Detailed view of Machinery

