Mahanana	r Telephone Nigam Ltd. Building			10°
viaitattaya	Telephone Migani Eta. Bullanig	Common Ref No: 101	1	
		Card No: 143	WALLAC	E STREET
	THE WAR HE	A	- 1979	STREET
		Ward (Part): A (II)	/ 4 // ~	The Ci
		CS No: 1410 sqm. (Fort division)		79/ 7
		Plot Area: 1634.62 sqm.		37 ///0/
		B U Area: -		Z Z
OLD HELDER		Date: 07/04/2005	TELEPHONE BIL	77 3
7		Recorded by: Sonal Modak	- J. T. D.	
V		Reviewed by:	Cu.	3/ × / 5
		Int: Sonal Modak, Arun Wadhwa	CHARANJIT RA	
		Ext: Sonal Modak, Arun Wadhwa	- / The	ROAD
		Photo Ref.: 101_MTNL building	KILLICK BUILDING	
		Frioto Rei 101_WTNL ballaling		
			Loca	tion Plan
1.0		Denomination		
1.1	Name of Premises	Mahanagar Telephone Nigam Ltd. Building		
1.2	Earlier Name	Telephone Buildings		
1.3	Built in:	Project Sanctioned on 26th November 1872	Extension Date: -	
		Commencement on 1st May 1874		
		Completed on 31st December 1877		
2.0		Access		
2.1	Main	Charanjit Rai Road – pedestrian		
2.2	Subsidiary	Amrut Keshav Nayak Path - pedestrian		
3.0		Ownership pattern		
3.1	Present	State Government		
3.2	Past	State Government		
3.3	Status	Owner		
4.0		Use		
4.1	Present	Institutional - Telephone Exchange and Office		
4.2	Past	Institutional - Telephone Exchange and Office	es	
4.3	Usage	Daily		
5.0		Significance & Value Classification		
5.1	Townscape (Manmade)	The building is located on a corner plot, at the		
		Keshav Nayak Path facing Killick House which		
		Building has main access from Charanjit Rai		de and subsidiary publi
- n	Auditorium Denning Con	entry from Amrut Keshav Nayak Path on eas	tern side.	
5.2	Architectural Description	Planning		anti-day of a set of a second
		The building is rectangular in plan located on		
		from southern façade and subsidiary entrano		
		Originally the main entrance was through a p		
		ground floor wing, forming terrace at first floo		
		with central staircase and open office space of	on either side. Service	areas and tollets are
		located on rear side of the building. Façade is divided in number of vertical bays l	hy causes opasaed co	lumne with arched
		window openings in between.	by square engaged co	iumns with arched
		, ,	rimple triangular pedin	ant with docorative
		On front façade central bay is topped with a sentablature.	mipie mangulai pedili	IOIIL WILLI UCCOIALIVE
		Features		
		Interior open office spaces have circular stee	l columns supporting t	he floors at equal
		intervals. Decorative cast iron doorways at th		
		Façade having several vertical bays defined		
		simple pediment with decorative entablature		
		topped by a segmental arch pediment.		
		Ground floor has semicircular entrances with	prominent keystones.	Facades are
		punctuated by segmental arched balustrade		-
		Style	, 0	
		The structure displays influence of European	Renaissance style in a	architecture.
5.3	Intrinsic	T		
5.4	Value Classification	A(arc), B(per), E, F, G(grp)	Recommended	II B
		. , . , , , , , , , , , , , , , , , , ,	grade:	
-				•
6.0		Topography		
	I .	1 -1-0-4-1		

wananagar	Telephone Nigam Ltd. Building	10	
6.1	Floors	G + 3 with basement and part terrace at first floor level.	
		·	
7.0		Construction	
7.1	Plinth	Medium plinth about 2 ft. 6 inches high in buff basalt masonary.	
7.2	Walls	External walls are thick composite load bearing walls. Internal non-structural walls in brick.	
7.3	Floor	Jack arch floor with steel sections resting on circular steel columns on upper floors. In most	
1.0	11001	areas floors not visible due to false ceiling.	
7.4	Stairs	There are total three staircases	
7	otano	Main staircase is timber open well with decorative newel posts at each floor.	
		Another cast iron dog-legged staircase on rear side with open risers which is not in use.	
		Third staircase is a narrow steel one having access from third floor to fourth floor.	
7.5	Openings	Arched balustrade window openings with wooden frame glazed shutters with wooden	
7.0	Openings	louvers in some parts. Main access is defined by couple of semicircular arches.	
7.6	Roofing	Partly timber truss with mangalore roofing tiles and partly jack arch flat roof with steel	
7.0	Rooming	sections.	
7.7	Articulation	Simple triangular and segmental arch pediments. Decorative spandrels. Bands at each flo	
1.1	Articulation		
7.0	Finishes	level. Engaged square columns forming vertical bays.	
7.8	Finishes	External exposed buff basalt masonary. Walls plastered and painted internally. Elevation	
7.0	Interior (Mr. 11 O.)	articulation and features painted.	
7.9	Interiors (Movable & Immovable)	Movable	
		Immovable	
		Decorative cast iron doorway of lift at each floor.	
7.10	Compound/ Fence/ Gate	Southern and eastern side external wall of building forms boundary. Narrow marginal open	
		space on northern and western sides.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Under ground water storage tank, pump house, AC condenser units kept on northern side	
	Landscape	open space.	
		Basement houses electrical transformers of few buildings in the same area.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light and supplemented by electrical lighting equipments.	
8.2	Ventilation	Adequate natural ventilation supplemented by forced ventilation devices wherever	
		necessary.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Provision of smoke detectors on all floors and basement.	
8.7	Other (HVAC/BMS/Security Systems)	Window and split AC units have been installed.	
0.1	Carer (1117 to 15 mer educating Cyclemic)	Trindon and opin to anno have been instance.	
9.0		Condition	
9.1	Plinth	Fair except for few damages to stone masonary.	
9.1	Walls		
		Fair	
9.3	Floor	Severe leakages observed through Service block floors. Mostly not visible due to false	
2.1	0:1	ceilings.	
9.4	Stairs	Fair	
9.5	Openings	Fair	
9.6	Roofing	Fair. No evident damages seen.	
9.7	Articulation & Finishes	Fair with re-plastering and re-painting.	
9.8	Services	Poor – severe leakages observed in service block.	
9.9	Out Buildings	Fair - Water is removed every alternate day with the help of three pumps from the	
		basement.	
9.10	Overall Conditions	Fair - Repair works are going on. Maintenance level Fair	
10.0		Transformation	
	Form	Originally planned porch on southern side has been enclosed with a ground floor wing	
	5/111	added.	
	Structure	-	
	Articulation & Finishes		
	ALTICUIATION & LINSINGS		
44.0		DD Damanira/ Damanirad Threats	
11.0		DP Remarks/ Perceived Threats	
		Telephone exchange, building forms part of C1 zone	
		Additional Notes/ References/ Documents available	
12.0			
12.0		Additional Notes:	
12.0			

INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD *Visual dictionary of Architecture*, Division of International Thomson Publishing Inc.



Front façade with extended structure blocking the view of the old building



Marble Tablet at the entrance about the building detail at the building entrance lobby



Stone clad side façade with arched openings, floor level bands, cornice bands, pediments etc.



Opening detail with recessed windows with sill bands and pediment, top level pediment with dentils and ornamented tympanum



Arched door opening on round columns with prominent keystone and floral pattern in the spandrel and floor bands.



Stone balustrade in the balconies



Arched window with alterations made in the shutter



Cast iron column capital section



Interior view with high Jack arch ceiling supported on cast iron columns and beams



Floral pattern stone motif in the parapet of the balcony



Open lift with an exposed lift cage



Projecting balcony supported on wooden brackets

To	10
Common Ref No: 102	June I Doubling III
Card No: 144	Charania
Ward (Part): A (Part II)	Charanjit Rai Road
CS No: 749 (Fort)	
Plot Area: 1,070.23 sq m	
	149 Alleh Bulding
B U Area: 4,203.64 sq m	
Date: 17/12/2004	
Recorded by: Sonal Modak	
Reviewed by:	
Int: Sonal Modak, Zankhana Prajapati	
Ext: Sonal Modak, Zankhana Prajapati	100 100 100
Photo Ref.: 102 Killick House	Contraday 1500 1 2
THOSE TABLE TO SELECT THE SELECT	Marior county
	Location Plan
Denomination	
Killick House	
Killick House	
1905	Extension Date: -
Access	
Charanjit Rai Road – Pedestrian and vehi	cular
-	oului
Ownership pattern	
Nippon Investment and Finance Company	<u></u>
Dinshaw Trust (Killick Nixon)	
Tenant (State Bank of India)	
Tonant (otate bank of illula)	
llee	
Use	
Institutional - Bank (Offices)	
Indeterminable	
Daily	
Significance & Value Classification	
Corner building standing at the junction of	Charaniit Rai road and A. K. Navak Marg
Planning	
Rectangular in plan and symmetrical about northern side. The service areas and service staircase at Northern façade is divided in number of being floor wise allocation of various departments.	nts of bank. It has a pediment to emphasize the entrance.
-	
A(arc), B(per), E, F, G(grp)	Recommended II B grade:
Topography	
G + 2 with basement.	
Construction	
Medium in rough grey basalt with ventilator	ors for hasement
Thick load bearing walls with grey basalt a Internal comparatively thinner walls as cas	st iron columns support the floors.
Flooring is mostly not visible due to false of Wherever visible, it is jack arch with mild siron columns.	ceilings. steel sections with RCC beams supported on cas
There are 2 staircases in all. Main timber staircase with wooden handra	ail with curb wall of about 2'6" in height.
	iron columns. There are 2 staircases in all.

	se	10.
7.5	Openings	The main entrance is through a rectangular door opening with a thick wooden shutter and a
		collapsible gate.
		Ground floor windows have segmental arches with ventilators. All upper floor windows are
		rectangular openings. All the windows have wooden frames and glazed panels with
		ventilators above.
		Square ventilators are fixed with stained glass panels.
		All the door window openings are provided with a steel jali and awnings from outside.
7.0	Deefee	
7.6	Roofing	Sloping Mangalore tile hipped roof on steel trusses. Flat concrete slab over toilet block.
7.7	Articulation	Internal cast iron decorative column capitals, red granite circular column imposts defining
		main entrance, Corinthian column capitals, small finial like features near main entrance,
		pediments with floral carvings above semi circular arched window openings bands at each
		floor level.
7.8	Finishes	Grey basalt for the exteriors with all decorative carvings in buff basalt and imposts in red
		granite.
		Walls are plastered and painted internally.
7.9	Interiors (Movable & Immovable)	Movable
1.5	interiors (Movable & Infinovable)	WIOVADIC
		· · · · · · · · · · · · · · · · · · ·
		Immovable
		•
7.10	Compound/ Fence/ Gate	Plastered stone compound wall about 5' in height.
		On northern side the external wall of building forms the boundary.
		There is no entrance gate.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	A pump house on eastern side margins.
	Landscape	A temporary shed on southern side open space.
	23.1300340	Triamporary once on countern olde open opaco.
8.0		Services & Utilities
	Linktin	
8.1	Lighting	Totally dependant on artificial lighting.
8.2	Ventilation	The building is centrally Air Conditioned.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	No traces.
8.7	Other (HVAC/BMS/Security Systems)	Window air conditioning units have been installed.
0.1	Other (ITVAO/DIVIO/Geculity Gystems)	William all conditioning driks have been installed.
0.0		Condition
9.0	Diate	
9.1	Plinth	Fair - Careless cement pointing done. Organic growth observed on rear side.
		Blackening of stone due to moss growth.
9.2	Walls	Fair - Careless cement pointing done. Third floor wall is plastered and painted externally.
		Plaster peeling off due to heavy leakage at top floor.
		Severe seepage and dampness is observed on internal walls too.
9.3	Floor	Flooring not visible due to false ceilings.
9.4	Stairs	Fair - Staircase in fair state except for seepage in certain walls of staircase has been
J. 1	Stano	observed.
0 E	Openings	Main timber staircase is fitted upon with granite treads at some places.
9.5	Openings	Fair - In many places pediments are broken to house the window AC units. Square
		ventilator openings are closed in some places damaging the decorative motifs.
		volume of the state of the stat
		Hoardings are blocking some of the openings.
9.6	Roofing	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible
9.6	Roofing	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible
9.6	, and the second	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing.
9.7	Articulation & Finishes	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places.
9.7 9.8	Articulation & Finishes Services	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair
9.7	Articulation & Finishes	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas
9.7 9.8 9.9	Articulation & Finishes Services Out Buildings	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building.
9.7 9.8	Articulation & Finishes Services	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas
9.7 9.8 9.9 9.10	Articulation & Finishes Services Out Buildings	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair
9.7 9.8 9.9	Articulation & Finishes Services Out Buildings	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building.
9.7 9.8 9.9 9.10	Articulation & Finishes Services Out Buildings	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair
9.7 9.8 9.9 9.10	Articulation & Finishes Services Out Buildings Overall Conditions	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair
9.7 9.8 9.9 9.10	Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation -
9.7 9.8 9.9 9.10	Articulation & Finishes Services Out Buildings Overall Conditions Form	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation -
9.7 9.8 9.9 9.10	Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation - Mezzanine has been added over the staircase well.
9.7 9.8 9.9 9.10	Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation - Mezzanine has been added over the staircase well. DP Remarks/ Perceived Threats
9.7 9.8 9.9 9.10	Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation - Mezzanine has been added over the staircase well.
9.7 9.8 9.9 9.10 10.0	Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation - Mezzanine has been added over the staircase well. - DP Remarks/ Perceived Threats Building forms part of C1 zone
9.7 9.8 9.9 9.10	Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation - Mezzanine has been added over the staircase well. - DP Remarks/ Perceived Threats
9.7 9.8 9.9 9.10 10.0	Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation - Mezzanine has been added over the staircase well. - DP Remarks/ Perceived Threats Building forms part of C1 zone
9.7 9.8 9.9 9.10 10.0	Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation - Mezzanine has been added over the staircase well. - DP Remarks/ Perceived Threats Building forms part of C1 zone Additional Notes/ References/ Documents available
9.7 9.8 9.9 9.10 10.0	Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	Hoardings are blocking some of the openings. Poor - Steel sections of roofing trusses are corroded though roofing is mostly not visible due to false ceiling. Heavy leakage takes place through roofing. Fair - Decorative features are damaged in many places. Fair Poor - It is in neglected condition. Drainage pipes are leaking leaving unhygienic areas around the building. Fair Maintenance level: Fair Transformation - Mezzanine has been added over the staircase well. - DP Remarks/ Perceived Threats Building forms part of C1 zone Additional Notes/ References/ Documents available

Killick House

Structures listed for Conservation.
FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
Division of International Thomson Publishing Inc.



Grey stone clad building with arched and rectangular openings, floor bands.





Pediment over openings ornamented with floral pattern in the tympanum, bands with dentils.



Arched window opening with bands and motifs in a neglected and transformed state



Cartouche at window sill level



Central higher bay with arched and round openings, bands etc



Decorative Cast iron column capital and bracket



Window sill level ornamentation with floral pattern, bands, dentils etc

Killick House 102




Entrance to the building with an added awning, incongruous painted walls and hoarding over it blocking the building features



Hoarding of the Bank blocking the façade features



Jack arch flooring supported on Cast iron columns and steel section beams



Meher Man 7.7	Articulation	Overhanging semicircular balcony supported on distinct corbel feature, raised octagona	
1.1	Articulation	potion with conical roof feature, comice bands at floor levels, fine carved capitals at the entrance archway.	
7.8	Finishes	External front and part side facades are dressed in yellow stone ashlars course masonry with arch openings, projecting balcony supported on corbel and carved features in lighter stone finish. Part side and rear facades are plain plaster finished. Indeterminable internal finishes.	
7.9	Interiors (Movable & Immovable)	Movable Indeterminable Immovable Indeterminable	
7.10	Compound/ Fence/ Gate	1.5 m. high compound wall along the front, side and rear with two gates to the north and south ends of the west front.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Cement paved open space on all sides of the building with few trees and plants dotting the boundary.	
8.0		Services & Utilities	
8.1	Lighting	Indeterminable	
8.2	Ventilation	Indeterminable	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM. Underground and Overhead Water storage tank.	
8.5	Drainage (Plumbing & Sanitation)	MCGM Connected to Municipal sewer lines.	
8.6	Fire Precaution	Indeterminable	
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable	
9.0		Condition	
9.1	Plinth	Indeterminable	
9.2	Walls	Indeterminable	
9.3	Floor	Indeterminable	
9.4	Stairs	Indeterminable	
9.5	Openings	Indeterminable	
9.6	Roofing	Indeterminable	
9.7	Articulation & Finishes	Indeterminable	
9.8	Services	Indeterminable	
9.9	Out Buildings		
9.10	Overall Conditions	Indeterminable Maintenance level: negligible as not in use	
10.0		Transformation	
	Form	-	
	Structure Articulation & Finishes	Third floor front open terrace enclosed. Insensitive pointing carried out on the stone dressed façade.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	

Meher Mansion 103



Buff stone clad building with arched openings, decorative balustrade, floor bands etc




Central higher bay with trefoil arched openings, decorative capital bands and balustrade, dentils, sill and floor level frieze bands, sloping roof supported on decorative brackets



Arched window openings with decorative balustrade, bands at sill and floor level, arched ventilator openings, added chajjas etc



Balcony balustrade with decorative stone tapering feature



Mayo hous	e	104	
		door shutters, large window openings with two pairs of operable glazed panel window	
		shutters also very distinct ventilator panels. Wooden awnings supported on brackets ove window openings and verandas.	
7.6	Roofing	Sloping Mangalore tile roof, flat concrete slab over servants wing.	
7.7	Articulation	Stone base of the projecting bay window, cornice band at floor levels,	
7.8	Finishes	Plaster painted external and internal wall surfaces with stone carved ornamental features Varied floor finishes.	
7.9	Interiors (Movable & Immovable)	Movable -	
		Immovable -	
7.10	Compound/ Fence/ Gate	Low compound wall about 0.5 m. with iron railing on the front side. Medium height walls to both sides. Iron gates with stone post on both sides of the western front.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Open space on all the four sides of the building, large to the rear side with a garage	
	Landscape	structure abutting the rear compound wall. Pump room and security room also provided within the rear space.	
8.0		Services & Utilities	
8.1	Lighting	Inadequate natural light relies on artificial light fixtures.	
8.2	Ventilation	Inadequate natural ventilation relies on artificial means.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to sewers of MCGM	
8.6	Fire Precaution	•	
8.7	Other (HVAC/BMS/Security Systems)	Widow unit AC	
9.0		Condition	
9.1	Plinth	Poor - painted and damaged stone dressing	
9.2	Walls	Poor - extensive leakage, damaged plaster & plant growth	
9.3	Floor	Poor - cracks and exposed reinforcement, also damp areas in the floor slab.	
9.4	Stairs	Poor - loose and damaged wooden treads corroding steel stair in the servant's wing.	
9.5	Openings	Poor - broken glass panes, neglected shutter finishes and numerous chajja and A.C additions. Also damaged wooden awnings.	
9.6	Roofing	Poor - broken tiles and missing eavesboard. Asphalt coating applied insensitively over mangalore tiles.	
9.7	Articulation & Finishes	Poor - neglected finishes, ornamental features damaged and blackened. Wooden parapet feature missing on first and third floor. Damaged cornice bands.	
9.8	Services	Poor - extensive seepage from drainpipes, open drain chambers, also old and messy electrical wiring.	
9.9	Out Buildings	Poor - unused garage structure, also neglected pump room and open space around with garbage and waste dumped.	
9.10	Overall Conditions	Poor Maintenance level: Poor	
10.0	F	Transformation	
	Form	Lift block added on the rear side.	
	Structure Articulation & Finishes	Totally reconstructed servant's wing and connecting passage. Painted plinth stone facing & ornamental features.	
	Atticulation & Finishes	ainted plinter stone racing & ornamental leatures.	
11.0		DP Remarks/ Perceived Threats	
-		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.	

Mayo house 104



Arched openings with decorative human motifs at springing point, floral pattern of column capitals, geometric pattern balustrade etc.



Wooden staircase with decorative railing



Neglected state of wooden decorative balustrade of the extended balcony supported on brackets



Side wing with extended balconies with decorative features such as arched openings with decorative motifs at springing point, keystone and column capitals, decorative balustrade, tapering lower level bands etc



Neglected state of projecting balconies, supported on brackets with sloping roof



Window openings with decorative ventilators, balustrade etc

Commerce	House		105
		Common Ref No: 105	
	NATIONAL LANGUAGES AND	Card No: 147	g line
1	See Page	Ward (Part): A (Part II)	
		CS No: 39/1187(Fort Division)	
100		Plot Area: 846.53 sqm.	O W THE SHAPE WAS A SHAPE WAS
		r	MAN MAN
377		B U Area: -	CONSTRUCTION OF THE PROPERTY O
		Date: 14/04/2005	a d
	The state of the s	Recorded by: Sonal Modak	COMBINE NOW
		Reviewed by:	SOURCE SO
		Int: Permission denied	7,84
- 2		Ext: Sonal Modak	37/IIS7
- 1 /		Photo Ref: 105_Commerce House	201E GFENING NIE
		5	J.N.HEREDIA MARG
4.0		D	Location Plan
1.0	Name of Description	Denomination Commence Library	
1.1	Name of Premises	Commerce House	
1.2	Earlier Name Built in:	Commerce House	Fidencies
1.3	Built III.	Indeterminable	Extension - Date
2.0			
2.0	Main	Access	
2.1	Main	Currimbhoy Marg - Pedestrian	
2.2	Subsidiary	-	
3.0	+	Ownership pattern	
3.1	Present	Indeterminable	
3.2	Past	Indeterminable	
3.3	Status	Indeterminable	
3.3	Status	Indeterminable	
4.0		Use	
4.1	Present	Commercial - Offices	
4.2	Past	Commercial - Offices	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)		e-lined avenue maintaining similar height and
		features as per urban design regulations laid	
F 0	Assistant and Deposition	Main access is from Currimbhoy Marg from t	ne nortnem road front.
5.2	Architectural Description	Planning Bostongular building plan with languar forced	le facing the road and sharing common oper
			Large floor heights without any setback or
		interception generate an urban scale-volume	
			office spaces intercepted only by supporting
		columns and window openings on three side	
			with side and central bays slightly rising above
		the building height.	
		Features	
		Symmetrical front façade in dressed regula	ar ashlar masonary partly rusticated at lowe
		level.	
			s at first and third floor levels, which serve as
			central bays have rectangular windows with
		projecting cornice bands as weather protection	
			essed semicircular arches. Upper floors have
		rectangular architrave window openings.	
		Style Influence of European Renaissance style.	
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp)	Recommended II B
***		(grade:
6.0		Tanagraphy	
6.0	Eleore	Topography	
6.1	Floors	G + 3 with basement	
7.0	+	Construction	
7.1	Plinth	High plinth about 4 ft. high to accommodate	ventilators for basement in vellow ashlar
/	[i iii ii i	I mgm pilitin about + it. high to accommodate	o vondictors for basement, in yellow delilar

ommerce	House	105
		masonry.
7.2	Walls	Load bearing yellow ashlar masonry along the entire periphery, open internal space is
		supported on columns.
7.3	Floor	Indeterminable
7.4	Stairs	Indeterminable
7.5	Openings	Large door/window openings with timber frame and double-glazing panels.
7.6	Roofing	Indeterminable
	, and the second	****
7.7	Articulation	Cornice bands, Bas-relief sculptures.
7.8	Finishes	Yellow Kurla stone dressed external wall surfaces and plaster painted internal finishes.
7.9	Interiors (Movable & Immovable)	Movable
		- Immovable
7.10	Compound/ Fence/ Gate	No compound wall, only an iron gate enclosing the common open space on both sides.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Paved open space shared with adjoining buildings. Tree lined avenue along the front an
	Landscape	services located in the rear common space.
8.0		Services & Utilities
8.1	Lighting	Indeterminable
8.2	Ventilation	Indeterminable
8.3	Electricity	BEST
		MCGM
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	
8.6	Fire Precaution	Indeterminable
8.7	Other (HVAC/BMS/Security Systems)	Split and window unit air-conditioners.
9.0		Condition
9.1	Plinth	Fair except plumbing interventions along the sides and rear.
9.2	Walls	Fair except plant growth and plumbing interventions on the rear side. Also seepage observed internally along the toilet walls.
9.3	Floor	Indeterminable
9.4	Stairs	Indeterminable
9.5	Openings	Fair except poor maintenance.
9.6	Roofing	Indeterminable
9.7	Articulation & Finishes	Fair except minor blackening, plant growth and interventions. Poor state of internal wa
9.1	Articulation & Finishes	and floor finishes.
9.8	Services	Poor – old and neglected plumbing lines to the rear side.
9.9	Out Buildings	-
9.10	Overall Conditions	Fair Maintenance level Poor
40.0		T
10.0	_	Transformation
	Form	No visible changes from outside
	Structure	No visible changes from outside
	Articulation & Finishes	No visible changes from outside
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone
42.0		Additional Nates / Defenses / Decompate auxilable
12.0		Additional Notes/ References/ Documents available Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.

Commerce House 105



Buff stone clad building with rectangular and arched openings, comice and sill bands.




Opening with decorative bracket and keystone supporting the projecting band. Projecting balcony supported on stone bracket band



Rusticated buff stone clad building with arched opening with a prominent keystone, stone bracket band etc.





Incongruous additions to the window openings

Bharat Bh	avan	106
Diidiat Dii	avail	Common Ref No: 106
	A second	
		Card No: 148
		Ward (Part): A (Part II) CS No: 46/1187(Fort Division) Plot Area: 890 sqm. B U Area: -
		CS No: 46/1187(Fort Division)
		Plot Area: 890 sqm. B U Area: - Date: 14/04/2005 Recorded by: Sonal Modak Reviewed by: Int: Sonal Modak Photography permission depied
		Plot Area: 890 sqm.
		D U AIGA
		Date: 14/04/2005
	TANK AN VAN	Recorded by: Sonal Modak
		Reviewed by:
	The state of the s	Int: Sonal Modak
		Photography permission denied
		Ext: Sonal Modak Photo Ref: 106 Bharat Bhayan
		Photo Ref: 106_Bharat Bhavan
		Location Plan
1.0		Denomination Location Flat
	Name of Descripto	Bharat Bhavan
1.1	Name of Premises	
1.2	Earlier Name	Bharat Bhavan
1.3	Built in:	1920's Extension -
		Date
2.0		Access
2.1	Main	Currimbhoy Marg - Pedestrian
2.2	Subsidiary	-
3.0		Ownership pattern
3.1	Present	Bharat Petroleum
3.2	Past	Bharat Petroleum
3.3	Status	Owner
4.0		Use
4.1	Present	Commercial - Offices
4.2	Past	Commercial - Offices
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	Located along a row of buildings on a tree-lined avenue maintaining similar height and
• • •		features as per urban design regulations laid down for the entire Ballard Estate.
		Main access is from Currimbhoy Marg from the northern road front.
5.2	Architectural Description	Planning
0.2	Alonitocialal Description	Rectangular building plan with longer façade facing the road and sharing common oper
		spaces with buildings on sides and rear. Large floor heights without any setback of
		interception generate an urban scale-volume to the building block.
		Typical layout on all upper floors with open office spaces intercepted only by supporting
		columns and window openings on three sides.
		The building is approached through a porch.
		Features
		Symmetrical front façade in dressed regular ashlar masonary partly rusticated at lower
		level.
		Ground floor has semicircular arches. Upper floors have rectangular architrave window
		openings.
		Style
		Influence of European Renaissance style.
5.3	Intrinsic	-
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp) Recommended II B
		grade:
6.0		Topography
6.1	Floors	G+3
V. 1	1.00.0	<u> </u>
7.0		Construction
	Dlinth	
7.1	Plinth	High plinth in yellow ashlar masonry.
7.2	Walls	Load bearing yellow ashlar masonry along the entire periphery, open internal space is
		supported on columns.
7.0		1 800
7.3	Floor	RCC
7.3 7.4 7.5	Floor Stairs Openings	RCC RCC Large door/window openings with timber frame and double-glazing panels.

Bharat Bha	avan	106
7.6	Roofing	Flat roof
7.7	Articulation	Cornice bands
7.8	Finishes	Yellow Kurla stone dressed external wall surfaces and plaster painted internal finishes.
7.9	Interiors (Movable & Immovable)	Movable - Immovable -
7.10	Compound/ Fence/ Gate	No compound wall, only an iron gate enclosing the common open space on both sides.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved open space shared with adjoining buildings. Tree lined avenue along the front and services located in the rear common space.
8.0		Services & Utilities
8.1	Lighting	Natural lighting supplemented with artificial means
8.2	Ventilation	Natural lighting supplemented with artificial means
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Smoke detecting system, fire extinguishers
8.7	Other (HVAC/BMS/Security Systems)	Central air conditioning system.
9.0		Condition
9.1	Plinth	Fair except plumbing interventions along the sides and rear.
9.2	Walls	Fair except plant growth and plumbing interventions on the rear side. Also seepage observed internally along the toilet walls.
9.3	Floor	Fair
9.4	Stairs	Fair
9.5	Openings	Fair except poor maintenance.
9.6	Roofing	Fair
9.7	Articulation & Finishes	Fair except minor blackening, plant growth and interventions. Poor state of internal wall and floor finishes.
9.8	Services	Poor – old and neglected plumbing lines to the rear side.
9.9	Out Buildings	
9.10	Overall Conditions	Fair Maintenance level Fair
10.0	Form	Transformation
	Structure	No visible changes from outside No visible changes from outside
	Articulation & Finishes	No visible changes from outside
11.0		DP Remarks/ Perceived Threats Building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.

Note: Photography permission denied

All Build	lings on Dadabhai Nowroii Road	d with special focus on Fort House	107	
		Common Ref No: 107		
		Card No: 149		
		Ward (Part): A (Part II)		
		CS No: -	Nagar Chowk	
		Plot Area: NA	Dr. Dadabhal Nowton	
		B U Area: NA		
	Not Applicable	Date: 14/04/2005		
		Recorded by: Prachi Merchant		
		Reviewed by:		
		Int: NA		
		Ext: Sonal Modak, Prachi Merchant		
		Photo Ref.: 107_D.N. Road precinct Location Plan		
1.0		Denomination	Location Figure	
1.1	Name of Premises	All Buildings on Dadabhai Nowroji Road	d with special focus on Fort House	
1.2	Earlier Name	All Buildings on Dadabhai Nowroji Road		
		-		
1.3	Built in:	Varied	Extension Date: -	
2.0		Access		
2.1	Main	Dr. Dadabhai Nowroji Road - Pedestria	n	
2.2	Subsidiary	Hornby Road		
L.L	outsidally .	Tioriby road		
3.0		Ownership pattern		
3.1	Present	Varied		
3.2	Past	Varied		
3.3	Status	Varied		
0.0	Olatao	Valled		
4.0		Use		
4.1	Present	Mixed - Commercial, Recreational and	Institutional areas	
4.2	Past	Mixed - Commercial, Recreational and		
4.3	Usage	,		
4.5	Usay e	Mixed - Commercial, Recreational and Institutional areas		
5.0		Significance & value Classification		
5.1	Townscape (Natural/	Dr. Dadabhai Nowroji Road is the most significant arterial road planned within the city.		
			ed as a north-south axis anchored by Cawford Market on the	
	Walling Co.	north end and b Flora Fountain in the south end.		
5.2	Architectural Description	Planning		
	· · · · · · · · · · · · · · · · · · ·		precinct have been planned as a part of greater urban scheme.	
			trian arcade. This forms the unifying element tying the various	
		building facades as one integrated urba		
		The western edge of the road has an in	nposing street elevation of magnificent buildings, the eastern	
		edge retains the modest scale.		
		Features		
			similar height and footprint relationship in the entire area,	
		except for a few exceptions.		
		Style Dr. D. N. Road is dotted with buildings.	of various styles of Architecture with a common unifying	
			style of Architecture ranges from Venetian Neo-Gothic style of	
			o-Saracenic expression of the Municipal Headquarters and	
			features of the State Bank of Indore and Parsi Panchayat, to	
			I and the Art Deco of the Citibank and Prospect Chambers.	
5.3	Intrinsic	One of the first planned integrated urba	n streetscape built as a main arterial axis with a common	
5.3	Intrinsic	One of the first planned integrated urba		
5.3 5.4	Intrinsic Value Classification	One of the first planned integrated urba	n streetscape built as a main arterial axis with a common	
		One of the first planned integrated urba	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	
		One of the first planned integrated urba	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	
5.4		One of the first planned integrated urba pedestrian arcade tying together the va	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	
5.4 6.0	Value Classification	One of the first planned integrated urba pedestrian arcade tying together the va - Topography	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	
5.4 6.0	Value Classification	One of the first planned integrated urba pedestrian arcade tying together the va - Topography	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	
5.4 6.0 6.1	Value Classification	One of the first planned integrated urba pedestrian arcade tying together the va - Topography Varied	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	
5.4 6.0 6.1 7.0 7.1	Value Classification Floors	One of the first planned integrated urba pedestrian arcade tying together the va - Topography Varied	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	One of the first planned integrated urba pedestrian arcade tying together the va - Topography Varied	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls Floor	One of the first planned integrated urba pedestrian arcade tying together the va - Topography Varied	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	One of the first planned integrated urba pedestrian arcade tying together the va - Topography Varied	in streetscape built as a main arterial axis with a common rious building facades of varied styles of Architecture.	

All Buildi	ngs on Dadabhai Nowroji Road v	vith special focus on Fort House 107
7.7	Articulation	-
7.8	inishes	-
7.9	Interiors (Movable &	Movable
	Immovable)	
	,	Immovable
		-
7.10	Compound/ Fence/ Gate	-
7.11	Curtilage/ Unbuilt space/ Out	-
	Buildings/ Landscape	
8.0		Services & Utilities
8.1	Lighting	-
8.2	Ventilation	-
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing &	MCGM
	Sanitation)	
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security	-
	Systems)	
9.0		Condition
9.1	Plinth	-
9.2	Walls	-
9.3	Floor	-
9.4	Stairs	-
9.5	Openings	-
9.6	Roofing	-
9.7	Articulation & Finishes	-
9.8	Services	_
9.9	Out Buildings	
9.10	Overall Conditions	- Maintenance level: -
0.10	O VOIGII OCITATIONO	multionality (976).
10.0		Transformation
1010	Form	-
	Structure	
	Articulation & Finishes	
	Autoliation & Finishes	
11.0		DP Remarks/ Perceived Threats
11.0		Dr Neillains) reiceived filleats
		-
42.0		Additional Notes/ References/ Documents available
12.0		
		Additional Notes:
		Lessees signed 99-year leases around 1896. Since there was a three year period mandated for completion, most were completed around 1898-1899. A supplementary Agreement between the
		Improvement Trust and the BMC stipulated that the frontages required lessees to arcade the
		footpaths in front of their properties. Lessees who proposed to arcade had to obtain the consent of
		the Government to the design. The designs and specifications were to be submitted to the Executive
		Engineer & Surveyor for the approval of Government within one year after the date of sale and such
		designs were to have some architectural character in the facade. All ornamental details in the design
		had to be of substantial material. Mouldings, if any, were to be of stone, terracotta or moulded brick.
		The buildings to be erected had to be in strict accordance with the block plan. Further, when buildings
		were continuous, there would be party walls common to both adjoining houses, with the party walls
		carried above the roofing and furnished with a coping projecting over each face. The buildings could
		not exceed 65 feet in height measured from the top of the plinth to the tie beam of the roof, except
		with the special sanction of Government. All exterior walls had to be of good stone, brick or other like
		enduring material. No lime, plaster or cement could be used as an exterior coating. All interior walls
		had to be built of brick and lime or rubblestone and lime or of wooden framing with brick filling in between. Bricks, if used in external walls were to be of English pattern, well burnt and of approved
		quality. Properly seasoned teakwood was mandated for all storey posts, girders, bressumers and all
		timbers on which the stability of the building depended. The sufficiency of the thickness of walls, of
		the scantlings of beams and girders and of the dimensions of all other parts of the structure were to
		be subject to the approval of the Surveyor to Government. The street plan is signed by John Adams,
		Architectural Engineer & Surveyor, dated 18 April, 1898.
		Note: Gostling & Morris (later Gostling, Fritchley & Chambers), Architects for Standard Building,
	<u> </u>	

107

Wallace Building, Canada Building, Cox's Building, Whiteway & Laidlaw,

The building was totally reconstructed after the fire in 1982 retaining the front façade. The building was built by the billionaire philanthropist, Sir Jamshetji Jeejeebhoy. The building with facing in porbunder stone, fronted the western Fort ramparts and was enclosed in front and separated from street by a large courtyard. The home featured three drawing rooms, bedrooms and dining rooms. Among the three drawing rooms one was in the English style with exquisite Waterford chandeliers, another in the French style with Bohemian glass and gilt couches and a third with Chinese inlaid furniture. In 1914 the building was leased to Frederick Evans, Donald Fraser and Duncan Fraser of the English firm, Evans Fraser, who remodelled the façade by adding a pediment and portico. The 1982 fire gutted the annexe completely and Fort House itself substantially.

References:

INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) *The Cities Within*, Bombay: Eminence Designs Pvt. Ltd.

RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols. Bombay.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt.

Dr. Dadabhai Naoroji Road, Mumbai – Design Handbook for a Heritage Streetscape Guidelines for Street Furniture & Signage, prepared by: Abha Narain Lambah, Coservation Architect. Published by MMR Heritage Conservation Society.

Name: W1 - Old Oriental Insurance building

Owner: Life Insurance Corporation Usage: Commercial Topography: G+3, with roof attic

Description:

The ground floor of the building forms a part of an arcade. It is a landmark building marked by high tower at corner facing flora fountain dressed in grey stone deriving influence from Gothic style with features such as pointed arches with white bands around, rose windows, high gable roof with turrets, spires, decorative brackets, corbels, jails etc.

Grade: II A

Name: W13 – Kodak House (Deutsche Bank)

Owner: Deutsche Bank
Usage: Commercial
Topography: G + 3
Description:

The ground floor of the building forms a part of an arcade with arched openings. Buff stone clad building derives influence from Neo classical style of Architecture with features such as arched openings

with keystones, cornice bands etc.





Name: W14 – Wheelers Building (State Bank Of Indore)

Owner: -

Usage: Commercial Topography: G+3

Description: The ground floor of the building forms a part of an

arcade with arched openings with rusticated stone façade. Building is divided in three level with ground floor arcade, first and second floor with a large pediment and plain third floor. The building has prominent features such as double floor height columns with a base and Corinthian capitals, decorative tympanum, dentils, louvered shutters,

rectangular openings etc.

Grade: II B



Name: W15 - Taj Building

Owner: -Usage: G + 3

Topography:
Description: The ground floor of the building forms a part of an

arcade with arched openings. Buff stone clad building with raised corner bay derives influence from Neo classical style of Architecture, recessed openings, floor cornice bands, balustrade etc.

Grade: II I



Name: W16 – National Insurance Building

Owner:

Usage: Commercial Topography: G+3

Description: The ground floor of the building forms a part of an

arcade with arched openings. Grey stone building with corner raised bays surmounted by a pediment. The building has features such as arched openings with kestone, projecting balconies supported on

brackets, floor bands etc.



Name: W17 – Kitab Mahal

Owner: -

Usage: Commercial Topography: G + 4

Description:

The ground floor of the building forms a part of an arcade with arched openings. Prominent red brick building with arched openings, pediment over openings, floor and sill level bands, etc. Many transformations have occurred to this building.

Grade: II B

Name: W18 – Shreeji Building

Owner:

Usage: Commercial Topography: Arcade

Description: Only ground floor of the building which forms a part of

an arcade with arched opening is remaining while the rest of the building was demolished in fire few years

back.

Grade: II B





Name: W19 – Hornby Building

Owner: -

Usage: Commercial Topography: G + 4

Description:

The ground floor of the building forms a part of an arcade with arched openings. The building has Neo Classical features such as arched openings with prominent keystones, columns with base and

decorative capitals.



Name: W20 – Khandelwal Building

Owner:

Usage: Commercial Topography: G + 4

Description:

The ground floor of the building forms a part of an arcade with arched openings. The building derives influence from Neo classical style of Architecture with features such as corner quoins, arched openings with

keystone etc.

Grade: II B



Name: W21 – Sheth Girls High School

Owner: Usage: Commercial
Topography: G +6

Description:

The ground floor of the building forms a part of an arcade with arched openings. A completely new building has been constructed on the old site with no

trace of the old building.

Grade: II B



Name: W22 – Esplanade High School

Owner: Usage: Institution
Topography: G + 3
Description:

The ground floor of the building forms a part of an arcade with arched openings. The buff stone clad building derives influence from Neo classical style of Architecture with features such as arched openings, columns with Corinthian capitals, corner quoins etc.

Grade: II B



Name: W23 – Mahendra Building

Owner: Usage: Commercial
Topography: G + 3

Description:

The ground floor of the building forms a part of an arcade with arched openings. Buff stone building derives influence from Neo classical style of Architecture with features such as arched openings, corner raised bays with a pediment surmounted,

balustrades etc.



Name: W24 - Mahendra Annexe Building

Owner:

Usage: Commercial Topography: G + 3Decsription:

> The ground floor of the building forms a part of an arcade with arched openings. Prominent corner building juxtaposed between important buildings like Chhattrapati Shivaji Terminus and Capital Cinema building. Buff stone building with a comer raised bay surmounted with a dome with two wings flanked on

either side. The building has features such as rectangular openings, floor cornice bands etc.

Grade:



Name: W25 - Capital Cinema

Owner: Nadir Company Private ltd. - Globe Theater Co.

Usage: Cinema Theater, Commercial

Topography:

Description:

Prominent corner building at the busy junction of VT station and BMC building is one of the first theaters in Mumbai. The building is clad in grey stone with white bands and has features, such as semicircular arches, pediments, cornice bands, columns with decorative capitals, floral motifs and human face carvings. It derives influence from Colonial and Baroque style of

Architecture

Grade:

W26 - Municipal Corporation of Greater Mumbai

Headquarters Owner:

Name:

Municipal Corporation of Greater Mumbai

Commercial

Usage:

G + 3 Main building, G + 6 Annex Building

Topography: Description:

> Prominent corner building complementing the VT station building derives influence from Indo Saracenic style of architecture with features such as a extended arched porch, pointed arches, floral motifs, decorative spandrel, stone balustrade, pilasters forming spires and minarets with cupola domes, onion shaped large central dome, cylindrical towers, pediments, turrets, decorative brackets, cornice

bands, corbels, stained glass tracery etc

Grade:

W27 - Times of India building Name:

Owner: Private Usage: Commercial

Topography:

Description:

G + 3 front wing, G + 5 rear wing

Regular dressed grey masonary building having visible influence of Islamic architecture with features like onion shaped dome, stone jalis, floral motifs, turrets, pointed arches with prominent imposts. Semicircular arches along corridors have decorative intrados. Decorative pilasters rise up the entire height. There are two towers rising beyond third floor level on northern and southern ends of the building. Neo-Gothic and Indo-Saracenic style of architecture

Grade: II A







Name: W28 - Anjuman-E-Islam High School

Owner: Private Usage: Institutional

Topography: G+ 5 Main building block

Description:

It has strong influence of Indo-Saracenic style of architecture. Ground floor is a verandah marked by Islamic arches all along. An onion shaped arch with intricately carved stone jali defines main entrance. The Corner of the building has two full height Islamic

arch openings.

Grade: IIB



Name: W29 – Akbar Peerbhoy Polytechnic

Owner: Private -Trust Usage: Institutional

Topography: G + 5 (Gr - old structure, Floors above added later)

Description:

Building with regular dressed grey masonary, having visible influence of Islamic Architecture having features like onion shaped domes, stone balustrades, floral motifs, ornate bands, semicircular arches with

decorative intrados.

Grade: IIB



Owner: State Government
Usage: Institutional
Topography: G + 1

Description:

Grey rough dressed masonary. Main entrance porch has double height. Window openings with pointed arches resting on prominent imposts. Carving works in limestone. Columns having Corinthian capitals. Intricately carved jalis. Decorative stone bands, cornices. Derives influence from Indo-Saracenic style

of Architecture

Grade: II A



Name: E1 – Ismail Building

Owner:

Usage: Commercial Topography: G + 4

Description:

The ground floor of the building forms a part of an arcade with arched openings. The building derives influence from Neo Classical style of Architecture with features such as double height columns with Corinthian capitals, balustrades, comice bands,

dentils etc.



E2 - Dariya Building Name:

Owner:

Usage: Commercial Topography: Description: G + 4

Newly constructed building. No trace of the original

building

Grade: IΙΒ



E3 - Sailor Building Name:

Owner:

Usage: Commercial Topography: Description: G + 4

Building with extended porch, rectangular openings, columns, balustrade etc. Many transformations have

taken place in this building

Grade:




E4 – Bisini Building Name:

Owner:

Usage: Commercial Topography: G + 5

Building with arched openings, bands etc.
The building is in a neglected state. Description:

Grade: IΙΒ



Name: E5 – Banaji House

Owner:

Usage: Commercial Topography: G + 3

Description:

Building with part sloping roof. Many transformations

have taken place

Grade: II B



Name: E6 – Petit Building

Owner:

-

Usage: Commercial Topography: G + 4

Description:

The ground floor of the building forms a part of an arcade with arched openings. The building has Neo classical features such as rusticated stone façade, bands, arched openings, columns with decorative capitals, balconies etc.

Capitai

Grade: II B



Name: E7 – Ardershir Dadibhoy Dadiseth Agiary
Owner: Seth Dadibhoy Naoshewwanji Dadiseth Atash

BehramTrust

Usage: Religious

Topography: G+1

Description: The Parsee fire temple derives influence from

vernacular style of architecture with a unique style of Mangalore tile roof supported on long wooden brackets. The façade consists of bands, cornices and has full height openings. Pre-industrial Vernacular

style architecture

Grade: IIA

Name: E8 – Alice building - Stone Arch

Owner:

Usage: Hawkers have occupied the arcade

Topography: Arcade

Description:

The continuous arched arcade is in buff basalt stone with its wall and columns horizontally rusticated, arches arising from impost, has decorative floral keystone and has marble tablet engraved Alice

Building.

Grade: III





Name: E9 – Nawaab Building

Owner: -

Usage: Commercial Topography: G + 4

Description:

New building has been constructed leaving no trace

of the old building.

Grade: II E



Name: E10 – Prospect Chambers

Owner:

Usage: Commercial Topography: G+ 5 Description:

The ground floor of the building forms a part of an arcade with rectangular openings. The building derives influence from Art Deco style of Architecture with vertical columns, rectangular openings etc.

Many transformations have taken place.

Grade: II B



Name: E11 – Bai Pirojbai Dadabhoy Maneckji Vachha Agiary Owner: Bai Pirojbai Dadabhoy Maneckji Vachha Agiary Trust

Usage: Religious

Topography: Main Agiary - G+2, Ancillary structure - G+1

Description:

The ground floor of the building forms a part of an arcade with rectangular openings. The Agiary entrance is emphasized by way of a winged lion supports (lamuses). The front façade shows features such as gigat persepolitan columns stone grillwork.

supports (lamuses). The front raçace snows reatures such as giant persepolitan columns, stone grillwork, and articulated entabulature, deriving influence from an industrial style of Architecture.

pre industrial style of Architecture.

Grade: II A



Name: E12 – Kermani Owner: -Usage: Commercial

Topography: G + 4
Description:

The ground floor of the building forms a part of an arcade with rectangular openings. The building has features such as rectangular openings, horizontal floor bands at 1st, 4th floor level, triple height columns

with Corinthian capitals, etc.



Name: E13 – Bombay Mutual Life

Owner:

Usage: Commercial Topography: G + 5

Description:

The ground floor of the building forms a part of an arcade with rectangular openings. Buff stone clad building with rectangular openings, floor bands, arched openings, red painted bands etc.

Grade:

Name: E14 – Elphinstone (Residency Hotel)

Owner:

Usage: Commercial Topography: G + 4

Description:

The ground floor of the building forms a part of an arcade with rectangular openings. The building has rectangular openings. Columns with base and

decorative capitals.

Grade: II E





Name: E15 – Reliance Building


Owner:

Usage: Commercial Topography: G+ 5

Description:

The ground floor of the building forms a part of an arcade with rectangular openings. Buff stone narrow building surmounted with a pediment, with features such as rectangular and arched openings with corner quoins, floor bands with dentils, columns with

Corinthian capitals



E16 - Kumud House Name:

Owner:

Commercial Usage: Topography: G + 5

Description:

The ground floor of the building forms a part of an arcade with rectangular openings. The building has cornice bands with dentils etc. Many transformations

have taken place.

Grade: IJΒ



Name: E17 - Bilquees Mansion

Owner:

Usage: Commercial Topography: Style: G + 4

The ground floor of the building forms a part of an

arcade with arched openings. Newly constructed building with no trace of the old building

Grade:



Name: E18 - Saldahana House

Owner:

Commercial Usage: G + 5Topography:

The ground floor of the building forms a part of an arcade with arched openings. The building has Style:

rectangular openings cornice bands, brackets, corner quoins etc. The building is in a state of neglect.

Grade:



Name: E19 – Saroosh Building

Owner: Usage: Topography: G + 4

Description:

The ground floor of the building forms a part of an arcade with rectangular openings. The building is in a demolished state and in a state of neglect. The building has features such as rectangular openings, projecting balconies supported on brackets, corner quoins etc.

Grade: II I



Name: E20 – Eruchshaw Building

Owner: Private
Usage: Commercial
Topography: G+ 6

Description:

The ground floor of the building forms a part of an arcade with arched openings. Symmetrical front with projecting balconies supported on decorative brackets, floor level comice bands, relief features and arch openings in both side bays, while the central projecting bay has pediment top.

Grade: II B



Name: E21 – Peninsula House

Owner: Private
Usage: Commercial
Topography: G + 4 with Terrace

Description:

The ground floor of the building forms a part of an arcade with rectangular openings with rusticated stucco colonnade and Doric capitals. Large double height semicircular arch recessed opening and projecting balconies supported on decorative

brackets form noted façade features.



Name: E22 - Commissariat Building

Owner:

Usage: Commercial Topography: G + 5

Description:

The ground floor of the building forms a part of an arcade with arched openings. Rusticated stone building with rectangular openings, vertical and

horizontal columns.

Grade: IIΒ



Name: E24 - Fort House (Old Handloom House)

Owner:

Usage: Commercial

G + 4 Topography:

Description:

The building has been totally transformed. The building porch extends out as a part of the arcade. The building derived influence from Neo Classical style of

Architecture

Grade: IJΑ

E25 - Badri Mahal Name:

Owner:

Usage: Religious Topography: G+4 Description:

The ground floor of the building forms a part of an arcade with arched openings. The front façade consist of alternate bays of wooden projecting balconies supported on decorative wooden brackets. The arched openings are articulated with decorative friezes, ventilator paneling, decorative swan neck pediment with decorative tympanum. Derives influence from Indo Sarscenic style of Architecture

Grade: IΙΑ

Name: E26 - Sir Jamsetjee Jeejeebhoy Parsi Benevolent

Institute

Description:

Owner: Sir Jamsetjee Jeejeebhoy Benevolent institute Trust

Usage: Institution G+4 Topography:

> The ground floor of the building forms a part of an arcade with arched openings. The building façade has features such as semicircular arches, double columns in relief with distinct base, projecting cornice bands at each floor, decorative cast iron railing etc.

Grade: IJΑ









Name: E27 - Mumbai Bank Bhuvan

Owner:

Usage: Commercial Topography: G + 3

Description:

The ground floor of the building forms a part of an arcade with arched openings. The buff stone clad building with recessed rectangular openings

balustrades etc.

Grade: IJΒ



Name: E28 - Fine Mansion

Owner:

Usage: Commercial Topography: Description:

The buff stone clad building has features such as cornice bands at double floor height, double height columns with Corinthian capitals etc.

Grade: IΙΒ



E29 - BNG House Name:

Owner:

Usage: Commercial

Topography:

Description:

Newly constructed building with no trace of the

original building

IJΒ Grade:

Name: E30 - Davar House

Owner:

Usage: Commercial Topography: G + 5

Description:

Newly constructed building with no trace of the

original building



Name: E31 – Saheb Building

Owner:

Usage: Commercial Topography: G + 5

Description:

New construction has taken place with no trace of the

old building.

Grade: II B



Name: E32 - Ravi Building

Owner:

Usage: Commercial Topography: G + 6

Descrition:

New construction has taken place with no trace of the

old building

Grade: II B



Name: E33 – Shreyas Chambers

Owner:

Usage: Commercial Topography: G + 4

Description:

The ground floor of the building forms a part of an arcade with arched openings. The building derives influence from Neo Classical style of Architecture with floor cornice bands supported on brackets, double height columns with base and Corinthian

capitals, arched openings etc

Grade: II B



Name: E34 – Deo Kripa

Owner: -

Usage: Commercial Topography: G + 5

Description:

New construction has taken place with no trace of old

building.



Name: E35 - Bachubhai

Owner:

Usage: Commercial Topography: G + 4

Description:

New construction has taken place with no trace of the

Grade: IΙΒ



Name: E36 - Chhatrapati Shivaji Terminus

Owner: Central Railway

Usage: Central Railway Headquarters and railway station

building

Topography: Description: Main building G+2+attic floor, with part terrace

This is the largest public building in Mumbai playing a significant role in urban life. Victorian Gothic Revival architecture with traditional Indian features. Its remarkable stone dome, turrets, pointed arches, and eccentric ground plan is the striking features. Currently, it is designated as a World Heritage

Monument.

Grade:

Name: E37 - Energy House

Owner:

Usage: Commercial Topography: G + 4

Description:

Derives influence from Art Deco style of Architecture with symmetrical stone façade, rectangular openings,

horizontal bands etc

Grade:





Name: E38 - Indian Global House

Owner:

Usage: Commercial Topography: G + 7

Description: Newly constructed building with no trace of original

building

Grade: IJΒ



Name: E39 - Himalaya House

Owner:

Usage: Commercial Topography: G +4

Description:

Derives influence from Art Deco style of Architecture with rectangular openings, round corners, horizontal balcony bands, vertical bands etc.

Grade:

Name: E40 - Sitaram Building

Owner:

Usage: Residential and Commercial

Topography: G + 4

Description:

Group of 5 building in a complex covering the corner plot. Each building has central and side wings higher than balcony bay. Derives influence from Vernacular and Neo classical style of Architecture. The building has features as corner façade with a high pediment arched openings with keystone, pediments and arched entrance with decorative tympanum. Many transformations have been done to this structure.

Grade:





Fort House		107
. OIL HOUSE		Common Ref No: 107
		Card No: 149
7		Ward (Part): A (Part II)
		CS No: 897(Fort Division)
		Plot Area: NA
		B U Area: - Date: 14/04/2005 Recorded by: Sonal Modak Reviewed by:
		Date: 14/04/2005
		Recorded by: Sonal Modak
		Reviewed by:
		M. i. M. i. Mariana
		Int: Permission denied Ext: Sonal Modak, Prachi Merchant
		Photo Ref: 107_Fort House Location Plan
新了用基金工人物 (600 mill) 中华		
1.0	Name of Promises	Denomination
1.1	Name of Premises	
1.2	Earlier Name	Fort House
1.3	Built in:	NA Extension -
	+	Date
2.0		Access
2.0	Main	Dr. Dadabhai Nowroji Road - Pedestrian
2.2	Subsidiary	-
<u> </u>	Substituti	
3.0	<u> </u>	Ownership pattern
3.1	Present	Indeterminable
3.2	Past	Indeterminable
3.3	Status	Indeterminable
0.0		
4.0		Use
4.1	Present	Commercial - Offices
4.2	Past	Commercial - Offices
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Townscape (Manmade)	Located along a row of buildings in a Heritage precinct with similar height and features as
		per urban design regulations laid down for the entire area.
		Main access is from Dr. Dadabhai Nowroji Road on the western road front.
5.2	Architectural Description	The building has been completely transformed. There is no trace of the original building.
5.2	Architectural Description	Planning Indeterminable.
		Features
		The building has been totally transformed. There is no trace of the original building.
		Style
		Influence of Classical style features.
5.3	Intrinsic	-
5.4	Value Classification	Nil Recommended II A
		grade:
6.0		Topography
6.1	Floors	G+4
7.0		Complemention
7.0	Dlinth	Construction
7.1	Plinth	
7.2	Walls	
7.3	Floor Stairs	-
7.4 7.5	Openings	The building is reconstructed in RCC
7.6	Roofing	1
7.7		1
	LATICULATION	
	Articulation Finishes	
7.8	Finishes	Movable
		Movable -
7.8	Finishes	Movable - Immovable
7.8 7.9	Finishes Interiors (Movable & Immovable)	
7.8	Finishes	


ort House		107	
	Buildings/ Landscape		
8.0		Services & Utilities	
8.1	Lighting	Indeterminable	
8.2	Ventilation	Indeterminable	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Indeterminable	
8.7	Other (HVAC/BMS/Security Systems)	Split and window unit air-conditioners.	
9.0		Condition	
9.1	Plinth		
9.2	Walls		
9.3	Floor		
9.4	Stairs	The building is reconstructed.	
9.5	Openings	The building is reconstructed.	
9.6	Roofing		
9.7	Articulation & Finishes		
9.8	Services		
9.9	Out Buildings	•	
9.10	Overall Conditions	- Maintenance level -	
10.0		Transformation	
	Form	The building is newly constructed	
	Structure		
	Articulation & Finishes		
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: The building was totally reconstructed after the fire in 1982 retaining the front façade. The building was built by the billionaire philanthropist, Sir Jamshetji Jeejeebhoy. The building with facing in porbunder stone, fronted the western Fort ramparts and was enclosed in front and separated from street by a large courtyard. The home featured three drawing rooms, bedrooms and dining rooms. Among the three drawing rooms one was in the English style with exquisite Waterford chandeliers, another in the French style with Bohemian glass and gilt couches and a third with Chinese inlaid furniture. In 1914 the building was leased to Frederick Evans, Donald Fraser and Duncan Fraser of the English firm, Evans Fraser, who remodelled the façade by adding a pediment and portico. The 1982 fire gutted the annexe completely and Fort House itself substantially. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.	



Porch forming the part of the common arcade supported on double columns.



Pediment with decorative band, dentils supported on columns with floral pattern capitals etc



Anand Bhava	ın	108
7.6	Roofing	Steel truss sloping roof with wooden planks and mangalore tiles above.
7.7	Articulation	Floral cast iron column capitals. Fluted cast iron columns. Wooden decorative corbels and brackets.
7.8	Finishes	Walls plastered and painted from externally as well as internally. Variety of flooring finishes like vitrified tiles, marble mosaic tiles, marble, granite, vinyl carpets etc. have been used.
7.9	Interiors (Movable & Immovable)	Cast iron columns painted. Door/window shutters painted. Movable
		Immovable
7.10	Compound/ Fence/ Gate	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-
8.0		Services & Utilities
8.1	Lighting	Adequate daylight is supplemented with artificial lighting equipments wherever necessary.
8.2	Ventilation	Adequate ventilation through windows and verandahs supplemented with electrical fans as required.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	No traces.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units added in few areas.
9.0		Condition
9.1	Plinth	Fair – Covered with planter boxes. Painted over.
9.2	Walls	Poor – Not maintained. Minor cracks on internal walls observed. Seepage, leakage seen. Plant growth on external façade.
9.3	Floor	Fair – All wooden members painted over.
9.4	Stairs	Fair – Treads have become slippery due to wear and tear. Railing in bad condition with rusted members.
9.5	Openings	Fair – Most of the door/window shutters are replaced.
9.6	Roofing	Poor – Timber members are deteriorated in some areas due to leakage. Dampness observed.
9.7	Articulation & Finishes	Fair – No evident damage except for layers of paint and plant growth.
9.8	Services	Poor – Broken pipes resulting in leakages and damp walls.
9.9	Out Buildings	
9.10	Overall Conditions	Fair Maintenance level Fair
10.0		Transformation
	Form	Addition of entire fourth floor.
	Structure	Addition of mezzanine on ground floor level. Some of the large timber beams have been replaced by steel sections.
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
		College, building forms part of C1 zone.
12.0		Additional Notes/ References/ Documents available
12.0		Additional Notes' References' Documents available Additional Notes: The building was owned by a Japanese bank prior to World War II. With the defeat of Japan in World War II, it was taken over by Indian government. Later it was given to Dr. Babasaheb Ambedkar to start an educational institute. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.


Anand Bhavan 108



Side façade with rusticated stone cladding, arched openings etc



Arched window opening with double glazed and louvered shutters, sill band etc



Corrugated tread and riser detail



Arcade with arched openings forming a pedestrian pathway



Wooden sloping roof supported on truss



Staircase lobby with cast iron railing, lift cage with wooden cladding etc

Anand Bhavan 108





Cast Iron Bracket supporting the roof system



Corner detail of façade articulation



Internal view with wooden roof supported on round cast iron columns with decorative column capital



Detail of the bracket supporting the wooden roof. Wall with seepage marks due to neglected state.



Column with decorative capital and bracket

Ardershir	Dadibhoy Dadiseth Agiary (Kadmi)		109
		Common Ref No: 109	last.
		Card No: 151	Ghoga Street
		Ward (Part): A (Part II)	The state of the s
		CS No: 440(Fort division)	1000
		Plot Area: 1037.63 sq .m	
10 1		B U Area: -	The strong was a strong with the strong was a strong was a strong with the
		Date: 19/05/01	
/		M = 1111 1111 1111	
1		Recorded by: Prachi Merchant	40 40 40 40 40 40 40 40 40 40 40 40 40 4
1-3	DINSHAW	Reviewed by:	NAMA (30) (36) (4)
THE 35 LOAD	OPTICIANS OPTICIANS	Int: Refer#	AND
100	The state of the s	Ext: Refer #	422 7 00 00 00 00
		Photo Ref.: 109_Dadyseth Agiary	
			Armet Basicans F V C C S FFFF
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Ardershir Dadibhoy Dadiseth Agiary (Kadı	mı)
1.2	Earlier Name	-	I F to the Date I
1.3	Built in:	1803	Extension Date: -
0.0		A	
2.0	Main	Access	
2.1	Main	Dr. Dadabhai Nowroji Road	
2.2	Subsidiary	Janmabhoomi Marg (Old Ghoga Street)	
2.0		Own and in wattom	
3.0 3.1	Present	Ownership pattern	tash BehramTrust (Trustees: Ratan Lalkaka,
3.1	Fiesent	Veera Chokshi, Behram Ardeshir, Mehern	
3.2	Past	Indeterminable	OSIT Oranwalia)
3.3	Status	Trust	
0.0	Cidido	11400	
4.0		Use	
4.1	Present	Religious	
4.2	Past	Religious	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	The Agiary is situated on a corner plot, dia	agonally behind Flora Fountain, at the junction of
		Dr. Dadabhai Nowroji Road and Janmabh	
			he historic Dr. Dadabhai Nowroji Road junction is
5.0	14.17.4.18.4.6	reminiscent of the early 19th century archit	ecture character
5.2	Architectural Description	Planning & Features	atom and the attended Manager Challes C.
		uith large breeketed roof everbage. A lar	cture covered by a hipped Mangalore-tiled roof ge lean-to-roof extends from the main structure
		upto the boundary wall.	ge lean-to-roor exterios from the main structure
		The five feet high plinth and ten feet deep	entrance verandah is accessed by an
		emphasized flight of steps.	childride verandan is decessed by an
			nns and emphasized brackets, leads to the main
		Ceremony hall, which accommodates the	,
			area equivalent to that of the Verandah and a par
		of the Ceremony hall, is located on the first	st floor.
		Ablution Pavilion (kasti enclosure):	
			space of the Agiary plot, between the main
			ommodates a square well and glazed ablution
			k basalt stone. The well is clad with glazed white
		ceramic tiles. The area around the well is	paved with Kotan stone.
		Kebla:	on eighteen feet in width with its enter an the
			an, eighteen feet in width with its entry on the
			outh walls. The walls are clad with white glazed I with a masonary dome further topped with
			tah stone with prominent pavis. The center of the
			ian stone with prominent pavis. The center of the fire vessel), surmounted by a German silver tray
			a stone pedestal (idhora). The walls are adorned
			ad of bulls) of a German silver stalk. Large bells
			silver "chattar" (umbrella) is suspended over the
		fire.	, , , , , , , , , , , , , , , , , , , ,
		Prayer Hall:	

Araersnir L	Dadibhoy Dadiseth Agiary (Kadmi)	The definition of the Drayer anger is unique. The eight feet doon anger with macanage is
		The definition of the Prayer space is unique. The eight feet deep space with masonary inbuilt seating is provided along the east wall of structure. It is open above the sill level to draw abundant light and ventilation from the rear open space. A glazed hood is provided at the eaves level for privacy. The prayer spaces along the north and south walls, are about fifteen feet deep. Ceremony Hall: It is accessed from the Verandah as well as from the steps along the northeast corner, within the lean-to-roof. The front ceremony hall is about twenty feet and fifteen feet high ceiling. The hall has a timber planked false ceiling. A part of the area above the Ceremony hall accommodates the Trust office, while the remaining area accommodates light and vent wells through the false ceiling upto the hipped roof.
		The Baj Hall is located to the south of the plot within the ancillary structure. There is a six feet wide passage between the Agiary and ancillary structure. The Baj room is about ten feet deep with simple teakwood false ceiling. Walls are painted with oil based emulsion paint. Flooring is in dressed basalt stone with optimally laid pavis.
		ave a congregation Hall. (Boiwala's) in serving: Within the side ancillary structure, accommodated along ground are the stores, kitchen and Baj rooms along with a straight flight timber staircase, which leads to the first floor. It provides access to the rest room for priests, storage etc. There is no permenant residence of the priest in serving. Curtilage Structure (Wells etc): It includes the square well in the front open space and toilet and bath areas in the rear open space (along southeast corner of plot). The rear open space is deep enough to draw light and ventilation.
		Style The structure derives influence from pre-industrial Vernacular style architecture.
5.3 5.4	Intrinsic Value Classification	- A(arc),A(his),A(cul),B(per),B (des), B(uu),C(seh),D(bio) Recommended grade II A
6.0 6.1	Floors	Topography G structure, part G+2, Ancillary structure G+1
0.1	110010	outdotals, part 0.2, raioliary saudeties 0.1
7.0	Dist	Construction
7.1	Plinth	Five feet high stone plinth for the main Agiary structure, with marble flooring. The ancillary structures have a minimal nine-inch plinth, lined with dressed black basalt stone.
7.2	Walls	Composite structure with timber trabeated frame accommodated within load bearing brick masonry walls.
7.3	Floor	Simple timber framed floor with timber beams and teakwood bridging joists. Shahabad stone tile has been used for the part first floor.
7.4	Stairs	A doglegged masonry staircase with timber baluster and handrail, at the north end of the structure, leads to the first floor Trust office.
7.5	Openings	The windows are teakwood framed, four shuttered, with glazing for those at the upper level, while the lower level windows are teakwood paneled with safety iron rods. The doorways have huge teakwood paneled shutters. The rear opening above the sill level has glazed hood, bracketed at the eaves level.
7.6	Roofing	Timber trussed roof with teakwood rafters, purlins, boarding, battens and Mangalore tiles.
7.7	Articulation	A part of the Ceremony hall has false ceiling that accommodates light and vent wells. Externally bracketed roof overhangs, roof configuration, elaborate compound wall design, rear glazed hoods, internal arched openings, light/ vent wells, column with brackets and ceiling are well articulated along with accessories used along interiors.
7.8	Finishes	The walls are externally cement painted, and internally finished with oil based emulsion paints. Timber members are oil painted while the flooring is in marble.
7.9	Interiors (Movable & Immovable)	Movable Timber photo frames, benches, cupboards. Immovable
7.10	Compound/ Fence/ Gate	About twelve feet high brick masonry wall elaborate in design by way of profile and openings is plastered and has emphasized piers topped with capitals. It supports a lean to roof extending from the verandah of the main structure to the boundary wall.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Toilets and bath blocks in brick masonry with lean to Mangalore tile sloping roof.
8.0		Services & Utilities
8.1	Lighting	Adequate in prayer space and ceremony hall through front verandah and light wells.
8.2	Ventilation	Adequate cross ventilation in Prayer space. Vent wells for ceremony hall. Inadequate in

Ardershir I	Dadibhoy Dadiseth Agiary (Kadmi)	109		
		Baj room.		
8.3	Electricity	BEST		
8.4	Water Supply	Well water and piped water through the MCGM connected supply.		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	-		
8.7	Other (HVAC/BMS/Security Systems)	-		
9.0		Condition		
9.1	Plinth	Fair		
9.2	Walls	Fair		
9.3	Floor	Fair		
9.4	Stairs	Fair		
9.5	Openings	Fair		
9.6	Roofing	Fair		
9.7	Articulation & Finishes	Fair		
9.8	Services	Fair		
9.9	Out Buildings	Fair		
9.10	Overall Conditions	Fair Maintenance level Fair -		
10.0		Transformation		
	Form	-		
	Structure	-		
	Articulation & Finishes	Excessive glazed tile dado has effectively diminished the austerity of the religious structure		
11.0		DP Remarks/ Perceived Threats		
		Building forms part of C1 zone		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes:		
		References: # The Study conducted by Pankaj Joshi Consultants with support from Mr Jamshed Guzder, Merwanji D M Jeejeebhoy Trust and Mrs Ketie Mehta, Gulestan and Rustom Billimoria Charitable Trust through auspices of Mr Cyrus Guzder.		



Verandah with arched openings, wooden roof and old light fittings



Double height wooden paneled ceiling with skylight above



Entrance to the Agiary through extended wooden sloping chajja supported on wooden brackets



Staircase with intricate wooden railing



Backyard with structures added later




Square Well finished with ceramic tiles

Alice hui	Iding - Stone Arch			110
Alloc Dul	Ming - Otolic Aleli	Common Ref No: 110		<u>。</u> 110
		Card No: 152		Murzban Road
		Ward (Part): A (Part II)	- /	Murzban Kodo
		CS No: - 696 (Fort Division)	- /	
		Plot Area: Indeterminable		1 1 2 1/10/20
100		B U Area: -	A Paris	1.1 1/2 10
		Date: 16/12/2004	- Maria	
			- 100 M	. 5/ // 1
100		Recorded by: Zankhana Prajapati	0.0	
		Reviewed by:		
9 (6)		Int: NA	7	Dr. Dacabhai Nounoi Road
		Ext: Zankhana Prajapati, Sonal Modak.		Dadah To Bo
-0		Photo Ref: 110_Alice building stone arch.	noga sy	nai No.
			Street	MOJI Ro
				AN AN
			1000	ation Plan
1.0		Denomination	LUCa	ILIUII FIAII
1.1	Name of Premises	Alice building - Stone Arch		
1.2	Earlier Name	Alice building		
1.3	Built in:	1902	Extension -	
			Date	
2.0		Access		
2.1	Main	Dr. Dadabhai Nowroji Road		
2.2	Subsidiary	Ghoga street		
2.0		Ournership nettern		
3.0 3.1	Present	Ownership pattern Indeterminable		
3.2	Past	Indeterminable		
3.3	Status	Owner		
0.0	Otatao	- Cimor		
4.0		Use		
4.1	Present	Hawkers have occupied the arcade.		
4.2	Past	-		
4.3	Usage	Daily		
- A		0:::::		
5.0 5.1	Tourseens (Manmada)	Significance & Value Classification Arcade is the remnant of the entire original by	wilding and it is along	Dadabbai Nauraii Daad
0.1	Townscape (Manmade)	Access is from D. N. Road and Ghoga stree		Dadabilai Nowioji Road.
5.2	Architectural Description	Planning	ι.	
0.2	a di modulari Bodonpuon	It is located along the length of Dadabhai No	owroji Road.	
		It is a ground structure semicircular arches a	arising from impost in b	ouff basalt stonewalls and
		columns are horizontally rusticated.		
		Features	حادموا مسمسامه اسماله	
		The arcade is in buff basalt stone with its warrising from impost, have decorative flora		
		Building'	ii keystorie and marbi	e lablet eligiaved Alice
		Style		
		Indeterminable.		
5.3	Intrinsic	-		
5.4	Value Classification	B(per)	Recommended	III
			grade	
6.0		Tonography		
6.0 6.1	Floors	Topography G		
V. 1	1 10013			
7.0		Construction		
7.1	Plinth	No plinth.		
7.2	Walls	Buff basalt stonewalls and columns horizont	ally rusticated.	
7.3	Floor	Shahabad paving is present.		
7.4	Stairs	-		
7.5	Openings	Semicircular arched openings.		
7.6	Roofing	-		
7.7	Articulation	Floral keystone.		
7.8	Finishes	Buff basalt stone.		

Alice buil	ding - Stone Arch	110	
7.9	Interiors (Movable & Immovable)	Movable	
	,	-	
		Immovable	
7.10	Compound/ Fence/ Gate	<u>.</u>	
7.10	Curtilage/ Unbuilt space/ Out Buildings/		
7.11	Landscape		
8.0		Services & Utilities	
8.1	Lighting	-	
8.2	Ventilation	•	
8.3	Electricity	-	
8.4	Water Supply	-	
8.5	Drainage (Plumbing & Sanitation)	-	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	-	
9.0		Condition	
9.1	Plinth	-	
9.2	Walls	Poor - blackening of stone, plant and moss growth, stones are weathering, dust	
		accumulation, has lots of holes and dent, nailed surface and condition worsened by	
		hawkers.	
9.3	Floor	Poor- not maintained, stone missing, uneven.	
9.4	Stairs	•	
9.5	Openings	Poor- blackening of stone, plant and moss growth.	
9.6	Roofing	-	
9.7	Articulation & Finishes	Weathered key stone and blackened wall surfaces.	
9.8	Services	•	
9.9	Out Buildings		
9.10	Overall Conditions	Poor. Maintenance level Neglected.	
10.0		Transformation	
10.0	Form	The arcade is the only remnant of the original building.	
	Structure	-	
	Articulation & Finishes		
11.0		DP Remarks/ Perceived Threats	
		The arcade is part of the plot marked for Receiving Station.	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		Alice Building was designed by Munchershaw Chandabhoy and constructed around 1902.	
		Gutted by fire in 1973. Only the arcade of the original building remains. References:	
		NTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation.	
		Onuclares noted for Conscivation.	
	1		







Column base with rusticated stone cladding

Thomas Co	ook building		111
momas oc	on building	Common Ref No: 111	
		Card No: 153	
		Ward (Part): A (Part II)	
			703
1		CS No: 744 (Fort division)	
1/2		Plot Area: 993.31 sq m.	
5/	10	B U Area: -	706 VI
FI:		Date: 11/02/05	
		Recorded by: Prachi Merchant	Transit a stay of the stay of
		Reviewed by:	
		Int: Prachi Merchant, Zankhana Prajapati.	
		Ext: Prachi Merchant, Zankhana Prajapati.	
	Thomas Cook	Photo Ref: 111_Thomas Cook building.	Location Plan
yes		-	Location Fian
1.0		Denomination	
1.1	Name of Premises	Thomas Cook building	
1.2	Earlier Name	Thomas Cook building	
1.3	Built in:	Indeterminable	Extension - Date
2.0		Access	
2.1	Main	Dr. Dadabhai Nowroji Road- pedestrian	
2.2	Subsidiary	Amrit Keshav Naik Marg	
3.0		Ownership pattern	
3.1	Present	Private – Thomas Cook India Ltd	
3.2	Past	Private – Thomas Cook India Ltd	
3.3	Status	Owner – multi-tenanted	
4.0		Use	
4.1	Present	Commercial – Banks, tourism offices, other	offices, dispensary.
4.2	Past	Commercial - Offices	
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)	The building stands on Dr. Dadabhai Nowro The building is accessed through an arc continuous arcade on the main street.	iji Road and forms a part of the streetscape. ade on the east side, which forms a part of
5.2	Architectural Description	the east-west direction with the smaller faça The arcade internally is highly ornamented.	-
		The building is accessed through two entrar	
		The building has sloping roofs over difference	ent sections. The rear west side block is lower
			e has the north side bay higher than the rest of
		the wings. The building is stepped at the rea	ar. igh a passage leading into a central staircase
		lobby.	igii a passage leadilig liito a celitial stalicase
		,	of the staircase lobby. The lobby opens into a
			obby area overlooking the terrace. The front side
		office on the fourth floor opens into a private	e terrace.
		The toilet block is located besides the sta	ircase area on the east side. The fire escape
		staircase opens into the rear side of the buil	
		The building has service <i>gullies</i> on the side.	
		Features	et of an arranda with archad ananings on aguara
			rt of an arcade with arched openings on square d internal semicircular arched openings with pattern hands and friezes
		The rest of the floors are set marginally be	hind with a continuous step balcony with stone
		row of double columns.	are defined by columns and the top floor has a
			emicircular pediment openings with emphasized
			els, stone balustrade, human face decorative
		springing arch point, floor cornice bands, ca	ist iron railing for step balconies, brackets. Dray with a dome on top and arched opening with
		a pediment, decorative spandrel, keystone,	
		Side and rear portion openings have woode	
L		2.22 and roar portion openings have woods	o.opg oriajjao.

nomas Co	ook building	11
		Internal cast iron columns with cast iron brackets. Staircase landing and third floor passag
		overlooking the terrace, steel beams supported with wooden and cast iron carved brackets Style
		The building derives influence from Neo Classical style of architecture.
5.3	Intrinsic	-
5.4	Value Classification	A(arc), B(per), E, F, G(grp) Recommended grade II A
0.1	Value Classification	7 (dro), 5(por), 2, 1, 5(grp)
6.0		Topography
6.1	Floors	Main structure - G+4 with basement and terrace , Rear block - G+3
7.0		Construction
7.1	Plinth	High stone plinth with plinth protection band.
7.2	Walls	Load bearing brick walls.
7.3	Floor	Jack arch floor construction with cast iron columns with brackets and cast iron beams.
7.4	Stairs	Main 'C' shaped staircase with a lift well in the center, with wooden risers, treads, new
		post and railing.
		Ladder connecting fourth floor to the terrace.
		Rear open well cast iron staircase as a fire escape opening into the subsidiary lane.
7.5	Openings	The arcade has rectangular openings with the ground floor with an internal colonnade wi
		arched openings.
		Staircase openings are full height arched windows with ventilators, louvered double hinge
		and outer paneled shutters and intricate cast iron railing.
		Arched window full height openings with glazed paneled and louvered double shutters with the sales of the sal
		ventilators.
7.6	Deefer	Rear and side rectangular openings.
7.0	Roofing	High pitched Mangalore tile roof structure with wooden supporting members. Part RCC slab and beam structure.
		Part terrace is covered with a shed.
7.7	Articulation	Arched colonnade, balconies with stone balustrade, cornice bands, etc.
7.8	Finishes	Walls are clad with stone on the external side, and plastered and painted from both sides.
1.0	Fillisties	Floor is finished with cement tiles.
7.9	Interiors (Movable & Immovable)	Movable
1.5	interiors (wovable & inimovable)	- Immovable
7.10	Compound/ Fence/ Gate	The building is directly accessed from the colonnade.
	· ·	The service gullies on either side of the building have MS gates.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	The side gullies have old trees, unpaved areas.
	Landscape	Generator and substation have been installed on the rear side on the building
8.0		Services & Utilities
8.1	Lighting	Adequate light from terrace, balconies, supplemented by artificial light.
8.2	Ventilation	Adequate ventilation supplemented by artificial ventilation.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
0 =	Drainage (Plumbing & Sanitation)	MCGM
8.5		
8.6	Fire Precaution	Individual tenants have installed fire extinguishers in their offices, rear fire escap
8.6	Fire Precaution	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase.
		Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed.
8.6	Fire Precaution	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase.
8.6	Fire Precaution	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security.
8.6	Fire Precaution	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition
8.6 8.7 9.0	Fire Precaution Other (HVAC/BMS/Security Systems)	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system.
9.0 9.1	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair
9.0 9.1 9.2	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair – Internal partitions added to suit individual requirements.
9.0 9.1	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor.
9.0 9.1 9.2 9.3	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor. Mezzanine floors in steel and wood have been added in some floors.
9.0 9.1 9.2 9.3	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor. Mezzanine floors in steel and wood have been added in some floors. Fair
9.0 9.1 9.2 9.3	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor. Mezzanine floors in steel and wood have been added in some floors. Fair Poor – The openings have been blocked to accommodate air conditioning units, windo shutters have been changed, grills have been added. The front façade opening, of such a
9.0 9.1 9.2 9.3 9.4 9.5	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor. Mezzanine floors in steel and wood have been added in some floors. Fair Poor – The openings have been blocked to accommodate air conditioning units, windo shutters have been changed, grills have been added. The front façade opening, of such a important building, has been maintained very insensitively.
9.0 9.1 9.2 9.3 9.4 9.5	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings Roofing	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor. Mezzanine floors in steel and wood have been added in some floors. Fair Poor – The openings have been blocked to accommodate air conditioning units, windo shutters have been changed, grills have been added. The front façade opening, of such a important building, has been maintained very insensitively. Fair – chajjas have been replaced.
9.0 9.1 9.2 9.3 9.4 9.5	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor. Mezzanine floors in steel and wood have been added in some floors. Fair Poor – The openings have been blocked to accommodate air conditioning units, windo shutters have been changed, grills have been added. The front façade opening, of such a important building, has been maintained very insensitively. Fair – chajjas have been replaced. Poor – All the features are painted. The materials are difficult to identify. Few articulations
9.0 9.1 9.2 9.3 9.4 9.5 9.6 9.7	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings Roofing Articulation & Finishes	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor. Mezzanine floors in steel and wood have been added in some floors. Fair – The openings have been blocked to accommodate air conditioning units, windor shutters have been changed, grills have been added. The front façade opening, of such a important building, has been maintained very insensitively. Fair – chajjas have been replaced. Poor – All the features are painted. The materials are difficult to identify. Few articulation features are broken
9.0 9.1 9.2 9.3 9.4 9.5 9.6 9.7 9.8	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings Roofing Articulation & Finishes Services	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor. Mezzanine floors in steel and wood have been added in some floors. Fair Poor – The openings have been blocked to accommodate air conditioning units, windo shutters have been changed, grills have been added. The front façade opening, of such a important building, has been maintained very insensitively. Fair – chajjas have been replaced. Poor – All the features are painted. The materials are difficult to identify. Few articulations
9.0 9.1 9.2 9.3 9.4 9.5 9.6 9.7	Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings Roofing Articulation & Finishes	Individual tenants have installed fire extinguishers in their offices, rear fire escap staircase. Individual tenants have installed AC's in their offices with outdoor units installed. Manual security and individual tenant security. Condition The interior of the building is completely altered, retaining only the main structural system. Fair Fair – Internal partitions added to suit individual requirements. Fair – Steel sections added to strengthen the floor. Mezzanine floors in steel and wood have been added in some floors. Fair – The openings have been blocked to accommodate air conditioning units, windo shutters have been changed, grills have been added. The front façade opening, of such a important building, has been maintained very insensitively. Fair – chajjas have been replaced. Poor – All the features are painted. The materials are difficult to identify. Few articulation features are broken

Thomas C	ook building	11
10.0		Transformation
	Form	•
	Structure	Projecting balconies are enclosed. Mezzanine floors have been added.
	Articulation & Finishes	Openings are blocked, window shutters have been changed, grills have been added. Terrace on the second floor has been partly covered. Chajja covering have been replaced. Hoardings have been installed insensitively in the openings.
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone.
12.0		Additional Notes/ References/ Documents available
		Additional Notes: References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc.



Arch of the arcade with decorative scroll bracket keystone and floral




Side View of the building with rectangular opening, bands etc



Arched window opening with human face motifs at springing point, keystone and cornice band above.



Side octagonal tower with a dome and highly decorative window pediment with floral pattern, balustrade etc



Front façade with arched openings, balconies, bands etc



Opening wit pediment above with dentils and decorative motifs in the tympanum



Articulation at the entrance with intricate floral pattern



111

Arcade with jack arch roof



Decorative stone frieze detail as the arch band



Cast iron railing detail

Thomas Cook building 111



Cast iron bracket supporting the floor



Wooden staircase with decorative railing



Wrought iron column and beam structure with decorative capital

Sir lamosti	ee Jeejeebhoy Parsi Benevolent Institut	Δ	112	
on Jamsey	ee Jeejeebnoy Parsi Benevolent institut			
		67	mear I I	
		Card No: 154		
-		Ward (Part): A (Part II)	So James 1 July Demond Institute of the State of the Stat	
	The state of the s	CS No: 745	230,	
		Plot Area: 141.3 sq. m	a Lane	
		B U Area: -	Gola	
		Date: 27/12/2004	So Josef Mary Statement of The Statement	
		Recorded by: Arun Wadhwa	Year 1912 \$50 r0336 11 V	
		Reviewed by:		
		Int: Arun Wadhwa, Zankhana Prajapati	Evens Frener &Co.	
		Ext: Arun Wadhwa, Zankhana Prajapati	897	
The same		Photo Ref.		
1900		THOIS FIGH.	Section and Section 2	
		8 693	395 W. A	
		5 . lost "-	Location Plan	
1.0		Denomination	Location Flan	
1.1	Name of Premises	Sir Jamsetjee Jeejeebhoy Parsi Benevolent Institute		
1.2	Earlier Name	Sir Jamsetjee Jeejeebhoy Parsi Benevolent Institute		
1.3	Built in:		ion Date: -	
1.0	- June III.	LAIGHS!		
2.0		Access		
2.1	Main	Dr. Dadabhai Nowroji Road		
2.2	Subsidiary	Gola lane		
		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
3.0		Ownership pattern		
3.1	Present	Sir Jamsetjee Jeejeebhoy Benevolent institute Trust		
3.2	Past	Sir Jamsetjee Jeejeebhoy Benevolent institute Trust		
3.3	Status	Trust		
4.0		Use		
4.1	Present	Institution – Primary school, Parsi Panchayat office		
4.2	Past	Institution – Primary school, Parsi Panchayat office		
4.3	Usage	Daily		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)	The building arcade forms the part of the arcade along		
		It is an important urban landmark and is an excellent example of architecture that respond		
		well to its urban context.	from the Dr Dadahhai Naviraii raad	
		The main entrance to the building is through the arcade and the rear entrance from the courtyard.	e from the Dr Dadabhai Nowroji road	
5.2	Architectural Description	Planning		
5.2	Architectural Description	The building is accessed through the arcade from the s	outh side leading to an entrance	
		porch	out old loading to all chilands	
		The building is a rectangular 'C' shaped in plan enclosing	ng an internal open courtvard	
		The building has a verandah running along the inner sid		
1		the classrooms	ao iaonig and obariyara, to aboost	
		the classrooms The building has a staircase in each wing. Toilets are lo		
		The building has a staircase in each wing. Toilets are lo Features	ocated on the rear wing.	
		The building has a staircase in each wing. Toilets are lo Features The buff stone clad building has semicircular arched pe	ocated on the rear wing.	
		The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched per openings, supported on circular double columns	ocated on the rear wing.	
		The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched per openings, supported on circular double columns The arcade is clad with buff rusticated stone	ocated on the rear wing.	
		The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and and D	ocated on the rear wing. Indestrian arcade and upper floor Description or the control of the c	
		The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Columns have distinct base and ported to projecting comice bands at ach floor level, decorative of the projecting comice bands at ach floor level, decorative of the projecting comice bands at ach floor level, decorative of the projecting comice bands at ach floor level, decorative of the projecting comice bands at ach floor level, decorative of the projecting comice bands at ach floor level.	ocated on the rear wing. Indestrian arcade and upper floor Description or the control of the c	
		The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Columns have distinct base and period comice bands at ach floor level, decorative of building facade.	ocated on the rear wing. Indestrian arcade and upper floor Description or the control of the c	
		The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Columns have distinct base and peroperting comice bands at ach floor level, decorative of building facade.	ocated on the rear wing. edestrian arcade and upper floor printhian order capital on each floor east iron railing punctuate the	
5.3	Intrinsic	The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Columns have distinct base and period comice bands at ach floor level, decorative of building facade.	ocated on the rear wing. edestrian arcade and upper floor printhian order capital on each floor east iron railing punctuate the	
5.3 5.4	Intrinsic Value Classification	The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched per openings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Color Projecting comice bands at ach floor level, decorative of building facade. Style The building derives influence from Gothic style of Archem.	ocated on the rear wing. Indestrian arcade and upper floor Indestrian arcade	
5.3 5.4	Intrinsic Value Classification	The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Columns have distinct base and peroperting comice bands at ach floor level, decorative of building facade.	ocated on the rear wing. Indestrian arcade and upper floor Indestrian arcade	
		The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched per openings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Color Projecting comice bands at ach floor level, decorative of building facade. Style The building derives influence from Gothic style of Archem.	ocated on the rear wing. Indestrian arcade and upper floor Indestrian arcade	
		The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Comprojecting comice bands at ach floor level, decorative of building facade. Style The building derives influence from Gothic style of Arched A(arc), A(his), B(per), B(des), B(uu), C(seh), E, F	ocated on the rear wing. Indestrian arcade and upper floor Indestrian arcade	
5.4		The building has a staircase in each wing. Toilets are long features The buff stone clad building has semicircular arched per openings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Color Projecting comice bands at ach floor level, decorative of building facade. Style The building derives influence from Gothic style of Archem.	ocated on the rear wing. Indestrian arcade and upper floor Indestrian arcade	
5.4 6.0	Value Classification	The building has a staircase in each wing. Toilets are long Features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Comprojecting comice bands at ach floor level, decorative of building facade. Style. The building derives influence from Gothic style of Arch A(arc), A(his), B(per), B(des), B(uu), C(seh), E, F.	ocated on the rear wing. Indestrian arcade and upper floor Indestrian arcade	
5.4 6.0	Value Classification	The building has a staircase in each wing. Toilets are long Features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Comprojecting comice bands at ach floor level, decorative of building facade. Style. The building derives influence from Gothic style of Arch A(arc), A(his), B(per), B(des), B(uu), C(seh), E, F.	ocated on the rear wing. Indestrian arcade and upper floor Indestrian arcade	
6.0 6.1	Value Classification	The building has a staircase in each wing. Toilets are long Features The buff stone clad building has semicircular arched peropenings, supported on circular double columns. The arcade is clad with buff rusticated stone. The columns have distinct base and Doric, ionic and Corprojecting comice bands at ach floor level, decorative obuilding facade. Style The building derives influence from Gothic style of Arch. A(arc), A(his), B(per), B(des), B(uu), C(seh), E, F. Topography G+3 (4th floor added later)	ocated on the rear wing. Indestrian arcade and upper floor Indestrian order capital on each floor Indestrian railing punctuate the Indestrian arcade and upper floor Indestrian arcade arc	

	ee Jeejeebhoy Parsi Benevolent Institute	112	
7.3	Floor	Wooden floor boards supported on wooden rafters and heavy steel girders.	
7.4	Stairs	Three staircases, Main grand 'c' shaped staircase with an open well, with wooden treads	
		and risers	
		One open well staircase in the central wing and a dog legged staircase in the rear wing	
7.5	Openings	Semi circular arched openings, wooden glass paneled shutters with ventilator panel with	
		tracery work.	
		Internal verandah openings with wooden ventilator louvered panels	
7.6	Roofing	Steep sloping pitched Mangalore tiled roof on the rear wing. Front wing with a flat slab	
7.7	Articulation	Arches, cornice bands, double columns with decorative capital	
7.8	Finishes	The external wall is dressed in buff basalt stone, internally walls are finished with plaster	
		and paint	
7.9	Interiors (Movable & Immovable)	Movable	
	,	Numerous large portraits of eminent Parsee personalities who served the institute, old	
		wooden cupboards	
		Immovable	
		Bronze statue of Sir Jamsetjee Jeejeebhoy at the entrance near staircase, Marble bust of	
		Ruttonsee Jeejeebhoy in the entrance hall	
7.10	Compound/ Fence/ Gate	The building arcade abuts the road. No front compound wall. Rear gate and compound wa	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	G+1 sloping roof building to the south serving as a classroom and lunch hall	
	Landscape	or recoping tool banding to the court corving as a stable contraint tand ratio.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light from the large openings, supplemented by artificial light	
8.2	Ventilation	Adequate natural ventilation supplemented by artificial ventilation	
8.3	l .	BEST	
	Electricity		
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	•	
8.7	Other (HVAC/BMS/Security Systems)	Manual security system	
9.0		Condition	
9.1	Plinth	Fair – Seepage and organic growth has been observed at places	
9.2	Walls	Fair	
9.3	Floor	Fair	
9.4	Stairs	Fair	
9.5	Openings	Fair – Windows have been enclosed	
9.6	Roofing	Fair	
9.7	Articulation & Finishes	Fair	
9.8	Services	Fair	
9.9	Out Buildings	Fair	
9.10	Overall Conditions	Fair Maintenance level Low	
3.10	Overall Conditions	i dii indiinteriance lever Low	
40.0		Transformation	
10.0	Form	Transformation	
	Form	No visible changes	
	Structure	No visible changes	
	Articulation & Finishes	No visible changes	
11.0		DP Remarks/ Perceived Threats	
		Secondary School, building forms part of C1 zone.	
12.0		Additional Notes/ References/ Documents available	
12.0			
12.0		Additional Notes:	
12.0		Additional Notes:	
12.0		Additional Notes: - References:	
12.0		References:	
12.0		-	
12.0		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.	
12.0		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture	
12.0		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc.	
12.0		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	
12.0		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai. Christopher W London, Bombay Gothic, India Book HousePvt. Ltd.	
12.0		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	



Buff stone clad building with arched openings with fanlight, decorative balustrade, columns with decorative capitals, cornice bands etc



Grand wooden open well staircase with wood and cast iron decorative railing



Marble Bust



Classroom with wooden ceiling, arched window openings with louvered ventilators




Internal opening articulation in verandah and balconies with wooden columns and louvered trellis work, wooden brackets supporting sloping chajjas, railing etc



Arcade with buff stone rusticated arches and columns with emphasized keystone








Marble tablet in the column of the arcade



Inscription in the base of the arcade column



annoogoo	Nesserwenji Petit Institute	1
		can still be found in the building.
7.4	Stairs	Two staircases.
		The main staircase is a timber spiral open well stair with an elevator shaft. The staircase has
		wooden handrail with spiral steel decorative work and is finished in Kotah stone.
		The secondary stair is a steel spiral staircase to the rear of the building with decorative work
7 5	Openings	The windows on the main façade are slender with pointed arches and floral decorative work
7.5	Openings	
		Window and ventilators have glazed paneled shutters with intricate stained glass work
7.6	Roofing	Timber sloping roof with Mangalore tiles supported on wooden truss
7.7	Articulation	The building is elaborately articulated internally as well as externally with limestone arches,
		decorative column capitals, arch infill, pinnacles, finials, cornices, the bases and capitals of t
		columns
7.8	Finishes	The external walls are clad in exposed grey stone while the interior is plastered and painted.
		External walls have white limestone lining and quoins. Minton tile floor finish
7.9	Interiors (Movable & Immovable)	Movable
1.9	interiors (Movable & Infinovable)	
		Many of the original teakwood tables and chair, original cupboard and shelves for the stacks
		Immovable
		Wooden partitions in the interior.
7.10	Compound/ Fence/ Gate	No compound wall.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	The space that lies to the side of the building is currently being used as a dumping ground.
	Landscape	
	•	
8.0		Services & Utilities
8.1	Lighting	Adequate natural light supplemented by artificial lighting.
	0 0	
8.2	Ventilation	Adequate natural ventilation supplemented with artificial ventilation
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security Systems)	
···	carer (1117 te/2111e/educatly eyeteme)	
9.0		Condition
	Diath	
9.1	Plinth	Fair - the plinth height has reduced due to the footpath along the front wall of the building.
9.2	Walls	Fair
9.3	Floor	Fair
9.4	Stairs	Fair - Broken treads and cracks have been observed at places.
		Balusters have been painted, few unused portions have been observed
9.5	Openings	The windows are in a generally good condition but the frames have been painted over. The
	- F - 19	stained glass has been soiled in many places and needs to be cleaned.
9.6	Roofing	Polished frame and is in good condition.
	Articulation & Finishes	
9.7	ALUCUIAUOTI & FINISNES	Much of the white limestone articulation has weathered and stained as in the cornices,
0.0		pediments, etc.
9.8	Services	Fair
9.9	Out Buildings	Fair
9.10	Overall Conditions	Fair Maintenance level Fair
10.0		Transformation
	Form	-
	Structure	In 1938 several alterations were made and one more floor was added with steel trusses
	Structure	
	A	roofing.
	Articulation & Finishes	Circular wall of the main stair has been clad with ceramic tiles up to half height.
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone
		· · · · · · · · · · · · · · · · · · ·
12.0		Additional Notae:
12.0		Additional Notes:
		- References:



Buff stone clad corner building with highly ornamented façade features



Arch of the arcade with decorative intrados, columns with highly decorative capitals with floral pattern, balconies with decorative brackets etc



Corner Detail of arched openings with floral pattern frieze, bands etc



Façade features such as arched openings with red columns, decorative arch bands, cornice bands, balustrade, round openings etc



Arched opening with black and white painted alternate voussoirs, floral pattern frieze of arch band and column capital, decorative cornice band. Opening with double arch with trefoils, decorative jaliwork and wooden glazed shutters



Stained glass windows from inside



Reading room with coffered ceiling, frieze bands, arched openings and wooden reading chairs



Detail of the column with buff stone and red stone cladding, decorative floral pattern capital.



Marble bust inset in interior wall



Staircase with intricately carved cast iron railing, lined with arched openings



Elevator well around main stair



Tracery detail in windows along the staircase



Internal arched door openings with wooden paneled shutters, ventilators



View of Double height space with an first floor overlooking balcony supported on cast iron columns



Cast iron columns with decorative capitals in floral pattern and inscribed letters



Balcony with minton tile flooring, decorative stone balustrade



Detail of the decorative cast iron railing of the overlooking first floor



Flooring in Minton Tiles





Column Base detail with floral pattern



Wooden newspaper stand


Panineula	House (Piramal Mansion)			114
reminsula	House (Firalitat Matistoti)	Common Ref No: 114		1
1			Chare /	FF
		Card No: 156	Charanjit Rai Road	Evans Fr
		Ward (Part): A (Part II)		897
	Control Contract Control Control Control Control Control	CS No: 764 - 765, (Fort division)	1 / 2	H
		Plot Area: 193.98 sqm.		11 V 896
		B U Area: -	7,	Sadlans Roses to
64		Date: 09/02/05	/ *	895 91
	THE PROPERTY OF THE PARTY OF TH	Recorded by: Prachi Merchant	D. Ladebhai Marray Read	POLICE COURT LAND
1		Reviewed by:		162 11 894
N.		Int: Prachi Merchant, Zankhana Prajapati		Countistariet Billy per
	THE THEFT	Ext: Prachi Merchant, Zankhana Prajapati	- 5 /s.T	T 105 E 3 W 622 1
	PENINSULA HOUSE	Photo Ref: 114_Peninsula House.	1/2/1 11	Shorab House DE Set Set Seaged 1837
7	THE COOL	THOSE TOD THE STITIONS TO SEC.	- ANT	5-rachus
2			AF/- 1"	YN Side No Wall Soo Wall War
			.64	W 808 1 812
			100 F	Location Plan
1.0		Denomination		Location Fian
1.1	Name of Premises	Peninsula House		
1.2	Earlier Name	Piramal Mansion		
1.3	Built in:	Indeterminable	Extension	-
	24		Date	
-				•
2.0		Access		
2.1	Main	Dr. Dadabhai Nowroji Road - Pedestrian		
2.2	Subsidiary	-		
3.0		Ownership pattern		
3.1	Present	Private – Mr. Patrawala		
3.2	Past	Private		
3.3	Status	Owner – multi-tenanted		
4.0				
4.0	Donatal	Use		
4.1 4.2	Present Past	Commercial - Offices Commercial - Offices		
4.2	Usage	Daily.		
4.0	Osage	Daily.		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)	The building arcade forms the part of the ar	cade along the Dr	Dadabhai Nowroii Road.
5.2	Architectural Description	Planning	oaao a.og a.o <u>o</u> .	2 dada man mananan manan mananan mananan mananan mananan mananan mananan manan mananan mananan mananan mananan mananan mananan mananan mananan mananan
	The second secon	The main entrance to the building is through	n an arcade from	the west side and is oriented in
		the east-west direction with the smaller faça	ide facing the stre	et.
		The entrance to the building is through a n	arrow passage, v	which leads to a staircase are
		and lift forming the central area of the buildi	ing along with a c	entral lobby area and two ope
		courts in the north and south side.		of the exterior and the ele-
		Two wings housing office area are planned Service areas such as toilets, pantry area, a		
		The west side of the façade facing the stree		
		The ground floor housing the bank is acce		
		house offices.	soca ancony no	in the poton. The apper hoor
		Features		
		The ground floor of the building forms a p	art of an arcade	with Doric columns, rusticate
		joints with emphasized keystone, and bands		
		The first floor and second floor have p		
		decorative columns with stone balustrade, a		
		The second and third floor openings form	aouble height se	emicircular arched with double
		arches within, decorative springing points, r festoons, circular windows and half round cl		inezes, fioral and round motifs
		The fourth floor consists of a row of Doric co		ngular openings
		Style	Jidiilii Willi IEClai	igaiai opoililigs.
		The building derives influence from Neo Cla	ssical style of arc	hitecture.
5.3	Intrinsic	-	2.3.000.000	
5.4	Value Classification	A(arc), B(per), E, F, G(grp)	Recommended	d grade II A
				<u> </u>
6.0		Topography		
6.1	Floors	G + 4 with Terrace.		
0.1	rioois	G + 4 WILLI TELLACE.		

7.0		Construction	
7.1	Plinth	Low stone plinth.	
7.2	Walls	Load bearing walls with wooden column supports, with steel supports.	
7.3	Floor	Jack arch floor construction.	
7.4	Stairs	Main 'C' shaped staircase with a lift well in the center, with wooden risers, treads a	
	o tamo	railing.	
7.5	Openings	Rectangular door and window openings with glazed paneled shutters.	
		Rear arched and rectangular openings.	
		Arched window openings on the front façade.	
7.6	Roofing	RCC slab and beam structure.	
		Semicircular chajjas.	
7.7	Articulation	Projecting balconies, friezes, motifs, bands colonnade etc.	
7.8	Finishes	Walls are clad with stone on the external side, and plastered and painted from both s	
7.0	Interiore (Mayable 9 Immeyable)	Floor is finished with Minton tiles. Movable	
7.9	Interiors (Movable & Immovable)	WOVADIE	
		Immovable	
7.10	Compound/ Fence/ Gate	No fence, no compound wall. The building is directly abutting the road.	
7.10	Curtilage/ Unbuilt space/ Out Buildings/	-	
	Landscape		
8.0		Services & Utilities	
8.1	Lighting	Adequate light from courts, balconies, supplemented by artificial light.	
8.2	Ventilation	Adequate ventilation supplemented by artificial ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Individual tenants have installed fire extinguishers in their offices.	
8.7	Other (HVAC/BMS/Security Systems)	Individual tenants have installed AC in their offices.	
		Manual security.	
9.0		Condition	
		In 2002, renovation of the building interior and strengthening work was carried	
		extensively.	
9.1	Plinth	Fair – Due to renovation of individual tenants, the plinth level is almost negligible.	
9.2	Walls	Fair – Internal partitions added to suit individual requirements.	
9.3	Floor	Fair – Steel sections added to strength the floor.	
		Mezzanine floors in steel and wood have been added on the ground, first and third floors	
9.4	Stairs	Fair	
9.5	Openings	Poor – The openings are blocked to occupy AC's, window shutters are changed.	
9.6	Roofing	Fair – chajjas have been replaced.	
9.7	Articulation & Finishes	Fair – All the features are painted. The materials are difficult to identify.	
9.8	Services	Fair – AC outdoor units are installed in the balconies of the front façade.	
9.9	Out Buildings	- Miles	
9.10	Overall Conditions	Fair Maintenance level Fair	
40.0		To a characteristic	
10.0	Form	Transformation	
	Form	Chaol postions are added to strongther the floor	
	Structure	Steel sections are added to strengthen the floor. Projecting balconies are enclosed.	
		Mezzanine floors have been added on ground, first and third floor.	
	Articulation & Finishes	Openings are blocked to occupy AC's, window shutters are changed, grills are added.	
	Articulation & Finance	Half round <i>chajjas</i> have been replaced.	
		Hoardings have been installed insensitively in the openings.	
		The second of th	
11.0		DP Remarks/ Perceived Threats	
-		Building forms part of C1 zone.	
		V Spring to the	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
	i	-	
		References:	
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	

RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,

Division of International Thomson Publishing Inc.








Projecting balconies with stone balustrade, cornice bands, columns with decorative capitals, scroll bracket keystone



Detail of decorative floral pattern at the lintel level



Eruchshav		115
7.7	Articulation	-
7.8	Finishes	Walls are plastered and painted externally as well as internally. Ceramic and vitrified tiles as flooring finish.
7.9	Interiors (Movable & Immovable)	Movable
7.10	Compound/ Fence/ Gate	The building sits on the entire plot.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-
8.0		Services & Utilities
8.1	Lighting	Adequate daylight through windows and step out balconies and artificial lighting.
8.2	Ventilation	Adequate ventilation through windows and balconies with a provision of forced ventilation.
8.3	Electricity	BEST STANDARD TO THE STANDARD
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Provisions made for fire alarm system along with separate provisions for water reservoir for fire fighting.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units have been installed.
9.0		Condition
9.1	Plinth	Fair
9.2	Walls	Fair
9.3	Floor	Fair
9.4	Stairs	Fair
9.5	Openings	Fair
9.6	Roofing	Fair
9.7	Articulation & Finishes	Fair – Original features have been reconstructed in glass reinforced concrete
9.8	Services	Fair
9.9	Out Buildings	
9.10	Overall Conditions	Fair (as it is a newly constructed structure) Maintenance level - Fair
10.0		Transformation
	Form	The building is reconstructed though the original façade is retained.
	Structure	The building is rebuilt after it was totally burnt in a fire. Entire structural system is in modern material.
	Articulation & Finishes	Features on front façade are reconstructed using glass reinforced plaster restoring the appearance of the building same as earlier.
11.0		DP Remarks/ Perceived Threats Building forms part of C1 Zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes: The building was totally destroyed in fire set in the year 1994 A.D. Earlier it was a complete timber structure with wooden flooring and roofing systems. Decorative cast iron columns. The features on front façade are replicated in glass reinforced plaster. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K. CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

Eruchshaw building 115



Front façade with rectangular openings, projecting balconies, top level pediment, bands etc




Arcade with rectangular openings forming a part of the continuous pedestrian pathway along Dr. D. N. Road






Rear façade with rectangular openings




Standard b	ounding	110
		pediment with dentil band at terrace floor level and triangular pediment at second floor
		level. Have balcony at third and first floor level with comice band at each floor level. A
		openings of rear and side elevation are rectangular.
		Side elevation has enclosed verandah with decorative wooden screen with window
		decorative railing and is supported on decorative wooden brackets.
		Style The main feeded displays derivatives of the Nee Classical at the and while the sides display
		The main façade displays derivatives of the Neo-Classical style and while the sides displays the characteristics of the Vergousles style.
E 2	Intrincia	characteristics of the Vernacular style. The building has three different and distinct elevations, which depicts different styles.
5.3	Intrinsic Value Classification	
5.4	value Classification	A(arc), B(per), E, F, G(grp) Recommended II A.
		grade
6.0		Tanagaahu
6.0 6.1	Floors	Topography G+ 3 with terrace.
0.1	Floors	G+ 3 With terrace.
7.0		Construction
	Plinth	
7.1 7.2		Medium height stone plinth cladded with granite.
1.2	Walls	Exterior walls are composite with stone fascia and internal are brick walls plastered an
7.3	Floor	painted; at certain places one can see wooden partitions.
7.4	Floor Stairs	Timber flooring and partly jack arch flooring. Only one staircase is present.
1.4	Stall's	It is C-shaped with a lift block inside well.
		Cast iron decorative staircase with cast iron baluster and wooden handrail.
7.5	Openings	All doors are within semicircular arched openings.
1.0	Эрония	All doors either single or double leaf wooden panel door.
		All windows are semicircular arched openings.
		All windows have either double or four leaf glazed panel.
7.6	Roofing	Partly sloping and part terrace, sloping roof is also part RCC sloping and other is covere
7.0	Treomig	with Mangalore tiling.
7.7	Articulation	Decorative scroll brackets, cornice band, pediments with statutory tympanum, pilaster
	7 it todiation	floral motif, fluted columns, fret band, Corinthian column capital, anthemion and acroterium
		projecting balcony, carved stone coronet, ancon, balconet, enclosed verandah wit
		decorative wooden screen with windows, decorative railing supported on decorative
		wooden brackets.
7.8	Finishes	External stone fascia.
		Internal walls are plastered and painted.
		Flooring is varied like Minton tiling, PVC floor, ceramic tiles, wooden planks etc.
7.9	Interiors (Movable & Immovable)	Movable
	, ,	Old wooden tables and chairs.
		Immovable
		Cast iron decorative pillars, CI railing, CI and stone decorative brackets.
7.10	Compound/ Fence/ Gate	Building abuts the entire plot.
		Cast iron gate at entrance.
7.11	Curtilage/ Unbuilt space/ Out	Small stretch of land lies between the two adjacent buildings which is used for service
	Buildings/ Landscape	purpose.
		Planter boxes in the arcade.
8.0		Services & Utilities
8.1	Lighting	Adequate Natural light through door-window openings supplemented by electric light
		fixtures.
8.2	Ventilation	Adequate Natural ventilation through door-window openings supplemented by electric fans
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Fire alarm systems with extinguishers.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units.
9.0		Condition
9.1	Plinth	Poor – cladded with green marble, edging gone, hidden by planter box, cracks, an exposed brickwork.
9.2	Walls	Fair – side and rear are well maintained but the front has cracks, exposed brickwor
7/	vvalis	externally plant growth, and dust accumulation, blackening of stone surface.
V.=		r exemple dialitrown and dos accumulation diackentio of Stone Surface
	Floor	Poor wooden members deteriorated recruing has isale and flooring replaced to the
9.3	Floor	Poor- wooden members deteriorated, rear wing has jack arch flooring, replaced top terrace
9.3		Poor- wooden members deteriorated, rear wing has jack arch flooring, replaced top terrace has seepage problem.
	Floor Stairs	Poor- wooden members deteriorated, rear wing has jack arch flooring, replaced top terrac has seepage problem. Fair – rusted railing, dust accumulation, needs polish and painting, wear and tear ar
9.3		Poor- wooden members deteriorated, rear wing has jack arch flooring, replaced top terrac has seepage problem.

Standard I	building	116
		and verandah are enclosed and have broken and missing window panes.
9.6	Roofing	Fair – replaced sloping roof, front railing has plant growth, the pilasters on top is blackened has dust accumulation, some mangalore tiles are missing in sloping roof.
9.7	Articulation & Finishes	Fair – external wall surface is blackened, has plant growth, internal plaster and paint is peeling off, has cracks and seepage problem; tiling is changed according to user.
9.8	Services	Poor – leakage and broken pipe, rusted pipes, plant growth, duct not maintained and totally unhygienic condition.
9.9	Out Buildings	-
9.10	Overall Conditions	Fair. Maintenance level Poor.
10.0		Transformation
	Form	Addition of awning and enclosed verandah.
	Structure	Addition of mezzanine floor and it may have altered structural loading.
	Articulation & Finishes	Ad hoardings covering features and articulation.
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone.
12.0		Additional Notes/ References/ Documents available
		Additional Notes: Designed by Architects, Gostling & Morris (later Gostling, Fritchley & Chambers and then V A Chambers & Co) References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.







Arcade with arched openings with decorative column capitals

Standard building 116



Rear façade with rectangular openings, sloping chajjas, dentil band, pediments etc



Side Elevation with vernacular features like wooden trellis work, sloping roof, wood paneling, wood and cast iron railing.



Pediment with highly decorative tympanum depicting human figures surmounted with floral pinnacle.



Arched openings with a scroll bracket keystone, pediment with decorative tympanum, projecting balcony supported on decorating brackets



Minton Tile flooring



Wooden paneled decorative ventilator

Standard building 116



Detail of decorative cast iron bracket



Cast iron column with decorative Corinthian capital and brackets in a floral pattern



Staircase with wooden railing

Bai Pirojba	ai Dadabhoy Maneckji Vachha Agiar	<u> </u>	11
		Common Ref No: 117	Di Dadabha Nomoli Ro
	- 1/29	Card No: 159	adabhai.
	Will.	Ward (Part): A ward (Part II)	Nowrous Nowros
	THE PARTY NAMED IN COLUMN TWO IS NOT THE PARTY N	CS No: 676 (Fort division)	"Ro
1	12.	Plot Area: Indeterminable	E 25 25 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
8	1 图 图		
		B U Area: -	
4		Date: 19/05/2001	Prospect Chamber Annexe
		Recorded by: Prachi Merchant	1 2 9 3 1 4 1
1		Reviewed by:	ft.5 - 13
1		Int: Refer#	Pitha Street
		Ext: Refer #	and Street
7.5		Photo Ref.: 117_Watcha Agiary	TET MO
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Bai Pirojbai Dadabhoy Maneckji Vach	ha Aniary
1.2	Earlier Name	-	na Agiai y
1.3	Built in:	1881	Extension Date: -
1.0	Built III.	1001	EXIGIOIOTI Date.
2.0	<u> </u>	Access	
2.1	Main	Dr.Dadabhai Nowroji Road	
2.1	Subsidiary	A rear vehicular access street for the	unloading of wood (rolling shutter)
L.L	Subsidial y	A loai volitodiai access street ioi tile	amodaling of wood froming structor)
3.0		Ownership pattern	
3.1	Present		ha Agiary Trust (Trustees: Sir Jamshedjee
0.1	resent		Vachha, Homi Bhabha, Ardershir Dubash, Homi
		Daruwalla)	Vacilia, Homi Briabria, Aruershii Bubasii, Homi
3.2	Past	Indeterminable	
3.3	Status	Trust	
0.0	Otatus	Trust	
4.0		Use	
4.0 4.1	Present	Religious	
4.1	Past	Religious	
4.3	Usage	Daily	
4.0	Osage	Dally	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)		-storied building along the well-known Dr. Dadabhai
0.1	Townsdape (Marimade)	Nowroji Road, forming an integral par	
			e entrance of the Agiary on the busy shopping spine
			ide by five storied commercial buildings with similar
			ression, thus qualifying as an appropriate urban
		insert.	, , , , , , , , , , , , , , , , , , , ,
5.2	Architectural Description	Planning and Features	
			y in line with the Dr. Dadabhai Nowroji Road arcade
			way of winged lion supports, skewed for indirect
		access and to align its direction.	3 · · · · · · · · · · · · · · · · · · ·
			s the entrance steps while the rest of the structure is
		in line with the adjacent building line.	·
		The rear open space, on the north sid	e of the structure, accommodates the Kasti pavilion
		ablution area and a small well. The re	ar to the main Agiary structure is a two-storied
			while the kitchen and rest rooms are located on the
		first floor.	
		The congregation halls are on the first	t and second floor along ground while the prayer ha
			odated along the ground of the main road affronting
		Agiary building.	
		Ablution Pavilion (Kasti enclosure):	
		It is located in the side open space of	the structure towards the north.
			ets and houses two small square wells.
			provided for women .The flooring is in marble mos
		while the walls are oil-based emulsion	
		Kebla:	•
			f the main building. It is square in plan and is toppe
	i		
		by a dome. Its internal walls of the en-	closure are lined with glazed tiles and the flooring is
			closure are lined with glazed tiles and the flooring is centre of the Kebla has a German silver "afarghany
		marble with adequate pavis laid. The	

sai Filojbai	Dadabhoy Maneckji Vachha Agiary	117
		"goorooj" (head of bull) on a German silver stalk. Large bells are hung from the two
		opposite sides of the Kebla. A German silver "chattar" (umbrella) is suspended over the fire Heavy teakwood paneled, four shuttered windows and doors are provided. Brass rods are fitted within the heavy teakwood window frames. Prayer Hall:
		The prayer space affronts the present entry, not the original one opening onto the pedestrian arcade. It is ten feet deep while the rest of the space is fifteen feet deep and functions as the ceremony hall. It is provided with two doorways and marble flooring. Walls are clad with high granite tile dado. Lightweight chandeliers adom the elaborately pattern timber coffered false ceiling. Ceremony Hall:
		None, as a part of the prayer space functions as the ceremony hall. <u>Baj Room:</u>
		It is located along the ground of the rear two-storied structure with a timber sloping Mangalore tile roof. This room is about eight feet deep with dressed basalt stone flooring. It is provided with three sets of doorways that open into the side open space drawing light and ventilation from the same. Congregation Hall:
		The first and the second floor of the main structure accommodate the congregation hall as well as room that houses the dome for ventilation of the Kebla further covered with pitched roof. The hall is well lit and ventilated with large glazed openings. The hall is skewed in plan, with a timber trabeated structure that has an exquisite set of circular timber columns with elaborate capitals. The interiors are finished in oil-based emulsion paint, with large photo frames, mirrors and delicate chandeliers. Residence for Priest's (Boiwala's)in serving: No permanent residence for the Boiwala in serving except for a rest room along first floor o
		the rear two-storied structure, especially during Muktad days. <u>Curtilege Structure (wells etc):</u> Two square wells are located in the side open space. However, there are no other curtilege structures as the other functions are accommodated in the ancillary rear two storied structure. It houses the Baj room and store room store on the ground floor, rest room,
		dining space kitchen and store on the first floor and is covered with a timber trussed roof accessed by two staircases drawing light and ventilation from the side and rear space. Style The structure derives influence from pre-industrial Vernacular style architecture.
5.3	Intrinsic	-
5.4	Value Classification	A(arc),A(his),A(cul),B(des),B(per),B(uu), Recommended II A C(seh),D(bio),E, G(grp) grade
6.0	+	Topography
6.1	Floors	Main Agiary - G+2, Ancillary structure - G+1
0.1	1 10010	Thairrigial y C. 2, Fillollial y Claudial C. 1
7.0		Construction
7.1	Plinth	Three feet high plinth in dressed Khandki stone masonry with emphasised offsets to accommodate piers.
7.2	Walls	The structure is composite with timber columns and beams and with load bearing walls. The external façade is dressed in stone masonry while the internal partition walls, like that of Kebla and walls dividing passage ways are in brick and plastered.
7.3	Floor	The floors are timber trabeated with teakwood bridging joists and covered with timber false ceiling. The ancillary structure has an exposed ceiling.
7.4	Stairs	The main winder staircase is in masonry with teakwood bridging joists and covered with timber false ceiling. The ancillary L-shaped timber staircase.
7.5	Openings	The ground storied, main Agiary structure has no windows but all four sets of doorways are four shuttered, teakwood paneled while windows at the upper levels are timber - framed with full height glazed panels.
7.6	Roofing	The main Agiary structure is flat –terraced while the ancillary structure is timber –trussed with a hipped Mangalore-tiled roof.
7.7	Articulation	The façade shows a number of features exquisite articulation and detailing, right from walls to the ceiling.
7.8	Finishes	Internally, the walls of the ground storied main structure are clad with granite while the remaining walls of the ground storied main structure are clad with granite while the remaining walls are oil-based emulsion painted.
7.9	Interiors (Movable & Immovable)	Movable -
		Immovable

	Landscape	
8.0		Services & Utilities
8.1	Lighting	Though the structure has few openings, the lighting is adequate due to limited depth of th structure.
8.2	Ventilation	Adequate cross-ventilation due to limited depth of the structure. Ventilation for the Kebla is elaborately worked out within the three-storied structure.
8.3	Electricity	BEST
8.4	Water Supply	Well water and piped water through MCGM
8.5	Drainage (Plumbing & Sanitation)	Adequate through the municipal connected supply.
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	Fair
9.2	Walls	Fair
9.3	Floor	Fair
9.4	Stairs	Fair
9.5	Openings	Fair
9.6	Roofing	Fair
9.7	Articulation & Finishes	Fair
9.8	Services	Fair
9.9	Out Buildings	Fair
9.10	Overall Conditions	Good Maintenance level Fair
10.0		Transformation
	Form	No visible changes
	Structure	No visible changes
	Articulation & Finishes	No visible changes
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes: Dinshaw Dorab Mistry designed this stone masonry building. References:
		# Study conducted by Pankaj Joshi Consultants with support from Mr Jamshed Guzder, Merwanji D M Jeejeebhoy Trust and Mrs Ketie Mehta, Gulestan and Rustom Billimoria Charitable Trust through auspices of Mr Cyrus Guzder.



Entrance of the building flanked with Lamasus on the sides, frieze band and Parsi emblem above



Kebla



Wooden service staircase with wooden railing



Baj room



Square wall



Main wooden staircase with wooden railing



Buff stone rusticated clad façade with frieze band and Parsi emblem



Buss stone clad corner façade with projecting balconies, fluted columns with highly ornamented capitals with animal motifs, receding comice band.

Jeevan Ud	yog Building - Khadi Gram Udyog (Whit	eway Laidlaw buildino) 118
G SECONOLISION I	79%	Common Ref No: 118
		Card No: 160
		Ward (Part): A (Part II)
		CS No: 743 (Fort Division)
46		Plot Area: 1280.86
4		B U Area: -
		Date: 17/2/2005
		Recorded by: Arun Wadhwa
		Recorded by: Arun Wadhwa Reviewed by: Int: Arun Wadhwa, Sonal Modak Ext: Arun Wadhwa, Sonal Modak Photo Ref: 118_Khadi Bhandar.
	P. C.	Int: Arun Wadhwa, Sonal Modak
		Ext: Arun Wadhwa, Sonal Modak
		Photo Ref: 118_Khadi Bhandar.
		an Dadhichi Maro
		Location Plan
1.0		Denomination
1.1	Name of Premises	Jeevan Udyog Building. (Commonly known as Khadi Gram Udyog)
1.2	Earlier Name	Whiteway Laidlaw building.
1.3	Built in:	Indeterminable Extension Date: -
2.0		Access
2.1	Main	Dr. Dadabhai Nowroji Road – vehicular and pedestrian.
2.2	Subsidiary	Maharishi Dadichi Marg - vehicular and pedestrian.
۷.۲	- Jubolalary	mananani badian marg variodidi dila padastilari.
3.0		Ownership pattern
3.1	Present	Life Insurance Corporation.
3.1	Past	Whiteway Laidlaw Departmental store.
3.3	Status	Owner, Tenants.
4.0		
4.0	-	Use
4.1	Present	Khadi Emporium on ground floor, Offices above.
4.2	Past	Departmental store.
4.3	Usage	Daily.
5.0		Significance and Value Classification
5.1	Townscape (manmade)	Corner building on the west side of the Dr. Dadabhai Nowroji Road streetscape, accessed
		from the street level pedestrian arcade, a continuous mandatory feature on the planned
		western road front serving as a physical and visual element tying together the eclectic
		styles of all the buildings.
5.2	Architectural Description	Planning
0.2	, normodala. 2000. puoli	A corner building with emphasis to the façade accentuating the junction of two roads. High
		ground floor accommodates mezzanine on all sides of the periphery. Accessed from north
		end of arcade front into a staircase and lift lobby with service stair and toilets behind and
		colonnaded open office spaces on the three road fronts subdivided by wooden partitions on
		upper floors. Central open court on the third floor with passages around. Toilets and service
		spaces are low heighted allowing intermediate levels also used as toilets and other ancillary
		requirements. Third floor-raised corner culminates as a truncated square topped by a
		pyramidal sloping roof. LIC offices occupy first floor whereas the upper floors are private
		offices including a nursing home on the third floor. Service stair rises as a high terrace
		block with adjoining metal water tank topped by a sloping roof.
		Features
		Eastern symmetrical front facade with richly decorative corner bays and a high pedestrian
		arcade. Distinct triangular pediment feature over the raised south corner, topped by a wide
		cornice - chajja band. High ground floor arcade has a rusticated colonnade with
		ornamentally carved capitals, brackets and frieze band. Two floor high colonnaded bays
		with inset architrave openings and projecting balcony feature form the long central portion
		flanked by decoratively carved cornice, capitals, brackets and pediment openings. South
		and west side facades are composed of cantilevered wooden verandas supported on
		decorative steel brackets.
		Style
F 2	1,12,-2,	Influence of Colonial and Vernacular style features.
5.3	Intrinsic	Overhanging wooden verandas on the side and rear facades.
5.4	Value Classification	A(arc), B(per), E, F, G(grp) Recommended grade II B
• • • • • • • • • • • • • • • • • • • •		 -
6.0		Topography
-	Floors	G + 3 floors and mezzanine.
6.1	1 10013	
6.1	110013	
7.0	110013	Construction
	Plinth	Plinth height about 0.75 m dressed in grey basalt ashlar course.
7.0		Plinth height about 0.75 m dressed in grey basalt ashlar course.
7.0 7.1	Plinth	

Jeevan Udy	og Building - Khadi Gram Udyog (Whitew	
		double flight service stair to the rear of lift shaft.
7.5	Openings	Architrave rectangular openings full height with upper wood framed glazed panel, wooder paneled lower part. Ground floor - full height glass display windows to the shopfront.
7.6	Roofing	Flat concrete slab over later added third floor. Sloping mangalore tile roof over staircase and terrace block. Asbestos sheet pyramidal roof over high corner block.
7.7	Articulation	Projecting balcony with decorative corbel feature, decorative carved capitals and brackets decorative pediment, corbel, cornice and frieze band feature.
7.8	Finishes	Grey basalt stone dressed external wall surfaces, soft Porbander stone for ornamenta
		features on the front façade and brick faced wooden verandah fronts to the south and west Plastered and painted internal wall surfaces. Original Minton tiling in the staircase landing Varied floor finishes with modifications over a period of time.
7.9	Interiors (Movable and Immovable)	Movable
		- Immovable
7.10	Compound/ Fence/ Gate	Low compound with iron railing and stone gatepost to the narrow south side space.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Narrow stretch of open space to the south side road front.
8.0		Services and Utilities
8.1	Lighting	Inadequate natural light in some internal portions and staircase also relies on artificial light.
8.2	Ventilation	Adequate natural ventilation but relies on A.C. units.
8.3	Electricity	BEST
8.4	Water Supply	MCGM Underground and overhead water tank
8.5	Drainage (Plumbing and Sanitation) Fire Precaution	Drainage connected to municipal sewers of MCGM Fire extinguishers.
8.6	Other (HVAC/BMS/Security Systems)	Window and split unit A.C.
0.1	Other (HVAC/BING/Security Systems)	window and spire unit A.O.
9.0		Condition
9.1	Plinth	Poor - Plant cultivation around the plinth area and plumbing interventions to the north side.
9.2	Walls	Poor – seepage and plant growth observed.
9.3	Floor	Poor – damaged first floor and south side verandas at all levels.
9.4	Stairs	Fair except wear and tear, also poorly lit and maintained.
9.5	Openings	Poor - Iron grills enclosing veranda openings, damaged and poorly finished door window shutters. Addition of metal sheet <i>chajjas</i> and bamboo mat over window openings.
9.6	Roofing	Fair except the neglected and vandalized terrace block.
9.7	Articulation and Finishes	Poor - Blackened stone-faced facades and veranda features.
9.8	Services	Poor - Old, neglected electrical and plumbing services.
9.9 9.10	Out Buildings Overall Conditions	Poor- external finishes, south and west verandah fronts. Maintenance level: Poor
40.0		·
10.0	Form	Transformation -
	Structure	Third floor seems to be added later.
	Articulation and Finishes	No major transformation except for encroachments to balconies, verandas damaging façade character. Also minor intervention to the ground floor interior cast iron column feature.
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone.
12.0		Additional Notes/ References/ Documents available
		Additional Notes: Designed by the firm of Gostling and Morris, for the departmental store Whiteway and Laidlaws. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.



Side facade with vernacular features with projecting balconies supported on wooden brackets, wooden trellis work etc.



Front facade with rectangular openings, double height columns with ornamented capitals, projecting balconies supported on scroll brackets, dentil bands etc



Arcade with columns with high base and ornamented capitals



Cast iron brackets supporting the cantilevered floor



Corner tower with projecting balconies supported on decorative brackets, stone balustrade, arched openings, pediment with dentils




Intricate ornamentation with floral pattern on column capital and bracket



Cast iron round column with decorative capital



Cast iron decorative railing



Badri Maha	I	11
7.6	Roofing	Indeterminable
7.7	Articulation	Arches, cornice bands columns with decorative capital, projecting balconies supported on brackets
7.8	Finishes	The external wall is dressed in buff basalt stone, internally walls are finished with plaster and paint
7.9	Interiors (Movable & Immovable)	Movable -
		Immovable -
7.10	Compound/ Fence/ Gate	-
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	•
8.0		Services & Utilities
8.1	Lighting	Natural light supplemented with artificial means
8.2	Ventilation	Natural ventilation supplemented with artificial means
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	•
8.7	Other (HVAC/BMS/Security Systems)	Manual security system
9.0		Condition
9.1	Plinth	Fair – plinth has been painted
9.2	Walls	Fair
9.3	Floor	Indeterminable
9.4	Stairs	Indeterminable
9.5	Openings	Fair – Balcony openings have been enclosed
9.6	Roofing	Indeterminable
9.7	Articulation & Finishes	Fair – All the façade features have been painted
9.8	Services	Indeterminable
9.9	Out Buildings	Indeterminable
9.10	Overall Conditions	Fair Maintenance level Fair
10.0		Transformation
	Form	-
	Structure	-
	Articulation & Finishes	Façade features have been painted. Balcony openings have been enclosed. Shutters have been replaced
11.0		DP Remarks/ Perceived Threats
11.0		
		Building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai. Christopher W London, Bombay Gothic, India Book HousePvt. Ltd. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd.

Badri Mahal 119



Entrance with multifoiled arch on columns with decorative capitals, floral pattern keystone and spandrel



Wooden projecting balcony supported on decorative brackets, wooden railing, dentil band etc



Façade articulation with projecting balcony bays supported on brackets



Rectangular opening with arched ventilator with floral pattern motif, lintel level frieze band, etc



Side multifoiled arched entrance with spandrel and column ornamentation, surmounted by domed roof with floral pattern bands.

Capitol Cin	ema		120
oupitor on	ioniu —	Common Ref No: 120	
		Card No: 162	
		Ward (Part): A (Part I)	
		CS No: 1385 (Fort division)	
		. ,	
		Plot Area: 2107.87 sq m.	
	The state of the s	B U Area: -	
1 98		Date: 15/12/04	Road
		Recorded by: Prachi Merchant	ad Somethin
1		Reviewed by:	Hozarina Color Color
16		Int: Sonal Modak, Prachi Merchant	
		Ext: Sonal Modak, Prachi Merchant	
		Photo Ref: 120_Capitol Cinema.	- ton Robert
(Mandelman III)	ME.		
A PAR			
			Location Plan
1.0		Denomination	Loodion Fidit
1.1	Name of Premises	Capitol Cinema	
1.2	Earlier Name	Gaiety Theater	
1.3	Built in:	1879	Extension Date: 1928
2.0		Access	
2.1	Main	Dr. Dadabhai Nowroji Road – pedestrian.	
2.2	Subsidiary	Hazarimal Somani Marg – separate entrance	es for pedestrian and vehicular.
	,		
3.0		Ownership pattern	
3.1	Present	Owner - Nadir Company Private Itd Globe	Theater Co.
3.2	Past	Owner - Hoshang Nadirshawedulji & others	
3.3	Status	Owner – multi tenanted.	
4.0		Use	
4.1	Present	Cinema Theater, Commercial Offices and sh	ops, Restaurants, Hotel.
4.2	Past	Cinema Theater, Commercial.	
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (Manmade)		natrapati Shivaji Terminus and MCGM building,
		the building is accessed from the east and the	
		The building forms an important part of the s	treetscape of Dr. Dadabhai Nowroji Road.
5.2	Architectural Description	Planning	
			ctangular shape, with a central wing and two
		projecting bays on either side.	o archad ananings from Dr. Dadahhai Nassasii
			e arched openings from Dr. Dadabhai Nowroji
		Road and Hazarimal Somani Marg. The entrance leads to the ticket counter area	a and staircase block
			ied by the theater stage on ground floor and
		catwalk area on the first floor.	isa sy tilo tiloatoi stage oli giouliu ilooi allu
			aurants, and ticket counter on the ground floor
		and offices on upper floors.	and asset sparitor on the ground hoof
			tion system and the generator system required
		for the theater.	,
		The offices, and projection room and the wes	stern side by the terrace and sloping,
			occupied by restaurant staff residential area,
		restaurant kitchen service area, hotel rooms	and offices.
		Features	
			of full height three semicircular arches on every
		floor with a stone balustrade, with bands and	corbels defining the floor level.
			ground and second floor semi circular arched
			with semi circular and triangular pediments,
			human face motifs tympanum. Columns with
			nds in a semicircular decorative pediment with
		geometric pattern tympanum within.	adow oponingo
		The end wings have semi circular arched wings the theater seating area includes weeden	ndow openings. columns with carved brackets, balconies with
		wooden seats, railing and old fan brackets.	Columns with Carved Diackets, Dalcomes With
		The ceiling has intricate carvings.	
		The coming has intilicate carvings.	

Capitol C	inema	120
oup.io. o		
		Style
		The building derives influence from Colonial and Baroque style of architecture.
5.3	Intrinsic	One of the first western style theater buildings after the demolition of Bombay Green
		Theater
		The theatre before being converted into a cinema hall, was popular venue for English
		Marathi and Gujarati dramas. The first promoters of Parsi drama which had its foundations
		in Marathi and Gujarati theatre were young students of Elphinstone college such as
		Dadabhai Nowroji, Nanbhai Ranina and Adersheer F Moos, who served as promoters behind the scenes as well as "gave a willing hand in raising and dropping the curtain"
5.4	Value Classification	A(arc), A(his), A(cul), B(per), B(des), B(uu), C(seh), F, I(sce) Recommended grade II A.
0.4	Value Glassification	7 (dro), 7 (mo), 7 (our), 5 (por), 5 (doo), 5 (du), 6 (our), 7 , 1 (ooo) 1
6.0		Topography
6.1	Floors	G + 2 with basement. The ground floor has an additional mezzanine space.
7.0		Construction
7.1	Plinth	Normal plinth with grey stone cladding with a protection band
7.2	Walls	Thick load bearing walls with wooden column and beam support.
7.3	Floor	Wooden section supports with concrete flooring.
7.4	Stairs	Main Open well staircase on the eastern side with stone risers and treads and wooden
		railing. Rear dogleg wooden staircase on the northern side with wooden risers, treads and railing.
		Cast Iron spiral staircase on the rear side of the building to access the residential areas.
7.5	Openings	The main entrance is through three semicircular arched openings with a ventilator.
	- Pormigo	The doors and windows have arched and rectangular openings with shutters consisting of
		partly paneled and partly louvered shutters with ventilators.
7.6	Roofing	Sloping asbestos sheet roof on wooden trusses. Flat concrete slab over certain areas
7.7	Articulation	Bands arched openings, intricate carvings, floral motifs, corbels, stone balustrade, human
		face motifs, columns with Corinthian capitals, pediments etc
7.8	Finishes	Walls are clad with rough dressed grey stone ashlar masonary on the external side and
		plastered and painted from the internal side.
		Floor finished with Minton tiles in office areas, mosaic tiles on staircase floor and dado,
		wooden flooring on the stage, catwalk and mezzanine floor. The Theater floor has IPS floor finish with carpet on it.
7.9	Interiors (Movable & Immovable)	Movable
1.0	monoro (morabio a mimorabio)	Office wooden table, chairs, storage units etc.
		Immovable
		The Theater wooden chairs, dress circle seats, railing etc
7.10	Compound/ Fence/ Gate	The Theater opens directly on the footpath of the road. The rear portion has a plastered
7.44	0 (1 /11 11 / 0 / 0 11	brick compound wall and MS gates.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	No front open space.
	Landscape	Rear open space is occupied by pump house, watchman's cabin, restaurant kitchen parking area.
		Concrete paving in few places of the rear open space.
		Shrubs and old trees line the rear compound wall.
8.0		Services & Utilities
8.1	Lighting	Inadequate natural light through the window openings, supplemented by artificial lights.
8.2	Ventilation	The Theater is naturally ventilated through the window openings, supplemented by artificial
		ventilation.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5 8.6	Drainage (Plumbing & Sanitation) Fire Precaution	MCGM Fire outinguishers at various places
8.7	Other (HVAC/BMS/Security Systems)	Fire extinguishers at various places. The theater is naturally ventilated. The offices have AC's as per individual requirement.
0.1	Other (FIVAC/DIVIS/Security Systems)	Strict manual security system at the entrance.
		2,000 and accounty a journ at the origination
9.0		Condition
9.1	Plinth	Fair - The front rented spaces of shops and restaurants have modified the plinth according
		to their individual requirements.
9.2	Walls	Poor - The stone on the external façade has weathered and blackened.
		Internally the walls are plastered and painted.
		Plaster peeling off due to leakage on the rear side.
		Severe seepage and dampness is observed in the external walls towards the south side.
		Organic growth on the south side of Building facade. Partitions are added in the offices internally.
9.3	Floor	Fair - due to ground water seepage, steel support are added to the floor for strengthening.
9.4	Stairs	Fair - The wood of the staircase is deteriorating. The spiral staircase is not maintained.
۲.,	Johanno	mo wood or the outstand to deterior during. The opinior stall educate to the maintained.

Capitol C	inema	120
9.5	Openings	Poor - In many places window and ventilators openings are blocked for AC fixing. Shutters
	' °	of the door and window openings changed.
		The ground floor openings have been completely changed as per individual tenant's
		requirement.
9.6	Roofing	Fair - The Mangalore tiling has been replaced by asbestos sheet roofing. The terrace floor
0.0	1.009	has been loaded with water tanks etc.
9.7	Articulation & Finishes	Poor - Motifs are blackened in many places. Corbels, brackets, bands are in broken
0.1	A thoulation a 1 misries	condition at various places in the front façade.
9.8	Services	Fair - Exposed wires have been added haphazardly. Rear and side drainage pipes are
9.0	Services	leaking leaving unhygienic areas around the building.
9.9	Out Buildings	Poor - The rear portion is used for restaurant kitchen wok and is not maintained.
	ŭ	
9.10	Overall Conditions	Fair Maintenance level: Poor
10.0		Transformation
10.0		
	Form	The turrets visible on the front façade were removed due to heavy leakage.
	Structure	Steel supports have been added to the floors for strengthening.
		Tanks have been added in the side of the building.
	Articulation & Finishes	Shops lined in the front side façade hide the features of the building.
		The building facade has been insensitively covered by hoardings, hiding many features.
		Window shutters are changed and grills have been added. Shop entrance door openings
		are altered according to individual tenant requirement.
		Various tenants have done illegal extensions and enclosures.
		Hawkers have occupied the front approach area.
11.0		DP Remarks/ Perceived Threats
		Cinema Hall, building forma part of C1 zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		The Gaiety theatre, as Capitol was originally known, was established by Nazir, a Parsi. In
		1928, the Gaiety was converted into a cinema and renamed Capitol, after extensive
		structural alterations including the provision of a new main entrance on Hornby Road, The
		work was carried out under the supervision of Mistri & Bhedwar, architects. The ceiling
		decoration in the renovated theatre was extraordinarily fine, a glowing gold sun and the
		signs of the Zodiac, also in gold, being set on a background of blue.
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay :
		Eminence Designs Pvt. Ltd.
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.
		RAHUL MEHROTRA and SHARADA DWIVEDI (2004) The Bombay High Court - The story
		of the building – 1878-2003, Bombay : Eminence Designs Pvt. Ltd.
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence
		Designs Pvt. Ltd.
		J
		1

Capitol Cinema 120



Highly ornamented front façade with arched openings, floor bands, pediments etc



Grey stone clad building with rectangular window openings with pediments, columns with decorative capitals, round openings. The building is in a neglected state with incongruous additions.



Interior view of the theater with wooden balcony railing



Side façade with arched openings of the verandah space with stone balustrade



Side elevation with arched openings, pediments, accouplement of columns with Corinthian capitals, stone balustrade etc

Chhatranati	Chivali Tarminua (Vietoria Tarminua)			121
Gilliatrapati	Shivaji Terminus (Victoria Terminus)	Common Ref No: 121		121
i		Card No: 163		
i		****		
i		Ward (Part): A (part I)	TANK T	三
		CS No: 1453 (Fort division)		
		Plot Area: 183279.68 sqm.		A 108
g.		B U Area: -		
		Date: 28/03/05		
4 . 4		Recorded by: Prachi Merchant	O 127.	
		Reviewed by:	- 300	
			AZAD MAIDAN	
1881 64 1	The defense of the page of the	Int: Sachin Borkar, Arun Wadhwa, Prachi		
MA TO THE		Merchant, Sonal Modak, Zankhana Prajapati Ext: Sachin Borkar, Arun Wadhwa, Prachi		
		Merchant, Sonal Modak, Zankhana Prajapati	3	NAGAR CHOME VIEW
İ		Photo Ref.: 121_Chattrapati Shivaji Terminus		
i		Prioto Rei 121_Oriatuapati Sriivaji Terminus		
İ				WALCHAND HIRACHAND
·				Location plan
1.0		Denomination		
1.1	Name of Premises	Chhatrapati Shivaji Terminus		
1.2	Earlier Name	Victoria Terminus (Bori Bunder)		
1.3	Built in:	1878 – commencement of work	Extension	1999
		1888 – Open to public	Date:	
2.0		Access		
2.1	Main	Dr. Dadabhai Nowroji road – pedestrian and v		
2.2	Subsidiary	Walchand Hirachand road – pedestrian and v	ehicular up to co	oncourse area
3.0	_	Ownership pattern		
3.1	Present	Owner - Central Railway		
3.2	Past	Owner - Great Indian Peninsula Railway		
3.3	Status	Owner		
4.0		Use		
4.1	Present	Central Railway Headquarters and railway sta	ation building	
4.2	Past	Central Railway Headquarters and railway sta		
4.3	Usage	Daily		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)	The Station building is located at an importan		
	Townocapo (maninado)	I Dadahhai Nowroii Road, Mahanalika Marq, H	lazarimal Somar	ni Marg, Walchand Hirachand
I	Tomicoapo (marimado)			
	romicape (maimac)	marg) with docks and the harbour on the east	t side, Capitol Ci	
	Tomiccape (maimage)	marg) with docks and the harbour on the east India building on the west, Crawford market o	t side, Capitol Ci on the north, Nag	ar chowk garden, bus stop,
	Tomiccape (maimage)	marg) with docks and the harbour on the east India building on the west, Crawford market o residential buildings and the Dr. Dadabhai No	t side, Capitol Ci on the north, Nag owroji Road prec	ar chowk garden, bus stop, inct on the south.
	Tomoccope (mailmado)	marg) with docks and the harbour on the east India building on the west, Crawford market o residential buildings and the Dr. Dadabhai No The main access is from the Dr. Dadabhai No	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from	ar chowk garden, bus stop, inct on the south. I the west side. A subway
	Tomoccope (mailmado)	marg) with docks and the harbour on the east India building on the west, Crawford market o residential buildings and the Dr. Dadabhai No The main access is from the Dr. Dadabhai No connects the main lobby to the other side of t	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede	ar chowk garden, bus stop, inct on the south. I the west side. A subway
	Tomoccope (mailmado)	marg) with docks and the harbour on the east India building on the west, Crawford market o residential buildings and the Dr. Dadabhai No The main access is from the Dr. Dadabhai No connects the main lobby to the other side of the accessed from the east side by Walchand Hir	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede rachand road.	par chowk garden, bus stop, inct on the south. I the west side. A subway estrian access. The building is
	Tomoccope (mailmado)	marg) with docks and the harbour on the east India building on the west, Crawford market o residential buildings and the Dr. Dadabhai No The main access is from the Dr. Dadabhai No connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with	t side, Capitol Ci in the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense url	par chowk garden, bus stop, inct on the south. I the west side. A subway estrian access. The building is
		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai No The main access is from the Dr. Dadabhai No connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista	t side, Capitol Ci in the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense url	par chowk garden, bus stop, inct on the south. I the west side. A subway estrian access. The building is
5.2	Architectural Description	marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai No The main access is from the Dr. Dadabhai No connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense url within the city.	par chowk garden, bus stop, inct on the south. If the west side. A subway estrian access. The building is pan significance as a
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai No. The main access is from the Dr. Dadabhai No. connects the main lobby to the other side of the accessed from the east side by Walchand Hir. The building is an architectural landmark with culmination point in an important scenic vista. Planning The main building is located towards the sout	t side, Capitol Ci in the north, Nag wroji Road prec wroji Road from recoad for pede rachand road. an immense un within the city.	par chowk garden, bus stop, inct on the south. If the west side. A subway estrian access. The building is pan significance as a
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai No. The main access is from the Dr. Dadabhai No. connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista Planning The main building is located towards the sout through a deep front setback. The platform ar	t side, Capitol Ci in the north, Nag wroji Road prec wroji Road from recoad for pede rachand road. an immense un within the city.	par chowk garden, bus stop, inct on the south. If the west side. A subway estrian access. The building is pan significance as a
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai No The main access is from the Dr. Dadabhai No connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath.	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from the road for pede rachand road. an immense und within the city. th of the plot, account ticket lobby an	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a seessed from the west side rea is accessed through side.
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai Not The main access is from the Dr. Dadabhai Not connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket lot	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from the road for pede rachand road. an immense und within the city. th of the plot, account ticket lobby an	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a seessed from the west side rea is accessed through side.
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai Not The main access is from the Dr. Dadabhai Not connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket loopening into the covered platforms.	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense und within the city. th of the plot, account ticket lobby and obbby, waiting con	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a cessed from the west side rea is accessed through side incourse on the north side,
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai Not The main access is from the Dr. Dadabhai Not connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket loopening into the covered platforms. The rear side semi covered entrance lobby contractions and the platforms.	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense und within the city. th of the plot, account ticket lobby and obbby, waiting com-	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a cessed from the west side rea is accessed through side incourse on the north side,
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai Not The main access is from the Dr. Dadabhai Not connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket loopening into the covered platforms. The rear side semi covered entrance lobby or west and the outstation concourse on the east	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense un within the city. th of the plot, according to obby, waiting con onnects the loca et side.	par chowk garden, bus stop, inct on the south. If the west side. A subway estrian access. The building is pan significance as a seessed from the west side rea is accessed through side ancourse on the north side,
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai Not The main access is from the Dr. Dadabhai Not connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista. Planning The main building is located towards the sout through a deep front setback. The platform ark wings directly from the footpath. The main building is connected to the ticket to opening into the covered platforms. The rear side semi covered entrance lobby covers and the outstation concourse on the east The east side of the plot occupies the annex.	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense un within the city. th of the plot, according to obby, waiting con onnects the loca et side.	par chowk garden, bus stop, inct on the south. If the west side. A subway estrian access. The building is pan significance as a seessed from the west side rea is accessed through side ancourse on the north side,
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai No. The main access is from the Dr. Dadabhai No. Connects the main lobby to the other side of accessed from the east side by Walchand Hir. The building is an architectural landmark with culmination point in an important scenic vista. Planning The main building is located towards the sout through a deep front setback. The platform ar wings directly from the footpath. The main building is connected to the ticket to opening into the covered platforms. The rear side semi covered entrance lobby or west and the outstation concourse on the east. The east side of the plot occupies the annex building through an internal courtyard.	t side, Capitol Ci in the north, Nag wroji Road prec owroji Road from he road for pede rachand road. an immense url within the city. th of the plot, acc and ticket lobby and obbby, waiting cor connects the loca at side. building, reserva	par chowk garden, bus stop, inct on the south. If the west side. A subway estrian access. The building is pan significance as a seessed from the west side rea is accessed through side incourse on the north side, I station concourse on the station building and the station
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai No. The main access is from the Dr. Dadabhai No. Connects the main lobby to the other side of the accessed from the east side by Walchand Hir. The building is an architectural landmark with culmination point in an important scenic vista. Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket loopening into the covered platforms. The rear side semi covered entrance lobby cowest and the outstation concourse on the east The east side of the plot occupies the annex building through an internal courtyard. The main building along with the out buildings.	t side, Capitol Ci in the north, Nag owroji Road prec owroji Road from he road for pede arachand road. an immense un within the city. The of the plot, according ticket lobby and obby, waiting contented to the connects the local st side. The order of the plot, according to	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a sessed from the west side rea is accessed through side accurse on the north side, I station concourse on the tion building and the station alle mass with domes, spires,
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai No. The main access is from the Dr. Dadabhai No. Connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista. Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket to opening into the covered platforms. The rear side semi covered entrance lobby or west and the outstation concourse on the east The east side of the plot occupies the annex building through an internal courtyard. The main building along with the out buildings statues, terraces, sloping stepped and north I	t side, Capitol Ci in the north, Nag owroji Road prec owroji Road from he road for pede arachand road. an immense un within the city. The of the plot, according ticket lobby and obby, waiting contented to the connects the local st side. The order of the plot, according to	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a sessed from the west side rea is accessed through side accurse on the north side, I station concourse on the tion building and the station ple mass with domes, spires,
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai No. The main access is from the Dr. Dadabhai No. The main access is from the Dr. Dadabhai No. Connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista. Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket to opening into the covered platforms. The rear side semi covered entrance lobby or west and the outstation concourse on the east The east side of the plot occupies the annex I building through an internal courtyard. The main building along with the out buildings statues, terraces, sloping stepped and north I monotony.	t side, Capitol Ci in the north, Nag owroji Road prec owroji Road from he road for pede arachand road. an immense un within the city. The of the plot, according ticket lobby and obby, waiting contented to the connects the local st side. The order of the plot, according to	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a sessed from the west side rea is accessed through side accurse on the north side, I station concourse on the tion building and the station ple mass with domes, spires,
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai Not The main access is from the Dr. Dadabhai Not Connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket to opening into the covered platforms. The rear side semi covered entrance lobby or west and the outstation concourse on the east building through an internal courtyard. The main building along with the out buildings statues, terraces, sloping stepped and north I monotony. Main building:	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense und within the city. th of the plot, acc nd ticket lobby and obby, waiting con onnects the loca st side. building, reserva as stand as a sing ight roof structur	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a cessed from the west side rea is accessed through side ancourse on the north side, I station concourse on the station building and the station gle mass with domes, spires, re over platforms, breaking the
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai Not The main access is from the Dr. Dadabhai Not connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista. Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket to opening into the covered platforms. The rear side semi covered entrance lobby of west and the outstation concourse on the east The east side of the plot occupies the annex building through an internal courtyard. The main building along with the out building statues, terraces, sloping stepped and north I monotony. Main building: The 'C' shaped building is symmetrically plan	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense und within the city. th of the plot, acc nd ticket lobby and obby, waiting con onnects the loca st side. building, reserva as stand as a sing ight roof structur	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a cessed from the west side rea is accessed through side ancourse on the north side, I station concourse on the station building and the station gle mass with domes, spires, re over platforms, breaking the station to the south direction the south direction the station that is the station of the station gle mass with domes, spires, the over platforms, breaking the station that is the station of the station that is the station of the
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai Not The main access is from the Dr. Dadabhai Not connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista Planning Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket to opening into the covered platforms. The rear side semi covered entrance lobby of west and the outstation concourse on the east The east side of the plot occupies the annex building through an internal courtyard. The main building along with the out buildings statues, terraces, sloping stepped and north I monotony. Main building: The 'C' shaped building is symmetrically plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the plan with its longer side facing west and its side expending the	t side, Capitol Ci on the north, Nag owroji Road prec owroji Road from he road for pede rachand road. an immense und within the city. th of the plot, acc nd ticket lobby and obby, waiting con onnects the loca st side. building, reserva as stand as a sing ight roof structur	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a cessed from the west side rea is accessed through side ancourse on the north side, I station concourse on the station building and the station gle mass with domes, spires, re over platforms, breaking the sted in north south direction
5.2		marg) with docks and the harbour on the east India building on the west, Crawford market or residential buildings and the Dr. Dadabhai Not The main access is from the Dr. Dadabhai Not connects the main lobby to the other side of the accessed from the east side by Walchand Hir The building is an architectural landmark with culmination point in an important scenic vista. Planning The main building is located towards the sout through a deep front setback. The platform arwings directly from the footpath. The main building is connected to the ticket to opening into the covered platforms. The rear side semi covered entrance lobby of west and the outstation concourse on the east The east side of the plot occupies the annex building through an internal courtyard. The main building along with the out building statues, terraces, sloping stepped and north I monotony. Main building: The 'C' shaped building is symmetrically plan	t side, Capitol Ci in the north, Nag wroji Road prec wroji Road from he road for ped- cachand road. an immense url within the city. th of the plot, acc and ticket lobby and bobby, waiting con connects the loca at side. building, reserva as stand as a sing ight roof structure	par chowk garden, bus stop, inct on the south. If the west side. A subway strian access. The building is pan significance as a cessed from the west side rea is accessed through side ancourse on the north side, at station concourse on the station building and the station gle mass with domes, spires, re over platforms, breaking the station the front side, enclosing a

The central porch of the main building, leads to the main staircase lobby through a verandah, connecting the two 'L' shaped wings on both sides. All wings on all four side ends have staircases connecting the upper floors.

The rooms are planned in the center with connecting verandahs in its periphery.

The central, side and internal wing façades have extended porches ending into gable ends. The junction of the two wings on both sides is joined with a circular corner drum like wing with a dome above. The linear wings have extended dormer windows.

The rear east side of the building opens into a court, which is now occupied by out buildings.

The ground floor houses the cash office on the south side, library in the center and other offices on the east and north side.

The first floor is occupied by museum above the porch, and offices in the side wings.

The second floor is occupied by senior official cabins, conference room.

The attic floor is occupied by offices.

The dormer windows with sloping roof open into terrace above the verandahs.

The side ticket lobby terrace with skylights is accessed by ladder connecting from the north

Ticket lobby and waiting concourse with local train platforms:

The main building connects the ticket building on the north side. The first floor verandah of the main building overlooks the double height of the ticket lobby. The ticket lobby is accessed from the west side through an extended porch with terrace above. The lobby opens into the waiting concourse now occupied by vendors on the north side. The concourse connects the platforms in the north.

Six platforms are covered by two high triangular trusses with stepped castellated steel sections, supported on steel columns and brackets, covered with asbestos sheets. Annex and Reservation building:

The building is located on the east of the main building, accessed from the east side from an internal court.

The building is 'L' shaped with its longer side facing east west overlooking the St George road. The staircase block is located on the north end, connecting the extended wing on every floor through verandahs on both sides. All floors house administrative functions. The annex building is connected to the reservation block from the rear. The main access to this building is from the east side through an internal court.

Station Building:

The station building is accessed from the south side through a porch and on the west side through a semi enclosed area connecting the local train station. The porch opens into a ticket lobby, housing central double staircase with lifts on both sides, leading to the upper floors. The double height staircase lobby connects the two residential and waiting room wings on either side.

The ticket lobby opens into the waiting concourse connecting the platforms to the north. **Features**

Main Building:

The building façade features are symmetrically planned, as described.

The central projecting bay has an extended porch with floors above. The porch has side single arched openings and front three arched openings with decorative intrados, supported on round columns with decorative capitals consisting of floral pattern and animal motifs at the springing point. The front side edge supporting pilasters with a wide base and tapering top and bands. Above the pilasters is a round decorative projection with receding decorative bands at the bottom ending into spires at the top. The projection is highly decorative with a row of semicircular arches with alternate buff and black voussoirs, bands, friezes, quatrefoil openings, fort like parapets, dog gargoyles.

The space above the squinch area of the arcade in the porte-cochere houses the basreliefs portraits of personalities of the Earl of Dufferin and the Marquess of Dalhousie. The internal entrance has double semi circular arches with receding decorative arched bands consisting of decorative floral pattern in buff stone, supported on a series of polychromatic stone finished round columns on square pedestals and decorative floral pattern capital bands. The arches have round motifs at its springing points.

The first floor openings have segmental arches with alternate grey and red voussoir pieces, and roundels above with stone bas-reliefs portraits of Thos Watt, Colonel Hollard in the first floor. The windows have projecting sill bands and decorative stone railing.

The second floor openings have trifoil arched openings with decorative ventilator, supported on columns with decorative capitals and a pediment above. The tympanum has projecting sphere, surrounded with stone jali. The pediment top edge has decorative features as crocketing, finial. The centre space between the two pediments has a projecting chattri like structure, which once housed the stone sculpture of Queen Victoria, which is now removed. The statue stood with an orb and spectre in her right and left hands beneath the canopy attached to the wall.

The gable end of the central projecting wing has a large round clock on the façade with alternate buff and red voussoir pieces, crocketing at the edge and a Lion sculpture with a cartouche representing British power at the apex of pediment.

The wings on both the sides of the staircase wing have arch colonnaded verandah openings with ground floor pointed arches with alternate buff and grey stone voussoir pieces, supported on octagonal columns with decorative capital bands. The first floor Islamic arches with decorative intrados and roundels at the squinch level, with jali work within supported on round columns. The second floor with row of semicircular arches with buff and red voussoir pieces, decorative intrados, stone balustrade and jali work in the tympanum. The capital bands at all floor levels, consist of animal, floral motifs finished with fine craftsmanship. The springing points of the arch bands have floral motifs. Eight large bas-relief portrait roundels depict the founders, directors, and other important personalities behind the railway's historic development, are located in the ground floor in the space above the squinch area in the arcade. The men are on the left: Sir Jijibhai Bart, Lord Reay, and Lord Elphinstone; on the right Mountstuart Elphinstone, Sir Bartle Frere Bart, and J Shankersheth. Another set of portrait roundels on the southern façade, includes James J Berkeley, the engineer who masterminded many of railways difficult building schemes.

The tympanums at the ground floor level depict Science, embodying astronomy, electricity, physical geography, medicine, chemistry, and mechanics on the north west porch façade. The southwest porch façade represents 'trade', represented by the central figure of peace fostering hormonious relations between the east and west, peace being an essential condition of commerce.

The two intersecting perpendicular wings - both sides have projecting corner drum, finishing into a dome. The bay has pointed arched openings in the ground and first and second floor, with decorative intrados in the ground floor arches, alternate buff and red voussoir pieces on the first floor arches, and trifoil arches on the second floor. The third floor has lancet windows with a row of semicircular arches. The floor levels are defined by floral bands. On a smaller scale, the 'castes' of India are represented in the sixteen bas-relief heads in each of the corner drum in the north and south side.

The onion shaped dome has a finial at the apex, fort like stone balustrade and Ram head gargoyles at the dome base level.

The extended wings have central projecting bays facing the internal courtyard. The wings have pointed arches with double windows and quatrefoil openings at ventilator level. A three sided bay projects on the first floor and second floor level, supported on wide pilaster below. The bay has a tapering bottom with receding decorative bands, and balconies with balustrade at the balcony level.

Th gable end of the north and south internal wings facing the front court, have round rosette windows on the façade and edge crocketing. The apex of the side and the central apex of the pediment house lion sculptures in a sitting position with medallions in hand. The side wings facing the west have central projecting wing with gable end, projecting porch and higher side bays with spires above.

The porch has pointed arched openings with decorative intrados, and alternate buff and red stone voussoir pieces, with pediments above. The arches are supported on double columns and end pilaster ending into a spire. The pediments have tympanum representing the monogram of 'GIPR" with intricate jaliwork at the background and central motif. The sculpture at the apex of the pediments: on the southwest corner represent Commerce, depicted by a central figure expressing invitation and welcome, a figure on the left holding Britanias trident, and on the right holding a laurel wreath in her left hand to represent successful enterprise, a clipper ship symbolising trade placed beneath her right hand. Agriculture on the south façade, depicted by a central figure with a cornucopia and ploughshare symbolizing plenty, a figure on the right with a sickle and sheath of wheat as a symbol of reaping; and Engineering on the northwest corner of the main façade, depicted by a central figure with the cylinder of a steam engine, a figure on the left with a gunner's quadrant (military engineering), and a figure on the right with a screw propeller (naval engineering)

The pediment has crocketing at the edge.

The central wing has a marginally projecting wing with a row of arched doorways and quatrefoil ventilators above, opening into the terrace above porch. The second floor windows have a row of arched openings with alternate red and buff voussoir. The bay ends into a stone balustrade with lion sculptors sitting on both sides and band with gargoyles at its base

The side projecting wings have arched openings with decorative tympanum depicting the national bird of India 'Peacock' inscribed in it and intricate *jali* work in the background. The wings end into four spires at each end, along with a central spire. The side spires have tapering bottom edges with receding bands and slit rectangular windows at the top. The internal roofing of the north side porch leading to the ticket lobby has groined vaulted roof with an animal figure at the center of the ribs. The porch leads to the double height ticket lobby with overlooking galleries above with cast iron railing. The lobby has groin vault with wooden ribs and painted curved surfaces, supported on round stone colonette with high pedestal and decorative capitals. The spandrel and tympanum of the arches have floral, animal motifs, floral springing points. The ticket counters are located in the south side and lobby opens into the concourse on its north side through pointed arches.

Chhatrapa	ati Shivaji Terminus (Victoria Terminus)	121
Grinatrapa	au Sinvaji Terminus (Victoria Terminus)	The waiting concourse has flat and arched alternate bays with skylight openings. The steel arches are supported on steel columns. The intrados of the steel arch and the column brackets are highly ornamented with floral pattern. The central main stone staircase with triple height atrium space has an eight sided ribbed dome The lobby has an overlooking gallery at the dome base level with stone balustrade, opening into the dome peripheral terrace. The bays have arched lancet windows supported on colonette. Each lancet window has double trifoil arches with round openings and pediments above. The ribbed bands have croketing and apex of the dome ends into a sculpture depicting 'Progress'. The statue carries a copper glit flaming torch in her right hand, and her left hand holds a winged wheel which rests at her side. The windows have lower panels as openable doors and upper fixed stained glass panels. The stain glass mural represents floral and animal pattern, 'GIPR' and engine monograms. Floral bands define the dome base level. The internal alternate octagonal dome walls have receding arches with decorative bands of floral and animal in buff stone. The internal dome walls have friezes, bands at various levels. The first floor lobby has arched openings supported on decorative brackets. The conference room of the second floor has wooden coffered ceiling and arched openings supported on columns projecting out from the wall. The spandrel of the arch is decorated with animal heads, floral pattern inscribed in it. The columns have griffe at the base. The gate entrance has three gate posts with entrance and exit on either side. The circular high stone gate posts have tapering top with decorative capital bands, friezes. The side gate posts have high pedestal base for two animal sculptures Peacocks, egrets, lotus flowers, monkeys, lotus flowers and coats of arms are depicted in sculptural relief on tympanums throughout the public spaces and entrances to the building.
L		The building displays characteristics of the Victorian Gothic Style
5.3 5.4	Intrinsic	The first railway ran from here to Thane in 1853. A(arc), A(his), B(per), B(des), B(uu), C(seh), E, F, Recommended grade:
5.4	Value Classification	A(arc), A(his), B(per), B(des), B(uu), C(seh), E, F, G(grp), H(tec), I(sce)
6.0		Topography
6.1	Floors	Main building G+2+attic floor, with part terrace.
•••	1.00.0	man sanding of 2 data notify man part to notify
7.0		Construction
7.1	Plinth	Normal height plinth with sloping stone plinth protection band
7.2	Walls	Load bearing stone external wall, internal stone arches with brick infill.
7.3	Floor	Floors supported on wooden rafters.
7.4	Stairs	Main central grand open well 'C' shaped stone staircase with stone risers and treads. The staircase has upper overlooking galleries Four elliptical wooden staircases in the end of extended wings with wooden treads, risers and wooden slit soffit. Five cast iron spiral staircases connecting the top of the dome. Single flight narrow stone staircase at the periphery of the main dome.
7.5	Openings	Arched verandah, door and window external openings with pointed, semicircular arches with glazed paneled shutters and fixed glazed quatrefoil, rose window openings as ventilators. Main entrance wooden paneled grand doors with brass exposed hardware, with intricate wooden jail work in the fixed ventilator.
7.6	Roofing	Mangalore tile sloping roof with gable ends to the projecting corner and side wings, dormer windows etc, supported on king post wooden truss. AC sheet roofing with skylights supported over steel truss over platforms, waiting concourse. Groined ribbed vaulted roof over ticket lobby and lobby porch.
7.7	Articulation	Pointed, segmental, Islamic arches, rose windows, columns with decorative capitals, decorative intrados and tympanum, animal and floral friezes, gargoyles, cartouche, turrets, spires, domes, crockets, monograms, bas relief work of personalities.
7.8	Finishes	Building is externally clad with buff stone. The building features are of polychromatic stones consisting of buff, red and grey Porbunder stone, limestone, sandstone. The floor is finished with Minton tile flooring, and natural stone and wooden flooring at places The main staircase dome is finished with buff stone, with polychromatic stone finished arches, columns. The staircase has stone dado work with intricate edge stone detailing.
7.9	Interiors (Movable & Immovable)	Movable Old clocks with wooden casing, storage units, railway accessories and instruments stored in the museum area. Immovable Intricate decorative iron railing of the main staircase, wood paneling in conference room, wooden jali and tracery work in partitions, Minton tile dado in the conference room. Cast iron sand buckets holder with hooks, with the manufacturer "Merryweather & Sons

ımatrapat	i Shivaji Terminus (Victoria Terminus)	CIDD" expressed on it and fire base holder at every floor
		GIPR" engraved on it and fire hose holder at every floor.
		The west side entrance has two stone gate posts with two feline creatures (one a lion to
		represent British interest in India, the other a tiger to represent the national symbol of India
7.10	Compound/ Fence/ Gate	Main entrance from the west side has two large stone octagonal gateposts with a tapering
		top, along with a decorative iron gate. The rear side entrance has three large stone
		gateposts.
		Compound wall is composed of cyclopean stone masonary with cast iron fence above.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Front open space with symmetrically planned landscaped space with integrated paved
	Landscape	areas. Old trees, shrubs and potted plants in the front space.
		Parking area at periphery of the front space.
		Out buildings:
		Toilet block G+2 building connected to the Main building on the rear side.
		Extension building on the rear east side in the north corner.
		Canteen
		Police quarters, Provisional store structure – Ground structure
		Substation building – Ground structure
		The rear entrance to the platforms has been paved and covered with arched gateway and
		semi enclosed.
		Annex and Reservation building on the rear east side – G+3 with terrace (3 rd floor added).
		Buff stone clad 'L' shape building with similar features as the main building.
		Station building – G+3 buff stone clad Art deco style building, built in 1929.
8.0		Services & Utilities
8.1	Lighting	Adequate lighting through verandahs, passages, supplemented with artificial lighting
8.2	Ventilation	Adequate ventilation through verandahs, passages, supplemented with artificial ventilation
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Fire hydrant attached to the tank in the front open space attached to fire hoses and sand
0.0	THE Frecaution	buckets on every floor.
8.7	Other (HVAC/BMS/Security Systems)	Window air conditioning units have been installed in individual rooms.
0.1	Other (TVAC/BW3/3eculity Systems)	villuow all collutioning utilis have been installed in individual rooms.
0.0		Condition
9.0	Diath	
9.1	Plinth	Fair – blackened and stained due to weathering.
9.2	Walls	Poor – Seepage through walls observed at the upper floors.
9.3	Floor	Fair – Wooden members are in a deteriorating state at places. Seepage observed in the
		south verandahs on the second floor.
• •	0.1	Partitions have been added
9.4	Stairs	Fair – deteriorating due to daily wear and tear.
9.5	Openings	Fair - blackened and stained due to weathering. Cracks observed in the stone arches.
		Openings have been blocked to occupy AC at places; window and door shutters have bee
		changed. Stain glass shutters have been replaced.
		The main north west entrance to the platforms has been blocked by the subway entry.
		The second floor rear opening has been broken to connect the new toilet building.
		Openings in the front side have been blocked with hoardings.
		Verandah openings have been enclosed to occupy office functions and toilet blocks in the
		south and east side.
9.6	Roofing	Fair – Many additions and alterations have been made
9.7	Articulation & Finishes	Poor – Blackened due to weathering. Few stone carved and tracery features in the front
		side are in a deteriorating condition with some in a broken state. The south side façade
		features are in a neglected state. The stone parapet wall is in a poor state. The features
		exhibit staining and salt deposition.
		The interior of the ticket office has been insensitively altered by using ceramic tile flooring
		and columns clad with granite stone.
		Stain glass of the round windows of the west porch and in the lancet windows of the main
		dome has been replaced by coloured acrylic sheets.
9.8	Services	Poor - Services at the rear side have been haphazardly added.
		Electric wires and drainage lines have been passed through walls.
		Insertion of lifts has caused cracks in the masonary.
9.9	Out Buildings	Poor – Out buildings have been insensitively added. The rear side court houses
		incongruous structures blocking the façade.
0.40	Overall Conditions	Fair Maintenance level Poor
9 10	Overall Continuents	i vali i i vali i i ce i ce i ce i ce i ce i ce i ce
9.10		
		Transformation
10.0	Earm	Transformation
	Form	Subway has been added in the north west entrance. The north east side wing has been
		Subway has been added in the north west entrance. The north east side wing has been extended insensitively.
	Form Structure	Subway has been added in the north west entrance. The north east side wing has been extended insensitively. Catwalk has been added from the main dome to the porch wing gable end.
		Subway has been added in the north west entrance. The north east side wing has been extended insensitively.

Chhatrapat	rapati Shivaji Terminus (Victoria Terminus) 121	
		Toilets and conference room has been added.
		Toilet block has been connected to the main building on the east side.
		Water tanks occupy front and rear side part terraces.
	Articulation & Finishes	Many details have been broken or painted.
11.0		DP Remarks/ Perceived Threats
		Railway station, building forms part of C1 zone.
12.0		Additional Notes/ References/ Documents available
		Additional Notes: Chhatrapati Shivaji or Victoria Terminus (the terminus of the Great Indian Peninsula Railway, now known as the Central Railway was designed by Frederick William Stevens. Work commenced in 1878 and the station itself was opened for traffic on 1st January 1882. On Jubilee Day, 1887, the terminus was named after the Queen Empress. There is exquisite ornamentation and embellishment on the facade and beautifully executed panels, dados and friezes adorning the walls and the many loggias, buttresses, arches and windows. Inside the crowded booking office is a wealth of choice Italian marble, polished Indian blue stone and elaborate stone arches covered with carved foliage and grotesques. All the ornamental details of the building were drawn by F W Stevens himself. Other features include a tasselated floor, dados of glazed tiles, stained glass windows, galleries of highly ornamented iron work, long counters made of cleverly blended woods. The groined roof was originally painted in a shade of azure with gold stars. Striking features in the main entrance include ornate wooden doors spaced between impressively crafted marble columns and a grand cantilevered staircase that loftily skirts the walls with eight and a half feet wide overhanging slabs of blue stone, beautiful wrought iron railing and rich sienna marble wall. Between each of the eight ribs of the dome are long, stained glass windows decorated with the GIP monogram and arms and foliage. This has been awarded the 'World Heritage Monument' status. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd. ABHA NARAIN LAMBAH Through the Looking Glass – The Grade I Heritage of Mumbai, Mumbai: Urban Design Research Institute, Jasubhai Media and Super Book House



Front view of the 'C' shaped symmetrical building with the central bay with dome structure and side gable end wings



Subsidiary building 1 with arched and rectangular openings, an additional third floor



Verandah with arched openings with buff and red stone alternate voussoirs, supported on columns with decorative capitals and high base, with geometric pattern spandrel and frieze bands



Subsidiary building 2 with vertical bands and rear side subsidiary building 3 $\,$



Buff stone clad central wing with high gable end façade with pointed, semicircular and trifoiled arched openings, round clock with red and buff stone voussoirs, side turrets, decorative frieze bands, spandrels, pediments, bas-relief portrait roundels



Main porch entrance with multifoil arched opening with decorative arch band supported on grey stone round column with omamented capital and high base, side projecting pilasters with bands



Central dome structure with arched lancet windows ending into pediments, high spires with gargoyles, dome with crocketing on ribs surmounted by the sculpture depicting 'Progress'



Column capital clad with granite with highly ornamented corinthian capitals, animal motif at the springing point, arch band with floral pattern



Corner round projecting bay with trefoil arched opening supported on accouplement of grey stone columns with ornamented capitals, frieze bands of floral pattern at floor levels



Gate post on either side of the carved gate flanked by the Tiger and Lion sculpture depicting the symbol of Power in two countries of India and Britain on a high pedestal with floral and geometric pattern frieze bands



Detail of a crocodile Gargoyle



Arch articulation with polychromatic column finish on high base with decorative floral pattern frieze and arch bands



Detail of bas relief portrait roundel of Jagannath Shunkersett and other important personalities behind the railway's historic development on the facade



Ornamental tympanum with intricately carved floral and animal motifs, floral arch band



Gate post of the rear gate with geometric pattern frieze bands



Gable end view with crocketing in the edge and animal sculptures on either



Multifoil decorative arched windows on red stone columns on pedestal with round windows and frieze band



Pointed arch opening of corridor overlooking the front courtyard with bands, roundels




Lancet window with stained glass and carved articulation bands, rose window



ecorative arches and brackets in the roof over concourse with skylights and ventilators to admit natural light



Interior view of the arched corridor on round columns



Bas relief portrait band in the curved wing with dentil band and stone balustrade above



Subsidiary dome with fort like parapet, gargoyles, bands, arched windows



Arched window articulation with floral pattern frieze bands, balustrade, dentil bands, rose window opening



Detail of the carved stone balustrade and frieze bands in the gallery within dome structure



Decorative bands with symbols depicting progress of the railways etc



Vault of porch with carved bands, ribs, ceiling clad in red and white stone



Double height space at ticket counter with ribbed vaulting, overlooking galleries



Round column with a high base





Dormer window in sloping roof of the main building



Grand open well staircase with arched openings



Cast iron columns with wide capital, geometric pattern frieze band



Wooden partition detail with intricate tracery work in geometric pattern



Door in subsidiary building no 2 with glazed paneled shutters



Internal door and paneling with carved paneled shutters



Cast iron carved bracket in subsidiary building 1



Main dome with ribs, carved frieze bands, arched openings



Internal corridor with arched openings overlooking the front courtyard



Cement tile dado in committee room



Door in subsidiary building no 1with louvered and glazed paneled shutters



Vault detail above ticket counter with painted ceiling, floral motifs, ribs



Lift cage in subsidiary building 2



Wooden side staircase with carved newel post in subsidiary building 1



Stone staircase with wood and tile dado paneling, stone sculpture newel post and carved cast iron railing



Roof truss over platform area admitting North light



Joinery detail in steel with human face and geometric pattern relief work



Logo inscription of 'Great Peninsular Indian Railway' in the arched opening



Stained glass panel detai



Detail of the cast iron railing of grand staircase 1

Anjuman E	Islam High School		122
X		Common Ref No: 122	JYN / PHILLING
		Card No: 164	
		Ward (Part): A (part I)	
N		CS No: 1459	
i		Plot Area: Indeterminable	一人人们一个
A		B U Area: -	
		= *:"**	
1171		Date: 21/12/2004	1 1 5
		Recorded by: Zankhana Prajapati	I MI DO WILL
1	Till coo cool : 1	Reviewed by:	1
100 miles		Int: Zankhana Prajapati	
		Ext: Zankhana Prajapati	Oringa Dr. Dadabhai Nowroji Road
1 2 m 1 2 m 1 2 m		Photo Ref.: 122_Anjuman -e-Islam High	Dr. Dadamar Co.
0		School	Location Plan
-			Eocation Fian
1.0		Denomination	
1.1	Name of Premises	Anjuman E Islam High School	
1.2	Earlier Name	Anjuman E Islam High School	
1.3	Built in:	1890	Extension Date: -
2.0		Access	
2.1	Main	Dr Dadabhai Nowroji Road	
2.2	Subsidiary	Badrudin Tyebji Marg	
0.0		Ownerst "	
3.0		Ownership pattern	
3.1	Present	Trust - Anjuman E Islam	
3.2	Past	Trust - Anjuman E Islam	
3.3	Status	Trust	
40		11.	
4.0	Burnet	Use	
4.1	Present	High School	
4.2	Past	High School	
4.3	Usage	Institutional	
ΕΛ		Cincificance 9 Value Classification	
5.0 5.1	Townscape (Manmade)	Significance & Value Classification	gs along Dr. Dadabhai Nowroji Road precinct.
5.1	Townscape (Manimade)		ldings of similar styles like Times Of India and
		The building is accessed from the east side	
5.2	Architectural Description	Planning	, 5 5 5 6 6 6 6 6 6
		The building is placed on the site with huge	setback from the compound wall.
			andah on one side connecting the classrooms.
		Front wing consists of the main staircase le	ading to the upper floors and the service stairs
		is located in the corners of the building.	
		The ground floor houses the administration	of the school, the offices and a few classrooms $% \left\{ \left\{ 1\right\} \right\} =\left\{ 1\right\} =\left\{ 1$
		while the other classrooms are upstairs.	
		•	hat has been converted to more classrooms.
		Features	
		The building has many important decorative	
		column capitals and bases, <i>jalis</i> , minarets,	
		balcony and terrace parapets.	ds, decorative stone brackets supporting the
		Spiral staircases in the corners and the win	g junction end in minarets on top
		Style	a Janouan and in militalors on rap
		The building displays characteristics of the	Indo Saracenic style of Architecture
5.3	Intrinsic	-	,
5.4	Value Classification	A(arc), B(per), B(des), E, F, G(grp)	Recommended II B
			grade
			<u> </u>
6.0		Topography	
6.1	Floors	G+2	
7.0		Construction	
7.1	Plinth	Low Plinth, three risers high of grey stone v	vith a plinth protection band.
7.2	Walls	Load bearing stone walls	
7.3 7.4	Floor	The floor is supported on wooden beams	spiral staircases, located at the two ends of the

Anjuman E	Islam High School	12	
· · · · · · · · · · · · · · · · · · ·		main building and at the junction of the two wings.	
7.		The fourth staircase is a doglegged stair with wooden treads, risers, handrail and balusters	
7.5	Openings	All door and window openings are either pointed arch openings or Mughal arches, with ventilators above and wooden and glass panels below.	
7.6	Roofing	Domes over some portions, flat roofs and sloping Mangalore tile roof, finished RCC roofs over other portions. Asbestos sheet roofing in some areas supported on a timber framework.	
7.7	Articulation	The building is elaborately articulated internally as well as externally with pointed arches, decorative column capitals and bases, <i>jails</i> , minarets, ventilators, <i>chhatris</i> , <i>jharokhas</i> , domes, Mughal arches, floral motif, comice bands, decorative stone brackets supporting the balcony and terrace parapets.	
7.8	Finishes	External walls are clad with exposed grey and buff basalt stone, internally the rooms are plastered and painted. The floor is finished with Minton tiles in some areas and ceramic tiles and Indian Patent Stone in others.	
7.9	Interiors (Movable & Immovable)	Movable Old wooden cupboards, book cases, light fixtures, chandeliers. Immovable -	
7.10	Compound/ Fence/ Gate	Compound wall consists of cast iron decorative gate with a grey stone gate post.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	The playground of the building occupies the front setback of the site along with some landscaped areas between other buildings. New buildings have been added in the compound like the canteen, the new building of the Anjuman e Islam school, Akbar Peerbhoy Polytechnic, Catering College and the Management building.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light supplemented by artificial lighting.	
8.2	Ventilation	Adequate naturally ventilation supplemented by artificial ventilation	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	WICOW	
8.7	Other (HVAC/BMS/Security Systems)	- Window air conditioners have been added	
0.1	ethor (HV/No/BMO/Geoding Gysteme)	THIRDW AII CONDITION HAVE DECIT ADDECT	
9.0		Condition	
9.1	Plinth	Poor - plinth has been covered with sand, earth. Seepage has been observed in different places along with dust collection and plant growth.	
9.2	Walls	Poor - cracks have been developed internally, external walls are blackened and damaged at places due to plant growth and seepage.	
9.3	Floor	Fair - The floor has also developed cracks at certain places.	
9.4	Stairs	Fair	
9.5	Openings	Poor - Many of the window panes are broken and have been blocked by wooden planks or brick walls. The door and window pattern has been changed in many places. The frames of the windows and stone arches have been changed and repainted, the have been painted	
9.6	Roofing	Fair - The original Mangalore tiled roof has been replaced in many places by asbestos sheets. The roof is leaking in many places.	
9.7	Articulation & Finishes	Fair - Plaster peeling has been observed in the interior spaces and seepage of walls has damaged much of the articulation.	
9.8	Services	Fair - Pipes are leaking and extensive plant growth has been observed.	
9.9	Out Buildings	Fair	
9.10	Overall Conditions	Fair Maintenance level Poor	
10.0		Transformation	
	Form	One of the largest transformations to the form of the building is the addition to the rear of the building of the Akbar Peerbhoy Management wing.	
	Structure	Loading conditions might have changed due to the addition of the new wing.	
	Articulation & Finishes	Stone has been painted in many places while a lot of the decorative articulation is damaged.	
11.0		DP Remarks/ Perceived Threats	
		Secondary school	
12.0		Additional Notes/ References/ Documents available Additional Notes:	
		-	
		References:	

Anjuman E Islam High School 122		
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.
		Fisher Goodearth Ltd. (2002) City Man., Mumbai, Mumbai



Grey stone clad building with Islamic style features like arches, spires, jail work, tower dome.



Minaret detail with floral motifs, spires, dentil moulding etc



Front façade with arched openings with buff and grey stone cladding



Main Entrance of the building with receding arches with multifoils and floral motifs in the spandrel.



Detail of jaliwork in a minaret



Arch detail with grey and buff stone band of voussoir, ventilator jaliwork, floral motifs and frieze bands, terrace balustrade, cornice band



Detail of frieze band with floral motif at floor level



Detail of the decorative bracket supporting the projecting floor above.



Gable end with arched openings. Incongruous additions to the façade opening, attered shutters etc mar the façade features



Octagonal tower with pointed arched openings with jaliwork, frieze and floor bands



Column with floral pattern Corinthian capital



Open well staircase with intricate cast iron and wood railing



Tower detail



Corner detail showing tower with minaret surmounted by a dome



Verandah with arched openings on columns with Corinthian capitals



Marble tablet with inscriptions written in Urdu



Arched window opening blocked by louvered shutters



Light fixture in interior



Wooden spiral staircase



Internal façade with arched openings. Many additions have taken



Detail of the multifoil arched opening with stone ventilator floral and geometric pattern tracery work



Dome detail with geometric pattern stone and ceramic frieze band with a pinnacle in the top



Intricate Jali work in an arch ventilator with floral motif in the spandrel

Times of India	huilding			400
i imes of india	Dulluling	Common Ref No: 123	- 11 mm	123 11 11 111 111 111 111 111 111 111 111
		Card No: 165	- SA TITLE	
		Ward (Part): A (Part II) CS No: 1451		
		Plot Area: 5676.93 sq m	10 II	P P
2		B U Area: 28384.65 sq m	7	Dadabhai Nowroji Roa Satingka Mars
904 00	Marian Wallet	Date: 10/01/2005		hai No
	WAY WILL SALE TO	Recorded by: Sonal Modak	Mahapalika	Sabhgrina Marg
	my m	Reviewed by	A ATE	Road
Care El		Int: Sonal Modak, Zankhana Prajapati		
	一	Internal photography permission denied		
	AMARIA	Ext: Sonal Modak, Zankhana Prajapati	- 6	
		Photo Ref: 123_Times of India.	1 2 8	Casula Terrinis
			The sales	Chhatrapati Sriver
				Location Plan
1.0	Nove (Decele	Denomination Times of the the theta		
1.1	Name of Premises	Times of India building		
1.2	Earlier Name	Times of India building	Extension	
1.3	Built in:	Commencement 1901, Completion 1903	Extension Date	-
			Date	
2.0		Access		
2.1	Main	Dr. Dadabhai Nowroji Road – Pedestrian		
2.2	Subsidiary	A narrow lane on north and south - Pedestria	n	
3.0		Ownership pattern		
3.1	Present	Private – Times of India Group		
3.2	Past	Private – Bennett Coleman and Company Bu	ilding	
3.3	Status	Owner		
4.0		Use		
4.0	Drocont	Commercial - Press, shops		
4.1	Present Past	Commercial – Press		
4.3	Usage	Commercial – Press		
	Coago	- Jany		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)	It is one of the heritage buildings along D		
		Chhatrapati Shivaji Terminus maintaining a	similar scale ar	nd features as the neighboring
		buildings.	norsh spannin	a across the feetwath in from
		Main access is a central access through a (eastern) side.	i porch spannin	g across the lootpath in from
		Two towers capped by onion shaped dome	es on northern	and southern ends define the
		expanse of the building.	oo on normon	and southern sinds define the
5.2	Architectural Description	Planning		
	· ·	A rectangular plan with central entrance throu		
		Provision of separate staff and goods entrand		
		Various in-house departments of Times of Ir		
		building. Service areas and toilets are locate differs from floor to floor as per the department		and northern facades. Layou
		Engaged octagonal pilasters tapering towar		vellow stone divide the from
		façade in seven vertical bays. The bays at no		
		shaped domes. Ground floor has large point		
		have comparatively smaller pointed arche		
		inscribed within on first floor and	·	
		Features		and collect by 0 1 19
		The north, south and east frontage are fa	aced with grey	and yellow basalt and white
		Porbunder stone. The eastern frontage has three large rose-win	ndowed gables	
		A bulbous dome-capped tower at north and s		eastern facade
		Step out balconies at first floor level rest on d		
		Features like floral motifs, decorative spand		
		be seen on the front façade.		
		Style		
F 2	1.02.2.	Predominant use of Neo-Gothic and Indo-Sar	racenic style of a	architecture.
5.3	Intrinsic	- A(ara) D(nor) D(d) E E O()	Deecono	d arada II A
5.4	Value Classification	A(arc), B(per), B(des), E, F, G(grp)	Recommended	g grade II A.

Times of In	dia building	12
6.0		Topography
6.1	Floors	G + 3 front wing, G + 5 rear wing
7.0	20.4	Construction
7.1	Plinth	Medium plinth about 2 ft high in grey stone with a plinth protection layer.
7.2	Walls	Thick load bearing composite external walls. Internal brick walls as per requirement.
7.3	Floor	Floors are resting on cast iron columns. Most of the areas have false ceilings. Floorir system is indeterminable as could not be seen.
7.4	Stairs	Main timber staircase with wooden balustrades and handrail. Narrow RCC staircase.
7.5	Openings	Main entrance door accessed from a porch spanning across the footpath on eastern side.
	3,	Large arched openings on ground floor, comparatively smaller arched openings on first ar
		second floors.
		First floor openings have circular ventilator panels inscribed inside the arch fixed wi
		glazed panel and glazed sashed shutters on second floor.
		Third floor has rectangular openings with wooden frame glazed double shutters. Step out balconies at first floor level resting on stone brackets.
7.6	Roofing	The eastern wing along Dr. D. N. Road has MS north-light trusses with AC roofing shee
7.0	1.00mig	and Mangalore tiles above.
		Remaining part has flat RCC slab roofing.
7.7	Articulation	Façade punctuated by pointed arched windows, rose windows, engaged pilaster
		decorative arch springing points, floral motifs.
7.8	Finishes	External walls with exposed grey basalt ashlar masonry facing.
		Walls plastered and painted internally. Porch columns clad with granite slabs.
7.0	Lateria or (Managhta O Languaghta)	Ceramic tile dado and wooden paneling in some parts of the building.
7.9	Interiors (Movable & Immovable)	Movable
		- Immovable
		-
7.10	Compound/ Fence/ Gate	Building sits on entire plot with a marginal open space on rear (western) side.
7.11	Curtilage/ Unbuilt space/ Out	
	Buildings/ Landscape	
8.0		Services & Utilities
8.1	Lighting	Adequate natural light through door-window openings and supplemented by electric light
8.2	Ventilation	fixtures. Though natural ventilation through door-window openings is available, it is totally dependent
0.2	Vertulation	upon a forced ventilation system.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Indeterminable
8.7	Other (HVAC/BMS/Security Systems)	Central AC unit. Window AC units in cabins
9.0	20.4	Condition
9.1	Plinth	Fair
9.2	Walls Floor	Good
9.4	Stairs	Good Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Fair
9.8	Services Out Buildings	Fair -
		- Good Maintenance level Good
9.9 9.10	Out Buildings	Good Maintenance level Good
9.9	Out Buildings Overall Conditions	- Good Maintenance level Good Transformation
9.9 9.10	Out Buildings Overall Conditions Form	- Good Maintenance level Good Transformation Fourth and fifth floors have been added on rear (western) wing.
9.9 9.10	Out Buildings Overall Conditions	- Good Maintenance level Good Transformation Fourth and fifth floors have been added on rear (western) wing. Temporary shed erected along northern side for parking.
9.9 9.10	Out Buildings Overall Conditions Form Structure	- Good Maintenance level Good Transformation Fourth and fifth floors have been added on rear (western) wing. Temporary shed erected along northern side for parking. Addition of steel sections to strengthen floors.
9.9 9.10	Out Buildings Overall Conditions Form	- Good Maintenance level Good Transformation Fourth and fifth floors have been added on rear (western) wing. Temporary shed erected along northern side for parking.
9.9 9.10 10.0	Out Buildings Overall Conditions Form Structure	- Good Maintenance level Good Transformation Fourth and fifth floors have been added on rear (western) wing. Temporary shed erected along northern side for parking. Addition of steel sections to strengthen floors. Interiors have been totally changed over the period.
9.9 9.10	Out Buildings Overall Conditions Form Structure	- Good Maintenance level Good Transformation Fourth and fifth floors have been added on rear (western) wing. Temporary shed erected along northern side for parking. Addition of steel sections to strengthen floors. Interiors have been totally changed over the period. DP Remarks/ Perceived Threats
9.9 9.10 10.0	Out Buildings Overall Conditions Form Structure	- Good Maintenance level Good Transformation Fourth and fifth floors have been added on rear (western) wing. Temporary shed erected along northern side for parking. Addition of steel sections to strengthen floors. Interiors have been totally changed over the period.
9.9 9.10 10.0	Out Buildings Overall Conditions Form Structure	- Good Maintenance level Good Transformation Fourth and fifth floors have been added on rear (western) wing. Temporary shed erected along northern side for parking. Addition of steel sections to strengthen floors. Interiors have been totally changed over the period. DP Remarks/ Perceived Threats

Times of India building

The Design was prepared by the firm of Gostling and Morris in keeping with the neighbouring buildings. The foundation stone laying ceremony of the building took place or December 30, 1901 and the building was completed in 1903. The design was prepared by the firm of architects, Gostling and Morris, in a mixed Gothic and Saracenic style in keeping with the neighbouring buildings. The north, south and east frontages are faced with blue and yellow basalt and with white Porbunder stone. The eastern frontage is specially effective with its three large rose-windowed gables, two subordinate pediments and a Saracenic dome capped tower at either end of the facade. Since its establishment in these offices, the Times of India is referred to as 'the old lady of Bori Bunder'.

References:

NTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) *The Cities Within*, Bombay : Eminence Designs Pvt. Ltd.

RAHUL MEHRÖTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.



Grey stone clad façade with arched openings with white bands, buff stone columns and corner tower with onion shaped roof dome roof.



North side façade with additions and transformations



Projecting balcony with decorative brackets, floral motifs, bands etc



South side elevation with additions and transformations



Balconies with stone balustrade, finials, supported on decorative brackets



Pointed arched window openings with buff stone voussoirs, arch bands with floral motifs at the springing point and spandrel



Pointed arch door opening with decorative pattern in the spandrel and ventilator.

Akbar Pee	erbhoy Polytechnic		124
		Common Ref No: 124	PROFULUDIAN MASS
		Card No: 166	- 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
		Ward (Part): A (Part I)	
		CS No: 1460	- ACTION DESCRIPTION OF
All and	24		
		Plot Area: 234.95 sqm.	
		B U Area: -	
		Date: 22/12/2004	
The same		Recorded by: Sonal Modak	10. W. W.
		Reviewed by:	
		Int: Sonal Modak	
13 = 1		Ext: Sonal Modak	4 18
1 Vanda		Photo Ref: 124_Akbar Peerbhoy Polytechn	io
		Filoto Rei. 124_Akbai Feerbiloy Folyteciili	1 51
			Dr. Dadabhai Nowroji Road
			Dr. December 1
			Location Plan
1.0	Name of December	Denomination	
1.1	Name of Premises	Akbar Peerbhoy Polytechnic	
1.2	Earlier Name	Akbar Peerbhoy Polytechnic	let believe to
1.3	Built in:	1860	Extension Date: Indeterminable
2.0		A	
2.0 2.1	Main	Access Dr. Dadahhai Nowroii Poad - Vohicular and	d Podostrian
2.1	Subsidiary	Dr. Dadabhai Nowroji Road – Vehicular and	u reuestiidii
2.2	Subsidiary		
3.0		Ownership pattern	
3.1	Present	Private -Trust	
3.2	Past	Indeterminable	
3.3	Status	Owner	
0.0	Otatas	OWNER	
4.0		Use	
4.1	Present	Institutional – Educational	
4.2	Past	Institutional – Educational	
4.3	Usage	Daily	
	- J		
5.0		Significance & value Classification	
5.1	Townscape (Manmade)		hai Nowroji Road standing opposite Chhatrapat
		Shivaji Terminus in the same campus as th	
			ground, shared by the Institute and the High
		School from eastern side.	
5.2	Architectural Description	Planning	
			ger arm has the classrooms and the shorter arm
		houses the main wide staircase, office area	
		All floors have a typical floor plan with wide	aving wide staircases connecting all the floors
		through a pointed arch having intricately ca	
		Longer arm has a stilted ground floor with p	
			on of additional floors above the western wing
		supported on an RCC frame structure that	
		Features	
		Arcade on ground level stilt has pointed a	arches. Main entrance is a pointed arch having
		intricately carved jali work.	·
			I floors on south and east façade in the corner.
		Decorative stone balustrade along the corri	dors on southern façade.
		Style	
		Influence of Indo-Saracenic style of archite	cture.
5.3	Intrincic	_	
5.4	Intrinsic Value Classification	A(arc), B(per), B(des), E, F, G(grp)	Recommended grade II B
J. T	value Glassification	π(αιο), υ(ροι), υ(αεο), L, I , Θ(g(ρ)	Trecommended gradel II D
6.0		Topography	
6.1	Floors	G+ 5 Main building block.	
	- 100.0		
7.0		Construction	
7.1	Plinth	Low plinth with stilts at ground level.	
7.2	Walls	Composite walls with grey ashlar masonry	
		Internal walls are non-load bearing brick wa	
	•		

	rbhoy Polytechnic	124
7.3	Floor	RCC flat slab floors.
7.4	Stairs	Main wide staircase in a common lobby.
		New dog-legged RCC staircase in the western wing.
7.5	Openings	Main entrance door has a pointed arch.
		All window openings are rectangular with wooden frames glazed double shutters.
		Ground floor stilts have an arcade of pointed arches.
		Large pointedarches span through all the floors on southern and eastern façades.
		Square ventilators at each floor fixed with stone <i>jalis</i> on eastern façade of the shorter arm.
7.6	Roofing	RCC slab flat roof.
7.7	Articulation	Formula was the control of the latest the control of the latest the control of the latest the control of the latest the control of the latest the control of the latest the control of the latest the latest the latest the control of the latest
7.8	Finishes	Exposed grey ashlar masonry externally. Walls plastered and painted internally.
7.9	Interiors (Movable & Immovable)	Movable
1.5	interiors (Movable & Infinovable)	
		Immovable
7.10	Compound/ Fence/ Gate	Institute shares a common boundary with the High School built in brick masonry about 3 ft 6
7.10	Compound/ Ferice/ Gate	inches high on all four sides.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Open ground on eastern side.
7.11	Landscape	open ground on casiem side.
	Landocape	
8.0		Services & Utilities
8.1	Lighting	Adequate natural light through door-window openings and corridors, supplemented by
0.1	Lighting	electrical lighting.
8.2	Ventilation	Adequate natural ventilation through door-window openings and corridors, supplemented
0.2	3.1.1.3.1.3.1	by electrical fans.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Indeterminable
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable
9.0		Condition
9.1	Plinth	Fair
9.2	Walls	Fair
9.3	Floor	Fair
9.4	Stairs	Fair
9.5	Openings	Fair – Broken door-window glazed panels.
9.6	Roofing	Fair
9.7	Articulation & Finishes	Fair
9.8	Services	Fair
9.9	Out Buildings	Fair
9.10	Overall Conditions	Fair Maintenance level Fair
10.0		Transformation
	Form	•
	Structure	Work is currently under way of adding floors on the western wing supported on an RCC
		frame rising from the ground.
	Articulation & Finishes	Barring the arches on the ground floor, the higher floors are devoid of any articulation.
11.0		DP Remarks/ Perceived Threats
		Secondary School, building forms part of R zone.
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		•
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd.
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,



Newly constructed building



Newly constructed Annex building




Verandah openings of the remaining old part of the building with jail work



Arcade with pointed arched openings of the old part of the building



Arched opening of the old building with intricate tracery work in the ventilator



Lord Raey Workshop building with its extended wing:

The structure is located in the north east corner of the plot, opposite school of Art and the sculpture workshop, accessed from the west side.

The building is 'T' shaped with its longer side facing east west and the extended wing in the north-south direction. The studios of the east side are accessed by a passage facing west side. The studios are lit by north lights, supported on wooden supporting members. North Side Structures:

Few ground storied structures for heavy machinery, student's common room, toilet blocks, servant's quarters with wooden truss roofing with eaves and wooden brackets supporting the Mangalore tile roof.

College Of Architecture:

The structure is located in the center of the plot, towards the east side with its main entrance from the east side, through a porch with an arched opening. The building is 'C' shaped with marginal extensions on the west side. It has a central lobby area with staircase located in the north side. The studios are located on the east side with verandahs with arched openings, overlooking on the west side. The studios have semicircular openings. The ground floor houses the administrative areas, staff rooms, multipurpose hall and deans room with a mezzanine floor. The upper floors are occupied by studio spaces. The new building housing studios and library is located on the south side of the old building.

Commercial Arts section and Canteen shed:

The commercial arts workshop behind the Architecture building is a long ground structure with an extended porch with sloping roof structure supported on wooden members. The canteen shed is located opposite to this structure.

Structures housing Record room, PWD department and recreation area, are located behind the Commercial Arts section in the rear east side.

Residence of Dean:

The residence of the dean is located in the west side of the plot, and is oriented in the east-west direction, with its main entrance from the north and south side through an extended wooden porch. The building has a longitudinal symmetrical plan with the central and side projecting wings. The rooms overlook into the verandah spaces and projecting balconies, on both sides, overlooking large setbacks on all sides within the plot. The building is completely wooden with wooden column posts, louvered paneling, intricately carved jali work, brackets with sloping gable roof. The central portion is higher than the side wings.

Applied Arts Building:

The building is located on the south side of the plot, and is oriented in the north south direction with its entrance from east side, enclosing a front open space. The building is 'C' shaped with an extended porch. The building has a central lobby space and staircase area with wings on either side. The building houses administrative rooms with verandahs overlooking the front courtyard. The central wing with a gable roof is higher than the rest of the wings with sloping roofs and projecting eaves. The building has intricately carved wooden verandahs with louvered paneled *jali*. The annex building housing studio spaces is on the rear side and is connected to the old building with bridges, enclosing rear courts. Offices of Director and Deputy Director of Art are located on the front north side and the canteen building is located in the south side of the old Applied Art building.

Many other small ground structures like Cook's room, Watchman's cabin, Mali's cabin, clay storage area are spread in the plot.

Features

School Of Arts:

The building is clad with grey stone ashlar masonry.

The porch entrance is through side pointed arched openings with grey and buff stone voussoirs, intricately decorative capitals with motifs representing floral pattern, animal face, human beings involved in some activity. The porch has a stone seat incorporated between the front columns. The first floor has two arched openings with trifoil arches supported on decorative columns. The façade is adorned with floor levels bands, geometric pattern motifs, friezes, architrave bands, quoins.

The side wings on the either side of the central wing have pointed arched openings with grey and buff stone voussoirs on the ground and first floor. The ground floor has round openings and wooden continuous chajjas with decorative brackets, above the windows. Bands at floor levels, dentil comice bands on the top with stone carved balustrade at the terrace level.

The arched openings on the front side have intricately carved spandrel with animal and floral tracery work.

College of Architecture:

The building is clad in grey stone on the ground floor and first floor clad with buff stone band. The entrance is an elaborately ornamented with concave arched openings with curved projecting steps, clad with rusticated buff stone and features such as festoons, mask motifs and comice bands above.

The entrances at four corners are elaborate with arched openings with alternate buff and

Sir J. J.	School of Arts Complex			125
Sir J. J.	School of Arts Complex	grey stone voussoirs, corner quoins, The ground floor is clad with grey st floor upper level is defined by buf openings with emphasized keystone capitals in between the openings w defined by bands below and corniverandah spaces of arched opening north side façade has rectangular op The internal doors have thick arch deans room with wooden mezzanine Residence Of Dean: The wooden structure with projectin gable roof, wooden posts, intricat shutters. The building has overlooking vera wooden paneling, wooden brackets a Applied Arts Section: The central entrance porch wing and stone cyclopean masonry. The entra spandrel consisting of floral pattern: receding floral bands below, intricate on wooden brackets. The first floor floor level bands. The second floor h The verandah spaces have woode sloping lean to roof below and slowindows. The end wings have carved receding pitched conical sloping roof. The windows. The internal spaces have large arc space on the first floor has and intrictions to the space of dean and the Vernacular style of Architecture.	one and has low-lever for stone band and has, clad with buff stone the human mask marker bands above. The same bands above. The same bands above. The same bands above. The same bands above. The same bands above. The same bands above. The same bands above. The same bands above. The same bands above. The same bands are transported to the same bands are th	el rectangular openings. Ground has ventilator level semicircular e. Doric columns with decorative notif above. The floor levels are le east side of the façade has f stone alternate voussoirs. The ls same as the wall thickness, porches on both sides with high ed paneling, wooden louvered bound projecting balconies with light Mangalore tile lean to roofs. Spiecting wings are clad with grey arched openings with decorative dipharokha, projects above with light opening. The sloping roof is supported is with white band architrave and with stone-carved balustrade. In an eling, intricate jali work and lecting eaves above with round both sides supporting the higher balconies supported on stone wooden flooring. The exhibition for Architecture.
5.3	Intrinsic Value Classification	Sir Jamsethjee Jeejeebhoy who fun the ancient crafts of India. Famous writer Rudyard Kipling, son the building, which now is the resider A(arc), B(per), B(des), E, F, G(grp)	of sculptor Jon Locky	Dean's bungalow: II A School of Art: II A, School of Architecture: II B, School of Commercial Art: II
				A
6.0		Topography		
6.1	Floors	G + 1		
7.0		Construction		
7.1	Plinth	Low plinth clad with grey (Kurla) stor	e and double plinth p	protection buff stone band.
7.2	Walls	Load bearing stone walls.		
7.3	Floor	Wooden flooring with wooden suppo		
7.4	Stairs	Central main staircases with ston staircases with wooden railing.		Ç
7.5	Openings	Large semicircular arched, rectangular or row of arched openings for the studio spaces with single panel pivoted shutters. Rectangular openings with glazed paneled shutters. Verandah stone arched openings, wooden verandahs with intricate wood paneling. Door - louvered or paneled shutters, with fixed paneled ventilators. Internal large column free arched open spaces.		
7.6	Roofing	Sloping Mangalore tiled roofs suppor		
7.7	Articulation	Arched openings, bands, friezes, jha		
7.8	Finishes	The walls are externally clad with sto Floor is finished with natural stone ar		ster and painted.
7.9	Interiors (Movable & Immovable)	Movable Tables, chairs, easels, notice board by students, carved boxes. Immovable	s, library furniture, d	isplay units, sculptures in stone

Sir J. J	. School of Arts Complex	125	
		Black bust of Sir Jamsethjee Jeejeebhoy installed at west side of the School of Arts entrance. Black stone sculpture in a sitting position on the east side between the School of Arts and Lord Raey Workshop building. Marble fountain in front of the south entrance, and brass plaque mentioning the birth of writer Rudyard Kipling on the north side at the Residence of Dean.	
7.10	Compound/ Fence/ Gate	Brick compound wall with fence above. MS gates from the two ends of the east side. Rear gate on the west side.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	The buildings are connected with paved pathways. The plot has very rare old trees, shrubs, green inlands, sculpture garden in the north end, amphitheater, informal stone seating area around canteen.	
8.0		Services & Utilities	
8.1	Lighting	Adequate light through large openings of studio and verandah openings, supplemented by artificial lighting.	
8.2	Ventilation	Adequate ventilation through large openings of studio and verandah openings, supplemented by artificial ventilation.	
8.3	Electricity	BEST BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Few cabins have window AC's installed.	
9.0		Condition	
9.1	Plinth	Fair - The School of Arts building plinth is almost negligible due to alterations. The plinth of other buildings is in a deteriorating state with organic plantation, seepage, chipping.	
9.2	Walls	Fair – Some places there are leakages observed. Internal partitions have been added.	
9.3	Floor	Fair – at some places the wooden members of the flooring are in a deteriorating state. Steel sections have been added for additional support.	
9.4	Stairs	Fair – Some places supports have been added.	
9.5	Openings	Poor – The openings have been blocked to house AC's, shutters have been changed. Few door openings have been closed with brick. Verandah openings have been blocked, paneled in an insensitive manner. Many changes in the internal and external openings of the School of Arts building have been planned.	
9.6	Roofing	Fair – Few places skylight material has been replaced, chajjas have been changed.	
9.7	Articulation & Finishes	Fair – Few places features are in a broken condition. The stone façade of the Architecture building has been painted. Applied Art building features are in a deteriorating state.	
9.8	Services	Fair – At few place pipes in toilet blocks and other electrical services have been insensitively added.	
9.9	Out Buildings	Fair – Few new buildings at the rear side are planned in an insensitive manner.	
9.10	Overall Conditions	Fair Maintenance level: Fair	
10.0		Transformation	
10.0	Form Structure Articulation & Finishes	Upper floors of the Old Architecture building have been added. Extensions have been made in various buildings. I-sections have been installed to strengthen the floor. Verandahs have been enclosed. Openings are blocked, opening size and shutters have been changed. Outbuildings have been insensitively added in the rear portion. Chaijas have been replaced with asbestos sheet.	
		Н 1	
11.0		DP Remarks/ Perceived Threats	
		College, complex forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: In 1853, Sir Jamsetjee Jeejeebhoy endowed Re 1 lakh towards an art school. The JJ School of Art building was designed by George Molecey and completed in 1878 at a cost of nearly Rs 200,000. Mr Terry, a draughtsman and engraver from England, was hired to organise the school. In 1866, Higgins and John Lockwood Kipling (father of Rudyard Kipling) began conducting classes in decorative painting, ironwork and modelling. Under Kipling's guidance, students prepared models for the sculptural details of the University buildings, Victoria Terminus, Crawford Market, the Alfred Sailors's Home and other public buildings. A commemorative plaque in the compound states that the renowned writer, Rudyard Kipling was born here. References:	

Sir J. J. Scho	of Arts Complex 125
	INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
	Structures listed for Conservation.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay:
	Eminence Designs Pvt. Ltd.
	RAHUL MEHRÖTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
	in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
	Division of International Thomson Publishing Inc.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence
	1 = =

Eicher Goodearth Ltd. (2002) City Map - Mumbai, Mumbai.

Designs Pvt. Ltd.

School of Architecture



Front façade of the Architecture section clad with grey and buff stone cladding, arched openings, brackets, cornice bands.



Verandah overlooking central court with arched openings with buff and grey stone voussoirs



Detail of the capitals with floral and human face motifs



New building of the Architecture faculty



Detail of the gargoyle



Semicircular window openings with pivoted openable glazed paneled shutters

Sir J. J. School of Arts Complex



Double height arched entrance with emphasized keystone, floral pattern embellishments, rusticated stone columns



Wooden and glazed notice board



Grand wooden paneled entrance door



Wooden staircase in the Deans room with wooden intricated railing



Arched opening with grey and buff stone voussoirs, floral pattern arch band, ornamented cartouche above arch, cornice band at floor level



Subsidiary entrance with arched opening, arch bands, scroll brackets. Arch bands





Residence of dean



Wooden structure of vernacular style with wooden panels, trellis work, sloping roof supported on brackets



Fountain at the entrance



Corner view of the wooden structure with wooden railing, paneling, roof supported on brackets, trellis work



Front entrance porch on wooden columns, wooden panels, railing and tracery work


School of Arts



Grey stone clad building with arched and round openings and comice bands in buff stone



Bust in stone of the founder of the school at the entrance



Stone statue



Central entrance wing with with high gable end, arched openings, frieze bands, dentil moulding etc



Arched window with buff stone voussoirs, sill band and wooden glazed window and louvered ventilator shutters



Entrance with trifoiled arch opening and a row of arched window openings above



Detail of the stone finial with floral pattern



Intricate stone tracery work in the ventilator with floral and animal motifs



Projecting balcony detail with decorative bracket supports and balustrade



Sloping wooden roof supported on wooden truss



Art school studio pivoted openable shutter



Intricate floral and animal motif in the column capital



Stone staircase with cast iron and wood railing



Trefoil arch in pointed arch window

Sir J. J. School of Arts Complex

School of Applied Art



Front façade with verandah and balconies with wooden trellis work, sloping roof



Central bay clad with grey stone, arched openings, projecting balconies, railing



Intricate floral pattern in column capitals, with bands



Ornate floral pattern tapering corbelling of the projecting balcony above entrance



Verandah and balcony with wooden columns, intricate wooden trellis work, paneling and sloping roof supported on brackets



Verandah with wooden roof, paneling, columns, louvered paneled shutters



Marble tablet



Projecting balconies supported on brackets



Roofscape





Internal landscaped pathway



Garden



Recreational room clad in grey ashlar masonary with sloping roof



Veranda at first floor with wooden sloping roof, wooden columns and railing



Amphitheater



Canteen shed



Workshop shed structure with Mangalore tiled sloping roof supported on wooden truss.

/lahatma P	Phule Market		12
		Common Ref No: 126	77 - 23 N
		Card No: 168	
		Ward (Part): A(Part I)	
		CS No: 1491	
		Plot Area: 22471.75 sq m	
		B U Area: -	of High St.
		Date: 10/12/2004	de de la companya del companya de la companya del companya de la c
		Recorded by: Zankhana Prajapati	
		Reviewed by:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		Int: Arun Wadhwa, Zankhana Prajapati	
The same of		Ext: Arun Wadhwa, Zankhana Prajapati	
		Photo Ref.: 126_Mahatma Phule Market	
		(Crawford Market)	
1.0		Denomination	Location plan
1.1	Name of Premises	Mahatma Phule Market	
1.2	Earlier Name	Arthur Crawford Municipal Market.	
1.3	Built in:	Completed in 1869.	Extension Date: Indeterminable
2.0		Access	
2.1	Main	Lokmanya Tilak Marg – vehicular and pedes	strian
2.2	Subsidiary	Dr. Dadabhai Nawroji road from the west an	
	Subolidiary	51. Budubhar Humoji Toda nom me west an	a randifficatio tilo odot.
3.0		Ownership pattern	
3.1	Dragant	Municipal Corporation of Greater Mumbai	
	Present		
3.2	Past	Bombay Municipal Corporation	
3.3	Status	Ownership	
4.0		II.	
4.0		Use	
4.1	Present	Commercial - Municipal market	
4.2	Past	Commercial - Municipal market	
4.3	Usage	Daily	
5.0		Significance & value Classification	
5.1	Townscape (Natural/ Manmade)		e at the junction of Lokmanya Tilak road and D
		Dadabhai Nawroji road with a high clock tow	ver.
5.2	Architectural Description	three large gateways. Staircase to the upper part leads to a high of The two wings of the market are planned as Features High octagonal clock tower with sloping roof Triangular gable roof profile along the street Semi-circular arched openings forming entra circular window openings in alternating stonicarved column capitals at the ground floor o	round a central open space. le along the Lokmanya Tilak road. with a central market hall and is accessed by lock tower above. long rows of stalls under a high sloping roof. profile. front. anceways to the market. Pointed arch and e courses. Circular columns with ornately penings. Projecting upper floor veranda ets. Beautifully sculpted marble panels in bas- openings. supporting the roof structure atop high Iron
5.3	Intrinsic	Beautifully sculpted marble panels in bas-re- piece of sculpture of its kind ever to be atten	lief, crafted by J Lockwood Kipling, largest npted in India.
5.4	Value Classification	A(arc), A(his), B(per), B(des), B(uu), E, F, H	(tec), I(sce) Recommended grade: I
6.0		Topography	
6.1	Floors	G+2 floor in the central building, large marke	et space is single storied.

Mahatma Pl	nule Market	126	
7.1	Plinth	Very low plinth constructed in rubble stone dressed.	
7.2	Walls	Built in coarse kurla rubble stone with porbunder coignes,	
7.3	Floor	Wooden floorboards and rafters, supported by load bearing walls on projecting stone brackets. Flagstone flooring in the ground market space.	
7.4	Stairs	Octagonal in plan, stone slab staircase with a central circular column and wooden handrail fixed to the wall.	
7.5	Openings	Pointed arch window openings with glazed paneled shutters. Entrance semicircular arched openings, circular rose window openings, with decorative relief panel, quatrefoil openings.	
7.6	Roofing	Central building has sloping Mangalore tile roof supported on timber trusses. The market space has series of sloping monitor roofs in corrugated iron sheet supported on lattice beams and brackets.	
7.7	Articulation	-	
7.8	Finishes	Porbunder stone dressing on external façade, decoratively carved features in limestone	
7.9	Interiors (Movable & Immovable)	Movable - Immovable Stone fountain at the main entrance, spire like, ornamental moldings. Ornamental stone fountain with decorative panels of tutelary animals and Indian river goddesses.	
7.10	Compound/ Fence/ Gate	Heavy iron gates with decorative features, form entrances to the market. Iron railings with similar features on parapet wall form the compound wall to the large market complex.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Numerous open structures serving as fish, meat and vegetable markets within the complex. Small Mangalore tile structure serving as restaurant at the southeast corner.	
8.0	11.10	Services & Utilities	
8.1	Lighting	Adequate natural light through door-window openings supplemented by electric light fixtures.	
8.2	Ventilation	Adequate natural ventilation supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No trace of fire fighting or precautionary system.	
8.7	Other (HVAC/BMS/Security Systems)	Window unit air conditioners installed at various locations.	
9.0		Condition	
9.1	Plinth	Poor – extensive seepage, interventions and waste dumped around the plinth causing unhygienic conditions.	
9.2	Walls	Poor – cracks, seepage and plant growth observed.	
9.3	Floor	Fair - except decaying wooden members	
9.4	Stairs	Fair - except for seepage in certain walls of staircase has been observed.	
9.5	Openings	Partly Fair – neglected and non-maintained.	
9.6	Roofing	Poor - Lattice beam and bracket members in a poor state, corroded and dilapidated. Neglected and poor state of maintenance.	
9.7	Articulation & Finishes	Poor -	
9.8	Services	Poor - Messy and unplanned service lines running across with exposed wires and	
9.9	Out Buildings	Poor - Numerous structures,	
9.10	Overall Conditions	Poor Maintenance level: Low	
10.0		Transformation	
	Form Structure	Internal space has undergone complete transformation as open stalls are converted into shop like enclosures.	
	Articulation & Finishes	Incongruous installation of hoardings, mar the marble carved Bas relief features and openings.	
11.0		DP Remarks/ Perceived Threats	
-		Municipal wholesale and retail market, building forms part of C1 zone	
12.0	+	Additional Notes/ References/ Documents available	
12.0		Additional Notes: References: Documents available Additional Notes: Designed by William Emerson and named after an enterprising former Municipal Commissioner, Arthur Crawford. Above the entrance are beautifully sculpted marble panels in Bas relief crafted by Lockwood Kipling, father of Rudyard Kipling. This was at that time the largest piece of sculpture of its kind ever to be attempted in India. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,	

Mahatma Phule Market 12		
	Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd.	
	ABHA NARAIN LAMBAH <i>Through the Looking Glass – The Grade I Heritage of Mumbai</i> , Mumbai: Urban Design Research Institute, Jasubhai Media and Super Book House.	



West side comer curved elevation with a rising clock tower and sloping roof structure



Side elevation of the wing with incongruous installation of hoardings



Octagonal shaped high rising clock tower clad with buff stone, floor bands, brackets, arched openings



Side wing with symmetrical façade of gable end bays and central sloping roof structure.



Entrance arched openings with a projecting balcony above, supported on stone brackets



Fountain at the entrance completely encroached by the vendors.

Mahatma Phule Market 126



First floor corridor space with curved sloping roof supported on wooden members



Cast iron bracket detail supporting the sloping roof



Corinthian column capital with floral pattern in stone



Lion head bas relief detail



Carved bas relief depicting 'working people' in the tympanum of semicircular arched opening



Dormer window detail in the sloping roof

Mahatma Phule Market 126





Quatrefoil opening in stone with organic growth



Spiral staircase



Hoardings covering elevational features



Rose window within an arch with polychromatic voussoirs



Side entrance gate, occupied by hawkers, temporary shed added

Mahatma Phule Market 126





Tablet on outside fountain



Marble tablet inserted in the arch with decorative jail in tympanum



Window arched openings with polychromatic voussoirs, bands etc





Rectangular window with band around, shutters in broken condition

Equatoia a	at Crowford Market	127
rountain a	at Crawford Market	
	W W 7	Card No: 169
	THE PURPLE TO	Common Ref No: 127 Card No: 169 Ward (Part): A (Part 1) CS No: 1491 Plot Area: 22471.75 co. m.
		CS No: 1491
10		Plot Area: 22471.75 sq m
W	PARTIE LANGE AND AND ADDRESS OF THE PARTIE A	B U Area: -
		//> "" // //
		Date: 10/02/05
		Recorded by: Prachi Merchant
-		Reviewed by:
	CHAIR OF CARRY	Int: NA
to the	N	Ext: Prachi Merchant, Arun Wadhwa Photo Ref: 127_Fountain in Mahatma Phule
		Market.
		Warnet.
		Location Plan
1.0	7	Denomination
1.1	Name of Premises	Fountain at Crawford Market
1.2	Earlier Name	Fountain at Crawford Market
1.3	Built in:	Indeterminable Extension -
		Date
2.0		Access
2.1	Main	Inside the Crawford Market - pedestrian
2.2	Subsidiary	-
3.0		Ownership pattern
3.1	Present	Municipal Corporation of Greater Mumbai
3.2	Past	Municipal Corporation of Greater Mumbai
3.3	Status	Ownership
4.0		Use
4.1	Present	Fountain – Not in a working condition. Presently used as selling platform, sitting and sleeping place,
		clothes drying line, fruit basket storage area.
4.2	Past	Fountain, Monument.
4.3	Usage	Not in use as fountain and monument
5.0		Significance & value Classification
5.1	Townscape (Manmade)	Three fountains are planned in the Crawford market, with one at the entrance and two in the internal
5.1	Townscape (Maninade)	open courtyard.
		The fountains are accessed from any of the four Crawford market entrances - from the main
		Lokmanya Tilak Marg and Dadabhai Nowroji Road.
5.2	Architectural Description	Planning & Features
		The south side stone fountain at the entrance is planned in three levels in a receding manner. The
		base has a wider level with four corner geometric motifs, slender round columns supporting the triangular motifs with trefoil decorations inside and a spire at the top. A parapet wall has been built
		around the fountain.
		The internal courtyard occupies an ornamental fountain with decorative panels of tutelary animals
		and the Indian river goddesses sculpted. The fountain is planned in four levels with the base with
		corner geometric projections holding short round columns with floral motif capitals. The upper layer
		has a cylindrical bowl with elaborate gargoyles, floral, animal and goddess motifs, which is supported
		on brackets. The topmost level holds a smaller clover shaped bowl with motifs, ending into a slender
		tall motif. Further to the east of the market in the open area is located a stone and plaster monument with
		chhattri, bearing multifoil arches on its square base and surmounted by brackets and an onion dome.
		On one of its trefoil arches is a marble commemorative plaque.
		Style
		The fountain at the entrance and the internal courtyard fountain derives influence from Victorian Neo
		Gothic style of Architecture.
F 2	Intringia	The extreme east end fountain derives influence from Islamic style of Architecture.
5.3	Intrinsic	The south side stone fountain at the entrance has been gifted by the philanthropist, Sir Cowasji Jehangir.
		The internal courtyard fountain has been designed by William Emerson with decorative panels of
		tutelary animals and the Indian river goddesses sculpted by John Lockwood Kipling.
5.4	Value Classification	A(his), B(per), B(des), B(uu), Recommended I
		grade
	1	

	t Crawford Market	12
6.0	5	Topography
6.1	Floors	
7.0	B###	Construction
7.1	Plinth	•
7.2	Walls	•
7.3	Floor	•
7.4	Stairs	-
7.5	Openings	•
7.6	Roofing	-
7.7	Articulation	Slender columns, animal and floral motifs, gargoyles, <i>chhatris</i> , multifoil arches.
7.8	Finishes	All parts of the fountain have been painted.
7.9	Interiors (Movable & Immovable)	Movable
		- Immovable
7.10	Compound/ Fence/ Gate	- Parapet walls have been added around the fountains.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-
8.0		Services & Utilities
8.1	Lighting	-
8.2	Ventilation	
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	All the parts of the fountain are insensitively finished with multi layers of various oil paint colours. There are numerous layers of oil paint of different colours, resulting in clogging of pores. Growth of plants and algae is visible at many sections. Rear monument is weathered and is in a neglected state.
9.2	Walls	-
9.3	Floor	
9.4	Stairs	
9.5	Openings	
9.6	Roofing	The internal fountain has an asbestos sheet roof built above with vertical MS supports taken from th sides.
9.7	Articulation & Finishes	Multiple layers of paint are applied on the Fountain. The original material and finish cannot b identified. The features are completely covered with fruit baskets, clothes drying line, etc.
9.8	Services	-
9.9	Out Buildings	·
9.10	Overall Conditions	Fair Maintenance level Low
3.10	Overall Conditions	Maintenance level Low
10.0	Form	Transformation Roof shed has been built over the central fountain insensitively. Parapet walls have been built around the fountain which have been occupied by hawkers and vendo cartons. Fountain is not in use.
	Structure Articulation & Finishes	All the features have been insensitively painted in many layers. The original material and finis cannot be identified.
11.0		DP Remarks/ Perceived Threats Municipal wholesale and retail market, building forms part of C1 zone
12.0		Additional Notes/ References/ Documents available Additional Notes: Just inside the main entrance of Crawford Market is a lovely fountain, gifted by the philanthropist, Si Cowasji Jehangir. In the outdoor courtyard is a remarkable ornamental fountain designed by Willian Emerson with decorative panels of tutelary animals and the Indian river goddesses sculpted by John Lockwood Kipling. Sadly, the fountain has been overpainted with bright colours highlighting it features. The flowing robes of the river goddesses have been converted into garish cholis and saree and their foreheads have been embellished with bright red bindi marks. The plaque bears the inscription: "This Fountain has been erected from funds subscribed by owner of private markets and stall holders of municipal markets to commemorate the visit to Bombay 1911

127 Fountain at Crawford Market

of their imperial majesties King George and Queen Mary".

References:

INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd.

RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay - Conserving an Image Centre, 2 Vols, Bombay.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt.

ABHA NARAIN LAMBAH Through the Looking Glass - The Grade I Heritage of Mumbai, Mumbai Urban Design Research Institute, Jasubhai Media and Super Book House.



Fountain with floral and animal ornamented motifs, encroached by vendors






Detail of fountain portion with floral, bird motifs in capital, bands and animal gargoyles



Incongruous encroachments by vendors




Sheth Char	mbers (No. 21 Building)	128
7.11	Curtilage/ Unbuilt space/ Out Buildings/	
	Landscape	
8.0		Services & Utilities
8.1	Lighting	
8.2	Ventilation	
8.3	Electricity	
8.4	Water Supply	
8.5	Drainage (Plumbing & Sanitation)	
8.6	Fire Precaution	
8.7	Other (HVAC/BMS/Security Systems)	
9.0		Condition
9.1	Plinth	
9.2	Walls	
9.3	Floor	
9.4	Stairs	
9.5	Openings	
9.6	Roofing	
9.7	Articulation & Finishes	
9.8	Services	
9.9	Out Buildings	
9.10	Overall Conditions	Fair Maintenance level: Fair
10.0		Transformation
	Form	Ground floor is completely transformed. Openings have been blocked to install AC units
	Structure	, , , , ,
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.





Main Entrance setback utilized as parking

Projecting Balcony supported on I-sections



	House (Building No. 74) Landscape	
	Zanaosapo	
8.0		Services & Utilities
8.1	Lighting	-
8.2	Ventilation	-
8.3	Electricity	-
8.4	Water Supply	-
8.5	Drainage (Plumbing & Sanitation)	-
8.6	Fire Precaution	-
8.7	Other (HVAC/BMS/Security Systems)	
9.0		Condition
9.1	Plinth	Completely transformed building with no trace of the original building
9.2	Walls	-
9.3	Floor	-
9.4	Stairs	-
9.5	Openings	-
9.6	Roofing	-
9.7	Articulation & Finishes	-
9.8	Services	-
9.9	Out Buildings	-
9.10	Overall Conditions	Fair Maintenance level: Fair
10.0		Transformation
	Form	Completely transformed building with no trace of the original building
	Structure	
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
		-
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings a Structures listed for Conservation.


Rallis Hous	SQ.	130
ixaiiis MUU:	A. H. C.	Common Ref No: 130
		Card No: 172
		Ward (Part): A (Part III)
9	The state of the s	CS No: 1411, 1412 (Fort division)
12		Plot Area: 1167.69 sq m.
	3. (2)	B U Area: - Date: 10/02/2005
		Date: 10/02/2005
		Recorded by: Sonal Modak
4		
-6		Reviewed by:
750	原则供参考的公司专	Int: Sonal Modak
īii		Ext: Sonal Modak Photo Port 130 Politic House
		Photo Ref: 130_Rallis House.
	(veil) and	Location Plan
4.0		Denomination
1.0	N (D)	
1.1	Name of Premises	Rallis House
1.2	Earlier Name	Rallis House
1.3	Built in:	1920's Extension -
		Date
2.0	<u> </u>	Access
2.1	Main	Murzban Road – vehicular and pedestrian
2.2	Subsidiary	Damodar Sukhadwala Road – pedestrian
3.0		Ownership pattern
3.1	Present	Private
3.2	Past	Private – Rallis India and others
3.3	Status	Owner
3.3	Status	Owilei
4.0		Use
4.1	Present	Commercial – Offices
4.2	Past	Commercial – Offices
4.3	Usage	Daily
5.0		Significance & value Classification
5.1	Townscape (Manmade)	The building is located on a corner of Damodar Sukhadwala Road, Murzban Road and
J. I	Townscape (Manimade)	Hazarimal Somani Marg.
		The main access is from Murzban Road on eastern side and subsidiary entrance is from
		Damodar Sukhadwala Road on the northern side.
5.2	Architectural Description	Planning
		It is a rectangular building with an internal court.
		The renovation of the building is in progress and only the enclosure is kept as is, the
		building is totally demolished internally.
		The northern façade is divided in three vertical bays, central bay projecting out marginally.
		Main entrance openings and windows on side bays are architrave openings with console
		and projecting cornice band serving as weather protection.
		Features
		Architrave openings with console and cornice band above the openings serving as weather
		shades at ground and first floor level.
		Rustication on ground floor external wall. Bands having key patterns at all floor levels.
		Projecting cornice band resting on dentils at fourth floor level.
		Style
		Influence of Neo-Classical style in architecture.
5.3	Intrinsic	-
5.4	Value Classification	A(arc), B(per), E, F, G(grp) Recommended II A
•		grade:
		grave.
		Tana amandan
6.0	Floring	Topography
6.1	Floors	G + 4 with basement.
7.0		Construction
7.1	Plinth	High plinth in grey ashlar masonry to accommodate ventilators for basement.
7.2	Walls	Thick load bearing external walls. Internal walls have been demolished.
7.3	Floor	Demolished.
7.4	Stairs	Demolished.
7.5	Openings	Rectangular openings

Rallis House		130
7.6	Roofing	Demolished.
7.7	Articulation	Console, on which cornice bands rest. Projecting cornice band at fourth floor level.
7.8	Finishes	External face clad with buff coloured stone. Internally, walls are plastered and painted.
7.9	Interiors (Movable & Immovable)	Movable
7.10	Compound/ Fence/ Gate	Building sits on entire plot.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-
8.0		Services & Utilities
8.1	Lighting	Natural supplemented with artificial means.
8.2	Ventilation	Natural supplemented with artificial means.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	•
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	Fair – Chipping seen in a few places.
	Walls	Fair – External walls retained. Minor cracks seen. Internal walls demolished for renovation.
9.2		
9.3	Floor	Demolished
9.4	Stairs	Demolished
9.5	Openings	Fair - Building is not in use. Renovation process in progress.
9.6	Roofing	Demolished
9.7	Articulation & Finishes	Demolished
9.8	Services	Demolished
9.9	Out Buildings	
9.10	Overall Conditions	Under Renovation. Maintenance level: Under Renovation.
10.0	Form	Transformation The enclosure of the building is retained and building is totally demolished from inside for
		renovation purposes.
	Structure	The enclosure of the building is retained and building is totally demolished from inside for renovation purposes.
	Articulation & Finishes	•
44.0		DD Demontor/ Demonstrat Threats
11.0		DP Remarks/ Perceived Threats Building forms part of C1 zone
		building forms part of CT zone
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd.

Rallis House 130



Buff stone clad corner building with rusticated joints on ground floor, cornice bands, chajja bands



Opening articulation with lintel band, geometric motif frieze band, scroll brackets, wooden paneled door shutters



Building articulation detail of the frieze band, dentil cornice band



Window detail with sill band, floor band in geometric pattern

The Freem	asons' Hall	131
		Common Ref No: 131
		Card No: 173
	Mark State of the	
		Ward (Part): A (Part II)
		CS No: 1404, 1403, 1402, 1401 (Fort
		division)
P. 3		Plot Area: 2648.66 sq m.
		B U Area: -
		Date: 17/12/2004
The same		division) Plot Area: 2648.66 sq m. B U Area: - Date: 17/12/2004 Recorded by: Zankhana Prajapati Reviewed by:
A SPECIAL PROPERTY AND ADDRESS OF THE PARTY AN		Recorded by. Zarikilaria i rajapati
		Reviewed by:
TI WAR		Int: Sonal Modak, Zankhana Prajapati
1 300		Ext: Sonal Modak, Zankhana Prajapati
DIO NE		Photo Ref: 131_Freemason's Hall.
		Location Plan
4.0		Location Plan Denomination
1.0	Name of Description	
1.1	Name of Premises	The Freemasons' Hall
1.2	Earlier Name	The Freemasons' Hall
1.3	Built in:	5 th June 1897 First stone was laid. Extension -
		Date
		<u> </u> .
2.0		Access
2.1	Main	Damodar Sukhadwala Road
2.2	Subsidiary	Murzban Road
3.0		Ownership pattern
3.1	Present	Scotch and English Constitution
3.2	Past	The Present Joint Trustees of the Free Hall & others
3.3	Status	Trust
4.0		Use
4.1	Present	Social Activities – Lecture Hall
4.2	Past	Social Activities – Lecture Hall
4.3	Usage	Weekly
	00090	1100111)
5.0		Significance & value Classification
5.1	Townscape (Manmade)	The building is located on a corner plot at the junction of Damodardas Sukhadwalla Marg
0.1	Townscape (Maninade)	and Murzban Road opposite Sterling Cinema and Tata Palace.
		Main access to the building is from the corner through a porch.
5.2	Architectural Description	Planning
0.2	7 Torritodarar Bosonption	The building is odd shaped in plan having a corner entrance through a porch.
		A spacious entrance lobby houses the main wide staircase leading to the above floors.
		There is a huge double height hall in the center of the building, around which are located
		offices and ancillary activities like kitchen, toilets store rooms, archives etc.
		Another big prayer hall is located right above at the second floor level on the central hall or
		ground floor. Along northern side there is a smaller prayer hall, which is accessed through
		the main staircase lobby.
		Basement is not in use, accessed from the main staircase lobby on ground floor.
		The rear side is recessed and extended with an additional floor. This facade has plair
		pediments altered by semicircular pediments.
		Features
		Projecting balustrade porch with semicircular arch in front and segmental arches on sides.
		Rectangular window openings with plastered architraves and some are balustrade
		openings. It also has a comice floor band and a fret band running above the first floor
		rectangular ventilators. Walls have quoins in all corners.
		Style
		Derives influence from Colonial style architecture.
5.3	Intrinsic	One of the oldest and the only Freemasons Halls in the city.
5.4	Value Classification	A(arc), B(per), E, F, G(grp) Recommended grade II A
J. T	value Classification	Nation, bypern, E. i., Oldin.
6.0		Tonography
6.0 6.1	Floors	Topography C + 2 with part torrace
. 0 1	Floors	G + 2 with part terrace.
		Construction
7.0	Plinth	Construction High plinth to accommodate basement ventilators.

The Freema	asons' Hall	131	
7.2	Walls	External thick load bearing walls with ashlar masonary facing and quoins.	
		Internal non-load bearing brick masonary.	
7.3	Floor	Timber floor with large timber beams, wooden rafters and wooden floorboards on top Some areas have jack arch flooring with MS sections.	
7.4	Stairs	Wide staircase with cast iron railing and highly carved newel posts. The mid landing of staircase is supported on inclined struts resting on corbel stones.	
7.5	Openings	All door/window openings are rectangular with wooden framed glazed double panels.	
7.6	Roofing	Timber roof truss hip roof with Mangalore roofing tiles.	
7.7	Articulation	Plain triangular and semicircular pediments above window openings at second floor level. Cornice band and fret band at second floor level.	
7.8	Finishes	Stone masonary is painted externally. Walls plastered and painted internally. Minton tiles, wooden floorboards are the materials used for flooring.	
7.9	Interiors (Movable & Immovable)	Movable Formal garments for meetings based on a dress code including aprons, collars and gauntlets, protective garments wom by the original masons stored in big wooden cupboards. Wooden triangular pyramidal boxes having divine pictures painted over and many more such wooden equipments required for rituals. Immovable Portraits of Grand Master of the Regional Grand Lodge hung in the main staircase lobby. Bust and statues of various Grand Masters placed in various places.	
7.10	Compound/ Fence/ Gate	Brick masonary wall on north, south and western sides.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	External wall of building forms compound wall on eastern side. The narrow marginal spaces around the structure are totally in neglected and unhygienic condition.	
8.0		Services & Utilities	
8.1 8.2	Lighting Ventilation	Adequate natural light available and supplemented by artificial lighting. Inadequate natural ventilation supplemented by electrical fans. Some areas are provided with forced ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No Traces.	
8.7	Other (HVAC/BMS/Security Systems)	Window AC units have been installed in some areas.	
9.0		Condition	
9.1	Plinth	Fair – No evident damages seen. Height reduced due to road filling.	
9.2	Walls	Fair – Minor cracks observed on external walls. Dampness due to leakages.	
9.3	Floor	Fair – Wooden members have been replaced in many places. Leakages observed.	
9.4	Stairs	Good	
9.5	Openings	Fair – Door/window shutters are replaced in many places. Addition of grills.	
9.6	Roofing	Fair – Deteriorated wooden members in some places.	
9.7	Articulation & Finishes	Fair	
9.8	Services	Poor – totally in neglected state. Unhygienic kitchen, toilets and open side margin spaces.	
9.9	Out Buildings	Poor – Cleanliness not maintained at all.	
9.10	Overall Conditions	Fair Maintenance level: Poor	
10.0		Transformation	
	Form		
	Structure	Steel sections in many places have replaced wooden members.	
	Articulation & Finishes	Repainted externally.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
12.0		Additional Notes: When Freemasonry was purely operative, there was a ceremony for admitting apprentices. A youth entered as an apprentice to learn the craft; an obligation was taken to preserve the mysteries of the Craft; the mason word and sign were communicated; charges were read telling the new mason of his duty to God, his master and his fellow man; and the legendary history was read. It was a simple ceremony - designed to impress him with the high moral standards required of him. Religious intolerance and social decadence were rife in Europe in the 16th century. The Holy Roman Church wielded much power, brooked no dissent, and ruthlessly suppressed all attempts at reformation as heresy.	

The Freemasons' Hall

With the formation of the Grand Lodge in 1717 Freemasonry emerged as a system of morality and spiritual development presented in the form of ritual. It proposed a graduated method by which instruction was imparted to candidates in proportion to their ability to absorb its teachings. Accordingly three degrees were developed, to teach.

The initial stage of preparation and purification, followed by the cultivation of the intellectual faculties and the quest for the ultimate reality, culminating in the realisation of spiritual truth and the mystical death.

Such is the probable origin of the Masonic ritual. It has subsequently been shaped and perfected by many hands, has drawn its wisdom from all parts of the world and from all ages, till it attained its present form.

The meetings of freemasons are formal affairs, processing lodge business according to strict and antique protocol. Dress is based on aprons, collars and gauntlets, and derives from protective garments worn by the original masons.

The Bible is opened as a reminder of God's Law, though in other countries this could just as easily be, say, the Koran. Any ceremonial business is heavily symbolic, designed to echo and reinforce the moral lessons being imparted. Where you and I see a square, the mason sees virtue. Masonic symbols represent: Truth, Benevolence and Brotherhood

References:

INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) *The Cities Within*, Bombay : Eminence Designs Pvt. Ltd.

RAHUL MEHRÖTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

SHARADA DWIVEDI and RAHUL MEHRŎTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.

www.masonindia.org



Buff stone clad corner building with an extended porch, corner quoins, frieze bands



Porch with arched opening and rusticated joints, scroll bracket keystone, dentil band, balustrade



Building with rectangular openings, floor bands



Stone cornice band detail

The Freemasons' Hall



Window detail with stone balustrade, frieze band



Bust in buff stone



Grand staircase with carved wooden railing



Interior view of the main hall with high ceiling, openings with pediment, comice band



Wooden intricately carved furniture



Minton tile flooring

Ruttonsee	Muljee Fountain			132
	joo : ouu	Common Ref No: 132		
		Card No: 174		Confectioner
				CASASY AS
	<u> </u>	Ward (Part): A (Part II)		
	7	CS No: 1089 (Fort division)	7	
	2	Plot Area: Indeterminable		Jamahay Mouse
		B U Area: Indeterminable		Annual diamana and
p. 307		Date: 11/01/05	- ∑a (€	
			Mint Road	2
**		Recorded by: Prachi Merchant	J ≥ U	og (
	CHANGE THE PROPERTY OF THE PARTY Reviewed by:		The state of the s	
		Int: NA		Shahid Bhagat Shigh Road
		Ext: Sonal Modak, Prachi Merchant	AGIARY LANE	agait and a grant
est.		Photo Ref.: 132_Ruttonsee Muljee fountain		Sarunde Blde
			-	Mitta Moneion
)	S ions
			1 1	700 Aug. 11
	A STATE OF THE PARTY OF THE PAR		Loca	ation Plan
1.0		Denomination		
1.1	Name of Premises	Ruttonsee Muljee Fountain		
1.2	Earlier Name	Muljee Jetha Fountain		
1.3	Built in:	Completed in 1894	Extension Date: -	
		- Completed III 100 I	ZALONOION ZULON	
2.0		Access		
2.1	Main	Intersection of Mint Road and Shahid Bhaga	t Singh Road	
2.2	Subsidiary	-	t Oiligii Noda.	
<u> </u>	Subsidially			
3.0		Ownership pattern		
3.1	Dragant	Municipal Corporation of Greater Mumbai		
	Present			
3.2	Past	Bombay Municipal Corporation		
3.3	Status	Owner		
4.0	-	Use		
4.1	Present	Ornamental Fountain located within a traffic	island	
4.2	Past	Drinking water Fountain		
4.3	Usage	Public Fountain		
5.0		Significance & Value Classification		
5.1	Townscape (Manmade)	It stands as a prominent ornate sculpture at		busy roads as a public
		fountain in past and a traffic island at presen	t.	
5.2	Architectural Description	Planning & Features		
		The fountain consists of a large, octagonal b	ased central tower sur	rounded by smaller
		chhatris.		
		There are water channels running at differen		
		on all 4 sides, plinth level drinking water spor		
		petal shaped upper basin from which water s	spouts out to the lower	basin.
		It is constructed using multi-coloured stones		
		chhatri, grey basalt for the plinth and limesto		
		The structure is built on a high plinth to acco		
		drinking troughs for animals, and the steps a	nd base of the central	portion is crafted in blue
		basalt stone.		
		The upper basin is of white stone and is sup		
		white stone moulded bases and carved caps	over which are projec	cting elephant heads
		from the trunks of which water flows.		
		The face of the basin is richly moulded and of		
		The white stone dome is supported on polish	ned blue Aberdeen gra	inite columns with
		moulded and carved caps and bases.		
		Style		
		The fountain derives influence from Indo-Sar		
		The influence is seen thorough the bulbous of	domes springing from	lotus
5.3	Intrinsic	-	_	1
5.4	Value Classification	A(cul), B(des), B(uu), D(bio), F, I(sce)	Recommended	II A
			grade	
_				
6.0		Topography		
	Floors	Topography The fountain is a stand-alone structure havin	g water basins at four	different levels
6.0 6.1	Floors		g water basins at four	different levels

Ruttonsee Mu	ljee Fountain	132	
7.1	Plinth	The structure is built on a high plinth which stores the water tank.	
7.2	Walls	Walls of the central tower are constructed in stone masonry.	
7.3	Floor		
7.4	Stairs	•	
7.5	Openings		
7.6	Roofing		
7.7	Articulation	Plain bands at different levels. Decorative stone <i>jalis</i> used in smaller <i>chhatris</i> housing drinking water spouts at plinth level. Decorative column capitals. The cantilever water basin is richly moulded and carved with animal heads and foliage.	
7.8	Finishes	The fountain is plastered and painted. The upper basin is in white stone supported by polished red granite columns with white stone moulded bases and carved capitals. Bulbous dome in white stone supported on Aberdeen granite columns.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	A compound wall has been constructed around the structure fixed with diamond mesh fencing.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	-	
8.0		Services & Utilities	
8.1	Lighting		
8.2	Ventilation	<u>-</u>	
		BEST	
8.3	Electricity		
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	•	
8.7	Other (HVAC/BMS/Security Systems)	•	
9.0		Condition	
9.1	Plinth	Poor - Water tank slab is in a broken state, opening covered with a metal jali.	
9.2	Walls	Poor - Effects of weathering observed such as peeling of paint. Organic growth at many places.	
9.3	Floor	•	
9.4	Stairs	•	
9.5	Openings	•	
9.6	Roofing	•	
9.7	Articulation & Finishes	Poor, stone finish seems uneven and blackish in appearance. Presence of organic growth. The stone jali is missing in few places due to lack of maintenance and. Animal head spouts are broken in many places. Broken columns have been repaired using cement concrete in few places.	
9.8	Services	•	
9.9	Out Buildings	•	
9.10	Overall Conditions	Poor Maintenance level Poor	
10.0	Form Structure	Transformation Fencing has been added around the fountain. The lowermost water basins are used as planters. Minor repairs to the columns are observed.	
	Articulation & Finishes	Animal head spouts have been painted with blue oil paint. Outer face of the upper basin has been painted.	
11.0		DP Remarks/ Perceived Threats Structure forms part of R zone	
12.0		Additional Notes/ References/ Documents available Additional Notes: Designed by Frederick William Stevens, the fountain was erected by Ruttonsee Mulji in memory of his only son in 1894. Under the dome is the statue of Mulji's son, the work of John Griffiths, former principal of the JJ School of Art, under whose direction the students crafted all the embellishments to the fountain. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.	

Ruttonsee Muljee Fountain		
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,	
	Division of International Thomson Publishing Inc.	
	Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	
	ABHA NARAIN LAMBAH Through the Looking Glass – The Grade I Heritage of Mumbai,	
	Mumbai: Urban Design Research Institute, Jasubhai Media and Super Book House.	



ew of the central portion, Highly ornamented fountain with intricately carved column capital, frieze bands, animal motifs



Corner water spouts with projecting chajja on stepped brackets, small dome above, jail work, animal gargoyle



Detail of plinth and columns with geometric pattern capital, ornamented stepped lintel

Monicas R	Residential Flats			133
nomicas P	Acordonitium i iuto	Common Ref No: 133	1///	130
		Card No: 175		
9			- " *ho h	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
		Ward (Part): A (Part IV)	- Jal 182	90 / / / / / / / / / / / / / / / / / / /
V		CS No: 90 (Colaba division)		200
		Plot Area: 998.33 sq m.		25
		B U Area: -		00/10
1		Date: 11/01/05	The state of the s	" N
16		Recorded by: Prachi Merchant	" "	· · · · · · · · · · · · · · · · · · ·
		Reviewed by:	- \\\.\\/	The state of the s
1		Int: Prachi Merchant, Sonal Modak	- X//	
		Internal photography permission denied		iii deal Road
		Ext: Prachi Merchant, Sonal Modak		and and
		Photo Ref: 133 Monica Residential flats.		90
		THOSE TRAIN TOO_THOMAS TOO SECOND THE SECOND		
			97	
			~ x	Leasting Dian
-49	11			Location Plan
1.0	1	Denomination	I	
1.1	Name of Premises	Monicas Residential Flats		
1.2	Earlier Name	Monicas Residential Flats Monicas Residential Flats Building (Forme	rly a villa)	
1.3	Built in:	1862	Extension	-
1.0	Built III.	1002	Date	
			•	
2.0		Access		
2.1	Main	Fazal Road – pedestrian and vehicular		
2.2	Subsidiary	Sobani Road - pedestrian		
•		0 1: "		
3.0	Descrit	Ownership pattern		
3.1	Present	Private		
3.3	Past Status	Bank of India & others		
ა.ა	Sidius	Owner – Tenant.		
4.0		Use		
4.1	Present	Residential – flats, Commercial – Offices, sh	nons etc	
4.2	Past	Residential – Villa	iopo oto.	
4.3	Usage	Daily		
-		. ,		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)	The building is located in a corner plot at the	junction of Faza	I road and Sobani Marg.
		The main access is from the north side through	ugh an extended	porch leading to the villa
		entrance. Other entrances to the shops on t	he ground floor ha	ave been opened up from the
		subsidiary road.		
5.2	Architectural Description	Planning		
		The building sits on the plot with minimum s		
		The original bungalow is low while the new l		
		setting it back from the main road. The porc		
		Building is accessed through an arched ope above it. The porch opens into a spacious lo		
		leading to the first floor.	bby with a granu	Stall case of the east side,
		The bungalow has verandah spaces on the	ground floor and	projecting balconies on the
		first floor.	ground hoor and	projecting baloonies on the
		Features		
		The building is clad with grey ashlar stone n	nasonry.	
		The ground floor has semicircular and point		gs on the north side with
		rectangular and round windows. The west s	ide has balconies	with sloping Mangalore tile
		roof and stone balustrade. The projecting co		
		spandrels, projecting balconies supported o		e brackets, with stone jali wo
		balustrade, decorative corbels and star shap	oed ventilators.	
		Terrace floor has stone balustrade.		
		Style The building has derived influences from the	Indo Caracaria	style of Architecture
5.3	Intrinsic	The building has derived influences from the	: indo-saracenic	Style Of Architecture.
5.4	Value Classification	A(arc), B(per)	Recommended	d grade II B
J.7	Value Glassification	, ((a) 0), D(poi)	, recommended	ש אַימעטן וו ט
6.0		Topography		
6.1	Floors	G+1+ 9 floors added above with terrace at t	he 1st and 9th floor	r

ionicas ix	esidential Flats	1;	
7.0		Construction	
7.0	Diat	Construction	
7.1	Plinth	High projecting plinth clad with grey stone, buff colored stone plinth protection band.	
7.2	Walls	Load bearing composite wall. Internal brick walls.	
7.3	Floor	Jack-arch floor construction.	
7.4	Stairs	Main grand doglegged staircase with wooden treads, risers and cast iron railing.	
7.5	Openings	Window opening with pointed arched openings with four simple wooden glazed paneled shutters.	
7.6	Roofing	Flat terrace space over original bungalow. Sloping chajjas with Mangalore tiles over it supported on wooden brackets.	
7.7	Articulation	Verandah spaces, arched openings, projecting balconies, cornice bands, stone balustrac	
7.8	Finishes	Walls are externally clad with grey dressed stone. Internally the walls are plastered and painted. The floor is finished with natural stone.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	- Low grey stone compound wall with cast iron fencing.	
	· ·	Two cast iron gates with gateposts on either side.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Ramp on the southern end leading to car parking on the first floor. Shrubs and potted plants in the planters. Concrete paved area in the building compound.	
9 N		Services & Utilities	
8.0	Lighting		
8.1	Lighting	Natural light through the windows supported by artificial lighting	
8.2	Ventilation	Inadequate ventilation, supported by artificial ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Individual tenants have fire extinguishers.	
8.7	Other (HVAC/BMS/Security Systems)	Individual tenants have installed window and split AC's	
9.0		Condition	
9.1	Plinth	Good –although stone has blackened due to weathering.	
9.2	Walls	Fair – Additional supports added to the walls to take the floors above. Walls show cracks if ew places. Organic growth is observed on the west side wall. The bungalow has been completely altered internally.	
9.3	Floor	Fair - The floor is strengthened by steel sections.	
9.4	Stairs	Good – The staircase is well maintained.	
9.5	Openings	Fair – The openings and the shutters of the windows have been sensitively retained. Openings are blocked by hoardings in few places. Porch arches are blocked by column supports.	
9.6	Roofing	Fair	
9.7	Articulation & Finishes	Fair – Front arches have been blocked by columns used as external supports for the floo above.	
9.8	Services	Fair – maintained well.	
9.9	Out Buildings	Temporary sheds have been added on the first floor, ramp has been added on the south side to access the parking area for the added floors.	
9.10	Overall Conditions	Fair Maintenance level Good	
10.0		Transformation	
10.0	Form	Nine floors have been added over the original bungalow. Column supports have been	
	Structure	taken externally. Internally the Villa space has been completely altered. The openings and the shutters of the windows have been altered at places. Openings has been blocked by hoardings, in few places. Shutters have been changed at places.	
	Articulation & Finishes	Arches have been blocked.	
11.0		DP Remarks/ Perceived Threats	
11.0		Building forms part of Residential zone	
40.0			
12.0		Additional Notes/ References/ Documents available Additional Notes: -	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.	

Monicas Residential Flats 133

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD *Visual dictionary of Architecture*, Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) *City Map – Mumbai*, Mumbai.



Newly added structure above the original structure



Porch with pointed arched openings, cornice band, balustrade



Grey stone clad building with projecting balconies, jail work, arched and round openings



Balcony with jaliwork, supported on brackets

Esplanade	Mansion		134
		Common Ref No: 134	MAHATMA GAHDHI ROA
		Card No: 176	MAHAIM
DS##		Ward (Part): A (Part II)	
		CS No: 731 (Fort division)	. 1
Control of the Contro			DAMPAGENTE
		Plot Area: 2809.40 sq. mts.	
		B U Area: -	
7/ 1		Date: 01/02/2005	MAZARMA
The state of		Recorded by: Sonal Modak	SCHAN MIGS
		Reviewed by:	Harana Rome
A A	表现现实的。	Int: Permission denied	TANIH IF
		Ext: Sonal Modak, Zankhana Prajapati	
994		Photo Ref.: 134 Esplanade Mansion	
			7 8 5 1 / 1// /
			magn, ale
		1.5.1	N nono
4.0		Denomination	Location Plan
1.0	Name of Premises	Denomination Esplanado Mansion	
1.1		Esplanade Mansion	
1.2	Earlier Name	Esplanade Mansion	Amazi bladi az zestere 22
1.3	Built in:	Indeterminable Extension Date:	Annex block on eastern side.
2.0		Access	
2.0	Main	Hazarimal Somani Marg – Vehicular and Pedestrian	
2.1	-	Hazarımai Somanı Marg – Venicular and Pedestrian	
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	Indeterminable	
3.2	Past	Jamshetjee Tata, Dinshaw Darabji Romer - Owner	
3.3	Status	Tenant	
3.3	Status	Tenant	
4.0		Use	
4.1	Present	Commercial – Offices	
4.2	Past	Residential	
4.3	Usage	Daily	
5.0		Significance & value Classification	
5.1	Townscape (Manmade)	The building is located on a corner of Hazarimal Soma	ni Road and P. Thakurdas Road
		Facing Bombay Gymkhana.	
		It has access from H. Somani Road from western side	having separate entry and exit
		gates.	
5.2	Architectural Description	Planning	
		Rectangular in plan with central access through a proje	cting porch.
		Features	
		A symmetrical front façade with projecting porch with the	
		accoupled Corinthian pilasters at end of each in center	. Above runs a continuous cornice
		band with baluster parapet.	atal da dila ataun 12 h han 2 h da na
		On each side of central porch are two circular, orname	
		with GI sheet awnings supported by CI brackets. Segm on first floor with a cornice band above.	ental arches with Corinthian pliaster
			onica having aunilinear awaings Cl
		Second floor has projecting supported balustrade balco post and elaborately carved brackets.	onles, naving curvilinear awnings, Cr
		The central balcony has classical style pediment restin	a on Corinthian nilaster
		Topmost floor has Tuscan pilasters and rectangular win	
		There is an Annex at rear side connected by an extern	
		Style	
5.3	Intrinsic		s on façades.
5.3		Style Predominant use of Neo-classical and Baroque feature The mansion, now converted into offices has few room The interiors have an imposing marble staircase.	s on façades.
5.3	Intrinsic Value Classification	Style Predominant use of Neo-classical and Baroque feature The mansion, now converted into offices has few room The interiors have an imposing marble staircase.	s on façades.
		Style Predominant use of Neo-classical and Baroque feature The mansion, now converted into offices has few room The interiors have an imposing marble staircase.	s on façades. s, but large in size.
		Style Predominant use of Neo-classical and Baroque feature The mansion, now converted into offices has few room The interiors have an imposing marble staircase.	s on façades. s, but large in size.
5.4		Style Predominant use of Neo-classical and Baroque feature The mansion, now converted into offices has few room The interiors have an imposing marble staircase. A(arc), B(per), B(des), B(uu), D(bio), E, F Recomm	s on façades. s, but large in size.
6.0 6.1	Value Classification	Style Predominant use of Neo-classical and Baroque feature The mansion, now converted into offices has few room The interiors have an imposing marble staircase. A(arc), B(per), B(des), B(uu), D(bio), E, F Recomm Topography G+3	s on façades. s, but large in size.
5.4 6.0	Value Classification	Style Predominant use of Neo-classical and Baroque feature The mansion, now converted into offices has few room The interiors have an imposing marble staircase. A(arc), B(per), B(des), B(uu), D(bio), E, F Recomm	s on façades. s, but large in size.

Esplanade M	ansion	134	
7.2	Walls	Indeterminable	
7.3	Floor	Indeterminable	
7.4	Stairs	Indeterminable	
7.5	Openings	Arched openings with wooden frame glazed paneled shutters and ventilators above. Double storey high bay windows with GI sheet awnings supported by CI brackets.	
7.6	Roofing	Indeterminable	
7.7	Articulation	Decorative stone brackets, cornice bands, corbels, engaged columns etc. form important part of facades.	
7.8	Finishes	External exposed buff ashlar masonary. Internal indeterminable.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
		-	
7.10	Compound/ Fence/ Gate	Buff basalt compound wall with stone coping about 2 ft 6 inches high with barbed wire fencing above wall. Decorative stone pillars define the entrance with cast iron gates.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	The Monument to the family pet dog above the gate house in south-west corner of the plot.	
8.0		Services & Utilities	
8.1	Lighting	Indeterminable	
8.2	Ventilation	Indeterminable	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Indeterminable	
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable	
9.0		Condition	
9.1	Plinth	Fair – No evident damages seen.	
9.2	Walls	Indeterminable	
9.3	Floor	Indeterminable	
9.4	Stairs	Indeterminable	
9.5	Openings	Fair – In many places original wooden shutters have been replaced by aluminum sliding windows. Many windows are provided with additional sloping weather sheds.	
9.6	Roofing	Indeterminable	
9.7	Articulation & Finishes	Fair – Not maintained. At some places broken features are observed. Blackening of stone due to weathering. Plant growth observed.	
9.8	Services	Poor – Leakages observed due to broken pipes. Plant growth observed.	
9.9	Out Buildings	Fair Maintenant of Book	
9.10	Overall Conditions	Fair Maintenance level Poor	
10.0		Transformation	
	Form	Indeterminable	
	Structure	Indeterminable	
	Articulation & Finishes	Indeterminable	
44.0		DDDd (D' ad Thurst	
11.0		DP Remarks/ Perceived Threats Building forms part of C1 zone	
		During Johns part of C1 2010	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: Designed by the firm of Gostling and Morris as a residential mansion for Tatas' (Nusserwanjee Tata obtained a 999-year lease for the plot on the Esplanade opposite the Bombay Gymkhana and laid the foundations for a family residence. After his death in 1886, his son, the renowned industrialist Jamseti Tata instructed his architect Mr Morris (of the firm Gostling and Morris, established in 1870) to design a mansion in the classical style with a central courtyard covered by a glass roof and surrounded by Spanish-type corridors or patios. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	

Esplanade Mansion 134



Highly ornamented building with an extended porch, bay windows, projecting balconies on intricately carved brackets, comice bands



Arched and round openings, carved arch, floor, lintel bands, jaliwork bands



Balconies on crved brackets, with carved opening band, balustrade



Curved awning detail on cast iron brackets



Stone bracket details



Cornice and lintel level ornamentation detail

134 Esplanade Mansion





Intricately carved stone gate posts



Bay windows with dentil band, curved chajjas over openings



Façade ornamentation



Window with balustrade, pediment, decorative spandrel, dentil bands



Pilaster detail with floral bands

Church of S	St. Andrew's and St. Columbia		135
		Common Ref No: 135	
		Card No: 177	1308
		Ward (Part): A (Part II)	burget 1
M 1// 1		CS No: 1405 (Fort division).	Sometimes &
10 6	TO VOICE IN	Plot Area: 1135.45 sq m.	the Harained
45	6.	B U Area: -	
			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		Date: 20/12/2004	
		Recorded by: Sonal Modak	Sering Land
(1)	THE THE PARTY OF T	Reviewed by:	" power
孫到	No. of the last of	Int: Sonal Modak, Zankhana Prajapati	Total and and and and and and and and and and
		Ext: Sonal Modak, Zankhana Prajapati	The state of the s
		Photo Ref: 135_St. Andrews & St. Columbia's	The work of the state of the st
		Church.	Woods House and
50			Damodar Suu
			Damodar Sukhadmala Many
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Church of St. Andrew's and St. Columbia	
1.2	Earlier Name	United Free Church of Scotland	
1.3	Built in:	Commencement 1841, Completion 1843	Extension Date: -
2.0		Access	
2.1	Main	Hazarimal Somani Marg – Vehicular and Pede	estrian
2.2	Subsidiary	Murzban Road - Pedestrian	
3.0		Ownership pattern	
3.1	Present	Trust	
3.2	Past	Mission	
3.3	Status	Owner	
4.0		<u> </u>	
4.0	Burnet	Use	I Ok'lde e d'Elemente e Och e d
4.1	Present	Religious - Prayer Hall. Institutional – The Pay	ement Childrens' Elementary School.
4.2	Past	Religious - Prayer Hall	
4.3	Usage	Daily	
5.0		Significance & value Classification	
5.1	Townscape (Manmade)	It is one of the heritage buildings along Hazar	imal Comani Poad facing north west, ennesite
J. I	Townscape (Manimade)	Azad Maidan forming a landmark.	illiai Somani Noad lading north-west, opposite
		The main access is from north-west Hazarii	mal Somani Road and rear entrance is from
		Murzban Road on south-east.	
5.2	Architectural Description	Planning	
		T-shaped plan having projecting porch with t	hree stilted pointed segmental arches resting
		on Corinthian columns. The building is syn	
		western corner, which forms an irregular of	
		pinnacles at corners atop the buttresses. T	The apsidal end is semicircular in plan with
		buttresses with a half conical roof.	
		The gable end has pointed arch with three s	lender pointed arches within it. One cross on
		top of the fascia board.	
		Features	the second technical action and constitution
		It is built in Kurla and Porbunder stone. It shades.	has carved teakwood gables and weather
		Pointed arches with trefoil and quatrefoil venti	latore
		Corbels, cornices, corinthian columns, rose	window ventilators architraves and stained
		glass panels.	The state of the s
		Style	
		Significant influence of Neo-Gothic style of arc	chitecture.
5.3	Intrinsic		
5.4	Value Classification	A(arc), B(per).	Recommended grade II A.
6.0		Topography	
6.1	Floors	Ground floor with high ceiling.	
7.0		Construction	
7.1	Plinth	Low plinth about 1ft. in height constructed in g	
7.2	Walls	Honeycombed dressed masonry with yellov	v dressed quoins. Thick load bearing walls
		strengthened by step buttresses.	

Church of S	St. Andrew's and St. Columbia	135	
7.3	Floor		
7.4	Stairs		
7.5	Openings	Door openings are wide rectangular with wooden double shutters, outer being glazed paneled and the inner being wooden louvered. Side elevation is punctuated with pointed arched windows with tri-foiled double arches with circular ventilators within the main arch placed in-between the low height step buttresses. All sides have two pointed arches with quatrefoil ventilators. Ventilators have stained glass panels within.	
7.6	Roofing	Windows have double shutters - outer are glazed panels and inner are wooden louverer shutters. All door/window openings are fixed with MS grills from outside. Arched braced wooden trusses with wooden planks and Mangalore tiles atop. Overhang.	
	_	resting on wooden brackets. Porch has a flat roof constructed in brickbat coba.	
7.7	Articulation	Floral corbels supporting arched braces internally. Corinthian column capitals. Floral arch springing points.	
7.8	Finishes	External walls have an exposed grey honeycomb pattern. Walls are plastered and painted internally. IPS and cement tile flooring finish.	
7.9	Interiors (Movable & Immovable)	Movable Wooden furniture like prayer hall chairs, benches, table, cupboards, book shelves and carved wooden baldachin all form a significant part of the church interiors. Immovable Wooden raised platform at apsidal end, wooden railing.	
7.10	Compound/ Fence/ Gate	A brick wall of about 2 ft. 6 inches with MS fencing above it.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Planter boxes along compound wall. A water storage tank on the west of the building Rooms at the apsidal end to accommodate the caretaker's family with toilets and washing area.	
8.0		Sorvices & Utilities	
8.1	Lighting	Services & Utilities Inadequate natural light through long window openings totally dependent on artificial lighting.	
8.2	Ventilation	Natural ventilation is inadequate. Dependent on supplementary ventilation devices lik fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No traces.	
8.7	Other (HVAC/BMS/Security Systems)	No traces.	
9.0		Condition	
9.1	Plinth	Fair – Covered with planter boxes. Blackening of protection band stone. Chipping off a some places.	
9.2	Walls	Fair – Inappropriate pointing has been done. Layers and layers of bitumen at eaves level Cracks seen in walls of porch.	
9.3	Floor	•	
9.4 9.5	Stairs Openings	Poor – Need immediate repairs. Few of the ventilators are blocked using plywood. Stained	
9.6	Roofing	glass panels have been replaced. Fair – External wooden members like fascia board, rafters have deteriorated in some places. Maintained fairly from internally. Porch roof slab has fallen off.	
9.7	Articulation & Finishes	Fair – No evident damages seen. All decorative features are painted over. Plant growth observed. The steeple had fallen off due to lightning few years back.	
9.8	Services	Poor – Unclean washing area. Leakages from broken service pipes. Unplanned electrica wiring.	
9.9	Out Buildings	Poor – Not maintained at all. Unhygienic. Structural members have cracks. There is a lot o debris lying in the plot itself.	
9.10	Overall Conditions	Fair Maintenance level Poor	
10.0		Transformation	
	Form		
	Structure	Repair Works going on upon the porch roofing.	
	Articulation & Finishes	-	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone.	
12.0		Additional Notes / Defenses of Decuments!!-	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	

135

The belfry tower does not have any staircase/ access.

The Church on H Somani Marg, was formerly built in the 1840s in Carnac Road (Lokmanya Tilak Marg) at Dhobi Talao. As the area became more crowded and the church became surrounded by shops and stables, the ground on which the church stood was sold in 1894 and the building was taken down. A plot was purchased on Waudby Road and a new church, designed by the Bombay firm of architects, Gostling and Morris, was erected here and opened in February 1896. The handsome church, which can accommodate 250 people, is built of Kurla and Porbunder stone with artistically worked teakwood gables and weather shades for the entrances.

References:

INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) *The Cities Within*, Bombay : Eminence Designs Pvt. Ltd.

RAHUL MEHRÖTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

SHARADA DWIVEDI and RAHUL MEHROŤRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.

Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.



Grey stone random masonary clad building with sloping roof, lancet windows, round and arched openings



Gable wall detail with wooden carved eaves board



Church building with an extended porch sloping roof supported on wooden truss



Main entrance with stepped lintel, wooden paneled shutters



Corinthian with floral pattern capital



Interior view of the arched window opening with stained glass panel



Interior of the column capitals



Lancet window with round and trifoiled arched openings, glazed paneled shutters, sill level jaliwork panels



Lancet window with stained glass panels




Belfry tower with arched openings, cornice bands



Floral pattern motif at the springing point of arch



Old wall clock



Fort Gratui	tous Dispensary	136	
7.3	Floor	Floor rests on wooden beams, some portion laid with wooden planks and some areas have	
		concrete laid and tiling done.	
7.4	Stairs	Two staircases, both in two diagonal corner of the building. Entire staircase is of wood with wooden tread, riser, baluster, handrail and newel post.	
7.5	Openings	Pointed arch openings of door and windows and cut out openings, door and windows are double shutter single leaf with louvered ventilator in between.	
7.6	Roofing	Sloping roof with wooden supporting members and truss work and laid by Mangalore tiles.	
7.7	Articulation	Column capital, wooden brackets, wooden partition wall.	
7.8	Finishes	External wall is in exposed stone masonry, internal wall plastered and painted, flooring is of varied nature such as IPS, marble mosaic and wooden planks.	
7.9	Interiors (Movable & Immovable)	Movable Presence of some old tables, cupboards, and furniture. Immovable	
7.10	Compound/ Fence/ Gate	Compound wall is of stone and has a decorative iron gate at the entrance.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	There are two out buildings, one is the caretaker's room and other is the storehouse. The	
	Landscape	unbuilt space is not maintained, unclean, and no landscape is present.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light and artificial lighting	
8.2	Ventilation	Adequate natural ventilation and artificial ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	•	
8.7	Other (HVAC/BMS/Security Systems)	•	
9.0		Condition	
9.1	Plinth	Poor - Stone at certain places has loosened; cement pointing, seepage through drainage pipes, dust accumulation and cracks on certain places, plant growth.	
9.2	Walls	Fair - Incongruous cement pointing, stones painted, dust accumulation, plant growth seepage below drainage pipes.	
9.3	Floor	Fair - The floor is in fair condition; only maintenance of woodwork and beam should be carried out.	
9.4	Stairs	Fair - One staircase, which is in rear, is not in use, and is in bad and neglected condition needs repair and strengthening. Even the staircase, which is in use, needs strengthening.	
9.5	Openings	Fair - Wooden frames painted, windowpanes broken, different color on different floor arches and columns are also painted.	
9.6	Roofing	Poor - Wooden members are in dilapidated condition at certain places, needs proper maintenance and seepage is seen in certain portion.	
9.7	Articulation & Finishes	Poor - Internal plaster and paint is peeling off, wooden floor needs polish and cleaning and repair, tiles are broken at certain portion and filled with cement grouting, cracks in IPS flooring.	
9.8	Services	Poor - Leaking pipes, poor sanitation, plant growth and blackened pipes.	
9.9	Out Buildings	Poor - Neglected condition, not maintained and is poor and dilapidated condition.	
9.10	Overall Conditions	Fair. Maintenance level Poor.	
40.0		Tourse	
10.0	Free	Transformation	
	Form	-	
	Structure Articulation & Finishes	 Painted stone surfaces and columns, decorative floral motif band and column capital is also painted. 	
11.0		DP Remarks/ Perceived Threats	
		Housing for dishoused, building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
12.0		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.	

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd. Eicher Goodearth Ltd. (2002) *City Map – Mumbai*, Mumbai.



Grey stone clad building with sloping roof, arched openings, sill and floor level bands



Arched openings with wooden shutters, floor bands



Windows with frieze band in geometric pattern



Arched door opening with round window, columns with carved capitals



Front central wing with sloping roof, projecting balcony supported on brackets



Column with floral pattern capital

Fort Gratuitous Dispensary



Frieze in floral pattern




Glazed wooden window with carved paneling, sill panels



Staircase with wooden steps, railing, nexel post



Tablet in marble



onarua iv	ew High School	137	
7.0		Construction	
7.1	Plinth	There is a medium plinth in black stone about 2 ft 6 inches high, with a plinth protection layer	
'.2	Walls	External thick load bearing brick walls. Internal non-structural brick walls.	
7.3	Floor	Partly original timber floor present and partly concrete floor slabs laid resting on wooder columns and beams. The floor is partly tiled and partly timber planked.	
7.4	Stairs	There are three 'L' Shaped staircases. The other main staircase goes to the first floor only. The risers are in stone, the balusters are in cast iron and the handrails and posts are made of timber. There is a timber staircase for	
		the entire building to access the terrace.	
7.5	Openings	The openings are semicircular. They have ventilators and are louvered. They have window shutters with glass panes. The doors are rectangular with decorative patterns on the panels.	
'.6	Roofing	The roofs are partly sloping and partly terraced. They are supported on timber rafters and beams and are Mangalore tiled. Some portion is asphalted for waterproofing.	
7.7	Articulation	The keystones are decorative, on semi circular arches; there are bands, cornices and flora column capitals.	
7 Q	Finishes	The interior walls are plastered and painted.	
'.8 '.9	Interiors (Movable & Immovable)	The interior wans are plastered and partied. The old cupboards, benches, chairs, desks, tables, old clock, mirrors and frames are still	
7.10	Compound/ Fence/ Gate	used. The front and rear, that is the external walls facing roads form the outer boundary. The sides	
	·	have brick compound walls.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	There is a water storage tank in the central courtyard. The side margins serve as a dump yard.	
3.0		Services & Utilities	
3.1	Lighting		
	Lighting	There is adequate natural and artificial lighting.	
.2	Ventilation	There is adequate natural and artificial ventilation.	
1.3	Electricity	BEST	
.4	Water Supply	MCGM	
.5	Drainage (Plumbing & Sanitation)	MCGM	
5.6	Fire Precaution	None	
3.7	Other (HVAC/BMS/Security Systems)	None	
9.0		Condition	
9.1	Plinth	Fair -There has been reduction in the plinth height due to the filling of the footpath.	
9.2	Walls	Fair - The internal plaster has peeled off due to seepage dampness and moss growth. The brick masonry has been exposed at some places, there are cracks in the verandah walls a some places and brick has been exposed on the façade.	
9.3	Floor	Poor - Some tiles are broken and the flooring has been patched up. Wear and tear of the stone flooring was observed. The verandahs facing the central court are sagging at their free end. The supporting timber members have deteriorated and show cracks.	
9.4	Stairs	Fair - The stone treads show wear and tear and some treads are broken. The timber handrai is not polished. The staircase is not adequately lit. Dust accumulation is observed.	
9.5	Openings	Fair - Some ventilators were closed. Grills and collapsible shutters have been added. Some	
9.6	Roofing	window shutters and panes have been broken. Some tiles are broken, a bitumen layer has been added for waterproofing, otherwise the roo	
9.7	Articulation & Finishes	is in a fair condition. Some faces carved on the keystones are missing. The mouldings and semi circular archer	
		are broken and have been repainted.	
8.0	Services	The services are in a fair state. The canteen pipes are broken.	
9.9	Out Buildings	•	
9.10	Overall Conditions	Poor Maintenance level Fair	
10.0		Transformation	
	Form		
	Structure	Some timber members supporting the flooring have been replaced with 'l' sections.	
	Articulation & Finishes	-	
1.0		DP Remarks/ Perceived Threats Secondary School, building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available Additional Notes:	
		- References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	

Bharda New High School

137

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd.

RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in

Bombay – Conserving an Image Centre, 2 Vols, Bombay.
FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.



Entrance to the building with arched openings with human face keystone, round columns, decorative frieze bands, floor bands



Side façade with arched openings, bands





Balustrade detail of window opening



Internal open to sky court with overlooking corridors



Human face motif keystone, arch band in geometric pattern

Bharda New High School 137







Column with carved capital with floral pattern



Ground floor with rusticated stone joints, arched openings



Marble bust



Arched door opening with carved paneled shutters, ventilator



Window with ventilator tracery work, louvered shutters

Deutsche	Bank			138	
		Common Ref No: 138		8 -	
		Card No: 180	13 El		
1		Ward (Part): A (Part II)		AZAD MAIDAN	
		CS No: 1/1406 (Fort Division)	7. 70		
	mitt somethe Bank	Plot Area: 274.25 sqm.	ROAL	TARIE OF	
	TITI MANAGEMENT OF THE PARTY OF	B U Area: -	LE III	B	
		Date: 30/4/05	Z Z	2	
2.9		B U Area: - Date: 30/4/05 Recorded by: Zankhana Prajapati Reviewed by: Int: Zankhana Prajapati Ext: Zankhana Prajapati Photo Ref.: 138_Deutsche Bank			
		Reviewed by:	3 0 0 1		
		Int: Zankhana Prajapati	- 2 V	Tool And And And And And And And And And And	
		Ext: Zankhana Prajapati	- 3 4 7	The Table	
		Photo Ref.: 138 Deutsche Bank	Nu 818 W	9.5	
the state of the s		T Hoto Not.: 130_Boutsone Bank	- 0 D B	1.	
			1000	Maria Maria	
			OF STATE OF		
			X . / . / . 0	an Dian	
1.0		Denomination	Locati	on Plan	
1.0 1.1	Name of Premises	Denomination Deutsche Bank			
1.1					
1.3	Earlier Name Built in:	Tata Palace. Indeterminable	Extension Date: -		
1.3	Bullt III.	indeterminable	Extension Date		
2.0		Access			
2.1	Main	Murzban Road.			
2.1	Subsidiary	Hazarimal Somani Marg.			
2.2	Subsidiary	nazanmai Somani Warg.			
3.0		Ownership pattern			
3.1	Present	Deutsche Bank - Private			
3.2	Past	Tata - Private			
3.3	Status	Ownership.			
5.5	Siaius	Ownership.			
4.0		Use			
4.1	Present	Bank.			
4.2	Past	Office and residence of Ratan Tata.			
4.3	Usage	Office and residence of Ratan Tata. Daily.			
1.0	ocago	Dany.			
5.0		Significance & Value Classification			
5.1	Townscape (Manmade)	It is a corner building at the junction of Ha	zarimal Somani Marg, Mur	zban Road and	
		Damodar Sukhadwala Road.			
		Entrance to the building is through Murzba		chere. The building has	
		magnificent Baroque Classical features ar	d statuary.		
5.2	Architectural Description	Planning			
		The building is rectangular in form and longer façade along Hazarimal Somani Marg.			
		Entrance to the building is through porte-			
		ground plus two-storied structure with bas			
		cochere one enters into grand entrance lo			
		which forms cylindrical shaft, towards the			
		doglegged and part C-shaped open well.			
		are placed. It was planned to have offices	at first and ground and re	sidence at second floor	
		level. In front it has landscaped area and	side open spaces.		
		Features	a la color de la c	ata atta a bassa a d	
		The building is rectangular with front corne			
		cylindrical shaft of central staircase. All the			
		rectangular openings. Above porte-coche			
		The building is marked with cornice band			
			terrace floor levels. Besides these many façade articulations are seen which comprises of cartouche at window, wall, underneath the main staircase; festoon on inside as well outside wall surface as ornamentation, presence of guilloche and scroll band to create interesting		
			pattern on exterior. Very ornamental scroll keystone with lion head and presence of balcon supported by caryatid. It also has floral motif, medallion, coat of arms, statuary pilasters		
		1	oui, inegallion, coat of arm	s, statuary pliasters	
		and window statuary with ancon.			
		Style The building displays characteristics of Ba	roque Classicism		
5.3	Intrincia	The building displays characteristics of Ba		its kind representing	
ე.ა	Intrinsic	Past residence of Ratan Tata and building	is maynimicent and one of	its kind representing	
5.4	Value Classification	Baroque Classicism. A(arc), B(per), B(des), D(bio), E, F	Recommended	IIA	
J. 4	value Glassification	$\Delta(aic)$, $D(pei)$, $D(aes)$, $D(bio)$, E , F		"^	
			grade	1	

Deutsche B	Dank	13	
6.0		Topography	
6.1	Floors	G+2 with mezzanine and basement.	
7.0		Construction	
7.1	Plinth	Medium height stone plinth with edging for plinth protection.	
7.2	Walls	External walls are load bearing composite wall whereas internal walls are brick walls.	
7.3	Floor	R.C.C. slab on load bearing walls.	
7.4	Stairs	Two staircases are present; the main staircase is a spiral staircase with marble tread and having decorative cast iron railings. While the other staircase starts as doglegged but from first floor it is a C-shaped open well with marble tread and cast iron railing.	
7.5	Openings	It has semicircular and rectangular openings for door and windows. All openings are eithe double leaf or four leafed, in wooden frame with glass panel. The entrance door is of cast iron with ornately carved.	
7.6	Roofing	Flat terrace with statuary pilasters.	
7.7	Articulation	Modillion, medallion, cartouche, festoon, guilloche, dentil and scroll band, caryatids, coat of arms, floral motif and decorative statuary.	
7.8	Finishes	External and internal walls are plastered and painted and have marble flooring.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	- Has huge fencing in cast iron with huge cast iron gates at both side of the building's longe façade.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Has side open spaces and front open space is well landscaped with gazebo, hard and sof surfaces and ornamental plants.	
8.0		Sarvicas & Utilities	
8.1	Lighting	Services & Utilities Adequate Natural light through door-window openings supplemented by electric light fixtures.	
8.2	Ventilation	Supplemented with central A.C. system.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
• • • • • • • • • • • • • • • • • • • •			
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Have smoke detectors and fire extinguishers.	
8.7	Other (HVAC/BMS/Security Systems)	Surveillance camera, swap card access system.	
• •		A 199	
9.0		Condition	
9.1	Plinth	Good. Well maintained.	
9.2	Walls	Good. Seepage at some places and minor cracks.	
9.3	Floor	Indeterminable.	
9.4	Stairs	Good. Well maintained.	
9.5	Openings	Good. Well maintained.	
9.6	Roofing	Good. Well maintained.	
9.7	Articulation & Finishes	Good. Well maintained.	
9.8	Services	Good. Well maintained.	
9.9	Out Buildings		
9.10	Overall Conditions	Good. Maintenance level Good.	
10.0		Transformation	
	Form	No visible changes	
	Structure	No visible changes	
	Articulation & Finishes	No visible changes	
		· · v ··	
11.0		DP Remarks/ Perceived Threats	
		Cinema Theatre, building forms part of C1 zone	
		- ·	
12.0		Additional Notes/ References/ Documents available Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd.	

Deutsche Bank 138



White painted corner building with arched openings, frieze, sill and lintel level bands and cornice bands



Colonnaded terrace with round columns on high base, Corinthian capitals, openings with frieze and lintel bands



Internal arched opening with keystone, arch and frieze band in floral pattern



Highly ornamented facade with floral pattern motifs, round balcony with Caryatid, cornice band




Canopy with statue as a part of the front landscaped portion



Semi round canopies with intricate carvings above

138 Deutsche Bank



Landscape portion on the front side



Column capital with carved floral pattern



Staircase with carved railing



Parapet detail with human sculpture statue details



Entrance corridor with vault roof, frieze bands, arch with keystone




Insignia in stone, dentil band






Soffit of staircase landing with carved floral pattern



Bombay Arch	San Diocese Association Building	139
7.4	Stairs	Two staircases are present. Both staircases in timber with wooden handrail and balusters.
7.5	Openings	Pointed arch and semicircular arched openings in the verandah. All doors are pointed arched with ventilators above. They are double leaf wooden paneled doors.
		All windows are rectangular with double leaved glazed with a wooden frame.
7.6	Roofing	Sloping roof with Mangalore tiling supported on wooden rafter and beam and has dormer window, has decorative cast iron pinnacle like feature on rooftop.
7.7	Articulation	Cornice and lintel bands, arches and jalis.
7.8	Finishes	External walls- gray stone ashlars masonry.
		Internal walls- plastered and painted. Tiling is either IPS, ceramic or mosaic in different rooms.
7.9	Interiors (Movable & Immovable)	Movable - Immovable
7.10	Compound/ Fence/ Gate	- Barbed wire fence on compound boundary.
	·	2 cast Iron gates at front and rear of the building.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Open space in all four side of the building. Residential small houses and toilet block form outbuildings at the rear. Has a landscaped area in front and a plant nursery on the left of the building.
8.0		Services & Utilities
8.1	Lighting	Adequate natural light through door-window openings supplemented by electric light
		fixtures.
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	•
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	Poor - Stones broken, has cracks, seepage and plant growth.
9.2	Walls	Poor - Extensive seepage with heavy cracks, exposed brickwork inside, fascia stone is blackened and has plant growth.
9.3	Floor	Dilapidated - All wooden members are badly deteriorated. Structural cracks observed.
9.4	Stairs	Poor - One staircase is not in use and is total dilapidated condition and its structural members have fallen apart. The other staircase is well maintained just needing a coat polishing of the wooden members.
9.5	Openings	Poor - Window panes are broken, frame loosened, grills broken, wooden members painted in different colors -needs polish and repairs. Arched openings are blackened with cracks and plant growth.
9.6	Roofing	Poor – Has a major leakage problem, deteriorating and in rear some portion has fallen apart, tiles are missing, no repairs and lack of maintenance.
9.7	Articulation & Finishes	Poor - Dust accumulation, broken comice bands, blackening, cracks in arches and plant growth on articulation. Internal plaster and paint peeling off. External blackening of stone, cracks and plant growth.
9.8	Services	Tiling has holes and dents. Poor - Not maintained, broken and leaking pipes, unhygienic conditions and haphazard
		arrangement of electrical wiring.
9.9	Out Buildings	Poor - Neglected condition and not maintained.
9.10	Overall Conditions	Poor. Maintenance level: Poor.
10.0	_	Transformation
	Form	
	Structure	Addition of I section for strengthening of building.
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone. The building is in a very dilapidated condition.
12.0		Additional Naton/ Beforenegg/ Description and State
12.0		Additional Notes/ References/ Documents available Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd.
<u> </u>	sion Research Institute	MMR- Heritage Conservation Society

Bombay Arch San Diocese Association Building	139
	RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
	in Bombay – Conserving an Image Centre, 2 Vols, Bombay.
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
	Division of International Thomson Publishing Inc.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence
	Designs Pvt. Ltd.





ERROR: stackunderflow
OFFENDING COMMAND: ~

STACK:

Curzon Hou	ise		140
- u12311 1100		Common Ref No: 140	model is the second
	AND TO CARE	Card No: 182	Viar VIII
7		Ward (Part): A (Part III)	390
_4		CS No: 392 (Colaba Division)	
		Plot Area: Indeterminable	48
		B U Area: -	
	0.0	Date: 11/01/2005	P J RAMCHANDANI WARG
		Recorded by: Zankhana Prajapati	Fan House O
		Reviewed by:	7
		Int: Arun Wadhwa, Zankhana Prajapati	HENRY ROAD
		Ext: Arun Wadhwa, Zankhana Prajapati	RY ROAD
		Photo Ref: 140 Curzon House.	
2.5		_	Evelyn House
4.19			"Oueo
			V //
1.0		Denomination	Location plan
1.0	Name of Premises	Denomination Current Heure	
1.1		Curzon House Curzon House	
1.3	Earlier Name Built in:	1905	Extension Date: -
1.3	Built III.	1905	Extension Date
2.0		Access	
2.0 2.1	Main	Access P. J. Ramchandani Marg - Vehicular and	Podostrian
2.1	Main Subsidiary		r cucollidii
L. L	Subsidially	-	
2.0		Our parable mattern	
3.0 3.1	Drocont	Ownership pattern Mr. Dilip Puri - Owner	
3.2	Present Past	Indeterminable	
3.3	Status	Owner. Tenants.	
3.3	Status	Owner, renants.	
4.0		Use	
4.1	Present	Show room and residences.	
4.2	Past	Residences.	
4.3	Usage	Daily.	
7.0	Osago	Dully.	
5.0		Significance & value Classification	
5.1	Townscape (manmade)		type buildings facing the sea at Apollo Bunder
J. I	Townscape (manimade)		th side road. It has wooden verandah fronts as in
		the adjoining buildings.	ar olde road. It ride wooden veranden nome de in
5.2	Architectural Description	Planning	
			ntre of the longer side resulting in two symmetrical
			ce is from a porch to the south side leading to the
			upper floor apartments. Each apartment has three
		and the contract of the contra	ong with verandah fronts. Large floor heights
1			
		accommodate intermediate levels servir	ng as servant's wing in the central portion of the
		accommodate intermediate levels servir long north side with toilets and kitchen	ng as servant's wing in the central portion of the
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently.	ng as servant's wing in the central portion of the
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features	ng as servant's wing in the central portion of the at the main floor. A narrow stair is provided to
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping M	ng as servant's wing in the central portion of the at the main floor. A narrow stair is provided to langalore tile awnings form the most prominent
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Martin feature. Projecting bay windows along	ng as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade	ng as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone reliefies; numerous projecting balconies supported on
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden ea	ng as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on wes board and supporting brackets impart villa
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping North feature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden each character to the buildings. Semicircular	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on wes board and supporting brackets impart villar window openings with keystone feature at the
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping N feature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden ea character to the buildings. Semicircular corner bay. Floor level cornice bands sca	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on wes board and supporting brackets impart villar window openings with keystone feature at the
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden eacharacter to the buildings. Semicircular corner bay. Floor level cornice bands sca Style	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on ves board and supporting brackets impart villar window openings with keystone feature at the le down the facades.
5.3	Intrinsic	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden eacharacter to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on wes board and supporting brackets impart villar window openings with keystone feature at the
5.3 5.4	Intrinsic Value Classification	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden eacharacter to the buildings. Semicircular corner bay. Floor level cornice bands sca Style	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on ves board and supporting brackets impart villar window openings with keystone feature at the le down the facades.
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden eacharacter to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on eves board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture
		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden eacharacter to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on eves board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture
5.4		accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden ea character to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp)	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on eves board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture
5.4 6.0	Value Classification	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden ea character to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp)	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on wes board and supporting brackets impart villar window openings with keystone feature at the ledown the facades. Vernacular and Colonial styles of architecture Recommended grade II B
5.4 6.0	Value Classification	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping N feature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden ea character to the buildings. Semicircular corner bay. Floor level cornice bands sca Style The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp) Topography G + 4 in main building, G + 7 in servant's	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief as; numerous projecting balconies supported on wes board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture Recommended grade II B portion. (Fourth floor has been added later on.)
6.0 6.1	Value Classification	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden ea character to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp) Topography G+4 in main building, G+7 in servant's	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief as; numerous projecting balconies supported on wes board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture Recommended grade II B portion. (Fourth floor has been added later on.)
5.4 6.0 6.1 7.0	Value Classification Floors	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping N feature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden ea character to the buildings. Semicircular corner bay. Floor level cornice bands sca Style The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp) Topography G + 4 in main building, G + 7 in servant's	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief as; numerous projecting balconies supported on ves board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture Recommended grade II B portion. (Fourth floor has been added later on.)
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden eacharacter to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp) Topography G + 4 in main building, G + 7 in servant's Construction Plinth height about 1.0 m. dressed in blact Load bearing stone masonry external wa	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief as; numerous projecting balconies supported on ves board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture Recommended grade II B portion. (Fourth floor has been added later on.)
5.4 6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping N feature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden ear character to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp) Topography G + 4 in main building, G + 7 in servant's Construction Plinth height about 1.0 m. dressed in blat Load bearing stone masonry external wa Jack arch floor slabs supported on steel	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to dangalore tile awnings form the most prominent with a sloping awning feature and stone relief ses; numerous projecting balconies supported on ves board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture Recommended grade II B portion. (Fourth floor has been added later on.)
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden eacharacter to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp) Topography G + 4 in main building, G + 7 in servant's Construction Plinth height about 1.0 m. dressed in blad Load bearing stone masonry external war Jack arch floor slabs supported on ste Shahabad stone slabs supported on woo wing.	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to at the main floor. A narrow stair is provided to display the main floor. A narrow stair is provided to display the main floor. A narrow stair is provided to display the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on ves board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture Recommended grade II B portion. (Fourth floor has been added later on.) sk basalt stone ashlars course masonry. Ils and wooden supporting members. et I - sections and large beams for large spans. den members form intermediate levels in servant's
6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden eacharacter to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp) Topography G + 4 in main building, G + 7 in servant's Construction Plinth height about 1.0 m. dressed in blad Load bearing stone masonry external wad Jack arch floor slabs supported on ste Shahabad stone slabs supported on woo wing. C- shaped wooden staircase with a certain started the started services and supported on woo wing.	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to at the main floor. A narrow stair is provided to display the main floor. A narrow stair is provided to display the main floor. A narrow stair is provided to display the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on oves board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture Recommended grade II B portion. (Fourth floor has been added later on.) sk basalt stone ashlars course masonry. Ils and wooden supporting members. el I - sections and large beams for large spans. den members form intermediate levels in servant's sentral open well serving as lift shaft. It has a
5.4 6.0 6.1 7.0 7.1 7.2 7.3	Value Classification Floors Plinth Walls Floor	accommodate intermediate levels servir long north side with toilets and kitchen access servant's wing independently. Features Wooden verandah front with sloping Meature. Projecting bay windows along parapet panel on the long side facade decorative steel brackets. Wooden eacharacter to the buildings. Semicircular corner bay. Floor level cornice bands scastyle The building displays influences from the Wooden veranda fronts A(arc), B(per), E, G(grp) Topography G + 4 in main building, G + 7 in servant's Construction Plinth height about 1.0 m. dressed in blad Load bearing stone masonry external wad Jack arch floor slabs supported on ste Shahabad stone slabs supported on woo wing. C- shaped wooden staircase with a certain started the started services and supported on woo wing.	ag as servant's wing in the central portion of the at the main floor. A narrow stair is provided to at the main floor. A narrow stair is provided to display the main floor. A narrow stair is provided to display the main floor. A narrow stair is provided to display the most prominent with a sloping awning feature and stone relief es; numerous projecting balconies supported on ves board and supporting brackets impart villar window openings with keystone feature at the le down the facades. Vernacular and Colonial styles of architecture Recommended grade II B portion. (Fourth floor has been added later on.) sk basalt stone ashlars course masonry. Ils and wooden supporting members. et I - sections and large beams for large spans. den members form intermediate levels in servant's

Curzon Hou	ISE	140	
7.5	Openings	Wooden verandas on the front and rear sides with sloping awning and wooden ventilato	
		panel. Semi circular, segmental window openings with wood framed glazed panel doo window shutters. Separate openable ventilator panel above most of the openings.	
7.6	Roofing	Sloping Mangalore tile roof over the part fourth floor supported on wooden truss members and flat jack arch roof over the part third floor.	
7.7	Articulation	Large molded base of bay window projection, long wooden verandas with sloping awnings.	
7.8	Finishes	Plaster/ painted external and internal wall surfaces, polished wooden members in verandas and door window shutters.	
7.9	Interiors (Movable & Immovable)	Movable	
		Immovable	
7.10	Compound/ Fence/ Gate	Low stone compound wall with iron railing above. Two gates at both ends of the east sid road front. Barbed wire fencing on the sides and rear.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Two garage structures and a dispensary at the rear end of the south side open space	
	Landscape	Narrow open spaces all around the building including the front side.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light except staircase, lobby and servant's wing. Thus also relies on	
0.0		artificial light.	
8.2	Ventilation	Adequate natural ventilation except in servant's wing. Also relies on artificial means.	
8.3	Electricity	BEST MOON Had a seed of a set of a feed of a f	
8.4	Water Supply	MCGM Underground & overhead water tank	
8.5	Drainage (Plumbing & Sanitation) Fire Precaution	Drainage connected to municipal sewers of MCGM	
8.6		Fire extinguishers present. Window and split unit A.C.	
8.7	Other (HVAC/BMS/Security Systems)	vvindow and split unit A.C.	
9.0		Condition	
9.1	Plinth	Poor – Neglected state.	
9.2	Walls	Poor – under repair.	
9.3	Floor	Poor – under repair.	
9.4	Stairs	Fair condition of main staircase, poor and damaged state of servant's stair.	
9.5	Openings	Poor – decaying wooden veranda members, modified and neglected window shutters.	
9.6	Roofing	Fair. Well maintained and in good state.	
9.7	Articulation & Finishes	Poor – external wall surfaces under repair, internally fair. Corroding Iron brackets and damaged relief features.	
9.8	Services	Poor – old and corroding plumbing lines. Messy and unplanned electrical wiring below staircase at ground floor lobby.	
9.9	Out Buildings	Poor – under repair and neglected open spaces.	
9.10	Overall Conditions	Poor Maintenance level: Poor externally, Well maintained internally.	
10.0		Transformation	
	Form	•	
	Structure	Repair Board is in the process of reconstructing some damaged slab portions. Cantilevered toilet areas in servant's wing reconstructed incongruously with concrete structural supports.	
	Articulation & Finishes	External replastering and repair work in progress is damaging stucco features and floor level cornice bands.	
44.0		DD Demontor/ Demontor of There etc.	
11.0		DP Remarks/ Perceived Threats Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: Curzon house is mirror image of adjoining Villar Ville building to its north except the south	
		side porch.	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation.	
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay : Eminence Designs Pvt. Ltd.	
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.	

Curzon House 140



Front façade with overlooking balcony spaces with carved railing, Side view with projecting balconies, carved railing sloping roof, arched openings






Bay window with receding bands, arched openings with keystone



Balcony spaces with carved railing, columns with wooden brackets, lintel level glazed panels



Feltham Ho	use	141(1
		Internal doors of various premises have transformed by occupants.
		All the openings of the ground floor are semicircular arched openings, and the first, second and
		third are flat arch plain opening with a prominent cornice.
7.6	Roofing	The building has flat roof while the staircase block has a pitched Mangalore tile roof.
7.7	Articulation	The Balcony projection over the cornice band is the major surface articulation of the building.
7.8	Finishes	The façade has a stone masonry fascia and internal walls are plastered.
		Flooring is different according to individual premises.
7.9	Interiors (Movable & Immovable)	Movable
		Nothing was visible, as the building has gone through major transformation.
		Immovable
		Decorative wooden baluster and railing.
		Decorative M.S. balcony railing.
7.10	Compound/ Fence/ Gate	Iron gate at entrance is of original nature.
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Adjoining space between the buildings is paved and it directly opens to the street. The plot doe
	Landscape	not have any out building or compound wall.
8.0		Services & Utilities
8.1	Lighting	Natural daylight through windows, together with electrical light fixtures.
8.2	Ventilation	Natural ventilation but there is also presence of AC units as well as fans.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	No integrated fire precaution system is present but some offices do have fire extinguishers for
		emergency.
8.7	Other (HVAC/BMS/Security Systems)	No trace.
9.0		Condition
9.1	Plinth	Fair - Plinth is in good condition in front but at rear and side it has deteriorated due to seepage
		from drainpipe and dampening.
9.2	Walls	Fair - At certain places cracks have developed.
		Plant growth in certain area is a structural threat if not taken care of.
		Leakages in down take pipes and at balcony projections have blackened the wall surfaces.
		It is punctuated with AC units.
9.3	Floor	Not visible due to false ceiling.
9.4	Stairs	Fair - Plaster is peeling off and cementing is exposed at certain area.
		Electrical conduits are open and exposed at landings.
9.5	Openings	Fair - At certain places window ventilators are damaged and altered and punctuated with AC
	, ,	units and hence disturbing the homogenous façade.
		Doors have also gone through major transformations differing greatly from one premise to
		another.
		Decorative grills and glass have been added, windowpanes have been broken and the original
		pattern has been changed.
9.6	Roofing	Fair - Waterproofing was done, parapet wall is blackened.
9.7	Articulation & Finishes	Fair - Small patches of cement pointing in wall, stone colored and blackened.
		Many cracks and peeling of plasters is seen in staircase.
		Coping brackets are damp due to seepage.
9.8	Services	Fair - The routing of electrical wires, plumbing and air-conditioner pipes have caused
		considerable damage.
9.9	Out Buildings	No out building.
9.10	Overall Conditions	Fair Maintenance level: Fair
10.0		Transformation
	Form	No change.
	Structure	Mezzanine addition in some premises, no other visible change.
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone
		v recent to
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		-
		References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		Structures listed for Conservation.
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
		Division of International Thomson Publishing Inc.
		Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First

Feltham House 141(1)



Wooden entrance porch added on a later date



Pediment with scroll brackets over opening



Rectangular opening with glazed sash window shutter



West side façade of the buff stone clad building with arched opening, with grills added on the window openings



Arched openings with a floor cornice and dentil band



Open well wooden staircase

Mercantile	e House	141(2)	
inor ouritin	7110400		
		Common Ref No: 141(2) Card No: 184 Ward (Part): A (Part II) CS No: 22/1187 (Fort Division) Plot Area: 658.40sq m. B U Area: - Date: 14/04/2005 Recorded by: Sonal Modak Reviewed by:	
1		Varid (Port): A (Port II)	
		Ward (Part): A (Part II)	
		CS No: 22/1187 (Fort Division)	
		Plot Area: 658.40sq m.	
- N		B U Area: -	
		Date: 14/04/2005	
7		Recorded by: Sonal Modak	
4		Reviewed by: Int: Permission denied Ext: Sonal Modak Photo Ref: 141(02)_Merchantile building	
1 1	月17日 18	Int: Permission denied	
THE PERSON NAMED IN	THE PARTY OF THE P	Ext: Sonal Modak	
		Photo Ref: 141(02)_Merchantile building	
		Photo Ref: 141(02)_Merchantile building	
0		14M MORK	
		NAROTT.	
		Location Plan	
1.0		Denomination Location Plan	
1.0	N (D)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
1.1	Name of Premises	Mercantile House	
1.2	Earlier Name	Mercantile House	
1.3	Built in:	1920-1930 Extension Date: -	
2.0		Access	
2.1	Main	J. N. Heredia Marg - Pedestrian	
2.2	Subsidiary	-	
	- Jubaidiai y		
2.0		O	
3.0		Ownership pattern	
3.1	Present	Private	
3.2	Past	Private	
3.3	Status	Owner and Tenant	
4.0		Use	
4.1	Present	Commercial - Offices	
4.2	Past	Commercial - Offices	
4.3	Usage	Daily	
7.0	Osago	Daily	
ΕΛ		Cinnificance 8 Value Classification	
5.0	Towns on (Managed In)	Significance & Value Classification	
5.1	Townscape (Manmade)	Located along a row of buildings on a tree-lined avenue maintaining similar height &	
		features as per urban design regulations laid down for the entire Ballard Estate.	
		Main access is from J. N. Heredia Marg from the southwest road front.	
5.2	Architectural Description	Planning	
		Rectangular building plan with sharing common open spaces with buildings on sides and	
		rear. Large floor heights without any setback or interception generate an urban scale-	
		volume to the building block.	
		Typical layout on all upper floors with open office spaces intercepted only by supporting	
		columns and window openings on three sides.	
		Features	
		Symmetrical front façade with two side entrances for two different office spaces.	
		Continuous projecting cornice bands at first, third and terrace floor levels.	
		Ground floor having segmental arched windows, all upper floors have rectangular	
		architrave window openings. Balustrade parapet at terrace level.	
		Style	
		Influence of European renaissance style features.	
5.3	Intrinsic		
5.4	Value Classification	A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended grade: II A	
J. 4	value CiassilicatiOH	A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended grade: II A	
c 0		Tanananaha	
6.0		Topography	
6.1	Floors	G+3	
7.0		Construction	
7.1	Plinth	Medium plinth about 2 ft. 6 inches high in yellow ashlar masonry.	
7.2	Walls	Load bearing yellow ashlar masonry along the entire periphery, open internal space is	
		supported on columns.	
7.3	Floor	Indeterminable	
7.4	Stairs	Indeterminable	
7.5	Openings	Large door/window openings with timber frame and double-glazing panels.	
7.6		Indeterminable	
	Roofing		
7.7	Articulation	Cornice bands, Bas-relief sculptures.	
7.8	Finishes	Yellow kurla stone dressed external wall surfaces and plaster painted internal finishes.	

Mercantile	e House			141(2)	
7.9	Interiors (Movable & Immovable)	Movable		, ,	
	· ·	-			
		Immovable			
		•			
7.10	Compound/ Fence/ Gate	No compound wall, an iron gate encloses the common open space on both the sides.			
7.11	Curtilage/ Unbuilt space/ Out	Paved open space shared with adjoining bui	ldings. Tree lined av	enue along the front and	
	Buildings/ Landscape	services located in the rear common space.			
0.0		Comicae 9 Háilitice			
8.0 8.1	Lighting	Services & Utilities Indeterminable			
8.2	Lighting Ventilation	Indeterminable			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing & Sanitation)	MCGM			
8.6	Fire Precaution	Indeterminable			
8.7	Other (HVAC/BMS/Security Systems)	Split & window unit air-conditioners.			
0.1	Other (ITVAC/BM3/3eculity Systems)	Split & willdow unit all-conditioners.			
9.0		Condition			
9.1	Plinth	Fair except plumbing interventions along the	sides and rear		
9.2	Walls	Fair except plant growth and plumbing int	erventions on the r	ear side. Also seenage	
J.2	VValio	observed internally along the toilet walls.	orventions on the r	cai side. 71100 scopage	
9.3	Floor	Indeterminable			
9.4	Stairs	Indeterminable			
9.5	Openings	Fair except poor maintenance.			
9.6	Roofing	Indeterminable			
9.7	Articulation & Finishes	Fair except minor blackening, plant growth	Fair except minor blackening, plant growth and interventions. Poor state of internal wall		
		and floor finishes.			
9.8	Services	Poor - old and neglected plumbing lines to the	ne rear side.		
9.9	Out Buildings	-			
9.10	Overall Conditions	Fair	Maintenance	Low	
			level		
10.0		Transformation			
	Form	No visible changes from outside			
	Structure	No visible changes from outside			
	Articulation & Finishes	No visible changes from outside			
11.0		DP Remarks/ Perceived Threats			
		Building forms part of C1 zone			
40.0		Additional Notes/ References/ Documents	!labla		
12.0			available		
		Additional Notes:			
		References:			
		INTACH (1990) Preliminary unedited listing of	of Unprotected Monu	ments Buildings and	
		Structures listed for Conservation.	Shiprotootou ivioliu	monto, Dananiyo ana	
		FRANCIS D.K.CHING and VAN NOSTRANE	REINHOLD Visual	dictionary of Architecture	
		Division of International Thomson Publishing	Inc.	, o. / normooduro,	
		Ballard Estate – A Corporate District (2000)		rch Institute and Bombay	
		First.	ŭ	,	

Mercantile House 141(2)



Front façade with arched and rectangular openings, cornice band.



Detail of the cornice band



Side façade used to take various services



Arched entrance with door band

Volkart House		141(3)
Common Ref No: 141(3) Card No: 185		141(3)
Ward (Part): A (Part II)	10 m	
	_	Banon, Ba
CS No: 19/1187 (Fort Division)	(6	N and a
Plot Area: 851.17 sq m.	SHIVSA	GAR RAMGULAM MARG
B U Area: - Date: 26/11/2004	- ne	OAR RAMGULAN
Date: 2071 1/2001	3	AM MARG
Recorded by: Zankhana Prajapati	Conne R	- 11 15-
Reviewed by:	Swarm	R G
Int: Permission denied	THE PARTY OF THE P	Z / E
Ext: Zankhana Prajapati	47/	746
Photo Ref: 141(03)_Volkart building.	The state of the s	10
	V / 8	W HEREDIA WARG
	> (6	THE STATE OF THE S
Control of the contro		N N
	# 4	7/
	* - //	// 、・「事 / / / / / / / / / / / / / / / / / / /
1.0 Denomination		Location Plan
1.1 Name of Premises Volkart House		
1.2 Earlier Name Volkart House		
1.3 Built in: Indeterminable	Extension	I -
1.3 Duilt III. Indeterminable	Date	
	1	•
2.0 Access		
2.1 Main J. N. Heredia Marg		
2.2 Subsidiary -		
3.0 Ownership pattern		
3.1 Present Tata group of Companies		
3.2 Past Indeterminable		
3.3 Status Owner/Tenant		
5.5 Status Owner/Tenant		
4.0 Use		
4.1 Present Commercial offices.		
4.1PresentCommercial offices.4.2PastOffices.		
4.1 Present Commercial offices.		
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily.		
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification	Road. It is part of	the Ballard Estate Precinct
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area.	Road. It is part of	the Ballard Estate Precinct
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning	·	
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five s	storied. Building ha	as a single entrance in center,
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of the staircase.	storied. Building ha	as a single entrance in center, fice premises. It maintains the
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All	storied. Building har	as a single entrance in center, fice premises. It maintains the re to the rear of the building.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five s which leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, no	storied. Building har	as a single entrance in center, fice premises. It maintains the re to the rear of the building.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five s which leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, no level.	storied. Building har	as a single entrance in center, fice premises. It maintains the re to the rear of the building.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features	storied. Building ha of staircase are of service utilities ar ot intercepted with	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, no level. Features Ground floor has semi-circular arched ope	storied. Building had staircase are of service utilities are of intercepted with enings and other	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Comice	storied. Building ha of staircase are of service utilities ar ot intercepted with enings and other band runs along t	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level,
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Comice supported with series of small brackets. The	storied. Building ha of staircase are of service utilities ar ot intercepted with enings and other band runs along t	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level,
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Cornice supported with series of small brackets. The Style	storied. Building ha of staircase are of service utilities ar ot intercepted with enings and other band runs along to a façade is of yello	as a single entrance in center, fice premises. It maintains the e to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Cornice supported with series of small brackets. The Style It displays characteristics of the European R	storied. Building ha of staircase are of service utilities ar ot intercepted with enings and other band runs along to a façade is of yello	as a single entrance in center, fice premises. It maintains the e to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Cornice supported with series of small brackets. The Style It displays characteristics of the European R 5.3 Intrinsic	storied. Building ha of staircase are of service utilities are of intercepted with enings and other band runs along to a façade is of yello Renaissance Style.	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Cornice supported with series of small brackets. The Style It displays characteristics of the European R	storied. Building ha of staircase are of service utilities ar ot intercepted with enings and other band runs along to a façade is of yello	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification The building is accessed from J.N. Heredia and follows the urban pattern of that area. Flanning It is a rectangular building ground plus five s which leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched operopenings, with keystone projection. Comice supported with series of small brackets. The Style It displays characteristics of the European R 5.3 Intrinsic Intrinsic A(arc), B(per), B(des), B(uu), E, F, G(grp)	storied. Building had staircase are of service utilities are of intercepted with enings and other band runs along the façade is of yello Renaissance Style.	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five s which leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched oper openings, with keystone projection. Cornice supported with series of small brackets. The Style It displays characteristics of the European Ref. S.3 Intrinsic 5.4 Value Classification A(arc), B(per), B(des), B(uu), E, F, G(grp) Topography	storied. Building had staircase are of service utilities are of intercepted with enings and other band runs along the façade is of yello Renaissance Style.	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification The building is accessed from J.N. Heredia and follows the urban pattern of that area. Flanning It is a rectangular building ground plus five s which leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched operopenings, with keystone projection. Comice supported with series of small brackets. The Style It displays characteristics of the European R 5.3 Intrinsic Intrinsic A(arc), B(per), B(des), B(uu), E, F, G(grp)	storied. Building had staircase are of service utilities are of intercepted with enings and other band runs along the façade is of yello Renaissance Style.	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched operopenings, with keystone projection. Cornice supported with series of small brackets. The Style It displays characteristics of the European Results	storied. Building had staircase are of service utilities are of intercepted with enings and other band runs along the façade is of yello Renaissance Style.	as a single entrance in center, fice premises. It maintains the e to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Planning It is a rectangular building ground plus five s which leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched oper openings, with keystone projection. Comice supported with series of small brackets. The Style It displays characteristics of the European Results	storied. Building had staircase are of service utilities are of intercepted with enings and other band runs along the façade is of yello Renaissance Style.	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present Commercial offices. 4.2 Past Offices. 4.3 Usage Daily. 5.0 Significance & value Classification 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. Flanning It is a rectangular building ground plus five which leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Comice supported with series of small brackets. The Style It displays characteristics of the European Research Value Classification 5.3 Intrinsic - 5.4 Value Classification A(arc), B(per), B(des), B(uu), E, F, G(grp) 6.0 Topography 6.1 Floors G + 5 7.0 Construction 7.1 Plinth Low plinth made of stone.	storied. Building ha of staircase are of service utilities ar ot intercepted with enings and other band runs along to a façade is of yello genaissance Style.	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present 4.2 Past 4.3 Usage 5.0 Significance & value Classification The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.2 Architectural Description Flanning It is a rectangular building ground plus five swhich leads to staircase, and on both side of profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Comice supported with series of small brackets. The Style It displays characteristics of the European Response o	storied. Building had staircase are of service utilities are of intercepted with enings and other band runs along the façade is of yello senaissance Style. Recommended grade	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present Commercial offices.	storied. Building had staircase are of service utilities are of intercepted with enings and other band runs along the façade is of yello senaissance Style. Recommended grade	as a single entrance in center, fice premises. It maintains the re to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone.
4.1 Present 4.2 Past 4.3 Usage Daily. 5.0 Significance & value Classification The building is accessed from J.N. Heredia and follows the urban pattern of that area. Flanning It is a rectangular building ground plus five swhich leads to staircase, and on both side oprofile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Comice supported with series of small brackets. The Style It displays characteristics of the European Results of the European R	storied. Building had staircase are of service utilities are of intercepted with enings and other band runs along the façade is of yello genaissance Style. Recommended grade Recommended grade grade grad	as a single entrance in center, fice premises. It maintains the e to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone. If the first and terrace floor level, w Malad stone. If the first and terrace floor level, w Malad stone. If the first and terrace floor level, w Malad stone.
4.1 Present 4.2 Past 4.3 Usage Daily. 5.0 Significance & value Classification The building is accessed from J.N. Heredia and follows the urban pattern of that area. 5.1 Townscape (Manmade) The building is accessed from J.N. Heredia and follows the urban pattern of that area. Planning It is a rectangular building ground plus five which leads to staircase, and on both side profile of the plot and curvature of street. All Floor space is huge with a column grid, not level. Features Ground floor has semi-circular arched ope openings, with keystone projection. Comice supported with series of small brackets. The Style It displays characteristics of the European Results of	storied. Building ha of staircase are of service utilities ar ot intercepted with enings and other band runs along t e façade is of yello genaissance Style. Recommended grade Recommended grade lar masonry on the n and mezzanine I has marble handra	as a single entrance in center, fice premises. It maintains the e to the rear of the building. In partition wall at ground floor floors have huge flat arched the first and terrace floor level, w Malad stone. If If A If A

Volkart House		141(3
		Original doors are heavy paneled, double shuttered wooden doors. Internal doors of various premises are all transformed according to the interiors done by occupants. All windows of ground floor are semicircular arched openings, but on both sides of entrance are segmental arched openings and the first and second floor windows are flat arch plain opening with a prominent cornice.
7.6	Roofing	Building has part flat roof and over added floors it has a series of sloping roofs.
7.7	Articulation	Balcony projection over the cornice band is a major articulation.
7.8	Finishes	Façade has stone masonry fascia and internal walls are plastered. Flooring varied.
7.9	Interiors (Movable & Immovable)	Movable
	,	Immovable -
7.10	Compound/ Fence/ Gate	Iron gates at the side of the compound.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Adjoining space between the buildings is paved and it directly opens to the street. The plot does not have any out building or compound wall.
		A 1 A 11/11/61
8.0		Services & Utilities
8.1	Lighting	Natural daylight through windows, together with electrical light fixtures.
8.2	Ventilation	Natural ventilation but there is also presence of AC units as well as fans.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	•
8.7	Other (HVAC/BMS/Security Systems)	•
	, , , , , , , , , , , , , , , , , , , ,	
9.0		Condition
9.1	Plinth	Fair - Plinth is in good condition in front but at rear and side it has deteriorated due to
		seepage from drainpipe and dampening. It also has plant growth at certain places, loose and broken stone and stains of tobacco.
9.2	Walls	Poor - Plant growth in certain area is a structural threat if not taken care of. Leakages in down take pipes and at balcony projections have blackened the wall at certain places. It is punctuated with AC units. Beams have cracks and reinforcement is exposed.
9.3	Floor	Poor - The floor of the ground floor is uneven and tiles are broken and are getting dislocated from screeding. Exposed reinforcement in certain areas, flooring is changed and the vacant offices are not maintained.
9.4	Stairs	Good - Stairs area seems to have undergone recent restoration and is in good condition.
9.5	Openings	Poor - Collapsible grills added in all ground floor openings. At certain places window ventilators are damaged and altered, punctuated with AC units and hence disturbing the homogenous façade. Doors have also gone through the major transformation from one premise to another. Windowpanes broken and pattern changed. Many openings have been closed by plywood pieces.
9.6	Roofing	Fair - Roofing was originally flat, but at present due to addition of two floors it has sloping roof in AC sheets.
9.7	Articulation & Finishes	Poor - Small patches of cement pointing in wall, stone colored and blackened. Many crack and peeling of plasters is seen in staircase. Coping brackets are damped due to seepage.
9.8	Services	Poor - The cabling of electrical wires, plumbing and air-conditioner pipes have caused considerable damage.
9.9	Out Buildings	
9.10	Overall Conditions	Fair. Maintenance level Poor.
10.0		Transformation
	Form	Incongruous addition of two floors have changed the entire form of the building, it also breaks the homogeneity of Ballard estate precinct. The new construction does not follow building line, pattern, material and has totally transformed the elevation.
	Structure Articulation & Finishes	Addition of two floors must have changed the structural loading of the building. Finishes have been changed and stone is blackened.
11.0		DP Remarks/ Perceived Threats Building forms part of C1 zone.
		V
12.0		Additional Notes/ References/ Documents available Additional Notes:
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.


Volkart House	141(3)
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
	Division of International Thomson Publishing Inc.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence
	Designs Pvt. Ltd.
	Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay
	First.




Buff stone clad curved façade with rectangular openings and floor bands



Step balconies supported by cornice bands



Arched opening with ventilator jail within



Sapt Build	lina			141(4)
7.2	Walls	Load bearing yellow ashlar masonry a	long the entire peripher	
		supported on columns.	3	7,
7.3	Floor	Indeterminable		
7.4	Stairs	Indeterminable		
7.5	Openings	Large door/window openings with timber frame and double-glazing panels.		
7.6	Roofing	Indeterminable		
7.7	Articulation	Cornice bands, Bas-relief sculptures.		
7.8	Finishes	Yellow kurla stone dressed external wall surfaces and plaster painted internal finishes.		
7.9			surfaces and plaster pa	airited iriterriai iriisries.
1.5	interiors (wovable & inimovable)	- Immovable		
7.10	Compound/ Fence/ Gate	No compound wall, only an iron gate en	closing the common ope	en space on the sides.
7.11	Curtilage/ Unbuilt space/ Out	Paved open space shared with adjoining		
	Buildings/ Landscape	services located in the rear common spa	ace.	.
		'		
8.0		Services & Utilities		
8.1	Lighting	Indeterminable		
8.2	Ventilation	Indeterminable		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	Indeterminable		
8.7	Other (HVAC/BMS/Security Systems)	Split & window unit air-conditioners.		
0.1	Other (HVAC/BMS/Security Systems)	Split & window unit air-conditioners.		
9.0		Condition		
9.1	Plinth	Good		
9.2	Walls	Good externally.		
9.3	Floor	Indeterminable		
9.4	Stairs	Indeterminable		
9.5	Openings	Fair – Heavy grills have been installed in	all the window enening	···
9.6	Roofing	Indeterminable	i ali tile willdow operling	JS.
9.7	Articulation & Finishes	Good – Well maintained.		
			4- 41	
9.8	Services	Fair – old and neglected plumbing lines	to the rear side.	
9.9	Out Buildings	-	Materia	01
9.10	Overall Conditions	Good	Maintenance level	Good
10.0		Transformation		
	Form	No visible changes from outside		
	Structure	No visible changes from outside		
	Articulation & Finishes	No visible changes from outside		
11.0		DP Remarks/ Perceived Threats		
		Building forms part of C1 zone		
12.0		Additional Notes / Poferences / Decum	onte available	
12.0		Additional Notes/ References/ Documents available Additional Notes:		
		References: INTACH (1990) Preliminary unedited list Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTR Division of International Thomson Publis Ballard Estate – A Corporate District (20 First.	RAND REINHOLD <i>Visua</i> Shing Inc.	l dictionary of Architecture,

Sapt Building 141(4)



Front façade with arched and rectangular openings, floor bands etc.



Arched openings with intricate work in the door shutters and ventilator



Step balcony with metal railing supported by stone brackets

Thakersey Ho	use		Li i =ri =ri	141(5)
		Common Ref No: 141(5)		
		Card No: 187		CURRIMBHOY ROAD
		Ward (Part): A (Part II)	\f ₆	NOAD TOAD
		CS No: 37/1187 (Fort Division)	M A R SOUTH HERE	./
	A COLUMN TO THE REAL PROPERTY OF THE PARTY O	Plot Area: 846.53 sq m.		8 00 L
		B U Area: -	KAMANI	N. HERED
		Date: 22/03/2005	TY S	THOUSER HOSE
		Recorded by: Arun Wadhwa	 	. N. HE
建工程	学的文献 (1)	Reviewed by:	RAMJIBHAI N	I. N. HEREDIA MARG
Col atting		Int: Sonal Modak, Arun Wadhwa	1 S 1 1 L	- / / ~ /
		Ext: Sonal Modak, Arun Wadhwa	/ / L	INMIN HORSE Q
1		Photo Ref: 141(05)_Thackersey Building.		7 / K
		Thoto Net. 141(03)_Thackersey building.	V	VILSON ROAD
			100	N ROAD "
			1 1) / os /
				Location Plan
1.0		Denomination		
1.1	Name of Premises	Thakersey House		
1.2	Earlier Name	Thakersey House		
1.3	Built in:	1923 (as per entrance tablet)	Extension	-
		,	Date	
2.0		Access		
2.1	Main	J. N. Heredia Marg - Pedestrian		
2.2	Subsidiary	-		
	,			
3.0		Ownership pattern		
3.1	Present	Mumbai Port Trust - Owner		
3.2	Past	Bombay Port Trust		
3.3	Status	Owner		
0.0	Cidido	CWIICI		
4.0		Use		
4.1	Present	Commercial - Offices		
4.2	Past	Commercial - Offices		
4.3	Usage	Daily		
7.0	Osago	Daily		
5.0		Significance and value Classification		
5.1	Townscape (Manmade)	Located along a row of buildings on a tree	lined avenue m	agintaining similar hoight and
3.1	Townscape (Manimade)	features as per urban design regulations laid		
		It is accessed centrally through a semicircular		
5.2	Architectural Description	Planning	arch opening in	on the south side road front.
J.2	Alcintectural Description	Rectangular building plan with longer side fa	cing road and s	haring common onen spaces
		with buildings on sides and rear. Large floo		
		generate an urban scale-volume to the bui		
		symmetrical wings to both sides and separa	italing block. Ce	ng a convice stair at the rear
		Typical layout in all upper floors with open		
		columns and window openings on three sides		iterespied only by supporting
		Features	•	
		Long symmetrical front façade with rusticated	central projectin	ng hay and a semicircular arch
		entrance marked by carved maritime figures.		
		on the ground floor. Distinct cornice bands a		
		roof over third floor. Projecting portal topped		
		form balconies at first floor. Large architra		
		façade. Stone carved medallion flanking both		
		supported on steel truss. Double circular co		
		overhang of roof above third floor.	ianinio and uell	rative conscis supporting the
		Style		
		Influence of European Renaissance style in fe	eatures.	
5.3	Intrinsic	-		
5.4	Value Classification	A(arc), B(per), B(des), B(uu), E, F, G(grp)	Recommended	grade II A
J.7	Taido Oldoniodioi1	, (a. 0), D(por), D(doo), D(dd), L, I , O(gip)	coommonaeu	91440 1171
6.0		Topography		
6.1	Floors	G + 3		
U. I	1 10013	U+3		
7.0		Construction		
7.0	Dlinth	Construction	rubblo masans:	
7.1 7.2	Plinth	Low plinth height about 0.4 M, constructed in		
1.2	Walls	Load bearing rubble stone masonry walls along authorized on signal and account account and account and account and account and account and account and account and account and account and account and account and account and account and account and account and account and account and account and account account and account and account account and account and account account and account account and account account account and account account and account acc	ng the entire per	ipnery, open internal space is
		supported on circular wooden columns.		

Thakersey	House	141(5)
7.3	Floor	Wooden floor boards supported on wooden rafters and beams.
7.4	Stairs	C - shaped wooden staircase with an open well accommodating lift shaft. Also marked by decorative wooden newel post. Narrow double flight service stair at the rear.
7.5	Openings	Large door openings along the front façade, shutters in three levels lower wood paneled, middle wood framed glazed panel and centrally pivoted glazed ventilator panel. Semi circular step arch openings on ground floor with fixed glazed ventilator panel in the arch portion.
7.6	Roofing	Sloping Mangalore tile hip roof supported on steel truss and slender circular steel columns. Roof is composed in two parts - front and rear, forming valleys at the center.
7.7	Articulation	Stepped arch window openings, architrave openings, pediment portal balcony feature at first floor.
7.8	Finishes	Yellow Kurla stone dressed external wall surfaces and plaster painted internal finishes. Original wooden floor finish topped with cement and ceramic tiles.
7.9	Interiors (Movable and Immovable)	Movable - Immovable
7.10	Compound/ Fence/ Gate	No compound wall, only an iron gate enclosing the common open space on both the sides.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Paved open space shared with adjoining and rear side buildings. Tree lined avenue along the front and services located in the rear common space.
8.0		Services and Utilities
8.1	Lighting	Adequate natural light also supplemented by artificial light.
8.2	Ventilation	Adequate natural ventilation also supplemented by artificial means.
8.3	Electricity	BEST
8.4	Water Supply	MCGM Underground and overhead water tank
8.5	Drainage (Plumbing and Sanitation)	Drainage connected to municipal sewers of MCGM
8.6	Fire Precaution	Fire extinguishers.
8.7	Other (HVAC/BMS/Security Systems)	Split and window unit air-conditioners.
9.0		Condition
9.1	Plinth	Fair except plumbing interventions along the sides and rear.
9.2	Walls	Fair except plant growth and plumbing interventions on the rear side. Also seepage observed internally along the toilet walls.
9.3 9.4	Floor Stairs	Fair except minor sagging of wooden members, reinforced with steel supports. Fair except the neglected service stair. Also negligible maintenance.
9.5	Openings	Fair except poor maintenance.
9.6	Roofing	Fair state of truss and wooden boards.
9.7	Articulation and Finishes	Fair except minor blackening, plant growth and interventions. Poor state of internal wall and floor finishes.
9.8	Services	Poor – old and neglected plumbing lines to the rear side.
9.9	Out Buildings	-
9.10	Overall Conditions	Fair Maintenance level Low
10.0	F	Transformation
	Form Structure	Structural repairs undertaken by providing steel supports to the wooden floor rafters.
	Articulation and Finishes	- Structural repairs undertaken by providing steel supports to the wooden floor raiters.
44.0		DD D
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone.
12.0		Additional Notes/ References/ Documents available
12.0		Additional Notes:
		The G+2 storey is exactly similar to Mahindra House except for bas-relief carving at the second floor. References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd.
		Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.

Thakersey House 141(5)



West side façade with arched and rectangular openings along with pediments above, step balconies, floor bands.



South side elevation with arched openings and stone voissoirs



Cartouche detail on the front facade



Main entrance with arched opening and rusticated stone joints



Step balcony supported on brackets, columns and pediment above

Thakersey House 141(5)



Frieze band in geometric pattern



Stained glass with the year of construction inscribed in the ventilator panel



Interior space with cast iron columns and beams



Subsidiary arched entrance with decorative door frame band



Frieze band in floral pattern below the window opening



Bas-relief at the entrance below window sill level





Window with band, stone balustrade

Mahindra H	ouse	141(6) 141/6) 141/6
4. 18		Common Ref No: 141(6) Card No: 188 Word (Port): A (Port II)
1		Card No: 188 Ward (Part): A (Part II)
100		CS No: 34/1187 (Fort)
		Plot Area: 589 sq m.
		T
		B U Area: - Date: 22/03/2005
		Date: 22/03/2005 Recorded by: Sonal Modak Reviewed by:
3		Reviewed by:
· · ·		Int: Sonal Modak, Arun Wadhwa
		Internal Photography denied
SH AN		Int: Sonal Modak, Arun Wadhwa Internal Photography denied Ext: Sonal Modak, Arun Wadhwa Photo Ref: 141(06)_Mahindra House
		Photo Ref: 141(06)_Mahindra House
	and the second s	Location Plan
1.0		Denomination
1.1	Name of Premises	Mahindra House
1.2	Earlier Name	Mahindra House
1.3	Built in:	1920-1930 Extension Date: -
2.0		Access
2.0 2.1	Main	Access J. N. Heredia Marg - Pedestrian
2.1	Subsidiary	U. 14. HOLGUIA IVIALY - L GUGOLIAII
۲.۲	Subsidially	
3.0		Ownership pattern
3.1	Present	Mumbai Port Trust - Owner
3.2	Past	Bombay Port Trust
3.3	Status	Owner
4.0		Use
4.1	Present	Commercial - Offices
4.2	Past	Commercial - Offices
4.3	Usage	Daily
5.0	7. (24 1)	Significance and Value Classification
5.1	Townscape (Manmade)	One in a row of buildings on the slight curvilinear road profile maintaining similar height and features as per urban design regulations laid down for the entire Ballard Estate.
		It is accessed through central door having a semi-circular concave arch from the northeast
		road front.
5.2	Architectural Description	Planning
	,	Rectangular building plan with longer side facing road and sharing common open spaces
		with buildings on sides and rear.
		Large floor heights without any setback or interception generate an urban scale-volume to
		the building block.
		Centrally located staircase with symmetrical wings to both sides and separate toilets
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides.
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade.
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor.
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style
5.3	Intrinsic	Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor.
5.3 5.4	Intrinsic Value Classification	Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style Influence of European Renaissance style in features.
	Intrinsic Value Classification	Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style Influence of European Renaissance style in features. - A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended II A
		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style Influence of European Renaissance style in features. - A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended II A
5.4		Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style Influence of European Renaissance style in features. - A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended grade II A
6.0 6.1	Value Classification	Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style Influence of European Renaissance style in features. - A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended grade II A Topography G + 3
6.0 6.1 7.0	Value Classification Floors	Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style Influence of European Renaissance style in features. - A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended grade II A Topography G + 3 Construction
6.0 6.1 7.0 7.1	Value Classification Floors Plinth	Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style Influence of European Renaissance style in features. - A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended grade II A Topography G + 3 Construction Low plinth height about 2 ft 6 inches, constructed in rubble masonry.
6.0 6.1 7.0	Value Classification Floors	Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style Influence of European Renaissance style in features. - A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended grade II A Topography G + 3 Construction Low plinth height about 2 ft 6 inches, constructed in rubble masonry. Load bearing rubble stone masonry walls along the entire periphery, open internal space is
6.0 6.1 7.0 7.1	Value Classification Floors Plinth	Centrally located staircase with symmetrical wings to both sides and separate toilets flanking a service stair at the rear. Typical layout in all upper floors with open office spaces intercepted only by supporting columns and window openings on three sides. Features Long symmetrical front façade with a rusticated central projecting bay and a semicircular arch entrance. Series of stepped semicircular arch openings on the ground floor. Distinct cornice bands at first and third floor level and overhanging roof over third floor. Projecting portal topped by a decorative triangular pediment feature form balconies at first floor. Large architrave openings regularly punctuate the upper façade. Sloping roof space supported on steel truss. Double circular columns and decorative corbels supporting the overhanging roof above third floor. Style Influence of European Renaissance style in features. - A(arc), B(per), B(des), B(uu), E, F, G(grp) Recommended grade II A Topography G + 3 Construction

Mahindra I	House	141(6)	
7.4	Stairs	C- shaped wooden staircase with an open well accommodating lift shaft. Also marked by	
		decorative wooden newel post. Narrow double flight service stair at the rear.	
7.5	Openings	Large door openings along the front façade, shutters in three levels, lower wood paneled,	
		middle wood framed glazed panel and centrally pivoted glazed ventilator panel. Semi	
		circular step arch openings on ground floor with fixed glazed ventilator panel in the arch	
		portion.	
7.6	Roofing	Sloping Mangalore tile hip roof supported on steel truss and slender circular steel columns.	
	1.1009	Roof is composed in two parts- front and rear, forming valleys at the center.	
7.7	Articulation	Stepped arch window openings, architrave openings and pediment portal balcony feature	
		at first floor.	
7.8	Finishes	Yellow Kurla stone dressed external wall surfaces and plaster painted walls internally.	
		Original wooden floor finish topped with cement and ceramic tiles.	
7.9	Interiors (Movable and Immovable)	Movable	
		-	
		Immovable	
		-	
7.10	Compound/ Fence/ Gate	No compound wall, only an Iron gate enclosing the common open space on both the sides.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Paved open space shared with adjoining and rear side buildings. Tree lined avenue along	
	Landscape	the front and services located in the rear common space.	
8.0		Services and Utilities	
8.1	Lighting	Adequate natural light also supplemented by artificial light.	
8.2	Ventilation	Adequate natural ventilation also supplemented by artificial means.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM Underground and overhead water tank	
8.5	Drainage (Plumbing and Sanitation)	Drainage connected to municipal sewers of MCGM	
8.6	Fire Precaution	Fire extinguishers.	
8.7	Other (HVAC/BMS/Security Systems)	Split and window unit air-conditioners.	
0.1	Other (HVAC/Bivis/Security Systems)	Split and window unit all-conditioners.	
0.0		Condition	
9.0	DP-th	Condition	
9.1	Plinth	Fair - Except plumbing interventions along the sides and rear.	
9.2	Walls	Fair - Plant growth and plumbing interventions on the rear side.	
9.3	Floor	Fair – Wooden floors reinforced with steel supports in some places.	
9.4	Stairs	Fair - Except the neglected service stair. Also negligible maintenance.	
9.5	Openings	Fair	
9.6	Roofing	Fair	
9.7	Articulation and Finishes	Fair except minor blackening, plant growth and interventions. Poor state of internal wall	
		and floor finishes.	
9.8	Services	Fair – No significant damages observed.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair Maintenance level Fair	
10.0		Transformation	
	Form	-	
	Structure	Structural repairs undertaken by providing steel supports to the wooden floor rafters.	
	Articulation and Finishes	-	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone.	
		•	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		-	
		References:	
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation.	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,	
		Division of International Thomson Publishing Inc.	
		Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay	
		First.	

Note: Photography permission denied

Hamilton Ho	ouse		141(7)
		Common Ref No: 141(7)	1 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
AN TOWN		Card No: 189	T T
1		Ward (Part): A (Part II)] AS
		CS No: 8/1187	1 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
	THE RESERVE TO SERVE THE PARTY OF THE PARTY	Plot Area: 520.440 sq m.	A / / / / / / / / /
		B U Area: -	1 1/ / 4/
		Date: 16/02/2005	
		Recorded by: Zankhana Prajapati	S. S. S. S. S. S. S. S. S. S. S. S. S. S
		Reviewed by:	Logo Barriero
		Int: Zankhana Prajapati, Prachi Merchant	S Harring
	THEFT	Internal photography permission denied Ext: Zankhana Prajapati, Prachi Merchant	
		Photo Ref: 141(7) Hamilton House.	J N HEREDIA MARG
		Filoto Kei. 141(7)_Hamilton House.	- WARG
		4 (3	
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Hamilton House	
1.2	Earlier Name	Hamilton House	
1.3	Built in:	1920-30	Extension Date: -
2.0		Access	
2.1	Main	J. N. Heredia Marg	
2.2	Subsidiary		
3.0		Ownership pattern	
3.1	Present	DEPE Shipping agency Pvt. Ltd.	
3.2	Past	British Petroleum.	
3.3	Status	Owner/Tenant	
4.0		Use	
4.1	Present	Offices.	
4.2	Past	Offices.	
4.3	Usage	Daily.	
1.0	Coago	Duny.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	The main access to the building is from J. N.	Heredia Marg.
		Building follows the language and scale of all	the buildings of the Ballard Estate precient.
5.2	Architectural Description	Planning	
		The building has a square plan with all service	es on the right side of the entrance.
		The building is ground plus four storied high.	dia Marg from the right of the building, which
			teach floor level this connects to a passage
			be behind the staircase block behind which a
		service staircase is present.	
		All floors have office premises.	
		Features	
			th semicircular openings on ground floor front
			ther openings are rectangular with has cornice
		· · · · · · · · · · · · · · · · · · ·	n corbels and a CI balcony railing at first floor.
		Style Ruilding displays characteristics of the Neo-C	Nassical style
5.3	Intrinsic	Building displays characteristics of the Neo-C	ગંવરસાવ્યા સંપાદ.
5.4	Value Classification	A(arc), B(per), B(des), B(uu), E, F, G(grp)	Recommended grade II A
0.4	raido Oldoomodilon	, η(αιο), Ε(ροι), Ε(αοο), Ε(αα), Ε, ι , Ο(g(ρ))	Treseminenced grace II rt
6.0		Topography	
6.1	Floors	G + 4 and terrace.	
7.0		Construction	
7.4	Plinth	Low height stone fascia plinth with edging do	
7.1	Malla		Malad stone fascia and internal brick wall
7.1	Walls		and the standard and the Miller of Maria and the standard
7.2		plastered and painted and fourth floor externa	ally cladded with china mosaic tiles.
7.2 7.3	Floor	RCC slab.	ally cladded with china mosaic tiles.
7.2		RCC slab. Two staircases are present.	
7.2 7.3	Floor	RCC slab. Two staircases are present. The main staircase is C-shaped with a lift bloom.	,
7.2 7.3	Floor	RCC slab. Two staircases are present. The main staircase is C-shaped with a lift bloom is doglegged.	ock inside the well, while the second staircase
7.2 7.3	Floor	RCC slab. Two staircases are present. The main staircase is C-shaped with a lift bloom.	ock inside the well, while the second staircase

Hamilton Ho	ouse	141(7)	
		floors have rectangular windows.	
7.0	Desfer	All windows have double or triple glazed panels in wooden frames.	
7.6	Roofing	Flat terrace with lift block and AC cooling fans and tanks; ceramic mosaic tiles for waterproofing.	
7.7	Articulation	Cornice band, projecting CI balcony and wooden porch.	
7.8	Finishes	External wall has Malad stone ashlar masonry and fourth floor has china mosaic.	
		Internal walls are plastered and painted.	
		Flooring changed according to user needs.	
7.9	Interiors (Movable & Immovable)	Movable -	
		Immovable -	
7.10	Compound/ Fence/ Gate	Building abuts the entire plot. Has an iron gate at both rear and sides.	
7.11	Curtilage/ Unbuilt space/ Out	Open spaces in rear and sides of the building.	
7.11	Buildings/ Landscape	No outbuilding.	
	Buildings/ Edindscape	No landscape.	
		110 lanabapo.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light through door-window openings supplemented by electric ligh	
J. 1	-19110119	fixtures.	
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Presence of smoke detectors and fire extinguishers.	
8.7	Other (HVAC/BMS/Security Systems)		
0.1	Cities (117710/BMC/CCGanty Cyclemo)	Trindow / To drinto.	
9.0		Condition	
9.1	Plinth	Good. Well maintained.	
9.2	Walls	Good. Well maintained.	
9.3	Floor	Good. Well maintained.	
9.4	Stairs	Fair. Service staircase is not maintained, blocked at fourth floor with loose wires hangin	
		and objects are stored in the area.	
9.5	Openings	Fair. Window frame changed, painted, addition of grills, AC units and blocked.	
9.6	Roofing	Good. Well maintained.	
9.7	Articulation & Finishes	Fair. External wall blackened and has holes and dents in some of the stone.	
9.8	Services	Good. Well maintained.	
9.9	Out Buildings		
9.10	Overall Conditions	Good Maintenance level: Good	
10.0		Transformation	
	Form	No visible changes	
	Structure	No visible changes	
	Articulation & Finishes	No visible changes	
11.0		DP Remarks/ Perceived Threats	
		Part of C1 Commercial Zone.	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		Hamilton studio supposed to be present in the building.	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation.	
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct	
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay.	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,	
		Division of International Thomson Publishing Inc.	
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i> , Bombay : Eminence	
		Designs Pvt. Ltd.	
		Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bomba	
		First.	
	1		

Hamilton House 141(7)




Buff clad façade with ground floor arched and rectangular openings, floor bands, step balconies



Main entrance with an added porch



Step balconies supported on brackets



Balmer Lawrie	and Co. Building	141(8)	
	¥	supported on circular wooden columns.	
7.3	Floor	Wooden floor boards supported on wooden rafters and beams.	
7.4	Stairs	-	
7.5	Openings	Large rectangular openings along the front façade, with glazed paneled shutters	
7.6	Roofing	Sloping Mangalore tile hip roof supported on steel truss and slender circular steel columns. Roof is composed in two parts - front and rear, forming valleys at the center.	
7.7	Articulation	Projecting balconies with cast iron railings, cornice bands	
7.8	Finishes	Yellow dressed regular ashlar masonary external wall and plaster painted internal finishes.	
7.9	Interiors (Movable and Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	No compound wall, only an iron gate enclosing the common open space on both the sides.	
7.10	Curtilage/ Unbuilt space/ Out Buildings/	Paved open space shared with adjoining and rear side buildings. Tree lined avenue along	
7.11	Landscape	the front and services located in the rear common space.	
8.0		Services and Utilities	
8.1	Lighting	Adequate natural light also supplemented by artificial light.	
8.2	Ventilation	Adequate natural ventilation also supplemented by artificial means.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and Sanitation)	MCGM	
8.6	Fire Precaution		
		Fire extinguishers Split and window unit air conditioners.	
8.7	Other (HVAC/BMS/Security Systems)	Spirt and window unit all conditioners.	
9.0		Condition	
9.1	Plinth	Fair - plumbing interventions along the sides and rear.	
9.2	Walls	Fair - plant growth and plumbing interventions on the rear side. Also seepage observed internally along the toilet walls.	
9.3	Floor	Fair	
9.4	Stairs	Fair	
9.5	Openings	Fair	
9.6	Roofing	Fair	
9.7	Articulation and Finishes	Fair - blackening, plant growth and interventions.	
9.8	Services	Fair – old and neglected plumbing lines to the rear side.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair Maintenance level Fair	
10.0		Transformation	
	Form		
	Structure	Structural repairs undertaken by providing steel supports to the wooden floor rafters.	
	Articulation and Finishes	•	
11.0		DP Remarks/ Perceived Threats	
11.0		Part of C1 Commercial Zone.	
		i artoro i commodal zono.	
12.0		Additional Notes/ References/ Documents available	
12.10		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Ballard Estate – A Corporate District (2000) Urban Design Research Institute and Bombay First.	

Balmer Lawrie and Co. Building 141(8)



Side façade used to take various services



Balcony projection supported on brackets



Step balcony opening with lintel band supported on scroll brackets

		Common Ref No: 141(9)	SHIVSAGAR RAMGULAM MARG
		Card No: 191	GULAM MARG
		Ward (Part): A (part II)	一
IIIII.		CS No: 23/1187 (Fort division) Plot Area: 597.09 sq m.	- SANTAN
		B U Area: -	
1		Date: 15/2/2005	T T
		Recorded by: Arun Wadhwa	
A STATE		Reviewed by:	m =
- WIL 1		Int: Arun Wadhwa	MA M
OLTAS	Ho.	Ext: Arun Wadhwa	
		Photo Ref: 141(9)_Voltas house.	HOUSE HOUSE
			N HEREDIA MARG
1.0	N (B :	Denomination	
1.1	Name of Premises	Voltas House	
1.2	Earlier Name	Strand House	
1.3	Built in:	-	Extension Date: -
2.0		Access	
2.0	Main	J. N. Heredia Marg	
2.1	Subsidiary	J. N. Hereula Wary	
L.L	Oubsidial y	-	
3.0		Ownership pattern	
3.1	Present	Voltas India Ltd – Owner	
3.2	Past	-	
3.3	Status	Tenant.	
4.0		Use	
4.1	Present	Offices of State Bank of India.	
4.2	Past	Offices of Voltas India Ltd.	
4.3	Usage	Daily	
5.0		Significance & value Classification	
5.1	Townscape (manmade)		curvilinear road profile maintaining similar height & tions laid down for the entire Ballard Estate. It is the southwest road front
5.2	Architectural Description	accessed through a staircase lobby of The entire floor forms columnar office have a similar layout except a slightheighted basement houses canteen & Style Influence of European Renaissance style Features	
5.3	Intrinsic	openings form prominent features. Pr	ominent lintel & sill projections in façade openings onsole feature beneath. Slightly setback Mangalore
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G	(grp). Recommended grade II A.
···	13.20 0.20011041011	(a. a), =(pai), = (aaa), = (aa), =, 1 , O	G.F. I
6.0		Topography	
6.1	Floors	G + 4 & basement	
7.0		Construction	
7.1	Plinth	Plinth height about 0.9 M dressed in	yellow kurla stone ashlar course with a separating
		cornice band.	
7.2	Walls	Non-loadbearing brick masonry walls &	
7.3	Floor	Concrete floor slab supported on colun	
7.4	Stairs	Regular double flight wooden stair with	litt block at the floor landing.
7.5	Openings	openings on ground floor & large red	trance on both ends of the front façade. Shallow arch stangular architrave openings on upper floor. Wood len door shutters, lately replaced with full heighted

Voltas House		141(9)		
7.6	Roofing	Concrete slab with slightly inclined walls and Mangalore tile finished appears like a		
1.0	T tooming	mansard roof.		
7.7	Articulation	Floor level Cornice bands, architrave facade openings.		
7.8	Finishes	External yellow Kurla stone dressed facades & internal plaster painted wall surfaces. Varied		
		floor finishes like marble, granite & ceramic tiles observed.		
7.9	Interiors (Movable & Immovable)	Movable		
	mienere (merasie a minerasie)	Renovated office interior spaces with no heritage value.		
		Immovable		
		Renovated office interior spaces with no heritage value.		
7.10	Compound/ Fence/ Gate	Building itself forms the boundary, iron gate & railing with adjoining buildings to secure		
		common open spaces on both sides & rear.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Paved open space on three sides shared with the adjoining buildings. Trees line the wide		
	Landscape	road front.		
8.0		Services & Utilities		
8.1	Lighting	Adequate natural light supplemented by artificial light.		
8.2	Ventilation	Adequate natural ventilation supplemented by artificial means.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM- Underground & overhead water tank		
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM		
8.6	Fire Precaution	Fire extinguishers.		
8.7	Other (HVAC/BMS/Security Systems)	Split & window unit air-conditioners.		
9.0		Condition		
9.1	Plinth	Poor - Damage & seepage observed on the sides & rear due to poor plumbing.		
9.2	Walls	Fair - except some damp patches on the fourth floor due to seepage.		
9.3	Floor	Indeterminable - due to false ceilings on all floors.		
9.4	Stairs	Fair - Well maintained except tiling done over wooden treads.		
9.5	Openings	Fair - except dormer window openings on fourth floors.		
9.6	Roofing	Fair - except some damp patches & exposed reinforcement on the terrace slab. Damaged		
		Mangalore tiling over mansard roof.		
9.7	Articulation & Finishes	Poor- stone dressed side & rear facades with blackening, plant growth & A.C units		
		observed. Fair condition of internal wall surfaces.		
9.8	Services	Poor external plumbing & electrical lines, but fair internally.		
9.9	Out Buildings			
9.10	Overall Conditions	Fair except services & external stone Maintenance level: Fair except external.		
		finishes.		
40.0		Tourstourstour		
10.0	Farm	Transformation		
	Form	•		
	Structure	Languigness strip attached at the first flear comics hand		
	Articulation & Finishes	Long signage strip attached at the first floor cornice band.		
11.0		DP Remarks/ Perceived Threats		
11.0		Part of C1 Commercial Zone.		
		Fait of C1 Confinercial Zone.		
12.0		Additional Notes/ References/ Documents available		
12.0		Additional Notes:		
		Additional Notes.		
		References:		
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and		
		Structures listed for Conservation.		
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct		
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay.		
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,		
		Division of International Thomson Publishing Inc.		
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence		
		Designs Pvt. Ltd.		
		Ballard Estate - A Corporate District (2000) Urban Design Research Institute and Bomba		
		, , ,		



Arch opening blocked with paneling



Side façade used to take various services



Mansard roof with dormer windows



Wooden staircase with carved railing



Window opening with lintel band with scroll brackets partly blocked by hoarding



Front façade with arched and rectangular openings, step balconies, floor bands



Rear side encroachments.



Internal spaces modified according to tenants requirements

40 K D 11			44440
40, K Dubha	sh Marg – popularly known as Rhythm H		141(10) MAHATMA GANDHI ROAD
		Common Ref No: 141(10)	
		Card No: 192	
		Ward (Part): A (Part III)	
		CS No: 143	
		Plot Area: 1729.94 sqm.	
		B U Area: -	
		Date: 19/11/2004	N N N N N N N N N N N N N N N N N N N
	COLE PAINTS & CONTRACTS PYTLID	Recorded by: Zankhana Prajapati	77 4 1
1	RHYTHLE	Reviewed by:	O O O O O O O O O O O O O O O O O O O
	Name and State of the State of	Int: Arun Wadhwa, Zankhana Prajapati	S PS 1/ NA
		Ext: Arun Wadhwa, Zankhana Prajapati	
THE		Photo Ref.: 141(10)_40 K Dubash Marg	4
		7-	
			The state of the s
	1		Location Plan
1.0		Denomination	
1.1	Name of Premises	40, K Dubhash Marg – popularly known as	
		Rhythm House building	
1.2	Earlier Name	40, K DubhashMarg.	
1.3	Built in:	Indeterminable	Extension Date: Indeterminable
2.0		Access	
2.1	Main	V.B. Gandhi Marg, K. Dubhash Marg (wrongl	y listed under Ballard estate precinct)
2.2	Subsidiary	-	
	•		
3.0		Ownership pattern	
3.1	Present	Private	
3.2	Past	Indeterminable	
3.3	Status	Owner and tenants.	
0.0	Ciatao	O WHOT AND CONTINUE.	
4.0		Use	
4.1	Present	Shops and offices (commercial)	
4.1	Past	Indeterminable	
4.2		Commercial. Daily	
4.3	Usage	Commercial. Dally	
F 0		Cimificance 8 Value Classification	
5.0 5.1	Townscape (Natural/ Manmade)	Significance & Value Classification The building sits on the important junction of	I/ Dubbas Mars and V/D. Candbi road and
5.1	Townscape (Natural/ Manimade)		
F 0	Anabitant and Depositation	maintains the corner of the junction forming a	major landmark on the Kalaghoda junction.
5.2	Architectural Description	Planning	harman Charles at the attention and the control of
		Being the corner plot the building maintains t	ne profile of the street and turns the corner
		while occupying the entire plot.	wilding FOVD Conditi Many bases the
		Access to the first floor is from the adjacent b	building – 59 V.B. Gandhi Marg because the
		original access has been closed.	in a the anadeide accession the effect of the
			cing the roadside accessing the offices on the
		other side. The ground floor is currently occu	pied by the music snop "Rhythm House".
		Features	al and the second and all the second floor and
		The building is a G+1structure, with segment	ai arch opening and niches, and fluted cast
		iron columns with a decorative floral motif ca	
		The verandah on the 1st floor is supported on	
		pattern. The baluster in cast iron is also orna	
		Columns and flooring are in wood. Even the	
		At the roof level a comice band runs along th	
		The Top of the rain water pipe is also treated with a moulding. A stucco of band of molding runs along all the arched openings on the first floor.	
			e arched openings on the first floor.
		Style The Duilding itself does not indicate any port	inclor shile hot serve of its factors and the first
			cular style, but some of its features and certain
F 2	letrie e le	areas depict inferences from Neo classical at	
5.3	Intrinsic	The Rhythm house music shop that occupies	sine ground floor of the building has become
E /	Value Classification	an important icon in the Kalaghoda circle.	Decemberded and J.D.
5.4	Value Classification	A(arc), I(sce)	Recommended grade II B
		Township	
6.0		Topography	
6.1	Floors	G+1	

-			
7.0 7.1	Plinth	Construction	g height due to paving, approximately 0.45 m.

lo, K Dubha	ash Marg – popularly known as Rhythm Hou		
		high and has a 5 cm projection on all sides	
7.2	Walls	Walls are constructed in rubble masonry stone whereas the internal partitions are in wooden panels.	
7.3	Floor	The verandah floor is supported on iron brackets, internally there is a row of steel columns.	
		The Ground floor has ceramic tile flooring but it is not originally laid whereas on the first	
		floor wooden planks are laid on wooden joists.	
		To support the loft wooden props have been added at certain places. Wooden flooring is	
		present on entire the floor area except for some portion, which has ceramic tile flooring.	
7.4	Stairs	Currently the staircase to the first floor is a doglegged staircase made in concrete and laid	
		with Kotah stone in the adjoining building which is said to be an annex/ extension of the	
		original building.	
7.5	Openings	All the openings are huge segmental arched openings.	
	3.	All the members are of wood, doors are paneled and louvered and windows are of fixed	
		glass panels with ventilators at the top.	
7.6	Roofing	The entire roof is composed of a series of three-pitched roofs with front portion being flat	
	, and the second	with lean-to roofs above the veranda on the first floor.	
7.7	Articulation	The wooden members of verandah roof in a curvilinear fashion forms a major articulation.	
7.8	Finishes	Internal and external walls are plastered and painted.	
7.9	Interiors (Movable & Immovable)	Movable	
1.0	microre (morable a minerable)	No trace of old interiors as the building has gone through major transformation internally.	
		Immovable	
		No trace of old interiors as the building has gone through major transformation internally.	
7.10	Compound/ Fence/ Gate	No compound wall, gate or fence is there as the building sits on the entire plot area.	
7.11	Curtilage/ Unbuilt space/ Out	- No compound wail, gate or fortice is those as the ballating sits of the critic plot area.	
7.11	Buildings/ Landscape		
8.0		Services & Utilities	
8.1	Lighting	Natural light available through large door-window openings, supplemented by electric light	
0.1	Lighting	fixtures.	
8.2	Ventilation		
0.2	ventilation	Door-window openings with ventilators derive ventilation from continuous verandas. Also	
0.0	Electrical	fan and air-conditioning units used.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No trace of fire fighting or security system.	
8.7	Other (HVAC/BMS/Security Systems)	Central and split unit airconditioning system installed by tenanted offices.	
9.0		Condition	
9.1	Plinth	Fair - Plaster exposed along the roadside may cause seepage.	
		Plant growth visible at some places along the plinth.	
9.2	Walls	Fair - Damaged plaster with exposed brickwork at a few places externally.	
9.3	Floor	Fair - Original wooden floorboards in the verandas have loosened and in need of	
		maintenance. Major changes in internal finishing observed.	
9.4	Stairs	Fair - The staircase from the adjacent building is in fair condition but requires maintenance	
		Small wooden stair added to access the mezzanine.	
9.5	Openings	Fair - Wooden members of door and window openings are in a state of decay. Window	
0.0		openings altered with fixed glass panels and rolling shutters. Wooden Door shutters	
		replaced with full height glass doors. Metal grills fixed externally to the north side openings	
		Air-conditioning units	
9.6	Roofing	Fair - Mangalore tile roof seems old and in need of repair and maintenance.	
9.7	Articulation & Finishes	Fair - No trace of original finishing to walls observed, presently painted with	
9.8	Services	Poor	
9.9	Out Buildings	-	
9.9	Out Buildings Overall Conditions		
9.10	Overall Conditions	Average Maintenance level: Average	
10.0	_	Transformation	
	Form	•	
	Structure	Steel columns and girders added to reinforce structural system. Internal addition of	
		partitions	
		In the western end a shop has a mezzanine floor by going below plinth, a kind of basemen	
	Articulation & Finishes	-	
11.0	Articulation & Finishes	DP Remarks/ Perceived Threats	
11.0	Articulation & Finishes	DP Remarks/ Perceived Threats Building forms part of C1 zone	
11.0	Articulation & Finishes		
11.0	Articulation & Finishes	Building forms part of C1 zone	
	Articulation & Finishes		

40, K Dubhash Marg - popularly known as Rhythm House building

141(10)

References:
INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structure's listed for Conservation.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.



West side curved façade with arched openings, verandah spaces



North side façade with projecting balconies supported on brackets, wooden columns and metal railing. Openings have been incongruously



Detail of the wooden carved column in verandah with a floral pattern capital



Curved Verandah along the building with sloping roof



Detail of the bracket supporting the wooden Verandah above

Trade Wir	ngs		141(11)
	-9-	Common Ref No: 141(11)	7 4 / / 3 / 5 #
		Card No: 193	
		Ward (Part): A (Part III)	The second secon
		CS No: 137	2 8 6 1
		Plot Area: 288.46 sqm.	
100		B U Area: -	AND AND AND AND AND AND AND AND AND AND
, h		Date: 06/04/2005	Good S GREEK HAM BOOM E
		Recorded by: Arun Wadhwa	
		Reviewed by:	
	E AND RESERVED	Int: Arun Wadhwa	
		Ext: Arun Wadhwa	
4	The same of the sa	Photo Ref: 141(11)_Trade Wings.	
Chetan		Photo Ref. 141(11)_frade wings.	
			5 = 5
			Location Plan
1.0		Denomination	Lookion i iun
1.1	Name of Premises	Trade Wings	
1.2	Earlier Name	Trade Wings	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Kaikhushroo Dubhash Marg (wrongly lis	ted under Rallard estate procinct/
2.2		Raikilusilioo Dubilasii warg (wioligiy iis	ted under ballard estate precinct)
Z.Z	Subsidiary	-	
• •		1: "	
3.0		Ownership pattern	
3.1	Present	Trade Wings company Ltd - Owner	
3.2	Past	Indeterminable	
3.3	Status	Tenant	
4.0		Use	
4.1	Present	Commercial - Restaurant, departmental	store and Banquet facilities.
4.2	Past	Indeterminable	•
4.3	Usage	Daily.	
		,	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)		e south side road front, formerly Rampart row.
	()		with sloping roof from south side road front.
			e rectangular openings and distinct cornice bands
		at floor levels.	- · · · · · · · · · · · · · · · · · · ·
5.2	Architectural Description	Planning	
0.2	Alcintectural Description		entry located at the east end forming large
		uninterrunted enace at all floors serving	as banquet facilities; narrow G+1 wing to the east
			nodating additional mezzanine within the sloping
		roof.	locating additional mezzanine within the sloping
			ith an added lift shaft in the lobby. Services are
		located to the rear north side.	illi ali added illi silali ili ille lobby. Services are
		Features	
			hands and large ananings with raliaf architectus
			bands and large openings with relief architrave
			pediment feature supported on small decorative
		brackets above architrave openings. U	Jpper floor openings open out as balcony over
		cornice bands with decorative cast iron	railing. Upper floor openings are also marked by
			anel in the front. Internally tall cast Iron fluted
			rt the floor structure. Continuous terrace parapet
			Also large wooden truss work supporting the roof
		seems interesting.	
		Style	
. 0	1	No particular style, Classical features ob	served.
5.3	Intrinsic	-	15
5.4	Value Classification	A(arc), B(per)	Recommended grade: III
6.0		Topography	
6.1	Floors	G + 2 floors.	
7.0		Construction	
7.1	Plinth	Plinth height of about 0.45 m.	
	1 111141	i mini noight of about 0.70 m.	

Trade Wings		141(11)	
7.2	Walls	Load bearing brick masonry walls and cast iron columns.	
7.3	Floor	Indeterminable due to false ceiling.	
7.4	Stairs	Wide double flight wooden stair with distinct balusters and handrail. Steel spiral stair to the rear side for services.	
7.5	Openings	Large door openings with wood framed glazed panel shutters, recently replaced with fixed glass panels.	
7.6	Roofing	Steep sloping mangalore tile roof supported on heavy wooden truss work.	
7.7	Articulation	Distinct cornice bands at floor levels, Architrave openings with relief features, wooden awning over upper floor openings.	
7.8	Finishes	Plain plastered/ painted finishes to both external and internal wall surfaces. Relief decorative features on façade also paint finish. Wooden stair and roof members polished. Wooden flooring in refurbished areas.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	Building itself forms boundary along the south front and east side, adjoining buildings very close to the west and north side.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape		
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light also relies on artificial sources.	
8.2	Ventilation	Relies on artificial means – fully air-conditioned spaces.	
8.3	Electricity	BEST.	
8.4	Water Supply	MCGM. Underground and Overhead Water storage tank.	
8.5	Drainage (Plumbing & Sanitation)	MCGM Connected to Municipal sewer lines.	
8.6	Fire Precaution	No fire detection system – only fire extinguishers installed.	
8.7	Other (HVAC/BMS/Security Systems)	Central AC system.	
9.0		Condition	
9.1	Plinth	Fair except plumbing interventions to side and rear portions.	
9.2	Walls	Fair.	
9.3	Floor	Fair.	
9.4	Stairs	Fair. Well maintained.	
9.5	Openings	Fair except altered openings along the front side.	
9.6	Roofing	Fair.	
9.7	Articulation & Finishes		
-		Good – fully refurbished interiors with well maintained finishes.	
9.8 9.9	Services	Fair	
	Out Buildings Overall Conditions	- Miston Ind Fit	
9.10	Overall Conditions	Good. Maintenance level: Fair	
10.0		Transformation	
	Form	-	
	Structure	-	
	Articulation & Finishes	Façade painted	
11.0		DP Remarks/ Perceived Threats	
11.0		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.	

Trade Wings 141(11)



Front façade with arched and rectangular openings with pediments, balconies, floor bands



Wide arcade along the building, openings with door bands, pediments, extended sloping roof porch



Bracket detail supporting projecting balcony now enclosed



Railing


Rear steel staircase








Roof detail



12)	Hargovindas building		141
		façade also painted.	
7.9	Interiors (Movable & Immovable)	Movable	
		- Immovable	
7.10	Compound/ Fence/ Gate	Narrow open space with boundary wall along the adjoining buildings on the three si except the southern front side.	des
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape		
0.0		Complete 0 Hallaha	
8.0 8.1	Lighting	Services & Utilities Adequate natural light except internal passage and lobby, also supplemented by artificial light fixtures.	
8.2	Ventilation	Adequate natural ventilation also supplemented by AC units and fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Fire extinguisher voluntarily adopted in the absence of integrated fire fighting syster	n.
8.7	Other (HVAC/BMS/Security Systems)	Air- conditioning units.	
9.0		Condition	
9.1	Plinth	Poor - in side and rear elevation due to seepage and water logging of the drainpipe:	s
9.2	Walls	Fair except some damage and cracks observed on the side and rear walls. Internally dilapidated and altered surfaces.	
9.3	Floor	Poor - Exposed reinforcement and plaster at some common and service areas.	
9.4	Stairs	Fair state except poor finishing and maintenance levels.	
9.5	Openings	Signboard has incongruously occupied the façade openings at ground level. Original shutters altered and replaced, louvered wooden panels replaced with glass pane Air-Conditioning unit's installed within door shutters on the façade openings.	
9.6	Roofing	Indeterminable since inaccessible.	
9.7	Articulation & Finishes	Fair on the front side and poor paint-plaster finishes on the side and rear facades.	
9.8	Services	Poor - Rear of the building is very poorly maintained and leakage and seepage is seen extensively, very unhygienic condition prevails. AC units have incongruously punctuated the façade and due to leakage spoil the façade. Electrical lines and conduits are exposed in main staircase.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair except altered openings, neglected services and modified internal spaces. Maintenance level: fair internally, neglected services and altered openings.	Jecte
10.0		Transformation	
	Form	-	
	Structure	Mezzanines added extensively throughout the large floor height and internal partitio the renovated and subdivided office spaces.	_
	Articulation & Finishes	Front façade including detail features are paint finished, signboards obscure and da the façade character.	ımage
11.0		DP Remarks/ Perceived Threats	
11.0		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings a Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Archit Division of International Thomson Publishing Inc.	





Arched openings with ventilator openings, carved spandrel.



Arched opening arcade supported on columns with rusticated joints

Oricon hou	se		141(13)
		Common Ref No: 141(13)	11137
		Card No: 195	131 To Real Control Co
W. (200)	770	Ward (Part): A (Part III)	
4		CS No: 135	9 134 E
		Plot Area: 467.77 sqm.	136
The same		B U Area: -	30
The state of the s		Date: 05/04/2005	115 125
		Recorded by: Arun Wadhwa	44.
		Reviewed by:	KAIKHUSHROODUBASH MARG
		Int: Arun Wadhwa	CAMAOR CAMAOR
THE PERSON NAMED IN		Internal photography permission denied	MA.
The same		Ext: Arun Wadhwa	
		Photo Ref: 141(13) Orikon House.	000
		· /=	AS.
			"Ma
Service April 1			"APC
			Location Plan
1.0		Denomination	
1.1	Name of Premises	Oricon house	
1.2	Earlier Name	Oricon house	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Kaikhushroo Dubhash Marg (formerly Rampa	art Row)
2.2	Subsidiary	MHCC lane.	,
	,		
3.0		Ownership pattern	
3.1	Present	Maharashtra Chamber of Commerce and Inc	dustry - Owner
3.2	Past	Private	
3.3	Status	Owner and tenants.	
4.0		Use	
4.1	Present	Commercial – offices, shops.	
4.2	Past	Commercial – offices, shops.	
4.3	Usage	Daily.	
	Joago	24.17.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	Prominent corner building along the row of	buildings with pedestrian arcade facing the
		south side road front, formerly Rampart row.	
			n side road front. Characterized by a high
			row of buildings, building is otherwise
		reconstructed with modern façade on upper	
5.2	Architectural Description	Planning	
	'	Rectangular plan with longer road front and	slightly inclined side along the subsidiary lane
			rcade into a staircase lobby leading to typical
			An internal chowk lights the stair and internal
		passages. Common toilet facilities are locate	ed to the rear north side accessed by narrow
		passage. An original large heighted G+ 3 s	structure was reconstructed into G+6 storied
		RCC structure.	
		Features	
			h semicircular arch openings and decorative
			lumns with distinct base and molded capitals
			orting arcade openings. Overhanging upper
			kets. Fine carved frieze with floral motifs runs
		continuous along the arcaded ground floor.	
		Style	
	1	Neo Classical features in ground floor arcade	9.
5.3	Intrinsic	-	In
5.4	Value Classification	A(arc), B(per)	Recommended grade: III
		-	
6.0		Topography	
6.1	Floors	G + 6 floors.	
7.0		Construction	
		Plinth height of about 0.45 m.	
7.1	Plinth		
7.1 7.2 7.3	Plinth Walls Floor	Load bearing brick masonry walls and cast in Indeterminable due to false ceiling.	on columns.

Stairs	141(13)	
	Wide double flight wooden stair with distinct balusters and handrail. Steel spiral stair to	
	the rear side for services.	
Openings	Rectangular window openings with sliding aluminum shutters on typical upper floors, ground floor arcade front has original stone dressed arch openings, though shutters are	
	modified.	
Roofing	Flat RCC slab with water proofing layer for rain water protection.	
Articulation	Semicircular arch openings with decorative keystone in pedestrian arcade, circular stone column projection with distinct base and molded capital feature in the arcade front.	
Firebox	fine stone carved frieze band	
	Buff basalt stone dressed ground floor arcade portion, otherwise plain plaster painted external and internal wall finishes. Also varied and ordinary floor finishes in the interiors.	
Interiors (Movable & Immovable)	Movable	
	Immovable	
Compound/ Fence/ Gate	Building itself forms boundary along the south front and east side, adjoining buildings very close to the west and north side.	
Curtilage/ Unbuilt space/ Out	-	
Buildings/ Landscape		
	Services & Utilities	
Lighting	Adequate natural light also relies on artificial sources.	
	Relies on artificial means – fully Air-conditioned spaces.	
	BEST.	
	MCGM. Underground and Overhead Water storage tank.	
	MCGM Connected to Municipal sewer lines.	
	No fire detection system – only fire extinguishers installed.	
	Central AC system.	
Systems)	Contract No System.	
	Condition	
Plinth	Poor - plantation done along the arcade and shop fronts causing seepage and damage to plinth courses.	
Walls	Fair.	
	Fair.	
	Poor – neglected state.	
Openings	Poor – window unit AC's haphazardly accommodated in façade openings. Also original stone dressed arch openings on ground floor altered.	
Roofing	Fair.	
	Poor neglected stone dressed arcade and decorative iron brackets	
Services	Fair	
Out Buildings	-	
Overall Conditions	Fair except original stone finishes in pedestrian arcade. Maintenance level: Low	
<u> </u>	Transformation	
Form	Reconstructed building except the ground floor arcade portion.	
	Original G + 3 wooden building reconstructed in RCC G + 6 structure.	
Articulation & Finishes	Fully reconstructed except the stone dressed ground floor arcade.	
	DP Remarks/ Perceived Threats	
	Building forms part of C1 zone	
	Additional Notes/ References/ Documents available Additional Notes:	
	References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.	
	Articulation Finishes Interiors (Movable & Immovable) Compound/ Fence/ Gate Curtilage/ Unbuilt space/ Out Buildings/ Landscape Lighting Ventilation Electricity Water Supply Drainage (Plumbing & Sanitation) Fire Precaution Other (HVAC/BMS/Security Systems) Plinth Walls Floor Stairs Openings Roofing Articulation & Finishes Services Out Buildings Overall Conditions Form Structure	

Oricon house 141(13)



Front façade with an ground floor arcade and 3 added floors above, opening alterations etc



Arched arcade opening with scroll bracket keystone, brackets supporting floor above




Arcade with arched openings



Scroll bracket keystone in the arched opening with a frieze band above



Bracket detail



Ador House		141(14	
7.2	Walls	The walls are constructed in brick masonry where as the internal partition in wooden panels.	
7.3	Floor	In veranda the floor is supported on iron bracket whereas internally there is a row of steel	
7.4	Stairs	columns. To support loft wooden props are added at certain places. Currently the staircase to the first floor is doglegged staircase made in concrete and laid with Kotah stand from the part hydrigg which is said to be approved to sign of the hydrigan.	
7.5	Openings	with Kotah stone from the next building which is said to be annex/extension of the building. Most façade openings are rectangular except on second floor where semicircular arch	
		openings. Window shutters are wood framed glazed paneled. Doors are wood paneled and louvered with ventilation at top.	
7.6	Roofing	Flat RCC slab on fifth floor, sloping cement sheet roof on part terrace block.	
7.7	Articulation	Rectangular arcade openings with rusticated colonnade, cornice bands at first and third floor, segmental pediment feature above third floor,	
7.8	Finishes	Buff basalt stone dressed south façade, plastered painted side and rear facades and internal wall surfaces. Varied and modified floor finishes. Wooden door / window shutters polished /painted.	
7.9	Interiors (Movable & Immovable)	Movable No trace of old interiors as the building has gone through major transformation internally. Immovable No trace of old interiors as the building has gone through major transformation internally.	
7.10	Compound/ Fence/ Gate	No boundary to the front, shares compound wall to the east side and rear north with	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	adjoining buildings. Narrow set back open spaces to the east and north side.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light except the staircase and lobby; also relies on electrical fixtures.	
8.2	Ventilation	Adequate natural ventilation; still relies on AC units and fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No trace of fire fighting or precautionary system.	
8.7	Other (HVAC/BMS/Security Systems)	Central air- conditioning for the fourth and fifth floor.	
0.1	Other (TVAO/DWO/Occurry Oystems)	Ochida dii- conditioning for the routh and mar noor.	
9.0		Condition	
9.1	Plinth	Poor - Plinth in back and rear elevation is in poor condition due to seepage and water logging of the drainpipes.	
9.2	Walls	Fair – seepage and plant growth at many places along the facades.	
9.3	Floor	Indeterminable - Due to the presence of false ceiling and carpet could not make out the	
9.4	Stairs	condition of the floors. Fair - recent renovation was undertaken, the condition of staircase is good and is laid in	
9.5	Openings	concrete and finished in green marble. Fair except modifications and A.C's installed within. Also signboards incongruously occupy	
9.5	Openings	the façade openings. Chajjas, grills, loose window frames, unpolished and low maintenance further deteriorates the condition.	
9.6	Roofing	Fair - Roof is in good condition, as the waterproofing was done, no visible damage.	
9.7	Articulation & Finishes	Poor - buff basalt stone is blackened at many portion, many stones have cracks and are filled with cement mortar. Plaster and paint is peeling off at many places. Varied and	
9.8	Services	modified floor finishes. Poor - Rear of the building is very poorly maintained and leakage and seepage is seen	
		extensively, very unhygienic condition prevails. AC units have incongruously punctuated the façade and due to leakage spoil the façade.	
0.0	0.15.11	Electrical lines and conduits are exposed in main staircase.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair except finishes, services. Maintenance level: Low	
10.0		Transformation	
	Form	Form of the entire original building has been transformed by the addition of two extra floors, and also on terrace there is an office setup, slightly receded from the front. Thus the building actually is not G+5 but is G+6.	
	Structure	I – sections girders have been used to strengthen the building due to the addition of the two floors. In the arcade closed box-typed iron brackets support the arched openings.	
	Articulation & Finishes	Plastering and coloring the stone fascia in some portion. Floor finish of the entire building is changed as per individual tenants of the office premises	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	

Ador House 141(14)


Additional Notes:

References:
INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.
FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.



ERROR: stackunderflow
OFFENDING COMMAND: ~

STACK:



Ador House		141(14	
7.2	Walls	The walls are constructed in brick masonry where as the internal partition in wooden panels.	
7.3	Floor	In veranda the floor is supported on iron bracket whereas internally there is a row of steel	
7.4	Stairs	columns. To support loft wooden props are added at certain places. Currently the staircase to the first floor is doglegged staircase made in concrete and laid with Kotah stand from the part hydrigg which is said to be approved to sign of the hydrigan.	
7.5	Openings	with Kotah stone from the next building which is said to be annex/extension of the building. Most façade openings are rectangular except on second floor where semicircular arch	
		openings. Window shutters are wood framed glazed paneled. Doors are wood paneled and louvered with ventilation at top.	
7.6	Roofing	Flat RCC slab on fifth floor, sloping cement sheet roof on part terrace block.	
7.7	Articulation	Rectangular arcade openings with rusticated colonnade, cornice bands at first and third floor, segmental pediment feature above third floor,	
7.8	Finishes	Buff basalt stone dressed south façade, plastered painted side and rear facades and internal wall surfaces. Varied and modified floor finishes. Wooden door / window shutters polished /painted.	
7.9	Interiors (Movable & Immovable)	Movable No trace of old interiors as the building has gone through major transformation internally. Immovable No trace of old interiors as the building has gone through major transformation internally.	
7.10	Compound/ Fence/ Gate	No boundary to the front, shares compound wall to the east side and rear north with	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	adjoining buildings. Narrow set back open spaces to the east and north side.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light except the staircase and lobby; also relies on electrical fixtures.	
8.2	Ventilation	Adequate natural ventilation; still relies on AC units and fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No trace of fire fighting or precautionary system.	
8.7	Other (HVAC/BMS/Security Systems)	Central air- conditioning for the fourth and fifth floor.	
0.1	Other (TVAO/DWO/Occurry Oystems)	Ochida dii- conditioning for the routh and mar noor.	
9.0		Condition	
9.1	Plinth	Poor - Plinth in back and rear elevation is in poor condition due to seepage and water logging of the drainpipes.	
9.2	Walls	Fair – seepage and plant growth at many places along the facades.	
9.3	Floor	Indeterminable - Due to the presence of false ceiling and carpet could not make out the	
9.4	Stairs	condition of the floors. Fair - recent renovation was undertaken, the condition of staircase is good and is laid in	
9.5	Openings	concrete and finished in green marble. Fair except modifications and A.C's installed within. Also signboards incongruously occupy	
9.5	Openings	the façade openings. Chajjas, grills, loose window frames, unpolished and low maintenance further deteriorates the condition.	
9.6	Roofing	Fair - Roof is in good condition, as the waterproofing was done, no visible damage.	
9.7	Articulation & Finishes	Poor - buff basalt stone is blackened at many portion, many stones have cracks and are filled with cement mortar. Plaster and paint is peeling off at many places. Varied and	
9.8	Services	modified floor finishes. Poor - Rear of the building is very poorly maintained and leakage and seepage is seen	
		extensively, very unhygienic condition prevails. AC units have incongruously punctuated the façade and due to leakage spoil the façade.	
0.0	0.15.11	Electrical lines and conduits are exposed in main staircase.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair except finishes, services. Maintenance level: Low	
10.0		Transformation	
	Form	Form of the entire original building has been transformed by the addition of two extra floors, and also on terrace there is an office setup, slightly receded from the front. Thus the building actually is not G+5 but is G+6.	
	Structure	I – sections girders have been used to strengthen the building due to the addition of the two floors. In the arcade closed box-typed iron brackets support the arched openings.	
	Articulation & Finishes	Plastering and coloring the stone fascia in some portion. Floor finish of the entire building is changed as per individual tenants of the office premises	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	

Ador House 141(14)

Additional Notes:

References:
INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.
FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.



ERROR: stackunderflow
OFFENDING COMMAND: ~

STACK:

Horniman	Circle Garden	142
		Common Ref No: 142
100 A Salar 1 100 A 100 A 100 A 100 A 100 A 100 A 100 A 100 A 100 A 100 A 100 A 100 A 100 A 100 A 100 A 100 A		Card No: 197
		Ward (Part): A (Part II).
100		CS No: - 224/554(Fort Division).
		Plot Area: 10092.88 sq m.
(P)		B U Area: -
		D + 4/0/0005
		Reviewed by: Int: Zankhana Prajapati, Sonal Modak. Ext: Zankhana Prajapati, Sonal Modak.
Y 100		Int: Zankhana Prajapati, Sonal Modak. Ext: Zankhana Prajapati, Sonal Modak. Photo Ref: 142_Horniman Circle Garden.
		Ext: Zankhana Prajapati, Sonal Modak.
		Photo Ref: 142_Horniman Circle Garden.
-		SSHA
	11/2/	BBAY TO THE THE THE THE THE THE THE THE THE THE
		and the second s
		Location Plan
1.0		Denomination
1.1	Name of Premises	Horniman Circle Garden
1.2	Earlier Name	Elphintstone Circle.
1.3	Built in:	Commenced in 1869, completed in 1872. Extension -
		Date
		2000
2.0		Access
	Main	
2.1	Main	Mumbai Samachar Marg.
2.2	Subsidiary	Shahid Bhagat Singh Road.
3.0		Ownership pattern
3.1	Present	Municipal Corporation of Greater Mumbai
3.2	Past	Municipal Corporation of Greater Bombay
3.3	Status	Owner
0.0	Status	Vinite .
4.0		llee .
4.0	D1	Use
4.1	Present	Garden
4.2	Past	Garden
4.3	Usage	Daily
5.0		Significance & value Classification
5.1	Townscape (Manmade)	This circular garden is planned on the Bombay Green, which stood opposite the Town Hall.
-	, , , , , , , , , , , , , , , , , , , ,	It lies between Mumbai Samachar Marg and Shahid Bhagat Singh Marg.
		The stone frontages of the buildings around Horniman Circle (formerly Elphinstone Circle),
		which evolved as the city's first planned business district, were designed by James Scott.
		Chief Engineer of the Elphinstone Land & Press Company, which was established in 1858
		to undertake reclamation projects in the city. The first building erected in the Circle was
		occupied by the Bank of Bombay (now State Bank of India) and the remaining buildings
		were completed by 1873. Keystone heads punctuate the arcade arches. The buildings have
		a covered arcade at ground level that provides protection from sun and rain. The
		architectural unity of the facades, accentuated by the spatial element of the arcade at
		ground level, enhances the legibility of this fine urban composition.
5.2	Architectural Description	Planning
		It is circular in plan with prominent north-south and east- west axis along it.
		It is a garden with many sub-structures like fountain, toilets, and electric substation etc.
		it is a garden with many sub-structures like fountain, tolicis, and electric substation etc.
		The garden is accessed on the north south and east west axis with gates on all four sides
		The center has a fountain with a sculpture in it around which paving is done and then
		The garden is accessed on the north-south and east-west axis with gates on all four sides. The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading
		The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garden
		The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading
		The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garden
		The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garden is made by wrought iron fencing with trees marking the boundary.
		The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garden is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has central
		The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garden is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has central fountain with sculpture, playing equipments, benches, old ornamental plants and trees.
		The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garden is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has central fountain with sculpture, playing equipments, benches, old ornamental plants and trees hard and soft landscape, Shahabad regular and irregular pavements.
		The center has a fountain with a sculpture in it around which paving is done and ther further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garder is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has centra fountain with sculpture, playing equipments, benches, old ornamental plants and trees
5 2	Intrinsia	The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garden is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has central fountain with sculpture, playing equipments, benches, old ornamental plants and trees, hard and soft landscape, Shahabad regular and irregular pavements. Style -
5.3	Intrinsic	The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garden is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has central fountain with sculpture, playing equipments, benches, old ornamental plants and trees hard and soft landscape, Shahabad regular and irregular pavements. Style The east west axis created by the Elphinstone Circle was later augmented by a similar
5.3	Intrinsic	The center has a fountain with a sculpture in it around which paving is done and then further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garden is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has central fountain with sculpture, playing equipments, benches, old ornamental plants and trees, hard and soft landscape, Shahabad regular and irregular pavements. Style The east west axis created by the Elphinstone Circle was later augmented by a similar semi-circular north-south bow-shaped axis along the original western edges of the fort
5.3	Intrinsic	The center has a fountain with a sculpture in it around which paving is done and ther further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garder is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has centra fountain with sculpture, playing equipments, benches, old ornamental plants and trees hard and soft landscape, Shahabad regular and irregular pavements. Style The east west axis created by the Elphinstone Circle was later augmented by a similar semi-circular north-south bow-shaped axis along the original western edges of the fort walls. Later, this axis was anchored at one end with the grand Victoria Terminus and at the
5.3	Intrinsic	The center has a fountain with a sculpture in it around which paving is done and ther further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garder is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has centra fountain with sculpture, playing equipments, benches, old ornamental plants and trees hard and soft landscape, Shahabad regular and irregular pavements. Style The east west axis created by the Elphinstone Circle was later augmented by a similar semi-circular north-south bow-shaped axis along the original western edges of the fort walls. Later, this axis was anchored at one end with the grand Victoria Terminus and at the other end by the Gateway of India. The intersection of the two axes was punctuated by
5.3	Intrinsic	The center has a fountain with a sculpture in it around which paving is done and ther further surrounded by a planter box, activity areas like lawns, stage for functions, reading areas, sitting areas, playing areas, water fountains, toilets etc. and the edge of the garder is made by wrought iron fencing with trees marking the boundary. Features Wrought iron decorative gate and fence with lampposts at regular intervals, has centra fountain with sculpture, playing equipments, benches, old ornamental plants and trees hard and soft landscape, Shahabad regular and irregular pavements. Style The east west axis created by the Elphinstone Circle was later augmented by a similar semi-circular north-south bow-shaped axis along the original western edges of the fort walls. Later, this axis was anchored at one end with the grand Victoria Terminus and at the

Horniman	Circle Garden	142	
6.0		Topography	
6.1	Floors	-	
7.0	B# #	Construction	
7.1	Plinth	-	
7.2	Walls		
7.3	Floor	Shahabad regular and irregular stone in pavement, hard and soft landscape is present.	
7.4	Stairs	•	
7.5	Openings	-	
7.6	Roofing	•	
7.7	Articulation	•	
7.8	Finishes	<u>-</u>	
7.9	Interiors (Movable & Immovable)	Movable	
		- Immanable	
		Immovable	
		Benches, wrought iron gates, light fixtures, but all these are in very poor condition and not maintained.	
7.10	Compound/ Fence/ Gate	Decorative wrought iron fencing with ornamental gate and lamppost at regular intervals.	
7.10	Compound/ Ferice/ Gate	Wrought iron fencing, four gates at four axes.	
7.11	Curtilage/ Unbuilt space/ Out	Many utility building like substation, toilets, water reservoir, telephone booth, watchman	
7.11	Buildings/ Landscape	cabin, stage, shed and drinking water fountain is present.	
	Dullalings/ Earlascape	Many old ornamental trees and plant are present.	
		many dia diffaminantia a doo ana piant are prodont.	
8.0		Services & Utilities	
8.1	Lighting	-	
8.2	Ventilation	-	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)		
0.7	Other (TVAO/DIVIS/Security Systems)	<u>-</u>	
9.0		Condition	
9.1	Plinth	-	
9.2	Walls		
9.3	Floor	Poor- not maintained, stone missing, uneven.	
9.4	Stairs	-	
9.5	Openings	-	
9.6	Roofing	•	
9.7	Articulation & Finishes	One of the gates is broken, wrought iron fencing needs maintenance, lamps not working.	
9.8	Services	Poor - Toilets are not maintained and are in unhygienic condition.	
9.9	Out Buildings	Poor - All the outbuildings are in neglected and no proper maintenance is done.	
9.10	Overall Conditions	Fair. Maintenance level Poor.	
3.10	Overall conditions	i dir.	
10.0		Transformation	
10.0	Form	Addition of substation, watchman's cabin, telephone booth.	
	Structure	- Addition of Substation, Wateriman's Cabin, telephone booti.	
	Articulation & Finishes	Hawkers surrounding the park are really nuisance and make the surrounding dirty and	
	Atticulation & Finishes	unhygienic.	
		unnygionio.	
11.0		DP Remarks/ Perceived Threats	
11.0	+	Recreation ground.	
	+	rootoation ground.	
12.0	+	Additional Notes/ References/ Documents available	
12.0		Additional Notes:	
		The circular garden and the buildings around the circle were constructed in the 1860s after	
		the demolition of the Fort Walls under orders of Sir Bartle Frere. Sir Bartle Frere realized	
		that Bombay's security was no longer under threat from attack by potential invaders	
		especially after the British Crown took over control of India from the East India Company in 1858. Queen Victoria's proclamation in this regard was, in fact, read from the very steps	
		you are standing on. After the removal of the Fort ramparts in the mid-1860s, the first important project initiated	
		by Police Commissioner, Charles Forjett, was the restructuring of the old Bombay Green	
		that once stretched over a large area fronting the Town Hall. Dr Buist, Editor of the	
		'Bombay Times' was a prime motivator of the project, which was fully supported by	
		Governors John Lord Elphinstone and his successor, Sir Bartle Frere. The orientation of the	
<u> </u>	l	Severiors contribute Elphinistonic and his successor, oil battle Freie. The offentation of the	

Horniman Circle Garden 142

Town Hall was felicitously incorporated in the circular garden development that was to become Elphinstone Circle, named after John, Lord Elphinstone who contributed in many ways to the development of Bombay. The laying out of the garden covering an area of 12,081 square yards was commenced in 1869 and completed in 1872.

The east west axis created by the Eliphinstone Circle was later augemented by a similar semi-circular north-south bow-shaped axis along the original western edges of the fort walls. Later, this axis was anchored at one end with the grand Victoria Terminus and at the other end by the Gateway of India. The intersection of the two axes was punctuated by Flora Fountain.

Following Independence in 1947, Elphinstone circle was renamed after Benjamin Guy Horniman, a former editor of the *Bombay Chronicle* who was an active participant in India's freedom movement. The memorial citation reads: 'dedicated to the Memory of Benjamin Guy Homiman 1873-1948 who lived and worked for the freedom of the press in India. He gave us the 'Mantra' – Liberty: Mahatma Gandhi'. If the gates are open, walk through this delightful garden, where officer-goers relax and children play in the verdant surroundings. The garden provides a beautiful venue for poetry readings, plays and other get-togethers. **References:**

INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) *The Cities Within*, Bombay : Eminence Designs Pvt. Ltd.

RAHUL MEHRÖTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.



Garden view with dense tree plantation, seating arrangement, paved ways



Metal carved fence around the garden



Lamp Post



LAWII Alea

Intricately carved metal entrance gate



Fountain at the center of the garden

			440()
Zoroastrian As	ssociation Building	Common Dof No. 142(a)	142(a)
		Common Ref No: 142(a)	CONTACTOR NO.
	-	Card No: 198	
ns ns	man .	Ward (Part): A (Part II)	S S S S S S S S S S S S S S S S S S S
		CS No: 236 (Fort division)	TO SE LAKE STORE
		Plot Area: 414.72 sqm.	A A R I
		B U Area: -	PERIN NA MARKET AND THE PERING TH
	A A A STORE	Date: 06/04/2005	11 S1 1 S2 1 S 1 S 1 S 1 S 1 S 1 S 1 S 1
		Recorded by: Arun Wadhwa	
		Reviewed by:	
		,	HORNIMAN CIRCLE
THE CA		Int: Arun Wadhwa	RNIM
		Internal photography permission denied	ANC.
Designation of the same of the		Ext: Arun Wadhwa	RCIE Z
	TAR A A A A A A A A A A A A A A A A A A	Photo Ref.: 142(a)_Zoroastrian Trust building	0 0
ion press neithe			
II.			
			Location plan
1.0		Denomination	Location plan
1.1	Name of Premises	Zoroastrian Association Building	
1.2		U	
	Earlier Name	Zoroastrian Association Building	F. Landing Date
1.3	Built in:	1900's.	Extension Date: -
2.0		Access	
2.1	Main	Horniman circle – vehicular and pedestrian.	
2.2	Subsidiary		
	,		
3.0		Ownership pattern	
3.1	Present	Zoroastrian Association Trust - Owner	
3.2	Past	Nasserwanji Sorabji Guzder - Owner	
		, ,	
3.3	Status	Trust	
4.0		Use	
4.1	Present	Commercial – offices and trust.	
4.2	Past	Commercial – offices and trust.	
4.3	Usage	Daily.	
5.0		Significance & Value Classification	
5.1	Townscape (manmade)	Prominent building to the north east of historic	Horniman Circle in a predominantly banking
0.1	Townsdape (maimade)	area. Main public access through pedestrian a	
		circle. Forms an important part of a well planner	
		features and pedestrian arcade of buildings or	
F 0	Analitant and Deposition		i ali sides di circular Homlinari garden.
5.2	Architectural Description	Planning	. Handara O'rela o'lle and adda de anno de
		Small building with crescent shaped front facir	
		along the ground floor providing relief from hea	
		through arcade into a staircase lobby leading to	o typical layout on upper floors with office
		spaces on all three sides of a narrow landing.	Offices along the front have an additional
		veranda like bay above ground floor arcade w	nich recedes back on the third floor forming a
		small stretch of terrace. Common toilets are pr	rovided to the rear north side which abuts
		adjoining building. Ground floor premises direct	
		some shop fronts along the west side.	,,,
		Features	
		Crescent shaped south façade facing Hornima	un circle has rusticated around floor arcade
		with distinct comice bands at all upper floors.	
		colonnaded bays with semicircular arch openia	
		faces of men and women at alternate floors. S	
		floor, also decorative trophy like feature adorn	
		verandas on the second and third floor along t	he west side.
		Style	
		Neo Classical features.	
5.3	Intrinsic	Part of well planned frontage around Hornima	n circle with pedestrian arcade and unique
		façade features.	
5.4	Value Classification	A(arc), B(per), B(des), B(uu), E, F, G(grp), I(so	e) Recommended grade: II A
6.0		Topography	
6.1	Floors	G + 4	
J. I	1 10010	<u> </u>	
7.0		Construction	
	Dlinth		
7.1	Plinth	Low plinth about 0.45 m.	

7.3 Floor Wooden floor boards supported on 7.4 Stairs C- shaped wooden stair enclosing a 7.5 Openings Semicircular arch openings along the shutters are wood framed glazed p Large and heavy wooden door shutters Indeterminable		
7.4 Stairs C- shaped wooden stair enclosing a 7.5 Openings Semicircular arch openings along the shutters are wood framed glazed p Large and heavy wooden door shu 7.6 Roofing Indeterminable	Load bearing rubble stone masonry walls.	
7.5 Openings Semicircular arch openings along ti shutters are wood framed glazed p Large and heavy wooden door shu 7.6 Roofing Indeterminable	wooden rafters and beam members.	
shutters are wood framed glazed p Large and heavy wooden door shu 7.6 Roofing Indeterminable	C- shaped wooden stair enclosing a lift shaft in between.	
shutters are wood framed glazed p Large and heavy wooden door shu 7.6 Roofing Indeterminable	he crescent shaped north side. All external window	
Large and heavy wooden door shu 7.6 Roofing Indeterminable	anel shutters. Also separate ventilator panels provided.	
7.6 Roofing Indeterminable		
	ent shaped arcade facing Horniman circle, fine carved	
human face over keystone in semid	circular arch openings, projecting circular colonnade with	
capital and base, also distinct comi		
	es in the north façade. Plaster painted internal wall	
	surfaces and internal facades. Varied floor finishes including mosaic and ceramic tiles.	
7.9 Interiors (Movable & Immovable) Movable	iod noor minoriod moldaring modale and cordinio dice.	
- Interiore (interiore a miniorable)		
Immovable		
-		
7.10 Compound/ Fence/ Gate Building itself forms boundary along	g front south and west side with abutting buildings to the	
north and east side.	g g g g g	
7.11 Curtilage/ Unbuilt space/ Out Buildings/ -		
Landscape		
8.0 Services & Utilities		
	and common passage also relies on artificial sources.	
	t in staircase and toilets also relies on artificial means.	
8.3 Electricity BEST.	till stall case and tollets also relies on artificial means.	
	war linea	
8.5 Drainage (Plumbing & Sanitation) MCGM Connected to Municipal set		
8.6 Fire Precaution Fire extinguishers only – no integra	ated fire fighting system.	
8.7 Other (HVAC/BMS/Security Systems) window and spilt unit A.C 's.		
	Condition	
9.1 Plinth Fair along arcade front, neglected a	and damaged along the side abutting adjoining building.	
	and damaged along the side abutting adjoining building.	
9.3 Floor Fair except minor damage and dec		
	ged in need of repairs and maintenance.	
9.5 Openings Fair along the front façade; damage	ed and neglected on the sides.	
9.6 Roofing Indeterminable		
	neglected on external side facades and common areas	
internally.		
9.8 Services Fair		
9.9 Out Buildings -		
9.10 Overall Conditions Fair along front side only.	Maintenance level: Fair along front otherwise	
	Low.	
1		
10.0 Transformation	n.	
Transformation Form Fourth floor seems to be an addition		
	n.	
Form Fourth floor seems to be an addition	n.	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition floor s	n.	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition floor s	n.	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes - DP Remarks/ Perceived Threats	n.	
Form Fourth floor seems to be an additio Structure Fourth floor seems to be an additio Articulation & Finishes -	n.	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes - 11.0 DP Remarks/ Perceived Threats		
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes - 11.0 DP Remarks/ Perceived Threats Building forms part of C1 zone 12.0 Additional Notes/ References/ Do		
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes - 11.0 DP Remarks/ Perceived Threats Building forms part of C1 zone 12.0 Additional Notes/ References/ Do	ocuments available	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes - 11.0 DP Remarks/ Perceived Threats Building forms part of C1 zone 12.0 Additional Notes/ References/ Do Additional Notes: The magnificent stone frontage of the structure of the s	ocuments available the buildings around Horniman circle were designed by	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes - 11.0 DP Remarks/ Perceived Threats Building forms part of C1 zone 12.0 Additional Notes/ References/ Do Additional Notes: The magnificent stone frontage of the structure of the s	ocuments available the buildings around Horniman circle were designed by Elphinstone Land & Press company which was	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes - 11.0 DP Remarks/ Perceived Threats Building forms part of C1 zone 12.0 Additional Notes/ References/ Down Additional Notes: The magnificent stone frontage of the established to undertake reclamatic	ocuments available the buildings around Horniman circle were designed by Elphinstone Land & Press company which was	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes 11.0 DP Remarks/ Perceived Threats Building forms part of C1 zone 12.0 Additional Notes/ References/ Down Additional Notes: The magnificent stone frontage of the established to undertake reclamation References:	ocuments available the buildings around Horniman circle were designed by Elphinstone Land & Press company which was on projects in the City.	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes 11.0 DP Remarks/ Perceived Threats Building forms part of C1 zone 12.0 Additional Notes/ References/ Down Additional Notes: The magnificent stone frontage of the established to undertake reclamation References:	ocuments available the buildings around Horniman circle were designed by Elphinstone Land & Press company which was	
Form Fourth floor seems to be an addition Structure Fourth floor seems to be an addition Articulation & Finishes 11.0 DP Remarks/ Perceived Threats Building forms part of C1 zone 12.0 Additional Notes/ References/ Down Additional Notes: The magnificent stone frontage of the established to undertake reclamation References: INTACH (1990) Preliminary unedite Structures listed for Conservation.	the buildings around Horniman circle were designed by Elphinstone Land & Press company which was on projects in the City. ed listing of Unprotected Monuments, Buildings and	
Form Structure Fourth floor seems to be an additio Articulation & Finishes	the buildings around Horniman circle were designed by Elphinstone Land & Press company which was on projects in the City. ed listing of Unprotected Monuments, Buildings and OSTRAND REINHOLD Visual dictionary of Architecture,	
Form Structure Fourth floor seems to be an addition Articulation & Finishes	the buildings around Horniman circle were designed by Elphinstone Land & Press company which was on projects in the City. ed listing of Unprotected Monuments, Buildings and OSTRAND REINHOLD Visual dictionary of Architecture, Publishing Inc.	
Form Structure Fourth floor seems to be an addition Articulation & Finishes	the buildings around Horniman circle were designed by Elphinstone Land & Press company which was on projects in the City. ed listing of Unprotected Monuments, Buildings and OSTRAND REINHOLD Visual dictionary of Architecture,	



Curved building façade with arched arcade on ground floor, arched openings with columns, step balconies, floor bands




Arched opening with decorative keystone, ionic columns, dentil band, glazed wooden shutters with fanlight



Arched arcade with human face motif keystone, floor band, frieze band below window etc



Detail of the human face keystone motif



long Kong	g and Shanghai Bank (Middle East Bank Bu	ilding) 142(b	
7.0		Construction	
7.1	Plinth	Medium height stone plinth with edging done for plinth protection.	
7.2	Walls	Composite load bearing wall with external stone fascia and internally plastered and painted	
7.3	Floor	Jack arch flooring and RCC slab.	
7.4	Stairs	Two staircases are present one main staircase and other service staircase. Main staircase is doglegged RCC staircase with wooden tread, baluster and handrail. The service staircase is doglegged in cast iron.	
7.5	Openings	All doors are rectangular openings with single or double leaf wooden shutter but bank ha glass door. Windows are a combination of segmental and semicircular and flat arched on first, secon and third respectively with ventilators above.	
		All shutters are glazed in wooden framework.	
7.6	Roofing	Flat terrace with staircase block and water tanks.	
7.7	Articulation	Cornice band, pediment, cartouche, floral motif, guilloche band, medallion, scroll keystone and decorative spandrel.	
7.8	Finishes	External walls are in stone with horizontal rusticated masonry, plastered and painted. Internal walls are plastered and painted. Varied tiling from premise to premise.	
7.9	Interiors (Movable & Immovable)	Movable	
		Immovable	
7.10	Compound/ Fence/ Gate	Building edges entire plot.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Unbuilt space at side and rear.	
8.0		Services & Utilities	
8.1	Lighting	Inadequate natural light supplemented by electric light fixtures.	
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Fire alarms system and some detectors.	
8.7	Other (HVAC/BMS/Security Systems)	Surveillance cameras, swipe card and window and central AC units.	
9.0		Condition	
9.1	Plinth	Fair - dust accumulation, stone painted and cement pointing.	
9.2	Walls	Fair - Blackened stone surface in some areas, seepage, dust accumulation and plan	
9.3		growth.	
	Floor	Indeterminable in HSBC portion due to false ceiling but in second and third the floor is well maintained.	
9.4	Stairs	Fair – anti slip edge missing, broken and cracked tread, dust accumulation while service staircase needs anti-corrosive paint.	
9.5	Openings	Poor - addition of grills, chajjas, window AC units, window frames changed, closed, pattern changed, ventilators closed, plant growth and broken windowpanes.	
9.6	Roofing	Fair – but staircase block not maintained.	
9.7	Articulation & Finishes	Fair – broken comice band, dust accumulation and blackening of articulation. Internal plaster and paint peeling off at certain places. External wall painted at certain areas, dust accumulation, plant growth, cracks, seepage and plaster and paint peeling off. Tiling is being changed due to reconstruction of floors.	
9.8	Services	Indeterminable.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair. Maintenance level: Poor.	
10.0		Transformation	
	Form	-	
	Structure	-	
	Articulation & Finishes	Hoarding blocking articulation and finishes changed due to individual premise holders.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		References:	

INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay :

Eminence Designs Pvt. Ltd.

RAHUL MEHRÖTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

SHARADA DWIVEDI and RAHUL MEHROŤRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.

Restoring A Banking District – Horniman Circle Association, (1999) Urban Design Research Institute.



Front façade with arched arcade on ground floor, arched openings above with columns, pediment above with decorative tympanum



Window arched opening with decorative keystone, spandrel, curved projecting balcony with stone balustrade



Window articulation detail with decorative column capital, frieze band, arched opening keystone



Arcade with arched openings, columns on high base with rusticated joints in stone



Side façade with arched openings between vertical columns with rusticated joints



Pediment detail with highly decorative tympanum

Dena Bank bi	uilding	142(c			
Dena Bank bi	unung	142(c) Common Ref No: 142(c)			
		Common Rei No. 142(c) Card No: 200			
	and the state of the	Ward (Part): A (Part II)			
la T					
		CS No: 373, 376, 377(Fort division) Plot Area: 1214.24 sq m.			
The La					
1	1 10	B U Area: -			
1	111111111111111111111111111111111111111	Date: 23/03/2005			
		Recorded by: Sonal Modak			
		Reviewed by:			
	THE RELEASE ASSOCIATION OF THE PERSON OF THE	Reviewed by: Int: Sonal Modak, Abhay Patil Integral photography nemission depied			
	A A A A A A A A A A A A A A A A A A A	Internal photography permission denied			
TANK A TANK		Ext: Sonal Modak, Abhay Patil Photo Ref: 142(c) Dena Bank.			
AND STREET		Photo Ref: 142(c)_Dena Bank.			
THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TW					
		Location Plan			
1.0		Denomination Location Flam			
1.1	Name of Premises	Dena Bank building			
1.2	Earlier Name	Dena Bank building			
1.3	Built in:				
1.0	Duilt III.	1900's Extension - Date			
	+	Date			
2.0	-	A			
2.0	Main	Access			
2.1	Main	Horniman Circle – Pedestrian			
2.2	Subsidiary	•			
3.0		Ownership pattern			
3.1	Present	Private - Bank			
3.2	Past	Private - Bank			
3.3	Status	Owner, Tenant			
4.0		Use			
4.1	Present	Institutional – Bank			
4.2	Past	Institutional – Bank			
4.3	Usage	Daily			
		• ,			
5.0		Significance & Value Classification			
5.1	Townscape (Manmade)	It forms a part of several curvilinear buildings around Horniman Circle facing the central			
•		garden having architectural unity by sharing a particular style, façade and height.			
		It was the first planned business district of Bombay.			
		Main access is from the southern façade through a curvilinear arcade.			
5.2	Architectural Description	Planning			
0.2		The building has a curvilinear plan with verandahs facing Horniman Circle garden on the			
		south side. A covered arcade at ground level, which provides protection from weather.			
		Dena Bank occupies two similar buildings adjacent to each other, which are connected			
		internally at upper floor levels.			
		The verandahs along the concave façade are also enclosed keeping intact the external			
		appearance of the building.			
		The internal floor layout varies as per occupants' needs.			
		Features			
		Arcaded verandahs with semi-circular openings.			
		The keystone heads with alternate men and women at each floor level.			
		Tapering circular engaged columns with square pedestal and ionic capitals. The masonary			
		below impost level is rusticated. Cornice bands at each floor level. Finial like features above			
		parapet on corners.			
		Style			
		Influence of Neo-classical architectural style in architecture.			
•	Intrinsic	•			
5.3		A(arc), B(per), B(des), B(uu), E, F, G(grp), I(sce) Recommended grade II A			
5.3 5.4	Value Classification				
5.3 5.4	Value Classification	7 (d. 0), 5 (b. 1), 5 (d. 0), 5 (d. 0), 2, 1, 3 (g. p), 1(0.00) 1 (0.00)			
5.4	Value Classification				
5.4 6.0		Topography			
5.4	Value Classification Floors				
6.0 6.1		Topography G + 3			
5.4 6.0 6.1 7.0	Floors	Topography G+3 Construction			
5.4 6.0 6.1 7.0 7.1	Floors Plinth	Topography G + 3 Construction Medium plinth in grey stone ashlar masonry.			
5.4 6.0 6.1 7.0 7.1 7.2	Floors Plinth Walls	Topography G + 3 Construction Medium plinth in grey stone ashlar masonry. Thick load bearing external walls. Internal non-load bearing brick masonary.			
5.4 6.0 6.1 7.0 7.1	Floors Plinth	Topography G + 3 Construction Medium plinth in grey stone ashlar masonry.			

Dena Bank		142(c		
7.5	Openings	Arched door/window openings with glazed ventilators and shutters. Stone balustrades at lower level.		
7.6	Roofing	Front wing timber sloping roof and rear wing with RCC flat slab roof with terrace above.		
7.7	Articulation	Keystone heads with alternate men and women faces. Ionic column capitals.		
7.8	Finishes	External wall exposed buff basalt ashlar masonary. Walls internally plastered and painted. Flooring finish changed as per occupant.		
7.9	Interiors (Movable & Immovable)	Movable -		
		Immovable -		
7.10	Compound/ Fence/ Gate	Building sits on entire plot. A narrow open space on western side, another building abuts on northern side.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Neglected narrow space on western side.		
8.0		Services & Utilities		
8.1	Lighting	Inadequate daylight in some parts of the building supplemented by artificial lighting.		
8.2	Ventilation	Inadequate ventilation in some parts of the building supplemented by forced ventilating systems.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	No Traces.		
8.7	Other (HVAC/BMS/Security Systems)	Window and split AC units have been installed wherever necessary.		
9.0		Condition		
9.1	Plinth	Fair – Blackening of stone, careless re-pointing done. Broken in some parts, Minor cracks observed, plant growth.		
9.2	Walls	Fair – Blackening of stone, dampness due to leakages, Internal walls in dilapidated state though repair works going on. Plant growth.		
9.3	Floor	Fair – In dilapidated state. Repairs under way.		
9.4	Stairs	Fair		
9.5	Openings	Fair – Few of the external openings have been closed. Shutters have been replaced, broken glazing panels in some places.		
9.6	Roofing	Fair – Some of the wooden roofing members are deteriorating, replaced by MS sections. Internally could not be seen.		
9.7	Articulation & Finishes	Fair – Plant growth, Minor cracks.		
9.8	Services	Poor – Broken pipes, leakages, cleanliness not maintained. Unplanned electrical wiring.		
9.9	Out Buildings	-		
9.10	Overall Conditions	Fair Maintenance level Fair		
10.0		Transformation		
	Form	-		
	Structure	Floors are supported with additional steel sections.		
	Articulation & Finishes	-		
11.0		DP Remarks/ Perceived Threats		
		Building forms part of C1 Zone.		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes:		
		- -		
		References:		
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.		
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay :		
		Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct		
		in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.		
	· · · · · · · · · · · · · · · · · · ·			
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd. Restoring A Banking District – Horniman Circle Association, (1999) Urban Design Research		



Curved façade along Horniman circle with arched arcade on ground floor



Side view with arched openings, columns with rusticated joints in stone



Brackets supporting projecting bay



Keystone detail with human face motif 1



Arched arcade with human face keystone, arched openings, columns, bands, projecting balconies



lonic column capital detail with dentil band above



Keystone detail with decorative motif 4



Keystone detail with human face motif 2

Rharat Ins	surance building	143		
indiat IIIS M	Taranto bununing	Common Ref No: 143		
	4	Card No: 201		
		Ward (Part): A (Part II)		
		CS No: 235 (Fort division)		
		Plot Area: 414.726 sq m.		
		B U Area: - Date: 19/01/2005. Recorded by: Sonal Modak Pevigued by:		
		Date: 19/01/2005.		
3		Recorded by: Sonal Modak		
3		Reviewed by:		
E C		Int: Sonal Modak, Zankhana Prajapati		
		Internal photography permission denied Ext: Sonal Modak, Zankhana Prajapati		
		Photo Ref: 143_Bharat Insurance Building.		
8		CENTON		
		Location Plan		
1.0		Denomination		
1.1	Name of Premises	Bharat Insurance building		
1.2	Earlier Name	Bharat Insurance building		
1.3	Built in:	1900's Extension Date: In 1930's fourth floor was added on rear wing		
		, , , , , , , , , , , , , , , ,		
2.0		Access		
	Main			
2.1	Main	Horniman Circle – Pedestrian.		
2.2	Subsidiary	-		
3.0		Ownership pattern		
3.1	Present	Bharat Insurance Building Owners' Association – Owners (6 co-owners).		
3.2	Past	Dalmiya Bank.		
3.3	Status	Owner, Tenant.		
0.0	Cidido	O mior, romand		
4.0		Hee		
	December	Use Osmanish Office		
4.1	Present	Commercial – Offices.		
4.2	Past	Institutional – Bank.		
4.3	Usage	Daily.		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)	It forms a part of the crescent of curvilinear buildings around Horniman Circle facing the		
0	central garden. The building is one of the many united by similar architectural for			
		particular style, façade and heights. An arcade runs at its base that is also continuous all		
		around the crescent.		
		It was the first planned business district of Bombay.		
		Main access is from the southern façade through a curvilinear arcade.		
5.0	A 13 (15) (Front façade is a curved southern façade.		
5.2	Architectural Description	Planning		
		The building has a curvilinear plan with verandahs facing Horniman Circle garden on the		
		southern side. A covered arcade runs the length of the building at ground level, providing		
		protection from weather.		
		The internal layout of the building was totally changed while repair works were undertaken		
		after one of the walls collapsed. The verandahs along the concave façade were also		
		enclosed keeping intact the external appearance of the building.		
		Features		
		Arcaded verandahs with semi-circular openings.		
		The keystone heads with alternate men and women at each floor level.		
		Tapering circular engaged columns with square pedestal and ionic capitals. The masonry		
		below impost level is rusticated. Cornice bands at each floor level. Finial like features above		
		parapet on corners.		
		Style		
l	1			
		Influence of the Neo-Classical style in its features.		
F 2	1.122.			
5.3	Intrinsic	•		
5.3 5.4	Intrinsic Value Classification	- A(arc), B(per), B(des), B(uu), E, F, G(grp), I(sce) Recommended grade II A		
		- A(arc), B(per), B(des), B(uu), E, F, G(grp), I(sce) Recommended grade II A		
		- A(arc), B(per), B(des), B(uu), E, F, G(grp), I(sce) Recommended grade II A Topography		
5.4		, , , , , , , , , , , , , , , , , , ,		
5.4 6.0	Value Classification	Topography		
6.0 6.1	Value Classification	Topography G + 3 front wing, G + 4 rear wing		
6.0 6.1 7.0	Value Classification Floors	Topography G + 3 front wing, G + 4 rear wing Construction		
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	Topography G + 3 front wing, G + 4 rear wing Construction Medium plinth in grey stone ashlar masonry.		
6.0 6.1 7.0 7.1 7.2	Value Classification Floors Plinth Walls	Topography G + 3 front wing, G + 4 rear wing Construction Medium plinth in grey stone ashlar masonry. Thick load bearing external walls.		
5.4 6.0 6.1 7.0 7.1	Value Classification Floors Plinth	Topography G + 3 front wing, G + 4 rear wing Construction Medium plinth in grey stone ashlar masonry.		

	urance building			143		
7.5	Openings	Arched door/window openings with glazed ventilators and shutters. Stone balustrades a lower level.				
7.6	Roofing	Front wing - timber sloping roof, Re	ear wing - RCC flat	slab roof with terrace above.		
7.7	Articulation	Keystone heads with alternate mer				
7.8	Finishes	External wall exposed buff basalt ashlar masonary. Walls internally plastered and painted.				
7.9	Interiors (Movable & Immovable)	Flooring finish changed as per occupant. Movable				
		- Immovable				
7.10	Compound/ Fence/ Gate	Building sits on entire plot.				
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	A narrow open space on western side, another building abuts on northern side. Neglected narrow space on western side.				
8.0		Services & Utilities				
8.1	Lighting	Inadequate daylight in some parts	of the building cupp	lomonted by artificial lighting		
8.2	Ventilation			supplemented by forced ventilating		
8.3	Electricity	BEST				
8.4	Water Supply	MCGM				
8.5	Drainage (Plumbing & Sanitation)	MCGM				
8.6	Fire Precaution	No Traces.				
8.7	Other (HVAC/BMS/Security Systems)	Window and split AC units have be	en installed wherev	er necessary.		
9.0		Condition				
9.1	Plinth	Poor – Blackening of stone, Inappropriate re-pointing done. Broken in some parts, Min				
		cracks observed, plant growth.				
9.2	Walls	Poor – Blackening of stone, dampness due to leakages, Internal walls in dilapidated state though repair works going on. Plant growth.				
9.3	Floor	Poor - In dilapidated state. Repairs				
9.4	Stairs	Poor – Timber main staircase in dilapidated state. New RCC staircase has beer constructed. Repairs underway.				
9.5	Openings	Fair – Few of the external openings have been closed. Shutters have been replaced broken glazing panels in some places.				
9.6	Roofing	Fair – Some of the wooden roofing members are deteriorating, replaced by MS sections.				
9.7	Articulation & Finishes	Fair - Plant growth, Minor cracks.		<u> </u>		
9.8	Services	Poor – Broken pipes, leakages, cleanliness not maintained. Unplanned electrical wiring.				
9.9	Out Buildings	-				
9.10	Overall Conditions	Poor	Maintenance level:	Poor. Repair work underway.		
10.0		Transformation				
1010	Form	Lift well added on western side temporarily.				
	Structure	Temporary steel staircase added of				
		Floors are supported with additional steel sections.				
	Articulation & Finishes	-				
11.0		DP Remarks/ Perceived Threats				
11.0		Building forms part of C1 zone.				
12.0		Additional Notes/ References/ Documents available Additional Notes:				
		Repair work underway at present. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay:				
		Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay: Eminence Designs Pvt. Ltd.				
		Restoring A Banking District – Horniman Circle Association, (1999) Urban Design Research Institute.				

Bharat Insurance building 143



Curved façade along Horniman circle, arched arcade, arched openings above with columns with high base



Side Elevation with incongruous additions to the facade



Arched arcade on columns with rusticated joints, ceiling with supporting members



Side view with arched openings, vertical columns with rusticated joints in stone



Arched window with columns on high base, frieze band, wooden shutters, fanlight etc



Human face motif arch keystone

Flora Four	ntain	144
		Common Ref No: 144
	2	Card No: 202
		Ward (Part): A (Part III)
		CS No: 427 (Fort division)
		Plot Area: 266.72 sq m.
Ã.		B U Area: -
		Date: 05/11/2004
Ī		Recorded by: Prachi Merchant
		Recorded by Practil Merchant
7		Reviewed by: Int: NA Ext: Prachi Merchant Sonal Modak
II.		Int: NA
· ·		2/41/10011111010111111111111111111111111
		Photo Ref: 144_Flora fountain.
	Charles	
		(CORRECTION AND CO.
		STREET
		Location Plan
1.0	News (Deceles	Denomination Start Secretaria
1.1	Name of Premises	Flora Fountain
1.2	Earlier Name	Flora Fountain
1.3	Built in:	1867 Extension Date: -
2.0		Access
2.1	Main	Hutatma Chowk (Junction of Mahatma Gandhi Road, Chhatrapati Shivaji Marg, Dr.
		Dadabhoy Nowroji Road, Veer Nariman Road)
2.2	Subsidiary	-
3.0		Ownership pattern
3.1	Present	Municipal Corporation of Greater Mumbai
3.2	Past	Bombay Municipal Corporation
3.3	Status	Owner
0.0	Cidido	- Carlot
4.0		Use
4.1	Present	Fountain, Civic square.
4.2	Past	Fountain
4.3		Daily
4.3	Usage	Daily
5.0		Significance & Value Classification
5.1	Tournagene (Manmada)	The Fountain is located at an important urban node at the intersection of the two main axe
J. I	Townscape (Manmade)	of the city, the north-south axis from Gateway Of India to Victoria Terminus and the eas
		west axes from the Town Hall to the sea.
		The fountain is surrounded by the Dadabhai Nowroji Road precinct on the north, bankin
5.2	Architectural Description	precinct in the east and south and gothic and art deco buildings on the west.
5.2	Architectural Description	Planning The force of 'Floor' is accordanted in white Dodland stone and is alread in four levels and
		The figure of 'Flora' is constructed in white Portland stone and is planned in four levels an
		has setbacks in a receding manner.
		The base level has a large circular shaped water basin with a stone parapet around housing the water collection and drainage system.
		In the center of the pool, the fountain stands on cylindrical multi pillars to support the clove
		shaped fountain base consisting of semicircular arched openings and projecting alcoves of
		pedestals in each comer. Each alcove consists of a statue of a lady in a sitting position
		intricately carved in stone. The base band of this level consists of gargoyles.
		The third level consists of a square base with four projecting pentagonal bowls with
		decorative brackets, bands and gargoyles.
		The main statue is surmounted on a cylindrical pedestal above the third level with carve
		dolphins at its base opening into smaller bowls.
		Features
		The fountain is highly ornamental with features such as fish and lion head spouts a
		gargoyles, floral band friezes at every level, semicircular arched openings with decorative
		intrados, cornices, shell shaped bowls with intricately carved brackets, statues of intricate
		carved Greek goddesses along with flora and fauna and the main fountain on square
		pedestal with floral pattern carved on it.
		Style
		The Fountain derives influences from the Neo-classical style of Architecture.
5.3	Intrinsic	The fountain was placed in 1869 at the important intersection of several major streets
		honour Sir Bartle Frere, Governor of Bombay and the creator of the newly laid out city after
		the demolition of the Fort.
5.4	Value Classification	A(arc), A(his), B(des), B(uu), C(seh), F, I (sce) Recommended grade I
<u> </u>		

Flora Fountain		144	
6.0		Topography	
6.1	Floors	•	
7.0		Construction	
7.1	Plinth	Low plinth with cylindrical pillars.	
7.2	Walls	•	
7.3	Floor	•	
7.4	Stairs	-	
7.5	Openings	•	
7.6	Roofing		
7.7	Articulation	Bands, projecting alcoves with statues, projecting shell shaped bowls, main statue on pedestal, decorative friezes.	
7.8	Finishes	All surfaces are painted on Portland stone fountain.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable A marble plaque is installed in the west side base, which reads "The fountain was constructed by the Esplanade fee fund committee at a total cost of Rs 47,000 with the help of the donation of Rs. 20,500 by Seth Cursetjee Parekh and was opened in 1869".	
7.10	Compound/ Fence/ Gate	Oblong shaped MS fence around the fountain and landscaped area. Small pedestrian gate in the north corner.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Lawn areas and tree/ shrub islands, hedges are planned in the oblong area. The outer parts are paved. Lampposts are placed at regular intervals. The Martyrs Memorial and the parking lot are located on either side of the fountain.	
0.0		Complete 0 Hallaine	
8.0	12-12-	Services & Utilities	
8.1	Lighting	-	
8.2	Ventilation	- DECT	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM MCGM	
8.5	Drainage (Plumbing & Sanitation) Fire Precaution	MCGM	
8.6 8.7			
0.7	Other (HVAC/BMS/Security Systems)	•	
0.0		Condition	
9.0 9.1	Plinth	All the parts of the fountain are insensitively painted with oil based paint. Organic growth	
0.0	NAC III	with algae, lichens is visible at many sections.	
9.2	Walls	-	
9.3	Floor	-	
9.4	Stairs	•	
9.5	Openings	•	
9.6	Roofing		
9.7	Articulation & Finishes	Paint applied on all parts, which makes it difficult for identifying the original material and finish. The features are chipped in many places.	
9.8	Services	-	
9.9	Out Buildings	-	
9.10	Overall Conditions	Poor Maintenance level Poor	
10.0	Form	Transformation The importance of the prime location of the fountain is compromised by the installation of the Martins Marginal in the parts and the partial let at the court.	
	Structure	the Martyrs Memorial in the north, and the parking lot at the south.	
	Articulation & Finishes	The fountain has been insensitively painted	
44.5			
11.0		DP Remarks/ Perceived Threats	
		Structure forms part of C1 zone	
42.0		Additional Nation/ Deferences/ Degraments	
12.0		Additional Notes/ References/ Documents available Additional Notes: Flora Fountain, originally set in its own small round garden was designed by R Norman Shaw and sculpted in fine Portland stone by James Forsythe. The Agri-Horticultural Society commissioned the fountain at a cost of Rs 27,000 (then £2,700), to be placed in the center of the Victoria Gardens (now Jijamata Udyan) in Byculla. The Society went insolvent during the stock market crash of 1865 and was unable to meet the enhanced estimated total cost of Rs 90,000 (£9,000). Arthur Crawford, President of the Society, obtained the funding from the Esplanade Fee-Fund Committee of which he was a Member. The fountain was placed in 1869 at the important intersection of several major streets to honour Sir Bartle Frere, Governor of Bombay and the creator of the newly laid out city after the demolition of the	

Flora Fountain 144

Fort. One of the three main gates to the Fort, known as Church Gate after St Thomas' Church, once stood on this site. The fountain, which once formed a striking central feature in the streetscape, depicts Flora, the Roman goddess of the flowering of plants with her attendants.

References:

INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) *The Cities Within*, Bombay : Eminence Designs Pvt. Ltd.

RAHUL MEHRÖTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.

ABHA NARAIN LAMBAH Through the Looking Glass – The Grade I Heritage of Mumbai, Mumbai : Urban Design Research Institute, Jasubhai Media and Super Book House.



The main statue surmounted on a cylindrical pedestal above the third level with carved dolphins at its base opening into smaller bowls.



Lowermost basin level on columns



Statues of Greek goddesses in four corners on high base, arched opening, frieze band



Detail of the projecting bowls with highly decorative frieze bands, animal spots, tapering floral and ribbed motif

Flora Fountain 144



Detail of the seated statue of Greek goddess with floral motifs




Seated statue detail with intricate carvings



Marble tablet with year of construction, cost details etc



Animal motif spouts at the base level



<u>inden Ho</u>	•	T45	
7.2	Walls	External walls are thick load bearing walls. Internal are non-load bearing brick walls.	
7.3	Floor	Timber floors with large wooden beams, rafters and wooden floorboards.	
7.4	Stairs	Wide timber doglegged staircase with wooden balustrade and handrail.	
7.5	Openings	The openings have Tabernacle frame with simple triangular pediment at first floor and	
		segmental arch pediment at second floor level.	
		All window openings have wooden frame glazed double shutters.	
7.6	Roofing	Indeterminable.	
7.7	Articulation	-	
7.8	Finishes	Walls are plastered and painted externally as well as internally.	
7.9	Interiors (Movable & Immovable)	Movable Old tables, chairs, shelves etc. Immovable Fixed wooden partitions in a flat at topmost floor.	
7.10	Compound/ Fence/ Gate	Building occupies entire plot area.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	There is a narrow alley on south side of building.	
9.0		Sarvinas & Hitilitias	
8.0	Lighting	Services & Utilities	
8.1	Lighting	Adequate light through skylight, balconies, terraces and openings supplemented by artificial light.	
8.2	Ventilation	Adequate ventilation through balconies, terraces and openings supplemented by artificial ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	No Traces.	
8.7	Other (HVAC/BMS/Security Systems)	Window AC units have been installed.	
9.0		Condition	
9.1	Plinth	Fair	
9.2	Walls	Fair – Minor cracks observed.	
9.3	Floor	Good - Wooden members of flooring are replaced with MS sections on lower floors in a pai of the building.	
9.4	Stairs	Good – Well maintained.	
9.5	Openings	Fair – Many of the door/window shutters are replaced.	
9.6	Roofing	Indeterminable.	
9.7	Articulation & Finishes	Fair	
9.8	Services	Fair – no evident damages seen.	
9.9	Out Buildings	1 dil – no evident damages seen.	
9.10	Out Buildings Overall Conditions	Fair Maintenance level Fair	
3.10	Overall Collditions	i dii ividii iteriari Ce rever 1 dii	
10.0		Turneformetion	
10.0	Form	Transformation	
	Form	The building has been recently received	
	Structure	The building has been recently repaired.	
	Articulation & Finishes	-	
44.0		DD Demonto / Demonto d Threate	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of Residential zone.	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: - References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay: Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. Creating A Tourist District – The Gateway of India Precinct, A proposal for upgrading and managing the area, (2004) Urban Design Research Institute	

Linden House 145




Corner view of the building with arched arcade on the ground floor with frieze band, rectangular openings with pediment above



Front façade with openings with triangular and arched pediments, floor bands, columns with exposed stone



Window detail with arched pediment, floor band etc



Bowen Mem	orial Church	148	
7.4	Stairs	Two staircases. The main wooden stair with wooden balusters and railing.	
		The staircase to the rear is a later addition cast in RCC.	
7.5	Openings	The windows are generally set in pointed or semi circular arches with openable lower portions that are glazed with two shutters, while the upper portions are horizontally hinged	
		openable ventilators. In some places, as in the verandahs the windows have wooden louvers that form the	
		external surface. In many places, as above the main window in the prayer hall circular openings with fixed glass has been used.	
7.0	D 5	Stained glass is laid in pointed arches that lie to the end of the prayer hall.	
7.6	Roofing	The steep sloping roof with a wooden substructure and Mangalore tile finishing in pyramida in shape.	
7.7	Articulation	Pitched roofs in Mangalore tile on a wooden structural system cover the rest of the building. The external surface of the building is articulated with many features like brackets for the	
1.1	Articulation	wooden balconies, stucco work forming cornices, etc.	
7.8	Finishes	Walls are plastered and painted internally as well as externally. Minton tile having different patterns can be seen in different parts of the building.	
7.9	Interiors (Movable & Immovable)	Ceramic tiles have also been used in many areas. Movable	
	(,	Large teak wood tables, chairs, partitions and cupboards can be seen in the interior of the building. Many of the original light fixtures also can be seen. Immovable	
7.10	Compound/ Fence/ Gate	_	
7.10	Curtilage/ Unbuilt space/ Out Buildings/	A pump house, toilets etc be seen in the paved courtyard to the rear.	
7.11	Landscape	A pump nouse, tollets etc be seen in the paved courtyard to the lear.	
8.0		Services & Utilities	
8.1	Lighting	Adequate light and ventilation in the building supplemented by light fixtures	
8.2	Ventilation	Adedquate natural ventilation through verandah, long windows and doors supplemented b artificial ventilation	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Air conditioning units can be seen in some parts of the building	
	Carrier Carrie		
9.0	D11 11	Condition	
9.1	Plinth	Fair - plant growth, surfaces weathering and seepage has been observed near the water pipes.	
9.2	Walls	Fair - cracks in the brickwork with many areas the plaster has peeled off.	
9.3	Floor	Fair	
9.4	Stairs	Fair - The plaster around the staircase is peeling off	
9.5	Openings	Fair - window ventilator glass have been replaced at certain places. Many broken window panes have been replaced insensitively and air conditioning units have blocked the openings	
9.6	Roofing	Poor - roof structure is in a deteriorating condition	
9.7	Articulation & Finishes	Poor	
9.8	Services	Fair - new electrical wires, plumbing pipes have caused considerable damage.	
9.9	Out Buildings	Fair	
9.10	Overall Conditions	Fair Maintenance level Poor	
10.0		Transformation	
	Form	A new wing added to the rear and side with a new staircase.	
	Structure	Floors have been supported with steel I sections in some areas for strengthening.	
	Articulation & Finishes	-	
11.0		DP Remarks/ Perceived Threats	
11.0		Building forms part of R zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: - References:	
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture	
		Division of International Thomson Publishing Inc. Eicher Goodearth Ltd. (2002) City Map – Mumbai, Mumbai.	

Bowen Memorial Church 146



Façade with arched band, round openings, projecting balcony supported on wooden brackets, frieze band



Window with arched band, floral motif etc





Window detail with bands, motifs.




Corner tower with steep sloping roof, pinnacles etc



in a neglected state



Detail of wooden brackets below balcony



Sardar Griha	1	147	
7.0		Construction	
7.0 7.1	Plinth	Construction Plinth height about 0.45 M dressed in grey basalt ashlars course.	
7.2	Walls	External Load bearing rubble masonry stonewalls and circular cast iron columns.	
7.3	Floor	Jack arch floor supported on steel sections, some areas have been replaced will Shahabad stone slabs supported on steel I-sections.	
7.4	Stairs	Steep single flight wooden stair, replaced with steel members on some floors due damage caused by accidental fire. Also very simple wooden baluster and handrail.	
7.5	Openings	High ground floor has semicircular arch openings above the rectangular shutter openings Verandas on upper floors are rectangular openings. Inner door window openings are bric arch with rectangular ventilator panels and wooden door window shutters.	
7.6	Roofing	Sloping Mangalore tile roof supported on wooden truss work. Rear side wing has flat ro terrace at third floor level.	
7.7	Articulation	Overhanging verandas supported on wooden brackets, projecting stone balconies wi ornamentally carved base. Stone pediment feature on top of corner bay openings.	
7.8	Finishes	Plastered and painted external and internal wall surfaces, decorative carved features in th façade openings and projecting balconies are dressed in buff basalt stone. Ordinary an varied floor finishes throughout the building.	
7.9	Interiors (Movable and Immovable)	Movable Tilak memorial on fourth floor has a marble bust, and many personal objects of Tilal including a turban, clothes, photographs, documents and certificates. Immovable -	
7.10	Compound/ Fence/ Gate	Building itself forms the boundary with the front and rear roads, and abuts adjoining buildings on both sides. Iron collapsible gate at both front and rear entrances.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Internal chowk and passage space is encroached by small shops to the broader west side whereas the triangular east chowk is in a dilapidated state.	
0.0		On the state of th	
8.0	Lighting	Services and Utilities	
8.1 8.2	Lighting Ventilation	Inadequate natural light in some internal portions and staircase also relies on artificial light. Adequate natural ventilation also relies on A.C. units.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM Underground and overhead water tank	
8.5	Drainage (Plumbing and Sanitation)	Drainage connected to municipal sewers of MCGM	
8.6	Fire Precaution	Fire extinguishers only, no fire detection system.	
8.7	Other (HVAC/BMS/Security Systems)	Window and Split unit A.C.	
9.0		Condition	
9.1	Plinth	Poor – encroachments and interventions by commercial establishments, also poo internally due to seepage in the internal chowk.	
9.2	Walls	Poor – damage, seepage and plant growth observed. Affected by commercial interventions	
9.3	Floor	Poor – cracks and damaged floors, also corroding steel members in reconstructed veranda and passage areas.	
9.4	Stairs	Poor – wooden stair old and weak, reconstructed steel stair is rusting and neglected.	
9.5	Openings	Poor - Iron grills enclosing veranda openings, damaged and poorly finished door window shutters. Addition of <i>chajjas</i> , A.C units supported on iron brackets. Encroached balconies.	
9.6	Roofing	Fair except the neglected and vandalized terrace block.	
9.7	Articulation and Finishes	Poor - Blackened facades and damaged features due to signage's and commercial interventions. Also neglected internal finishes.	
9.8	Services	Poor – dilapidated internal chowk with open drains and filth around. Old, Messy and unplanned electrical lines in lobbies and passages. Also neglected plumbing services.	
9.9	Out Buildings	- I Maistern and London	
9.10	Overall Conditions	Poor Maintenance level: poor	
10.0		Transformation	
	Form	•	
	Structure	The repair board has reconstructed large portion of passages, verandas and staircase in ar incongruous and unsatisfactory manner.	
	Articulation and Finishes	Various encroachments, shop fronts and signages have spoiled façade integrity and damaged decorative features on front and rear facades.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone.	
12.0		Additional Notes/ References/ Documents available Additional Notes: Building has been interconnected to the adjoining west side Roopam building at ground and third floor levels being co-owned by Mr. Shah proprietor of Roopam. Haphazard encroachments of internal chowk and passage spaces by shops, stalls and small-scale vendors have caused the fast deterioration of the building space, structure and features. It is notified as a cessed building and has undergone repair works on various	

Sardar Griha 147

occasions under the Repair Board.

References:
INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structure's listed for Conservation.

FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.

SIR BANNISTER FLETCHER A History of Architecture, CBS publication and distributors.



Front façade with central and side higher bays, arched openings, carved railing etc



Arched openings in the verandahs. Carved railing, stain glass ventilator panels etc



Central bay with arched openings, columns with capitals, frieze bands, pediment above



Corner façade detail with projecting balcony on stone brackets, bands etc



Façade transformations completely covering original façade articulation



Wooden staircase with carved railing

Sardar Griha 147



Balcony projection with bracket, balustrade in a completely neglected state



Arched opening with floral motif keystone



Bracket detail



Internal courtyard



Marble bust of Lokmanya Bal Gangadhar Tilak




Tilak's headgear



Main entrance with information on 'Lokmanya Bal Gangadhar Tilak'



Encroachments over the façade covering the articulation



Kerrawalla	Mansion	148	
7.5	Openings	High ground floor has semicircular arch openings above the rectangular shutter openings	
		Verandahs on upper floors are rectangular openings. Inner door/ window openings are	
		brick arch with rectangular ventilator panels and wooden door window shutters.	
7.6	Roofing	Sloping Mangalore tile roof supported on wooden truss work. Rear side wing has flat roof	
		terrace at third floor level.	
7.7	Articulation	Pediment feature supported on decorative console above window openings, floor leve	
		cornice feature, overhanging verandas, double height colonnade with a large decorative	
		pediment forming the top floor. Steel bracket at the beam junction over circular steel columns display fine structural articulation.	
7.8	Finishes	Plaster painted external and internal wall surfaces, stucco relief arch, pediment and	
7.0	T WHISTIGG	decorative features. Wooden post and bracket members with iron railings in the verandas.	
		Varied floor finishes as modified by the individual occupant.	
7.9	Interiors (Movable & Immovable)	Movable	
		Fine old wooden furniture in the trust office and adjoining apartment	
		Immovable	
7.40	10 115 10 1		
7.10	Compound/ Fence/ Gate	Building occupies the entire plot. Collapsible gate and wooden door shutters at the	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	entrance.	
7.11	Landscape	-	
	Earldodape		
8.0		Services & Utilities	
8.1	Lighting	Inadequate natural light in some internal portions and staircase also relies on artificial light.	
8.2	Ventilation	Adequate natural ventilation also relies on A.C. units.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM, underground and overhead water tank	
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM	
8.6	Fire Precaution	Fire extinguishers only, no fire detection system.	
8.7	Other (HVAC/BMS/Security Systems)	Window and split unit A.C.	
9.0		Condition	
9.1	Plinth	Condition Fair except some interventions along the shop front.	
9.2	Walls	Fair except the neglected rear service side.	
9.3	Floor	Fair.	
9.4	Stairs	Fair except modifications like cladding carried out upto first floor.	
9.5	Openings	Fair except modifications along shop front.	
9.6	Roofing	Indeterminable due to locked top floor.	
9.7	Articulation & Finishes	Fair except certain modifications carried out to the interiors obscuring circular steel	
		columns.	
9.8	Services	Fair except minor seepage due to leaking plumbing lines.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Fair Maintenance level: Fair	
40.0		Turneforms of our	
10.0	Form	Transformation	
	a		
	Structure Articulation & Finishes	Shop fronts and signages have marred façade integrity at ground floor, also damaging arch	
	Articulation & Fillishes	and decorative features.	
11.0		DP Remarks/ Perceived Threats	
		Building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		- Petermana	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
		Structures listed for Conservation.	
		SIR BANNISTER FLETCHER A History of Architecture, CBS publication and distributors.	
		On the state of the content of this top you and meeting, Obe publication and distributions.	

Kerrawalla Mansion 148



Front façade with side bays with pediment, central floors with projecting balconies



Cast iron column capital detail



Projecting balconies with supporting brackets



Step balconies with pediment, frieze bands, floral motifs, railing etc



Entrance with pediment above, frieze band etc




Side bay pediment with carved motifs, bands etc



Balcony opening with pediment above, cartouche motif, rusticated joints, carved railing, floor bands etc



Wooden staircase with carved railing



Court of Smal	l Causes	149	
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(per), B(des), B(uu), F Recommended grade: II A	
6.0		Topography	
6.1	Floors	G + 4 floors.	
7.0		Construction	
7.1	Plinth	Low plinth of height of about 0.3 m. dressed in grey basalt stone.	
7.2	Walls	Load bearing rubble stone masonry walls.	
7.3	Floor	Reinforced concrete slab with heavy steel girders for large spans and concrete encased steel I-section beams.	
7.4	Stairs	Pair of C-shaped basalt stone stairs with lift shaft flanking both sides of veranda in the central wing.	
7.5	Openings	Semicircular, segmental and rectangular arch openings in verandas. Wooden framed glazed panel folding door shutters in wide veranda openings.	
7.6	Roofing	Steep sloping Mangalore tile roof supported on sleek steel truss members.	
7.7	Articulation	Segmental arch porch surmounted by a dome, projecting balcony supported on brackets at first floor, rusticated semicircular arch openings on first floor. Relief panel within architrave opening and in raised corner bay.	
7.8	Finishes	Grey stone dressed low ground floor, yellow stone dressed upper floors. Plain plaster paint finish internal wall finishes. Varied floor finishes.	
7.9	Interiors (Movable & Immovable)	Movable Old wooden benches and furniture, though inconsequential in terms of heritage value. Immovable Wood paneling in courtrooms behind judge's back wall and in barricades.	
7.10	Compound/ Fence/ Gate	-	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	G + 5 storied RCC annex added along the front side connected through floor level passages. Also ancillary barrack structures to the rear side.	
8.0		Services & Utilities	
8.1	Lighting	Adequate except staircases, also relies on artificial sources.	
8.2	Ventilation	Adequate except staircases, also relies on artificial means.	
8.3	Electricity	BEST.	
8.4	Water Supply	MCGM. Underground and Overhead Water storage tank.	
8.5	Drainage (Plumbing & Sanitation)	MCGM Connected to Municipal sewer lines.	
8.6	Fire Precaution	Few Fire extinguishers.	
8.7	Other (HVAC/BMS/Security Systems)	Window & Split unit A.C.	
9.0		Condition	
9.1	Plinth	Fair except neglected state.	
9.2	Walls	Fair except minor seepage in certain places.	
9.3	Floor	Fair except exposed steel observed at few places.	
9.4	Stairs	Fair except pan stains and neglected state.	
9.5	Openings	Fair except low maintenance.	
9.6	Roofing	Fair.	
9.7	Articulation & Finishes	Poor – blackening of stone dressed surfaces, also varied and poorly executed floor finishes.	
9.8	Services	Poor – old neglected services, also numerous insensitive interventions.	
9.9	Out Buildings	Fair – RCC annex except neglected state of barracks.	
9.10	Overall Conditions	Fair except finishes. Maintenance level: Low	
10.0		Transformation	
10.0	Form	G+5 RCC annex added along side the road front with connecting floor level passages. Also two lift shafts added along the east side.	
	Structure	Verandas encroached on the rear side.	
	Articulation & Finishes	Painting of stone dressed veranda wall surfaces.	
11.0		DP Remarks/ Perceived Threats	
11.0		Court and Police Station, building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes: George Wittet Architect designed the building in Renaissance Revival Style. References:	
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.	

Court of Small Causes

149

FRANCIS D.K. CHING and VAN NOSTRAND REINHOLD. Visual dictionary of Architecture.


FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.



Buff stone clad façade with side higher bays, arched openings, floor bands



Rusticated joints in stone with stone balustrade



Balcony with stone balustrade supported on brackets




Openings with arched and rectangular openings, double height columns, bands, motifs, jaliwork, balustrade etc



Arched porch with prominent keystone



Corner bay with floor bands, geometric motifs, window opening with bands, geometrical motifs



	High School		
7.1	Plinth	Low plinth constructed in rubble stone dressed with ashlar masonry.	
7.2	Walls	Rubble masonry load bearing walls dressed in rough black basalt ashlar masonry, fine dressed at the edges to openings.	
7.3	Floor	Originally, wooden floorboards and heavy rafters, supported on load bearing walls, long	
		extension wing has coffered slab in concrete,	
		Additional building also has reinforced concrete slab supported on RCC column-beam	
		structure.	
7.4	Stairs	Numerous stairs, narrow regular wooden staircases in each of the three wings, two small	
		spiral wooden stairs in each of the east and west wings, large concrete stair at the junction	
		leading into the long extension wing. Also a concrete stair in the additional wing at split level.	
7.5	Openings	Large pointed arched openings, small pointed and circular windows within, segmental and	
7.0	Opermige	flat arched openings at various locations on the side and rear facades.	
		Ornamental wooden tracery in the ventilator panel glazed and fixed. Door and window	
		shutters in wooden and glazed panel, louvered and double shutter at places.	
7.6	Roofing	Cement sheet sloping roof supported on timber trusses, replaced with flat slab over east	
		side wing, the additional building to the eastern end has concrete slab.	
7.7	Articulation	Timber column-bracket archway in the chapel hall on the first floor is ornamental as well as	
		structural.	
7.8	Finishes	Externally walls are dressed in black basalt ashlars masonry stone, brick faced and light	
		colored limestone in arch openings,	
		Internally walls are plastered and painted.	
7.9	Interiors (Movable & Immovable)	Door- window shutters are polished and painted. Moyable	
1.9	interiors (Movable & Intriovable)	Old piano	
		Immovable	
		Marble statues of Mother Mary, Jesus Christ, Father Xavier; Old Paintings	
7.10	Compound/ Fence/ Gate	Stone-faced gate pillars, low stone faced wall with iron grill above.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Large playground with old dense trees to the rear south side, also well maintained and	
	Landscape	landscaped open spaces around the building.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light through door-window openings supplemented by electric light	
0.0	Vantilation	fixtures.	
8.2	Ventilation	Adequate natural ventilation through door-window openings supplemented by electric fans and air-conditioning units in the computer and staff areas.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Fire extinguishers.	
8.7	Other (HVAC/BMS/Security Systems)	Window unit air-conditioners installed at various locations.	
9.0		Condition	
9.1	Plinth	Fair except plumbing interventions to the rear side have caused weakening of plinth.	
		Planter boxes have added load and caused water clogging damaging plinth course.	
9.2	Walls	Fair except damp patches in staircase walls.	
9.3	Floor	Fair - No major damage observed,	
9.4	Stairs	Fair except seepage in certain walls of staircase has been observed.	
9.5	Openings	Fair – well maintained.	
9.6	Roofing	Fair - except for waterproofing and maintenance. Repair work undertaken in the vertical tower roof and wooden members.	
9.7	Articulation & Finishes	Fair except floor finishing not uniform, weared out and neglected in common areas.	
9.8	Services	Fair – well maintained.	
9.9	Out Buildings	Fair	
9.10	Overall Conditions	Fair Maintenance level: Fair.	
		· · · · · · · · · · · · · · · · · · ·	
10.0		Transformation	
	Form	Additional wing at the eastern end does not reflect similar character as the original building	
		Sloping roof transformed into a flat slab in the east main wing.	
	Structure	-	
	Articulation & Finishes		
11.0		DP Remarks/ Perceived Threats	
		Secondary school, building forms part of R zone	
40.0		Additional Metael Defendance Decourse Community	
12.0		Additional Notes/ References/ Documents available Additional Notes:	

St. Xavier's High School

high with a statue of St. Xavier placed 90 feet above ground.

References:
INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.
FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.



Birds eye view



Courtside view



Lancet windows



CI Capital





Courtside elevation



Gable wall Marble Statue



Corbel





Entrance Pillars



Arched openings



CI bracket



Main Entrance



Floorboard pattern



Central bay articulation



CI column



Main staircase

Urban Design Research Institute

MMR- Heritage Conservation Society

Indian Mo	rcantile Mansion		151
illulali Wei	Caritile Marision	Common Ref No: 151	
		Card No: 209	Madam Cama Road Road Sharid shaga
The state of the s		Ward (Part): A (Part III)	
m			
	1000	CS No: Indeterminable	and the state of
		Plot Area: Indeterminable	Madam Cama Road Be Shanid Broad Shanid Road
o m		B U Area: -	Shall Road Shall Re
		Date: 18/01/2005	
	MAN MAN M	Recorded by: Sonal Modak	
		Reviewed by:	9.
		Int: Sonal Modak, Arun Wadhwa	The state of the s
O TRANSPORT		Internal photography permission denied	
	DOWNER	Ext: Sonal Modak, Arun Wadhwa	RECAL
ora rene		Photo Ref: 151 Indian Mercantile Mansion.	MAJESTIC
		FIDIO Rel. 131_ Ilidian Mercantile Mansion.	Location Plan
1.0		Denomination	
1.1	Name of Premises	Indian Mercantile Mansion	
1.2	Earlier Name	Waterloo Mansions	Text by Laving the
1.3	Built in:	1900's	Extension Date: Addition of New wing.
2.0	Maia	Access	annead Malabariae Obsaile and testing
2.1	Main	Nathalal Parekh Road – pedestrian, Shyama	prasad Muknerjee Chowk – pedestrian
2.2	Subsidiary	Madam Cama Road – pedestrian	
3.0		Ownership pattern	
3.1	Present	Life Insurance Corporation	
3.2	Past	Indeterminable	
3.3	Status	Owner and tenant	
4.0		Use	
4.1	Present	Residential and Commercial – Offices, Clinic	Restaurant Store
4.2	Past	Residential, Commercial	, Nostadrani, Otoro
		,	
4.3	Usage	Daily	
E 0		Simificance 8 Value Classification	
5.0	T (14	Significance & Value Classification	111111111111111111111111111111111111111
5.1	Townscape (Manmade)	Prominent corner building located at the Shy	
		of Madam Cama Road and Nathlalal Parekh	
		There are two main entrances to building, ea	
		are accessed from all three sides of the road	
			site context with two towers emphasizing the
		road junctions.	
			nt buildings of different styles and periods, like
			stel, Regal Cinema, the Museum and NGMA.
5.2	Architectural Description	Planning	
	·	The complex comprises of two rectangular by	uildings connected at first floor level facing
		Shyamaprasad Mukherjee Chowk with separ	rate entrances from three sides.
		The two buildings are connected in the center	
1		I THE INC DUNGINGS ARE CONTRECTED IN THE CENTE	er with a single storied arched bay. The corner
			er with a single storied arched bay. The corner be higher than the rest of the building. The
		projecting tower bays of the two buildings are	higher than the rest of the building. The
		projecting tower bays of the two buildings are central portion of the building has corridor sp	higher than the rest of the building. The
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays.	e higher than the rest of the building. The aces lined with a series of arched openings,
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. F	e higher than the rest of the building. The aces lined with a series of arched openings,
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. F residential flats	e higher than the rest of the building. The aces lined with a series of arched openings,
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. F residential flats Features	e higher than the rest of the building. The aces lined with a series of arched openings, First floor houses offices. Upper floors have
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. F residential flats Features The front façade has drop and shoulder arch	e higher than the rest of the building. The aces lined with a series of arched openings, First floor houses offices. Upper floors have es at first floor level, series of lancet arches at
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. F residential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like	e higher than the rest of the building. The aces lined with a series of arched openings, First floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level.
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. F residential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like. The towers have corbel tables while the inne	e higher than the rest of the building. The aces lined with a series of arched openings, First floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level.
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor lik. The towers have corbel tables while the innerising higher than quatrefoil stone parapet.	e higher than the rest of the building. The aces lined with a series of arched openings, first floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. r bay end of the buildings has a pediment
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like The towers have corbel tables while the innerising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have control or the second and topmost floor level.	e higher than the rest of the building. The aces lined with a series of arched openings, first floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. r bay end of the buildings has a pediment
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like The towers have corbel tables while the inner sing higher than quatrefoil stone parapet. The inner bays ending in a pediment, have cand blind rose window.	e higher than the rest of the building. The aces lined with a series of arched openings, first floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. r bay end of the buildings has a pediment oupled lancet arch within the equilateral arch
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor likt The towers have corbel tables while the inner ising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have cand blind rose window. Projecting balconies with decorative corbels.	e higher than the rest of the building. The aces lined with a series of arched openings, cirst floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. It bay end of the buildings has a pediment oupled lancet arch within the equilateral arch and stone balustrade.
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like The towers have corbel tables while the inner sing higher than quatrefoil stone parapet. The inner bays ending in a pediment, have cand blind rose window.	e higher than the rest of the building. The aces lined with a series of arched openings, cirst floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. It bay end of the buildings has a pediment oupled lancet arch within the equilateral arch and stone balustrade.
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor likt The towers have corbel tables while the inner ising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have cand blind rose window. Projecting balconies with decorative corbels.	e higher than the rest of the building. The aces lined with a series of arched openings, cirst floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. It bay end of the buildings has a pediment oupled lancet arch within the equilateral arch and stone balustrade.
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like The towers have corbel tables while the innerising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have cand blind rose window. Projecting balconies with decorative corbels Cast iron columns with decorative capitals su	e higher than the rest of the building. The aces lined with a series of arched openings, first floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. r bay end of the buildings has a pediment oupled lancet arch within the equilateral arch and stone balustrade. upport RCC beams.
5.3	Intrinsic	projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like The towers have corbel tables while the inner rising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have cand blind rose window. Projecting balconies with decorative corbels Cast iron columns with decorative capitals su Style	e higher than the rest of the building. The aces lined with a series of arched openings, first floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. r bay end of the buildings has a pediment oupled lancet arch within the equilateral arch and stone balustrade. upport RCC beams.
5.3 5.4	Intrinsic Value Classification	projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like The towers have corbel tables while the inner rising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have coand blind rose window. Projecting balconies with decorative corbels. Cast iron columns with decorative capitals su Style The building displays characteristics of the Nether that the strength of the strength	e higher than the rest of the building. The aces lined with a series of arched openings, first floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. r bay end of the buildings has a pediment oupled lancet arch within the equilateral arch and stone balustrade. upport RCC beams.
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like The towers have corbel tables while the inner rising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have cand blind rose window. Projecting balconies with decorative corbels Cast iron columns with decorative capitals su Style	e higher than the rest of the building. The aces lined with a series of arched openings, first floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. r bay end of the buildings has a pediment oupled lancet arch within the equilateral arch and stone balustrade. Ipport RCC beams.
		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. F residential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like The towers have corbel tables while the inner rising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have cand blind rose window. Projecting balconies with decorative corbels. Cast iron columns with decorative capitals su Style The building displays characteristics of the N - A (arc), B (per), B(des), E, F, I(sce).	e higher than the rest of the building. The aces lined with a series of arched openings, cirst floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. r bay end of the buildings has a pediment oupled lancet arch within the equilateral arch and stone balustrade. Ipport RCC beams.
5.4		projecting tower bays of the two buildings are central portion of the building has corridor sp interspersed with projecting bays. Ground floor houses restaurant and shops. Fresidential flats Features The front façade has drop and shoulder arch the second and topmost floor level. Tudor like The towers have corbel tables while the inner rising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have coand blind rose window. Projecting balconies with decorative corbels. Cast iron columns with decorative capitals su Style The building displays characteristics of the Nether that the strength of the strength	e higher than the rest of the building. The aces lined with a series of arched openings, cirst floor houses offices. Upper floors have es at first floor level, series of lancet arches at e arches at the third floor level. r bay end of the buildings has a pediment oupled lancet arch within the equilateral arch and stone balustrade. Ipport RCC beams.

Indian Mercar	ntile Mansion	151	
7.0		Construction	
7.1	Plinth	Medium height plinth in grey and buff basalt stone with a sloping plinth protection band	
7.2	Walls	Thick load bearing composite walls.	
7.3	Floor	RCC flat slab and beam structure supported on cast iron columns.	
		Lobby areas and corridors have jack arch flooring with steel sections.	
7.4	Stairs	Three staircases accessing three different buildings. Two open well timber staircases in	
		main buildings with decorative cast iron railing and wooden handrail.	
		One RCC staircase in the new wing.	
7.5	Openings	Arches with fixed glazed ventilators and glazed paneled double shutters	
7.6	Roofing	RCC terrace	
7.7	Articulation	Circular columns with decorative capitals, balconies with corbelling, bands, arches, stone	
		balustrade	
7.8	Finishes	Exposed grey stone rough dressed ashlar masonry externally.	
		Walls plastered and painted internally.	
7.9	Interiors (Movable & Immovable)	Movable	
	,	-	
		Immovable	
		•	
7.10	Compound/ Fence/ Gate	The building abuts the site boundary on the front two sides. Brick compound wall on	
	·	remaining two sides with MS gates.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Rear side of the plot occupies electric substation and pump house.	
	Landscape		
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light through balconies, passages and openings, supplemented by	
		artificial light.	
8.2	Ventilation	Adequate natural ventilation through supplemented by artificial ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM (original cast iron pipes still present)	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	Individual tenants have installed window and split air conditioners.	
-			
9.0		Condition	
9.1	Plinth	Poor – major alterations have been made as per the independent shop owners on ground	
		floor. Leakages at plinth level in service court have been observed	
9.2	Walls	Fair – brick masonry on ground floor exposed in some places. Organic growth, leakages	
		and dampness has been observed at places	
9.3	Floor	Fair	
9.4	Stairs	Fair – balustrades are in a broken condition in few places. Loose floorboards	
9.5	Openings	Poor - main pointed arch entrance on ground floor has been altered. Lancet arches on first	
		and third floor level have been blocked with brick masonry	
		Passages have been enclosed. Door and window shutters have been replaced	
9.6	Roofing	Fair	
9.7	Articulation & Finishes	Poor – corbel are in a broken condition, balconies are badly damaged, decorative features	
		are insensitively painted over.	
9.8	Services	Poor – corroded service pipes resulting in leakages and dampness. Service court is in an	
		unhygienic condition.	
9.9	Out Buildings	Poor – marginal open spaces and ancillary structures in neglected state.	
9.10	Overall Conditions	Poor Maintenance level Poor	
		· · · · · · · · · · · · · · · · · · ·	
10.0		Transformation	
	Form	Addition of a wing on rear side.	
	Structure	•	
	Articulation & Finishes	Hoardings cover the ground floor of the building façade. Alterations and additions have	
		been insensitively done	
		·	
		DP Remarks/ Perceived Threats	
11.0			
11.0		Building forms part of C1 Zone	
11.0		Building forms part of C1 Zone	
11.0		Building forms part of C1 Zone Additional Notes/ References/ Documents available	
		Additional Notes/ References/ Documents available	
		Additional Notes/ References/ Documents available Additional Notes:	
		Additional Notes/ References/ Documents available Additional Notes: - References:	
		Additional Notes/ References/ Documents available Additional Notes:	
		Additional Notes/ References/ Documents available Additional Notes: - References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	

Indian Mercantile Mansion 151



Façade of the two grey stone clad buildings with a connecting structure with an arcade and corner towers as viewed from the main road



Incongruous additions and transformations made to the openings



Grey stone clad building with buff stone arched openings, projecting balconies, balustrades etc.



Arched opening with buff stone voussoirs, internal pointed arched openings, round floral motifs, balustrade etc.

C4 Ammala	Cirls High Cabasi		AF
ot. Anne's	Girls High School	Common Ref No: 152	152
			94
		Card No: 210	ATWA GANDHI ROAD
100		Ward (Part): A (part IV)	iday
	THE PARTY NAMED IN	CS No: Indeterminable	0
- 2	THE REAL PROPERTY.	Plot Area: Indeterminable	P A STATE OF THE S
2.6	MAIN TO A STATE OF THE STATE OF	B U Area: -	MADAM CAMAROAD
160		Date: 10/01/2005	TAMA ROAD
e IUN	TO THE PARTY OF TH	Recorded by: Arun Wadhwa	RG RG
1800	THE RESERVE TO SERVE THE PARTY OF THE PARTY	Reviewed by:	E PER
Sec. (5)	1	Int: Arun Wadhwa, Sonal Modak	000
100	1000	Ext: Arun Wadhwa, Sonal Modak	THEODY TO
200		Photo Ref: 152_St. Anne's High School	To be to the same of the same
185/15		Filoto Ref. 132_St. Affile's High School	ETHAL SE
1 Sept 19.00			
			Location plan
1.0		Denomination	·
1.1	Name of Premises	St. Anne's Girls High School	
1.2	Earlier Name	St. Anne's School	
1.3	Built in:	Indeterminable	Extension Date: -
1.5	Dulit III.	mueterminable	Extension Date
2.0		A	
2.0	14.	Access	
2.1	Main	Madam Cama Road – vehicular and pedestrian	<u> </u>
2.2	Subsidiary	-	
3.0		Ownership pattern	
3.1	Present	St. Anne's School Trust	
3.2	Past	St. Anne's School Trust	
3.3	Status	Trust	
4.0		Use	
4.1	Present	Institutional - Primary and Secondary Girl's Sch	iool.
4.2	Past	Institutional - School.	
4.3	Usage	Daily	
	9-		
5.0		Significance & value Classification	
5.1	Townscape (manmade)	The building is placed along a row of buildings v	with uniform scale on Madam Cama Road
J. I	Townscape (manimade)	and is surrounded with buildings of different styl	
		Science on the north and Wellington fountain to	
	A 12 (1D) (The building is accessed from the north side roa	au ironi
5.2		Planning	
	Architectural Description		ed at the center of western side dividing the
	Architectural Description	Rectangular plan with entrance staircase locate	
	Architectural Description	building into symmetrical front and rear portions	S
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar	s. nd narrow passages.
	Arameedural bescription	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f	s. nd narrow passages. ront and rear sides.
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar	s. nd narrow passages. ront and rear sides.
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates large	s. nd narrow passages. front and rear sides. ge hall with balcony resulting in a level
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates larg difference at the upper floors. Kindergarten, offi	s. nd narrow passages. front and rear sides. ge hall with balcony resulting in a level ices and canteen occupy rest of the ground
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates larg difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper	s. nd narrow passages. front and rear sides. ge hall with balcony resulting in a level lices and canteen occupy rest of the ground three floors, along with teacher's room,
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates larg difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a	s. nd narrow passages. front and rear sides. ge hall with balcony resulting in a level lices and canteen occupy rest of the ground three floors, along with teacher's room,
	Aramedurar Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates larg difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style	nd narrow passages. front and rear sides. ge hall with balcony resulting in a level dices and canteen occupy rest of the ground three floors, along with teacher's room, added later to serve as a Nuns residence.
	Aramedurar Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates larg difference at the upper floors. Kindergarten, off floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic	nd narrow passages. front and rear sides. ge hall with balcony resulting in a level dices and canteen occupy rest of the ground three floors, along with teacher's room, added later to serve as a Nuns residence.
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features:	and narrow passages. In and rear sides. If an and rear sides. If an and rear sides. If an and rear sides. If an and rear
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opens.	and narrow passages. In and rear sides. If a
	Aramedurar Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lark difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the ground.	and narrow passages. In and rear sides. If a
	Aramedurar Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the ground Intricately carved iron brackets on stone blocks	and narrow passages. In and rear sides. If a
	Aramedurar Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates large difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the groul Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches	and narrow passages. In and rear sides. If a
	Aramedurar Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates large difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the groul Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches below window openings.	and narrow passages. In and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and rear sides. If and sides is a level If and sides. If and sides is a level If and sides. If and sides is a level If and sides. If and sides is a level If and sides. If and sides is a level If and sides. If and sides is a level If and sides. If and sides is a level If and sides. If and sides is a level If a
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates large difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the ground Intricately carved iron brackets on stone blocks. Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with or	and narrow passages. In and rear sides. If and narrow passages. If and rear sides. If and rear sides room, If and rear sides room, If and sides rear sides room, If and sides rear sides room, If and sides room, If and rear sides. If and
	Ardinectural Description	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates large difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the ground Intricately carved iron brackets on stone blocks. Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with other stones.	and narrow passages. In and rear sides. If and narrow passages. If and rear sides. If and rear sides room, If and rear sides room, If and sides rear sides room, If and sides rear sides room, If and sides room, If and rear sides. If and
		building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates large difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the ground Intricately carved iron brackets on stone blocks. Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with or	and narrow passages. In and rear sides. If and narrow passages. If and rear sides. If and rear sides room, If and rear sides room, If and sides rear sides room, If and sides rear sides room, If and sides room, If and rear sides. If and
5.3	Intrinsic	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates large difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the ground Intricately carved iron brackets on stone blocks. Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with other stones.	and narrow passages. In and rear sides. If a
5.3 5.4		building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, off floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the groun Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with a Sloping chajjas supported on wooden brackets. floor level.	and narrow passages. In and rear sides. If a
	Intrinsic	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, off floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the groun Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with a Sloping chajjas supported on wooden brackets. floor level.	and narrow passages. In and rear sides. It is ge hall with balcony resulting in a level loces and canteen occupy rest of the ground three floors, along with teacher's room, added later to serve as a Nuns residence. It is and verandahs with stone baluster and floor. It is support the projecting balconies. It is and keystone. Stone carved floral pattern carved relief panels. It is a level of architecture band at second
5.4	Intrinsic	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the groun Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with or Sloping chajjas supported on wooden brackets. floor level. A (arc), B (per), B(des), B(uu), F	and narrow passages. In and rear sides. It is ge hall with balcony resulting in a level loces and canteen occupy rest of the ground three floors, along with teacher's room, added later to serve as a Nuns residence. It is and verandahs with stone baluster and floor. It is support the projecting balconies. It is and keystone. Stone carved floral pattern carved relief panels. It is a level of architecture band at second
5.4 6.0	Intrinsic Value Classification	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the groun Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with of Sloping chaijas supported on wooden brackets. floor level. Topography	and narrow passages. In and rear sides. It is ge hall with balcony resulting in a level loces and canteen occupy rest of the ground three floors, along with teacher's room, added later to serve as a Nuns residence. It is and verandahs with stone baluster and floor. It is support the projecting balconies. It is and keystone. Stone carved floral pattern carved relief panels. It is a level of architecture band at second
5.4	Intrinsic	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the groun Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with or Sloping chajjas supported on wooden brackets. floor level. A (arc), B (per), B(des), B(uu), F	and narrow passages. In and rear sides. It is ge hall with balcony resulting in a level loces and canteen occupy rest of the ground three floors, along with teacher's room, added later to serve as a Nuns residence. It is and verandahs with stone baluster and floor. It is support the projecting balconies. It is and keystone. Stone carved floral pattern carved relief panels. It is a level of architecture band at second
6.0 6.1	Intrinsic Value Classification	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the groun Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with of Sloping chajjas supported on wooden brackets. floor level. A (arc), B (per), B(des), B(uu), F	and narrow passages. In and rear sides. If ont and rear sides. If one and canteen occupy resulting in a level If oces and canteen occupy rest of the ground If three floors, along with teacher's room, If occupy rest of the ground If occupy rest of the ground If occupy rest of the ground If occupy rest of the ground If occupy rest of the ground If occupy residence. If occupy residence If occupy residence If occupy residence If occupy resulting balconies. If occupy residence If occupy residence If occupy resulting balconies. If occupy residence If occupy resulting balconies. If occupy resulting balconies residence If occupy resulting balconies. If occupy resulting balconies residence If occupy resulting in a level If occupy resulting in
6.0 6.1 7.0	Intrinsic Value Classification Floors	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the ground Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with of Sloping chajjas supported on wooden brackets. floor level. A (arc), B (per), B(des), B(uu), F Topography G+4 Construction	and narrow passages. Front and rear sides. The general with balcony resulting in a level coes and canteen occupy rest of the ground three floors, along with teacher's room, added later to serve as a Nuns residence. The coefficient of architecture enings and verandahs with stone baluster and floor. The support the projecting balconies. The projecting balconies of the ground relief panels. The coefficient of th
6.0 6.1	Intrinsic Value Classification	building into symmetrical front and rear portions Classrooms are accessed from central lobby ar Toilets are placed on the eastern side on both f Eastern side of ground floor accommodates lard difference at the upper floors. Kindergarten, offi floor. Classrooms occupy portions of the upper laboratories and library. Fourth floor has been a Style The building derives influence from Neo Classic Features: The front façade consists of segmental arch opparapet with rusticated relief facing on the groun Intricately carved iron brackets on stone blocks Window openings with architrave, relief arches below window openings. Pediment feature in the western entrance with of Sloping chajjas supported on wooden brackets. floor level. A (arc), B (per), B(des), B(uu), F	and narrow passages. Front and rear sides. It is ge hall with balcony resulting in a level coes and canteen occupy rest of the ground three floors, along with teacher's room, added later to serve as a Nuns residence. It is and verandahs with stone baluster and floor. It is support the projecting balconies. It is and keystone. Stone carved floral pattern carved relief panels. It arge projecting comice band at second

	Girls High School	Consents floor supported on atrail positions	
7.3	Floor	Concrete floor supported on steel I-sections.	
7.4	Stairs	Two staircases with a common floor landing. Front double flight wide staircase, narrow internal staircase accommodating lift in the central open well.	
7.5	Openings	Arch verandah openings. Rectangular door and window openings with separate ventilator panels and wood framed glazed panel shutters. Shallow segmental arches span internal door openings.	
7.6	Roofing	Sloping Mangalore tile hipped roof with wide overhangs.	
7.7	Articulation	Arches, bands, projecting balconies, pediment feature, carved relief panels	
7.8	Finishes	Buff basalt stone finished external front, plastered and painted internal wall surfaces. Original Minton tiling on ground floor and modified ceramic tiles on upper floors.	
7.9	Interiors (Movable & Immovable)	Movable - Immovable	
7.10	Compound/ Fence/ Gate	 Low front compound wall with MS gate, cast iron railing and stone pillars at regular interval with a decorative coping. Side and rear compound wall about 1.5 M in height. 	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Large playground to the rear south side. Underground tank with pump room, watchman's room to the rear side. Play area in the front open space.	
8.0		Services & Utilities	
8.1	Lighting	Adequate natural light supplemented by artificial light	
8.2	Ventilation	Adequate natural ventilation supplemented by artificial ventilation	
8.3	Electricity	BEST.	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution		
8.7	Other (HVAC/BMS/Security Systems)	Fire extinguishers	
9.0		Condition	
9.1	Plinth	Fair	
9.2	Walls	Fair – organic growth has been observed on the rear side.	
9.3	Floor	Fair	
9.4	Stairs	Fair	
9.5	Openings	Fair – arched openings have been blocked at places	
9.6	Roofing	Indeterminable	
9.7	Articulation & Finishes	Fair	
9.8	Services	Fair	
9.9	Out Buildings	Fair	
9.10	Overall Conditions	Good Maintenance level: Good	
5.10	Overall Conditions	Indirection of Cook	
10.0		Transformation	
	Form	-	
	Structure	-	
	Articulation & Finishes	External stone façade has been painted	
11.0		DP Remarks/ Perceived Threats	
11.0		Secondary School, building forms part of C1 zone	
12.0		Additional Notes/ References/ Documents available	
. 2.0		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.	

152 St. Anne's Girls High School



Openings with floral motif at the sill level



Internal balcony with arched openings, stone balustrade, minton tiles etc



Openings with lintel bands, wooden glazed paneled shutters, arched and round motifs above.



Compound Wall with pilasters and jail work



Painted stone faced building façade with arched opening, arch and sill band, dentil moulding.





Minton tile flooring



Decorative brackets supporting the projecting balconies

Y.W.C.A bu	uilding		153
``		Common Ref No: 153	DI V O COMP
		Card No: 211	9
	3714	Ward (Part): A (Part IV)	MAR
		CS No: Indeterminable	RAO PATIL MARG
Fre		Plot Area: Indeterminable	OVAL MAIDAN OV
		B U Area: -	OVAL NATAN AND AND AND AND AND AND AND AND AND A
		Date: 04/01/2005	H H A M A M A M A M A M A M A M A M A M
		Recorded by: Prachi Merchant Reviewed by:	MADAMCAN
		Int: Arun Wadhwa, Prachi Merchant	MADAM CAMAROAD
	The same of the sa		W W W
		Ext: Arun Wadhwa, Prachi Merchant	H F R A
		Photo Ref: 153_YWCA.	000
			Location plan
1.0		Denomination	
1.1	Name of Premises	Y.W.C.A building	
1.2	Earlier Name	Bombay Young Women's Christian	
		Association	
1.3	Built in:	1900 – Foundation laid, 1918 - Completed	Extension Date: 1964 – New Building
-			
2.0		Access	
2.1	Main	Madam Cama Road	
2.2	Subsidiary	-	
L.L	Substituti		
3.0		Ownership pattern	
3.1	Present	YWCA Trust	
3.1		1 11	
	Past	Indeterminable	
3.3	Status	Trust	
4.0			
4.0		Use	
4.1	Present	Womens Hostel, Guest House, Conference I	
4.2	Past	Womens Hostel, Guest House, Conference I	Hall
4.3	Usage	Daily.	
5.0		Significance & value Classification	
5.1	Townscape (manmade)	The building is placed along a row of buildings with uniform scale on Madam Cama Road and is surrounded with buildings of different styles and periods including the Institute of Science on the north and Wellington fountain to the east. The building is accessed from the north side through an extended porch.	
5.2	Architectural Description	Planning	unough an extended porch.
J.2	Architectural Description		shorter side facing the main road
		The building is rectangular in shape with its shorter side facing the main road. The central and side wings marginally project out.	
		The entrance is through an extended porch in	
			ocated in the center opposite each other. The
		toilet block has a sub level in the original floo	
		steps.	in fleight, accessed by the main floor level by
		The ground floor houses office areas and a r	nultinurnose hall at the south and accessed
		from outside south and east side entrances.	numpurpose namat the south cha accessed
			area in the south end above the hall, meeting
		The first floor flouses the kitchen and diffing	
		hall in the north and and single double and o	Anrmitoriae
		hall in the north end and single, double and o	
		The upper floors house single, double rooms	and dormitories.
		The upper floors house single, double rooms The main building is connected to the new bu	and dormitories.
		The upper floors house single, double rooms The main building is connected to the new bu Features	and dormitories. uilding from a gate in the west side.
		The upper floors house single, double rooms The main building is connected to the new by Features The central wing is extended with a terrace a	and dormitories. uilding from a gate in the west side. shove, supported on round columns with high
		The upper floors house single, double rooms The main building is connected to the new by Features The central wing is extended with a terrace a square base and decorative capitals. The ter	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade.
		The upper floors house single, double rooms The main building is connected to the new by Features The central wing is extended with a terrace a square base and decorative capitals. The ter The central wing floors have rectangular ope	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade. nings with round columns on both sides with
		The upper floors house single, double rooms The main building is connected to the new by Features The central wing is extended with a terrace a square base and decorative capitals. The ter The central wing floors have rectangular ope decorative capitals with frieze bands between	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade. nings with round columns on both sides with a the windows. The side bay has projecting
		The upper floors house single, double rooms The main building is connected to the new by Features The central wing is extended with a terrace as quare base and decorative capitals. The ter The central wing floors have rectangular ope decorative capitals with frieze bands between balconies supported on decorative brackets.	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade. nings with round columns on both sides with a the windows. The side bay has projecting
		The upper floors house single, double rooms The main building is connected to the new bu Features The central wing is extended with a terrace a square base and decorative capitals. The ter The central wing floors have rectangular ope decorative capitals with frieze bands between balconies supported on decorative brackets. Bay windows project out on the east side.	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade. nings with round columns on both sides with n the windows. The side bay has projecting and a cast iron railing.
		The upper floors house single, double rooms The main building is connected to the new bu Features The central wing is extended with a terrace a square base and decorative capitals. The ter The central wing floors have rectangular ope decorative capitals with frieze bands between balconies supported on decorative brackets a Bay windows project out on the east side. The façade has stucco features such as a ge	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade. nings with round columns on both sides with in the windows. The side bay has projecting and a cast iron railing. cometric pattern frieze at the sill and lintel leve
		The upper floors house single, double rooms The main building is connected to the new bu Features The central wing is extended with a terrace a square base and decorative capitals. The ter The central wing floors have rectangular ope decorative capitals with frieze bands between balconies supported on decorative brackets. Bay windows project out on the east side. The façade has stucco features such as a ge Dentil corbelling, festoons and floral motifs by	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade. nings with round columns on both sides with in the windows. The side bay has projecting and a cast iron railing. cometric pattern frieze at the sill and lintel leve
		The upper floors house single, double rooms The main building is connected to the new bu Features The central wing is extended with a terrace a square base and decorative capitals. The ter The central wing floors have rectangular ope decorative capitals with frieze bands between balconies supported on decorative brackets a Bay windows project out on the east side. The façade has stucco features such as a ge Dentil corbelling, festoons and floral motifs bo The windows have sloping wooden chajjas.	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade. nings with round columns on both sides with the windows. The side bay has projecting and a cast iron railing. cometric pattern frieze at the sill and lintel leve etween the windows and corner quoins.
£2	Intrincia	The upper floors house single, double rooms The main building is connected to the new bu Features The central wing is extended with a terrace a square base and decorative capitals. The ter The central wing floors have rectangular ope decorative capitals with frieze bands between balconies supported on decorative brackets. Bay windows project out on the east side. The façade has stucco features such as a ge Dentil corbelling, festoons and floral motifs by	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade. nings with round columns on both sides with the windows. The side bay has projecting and a cast iron railing. cometric pattern frieze at the sill and lintel leve etween the windows and corner quoins.
5.3 5.4	Intrinsic Value Classification	The upper floors house single, double rooms The main building is connected to the new bu Features The central wing is extended with a terrace a square base and decorative capitals. The ter The central wing floors have rectangular ope decorative capitals with frieze bands between balconies supported on decorative brackets a Bay windows project out on the east side. The façade has stucco features such as a ge Dentil corbelling, festoons and floral motifs bo The windows have sloping wooden chajjas.	and dormitories. uilding from a gate in the west side. above, supported on round columns with high race has a stone balustrade. In high round columns on both sides with the windows. The side bay has projecting and a cast iron railing. cometric pattern frieze at the sill and lintel level etween the windows and corner quoins.

	ilding	153	
6.0		Topography	
6.1	Floors	G+3 with Terrace	
7.0		Construction	
7.1	Plinth	High plinth clad with grey stone with a plinth protection band.	
7.2	Walls	Load bearing brick walls.	
7.3	Floor	RCC structure supported on I section and cast iron columns.	
7.4	Stairs	Main wooden doglegged staircase with wooden treads, risers and railing.	
1.4	Stalls	Service staircase on the east side.	
7.5	Openings		
7.5	Openings	Rectangular window openings with double shutters consisting of louvered shutters outside	
		and glazed paneled shutters inside.	
7.0	D 6	Bay windows with glazed paneled shutters.	
7.6	Roofing	RCC slab terrace.	
		Service block with toilets planned in split-levels has a sloping asbestos roof.	
		Windows have wooden chajjas.	
7.7	Articulation	Bands, friezes, columns with decorative capitals, floral motifs, projecting balconies with	
		brackets, quoins.	
7.8	Finishes	The walls are externally clad with stone, plastered and painted internally and externally.	
		Floor is finished with cement tiles.	
7.9	Interiors (Movable & Immovable)	Movable	
	,	Meeting room table, chairs, dressing table, chaise, chests.	
		Immovable	
		Marble plaque on the front east side plinth wall, explaining the details of foundation.	
7.10	Compound/ Fence/ Gate	Brick compound wall with fence above.	
		Three MS gates on the north side with gate posts.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Front curvilinear lawn space on both sides of the central gate. Line of trees along the front	
	Landscape	compound wall. Potted plants have been kept along the building.	
	Landscape	New hostel building added on the west side.	
		Watchman's cabin added near the west end gate.	
		Pump house and a temporary shed for activities added in the rear south side.	
		t unip nouse and a temporary sned for activities added in the real soditi side.	
0.0		Services & Utilities	
8.0	Limbia a		
8.1	Lighting	Adequate natural light through openings supplemented with artificial lighting.	
8.2	Ventilation	Adequate natural ventilation through openings supplemented with artificial ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	•	
9.0		Condition	
9.1	Plinth	Fair – stone cladding has been painted.	
9.2	Walls	Fair – loose plaster due to seepage was observed in the rear side.	
9.3	Floor	Fair – Shed has been added at the terrace level.	
9.4	Stairs		
9.5	Openings	Fair – well maintained except wear and tear of the wooden treads. Fair – Openings have been blocked, shutters have been changed.	
3.3	Operings		
0.6	Doofing	Rear side window shutters are not maintained well.	
9.6	Roofing	Fair – at few places slab reinforcement is exposed.	
9.7	Articulation & Finishes	Fair – internally features have been maintained. The external relief features and projecting	
0.0	0	balconies are in a damaged state.	
9.8	Services	Poor – old plumbing lines are not maintained. New service lines added haphazardly.	
9.9	Out Buildings	Fair	
9.10	Overall Conditions	Fair Maintenance level: Good.	
10.0		Transformation	
	Form	-	
	Structure	•	
	Articulation & Finishes	Toilet roof has been changed.	
		Out buildings added in the west and south side.	
		Plastered and painted external stone façade.	
		All features are painted and it is difficult to identify the original material.	
11.0		DP Remarks/ Perceived Threats	
11.0		Building forms part of C1 zone	
		building forms part of 61 2016	
40.0		Additional Notes (Defense of December 1971)	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
	I		
		- References:	

Y.W.C.A building	153
	INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
	Structures listed for Conservation.
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,
	Division of International Thomson Publishing Inc



Entrance porch on round columns with Corinthian capitals and terrace with balustrades



Projecting balconies with cast iron railing, supported on brackets, frieze bands with floral pattern



Sloping wooden chajjas with louvers



Sill and lintel level ornamentation in floral pattern, dentil moulding, floor bands etc



Wooden staircase with intricately carved wooden railing



Marble tablet explaining the foundation details

Y.W.C.A building




Cast iron column capital and bracket detail



Carved cast iron bracket detail



Round column with corinthian capital with floral pattern



Amarchand	Mansion	1
		and handrail.
		Other two are accessed from sides of the building constructed in timber, dog legged.
7.5	Openings	The main entrance is through a porch. Main entrance door is an Islamic arch with wooder
		doorframe and partly glazed double shutter. Ventilators above have stained glass panels.
		Northern facade has balconies along the length.
7.6	Roofing	Flat jack arch roof with a terrace above.
7.7	Articulation	That just are the a terrace above.
7.8	Finishes	Buff basalt for the exteriors with all decorative carvings in white sand stone and circular
7.0	i illiones	columns near entrance in red granite.
		Walls are plastered and painted internally.
7.0	Interiore (Massahla O Immessahla)	Coloured clay tiles for flooring.
7.9	Interiors (Movable & Immovable)	Movable
		Immovable
7.10	Compound/ Fence/ Gate	Plastered compound wall about 2'6" in height with cast iron railing.
		Stone pilasters topped with Islamic cupolas, which define the entrance gate.
	Curtilage/ Unbuilt space/ Out Buildings/	Planter boxes along northern compound wall. The side margins are paved using cement
	Landscape	tiles. Northern open space is used as parking area.
		Southern side margin houses pump house, society office and AC plants.
8.0		Services & Utilities
8.1	Lighting	Adequate daylight through windows and verandahs along the light courts and artificial
		lighting.
8.2	Ventilation	Adequate ventilation through windows and verandahs with a provision of electric
		equipments like fans.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
	Drainage (Plumbing & Sanitation)	MCGM
8.5	, , , , , , , , , , , , , , , , , , , ,	
8.6	Fire Precaution	No traces.
8.7	Other (HVAC/BMS/Security Systems)	No traces.
9.0		Condition
9.1	Plinth	There are planters along the plinth.
9.2	Walls	There is no evident damage to the walls internally as well as externally. Little dampness i
		observed in top floor walls.
9.3	Floor	There is no evident damage to the floors.
9.4	Stairs	There is no evident damage to the staircases. Maintained in a good condition.
9.5	Openings	Window openings are blocked in some places. Stained glass broken.
9.6	Roofing	Major leakage during monsoon is observed through roofing.
9.7	Articulation & Finishes	
9.8		
	Services	-
9.9	Out Buildings	<u></u>
9.10	Overall Conditions	Fair Maintenance level - Fair
10.0		Transformation
	Form	-
	Structure	Additional MS sections have been added to support step out balconies in some areas.
	Articulation & Finishes	Balusters, railing are replaced in few places.
		• .
11.0		DP Remarks/ Perceived Threats
		Building forms part of C1 zone.
		.
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		-
		- References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and

Amarchand Mansion 154



Buff stone clad symmetrical building with central and alternate bay higher than the balcony bay



Ornamented projecting balcony with floral pattern carved on its underside.



Detail of the cast iron railing



Entrance porch with multifoied arches with decorative spandrel, turrets, bands, friezes, balustrade



Projecting balconies supported on intricately carved brackets, balustrade.



Arched window with glazed paneled openable and fixed ventilator shutters, intricate floral pattern in the spandrel

Amarchand Mansion 154



Internal lobby with Minton tile flooring



Detail of the arched window, with decorative intrados, spandrel, bands, friezes



Original wooden list paneling and shutters



Rectangular opening with intricately carvings in sill and lintel level, chajjas supported on brackets.




Balustrade in decorative floral pattern



Frieze band with floral motifs



Column capital with intricately carved capital in floral pattern



Stained glass window in a floral shaped opening

Institute of	Science		155
montute UI	COLONIO	Common Ref No: 155	A COMMO ROW (STEELS TO THE HERE
		Card No: 213	A DANDHI ROAD A DAND
		Ward (Part): A (Part III)	A THE STATE OF THE
		CS No: Indeterminable	NA SUNIA
THINING TO SERVE		Plot Area: Indeterminable	n a do do do do do do do do do do do do do
		B U Area: -	Tanga da
		Date: 18/1/2005	KAR KAR S S I N G
Di Jing		Recorded by: Arun Wadhwa	L Value Value
		Reviewed by:	MADAM CAMA ROAD CI SHAHID
		Int: Arun Wadhwa, Sonal Modak	8 PAG
16.17		Internal photography permission denied	
1	THE REPORT OF THE PERSON OF TH	Ext: Arun Wadhwa, Sonal Modak	
and the second		Photo Ref: 155_Institute of Science.	Line Posts
			The state of the s
			Location plan
1.0		Denomination	
1.1	Name of Premises	Institute of Science	
1.2	Earlier Name	Royal Institute of Science	
1.3	Built in:	1924	Extension Date: -
			•
2.0		Access	
2.1	Main	Madam Cama Road - pedestrian	
2.2	Subsidiary	Mahatma Gandhi Road and Karmaveer Bha	aurao Patil Marg - vehicular and pedestrian
			·
3.0		Ownership pattern	
3.1	Present	State Government of Maharashtra	
3.2	Past	Indeterminable	
3.3	Status	Owner	
4.0		Use	
4.1	Present	Institutional - College of Science	
4.2	Past	Institutional - College of Science	
4.3	Usage	Daily	
5.0		Significance & value Classification	
5.1	Townscape (manmade)	Prominent corner building located at the jun	ction of three roads, with two wings on the
		building, in the southeast corner on the Mah	ao Patil Marg connected by an imposing NGMA
		The building is placed along a row of building	ngs with uniform scale on Madam Cama Road
		and is surrounded with buildings of different	styles and periods including the YWCA, St.
		Annes School on the south and Wellington	
		The curvilinear building form is a site respor	nse, with its main entrance from south side of
		Madam Cama Road.	.,
5.2	Architectural Description	Planning	
	·		ow wings with spacious verandahs along the
		three road fronts enclosing an internal court	
		Main access is from the south side into a gr	
		laboratories and staff areas arranged to the inner side of the long wings.	
		Subsidiary entrances from the west and eas	
			rth side connected from the west end. Also an
			ral staircase wing housing the Library. Small
		ancillary structures are present in the international Features	ai open space.
			olonnaded central portion marked by projecting
		balcony above with circular ionic columns ri	
		frieze band and decorative relief feature.	onig the needs ingli callication by alcalicat
		Front side stone facade has rusticated semi	icircular arch verandahs on the ground floor and
		rectangular openings on the two upper floor	s with infill relief panels and stone jali ventilator
		and parapet. Terrace parapet is distinctly tre	
		entire edge light in appearance.	
		Projecting stone balconies supported on lan	
		Distinct keystone feature surmounting the s	emicircular arch openings.
		Style The building displays features of the Renais	econog Povival style of architecture
5.3	Intrincio	The building displays features of the Renais	sance revival style of architecture
5.3 5.4	Intrinsic Value Classification	A (arc) B (per) B(dos) B(m) E E C (arc)	I(see) Decommended grade I
ე.4	Value Classification	A (arc), B (per), B(des), B(uu), E, F, G (grp)	, I(sce) Recommended grade I
6.0	+	Topography	
6.1	Floors	G+2 and part third floor.	
U. 1	7 10010	5 2 and part and noor.	
	<u> </u>	I .	

Institute of Sc	ience	155	
7.0		Construction	
7.1	Plinth	High plinth height dressed in rough buff stone	
7.2	Walls	Load bearing rubble masonry stonewalls.	
7.3	Floor	RCC slab resting on load bearing walls.	
7.4	Stairs	Three staircases – central grand curvilinear C-shaped stone staircase with large open	
		atrium under the domed space with lift installed in the open shaft at the end of East wing.	
7.5	Openings	Regular double flight stone stair with semi circular mid-landing in the west wing. Semicircular arch openings on ground floor verandahs and rectangular on two upper floors.	
1.5	Openings	Segmental arch window openings on the rear facades. Wooden paneled door and wooden	
		glazed panel window shutters with separate ventilator openings in the arch portions.	
7.6	Roofing	Flat RCC slab over long curvilinear wings and large dome over the central staircase block.	
7.7	Articulation	Central portion emphasised with high circular columns, frieze band, stone jali, decorative	
		relief feature, prominent keystone on semicircular arches, semicircular arch verandahs on	
		the ground floor, projecting stone balconies supported on large brackets.	
7.8	Finishes	Buff colored Kurla stone dressed ashlar course external wall surfaces and plaster painted	
		internal finishing. Ceramic tile floor finishes. Polished wooden door and window shutters.	
7.9	Interiors (Movable & Immovable)	Movable	
		·	
		Immovable	
		Standing Marble statue of Baron Sydenham, Governor of Bombay in the central foyer of	
7.40	0	main staircase. Wooden folding benches in the stepped lecture halls on the second floor.	
7.10	Compound/ Fence/ Gate	Original small stone post and chained fence now replaced with iron frame and chain link.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/	Numerous small structures located in the central open space including a G+1 Radioactive	
	Landscape	Research Centre and single storied sloping roof canteen, staff union office and pump room structures.	
		structures.	
8.0		Services & Utilities	
	Lighting		
8.1 8.2	Lighting Ventilation	Adequate natural light in passages and service areas supplemented by artificial light. Adequate natural ventilation supplemented by artificial ventilation	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Fire extinguishers and dry riser arrangement.	
8.7	Other (HVAC/BMS/Security Systems)	Window and Split air conditioning units	
0.1	Curci (TVAO/BINO/Occurity Gysteriis)	window and opin an conditioning units	
9.0		Condition	
9.1	Plinth	Poor - Plant cultivation around the plinth area and plumbing interventions on the rear side.	
9.2	Walls	Fair - seepage in staircase, corridors and internal rooms.	
9.3	Floor	Fair - exposed reinforcement and damp patches in some verandas.	
9.4	Stairs	Fair	
9.5	Openings	Poor – modified shutters, internal <i>verandahs</i> have been enclosed, brick walls replaced	
	' "	stone parapet. Addition of cement sheet <i>chajjas</i> in the rear side.	
9.6	Roofing	Fair except exposed reinforcement and seepage in some verandas.	
9.7	Articulation & Finishes	Poor - blackened stone facades, keystone feature, also chipping done over stone work.	
9.8	Services	Poor – haphazard addition of exposed wiring in corridors, old and corroding plumbing lines.	
9.9	Out Buildings	Fair	
9.10	Overall Conditions	Fair Maintenance level: low	
10.0		Transformation	
	Form	Annex building has been added along the north side	
	Structure	-	
		Compart pointing has been corried out an atoms dragged founded	
	Articulation & Finishes	Cement pointing has been carried out on stone dressed facades.	
	Articulation & Finishes	, ,	
11.0	Articulation & Finishes	DP Remarks/ Perceived Threats	
11.0	Articulation & Finishes	, ,	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone	
11.0	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes:	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum.	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum. Foundation stone was laid in 1911, was opened only in 1920 due to the outbreak of World	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum. Foundation stone was laid in 1911, was opened only in 1920 due to the outbreak of World War I in 1914.	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum. Foundation stone was laid in 1911, was opened only in 1920 due to the outbreak of World War I in 1914. Building has a height of 50 feet with a total frontage of 400 yards.	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum. Foundation stone was laid in 1911, was opened only in 1920 due to the outbreak of World War I in 1914. Building has a height of 50 feet with a total frontage of 400 yards. References:	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum. Foundation stone was laid in 1911, was opened only in 1920 due to the outbreak of World War I in 1914. Building has a height of 50 feet with a total frontage of 400 yards.	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum. Foundation stone was laid in 1911, was opened only in 1920 due to the outbreak of World War I in 1914. Building has a height of 50 feet with a total frontage of 400 yards. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum. Foundation stone was laid in 1911, was opened only in 1920 due to the outbreak of World War I in 1914. Building has a height of 50 feet with a total frontage of 400 yards. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.	
	Articulation & Finishes	DP Remarks/ Perceived Threats College and Public Hall, building forms part of C1 zone Additional Notes/ References/ Documents available Additional Notes: George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum. Foundation stone was laid in 1911, was opened only in 1920 due to the outbreak of World War I in 1914. Building has a height of 50 feet with a total frontage of 400 yards. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,	

Institute of Science 155



Entrance bay with double height ionic columns, bands, friezes, round openings, balustrade of buff stone clad curvilinear façade with Renaissance Revival style features



Rectangular verandah/ passage openings with frieze bands in geometric pattern, bands, floral motifs



Side façade with arched and rectangular openings, projecting balconies, lintel and sill level bands, scroll bracket keystone



Balcony with stone balustrade, comer high parapet, brackets, geometric pattern ornamentation



Scroll bracket pattern keystone



Frieze detail in buff stone with bands at floor level



Main entrance bay with rusticated buff stone cladding, projecting balcony with brackets.