THE VICTORIAN & ART DECO ENSEMBLE OF MUMBAI

SUBMISSION TO UNESCO AS A WORLD HERITAGE SITE

BUILDING INVENTORIES



PREPARED FOR GOVT. OF MAHARASHTRA SUPPORTED BY MMR-HCS, UDRI, OCRA FORT, KGA

PREPARED BY

ABHA NARAIN LAMBAH ASSOCIATES CONSERVATION ARCHITECTS & HISTORIC BUILDING CONSULTANTS

THE VICTORIAN & ART DECO ENSEMBLE OF MUMBAI- BUILDING INVENTORY

	idan		07	
	Idan	Common Ref No: 075		
		Card No: 116	VEER NARIWAN ROAD	
Willy, Su		Ward (Part): A (Part III)		
- Min		CS No: 11(Fort division)		
	A CONTRACTOR	Plot Area: Part of 91693.08 sq. m		
14/10		B U Area: -		
1 17		Date: 10/11/04		
199 B	Adapted in the second s	Recorded by: Prachi Merchant	THE THE THE	
AND A CONTRACT	HARDING , THE REAL PROPERTY OF	Reviewed by: UDRI		
-	2			
THE STAN	- AND	Int: Not applicable		
		Ext: Prachi Merchant, Sonal Modak		
		Photo Ref: 075_Oval Maidan.	MADAN FANKTUR	
		Reviewed in 2013		
			Location Plan	
1.0		Denomination		
1.1	Name of Premises	Oval Maidan		
1.2	Earlier Name	Oval Maidan		
1.3	Built in:	-	Extension Date: -	
2.0		Access		
2.1	Main		laharshi Karve Road, Madam Cama Road & Vee	
£.1	Man	Nariman Road		
2.2	Subsidiary	-		
2.2				
3.0		Ownership pattern		
3.1	Present	Owner - State Government		
3.1	Past	Owner – The Governor of Bombay and Othe		
3.3		Owner	12	
3.3	Status	Owner		
10		Use		
4.0 4.1	Drocont		Public open space used partially as a walking track, cricket ground and a pedestrian	
4.1	Present			
4.2	Past		thoroughfare between Maharshi Karve Road and Karmaveer Bhaurao Patil Marg Public open space	
4.2	Usage	Daily		
4.3	Usage	Dally		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)		The central open space is located in a plot bound by Karamveer Bhaurao Patil Marg in the	
J. I	Townscape (Maninade)		dam Cama Road in the south and Veer Narimar	
		Road on the north side.		
			separating the fort district from the rest of the	
		city.		
		The buildings around this space form an imp	ortant nature of the townscape of the city with	
			ortant nature of the townscape of the city with y building, Secretariat building, High Court and	
		Victorian Neo-Gothic buildings like Universit	y building, Secretariat building, High Court and	
		Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side.		
5.2	Architectural Description	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on th	y building, Secretariat building, High Court and	
5.2	Architectural Description	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the	
5.2	Architectural Description	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west.	
5.2	Architectural Description	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west.	
		Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style -	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space.	
5.2	Intrinsic	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3		Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style -	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3	Intrinsic	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
<u>5.3</u> 5.4	Intrinsic	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3 5.4 6.0	Intrinsic	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
	Intrinsic	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3 5.4 6.0 6.1	Intrinsic Value Classification	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J Topography -	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3 5.4 6.0 6.1 7.0	Intrinsic Value Classification Floors	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3 5.4 6.0 6.1 7.0 7.1	Intrinsic Value Classification Floors Plinth	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J Topography -	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3 5.4 6.0 6.1 7.0 7.1 7.2	Intrinsic Value Classification Floors	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J Topography -	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3 5.4 6.0 6.1 7.0 7.1	Intrinsic Value Classification Floors Plinth	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J Topography -	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3 5.4 6.0 6.1 7.0 7.1 7.2	Intrinsic Value Classification Floors Plinth Walls	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J Topography -	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3 5.4 6.0 6.1 7.0 7.1 7.2 7.3	Intrinsic Value Classification Floors Plinth Walls Floor Stairs	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J Topography -	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	
5.3 5.4 6.0 6.1 7.0 7.1 7.2 7.3 7.4	Intrinsic Value Classification Floors Plinth Walls Floor	Victorian Neo-Gothic buildings like University PWD building built in 19 th century lined on the residential buildings on the western side. Planning and Features A large open space that was once at the edge Victorian Neo-Gothic buildings on the east a The recently added railing that encircles the Style - One of the most important public spaces in t A(his), B(uu), C(seh), E, I(sce), J Topography -	y building, Secretariat building, High Court and e eastern side and 20 th century Art Deco style ge of the city but today stands in between the nd the Art deco buildings on the west. entire space. he city.	

THE VICTORIAN & ART DECO ENSEMBLE OF MUMBAI- BUILDING INVENTORY

) Oval Maid	lan	075	
7.8	Finishes	•	
7.9	Interiors (Movable & Immovable)	Movable	
		•	
		Immovable	
7 10	0	-	
7.10	Compound/ Fence/ Gate	MS fence	
7.11	Curtilage/ Unbuilt space/ Out Buildings/		
	Landscape	Sorabjee Shapurjee Bengalee installed at the North and South end of the Maidan	
8.0		Services & Utilities	
8.1	Lighting	Services & Unities	
8.2	Ventilation	•	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution		
8.7	Other (HVAC/BMS/Security Systems)		
0.7			
9.0		Condition	
9.1	Plinth		
9.2	Walls	-	
9.3	Floor	•	
9.4	Stairs	•	
9.5	Openings		
9.6	Roofing		
9.7	Articulation & Finishes		
9.8	Services		
9.9	Out Buildings	Poor – East side sheds are not maintained well.	
9.10	Overall Conditions	Good Maintenance level Good	
10.0		Transformation	
	Form		
	Structure	Bus stop and BMC Sheds have sprung up on the eastern edge.	
	Articulation & Finishes	· · · · · · · · · · · · · · · · · · ·	
11.0		DP Remarks/ Perceived Threats	
		Plot demarcated asOpen Spaces in DP	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		After the demolition of the Fort in the mid-1860s, many new building plots and roads were laid	
		out on the freed space. The single stretch of open space known as the Esplanade, which lay	
		to the west of the Fort, was thus subdivided into four distinct sections comprising the Cross	
		and Azad maidans in the north, the central portion of the Oval maidan, and the Cooperage	
		maidan in the south. The open greensward of the Oval maidan provides a counterpoint for	
		the row of 1930s Art Deco residential houses at its western periphery, valiantly facing the	
		imposing 19th century Gothic edifices on the eastern edge. Trees that line the maidan where	
		dozens of cricket pitches are set up during the day. In addition to its use as a cricket ground,	
		the Oval is also used as a shortcut by thousands of commuters. The Oval, which once had a	
		riding track on the periphery known as Rotten Row, was restored and re-fenced by the OVAL	
		Trust in 1997.	
		<u>References:</u> SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks,</i> Bombay : Eminence	
		Designs Pvt. Ltd.	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture,	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc.	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc. INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and</i>	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc. INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and</i> <i>Structures listed for Conservation.</i>	
		FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc. INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and</i> <i>Structures listed for Conservation</i> . SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay :	
		 FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. 	
		 FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in 	
		 FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. 	
		 FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within, Bombay : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay. 	

0 Oval Maidan




V1 City (Civil & Sessions Court (Old Se	ocretariat) 074
VICity		Common Ref No: 074
		Card No: 115
		Ward (Part): A (Part III)
	and the second s	CS No: 31(Fort Division)
		Plot Area: 1085.01 sq. m
		B U Area: -
9-		Plot Area: 1085.01 sq. m B U Area: - Date: 28/12/2004
		Recorded by: Arun Wadhwa
		Reviewed by: UDRI
100	J. S.	Int: Arun Wadhwa, Prachi Merchant
.并		
	A CONTRACTOR	Ext: Arun Wadhwa, Prachi Merchant
		Merchant Photo Ref: 074_Old Secretariat.
		The second s
1.0		
1.0	Name of Dramiase	Denomination
1.1	Name of Premises	Old Secretariat
1.2	Earlier Name	Offices of the Government of Bombay
1.3	Built in:	Completed March 1874, Commenced April Extension Date: -
		1867
2.0		Access
2.1	Main	Karmaveer Bhaurao Patil Marg – vehicular and pedestrian
2.2	Subsidiary	A. S. D'mello Road (University road) - vehicular and pedestrian
3.0		Ownership pattern
3.1	Present	Owner - State Government Of Maharashtra
3.2	Past	Owner – The Governor of Maharashtra
3.3	Status	Owner
4.0		Use
4.1	Present	City Civil and Sessions Court, Post Office and Sheriff's Office.
4.2	Past	Offices of the Government of Bombay, Secretariat.
4.3	Usage	Institutional - Court of Law
5.0		Significance and value Classification
5.1	Townscape (manmade)	Long prominent building facing the oval maidan to its west, placed
		alongside High Court, University, PWD offices.
		The building is built in the same period and with similar architectural
		language, has been consciously conceived as an urban design
		gesture, forming an interesting skyline along the eastern edge of Oval
		maidan.
		Accessed through the central porch along the long western front and
		also from the rear eastern side.
5.2	Architectural Description	Planning
		Long symmetrical building planned along the central staircase with
		slightly projecting wings splayed at the corners.
		Large floor heights provide increase the overall scale of the building
		with a high pyramidal roof tower above the central staircase.
		A continuous verandah along the long eastern side connecting all
		activities varying from first floor offices to courtrooms on the second
		and third floors.
		Toilets and other ancillary facilities are attached to the long eastern

V1 City C	Civil & Sessions Court (Old S	Secretariat)	074
		 verandah. Ground floor has PWD and Sheriff's office. Library is placed in the central wing on the first floor. Registrars and staff activities are accommodated along the long length of first floor. Courtrooms along with the judge's chambers are placed on the second and third floor. Western side verandahs accommodate varied staff areas and judge chamber. An annex building has been added parallel to the long rear side and connected by floor level passages. Features Large pointed recessed arch opening in the projecting gable end at front and a high pyramidal roof tower in the centre of the long west façade. Polychromatic arched openings, alternate grey basalt with buff porbander pointed arches on ground and red basalt with buff porbander pointed arches on upper floors. Decorative terrace cornic band, continuous along the entire length of the building and central tower base. Large iron brackets supporting deep awnings on the front façade. Intricately carved floral relief panel in arched openings with medallio at the main porch entrance. Stone carved lion head in column capitals below the central staircas landing. Highly intricate wooden tracery ventilator panels within pointed arch openings. Style The building derives influence from Venetian Gothic style of architecture 	s is the nder ce
5.3	Intrinsic	Porte-cochere (porch) bears Governor Frere's coat of arms, a lasting tribute to his vision for Bombay and its Governance.	g
5.4	Value Classification	A(arc), A(his), B(per), B(des), B(uu), C(seh), D(bio), E, F, I(sce)Recommended grade:	Ι
6.0		Topography	
6.1	Floors	G+3	
7.0		Construction	
7.1	Plinth	Normal height plinth dressed in Malad ashlar stone course with grey basalt plinth protection.	l
7.2	Walls	Load bearing rubble masonry stonewalls.	
7.3	Floor	Shahabad stone slabs on wooden supports and steel girders in case large spans.	9 OL
7.4	Stairs	Central C- shaped cantilevered stone staircase with an open well accommodating lift block. Wooden spiral stairs supported from the walls, at both the ends of the long front facade. Two narrow spiral service stairs centrally supported on the rear long side.	
7.5	Openings	High and shallow pointed arch openings on circular columns in verandahs. Multi foil ventilator in the arch portion of openings. Doub door window with outer louvered and inner diamond sash glazed paneled shutters. Wooden tracery works in the ventilator panels. Dormer roof windows at regular intervals along the long roof.	
7.6	Roofing	Steep sloping Mangalore tile roof, high pyramidal tower at center an	d

V1 City C	ivil & Sessions Court (Old Secr	etariat) 074	
		corner blocks, supported on intricate wooden truss work.	
7.7	Articulation	Continuous cornice band at terrace level and base of pyramidal roof over high central tower, recessed arch opening, large metal bracket supporting sloping awnings on the western verandah fronts. Ornate column capitals supporting arches over circular columns.	
7.8	Finishes	Yellow Kurla stone external dressed facades and basalt dressing to inside of verandah walls. Plaster painted internal wall surfaces. Wood paneled ceiling in major courtrooms. Original Minton tiles on the ground floor and also in some courtrooms on the upper floors. Varied floor finishes in the rest of the building.	
7.9	Interiors (Movable and Immovable)	Movable Neo Gothic scheme included John Adam's furniture design in teak inlaid with blackwood, few courtrooms. Immovable	
7.10	Compound/ Fence/ Gate	Low parapet wall upto 1 M with iron railing above. Two iron gates on the front western side and also a gate on the rear eastern side.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	 t Large plot with various ancillary structures. G+5 annex building parallel to the rear east side. G+5 N.C.C building to the southern side. Long single storied structure at the rear side, houses emergency staff quarters. P.W.D barrack buildings abut the front boundary wall. Paved space at the rear and side spaces serve as vehicular accesses. 	
8.0		Services and Utilities	
8.1	Lighting	Adequate natural light except for some areas including central staircase, thus supplemented by artificial light.	
8.2	Ventilation	Adequate natural ventilation supplemented by artificial means.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Sanitation)	MCGM	
8.6	Fire Precaution	Fire extinguishers	
8.7	Other (HVAC/BMS/Security Systems)	Window air conditioning units.	
9.0		Condition	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Fair - replacement of wooden supporting members with steel sections	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation and Finishes	Good	
9.8	Services	Fair	
9.9	Out Buildings	Fair	
9.10	Overall Conditions	Good Maintenance level: Good	
10.0		Transformation	
	Form	Lift shafts and connecting bridge with the annex added to the long rear side.	

V1 City Ci	Civil & Sessions Court (Old Secretariat) 07	
	Structure	Many toilets and partitions built in <i>verandah</i> spaces.
	Articulation and Finishes	Iron grills fixed to veranda openings damaging column capitals.
11.0		DP Remarks/ Perceived Threats
		Plot has been demarcated for law and order in DP
12.0		Additional Notes/ References/ Documents available
12.0		Additional Notes:
		The building, with a frontage of around 450 feet, was designed in a Venetian Gothic style by Colonel Wilkins of the Royal Engineers and completed in 1874. It now houses a number of courts and government departments. Constructed in rubble and stone, the walls are faced with Kurla stone. The corridor arches on the ground floor are of alternate Porebunder stone and blue basalt while those on the first floor level are alternate red basalt and Porebunder stone. The pillars are moulded Kurla cut-stone, corridor shafts, capitals and cornices of milky white Hemnagar sandstone. There are two wings to the east, the ends of which form three sides of an octagon. The main staircase is illuminated by shafted windows, contained in a lofty arch rising through the building and culminating in a large gable at the top. The arcaded verandahs facing the westerly breezes are designed to provide ventilation and light to the building. The main doors are of beautifully carved wood and were designed by George Twigge Molecey. Frontage of about 450 Ft. and the central tower rises about 170 Ft high. Designed by Colonel H St Clair Wilkins of the Royal Engineers and executed by PWD from its own funds and became a Paradigm of
		subsequent work in Bombay. References: SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks,
		Bombay : Eminence Designs Pvt. Ltd. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual</i>
		<i>dictionary of Architecture</i> , Division of International Thomson Publishing Inc.
		Christopher W London, <i>Bombay Gothic,</i> India Book HousePvt. Ltd. INTACH (1990) <i>Preliminary unedited listing of Unprotected</i> <i>Monuments, Buildings and Structures listed for Conservation.</i>

V1 City Civil & Sessions Court (Old Secretariat)














074

V1 City Civil & Sessions Court (Old Secretariat)





FOR THE OFFICES OF THE COVERIMENT OF BOMBAN
AND EMECTED FROM THE DESIGNS SUBJICTION ON THE 29% SEPTEMBER BOX
COLORED (THER CAPTAIN) H. SE CLAIR WILEINS R.E. A.D.C. TO THE QUI
Hin Excellency this Honourable Sin Bartle Frame GoSil K.c. Governor and Presidery in Council And Sanctiones By
THE REALT HOROURABLE SIN CHARLES WOOD BART C. C.E. HER MAJESTY'S SECRETARY OF STATE IN COUNCIL OR THE 164 JUNE 1666.
THE WORK WAS CONCERCED ON THE 16W APAIL 1867. IS EXCELLENCY WE REART HOROMANE SO WILLIAG ROBERT SERVICE THE CAR COVERING AND FRESHDERT IN COUNCIL. AND WAS CONFLETED ON THE 20 W MARCH 1874. HIS EXCELLENCY THE HOROMARD FILSTER DEMOND WODEHOUSE GOVERNOT AND FRESHDERT IN COUNCIL.
The work was carried out under the inmediate orders o Captain C.W. Finge R.EPROM April1667 To Tovemen La Colonel J.A.Fuller R.E Novement 1867 . May J.H.E. Harr M. Inst C.E May 1871 . Rovement
COLOREL J.A.FULLER R.E DOVEMBER 1872 . MARCH Mg WASUDEW BAPUJI KARITKAR ASSISTANT ENGINEER BEIRG IN C ESTIMATE AS SARCTIONED RS 12.80.731.
ACTUAL COST 12,60,854.













V1-vi

V2a Sir Cowasjee Jahangir Convocation Hall (University of Mumbai Complex) 076(a)				
vza Sir C		Common Ref No: 076(a)	676(a)	
		Card No: 117		
		Ward (Part): A (Part III)		
		CS No: 148 (Fort division)	81 11/11 77 1 12 - B	
			il fer s data	
		Plot Area: Part of 22108.03 sq. m	11.15 江西	
STAT.	A MAR	B U Area: -		
TAN		Date: 29/12/2004	Oval Maidan University Road	
		Recorded by: Arun Wadhwa	il g (induction)	
	A STATE THE DESIGN AND A STATE OF A STATE	Reviewed by: UDRI	amover Bhauao Pall IA	
		Int: Arun Wadhwa, Zankhana	and and a second	
		Prajapati		
La Mar		Ext: Arun Wadhwa, Zankhana	and a second sec	
	N OF THE O CONTRACTOR	Prajapati		
		Photo Ref: 076(a) Convocation		
		Hall.	No. 1	
		Reviewed in 2013	Location plan	
1.0		Denomination		
1.1	Name of Premises	Sir Cowasjee Jahangir Convocation	Hall of the University of Bombay.	
1.2	Earlier Name	Initially known as University Senate		
=		Hall.		
1.3	Built in:	Completed 1874, commenced 1869	Extension Date [,] -	
1.5				
2.0		Access		
2.1	Main	K. Bhaurao Patil Marg – Vehicular a	nd Pedestrian	
2.2	Subsidiary	M.G. Road, A. S. D'mello Road, Uni		
3.0		Ownership pattern		
3.1	Present	Owner - State Government		
3.2	Past	Owner – The University of Bombay	& Others	
3.3	Status	Owner		
_				
4.0		Use		
4.1	Present	Convocation Hall, Seminar Hall		
4.2	Past	Convocation Hall.		
4.3	Usage	Institutional - Occasionally		
5.0		Significance & Value Classification	on	
5.1	Townscape (manmade)	The building forms part of an impo		
		buildings planned as urban design		
		the Oval Maidan.	greater and ing obtained rate along	
5.2	Architectural Description	Planning		
0.2		Convocation building is placed al	longside the Library building and	
		Rajabai tower at the western edge		
		an ample lawn in front. Entrance		
		side.	is anough a potent from the hortin	
		Large rectangular hall with an at	ttached semicircular apse portion	
		serving as a stage at the rear.	adened semicircular apsc portion	
		An extended porch and spiral stairc	ases flanking the gable end on the	
		north side indicate the entrance w		
L		ן הטונה שוער והעורמוב נהב בחונומהורה M	nui a iuyei space rigiit beluw the	

V2a Sir C	owasjee Jahangir C	nvocation Hall (University of Mumbai Complex) 076(a)
		gallery.
		Projecting balconies on three sides except the rear, serve as viewing
		galleries with long wooden benches therein.
		Verandah spaces flank the long hall on both the longer sides at ground
		and gallery floor. Features
		High gable ended north side with a large recessed circular rose
		window flanked by projecting open arcade spiral staircases and distinc
		steep spires at all the four corners.
		Semicircular apse with pointed arch openings, decorative column
		capitals, cornice band, terrace parapet. Identical east and west arcade
		facades with setback buttressing and projecting stone gargoyles.
		Larger pointed arches on ground floor with smaller arches on the firs
		floor with foliated circular stain glass panels. Intricate ornamenta
		features – floral pattern, animal forms on cornice band, column capitals
		in the interiors.
		Circular rose window with stain glass panels depicting Zodiac signs in the gable end on the northern facade. Highly ornate iron brackets
		supporting projecting gallery and parapet railings.
		Supporting projecting gallery and parapet railings.
		The building displays Neo Gothic features in it architecture.
5.3	Intrinsic	Famous personalities like William Wordsworth, Lord Hardingee
		Dadabhai Naoroji, JRD Tata, etc. have been conferred Honorary
		degree of LL.D.
		Circular rose window with twelve divisions and stained glass depicting
		the months of the year and signs of the Zodiac. Stained glass panels
		depicting coats of arms of numerous Governors, eminent personalities
5.4	Value Classificatio	and countries. A(arc), A(his), B(per), B(des), B(uu), C(seh), Recommende I
5.4		D(bio), E, F, I(sce)
6.0		Topography
6.1	Floors	Ground + mezzanine
7.0	Dlinth	Construction
7.1	Plinth	Plinth height about 1.0 M dressed in grey basalt ashlar stone with projecting top cornice in buff basalt course.
7.2	Walls	Load bearing rubble masonry walls and circular stone columns.
7.2	Floor	Wooden floorboards supported over wooden members form first floor
,		gallery. Groin vaulted verandas of the first floor. Raised wooder
		platform forms the convocation stage at the ground floor.
7.4	Stairs	Pair of circular stone spiral stairs flanking both the front sides
		supported on load bearing stonewalls. Elaborate stone cut navel pos
		and decorative balusters. Very narrow spiral stairs lead to the terrace
7 -		within spires on all the four corners.
7.5	Openings	Large pointed arch openings with smaller arches and circular openings
		within. Double shutter door openings, outer wooden louvered and inne
		glazed geometric sash panels. Varied color and design of stained glass panels in arch and circular ventilators.
7.6	Roofing	High sloping Mangalore tile gable ended roof over the main hall, lower
7.0		over the side verandahs, internally teakwood planking forms vault
		Steep stone spires over circular staircase at the corners.
7.7	Articulation	Wheel rose window in two layers with twelve divisions in each


V2a Sir C	owasjee Jahangir Convocation	Hall (University of Mumbai Complex) 076(a)
		Decorative cornice bands, finely carved column capitals on circular columns
7.8	Finishes	Malad stone ashlar course dressed in external and verandah walls. Ornamental carved features in soft Porbander stone. Plastered painted internally. Granite circular columns supporting entrance arches. Minton floor tiling and stained glass panels in window and ventilator openings. Decorative Iron brackets supporting projecting gallery and parapet railings.
7.9	Interiors (Movable & Immovable)	Movable Marble busts of eminent personalities like Pherozshah Mehta, Kashinath Trimbak Telang, Narayan Chandravarkar, Vithal Chandravarkar, Chimanlal H Setalvad. Old wooden tables. Immovable
7.10	Compound/ Fence/ Gate	Low compound wall with iron railing above and central iron gate.
7.11		Located within the large university campus along with Library, Rajabai Clock Tower and the main University building. Expansive lawn with old and varied trees in the central open space. Statue of Sir Cowasjee Jehangir in front of the entrance porch. Marble statue of Thomas Ormiston, Dean of faculty of Civil Engineering to the east side lawn.
8.0		Services & Utilities
8.1	Lighting	Adequate natural light through large openings on all sides, supplemented by artificial light fixtures.
8.2	Ventilation	Adequate natural ventilation, also supplemented by artificial means.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Few fire extinguishers.
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Out Buildings	-
9.10	Overall Conditions	Good Maintenance level: Good
10.0		Transformation
10.0	Form	-
	Structure	-
	Articulation & Finishes	Intricate stone carvings inside the interiors have been painted over. Cement pointing done over stone dressed courses.
11.0		DP Remarks/ Perceived Threats

V2a Sir Cowasjee	Jahangir Convocation Hall (University of Mumbai Complex) 076(a)
	Plot has been demarcated for educational amenities in DP
12.0	Additional Notes/ References/ Documents available
	Additional Notes:
	The Fort University complex comprises the Library, the Senate or
	Convocation Hall and administrative offices. The Hall 104 feet long, 44
	feet wide & 63 feet high designed to seat about a thousand people.
	The university complex took eight to twelve years to design and
	complete and the buildings established new standards of proficiency in
	the city's Architectural profession.
	Eminent British Architect Sir George Gilbert Scott designed the
	building.
	Estimated cost 415804/- Actual cost 379389/-
	Coats of arms of Sir Bartle Frere, Sir Seymour Fitzgerald, Sir Philip
	Wodehouse, and Sir George Russell Clerk, successive Governors of
	Bombay can be seen in the eastern lancet lights. The Rose, the
	Shamrock and the thistle symbolise England, Ireland and Scotland in
	the stained glass below. Sir Cowasjee Jehangir's coat of arms and
	those of England, Scotland, Ireland, Wales and Bombay are depicted
	in the western stained glass windows.
	References:
	INTACH (1990) Preliminary unedited listing of Unprotected
	Monuments, Buildings and Structures listed for Conservation.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities
	Within, Bombay : Eminence Designs Pvt. Ltd.
	RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT
	(1994) <i>The Fort Precinct in Bombay – Conserving an Image Centre</i> , 2
	Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual
	dictionary of Architecture, Division of International Thomson Publishing
	Inc.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks,
	Bombay : Eminence Designs Pvt. Ltd.
	ABHA NARAIN LAMBAH <i>Through the Looking Glass – The Grade I</i>
	Heritage of Mumbai, Mumbai : Urban Design Research Institute,
	Jasubhai Media and Super Book House.
	Imperial designs & Indian realities the planning of Bombay city 1845-
	1875 – Mariam Dossal, Oxford Indian paperbacks
	SIR BANNISTER FLETCHER A History of Architecture, CBS
	publication and distributors.













076(a)














076(a)














V2 h₋c II	Iniversity Library and Annexe	huilding	076(b)
		Common Ref No: 076(b)	070(b)
		Card No: 118	811 117# (ST) 11
2			Il for e the
		Ward (Part): A (Part III)	
精神	A A A A A A A A A A A A A A A A A A A	CS No: 148 (Fort Division)	
		Plot Area: 22108.03 sq. m	Oval Maidan University Road
		B U Area: -	and the second second
		Date: 28/12/2004	
1		Recorded by: Zankhana Prajapati	don loui
	AND A CONTRACTOR	Reviewed by: UDRI	and the second sec
	Convocation Hall	Int: Zankhana Prajapati, Arun	
	and the second	Wadhwa	
		Ext: Zankhana Prajapati, Arun	
1		Wadhwa	
	Sector Marsh	Photo Ref: 076_Mumbai University	CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR
		Library.	
4.		Reviewed in 2013	
1			Location Plan
1111	Annex building		
1.0		Denomination	
1.0	Name of Premises	University Library and Annex buildir	ng
1.1	Earlier Name	, , ,	iy
1.2		Bombay University - Library	Extension Annov building
1.3	Built in:		Extension Annex building:
		completed in 1878.	Date 1920's
2.0			
2.0		Access	
2.1	Main	Karamveer Bhaurao Patil Marg	
2.2	Subsidiary	Annex building - Mahatma Gandhi	Marg (gate closed) and University
		road, A D'mello road (gate closed)	
3.0		Ownership pattern	
3.1	Present	Owner - State Government.	
3.2	Past	Owner – The University of Bombay	& Others
3.3	Status	Owner.	
4.0		Use	
4.1	Present	Library	
4.2	Past	Library	
4.3	Usage	Daily	
5.0		Significance & value Classificatio	n
5.1	Townscape (Manmade)	The library and Rajabai Tower lies a	
0.1		Oval maidan and between the Old S	Secretariat and High Court.
		Main access to the building is through	
		The building forms part of an impo	
		buildings planned as an imposing u	
		rule along the Oval maidan front.	San design gesture during colonial
		The Rajabai clock tower is an in	nortant landmark symbolizing for
		many years, the city of Mumbai.	iponani ianumark symbolizing tu
		Annex building is located at the ea	st side of the plot facing the street
		on three sides.	st side of the plot lacing the sileet
5.2	Architoctural Decoription		
D.Z	Architectural Description	Planning Convocation Hall:	


V2 b-c University Library and Annexe bu	uilding 076(b)
	Library building is placed alongside the Convocation Hall at the
	western edge of the large university campus with an ample front lawn.
	Entrance is through a <i>porte-cochere</i> formed by Rajabai tower and an
	arcade at the ground floor.
	It is rectangular in plan with the Rajabai clock tower in the center of the
	front façade behind which is a half octagonal projection of the main
	staircase block.
	The building is a ground plus one structure. The Rajabai tower is 280
	feet high.
	The two storey University Library has Rajabai tower abutting the
	center of the main building, with large pointed arch openings at the
	base to provide the Library's <i>porte-cochere</i> .
	The ground floor has a huge groin-vaulted entrance hall with a large
	reception counter on right.
	Two lecture rooms are separated from this hall by wooden screens,
	each with stained glass inserted within.
	The front two corners have spiral staircases terminating in conical
	feather cut patterned roofs. The central staircase is placed to the left of
	the reception desk. Walking up from the ground floor, where two cross arches spring from a capital, we can see carved heads of Homer and
	Shakespeare.
	The staircase also has a vaulted ceiling lit by large lancet stained glass
	windows. At first floor the landing leads to the large reading room with
	a teak wood vaulted roof above it.
	The reading room has a 32-foot high ceiling, and is lit from the north
	and south by large stone Early English bar-tracery windows, and from
	east and west through a series of large pointed arch windows, shaded
	by an arcade on west.
	The clock tower consists of seven storeys; the fourth floor of the tower
	contains clock's mechanism. The opal glass dials can be illuminated at
	night, originally by gas jets placed behind them.
	The corner balconies below the dial were intended as viewing points. It
	forms decorative pinnacles at the top of the tower; the canopies
	support the buttress holding the octagonal crocketed lantern that
	terminates the composition.
	Annex building:
	Annex building is a 'C' shaped building enclosing courtyards and
	central access paved road.
	The building is symmetrical with a central wing and north and south
	wing similar wings. Each wing has a central staircase higher than the
	rest. The verandahs of the East and South wing face the street. The
	rooms are accessed through verandahs overlooking the internal
	courtyard.
	North wing occupies the library extension and Record room on the ground floor, the Vice changellars wing on the first floor with verandahe
	ground floor, the Vice chancellors wing on the first floor with verandahs
	overlooking the internal courtyard. The south and east wings occupy
	administration offices, library, canteen etc Features
	Two intricately carved spiral staircase shafts at the two ends and centrally with Rajabai tower mark the building front façade.
	The main building is divided into four bays on each side at ground floor
	and eight bays on first floor level forming an arcade at both first and
	ground floor levels.
	The elevations show and interesting composition using Malad,
	The devaluous show and interesting composition using initiality,

V2 b-c Ur	niversity Library and Annex	e building 076(b)	
		Porbander, Coorla, red sandstone and gray basalt stone.	
		An arabesque patterned cornice band marks each floor with floral and animal motif in it.	
		 All openings are huge pointed arched openings with two lancet window and multifoil rose window within it forming a high gothic characteristic. The arches are marked with ornate intrados and extrados with decorative floral and motif bands. The arch ends are marked by mask or floral motif. The entrance arch has ornate tracery at the base of Rajabai clock tower. The ground floor arcade is marked with decorative column capitals and ribbed-groined vault. The first floor arcade is formed by multifoil arch with multifoil rose window above it with decorative spandrel and cornice band above which railing is present. On the Rajabai clock tower there are projecting balconies supported on decorative brackets and have ornately carved railing with sculptures on it - four sides representing 24 castes of western India, standing within niches or sitting under canopies of crocketed pinnacle forms of varying Neo-Gothic designs. Beautiful stained glass in arched window openings and ornamentation elements such as grotesque flying gargoyles, buttresses, floral motifs, medallions, impost bands, crocketed pinnacles and finials. Annex building is clad with buff stone, with central staircase higher bay, arched openings, projecting columns externally like pilasters in stone 	
		5	
5.3	Intrinsic	 The building displays characteristics of Neo Gothic style. The library building, houses a fine collection of rare manuscripts, maps and books. Marble busts of Homer and Shakespeare are present on the cross arches underneath the landing to the staircase. On the stone steps at the entrance to the library is a benchmark similar to those at the Town Hall and the PWD building. 	
5.4	Value Classification	A(arc), A(his), B(per), B(des), B(uu), Recommended I	
		C(seh), D(bio), E, F, I(sce) grade Annex bldg: IIA	
6.0		Topography	
6.1	Floors	G + 1 with clock tower and book stacking area with mezzanines. G + 2 Annex building	
7.0		Construction	
7.1	Plinth	Low stone plinth with edging done for plinth protection.	
7.1	Walls	Load bearing stonewalls with stone ashlar masonry as external fascia	
, . <u>c</u>		and plastered and painted inside with circular columns for support.	
7.3	Floor	Floor rests on ribbed-groined vault in arcade and ground floor hall and has coffered ceiling in the adjacent two rooms.	
7.4	Stairs	Six staircases are present. The main central staircase is a grand stone spiral staircase with stain glass windows, decorative Corinthian column capitals and animal form post and stone balusters. Two spiral stone staircases are at the two corners in front of the building while one staircase is inside the Rajabai tower. Two cast iron staircases are also found in the book stacking area of which one was spiral and other doglegged.	

	niversity Library and Annexe bu			076(b)
7.5	Openings	Large pointed arch openings with s		1 0
		within. Double shutter door open		
		inner glazed geometric sash panel		and design of stain
		glass panels in arch and circular ve		
7.6	Roofing	High sloping Mangalore tile gable		
		teakwood-vaulted ceiling from insid	de, steep stone	spires over circular
		staircase at the corners.		
7.7	Articulation	Cornice bands, Corinthian colu		
		gargoyles, and statues of Indian at		acery, and masks at
		arch ends, floral motifs, projecting b		
7.8	Finishes	Malad stone ashlar course dress		
		Ornamental carved features in soft		e.
		Internal walls are plastered and pai	nted.	
		Flooring is done in Minton tiling.		
7.9	Interiors (Movable &	Movable		
	Immovable)	Old tables, chairs, decorative book	0	handeliers, portraits,
		statues, model of building, reading	ledge.	
		Immovable		
		Plaques, tablets, partition panels,	wooden door	panels with stained
7 10		glass.		the second
7.10	Compound/ Fence/ Gate	Compound wall with stone at the le		ast fron railing. Has
7 1 1	Curtilere/ Unbuilt an eas/ Out	stone gateposts and a cast iron dec		
7.11	Curtilage/ Unbuilt space/ Out	Located within the large university		
	Buildings/ Landscape	Hall and the main university build		
		varied trees in the central open		
		Jehangir in front of the entrance statue of Thomas Ormiston, Dean		
		east side lawn.	of faculty of Civ	II Engineering to the
8.0		Services & Utilities		
8.1	Lighting	Adequate Natural light through do	or-window oper	nings supplemented
		by electric light fixtures.	-	
8.2	Ventilation	Adequate Natural ventilation	through door-	window openings
		supplemented by electric fans.	-	
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing &	MCGM		
	Sanitation)			
8.6	Fire Precaution	Presence of fire extinguishers.		
8.7	Other (HVAC/BMS/Security	-		
	Systems)			
9.0		Condition		
9.1	Plinth	Good		
9.2	Walls	Good		
9.3	Floor	Fair – stacking areas have some ex	posed reinforce	ement in ceiling.
9.4	Stairs	Good		
9.5	Openings	Good		
9.6	Roofing	Indeterminable		
9.7	Articulation & Finishes	Good		
9.8	Services	Fair – electrical wiring runs haphaza	ardly.	
9.9	Out Buildings	-		
9.10	Overall Condition	Good	Maintenance	Good


V2 b-c Ur	niversity Library and Annexe	building 076(b)
10.0		Transformation
1010	Form	-
	Structure	-
	Articulation & Finishes	Painted stonewall and articulation.
11.0		DP Remarks/ Perceived Threats
11.0		Plot has been demarcated for educational amenities in DP
12.0		Additional Notes/ References/ Documents available
		Additional Notes: The Fort University complex comprises the Library, the Senate or Convocation Hall and administrative offices. The Library with the Rajabai clock tower were both designed by the eminent British architect, Sir Gilbert Scott. The library building, housing a fine collection of rare manuscripts, maps and books was commenced in 1869 and completed in 1878. Premchand Roychand, a well-known banker of the last century, funded the library and the 280 feet high Rajabai Clock tower. The ornamentation on the Rajabai Tower includes immense 8 feet tall statues representing the many communities that form the population of cosmopolitan Bombay, modelled by a local engineer, Rao Bahadur Mukund Ramchandra. Inside, the ground floor has two side rooms, a central hall and a staircase vestibule. The upper floor is approached by a stone spiral stairway, along which are lovely stained glass windows. The library reading room on the first floor is embellished with stained glass windows and a remarkable arched teakwood ceiling. The Rajabai Tower clock chimes on the Westminster pattern. The carillon or joybells, which can play 16 different tunes including God Save the Queen, has unfortunately been in disrepair for several years. The restful gardens of the University complex have some unusual, old and beautiful trees and statues. References: INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.</i> SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks,</i> Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture,</i> Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks,</i> Bombay : Eminence Designs Pvt. Ltd. ABHA NARAIN LAMBAH Through the Looking Glass – The Grade
		Imperial designs & Indian realities the planning of Bombay city 1845- 1875 – Mariam Dossal, Oxford Indian paperbacks SIR BANNISTER FLETCHER <i>A History of Architecture,</i> CBS publication and distributors.

















V2 b-c University Library and Annexe building











V3 Bo	mbay High Court		077
		Common Ref No: 077	
		Card No: 119	
		Ward (Part): A (Part II)	VEER NARIMAN ROAD
		CS No: 149	P P FLORA
		Plot Area: 32.61sqm.	ARRAYER BHAURAD PAIL HARG
-	-	B U Area: -	P PAL
las		Date: 26/10/2004	NDH
		Recorded by: Sachin Borkar	BHA
		Reviewed by: UDRI	THE REPORT OF
		Int:	
		Ext: Arun Wadhwa, Prachi Merchant,	UNIVERSITY ROAD
		Sonal Modak, Zankana Prajapati	
		Photo Ref.: 077_High Court Reviewed in 2013	Location Plan
1.0			
1.0	News (D)	Denomination	
1.1	Name of Premises	Bombay High Court	
1.2	Earlier Name	Bombay High Court	
1.3	Built in:	Construction commenced in 1871,	Extension Date (if any): Annex
		Completed in 1878, Building occupied	Building- 1930's.
L		in 1879.	
2.0		Access	
2.1	Main	Karmaveer Bhaurao Patil Marg (Mayo	Road), Entry restricted to Judges
		only.	
2.2	Subsidiary	Dr. Mahamahopadhyay Kane Marg (El	don Road) Common Public Entry,
		subsidiary entry from northern side PW	/D building.
3.0		Ownership pattern	
3.1	Present	State Government	
3.2	Past	State Government	
3.3	Status	Ownership	
4.0		Use	
4.1	Present	Judiciary, Court of Law	
4.2	Past	Judiciary, Court of Law	
4.3	Usage	Daily	
5.0		Significance & Value Classification	
5.1	Townscape (Natural/	High Court forms one of the major build	dings which were planned on the
0.1	Manmade)	Esplanade after the demolition of the fo	
		The main feature that strikes is the imp	
		High Court, the University, the PWD of	
		same period and with a similar archited	
		conceived as an urban design gesture,	
		High Court, which forms a part of the e	
		Oval Maidan, bears a strong visual cha	
		the Maidan.	and the of sign normal across
5.2	Architectural Description	Planning	
0.Z			courtward on the rear side
		It's a U-shaped building with a central of Northern and southern and s	
		Northern and southern ends of the buil specifically planned for administrative p	
		to the Court activities, and Judges chai	
	I	to the Court activities, and Judges that	11DCI 2.


V3 Boi	mbay High Court	077			
		Verandahs and corridors form the major circulation spaces as also the transition between the interiors and exteriors.			
		The main western side entrance has been planned with a porch for Judges			
		and a driveway. Spiral staircases have been strategically planned at the corners of the building, which form the special feature of the facade.			
		 Features The Facade is punctuated with arches and columns supporting the verandahs and corridors that run through the complete length of each floor. The front facade is flanked by four octagonal towers enclosing spiral staircases with steep spires on the top. On either side of the main (western) entrance is a 120 feet high octagonal tower with life-size statues. One is a blindfolded "Goddess of Justice" holding a sword of justice in one hand with equally balanced scales in the other and the second spirelet with "Goddess of Mercy" with hands folded in supplication. Dormer windows punctuate the steep roof slopes. Groined corridor forms the welcoming feature at the central entrance on western side. Style It derives a strong influence from Neo-Gothic style, English Gothic style and 			
		also has certain local influences. Neo-Gothic elements are predominantly observed like spires, pointed			
		arches, traceries etc. that form coherent part of the building facade.			
5.3	Intrinsic Value Classification	The High Court was associated with the National freedom movement of India.High Court forms an important court of archives and records.Prominent freedom fighters, leaders of Independence movement and luminaries have been associated with the High Court.The Historic trial of Lokmanya Balgangadhar Tilak in 1908, was conducted in the imposing Criminal Court, later known as 'The Central Court'.In terms of the features two life-sized stone statues, one of a blindfolded "Goddess of Justice" holding a sword of justice in one hand with equally balanced scales in the other and the second spirelet with "Goddess of Mercy" with hands folded in supplication, surmount octagonal tower on the either side of the western entrance of the High Court.The carved stone detailing found on walls, atop columns, on the springing point of corridor arches, and at many nooks & corners, comprise of botanical motifs and a menagerie of animals, reptiles and birds.The western side corridor arch column capitals are carved in porbandar 			
5.4		A(arc), A(nis), A(cui), B(per), B(des), Recommended T B(uu), C(seh), D(bio), E, F, G(grp), grade: H(tec), I(sce)			
6.0		Topography			
6.1	Floors	G + 3, Mezzanine floors have been added in the corridors of 2 nd and 3 rd floor. Central file store is accommodated in the central roof. Housing is provided for the Court keeper in the north and the south wing. Accommodation was been provided for several Court officers and employees within the apartments in the wings that rise above the roof of third floor.			

V3 Bo	mbay High Court	077
7.0		Construction
7.0	Plinth	The plinth marginally varies in height from east to west, as the site is sloping
7.1		along seaside.
		Two types of stones have been used as different courses namely grey
		basalt and buff basalt.
7.2	Walls	The walls are constructed in rubble, with lime mortar joints. The lintels of the
		openings are of the arched/ flat stone courses and the stone sills of the
		windows project into a sloped coping.
7.3	Floor	Plate iron girders and timber joists support the upper concrete floors with
		tongue and grooved narrow planking on fillets.
		Floor finish consists of clay based and Italian mosaic tiles. In many places decorated Minton tiles have been used.
		Some courtrooms have raised platforms, finished with wooden flooring.
7.4	Stairs	Main Eastern side staircase is an open well staircase constructed in stone.
7.4	Stans	It has a decorative cast iron railing and teak wood handrail.
		Two pairs of spiral private staircases constructed in stone are enclosed in
		octagonal towers.
		Two elliptical staircases on eastern side are constructed in stone,
		cantilevered from the wall. These are provided with decorative cast iron
		railing with carved wooden handrail.
		Nine single flight wooden staircases ascend from third floor to the
		mezzanine and attics. These are provided with wooden balustrades and handrail.
		Seven spiral wooden staircases lead to judges' chambers from third floor.
		These have decorative wreathe pieces, balustrades and teakwood
		handrails.
		Six narrow spiral enclosed stone staircases ascend from the first to the third
		floor.
7.5	Openings	The facade is punctuated with a series of arches supported on columns.
		The door and window openings are also arched with intricately carved
		wooden traceries.
		The teak wood double doors consist of an inner teakwood double leaf fixed
		louvered paneled shutter and an outer teakwood double leaf, glazed paneled shutter with diamond shaped sashes.
		Original iron grilled double leaf doors, lead to spiral staircases.
		Windows consist of teakwood single/ double leaf glazed shutters, with
		diamond shaped sashes.
		High vertical openable windows serve as Clerestory to the Central
		Courtroom.
		Gable Dormer windows are located within the roof slopes.
7.6	Roofing	The High court has a hipped roof with terracotta tiles over tongue and
		grooved teak planking supported over teak wood trusses.
		Gable Dormer windows punctuate the roof slopes at regular intervals.
		The central portion has a high pyramidal roof with stone turrets at the four corners.
		The roof of the octagonal towers end in steep stone decorated spires.
7.7	Articulation	Extensive detailed ornamentation is seen more in interiors than the
		exteriors.
		Animals, plant life and mythological characters have been depicted through
		the bands, cornices, column capitals, column bases, mouldings and
		springing point of arches.
		All along the corridors are stone carved balustrades and handrails.

V3 Bon	nbay High Court	077
		Carved stone water fountains are positioned at various places on each floor. Each floor is accentuated by the porbunder projecting stone bands supported by carved stone brackets.
7.8	Finishes	The walls are finished with hammer dressed grey Sewree basalt stone in shallow courses (approximately 10 cm) on exterior face, and finished with lime plaster from inside. The lighter bands of Porbunder limestone used in the column capitals and balustrades relieve the grey exterior facade. The buff basalt and red sandstone in the columns, arches and other decorative elements give Polychromatic effect to the exteriors. The floor in the courtrooms and corridors were originally paved with Minton and Italian Mosaic tiles.
7.9	Interiors (Movable & Immovable)	 Movable Each of the judges' chambers is equipped with a round table, chairs, a couch, carved cabinets and bookcases. A unique piece of furniture, served as a miniature pantry resembling size, shape and appearance to a baptismal font. Wooden furniture like benches, chairs form a significant part of the interiors. There are various portraits of former judges in the courtrooms and the library Immovable Statue of M C Chagala, First Indian Chief Justice of Bombay is kept in a niche of the second floor corridor. Commemorative marble plaque with decorative stone border, describing the title of the building, date of completion and details of people involved in the construction, is inscribed in the wall at the first floor landing of the main staircase. There is an ornamental wooden canopy above judge's seat in the main courtroom. Viewing gallery on the three sides of main courtroom are finished with
7.10	Compound/ Fence/ Gate	teakwood floor, heavily carved teakwood railings and supporting brackets. The Compound wall is made in the grey basalt stone upto an approximate height of 2'6", above which is an iron Railing with decorative motif at the top. The annexe building and other ancillary structures form the eastern edge of the premises. The original Iron entrance gates still stand in their places.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	The eastern side open court forms as a pedestrian and vehicular entrance to the all the buildings of the premises. Ancillary structures for the garages, a canteen and support services such as police chowky, pump rooms etc. are located on the east side along the annexe building. The western and southern side has a soft landscaped garden with some rare cannonball trees. Statue of Sir D F Mulla and Sir Lawrence Jenkins, distinguished counsel and Judge respectively, represented Bombay High Court on the judicial committee, are located in the front lawns along the driveway. The northern side is shared with the PWD building.
0.0		
8.0 8.1	Lighting	Services & Utilities Natural daylight through verandahs and skylights together with electrical lighting fixtures suspended from high ceiling.
8.2	Ventilation	Verandahs act as wind catchers allowing natural ventilation through traceries and openings. Dormer windows supplement the ventilation


V3 Bor	nbay High Court	077
		process.
		Electrical fans have been suspended from high ceiling and few courtrooms
		are provided with forced ventilation like Air- conditioners.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing &	MCGM
	Sanitation)	
8.6	Fire Precaution	Initial fire fighting and a few additional equipments like, hosepipes and hose
		taps are installed on each floor.
8.7	Other	Security guards posted.
	(HVAC/BMS/Security	
	Systems)	
9.0		Condition
9.1	Plinth	Good.
9.2	Walls	Good
9.3	Floor	Good.
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Out Buildings	Good
9.10	Overall Conditions	Good Maintenance level : Good
10.0		Transformation
	Form	The insensitive installation of lift shafts has destroyed the integrity of the
		aesthetics of the building.
		Asbestos sheet chajjas have been used to serve as weather shading
		devices at certain windows.
		Some of the functions of the high court have been transferred to PWD
		building, which is now connected by a covered walkway.
	Structure	The main staircase is strengthened by adding I-section.
		Additions of mezzanine floors supported on I-sections in the corridors of the
		2nd and 3rd floor alter the interior space
		Original carved stone water fountain juxtaposed with modern water cooler.
		Corridors have been encroached where the records are stacked
		haphazardly.
	Articulation & Finishes	Oil painting (black) to column shaft at the western side entrance corridor.
		The original floor tiles have been insensitively replaced by ceramic and
 		mosaic tiles in the corridors, Judge's chambers and courtrooms.
11.0		DD Demerke/Derectured Threats
11.0		DP Remarks/ Perceived Threats
┝───		Plot has been demarcated for law and order in DP
12.0		Additional Notos/ Poforoncos/ Documents available
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		Commenced in 1871 and completed in 1878 at a cost of Rs 16.5 lakhs, the High Court is next to the Victoria Terminus, the second largest Gothic
		building in the city. The length of the building is an enormous 562 feet, the
		breadth 187 feet and the height to the eaves, 90 feet. The architect, Colonel
		Fuller of the Royal Engineers, is believed to have designed the building from
		a sketch taken by him of magnificent castle on the River Rhine while touring
		ם אפונה ומגבוד אין חוודו טו דומצווווגבווו נמצווב טוד נווב גועבו גרווווב שוווב נטעוווע


around Germany. The imposing turrets, the massive central tower black local stone used in the construction, give the High Co	
 appearance of a massive fortress. The building has galleries ope westerly breezes, a grand central staircase, beautiful Minton tili appointed court rooms and a library room with portraits of distin judges and eminent lawyers. There is beautifully carved detailing i many pillars and arches, comprising human heads, birds and beas several, including a monkey judge wearing an eye-patch, holding al scales of justice and foxes wearing lawyers' neck bands, lampool legal profession. All the interior fittings were executed to the designs Adams. Outside the Court is a well which provides water for or Hindus who will not drink tap water. Until a number of lakes were or the suburbs from the 1850s, Bombay's water supply came from su that once dotted the entire city. Height of central tower to eaves 90 feet and that of central tower is 1 The actual cost of the project was Rs 16,44,528, were as the sanctic estimate was Rs. 16,47,196. <u>References:</u> INTACH (1990) <i>Preliminary unedited listing of Unprotected Monume Buildings and Structures listed for Conservation.</i> FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dic of Architecture</i>, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i>, E : Eminence Designs Pvt. Ltd. RAHUL MEHROTRA and SHARADA DWIVEDI (2004) <i>The Bombay Court - The story of the building – 1878-2003</i>, Bombay : Eminence D Pvt. Ltd. Buildings of the Kalaghoda Art District, (2000) Marg Publications, Ma Mueller Bhavan Bombay, Urban Design Research Institute. MARIAM DOSSAL (1996) <i>Imperial designs and Indian Realities - Th Planning of Bombay City</i> - 1845-1875, Bombay : Oxford University P SIR BANNISTER FLETCHER A <i>History of Architecture</i>, CBS publica and distributors. 	n to the ng, well guished atop the sts with oft tilted ning the of John orthodox eated in ch wells 78 feet. ned <i>nts,</i> <i>tionary</i> Bombay <i>High</i> besigns ax <i>e</i> ress.












077


6 1

V3 Bombay High Court





















077

V3 Bombay High Court









V4 PWD	Building			254
	Danding	Common Ref No: 254		201
		Card No: 345		Mar And
	Sector B	Ward (Part): A (Part II)		
				BELIN & HUTATMA CHOWK
		CS No: 150 (Fort division)	VEER NARIS	MAN ROAD
1	A State of the second s	Plot Area: 6161.42 sq m	- NA	
15		B U Area: -	VEER NARI	A HA
2.4		Date: 14/04/2005		
Mar 1		Recorded by: Sonal Modak		
		Reviewed by: UDRI	- I AD	
S		Int: Permission denied	18 3 5	温白山
		Ext: Sonal Modak	I III I TH	41171.
		Photo Ref.: 254_PWD building	II LEY_M	
		Reviewed in 2013	Loc	ation Plan
1.0		Denomination		
1.1	Name of Premises	PWD Building		
1.2	Earlier Name	PWD Building		
1.3	Built in:	1872	Extension	-
			Date:	
			•	
2.0		Access		
2.1	Main	Veer Nariman Road – Vehicular an	d Pedestrian	
2.2	Subsidiary	Karmaveer Bhaurao Patil Marg (Ma		destrian
3.0		Ownership pattern		
3.1	Present	State Government		
3.2	Past	State Government		
3.3	Status	Owner		
0.0				
4.0		Use		
4.1	Present	Government Offices (Public Service	26)	
4.2	Past	Government Offices (Public Service		
4.2	Usage	Daily	53)	
4.3				
5.0		Significance & Value Classificati	00	
5.0	Townscape (Manmade)	The building stands on a corner plo		romicos os that of
5.1	Townscape (Mannade)	High Court. Main access to the buil		
		northern side.	ung is norn ve	
		It forms a part of cluster of Heritage	huildings in Fl	ora Fountain Area
		such as Old Insurance Building, Cit		
		of India etc.	ly Dalik, Fiora i	
5.2	Architectural Description	Planning		
J.Z	Architectural Description	3	to the building	donied
		Planning Indeterminable as access Features		uenieu.
				a currenting the
		The Facade is punctuated with arch		
		verandahs and corridors that run al		
		Continuous bands run at each floor	iever resting of	n dentiis at the
		topmost floor level.	lith pointed are	has supported as
		Main entrance is through a porch w		nes supported on
		circular columns with Corinthian co		
		Pointed arches have quatre foil ver		
		Ornate multifoil parapet at porch te		
		Arches are constructed in alternate	yellow and buf	t stone.

V4 PWD	Building			254
		Style		
		It derives a strong influence from Nec	o-Gothic style	
5.3	Intrinsic	-		
5.4	Value Classification	A(arc), A(his), B(per), B(des), B(uu), F, I(sce)	E, Recomme grade	ended I
6.0		Topography		
6.1	Floors	G + 2, G + 3 partly		
7.0		Construction		
7.1	Plinth	Medium plinth about 2 ft height in gre masonary.	y rough dress	sed ashlar
7.2	Walls	Indeterminable		
7.3	Floor	Indeterminable		
7.4	Stairs	Indeterminable		
7.5	Openings	Arched openings with wooden frame louvers at bottom.	partly glazed	panels with wooder
7.6	Roofing	Indeterminable		
7.7	Articulation	Corinthian column capitals, dentils, q	uatrefoil open	ings etc.
7.8	Finishes	Externally grey ashlar masonary. Inte	ernal finishes i	ndeterminable.
7.9	Interiors (Movable & Immovable)	Movable		
		Immovable		
7.10	Compound/ Fence/ Gate	A stone compound wall with MS fenc	ing atop.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Indeterminable.		
8.0		Services & Utilities		
8.1	Lighting	Indeterminable		
8.2	Ventilation	Indeterminable		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	Indeterminable		
8.7	Other (HVAC/BMS/Security Systems)	Indeterminable		
0.0				
9.0		Condition	1 1 6 4	
9.1	Plinth	Good no evident damages seen. Blac	ckening of sto	ne.
9.2	Walls	Good		
9.3	Floor	Good		
9.4	Stairs	Good		
9.5	Openings	Good		
9.6	Roofing	Good		
9.7	Articulation & Finishes	Good		
9.8	Services	Good		
9.9	Out Buildings	Fair		1
9.10	Overall Conditions		<i>l</i> laintenance evel	Good

V4 PWD	Building	254
10.0		Transformation
	Form	Indeterminable
	Structure	Indeterminable
	Articulation & Finishes	Indeterminable
11.0		DP Remarks/ Perceived Threats
		Plot has been demarcated for law and order in DP
12.0		Additional Notes/ References/ Documents available Additional Notes:
		The Public Works Department offices were designed by Colonel H St Clair Wilkins in the Venetian Gothic style and completed in 1872 under the supervision of Colonel J A Fuller and J H E Hart. The building is faced with cursed blue basalt stone with bands in Kurla and dressings in Porebunder stone, with red and blue basalt alternating with Porebunder stone in the arches. The building was enlarged in the 1890s with an additional wing facing west. <u>References:</u> INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.</i> FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture,</i> Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks,</i> Bombay : Eminence Designs Pvt. Ltd.

V4 PWD Building















V5 Mahe	V5 Mahendra Mansion (Watson's Hotel) 168			
vo mario		Common Ref No: 168	100	
		Card No: 226	-	
		Ward (Part): A (Part III)	and I have II	
1	And Annual Superior States Annual Annual Annual Superior			
17		CS No: 147	A.S.Demello Road	
		Plot Area: 1240.80 sqm.		
		B U Area: -		
- Partie		Date: 17/11/2004	ha a second	
N I BELL		Recorded by: Arun Wadhwa		
- SLOP		Reviewed by: UDRI		
		Int: Arun Wadhwa, Zankhana		
		Prajapati		
87		Ext: Arun Wadhwa, Zankhana		
		Prajapati		
			Location plan	
		Photo Ref.: 168_Watson's Hotel	-	
		Reviewed in 2013		
1.0		Denomination		
1.1	Name of Premises	Esplanade Mansion		
1.2	Earlier Name	Watson's Esplanade Hotel		
1.3	Built in:	Commenced 1867 in and	Extension Date: -	
		completed 1869		
2.0		Access		
2.1	Main	University Road		
2.1	Subsidiary	Mahatma Gandhi Road		
Ζ.Ζ	Subsidialy			
3.0		Ownership pattern		
3.1	Present	Sadiq Ali - Private		
3.2	Past		city draper, later owned by Tatas for	
0.2		a brief period.	ong arapor, lator owned by ratas for	
3.3	Status	Ownership with multi tenanted prei	mises	
5.5			111303.	
4.0		Use		
4.1	Drocont		appizations	
	Present	Shops, Offices, and institutional or		
4.2	Past	Large luxury hotel, first of its kind in	прошрай	
4.3	Usage	Daily		
5.0		Significance & Value Classified	ion	
5.0		Significance & Value Classificati		
5.1	Townscape (Manmade)	Landmark corner building facing th		
		intersection of Mahatma Gandhi ro	5	
		Accessed from the north side entra		
		forms part of the continuous arcade	0,	
		buildings in the Kala Ghoda precin		
		regulations laid by City improveme	nt trust.	
5.2	Architectural Description	Planning		
		The Building stands on a corner pl	ot, with its east and north elevations	
		facing the roads.		
			ision for 130 rooms, a grand central	
		atrium around which were placed t	8	
		colonnaded ground floor.		
			a garden on the south – the present	
		site of Army and Navy building.	gardon on the south the present	
		The present building accommodate	as numerous subdivision and	
L			S HUITEI DUS SUDUIVISIUIT AITU	

V5 Mahe	ndra Mansion (Watson's Hote	l) 168
		accretions within and outside the main building.
		Features
		The building reflects strong structural grid in the external facades,
		exposing the vertical lines of the cast iron columns and the horizontal
		bands of the balustrades at each level.
		Decorative cast iron balusters and railings with monogrammed letters
		of Watson's hotel. The atrium at ground floor was once a fashionable lobby housing the
		banquet hall.
		Style
		Early Post Industrial Architecture
5.3	Intrinsic	The building witnessed the first screening of a motion film in India,
		Lumiere Brothers cinematograph in 1896.
		First Cast Iron structure in India, with most of the structural members
		being manufactured in England and shipped into Bombay for
		assembly.
5.4	Value Classification	A(arc), A(his), B(per), B (des), B (uu), E, Recommended grade: II A
		F, I(sce)
()		
6.0		Topography
6.1	Floors	G + 4 (extensive mezzanines added within the large floor heights)
7.0		Construction
7.0	Plinth	Plinth and bases of the arcaded columns are constructed of red
7.1	F 111 (0.1	colored stone imported directly from the town of Penrith in
		Cumberland, Watson's home county.
7.2	Walls	Non-load bearing infill brick masonry walls, largely imported from
		Webster's manufactory in Burnham, England.
7.3	Floor	Timber floor boarding was installed on a structural grid of prefabricated
		cast iron columns and wrought iron beams.
		The structure supports a continuous band of balconies at each level.
7.4	Stairs	Centrally located grand straight flight stair overlooking the atrium has
		treads and balusters made in timber.
		The support is derived from wrought iron girders supported on cast
7 5	Ononingo	iron columns.
7.5	Openings	Generally all openings are punctuation in the infilling brick walls. The sides to the east, north, and west have doors opening onto projecting
		balconies. The door shutters are timber panels with top hung ventilator
		above. The south side with adjoining Army and Navy building has
		similar window openings.
		Decorative tracery window at the upper part of ground floor opening.
7.6	Roofing	The ground floor atrium covered by a gable roof supported on steel
		truss and Mangalore tile finishing with a few skylights. The roof is
		constructed of flat slab covered with water proofing membrane on top
7.7	Articulation	· · · · · · · · · · · · · · · · · · ·
7.8	Finishes	Lime mortar finishing to both the internal and external surfaces
		throughout the building. Timber partitioning to divide internal spaces.
		Timber boards formed the floor finishing including staircase. Door and
7.0	Interioro /Mauskie 0	window openings finished with paint.
7.9	Interiors (Movable &	Movable
	Immovable)	- Immovable

V5 Mahe	ndra Mansion (Watson's Hotel)	168
7.10	Compound/ Fence/ Gate	Building itself forms boundary along the three road fronts to the east, north and west side, shares a narrow open space along the south side
7 4 4		with adjoining building.
7.11	Curtilage/ Unbuilt space/ Out	-
	Buildings/ Landscape	
8.0		Services & Utilities
8.1	Lighting	Adequate natural light also supplemented by artificial means.
8.2	Ventilation	Adequate natural ventilation also supplemented by artificial means.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Fire extinguishers installed at places
8.7	Other (HVAC/BMS/Security Systems)	-
9.0		Condition
9.1	Plinth	Poor - Plumbing line additions seen
9.2	Walls	Poor - All external as well as internal walls are in a state of neglect and dilapidated; issues of ficus growth
9.3	Floor	Poor - Wooden floorboards damaged and unleveled, insensitively covered with varied tiling and plain cement, cracks visible
9.4	Stairs	Poor - poor maintained state of the once grand staircase.
9.5	Openings	Poor – lack of maintenance
9.6	Roofing	Poor - in need of repair and waterproofing
9.7	Articulation & Finishes	Poor – transformation visible
9.8	Services	Poor - Various additions and modifications in services
9.9	Out Buildings	-
9.10	Overall Conditions	Poor Maintenance level: Poor
10.0		Transformation
10.0	Form	
	Form Structure	Balcony encroachment
	Siruciure	Addition of mezzanine on ground floor False ceiling and partitioning of office spaces
		Many additions and alterations in the structure
	Articulation & Finishes	transformations
11.0		DP Remarks/ Perceived Threats
1110		Plot falls under commercial zone in DP
12.0		Additional Notes/ References/ Documents available
		<u>Additional Notes:</u> The oldest building at the Kala Ghoda Circle, located at the corner site next to the Army & Navy Building, was once the grand Watson's Esplanade Hotel, erected between 1867-69 by John Watson, a wealthy city draper, who imported all the building materials from England. While still under construction, the building, with its unique cast iron frame imported from England, was described by one writer as a 'huge birdcage'. The spacious arcade at street level displays the original cast iron pillars. History was created here in 1896 when the foundations of the Indian Cinema industry – now the largest in the

V5 Mahendra Mansion (Watson's Hotel)	168
	 world – were laid with the screening of the Lumière Brothers' Cinematograph. <u>References:</u> INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.</i> SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i>, Bombay: Eminence Designs Pvt. Ltd. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i>, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i>, Bombay: Eminence Designs Pvt. Ltd.



V6 David	6 David Sassoon Library & Reading Room 1			
		Common Ref No: 166		
		Card No: 224	- A BEREISSING	
		Ward (Part): A (Part III)		
	4	CS No: 145	REMANDE HANGSON	
		Plot Area: 2240.81 sqm.		
	0	B U Area: -		
		Date: 02/11/04	ABHY & MAVY STORES	
An				
		Recorded by: Prachi Merchant		
1	AAA AAA AAA	Reviewed by: UDRI		
and a		Int: Arun Wadhwa, Prachi	A HOPE STREET	
		Merchant	Location Plan	
		Ext: Arun Wadhwa, Prachi	LUCALIUIT PIAIT	
	A REAL PROPERTY AND A REAL	Merchant		
		Photo Ref.:		
		166_David_sassoon_library		
		Reviewed in 2013		
1.0		Denomination		
1.1	Name of Premises	David Sassoon Library and Reading		
1.2	Earlier Name	The Sassoon Mechanic's Institute/ T	he David Sassoon Mechanic's	
		Institute and Library		
1.3	Built in:	Construction of building in 1867, Cor	mpleted in Extension -	
		1870	Date:	
			· · · ·	
2.0		Access		
2.1	Main	Mahatma Gandhi Road		
2.2	Subsidiary	Library Marg		
3.0		Ownership pattern		
3.1	Present	Trust		
3.2	Past	Trust		
3.3	Status	Owner		
0.0				
4.0		Use		
4.0	Present	Library and Reading room, Commerce	cial shops on the street front	
4.1	Past	Library and Reading room	אמן אוסףא סון נווב אובבו ווסוונ	
4.2		Institutional, Library, and Commercia	l shons	
4.J	Usage	insulutional, Library, and Commercia	แ รมบุษร	
F 0		Cignificance & Value Classification	-	
5.0		Significance & Value Classification		
5.1	Townscape (Manmade)	One of the first Library buildings plan		
		It forms a part of well-integrated build		
		and an arcade, along the Kalaghoda		
F 2	Anabita at wel D a d' d'	The series of buildings form an intere	esung vista and skyline.	
5.2	Architectural Description	Planning		
		Rectangular shaped building with its		
		The building opens into a garden at t		
		The entrance porch opens into a wid		
		leading to the main hall with adminis	trative offices and toilets on either	
		side.		
		The garden serves as a relaxing and	reading area for the library	
		members.		
		The reading room, main library and t	he lecture rooms are on the mid	
		and first floor levels. Features		

V6 David Sassoon Library & Reading Room 166			
		The building is clad in coarse buff colored basalt stone. Façade elements consist of black stone columns with decorative capitals with springing pointed arches in verandah and arcade area, black and white bands over arched openings, mouldings and cornices in limestone, cast iron balustrade, delicate spires, rose windows, circular trefoil glazed openings, pediments, friezes, pinnacles etc. Gothic arched openings with the black and white limestone alternate voussoir and high gable roof over the imposing porch and the clock tower with spires, forms a distinctive character of the building. Style The building derives influences from Venetian Gothic style.	
5.3	Intrinsic	-	
5.4	Value Classification	A(arc), B(des), B(uu), E, F, I(sce) Recommended I grade	
6.0		Topography	
6.1	Floors	G+1 with a mezzanine floor, clock tower rises from the terrace level.	
0.1			
7.0		Construction	
7.1	Plinth	Low plinth of approximate 1'-6" height of the coarse buff basalt stone.	
7.2	Walls	Thick load bearing walls	
7.3	Floor	Concrete floor with tongue and grooved narrow planking on the	
7.4	Stairs	 underside of the floor. Terrace slab is an RCC beam structure with IPS waterproof finishing. Vaulted floor over reading room in the verandah. Main open well staircase with stone risers and treads and cast iron 	
		balustrade with floral pattern and teakwood handrail. Narrow spiral staircase from the verandah to the terrace with risers, treads and railing in wood. A teakwood steep ladder leading from terrace to the clock tower.	
7.5	Openings	 Doors and Openings The main porch is a gothic pointed arch opening with trefoil and tracery work. The arch springs from Corinthian capitals. The arch is extended into a pediment with a pinnacle above. The grand main entrance wooden doors have single panel double shutters with a post box integrated in the shutter, loose stone stoppers. The ventilator of the door is an intricate tracery work of cast iron painted in black and gold. The administrative room doors have thick wooden frames of the wall thickness, with double paneled double leaf wooden shutters. Terrace doors are teakwood, flushed doors with an arched ventilator opening above. The reading room door openings are in the form of pointed arch, with radiating type stained glass fixed in the ventilators above. The double leaf double paneled wooden folding louvered shutter doors are fixed to a wooden frame. A row of arched openings in the verandah run through the entire width of the building. They spring from polished slender black column with Corinthian capitals. The internal arches in the verandah are joined to the array of smaller similar arched openings by the capital band. Windows Mid-landing consist of French windows with the height divided into two 	

V6 David Sassoon Library & Reading Room 166			
		parts. The upper and lower part are wooden paneled double shutter,	
		with the lower shutters protected with cast iron railing.	
		The small independent reading room windows have long French	
		windows, with the height divided into two parts. The outside upper and	
		lower windows are wooden paneled double shutter. The upper inside	
		shutters are double shutter hinged louvered shutters. The lower	
		shutters are protected with cast iron railing.	
		Windows at the main reading room entrance have wooden openable	
		glazed shutters with grills inside.	
		Windows along the longer sides of the reading room have full height	
		arch shaped wooden long glazed openable sash window shutters with	
		teakwood transoms on the outside and teakwood louvered shutters on the inside.	
		Main reading room consists of ventilators above windows with	
		radiating wooden members and coloured glass panels.	
		Windows along the smaller sides of the reading room consist of long	
		French windows with glazed openable shutters.	
		Terrace consists of arch shaped wooden glazed openable sash	
		window shutter with circular glazed fixed ventilator.	
7.6	Roofing	Main staircase block has a unique wooden collar braced roof with	
	3	teakwood planks and framing members.	
		Pitched Mangalore tiled roof over administrative block.	
		RCC slab and beam structure over main library hall.	
		Verandah has wooden planks roof cladding over concrete slab in the	
		center and vaulted concrete and steel section roofing over side	
		sections.	
		Clock room has Mangalore tile roof with wooden framework below.	
7.7	Articulation	Coursed buff basalt stone cladding with alternate black and white	
		stone bands along the arched openings forms the main feature of the	
		building. Bands of alternate black and white limestone over arch	
7.0		openings	
7.8	Finishes	Walls are finished with coarse buff basalt with thin mortar pointing	
		externally, and plastered and painted internally.	
		Minton tile having different patterns segregate each area. Wooden flooring in independent reading rooms and with teak wood	
		joists and rafters in clock tower.	
		Verandah and mezzanine floor have cast iron railing with floral pattern.	
7.9	Interiors (Movable &	Movable	
1.7	Immovable)	Large teak wood reading tables, a grand reception table, librarian's	
		table and other working table form furniture having antiquity value	
		along with wooden chairs, chaises and benches.	
		A clock along with various photo frames adorns the interior.	
		Donors list exhibited at the entrance foyer.	
		Marble plaque at the library entrance.	
		Statue of David Sassoon in the entrance lobby.	
		A marble sculpture on granite pedestal of James Berkley has been	
		installed in the mid-landing of the staircase.	
		Another marble plaque has been installed at the entrance of the main	
		reading room stating the fund provider, earlier purpose of the library,	
		its cost, and year of completion.	
		Immovable	
		Wooden paneling within the entrance foyer.	
7.10	Compound/ Fence/ Gate	Compound wall on two sides, upto 2'-0", with fencing and chain link	

6 David	Sassoon Library & Reading Ro	pom 10		
		above.		
		Narrow alley between David Sassoon Library and Army Navy Buildir which is not in use.		
		Original iron-gate on the rear side.		
7.11	Curtilage/ Unbuilt space/ Out	Garden serves as a reading area.		
7.11	Buildings/ Landscape	Old trees in the garden create an ambience for reading.		
	Dullulligs/ Lalluscape	Paved pathways, benches, tables, lampposts, form a part of the		
		landscaped garden.		
8.0		Services & Utilities		
8.1	Lighting	Adequate natural daylight through long openable windows from the verandah of first floor and garden area.		
		Adequate artificial lighting through electrical light fixtures such as old chandeliers in the lobby area, and suspended tube lights in the reading room.		
8.2	Ventilation	Verandah, long windows, doors act as the natural ventilation.		
0.0		Electrical fans have been suspended from high ceiling.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	Sprinkler system has been installed in the main library and reading room.		
8.7	Other (HVAC/BMS/Security Systems)	-		
9.0		Condition		
9.0 9.1	Plinth	Good.		
9.2	Walls	Good		
9.3	Floor	Good		
9.4	Stairs	Good		
9.5	Openings	Good.		
9.6	Roofing	Good.		
9.7	Articulation & Finishes	Good		
9.8	Services	Good		
9.9	Out Buildings	good		
9.10	Overall Conditions	Good Maintenance Good level Good		
10.0		Transformation		
10.0	Form	Toilets have been added in the space below the main staircase, with		
	FOIII	punctures made in the walls for ventilation.		
		Asbestos sheet <i>chajjas</i> have been used to serve as weather shading		
		devices for the ventilators.		
	Structure	No major changes in the structure have taken place.		
	Articulation & Finishes	No major transformation		
11.0		DP Remarks/ Perceived Threats		
		Plot has been demarcated for commercial activities and social		
		amenities in DP		
12.0		Additional Notes/ References/ Documents available		

V6 David Sassoon Library & Reading Room















V6 David Sassoon Library & Reading Room









V7 Flohi	nstone College	165
		Common Ref No: 165
		Card No: 223
		Ward (Part): A (Part III)
		CS No: 144 (Fort Division)
		Plot Area: Indeterminable
13	The second second second	B U Area: -
	the second core	Date: 04/01/2005
in.	HALL BUT IT	Recorded by: Arun Wadhwa
	WHE IS LINE A R. C.	Reviewed by: UDRI
	A DILL CHAT PERSON	Int: Arun Wadhwa Drachi
、不然的		Merchant
al the	1 24 100 0 0	Ext: Arun Wadhwa, Prachi
		Merchant
		Photo Ref: 165_Elphinstone Location Plan
		College.
		Reviewed in 2013
1.0		Denomination
1.0	Name of Premises	Elphinstone College
1.1	Earlier Name	Cowasjee Jehangir Readymoney building for Elphinstone College.
1.2	Built in:	1889 Extension Date: -
1.5		
2.0		Access
2.0	Main	Mahatma Gandhi Road (not used) – vehicular and pedestrian
2.1	Subsidiary	David Sasson Library Marg - vehicular and pedestrian
Z.Z		David Sasson Library Iviary - Venicular and pedestrian
3.0		Ownership pattern
3.0	Present	Government of Maharashtra (B. Sc. I.T. Department.)
3.1	Past	Government of Bombay.
3.2	Status	Owner
5.5		
4.0		Use
4.1	Present	Degree College and Department of Archives.
4.2	Past	Government Central press and State records.
4.3	Usage	Daily.
5.0		Significance & Value Classification
5.1	Townscape (manmade)	Landmark building close to the historic Kala Ghoda square alongside
	1	important institutional buildings with a mandatory pedestrian arcade
		along the road front forming one of the most important avenues within
		the Fort area.
5.2	Architectural Description	Planning
		Rectangular building with a central open quadrangle around which
		continuous verandah passages provide access to all rooms arranged
		around it. Main entrance from the arcaded east side leads to a
		spacious entrance lobby leading to wide stone stair. Subsidiary
		staircases are also provided in the three corners except the northeast.
		East front also has narrow veranda bays on upper two floors above
		the pedestrian arcade. Ground and west side of first floor is occupied
		by Department of Archives to serve as storage facilities. Rest of the
		first, second and upper floors are occupied by the college.
		Administrative areas and classrooms are located on first floor whereas
		library, teacher's room, cultural hall and laboratories are all located in
		the pitched roofed second floor. Grand spaces in the part third and

V7 Elphi	instone College	165
		fourth floor were planned to be Principal's residence but presently lie vacant. It is connected to an annex building to the west side through a bridge at second floor. Features Well-composed long symmetrical front façade with the high central portion topped by a steep pyramidal roof. Raised central and edge portions are marked by decorative stone spires at all the four corners. Pedimented central porch has the carved head of Sir Cowasjee Jehangir above the ornamentally treated front arch. Entire long façade is marked by alternate red and Porbunder stone arch openings, semicircular on ground arcade level and pointed arch on upper two floors. Central Arch openings are supported on finely carved capitals with floral and animal motifs. Finely carved stone relief cornice band at the second floor level. Projecting stone balconies with decorative brackets and stone relief parapet at both ends of the front façade. Highly ornate iron railing in staircase parapet. Style
5.3	Intrinsic	The building displays Victorian Gothic style features. Eminent nationalist personalities have received education in this
5.4	Value Classification	institution. A(arc), B(per), B (des), B (uu), E, Recommended I F, I(sce) I
6.0		Topography
6.1	Floors	G + 3
0.1	110013	0+5
7.0		Construction
7.1	Plinth	Low Plinth height about 0.3 m. dressed in Malad stone ashlar course.
7.2	Walls	Load bearing rubble stone masonry walls supported on steel girders, brick load bearing walls on the third and fourth part floor.
7.3	Floor	Shahabad stone slabs on wooden supports & heavy steel girders support large floor spans.
7.4	Stairs	Overall four staircases. Central C- shaped stone stair supported on decorative brackets. Two of the corner stairs are steel C- shaped with decorative railing and wooden handrail.
7.5	Openings	Semis circular and pointed arch openings on the front and rear facades, also tracery within arch portions.
7.6	Roofing	Sloping Mangalore tile roof on the three sides and steep pyramidal sloping roof supported on slender steel trusses. Central portion is also steep pyramidal roof.
7.7	Articulation	High central bay with a projecting porch and stone spires at all the four corners and a semicircular projecting balcony with large ornamental corbel feature; intricately carved frieze band at the second floor level of the long façade; projecting balcony and supporting corbels, alternate buff and porbunder stone arches supported on richly carved capitals and circular columns. Stone parapet with trefoil and quatrefoil opening feature.
7.8	Finishes	Buff basalt stone dressed external wall finishes and grey basalt stone in verandah walls and soft Porbunder stone for ornamental features. Brick faced arches in inner verandahs. Plastered painted internal wall surfaces. Minton floor tiling in ground floor and wooden floorboard finishing on upper floors.
7.9	Interiors (Movable Immovable)	& Movable Carved wooden furniture – benches and wall paneling have decorative

V7 Elphir	nstone College	165
		value.
		Portraits of Dadabhai Nowroji present
		Immovable
		Original wooden partition panels and furniture some embellished with
		relief work.
7.10	Compound/ Fence/ Gate	North and south sides have chain link fencing whereas the east front
		abuts the road and west side has ancillary structure forming
		compound boundary. Iron railing and gate, recently installed fences in
		the open front arcade but seems very incongruous to the open nature
		of arcade. Gate to the north side forms the main entry.
7.11	Curtilage/ Unbuilt space/ Out	Paved quadrangle inside the building is the hub of college activities.
	Buildings/ Landscape	Second floor bridge connects to the west side annex building in the
		Old Secretariat compound. Also a water tank and small pump room
		along with watchman's cabin in the north side open space.
0.0		
8.0	Link the re	Services & Utilities
8.1	Lighting	Adequate natural light also relying on artificial light.
8.2	Ventilation	Adequate natural ventilation also relies on artificial means.
8.3	Electricity	BEST
8.4	Water Supply	MCGM - Underground and overhead water tank
8.5	Drainage (Plumbing & Sanitation)	Drainage connected to municipal sewers of MCGM
8.6	Fire Precaution	Fire extinguishers only.
8.7	Other (HVAC/BMS/Security	Window unit A.C.
	Systems)	
9.0		Condition
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Fair
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Fair, with minor repairs required.
9.9	Out Buildings	Fair
9.10	Overall Conditions	Good Maintenance level: Good
10.0		T
10.0		Transformation
	Form	Small G+1 classroom extension to the south side of internal courtyard.
	Ctructure	Connecting bridge at second floor rear side to the annex building.
	Structure	Inner wooden verandas seem to be reconstructed in concrete.
	Articulation & Finishes	-
11.0		DP Remarks/ Perceived Threats
11.0		Plot has been demarcated for educational activities in DP
12.0		Additional Notes/ References/ Documents available
12.0		Additional Notes:
		The Elphinstone College is named after Mount Stuart Elphinstone, a
		former Governor of Bombay who championed the cause of education.
		Marble tablet at the spacious entrance lobby records the
		commencement of building giving details: Architect Khan Bahadur M.
		sommencement of building giving uctails. Architect than barlault Mi

V7 Elphinstone College	165
	C. Murzbhan. Cost Rs. 7,41,497/- <u>References:</u> INTACH (1990) <i>Preliminary unedited listing of Unprotected</i> <i>Monuments, Buildings and Structures listed for Conservation.</i> SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities</i> <i>Within</i> , Bombay : Eminence Designs Pvt. Ltd. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual</i> <i>dictionary of Architecture,</i> Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks,</i> Bombay : Eminence Designs Pvt. Ltd. ABHA NARAIN LAMBAH <i>Through the Looking Glass – The Grade I</i> <i>Heritage of Mumbai,</i> Mumbai : Urban Design Research Institute, Jasubhai Media and Super Book House. <i>Buildings of the Kalaghoda Art District,</i> (2000) Marg Publications, Max Mueller Bhavan Bombay, Urban Design Research Institute. SIR BANNISTER FLETCHER <i>A History of Architecture,</i> CBS publication and distributors.

V7 Elphinstone College













165

V7 Elphinstone College













V7 Elphinstone College

















V7-vii

V8 Maha	rashtra State Police Headqua	rters (Sailor's Home)		095
vo mana		Common Ref No: 095		0,0
		Card No: 137		
		Ward (Part): A (Part III)		
	6			A A A A
	1 march	CS No: 36 (Colaba division)	COAD	
		Plot Area: 10503.420 sq m.	IHON	- HEN
		B U Area: -	A GA	
	A PART A PART A	Date: 30/12/05	ALL	aono /
1	AND AND DOUB	Recorded by: Arun Wadhwa	WADAN	Sinon
		Reviewed by: UDRI	MADAM CAMA ROAD	autori
2		Int: Prachi Merchant, Sonal Modak,		RO
		Arun Wadhwa		
		Internal photography permission	ana a	
<u> </u>		denied	Walatean	A CALAN
	Contraction of the second second	Ext: Prachi Merchant, Sonal Modak,	We Color	
		Arun Wadhwa		San Di
		Photo Ref: 095_Maharashtra State	L	Location Plan
		Police Headquarters.		
		Reviewed in 2013		
1.0		Denomination		
1.1	Name of Premises	Maharashtra State Police Headquarte	ers	
1.2	Earlier Name	Royal Alfred Sailor's Home		
1.3	Built in:	Commenced: Feb Extension Date		1928 - Bombay
110	Bailt ini	1872		Legislative Council
		Completed: Feb		1980 – Maharashtra
		1876		State Police
		1070		Headquarters
				Ticaaquarters
2.0		Access		
2.0	Main	Shahid Bhagat Singh Marg – vehicula	and podect	rian
2.1	Subsidiary	Chhattrapati Shivaji Marg (exit from th		
Z.Z			ie plotj- verili	Julai anu peuesinan.
2.0		Our anabia a attana		
3.0		Ownership pattern		
3.1	Present	Owner - State Government		
3.2	Past	Owner - State Government		
3.3	Status	Owner		
4.0		Use		
4.1	Present	Government Services		
4.2	Past	Government Services		
4.3	Usage	Daily		
5.0		Significance & value Classification		
5.1	Townscape (Manmade)	Prominent corner building located at	the Shyama	prasad Mukherjee chowk
		at the junction of Shahid Bhagat Sing		
		The building is located on a plot with		
		accessed from the west side from S		
		can be found on the south side to Ch		
		The building is juxtaposed with other		
		and period, like Majestic Hostel, India		
		Prince of Wales museum and Cowa		
		circle.	-j. e e la la la	
5.2	Architectural Description	Planning		
0.2		l'initia di la constante di la		

Ihe main stärcase connecting both the side wings. The building has a central projecting wing, and side twin towers with conical roof, standing taller than the rest of the wings, with lower tetrace spaces in between. The office rooms (initially planned as Sailors rooms) are planned in the east side, connected with passages and verandahs on the west side and projecting balconies on the east side. Features The rough stone dressed grey clad stone building has a central projecting wing with an extended porch accessed through side pointed and front three semicircular arched openings with alternate builf and grey voussoi pieces. The springing point of the arches is adorned with animal motils and round motil with Sailors Home symbol engraved below. The entrance porch displays a marble bas-relief of Baroda's Khanderao Gaekwad Sayaji Rao II. The central wing ends into a pediment decorated with stone crockeling, finial and bands of foral motif below. The tympanum is highly decorative with the figures of Neplune surrounded by nymphs and sea horses. To the left and right, two griffins bear shields that display coats of arms. The ground floor openings have pointed double arched openings with alternate built and grey voussoi pieces supported on square columns with becarative capitals and round florial motils above with stone-carved balustrade below. Cornice bands define the floor levels. The second floor and the third floor of the central wing have a row of four arched openings and round windows above with alternate built and grey voussoi pieces supported on short columns with decorative capitals and round windows above with stander. The side towers have ground floor double arches with smaller arches within the bigger. The iddle wings have terrace graces with quatterolistone balustrade. The side towers have ground	V8 Mahar	ashtra State Police Headqua	rters (Sailor's Home) 095
Style Gothic style 5.3 Intrinsic The bands, mouldings and carved corners in buff-coloured Porbunder stone with the caps and finer carvings in Hemnagar stone, were crafted by students of the JJ School of Art under the supervision of Professor John Lockwood Kipling (father of the famous writer, Rudyard Kipling). The funds for this building were donated by Maharaja Khanderao Gaekwad of Baroda. 5.4 Value Classification A(arc), A(his), B(per), B(des), B(uu), E, F, I(sce) Recommended I	<u>V8 Mahar</u>	ashtra State Police Headqua	 Main building is rectangular in shape with its longer side facing west. The building is planned with a central projecting entrance lobby leading to the main staircase connecting both the side wings. The building has a central projecting wing, and side twin towers with conical roof, standing taller than the rest of the wings, with lower terrace spaces in between. The office rooms (initially planned as Sailors rooms) are planned in the east side, connected with passages and verandahs on the west side and projecting balconies on the east side. Features The rough stone dressed grey clad stone building has a central projecting wing with an extended porch accessed through side pointed and front three semicircular arched openings with alternate buff and grey voussoir pieces. The springing point of the arches is adorned with animal motifs and round motif with Sailors Home symbol engraved below. The arches are supported on corner double columns and flying buttress. The columns have projecting capital bands and wide base. The porch has a terrace above with stone balustrade and corner finials with gargoyles below. The entrance porch displays a marble bas-relief of Baroda's Khanderao Gaekwad Sayaji Rao II. The central wing ends into a pediment decorated with stone crocketing, finial and bands of floral motif below. The tympanum is highly decorative with the figures of Neptune surrounded by nymphs and sea horses. To the left and right, two griffins bear shields that display cause of arms. The ground floor openings have pointed arched openings, supported on short columns with decorative capitals and round floral motifs above with stone-carved balustrade below. Cornice bands define the floor levels. The second floor and the third floor of the central wing have a row of four arched openings and round windows above with alternate buff and red stone voussoirs and couble side short columns with decorative capitals. The middle wings have terr
5.3 Intrinsic The bands, mouldings and carved corners in buff-coloured Porbunder stone with the caps and finer carvings in Hemnagar stone, were crafted by students of the JJ School of Art under the supervision of Professor John Lockwood Kipling (father of the famous writer, Rudyard Kipling). The funds for this building were donated by Maharaja Khanderao Gaekwad of Baroda. 5.4 Value Classification A(arc), A(his), B(per), B(des), B(uu), E, F, I(sce) Recommended I			Internally the openings are arched and are supported on columns with decorative capitals with floral motifs, intricately carved cast iron ventilator <i>jalis</i> , symbols and monograms of sailor anchors, name engraved at places. Style
			The bands, mouldings and carved corners in buff-coloured Porbunder stone with the caps and finer carvings in Hemnagar stone, were crafted by students of the JJ School of Art under the supervision of Professor John Lockwood Kipling (father of the famous writer, Rudyard Kipling). The funds for this building were donated by Maharaja Khanderao Gaekwad of Baroda.
	5.4	Value Classification	

/8 Maha	rashtra State Police Headquarte	rs (Sailor's Home) 095	
6.0		Topography	
6.1	Floors	Central wing G+4, other wings G+3	
7.0		Construction	
7.1	Plinth	Normal height - grey stone clad plinth with buff stone bands.	
7.2	Walls	Load bearing stone rubble masonry walls.	
7.3	Floor	Stone slabs over wooden members in the verandah and internal areas.	
7.4	Stairs	Main central stair has a grand open well constructed with wooden treads and risers enclosed by intricate cast iron railing. Narrow and steep winding	
7.5	Openings	wooden stairs in both the wings. Verandah and passage arched openings: Semicircular, pointed, round arches with intricate <i>jali</i> work in the ventilators. Arched doors and windows with double shutters of wooden paneled and lauvored door with cast iron <i>jali</i> work and floral motifs at places	
7.6	Roofing	louvered door with cast iron <i>jali</i> work and floral motifs at places. The central portion has higher hip sloping Mangalore tile roof with overhangs over the central block. The twin towers on sides have high pyramidal sloping roof with overhangs supported on brackets. Asymmetrical sloping roof over extended wing. Several small pyramidal roofs.	
7.7	Articulation	Arches, buttress, gargoyles, bands, pediments, polychromatic stone features.	
7.8	Finishes	The walls are finished with rough dressed grey stone externally with red and buff stone features. Internally walls are finished with plaster and paint. Floor is finished natural stone.	
7.9	Interiors (Movable & Immovable)	Movable Heavy wooden furniture of table and chairs. Immovable Marble plaque in the entrance lobby explaining the history of the building.	
7.10	Compound/ Fence/ Gate	High brick compound wall with fence and planters above. Two main cast iron gates for entry and exit with gate posts.	
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Front landscaped islands with trees, lawn and shrubs. Security sheds at both the entrances.	
8.0		Services & Utilities	
8.1	Lighting	Adequate light through verandah and passage spaces, supplemented by artificial lighting.	
8.2	Ventilation	Adequate ventilation through verandah and passage spaces, supplemented by artificial ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing & Sanitation)	MCGM	
8.6	Fire Precaution	Fire extinguishers are installed at regular intervals	
8.7	Other (HVAC/BMS/Security Systems)	Main rooms have window AC's installed.	
		Manual security.	
9.0		Condition	
9.1	Plinth	Good	
9.2	Walls	Good	

V8 Mahai	rashtra State Police Headqua	arters (Sailor's Home) 095
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Out Buildings	Good
9.10	Overall Conditions	Good Maintenance level Good
,,,,,,		
10.0		Transformation
10.0	Form	-
	Structure	Extensions have been made in various buildings.
	Structure	I-sections have been installed to strengthen the floor.
	Articulation & Finishes	Openings have been blocked, shutters have been changed.
	Articulation & Finishes	Outbuildings have been insensitively added.
		<i>Chajjas</i> have been replaced with asbestos sheet.
		Façade features have been painted insensitively in the porch area.
11.0		DP Remarks/ Perceived Threats
11.0		
		Plot has been demarcated for Government Office in DP
12.0		Additional Natas/Deferences/Decuments susilable
12.0		Additional Notes/ References/ Documents available
		Additional Notes:
		Police Commissioner's Office (Formerly Royal Alfred Sailors' Home and
		Old Council Hall)
		This is the oldest and perhaps historically the most important building
		constructed in the city after the demolition of the Fort walls in the 1860s.
		The sprawling Royal Alfred Sailor's Home, which in later years functioned
		as the Council Hall, is now the Maharashtra State Police headquarters. It
		was built on the site of Mendham's Point, the oldest English cemetery in
		the city – Mendham being the first Englishman to be buried here. The main
		building, designed in the Gothic style by the renowned architect, Frederick
		William Stevens, is 270 feet long and 58 feet wide and was completed in
		1876. Important features include the sculpture of Neptune in bas-relief in
		the pediment at the top and the ingenious use of different coloured natural
		stones in the building, which is faced with blue basalt. The bands,
		mouldings and carved corners in buff-coloured Porebunder stone with the
		caps and finer carvings in Hemnagar stone, were crafted by students of the
		JJ School of Art under the supervision of Professor John Lockwood Kipling
		(father of the famous writer, Rudyard Kipling). The arches are of Hemnagar
		stone mixed with Kurla and basalt. The aesthetic combination of the
		various local stones gives the building a striking appearance. The
		renowned British writer, Joseph Conrad, once stayed in the 1880s in the
		Sailors' Home and his visit and experiences here inspired the story of the
		sailing ship, The Nigger of the Narcissus, which he finished writing in 1897.
		In 1928, the Bombay Government took over the building for use by the
		Bombay Legislative Council. A new Council Hall was built behind the
		Sailor's Home and connected by a corridor to the main building. Designed
		by the Consulting Architect to the Government, J Mercer, the walls of the
		Council Hall were built of stone with a yellow basalt facing. A unique
		feature incorporated in the building was the flooring of the main Chamber
		in rubber asbestos. The Council Hall was probably the first building in
		Bombay – and perhaps in the country to be equipped with an air-
L	1	pointed and pointed in the country to be equipped with all all

V8 Maharashtra State Police Headquarte	rs (Sailor's Home) 095
	conditioning plant. In the 1980s, the buildings were taken over by the
	Maharashtra Police Headquarters.
	References:
	INTACH (1990) Preliminary unedited listing of Unprotected Monuments,
	Buildings and Structures listed for Conservation.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) The Cities Within,
	Bombay : Eminence Designs Pvt. Ltd.
	RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994)
	The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols,
	Bombay.
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary
	of Architecture, Division of International Thomson Publishing Inc.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks,
	Bombay : Eminence Designs Pvt. Ltd.
	, , , , , , , , , , , , , , , , , , , ,


V8 Maharashtra State Police Headquarters (Sailor's Home)














V9 India	n Mercantile Mansion (Waterlo	o Mansion)	151
. ,		Common Ref No: 151	131
		Card No: 209	-
			-
		Ward (Part): A (Part III)	S REION
		CS No: Indeterminable	Madam Cama Road
m		Plot Area: Indeterminable	a Ca
		B U Area: -	Mad an Ahagat
		Date: 18/01/2005	Madam Cama Road
		Recorded by: Sonal Modak	Starting Starting
		Reviewed by: UDRI	has a la
11-1-1-	11	Int: Sonal Modak, Arun Wadhwa	
		Internal photography permission	
	and the second second	denied	Malester Reality
ER		Ext: Sonal Modak, Arun Wadhwa	Location Plan
		Photo Ref: 151_ Indian Mercantile	
		Mansion.	
		Reviewed in 2013	1
1.0		Denomination	
1.1	Name of Premises	Indian Mercantile Mansion	
1.1	Earlier Name	Waterloo Mansions	
1.3	Built in:	1900's	Extension Addition of New
1.5	Duit III.	17003	Date: wing.
			Date. Wing.
2.0		Access	
2.0	Main		Shyamanracad Mukhariaa Chowk
Z. I	IVIAILI		n, Shyamaprasad Mukherjee Chowk
2.2	Subsidiary	– pedestrian Madam Cama Road – pedestrian	
Z.Z	Subsidiary	Mauain Cana Roau – peuesinan	
2.0		Our anabia a attana	
3.0		Ownership pattern	
3.1	Present	Life Insurance Corporation	
3.2	Past	Indeterminable	
3.3	Status	Owner and tenant	
4.0		Use	
4.1	Present	Residential and Commercial – Offic	ces, Clinic, Restaurant, Store
4.2	Past	Residential, Commercial	
4.3	Usage	Daily	
5.0		Significance & Value Classificati	on
5.1	Townscape (Manmade)	Prominent corner building located a	at the Shyamaprasad Mukherjee
	, , , ,	Chowk at the junction of Madam Ca	
		Road.	
		There are two main entrances to bu	uilding, each from the south and
		east side. The shops are accessed	
		The building form is a response to	
		towers emphasizing the road juncti	
		The building is juxtaposed with othe	
		styles and periods, like State Police	
		Hostel, Regal Cinema, the Museun	
5.2	Architectural Description	Planning	
0.2			angular buildings connected at first
		floor level facing Shyamaprasad M	
		entrances from three sides.	annergee enowik with separate
	1		

V9 Indian	Mercantile Mansion (Waterloo	Mansion) 151
		The two buildings are connected in the center with a single storied arched bay. The corner projecting tower bays of the two buildings are higher than the rest of the building. The central portion of the building has corridor spaces lined with a series of arched openings, interspersed with projecting bays. Ground floor houses restaurant and shops. First floor houses offices. Upper floors have residential flats Features The front façade has drop and shoulder arches at first floor level, series of lancet arches at the second and topmost floor level. Tudor like arches at the third floor level. The towers have corbel tables while the inner bay end of the buildings has a pediment rising higher than quatrefoil stone parapet. The inner bays ending in a pediment, have coupled lancet arch within the equilateral arch and blind rose window. Projecting balconies with decorative corbels and stone balustrade. Cast iron columns with decorative capitals support RCC beams. Style The building displays characteristics of the Neo-Gothic style.
5.3	Intrinsic	
5.4	Value Classification	A (arc), B (per), B(des), E, F, I(sce). II A It A
4.0		Tonography
6.0 6.1	Floors	Topography G+4
0.1	1 1001 3	0+4
7.0		Construction
7.1	Plinth	Medium height plinth in grey and buff basalt stone with a sloping plinth protection band
7.2	Walls	Thick load bearing composite walls.
7.3	Floor	RCC flat slab and beam structure supported on cast iron columns. Lobby areas and corridors have jack arch flooring with steel sections.
7.4	Stairs	Three staircases accessing three different buildings. Two open well timber staircases in main buildings with decorative cast iron railing and wooden handrail. One RCC staircase in the new wing.
7.5	Openings	Arches with fixed glazed ventilators and glazed paneled double shutters
7.6	Roofing	RCC terrace
7.7	Articulation	Circular columns with decorative capitals, balconies with corbelling, bands, arches, stone balustrade
7.8	Finishes	Exposed grey stone rough dressed ashlar masonry externally. Walls plastered and painted internally.
7.9	Interiors (Movable & Immovable)	Movable - Immovable -
7.10	Compound/ Fence/ Gate	The building abuts the site boundary on the front two sides. Brick compound wall on remaining two sides with MS gates.
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Rear side of the plot occupies electric substation and pump house.

V9 Indiar	n Mercantile Mansion (Waterloo	Mansion) 151		
8.0		Services & Utilities		
8.1	Lighting	Adequate natural light through balconies, passages and openings, supplemented by artificial light.		
8.2	Ventilation	Adequate natural ventilation through supplemented by artificial ventilation.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM (original cast iron pipes still present)		
8.6	Fire Precaution	-		
8.7	Other (HVAC/BMS/Security Systems)	Individual tenants have installed window and split air conditioners.		
9.0		Condition		
9.1	Plinth	Fair		
9.2	Walls	Fair		
9.3	Floor	Fair		
9.4	Stairs	Fair		
9.5	Openings	Fair		
9.6	Roofing	Fair		
9.7	Articulation & Finishes	Fair		
9.8	Services	Fair		
9.9	Out Buildings	Fair		
9.10	Overall Conditions	Fair Maintenance Fair level		
10.0		Transformation		
10.0	Form	Addition of a wing on rear side.		
	Structure	-		
	Articulation & Finishes	Hoardings cover the ground floor of the building façade. Alterations and additions have been insensitively done		
11.0		DD Demarka/ Derectived Threats		
11.0		DP Remarks/ Perceived Threats		
		Plot has been demarcated for commercial activities in DP		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes:		
		References: INTACH (1990) <i>Preliminary unedited listing of Unprotected</i> <i>Monuments, Buildings and Structures listed for Conservation.</i> FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual</i> <i>dictionary of Architecture</i> , Division of International Thomson Publishing Inc.		

V9 Indian Mercantile Mansion (Waterloo Mansion)









Indu
MADAN CLA
LAN AND STRUCT
Cr Sunne and Sun
AMA ROAL
erchant
run
Aunter Botte
pton Location Plan
Extension -
Date:
I
nerjee Chowk (Junction of Chattrapati Shivaji
ingh Marg, Madam Cama Road, Nathalal
ngi marg, madam bana Koda, Nathalai
f Greater Mumbai
f Greater Mumbai
Classification
in an important urban node at Shyamaprasad
ound by an array of buildings of varied
d periods, with Mercantile building, Majestic
eadquarters, Prince Of Wales Museum, Metro
hangir Hall.
with stone parapet wall, housing water supply
t the center of this basin.
I capped with two tiers of shallow troughs
base is a wide trough with geometric patterns
el of the fountain has floral pattern.
n level, depicting Dukes victories in war.

r. wellir	igton Fountain	219		
		The levels are demarcated by bands, floral friezes and inscriptions in geometric pattern. Style -		
5.3	Intrinsic	The fountain was erected in commemoration of the arrival of Duke of Wellington.		
5.4	Value Classification	A(his), B(per), B(des), B(uu), E, Recommended I I(sce) grade		
6.0		Topography		
6.1	Floors			
7.0		Construction		
7.0	Plinth			
7.1	Walls			
7.2	Floor	-		
7.4	Stairs			
7.5	Openings	-		
7.6	Roofing	-		
7.0	Articulation	- Bands, Bas- reliefs, floral pattern inscription.		
7.7	Finishes	All parts of the fountain have been painted.		
7.0 7.9	Interiors (Movable &	Movable		
	Immovable)	- Immovable -		
7.10	Compound/ Fence/ Gate	Two successive rows of MS railing around the fountain.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	Concrete guard post located at the Pay and Park area to the south of the Fountain. Area around the fountain is paved. Lawn, shrubs are planned in the island. Lamp posts are installed at intervals.		
8.0		Services & Utilities		
8.1	Lighting	-		
8.2	Ventilation	-		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	-		
8.7	Other (HVAC/BMS/Security Systems)	-		
9.0		Condition		
9.1	Plinth	All the parts of the fountain are insensitively finished with oil paint. There are numerous layers of oil paint of different colors, resulting in clogging of pores. Growth of plants and algae is visible at many sections.		
9.2	Walls	-		
9.3	Floor	-		
9.4	Stairs	-		

gton Fountain	219		
	-		
	-		
Articulation & Finishes	Multiple layers of paint are applied on the fountain. The original material and finish cannot be identified.		
Services	-		
Out Buildings	-		
Overall Conditions	Fair Maintenance Low level		
	Transformation		
Form	-		
Structure	Fencing around the fountain, surrounding area is occupied by parking lot. Signage board obstructs the vision of the fountain from the Gateway of India end.		
Articulation & Finishes	All the features are insensitively painted. The original material and finish cannot be identified.		
	DP Remarks/ Perceived Threats		
	It has been demarcated for transport and area demarcated as Open Spaces.		
	Additional Notes/ References/ Documents available		
	Additional Notes/ References/ Documents available Additional Notes: The fountain was erected by public subscription around 1865 to commemorate the visits of the Duke of Wellington to Bombay in 1801 and 1804. There are eight bas-reliefs on the pedestal, illustrating the Duke's many victories in battle. Sadly, this fountain, which was one of the earliest to be installed in Bombay, has been painted like other fountains in the city – a 'beautifying' effort that actually damages porous stone with the permeation of synthetic paint through its natural crevices. The parking around the fountain and the double layer of enclosing fencing have also significantly altered the pivotal quality that such monuments exert on traffic intersections. References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. ABHA NARAIN LAMBAH Through the Looking Glass – The Grade I Heritage of Mumbai, Mumbai : Urban Design Research Institute,		
	Openings Roofing Articulation & Finishes Services Out Buildings Overall Conditions Form		

F. Wellington Fountain









A 1	MOONLIGHT		
		ommon Ref no: A1	Not Available
		ird No.:	
Ward :		ard : Ward A	
		S No. 1552	
		ot Area: 1144.97	
		U Area : 3686	
STREET.		ite : January, 2013	
		ecord by : Aneri S, Adele Z	
		eview by : Shraddha B.	
一个场		: As above Ext: As above	
- DN		oto Ref : A1 MOONLIGHT a-e	
1.0		DENOMINATION	
1.1	Name of Premises	Moonlight	
1.2	Earlier Name	Not applicable	
1.3	Built In : 1930's	Extension Date(if any): Not Appli	cable
2.0		ACCESS ROADS	
2.1	Main	Madam Cama road	
2.2	Subsidiary	Maharshi Karve road	
3.0		OWNERSHIP PATTERN	
3.1	Present	Nargis Abdul Rahman Antulay	
		Naveed Abdul Rehaman Antulay	
3.2	Past		cretary of state for India in council,
		Phirozshaw Cooverji Mistry & his	
			shaw Mistry & Shiarox Phirozshaw
			stry & Behram Phirozshaw Mistry &
		Homi Phirozshaw Mistry & Mani	
		Engineer & Mrs.Tarabai Madhav	
			ao Madhavrao Ghatate & Shridhar
2.2	Chalas	Madhavrao Ghatate	
3.3	Status	Tenanted	
4.0		USE	
4.0	Present		ent in the right wing used by Power
4.1		Finance Corporation Ltd.)	ient in the right wing used by Powel
4.2	Past	Residential	
4.2	Usage	Regular in residential use	
4.5			
5.0		SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		nt, which is one of the major North-
			he junction of Madam Cama road.
5.2	Architectural Description	Planning: It is a large building in	modest Art Deco style with
		adequate light and ventilation. It	has a void where the interior
		windows of the buildings open in	
			ing is curved along the junction of
		the main and subsidiary road, the	
		road are large, and balconies fac	ing the main road are narrower.

A 1	MOONLIGHT		
		The front gate and most of the grills of the building are still the original Art Deco style grills.	
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations.	
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
0.1			
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well stone staircase with marble cladding and wooden railing.	
7.5	Openings	Regular openings with wooden frames and glazed shutters.	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Curved corner	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Granite flooring in the lobby Staircases: Polished marble staircase	
7.9	Interiors (Movable & Immovable)	Entrance Foyer	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building	
8.0		SERVICES & UTILITIES	
8.1	Lighting		
8.2	Lighting Ventilation	Natural and artificial, good natural lighting Natural and artificial, good natural lighting	
8.2 8.3	Electricity	BEST	
8.3 8.4	Water Supply	MCGM	
8.4 8.5	Drainage (Plumbing and sanitation)	MCGM	
8.5 8.6	Fire Precaution	Not provided	
8.0 8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
0.7			
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good (no structural damage but needs cleaning and polishing)	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
-		I	

A 1	MOONLIGHT	
9.8	Services	Good (Drainage pipe needs no replacement)
9.9	Outbuildings	Good
9.10	Overall Condition	Good
10.0		TRANSFORMATION
10.1	Form	Additional apartment on the terrace level
10.2	Structure	No transformation
10.3	Articulation & Finishes	Recently painted
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A1 MOONLIGHT





(c)







(d)



A 2	SUNSHINE			
-772		Commo	n Ref no: A2	Not Available
		Card No		
		Ward : \		
A. 18		CS No.:		
			ea : 1209.28	
	- All share - may till		a : 2877	
The state			anuary, 2013	
Till are				-
and an Ille			by : Aneri S, Adele Z by : Shraddha B.	
A BOARD		Int : As		
			Ref : A2 SUNSHINE a-e	
1.0			DENOMINATION	
1.1	Name of Premises		Sunshine	
1.1	Earlier Name		Not applicable	
1.2	Built In : 1936		Extension Date(if any): Not App	alicablo
1.3			LATENSION DATE(II ANY). NUT APL	
2.0			ACCESS ROADS	
2.0	Main		Maharshi Karve Road	
2.1	Subsidiary		Not applicable	
Z.Z				
3.0			OWNERSHIP PATTERN	
3.1	Present			- Housing Society Ltd
3.1	Past		The real Sunshine Co-operative Housing Society Ltd. The Governor of Bombay, Phirozshaw Cooverji Mistry & his wife Bai	
J.Z	Fasi			Mistry & Pesi Phirozshaw Mistry &
				ulstad Phirozshaw Mistry & Behram
				ozshaw Mistry & Mani Gali Shroff &
			Rati Jamshed Engineer & Mrs. ⁻	
				e & Narayanrao Madhavrao Ghatate &
			Shridhar Madhavrao Ghatate	a Marayaniao Madhaviao Ohatate a
3.3	Status		Co-operative Housing Society	
5.5			co-operative housing Society	
4.0			USE	
4.0	Present		Residential	
4.1	Past		Residential	
4.2				
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			ont, which is one of the major North-
			South arterial roads.	
5.2	Architectural Description		Planning: It is a large building in	n modest Art Deco style with
0.2			adequate light and ventilation. I	
			windows of the buildings open i	
				es facing the road are recessed and
				d most of the grills of the building are
				rills. Horizontal and vertical bands
				cing side of the building. The interior
			mailboxes and the design near	
				ject out towards the left rear edge of
L				

A 2	SUNSHINE		
-772		the building.	
		the senenge	
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations.	
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
0.1			
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Vertical and horizontal moldings	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Cement terrazzo in the lobby Staircases: Polished wooden staircase	
7.9	Interiors(Movable & Immovable)	None	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
0.7			
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good (no structural damage but needs cleaning and polishing)	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	

A 2	SUNSHINE	
9.8	Services	Good (Drainage pipe needs no replacement)
9.9	Outbuildings	Good
9.10	Overall Condition	Good
10.0		TRANSFORMATION
10.1	Form	No transformation
10.2	Structure	No transformation
10.3	Articulation & Finishes	Recently painted
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A2 SUNSHINE

(a)



(b)



(C)

(d)



A 3	IVORINE		
		Commo	on Ref no: A3
		Card N	Hore to a
ALC: NO			Ward A
an -	CS No		
34			ea : Not Available
			ea: 3591
			January 2012
			I by : Aneri S, Adele Z
Carlo Carlo			v by : Shraddha B.
E FLOR			above Ext: As above
			Ref : A3 IVORINE a-e
1.0			DENOMINATION
1.1	Name of Premises		Ivorine
1.2	Earlier Name		Not applicable
1.3	Built In:1930's		Extension Date(if any): Not Applicable
2.0			ACCESS ROADS
2.1	Main		Maharshi Karve road
2.2	Subsidiary		J.D. Daruwala Marg
3.0			OWNERSHIP PATTERN
3.1	Present		Not Available
3.2	Past		Not Available
3.3	Status		Tenanted
0.0			Tohuhudu
4.0			USE
4.1	Present		Residential
4.2	Past		Residential
4.3	Usage		Regular in residential use
5.0			SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Maharshi Karve road front, which is one of the major North-
F 0	Analytic should be a shallow		South arterial roads, situated at the junction of J.D. Daruwala road
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with
			adequate light and ventilation. It has a void where the interior
			windows of the buildings open into.
			Stylistic Classification: The Building rounded along the junction of the road, the balconies facing the subsidiary road are rounded and
			project out, the balconies facing the subsidiary road are recessed and
			small . The front gate and most of the grills of the building are still the
			original Art Deco style grills.
			A service spiral staircase at the rear end of the building. Rectangular
			chajjas on the front of the building and rounded at the rear end.
5.3	Intrinsic		Art Deco building representing its era. The various Art Deco style
			buildings on the newly reclaimed lands created a cohesive image.
			Like the Gothic buildings in their time represented the new face of
			the city and an expression of power, so did the Art Deco buildings
			and precincts symbolized the shift in expression to represent

A 3	IVORINE		
		contemporary aspirations.	
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well stone staircase with granite cladding	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded corner	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Marble flooring in the lobby Staircases: Granite Cladding	
7.9	Interiors(Movable & Immovable)	Entrance canopy	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building and a temporary service shed	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good (no structural damage but needs cleaning and polishing)	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good (Drainage pipe needs no replacement)	
9.9 9.10	Outbuildings	Good	
	Overall Condition	Good	

A 3	IVORINE	
10.0		TRANSFORMATION
10.1	Form	No transformation
10.2	Structure	No transformation
10.3	Articulation & Finishes	Recently painted
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

(b)















A 4	PALM COURT			
		Comm	non Ref no: A4	
	Card N Ward CS No			The second second
1 2 4 4 go 1 4			: Ward A	
5 2 1				
			rea : 1352.85	
			rea : 3510	Palm Court
			January, 2013	
-			d by : Aneri S, Adele Z	PLOT No. 191 B.B.A
			w by : Shraddha B.	Propagane /
			s above Ext: As above	+
			Ref : A4 PALM COURT a-d	
1.0			DENOMINATION	
1.1	Name of Premises		Palm court	
1.2	Earlier Name		Not applicable	
1.3	Built In:1930's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Maharshi Karve road	
2.2	Subsidiary		J.D. Daruwala Marg	
2.2			Sibi baranala marg	
3.0			OWNERSHIP PATTERN	
3.1	Present		Palm court Buildings Limited	
3.2	Past		The Governor of Bombay	
3.3	Status		Tenanted	
0.0			lonantoa	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)			ont, which is one of the major North-
				the junction of J.D. Daruwala road
5.2	Architectural Description		Planning: It is a large building in	
0.2			adequate light and ventilation.	
			windows of the buildings open in	
				ding curved along the junction of the
			road, the balconies facing the s	
				are narrower. The structure has a
			spiral service staircase. The front gate and most of the grills of the	
				Deco style grills. Shows recessed
			balconies on the façade facing	
			recessed windows on the rear f	
5.3	Intrinsic			its era. The various Art Deco style
				d lands created a cohesive image.
				r time represented the new face of
				ower, so did the Art Deco buildings
			and precincts symbolized the sh	nift in expression to represent

A 4	PALM COURT		
		contemporary aspirations.	
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Dog legged wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded corner	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Cement terrazzo Staircases: Polished wooden staircase	
7.9	Interiors(Movable & Immovable)	Entrance Foyer	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building , Pump room, Meter room, Underground water tank	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good(Needs painting)	
9.2	Walls	Good (Shallow cracks, needs painting)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Fair	
9.8	Services	Fair (Drainage pipe needs cleaning and a few of them needs to be changed)	
9.9	Outbuildings	Bad(need repairs and painting)	
9.10	Overall Condition	Fair	
-			

A 4	PALM COURT	
10.0		TRANSFORMATION
10.1	Form	Additional box grills, A.C.P. sheet chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	No transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A4 PALM COURT

(a)



(b)



(C)



A 5	OVAL VIEW		
		Comm	non Ref no: A5
		Card N	
			Ward A
- Ma			0. 1548
	and a star of the second star of the		rea : 1365.39
-	and the second sec		roa : 2262
	AND DE CONTRACTOR	-	January, 2013
			d by : Aneri S, Adele Z
	A REAL PROPERTY AND	Review	w by : Shraddha B.
1			s above Ext: As above
			Ref : A5 OVAL VIEW a-e
1.0		1 11010	DENOMINATION
1.1	Name of Premises		Oval view
1.2	Earlier Name		Not applicable
1.3	Built In: 1930's		Extension Date(if any): Not Applicable
2.0			ACCESS ROADS
2.1	Main		Maharshi Karve road
2.2	Subsidiary		Not applicable
3.0			OWNERSHIP PATTERN
3.1	Present		The Life Insurance Corporation of India
3.2	Past		The Secretary of State for India in Council, M/s. Mafatlal Gagalbhai
			& Co Private Ltd.]
3.3	Status		Tenanted
1.0			105
4.0			USE
4.1	Present		Residential
4.2	Past		Residential
4.3	Usage		Regular in residential use
FO			
5.0 5.1	Townscape(Natural/Manmade)		SIGNIFICANCE & VALUE CLASSIFICATION Part of Maharshi Karve road front, which is one of the major North-
D. I	Townscape(Natural/Marimaue)		South arterial roads.
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with
J.Z	Architectural Description		adequate light and ventilation. It has a void where the interior
			windows of the buildings open into.
			The Building rounded along the left corner, the balconies facing the
			main road are large rounded and project out. The balconies on the
			rear end of the building are projecting out and are smaller. The front
			gate and most of the grills of the building are still the original Art
			Deco style grills. The structure has a spiral service staircase.
5.3	Intrinsic		Art Deco building representing its era. The various Art Deco style
			buildings on the newly reclaimed lands created a cohesive image.
			Like the Gothic buildings in their time represented the new face of
			the city and an expression of power, so did the Art Deco buildings
			and precincts symbolized the shift in expression to represent
			contemporary aspirations.

A 5	OVAL VIEW		
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded corner	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Cement terrazo Staircases: Wooden polished	
7.9	Interiors(Movable & Immovable)	None	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grills at equal intervals; Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, Pump room, U.G.T., Meter room	
0.0		SERVICES & UTILITIES	
8.0 8.1		Natural and artificial, good natural lighting	
8.2	Lighting Ventilation		
8.3	Electricity	Natural and artificial, good natural lighting BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.0	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Average (needs cleaning)	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good (Drainage pipe needs no replacement)	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	
-			

A 5	OVAL VIEW	
10.0		TRANSFORMATION
10.1	Form	A.C.P. sheet canopy on the ground floor and roofing on the top floor balcony, box grills, A.C.P. chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	Painted
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995





(C)





(d)




Δ.6	RELVEDEDE COUDT			
- A 0		Common	n Ref no: A6 (Reviewed in	
		2013)		NATHIBAL THALFROMY CO
De.		Card No.	· A-18b	
-			art): Ward A	
100 miles		CS No. 1		
			a: 1352.85	
1	A AND THE A A A A A A A A A A A A A A A A A A A		a: 2959.30	
		Date: Ap		
			y: Raveena Garg	I BOXANA
-	the second second second	Review b	y: Shraddha B.	
-	BELADERE BOURT	Int: As at]
		Photo Re	ef: A6 BELVEDERE	1
		COURT		
1.0			DENOMINATION	
1.1	Name of Premises		Belvedere Court	
1.2	Earlier Name		Not applicable	
1.3	Built In 1940		Extension Date(if any): No	t applicable
2.0			ACCESS ROADS	
2.1	Main		Maharshi Karve Road (Que	en's Road)
2.2	Subsidiary		Nathibai Thakersay Road	, some rieday
3.0			OWNERSHIP PATTER	
3.1	Present		The Life Insurance Corpora	
			Gagalbhai & Company Priv	rate Ltd, The Governor Of
			BombayMA	
3.2			The Governor Of Bombay	
3.3	Status		The Life Insurance Corpora	ation Of India
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular residential use	
5.0				LUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)			coad front, which is one of the
			major	
				s, situated at the junction of
			Nathibai	
5.2	Architectural Description		Thakersay Road.	o parts of recessed balconies
0.Z				the corners. Front elevation
			has moldings in the center.	
5.3	Intrinsic		Art Deco building represent	ting its era. The various Art
			Deco style	
			buildings on the newly recla	aimed lands created a cohesive

A 6	BELVEDERE COURT	
-110-		image.
		Like the Gothic buildings in their time represented the new
		face of
		the city and an expression of power, so too the Art Deco
		buildings
		and precincts symbolized the shift in expression to
		represent
		contemporary aspirations.
5.4	Value Classification	Existing Grade: NA Recommended Grade: III
0.1		A(arc), B(des), G(grp), E, I(sce)
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Brick masonry plinth
7.2	Walls	Plastered masonry plinth
7.2	Floor	R.C.C. floor slab
7.4	Stairs	R.C.C. open well staircase with wooden cladding
7.5	Openings	Rectangular openings with wooden frames and translucent
7.5	openings	shutters
7.6	Roofing	Flat roof terrace
7.7	Articulation	Moldings in the center, projecting balconies at corner
7.8	Finishes	Walls: Internally and externally cement plastered and
7.0		painted
		Flooring : Marble flooring
		Staircases: Polished marble staircase with wooden
		cladding.
7.9	Interiors(Movable & Immovable)	Entrance foyer
7.10	Compound/Fence/Gate	Plastered brick wall. M.S. gates are (original) painted.
7.10	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building.
7.11	Curriege/ Onbuilt space/out buildings/landscape	r arking shous at the rear side of the building.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural ventilation
8.3	Electricity	BEST
8.4	Water Supply	MCGM
0.4 8.5	Drainage (Plumbing and sanitation)	MCGM
8.5 8.6	Fire Precaution	Not provided
8.0 8.7	Other (HVAC/BMC/Security Systems)	Not provided
0.7	UITER (ITVAC/DIVIC/JECUITY JYSTETTS)	
0.0		CONDITION
9.0	Dlinth	CONDITION
9.1	Plinth	Good (No settlement or cracks observed but needs
0.2	Walls	maintenance)
9.2	Walls	Good (No dampness or cracks observed)
9.3	Floor	Good(Replaced by ceramic tiles)
9.4	Stairs	Good(Needs polishing)

A 6	BELVEDERE COURT		
9.5	Openings	Good	
9.6	Roofing	Good (No leakage observed)	
9.7	Articulation & Finishes	Good	
9.8	Services	Good (Drainage pipes need no replacement)	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good Maintenance level Good	
10.0		TRANSFORMATION	
10.1	Form	No transformation	
10.2	Structure	No transformation	
10.3	Articulation & Finishes	No transformation	
11.0	DP REMARKS/PERCEIVED THREATS	Plot falls under Residential Zone in DP	
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps -	
	NOTES/REFERENCES/DOCUMENTS	Mumbai,	
	AVAILABLE/RECOMMENDATIONS &	Dwivedi, Mehrotra Bombay, The Cities Within Bombay	
	SUGGESTIONS FOR IMPLEMENTATION	1995	

A6 BELVEDERE COURT






Α7	A7 SHIV SHANTI BHUVAN				
			on Ref no: A7		
		Card N			
		Ward: Ward A		Particular and a second s	
			0. 1546		
			rea : Not Available		
Property in	B D		rea: 3546		
			January, 2013	Shingly Bharan	
1 20			d by : Aneri S, Adele Z	12 12 No. 128 8.8.R.	
			w by : Shraddha B.	4-manual o	
The second	Address from the		s above Ext: As above	the second se	
-11			Ref: A7 SHIV SHANTI		
			AN a-e		
1.0		-	DENOMINATION		
1.1	Name of Premises		Shiv Shanti Bhuvan		
1.2	Earlier Name		Not applicable		
1.3	Built In : 1930's		Extension Date(if any): Not App	licable	
2.0			ACCESS ROADS		
2.1	Main		Private (H.T. Parekh Marg)		
2.2	Subsidiary		Maharishi Karve road		
3.0			OWNERSHIP PATTERN		
3.1	Present		Not Available		
3.2	Past		Not Available		
3.3	Status		Co-operative Housing Society		
4.0			USE		
4.1	Present		Residential		
4.2	Past		Residential		
4.3	Usage		Regular in residential use		
			-		
5.0	-		SIGNIFICANCE & VALUE		
5.1	Townscape(Natural/Manmade)			ont, which is one of the major North-	
5.2	Architectural Description		South arterial roads. Planning: It is a large building in	modest Art Deco style with	
J.Z			adequate light and ventilation.	modest Art Deco style with	
				corner at the junction of H.T. Parekh	
				bund balcony on the first floor of the	
				Typical Art Deco panel made of glass	
				taircase on the surface facing the	
				dings on front and side facades.	
5.3	Intrinsic			is era. The various Art Deco style	
			buildings on the newly reclaimed	d lands created a cohesive image.	
				time represented the new face of	
				wer, so did the Art Deco buildings	
			and precincts symbolized the sh	ift in expression to represent	
			contemporary aspirations.		

Α7	SHIV SHANTI BHUVAN		
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Vertical and horizontal moldings	
1.1	Aniculation	Venical and horizontal molalitys	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Mosaic tiling in the lobby Staircases: Polished wooden staircase	
7.9	Interiors(Movable & Immovable)	None	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill (original)	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, U.G.T.	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Gas sprinkler system	
8.7	Other (HVAC/BMC/Security Systems)	Video surveillance provided for security purposes.	
9.0		CONDITION	
9.0 9.1	Plinth	Good	
9.1 9.2	Walls	Good	
9.2 9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.0 9.7	Articulation & Finishes	Good	
9.7 9.8	Services	Good (Drainage pipe needs no replacement)	
9.0 9.9	Outbuildings	Good (brainage pipe needs no replacement) Good (needs regular cleaning)	
9.9 9.10	Overall Condition	Good	

A 7	SHIV SHANTI BHUVAN	
10.0		TRANSFORMATION
10.1	Form	No transformation
10.2	Structure	No transformation
10.3	Articulation & Finishes	Painting of the building going on
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

(a)



(b)



(C)







A 8	RAJJAB MAHAL	
		Common Ref no: A8 (reviewed in
R. Bat	12000	2013)
	and the state of t	Card No.: A-34
Ling	No.	Ward (Part): Ward A
1 157		CS No.: 1545
		Plot Area: 1365.39 sq.m.
-		B U Area: 7168.29 sq.m.
12	AND MALEN	Date: September, 2005
	A STATE OF THE OWNER	Record by: Gauri J, Ambika K
		Review by: Neera Adarkar
a far en en en		Int: As above Ext: As above
		Photo Ref: A8 RAJJAB MAHAL a-f
1.0		DENOMINATION
1.1	Name of Premises	Rajjab Mahal
1.2	Earlier Name	Not applicable
1.3	Built In: 1930s	Extension Date(if any): Not applicable
2.0		ACCESS ROADS
2.1	Main	Maharshi Karve Marg (Queen's Road)
2.2	Subsidiary	Not applicable
3.0		OWNERSHIP PATTERN
3.1	Present	Rajjab Mahal Co-operative Housing Society
3.2	Past	Governor of Bombay (Lessor)
3.3	Status	Co-Op Housing Society
4.0		USE
4.1	Present	Residential
4.2	Past	Residential
4.3	Usage	Regular residential use
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Facing Oval Maidan, this precinct has buildings of same scale and
	, , , , , , , , , , , , , , , , , , , ,	foot prints. Forms part of Fort Precinct.
5.2	Architectural Description	An Art Deco building having features like curved balconies at the
		corners, projecting bands at all floor levels and central bay
		accentuated with symmetrical stepped profile adds to the grandeur.
		The M.S. railing symmetrically set between the masonry parapets
		of the balconies and window mullion pattern are typical Art Deco
		features. The façade bears motifs like grooved floor bands.
5.3	Intrinsic	The various Art Deco style buildings on the newly reclaimed lands
		created a cohesive image. Like the Gothic buildings in their time
		represented the new face of the city and an expression of power,
		so too the Art Deco buildings and precincts symbolized the shift in
		expression to represent contemporary life style.
5.4	Value Classification	Existing Grade: NA Recommended Grade: III
		A(arc), G(grp), I(sce)

A 8	RAJJAB MAHAL			
Ao	RAJJAD MAHAL			
6.0		TOPOGRAPHY		
6.1	Floors	G + 6		
0.1				
7.0		CONSTRUCTION		
7.1	Plinth	Plastered masonry plinth		
7.2	Walls	Brick masonry walls		
7.3	Floor	R.C.C. floor slab		
7.4	Stairs	Open well wooden staircase with decorative wooden balustrade		
7.5	Openings	Rectangular openings with wooden frames and glazed shutters		
7.0	oponingo			
7.6	Roofing	Flat roof with terrace		
7.7	Articulation	Minimal articulation on the façade except for projecting bands on		
		all the floors and rounded balconies at the corners.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors(Movable&Immovable)	Entrance foyer		
7.10	Compound/Fence/Gate	Plastered brick wall		
7.11	Curtilege/ Unbuilt space/out	Marginal paved side open spaces		
	buildings/landscape			
8.0		SERVICES & UTILITIES		
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and sanitation)	MCGM		
8.6	Fire Precaution	Not provided		
8.7	Other (HVAC/BMC/Security Systems)	Window air-conditioning units		
9.0		CONDITION		
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good		
9.4	Stairs	Good (Wooden members in good condition)		
9.5	Openings	Good		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Good		
9.8	Services	Good (Drainage pipes need no replacement)		
9.9	Outbuildings	Good		
9.10	Overall Condition	Good Maintenance level Good		
10.0				
10.0	. Form	TRANSFORMATION		
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		

A 8	RAJJAB MAHAL	
11.0	DP REMARKS/PERCEIVED THREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai, Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995







(C)



(e)



(b)



(d)



(f)



A 9	EMPRESS COURT		
		2013) Card No. Ward (Pa CS No.: Plot Area B U Area Date: Se Record b Review b Int: As ab	art): Ward A 1544 1544 1644.65 sq.m. 168634.41 sq.m. ptember, 2005 by: Gauri J, Ambika K by: Neera Adarkar
1.0			DENOMINATION
1.1	Name of Premises	E	mpress Court
1.2	Earlier Name	Ν	lot applicable
1.3	Built In: 1930s		Extension Date(if any): Not applicable
2.0		ŀ	ACCESS ROADS
2.1	Main		Aharshi Karve Marg (Queen's Road)
2.2	Subsidiary		Dinsha Wacha Road
3.0			OWNERSHIP PATTERN
3.1	Present		Ar. Hector H. Mehta and Others
3.2	Past	F a	Governor of Bombay (Lessor) Ramesh Dhirajlal Mehta, Firedoon Ardeshir Mehta. Trustees under I Deed of trust Hector Hoshang Mehta dated 1964
3.3	Status	T	enanted
4.0		ι	JSE
4.1	Present	F	Residential
4.2	Past	F	Residential
4.3	Usage	F	Regular residential use
5.0			SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	e p F	Responds to the junction of north south Maharshi Karve road and east west Dinshaw Watchha Road. Facing Oval Maidan this precinct has buildings of same scale and foot prints. Part of Fort Precinct.
5.2	Architectural Description	b C T C n	ypical corner building in Art Deco style having a splayed staircase bay accentuated with a pavilion type room on the terrace and with surved balconies as if emerging out of the corner splayed façade. The projecting bands especially at all the top floors highlight the otherwise plain character. The façade also bearstypical Art Deco notifs like grooved floor bands.
5.3	Intrinsic	T C	he various Art Deco style buildings on the newly reclaimed lands reated a cohesive image. Like the Gothic buildings in their time epresented the new face of the city and an expression of power,

A 9	EMPRESS COURT	so too the Art Deco buildings and precincts symbolized the shift in		
		expression to represent contemporary life style of the elite class.		
5.4	Value Classification	Existing Grade: NA Recommended Grade: III		
0.1		A(arc), G(grp), I(sce)		
6.0		TOPOGRAPHY		
6.1	Floors	G + 6		
7.0		CONSTRUCTION		
7.1	Plinth	Plastered masonry plinth		
7.2	Walls	Brick masonry walls		
7.3	Floor	R.C.C. floor slab		
7.4	Stairs	Open well wooden staircase with decorative wooden balustrade		
7.5	Openings	Rectangular openings with wooden frames and glazed shutters		
7.6	Roofing	Flat roof with terrace		
7.7	Articulation	Minimal articulation on the façade except for projecting bands on		
		all the floors and rounded balconies at the corners.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors(Movable & Immovable)	Entrance foyer		
7.10	Compound/Fence/Gate	Plastered brick wall		
7.11	Curtilege/ Unbuilt space/out	Marginal paved side open spaces		
	buildings/landscape			
8.0		SERVICES & UTILITIES		
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and sanitation)	MCGM		
8.6	Fire Precaution	Not provided		
8.7	Other (HVAC/BMC/Security Systems)	Window air-conditioning units		
9.0		CONDITION		
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good		
9.4	Stairs	Good (Wooden members in good condition)		
9.5	Openings	Good		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Good		
9.8	Services	Good (Drainage pipes need no replacement)		
9.9	Outbuildings	Good		
9.10	Overall Condition	Good Maintenance level Good		
10.0		TRANSFORMATION		
10.1	Form	No transformation		
10.2	Structure	No transformation		

A 9	EMPRESS COURT		
10.3	Articulation & Finishes	No transformation	
11.0	DP REMARKS/PERCEIVED	Plot falls under Residential Zone in DP	
	THREATS		
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai,	
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995	
	AVAILABLE/RECOMMENDATIONS		
	& SUGGESTIONS FOR		
	IMPLEMENTATION		

A9 EMPRESS COURT

(a)

(b)



(C)



(d)





A10	RAJESH MANSION			
		Comn	non Ref no: A10	5.0 8
		Card		d=
			Ward A	1 games and 1
			0. 1543	ice let
			vrea : 1202.34	A REAL
			rea : 3890	
	A CONTRACTOR OF THE OWNER		: January, 2013	
			rd by : Aneri S, Adele Z	The set of the
			w by : Shraddha B.	
	A CONTRACTOR OF A CONTRACTOR O		s above Ext: As above	4 0
			Ref : A10 RAJESH MANSION	the state of the s
		a-e		
1.0		u u	DENOMINATION	
1.1	Name of Premises		Rajesh Mansion	
1.2	Earlier Name		Sorab Mansion	
1.3	Built In 1930's		Extension Date(if any): Not Ap	plicable
				p
2.0			ACCESS ROADS	
2.1	Main		Dinshaw Vatcha road	
2.2	Subsidiary		Maharshi Karve road	
3.0			OWNERSHIP PATTERN	
3.1	Present		Oval Co-operative Housing Society Ltd	
3.2	Past			Aimai Sorabji Shavkasha, The Central
0.2				bany Ltd., Shavak Sorabji Shavaksha
			& Pirosha Sorabji Shavaksha	
				aji, the Jam Shri Ranjitsinhji Spinning
			and Weaving Mills Company Li	
3.3	Status		Co-operative Housing Society	
4.0			USE	
4.1	Present		Mixed use(entire ground floor h	as IDBI bank)
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Maharshi Karve road fr	ont, which is one of the major North-
			South arterial roads, situated at the junction of Madam Cama road.	
5.2	Architectural Description		Planning: It is a large building ir	n modest Art Deco style with
			adequate light and ventilation.	
			Stylistic Classification: The build	
				the Maharishi Karve road, Recessed
				The building has a rounded corner at
				road. Show the original grills on the
				Driginal wooden chajjas still retained
			on all windows.	
5.3	5 1 5			
	buildings on the newly reclaimed lands created			d lands created a cohesive image.


A10	RAJESH MANSION	
		Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations.
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well marble staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.0	Articulation	Rounded corner
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Polished marble flooring in the lobby Staircases: Polished marble staircase
7.9	Interiors(Movable & Immovable)	Entrance Foyer
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S. (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.0 9.9	Outbuildings	Good
9.10	Overall Condition	Good

A10	RAJESH MANSION	
10.0		TRANSFORMATION
10.1	Form	Additional office on the terrace level
10.2	Structure	No transformation
10.3	Articulation & Finishes	Building is getting painted
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A10 RAJESH MANSION



(b)









(d)



A <u>11</u>	WINDSOR HOUSE			
			on Ref no: A11 (Reviewed in	
	(m)	2013)		
TIT B	The second second		lo.: A-35 Part) : A .: 1542 ea: 988.29 sq.m.	
THE F			Part) : A	
11	and a second		.: 1542	
The second se			ea: 988.29 sq.m.	
and the second			ea: 3913.62 sq.m.	
II II			September, 2005	
L. P.			I by: Gauri J, Ambika K	
1			v by: Neera Adarkar above Ext: As above	
			Ref: A11 WINDSOR HOUSE a-	
- States			Rel: ATT WINDSOR HOUSE a-	
		С		
1.0			DENOMINATION	
1.1	Name of Premises		Windsor House	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1930s		Extension Date(if any): Not applicable	
1.0				
2.0			ACCESS ROADS	
2.1	Main		Maharshi Karve Marg (Queen's Road)	
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Windsor House Co-operative Housing Society	
3.2	Past		The Governor of Maharashtra (lessor)	
3.3	Status		Co-operative Society	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular residential use	
5.0			SIGNIFICANCE & VALUE CLASSIFICATION	
5.1	Townscape(Natural/Manmade)		Facing Oval Maidan, this precinct has buildings of same scale and	
5.0			foot prints. Forms part of Fort Precinct.	
5.2	Architectural Description		Belongs to the typology of Art deco building with plain facades	
			highlighted only by a series of balconies, curved on the corners of	
			the building, and with projecting bands/chajjas at all floor levels.	
5.3	Intrinsic		The various Art Deco style buildings on the newly reclaimed lands	
0.5	munisic		created a cohesive image. Like the Gothic buildings in their time	
			represented the new face of the city and an expression of power,	
			so too the Art Deco buildings and precincts symbolized the shift in	
			expression to represent contemporary aspirations.	
			· · · · · · · · · · ·	
5.4	4 Value Classification Existing Grade: NA Recommended Grade: III		Existing Grade: NA Recommended Grade: III	
			A(arc), G(grp), I(sce)	

A11	WINDSOR HOUSE			
AII	WINDSOR HOUSE			
6.0		TOPOGRAPHY		
6.1	Floors	G+5		
0.1	1 1001 3			
7.0		CONSTRUCTION		
7.1	Plinth	Plastered masonry plinth		
7.1	Walls	Brick masonry walls		
7.2	Floor	R.C.C. floor slab		
7.4	Stairs	Open well wooden staircase with decorative wooden balustrade		
7.4	Openings	Rectangular openings with wooden frames and glazed shutters		
7.5	Opennigs	Reciangular openings with wooden names and glazed shutters		
7.6	Roofing	Flat roof with terrace		
7.7	Articulation	Minimal articulation on the façade except for projecting bands on		
7.7		all the floors and rounded balconies at the corners.		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors(Movable&Immovable)	Entrance foyer		
7.10	Compound/Fence/Gate	Plastered brick wall		
7.11	Curtilege/ Unbuilt space/out	Marginal paved side open spaces		
	buildings/landscape			
8.0		SERVICES & UTILITIES		
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and sanitatition)	MCGM		
8.6	Fire Precaution	Not provided		
8.7	Other (HVAC/BMC/Security Systems)	Window air-conditioning units		
		÷		
9.0		CONDITION		
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good		
9.4	Stairs	Good (Wooden members need maintenance)		
9.5	Openings	Good		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Good		
9.8	Services	Good (Drainage pipes need no replacement)		
9.9	Outbuildings	Good		
9.10	Overall Condition	Good Maintenance level Good		
10.0		TRANSFORMATION		
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		

A11	WINDSOR HOUSE		
11.0	DP REMARKS/PERCEIVED THREATS	Plot falls under Residential Zone in DP	
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai, Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995	





(b)





(C)



A12	QUEEN'S COURT			
		Comm	non Ref no: A12	I I
		Card N		
2			: Ward A	and the second second
). 1541	pro-
		rea : 1007.52	E. F. F.	
		rea : 3444	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		January, 2013		
×.			d by : Aneri S, Adele Z	A Land
			w by : Shraddha B.	
			s above Ext: As above	
6			Ref : A12 QUEEN'S COURT a-	
		d		
1.0		-	DENOMINATION	
1.1	Name of Premises		Queen;s Court	
1.2	Earlier Name		Not applicable	
1.3	Built In 1930's		Extension Date(if any): Not Applica	able
2.0			ACCESS ROADS	
2.0	Main		Maharishi Karve road	
2.1			Not applicable	
Z.Z	Subsidiary			
3.0			OWNERSHIP PATTERN	
3.1	Present		The Life Insurance Corporation of India	
3.2	Past		The Governor of Bombay. M/s. Ma	afatlal Gagalbhai & Co.private Ltd.
3.3	Status		Tenanted	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE C	LASSIFICATION
5.1	Townscape(Natural/Manmade)			, which is one of the major North-
			South arterial roads.	, ,
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with	
			adequate light and ventilation. It have	
			windows of the buildings open into	
			Stylistic Classification: The building	
			façade facing the road, the windows are recessed.	
		The original grills and gates are still maintained. Rectangular		
			balconies projecting out on the sides and back. Shows an interior	
	Intrincia		service staircase at the back of the	
5.3	5.3 Intrinsic		Art Deco building representing its	
			buildings on the newly reclaimed la	
			Like the Gothic buildings in their til	
			the city and an expression of power, so did the Art Deco buildings	
			and precincts symbolized the shift in expression to represent	
L			contemporary aspirations.	

A12	QUEEN'S COURT		
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct	
()		TODOODADUW	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well stone staircase with granite cladding	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Cement terrazzo Staircases: Granite Cladding	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room, temporary sheds, water tank	
0.0			
8.0	Lighting	SERVICES & UTILITIES	
8.1 8.2	Lighting Ventilation	Natural and artificial, good natural lighting	
0.2 8.3	Electricity	Natural and artificial, good natural lighting BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good(exterior walls need painting)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Average (Needs cleaning and repairs)	
9.9	Outbuildings	Average(Shows cracks needs repairs)	
9.10	Overall Condition	Good	

A12	QUEEN'S COURT	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. canopies and chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformations
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A12 QUEEN'S COURT



(b)



(C)



(d)



A13	GREEN FIELDS			
7110		Common Ref no: A13		
		Card No.:		1
		Ward : Ward A		
		CS No. 1540		
		Plot Area: 1015.05		
		B U Area: 3514		or Fa
		Date : January, 2013		
	Record by : Aneri S, Ad			
		Review by : Shraddha E		
			As above	
		Photo Ref : A13 GREE		-
1.0			DENOMINATION	
1.1	Name of Premises		Green fields	
1.2	Earlier Name		Not applicable	
1.3	Built In 1939(approx)		Extension Date(if any): Not A	Applicable
2.0			ACCESS ROADS	
2.1	Main		Maharshi Karve road	
2.2	Subsidiary		Not applicable	
2.0				
3.0 3.1	Dracont		OWNERSHIP PATTERN	
3.1	Present		Urmila Wife of Manoranjan Nandlal Amersey The Governor of Maharashtra , Haridas Madhavdas,	
3.Z	Past		Manmohandas Madhavdas Amaersey, Manoranjan Nandlal	
			Amersey, Purshottam Nandl	
3.3	Status		Tenanted	
0.0				
4.0			USE	
4.1	Present		Mixed use	
4.2	Past		Mixed use	
4.3	Usage		Regular in mixed use	
	j			
5.0			SIGNIFICANCE & VAL	UE CLASSIFICATION
5.1	Townscape(Natural/Manma	ade)		front, which is one of the major
		-	North-South arterial roads.	,
5.2	Architectural Description		A large building in the modes	st Art Deco style adequate light
			and ventilation.	
			Stylistic Classification: The b	uilding shows curved balconies
			and recessed windows on the façade facing the main road.	
			The original Art Deco window	
				valls is retained as well. In the
			interiors the building shows s	
5.0				nd gates are retained as well.
5.3	Intrinsic			ng its era. The various Art Deco
			style buildings on the newly r	
			cohesive image. Like the Go	
				the city and an expression of
			power, so did the Art Deco b	ulidings and precincts

A13	GREEN FIELDS	
		symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under
		Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+6
0.1	FIDUIS	G+0
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with yellow granite cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and
		painted
		Flooring: Cement Terrazzo
		Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates
		are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room,
		temporary sheds, water tank
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the
		houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good(exterior walls need painting)
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.0 9.7	Articulation & Finishes	Good
9.7	Services	Average (Needs cleaning)
<u>9.0</u> 9.9	Outbuildings	Average (Needs cleaning) Average (Needs cleaning)
9.9	Outputilings Overall Condition	Good
7.IU		GUUU

A 1 3	GREEN FIELDS	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. canopy and chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-
	NOTES/REFERENCES/DOCUMENTS	Mumbai,
	AVAILABLE/RECOMMENDATIONS &	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	SUGGESTIONS FOR IMPLEMENTATION	

A13 GREEN FIELDS








(C)

(d)





A14	SWASTIK COURT			
entra a		Comm	non Ref no: A14	Comment of the second s
		No.:	The second secon	
		: Ward A		
	CS No. Plot Ard			
Te.			rea : 903.01	E BB
at l		_	rea : 2538	
			January, 2013	Service Se
THE REAL		Recor	d by : Aneri S, Adele Z	4 4
			w by : Shraddha B.	R. L.
A.		-	s above Ext: As above	
			Ref : A14 SWASTIK COURT a-	1.5
1.0		е	DENOMINATION	
1.0	Name of Premises		Swastik Court	
1.1	Earlier Name		Not applicable	
1.2	Built In 1930's		Extension Date(if any): Not Application	ablo
1.3	Built III 1930 S			
2.0			ACCESS ROADS	
2.1	Main		Maharshi Karve road	
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Deval Vinay Saraiya & Manorama	J. Saraiya
3.2	Past		The Governor of Maharashtra, Va	
				/inod Varjiwandas Saraiya & Vinay
			Varjiwandas Saraiya & Jayant Var	
			Varjiwandas Saraiya & Manorama	Jayant Saraiya
3.3	Status		Tenanted	
1.0			USE	
4.0	Drocont		Residential	
4.1	Present Past		Residential	
4.2	Usage		Regular in residential use	
4.3	Usage			
5.0			SIGNIFICANCE & VALUE C	LASSIFICATION
5.1	Townscape(Natural/Manmade)			t, which is one of the major North-
			South arterial roads.	
5.2	Architectural Description		Planning: It is a large building in m	nodest Art Deco style with
	· ·		adequate light and ventilation.	5
			Stylistic Classification: Curved pro	
				de of the buildings, the old grills on
			the balconies, compound wall and	
			balconies on the sides and rear of	
_			shows recessed windows and curv	
5.3	Intrinsic		Art Deco building representing its	
			buildings on the newly reclaimed la	
			Like the Gothic buildings in their til	
			the city and an expression of powe	er, so did the Art Deco buildings

A14	SWASTIK COURT	
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine
		Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
1.1	Anticulation	Rounded balcomes
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Cement terrazzo
		Staircases: Polished wooden staircase
7.9	Interiors(Movable & Immovable)	Entrance foyer
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S.
		gates (original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,
	buildings/landscape	temporary sheds, water tank
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning)
0.0		CONDITION
9.0	Dlinth	CONDITION
9.1 9.2	Plinth Walls	Good
9.2	Floor	Good
9.3 9.4	Stairs	Good
9.4	Openings	Good
7.0		
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Average (Needs cleaning)
9.9	Outbuildings	Good
9.10	Overall Condition	Good

A14	SWASTIK COURT	
10.0		TRANSFORMATION
10.1	Form	Additional box grills and A.C.P. chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A14 SWASTIK COURT

(C)





(d)





A15	MOTABHOY MANSION	Comp	non Dofino: A1E	
	dist a. analogical	-	non Ref no: A15	f
		-	and the second	
			S Statement S	
1.11				a and a a second a se
1 (1)	KA TO BERNA		rea : 862.88	and
104			rea : 2667	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
1277.			: January, 2013	
Links-			d by : Aneri S, Adele Z	A O B
ili I	RIFER II. IR. III. IN TO SALES		w by : Shraddha B.	A TO TO T
			s above Ext: As above	1
			Ref : A15 MOTABHOY	4 - 1 12
1.0		WANS	SION a-e DENOMINATION	
1.0 1.1	Name of Premises			
1.1	Earlier Name		Motabhoy Mansion Not applicable	
1.2	Built In 1930's		Extension Date(if any): Not Applic	cabla
1.3	Built III 1930 S			
2.0			ACCESS ROADS	
2.1	Main		Maharshi Karve road	
2.2	Subsidiary		Not applicable	
2.2				
3.0			OWNERSHIP PATTERN	
3.1	Present		The Motabhoy Co.Operative Hou	sing Society Limited
3.2	Past		The Governor Of Bombay. Motab	
			Motabhoy Munim & Kantilal Mota	
			Munim, Kantilal Motabhoy Munin	
			Pramila Wd/O Virendra Motabhai	Munim & Kulin Verendra Munim
3.3	Status		Co-Operative Housing Society	
1.0				
4.0			USE	
4.1	Present		Residential	
4.2	Past		Mixed use	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)			nt, which is one of the major North-
			South arterial roads.	
5.2	Architectural Description		Planning: It is a large building in r	modest Art Deco style with
	·····		adequate light and ventilation.	
			Stylistic Classification: The front f	açade shows rectangular
				as, the old Art Deco style grills are
			retained in the windows and the	
			The rear and the sides show back	onies and recessed windows as
			well. A void in the centre of the bu	uilding houses a M.S. spiral
			staircase used as a service stairc	
5.3	Intrinsic		Art Deco building representing its	s era. The various Art Deco style
			buildings on the newly reclaimed	
			Like the Gothic buildings in their t	time represented the new face of


		the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations.
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Ceramic tiles in the lobby Staircases: Wooden polished staircase
7.9	Interiors(Movable & Immovable)	Entrance Foyer and porch steps with marble cladding.
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room, temporary sheds, water tank, and Additional canopy on the left side of the building.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
0.0		
9.0 9.1	Plinth	Good
9.1	Walls	Good Good (Paint scraping off in a few places due to moisture)
9.2	Floor	Good Good
9.3 9.4	Stairs	Good
9.4 9.5	Openings	Good
9.6	Roofing	Good
9.0	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good
2.10		

A15	MOTABHOY MANSION	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , Additional canopy on the left of the building.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A15 MOTABHOY MANSION



(b)





(d)



A16	FAIR LAWN			
7110		Commo	on Ref no: A16	
	Date of the	Card N		
	and with the second		Ward A	do do do
	50 m	CS No.		E C
			ea : 908.03	H H H
	and the second second		ea: 2667	MACT S BOAR
			January, 2013	120
			l by : Aneri S, Adele Z	Lot) Carl
			/ by : Shraddha B.	
	and the state of t	Int : As	5	
	and a second a first of the	Photo F	Ref : A16 FAIRLAWN a-e	L - L
1.0			DENOMINATION	
1.1	Name of Premises		Fair Lawn	
1.2	Earlier Name		Not applicable	
1.3	Built In 1930's		Extension Date(if any): Not App	olicable
2.0			ACCESS ROADS	
2.1	Main		Maharshi Karve road	
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Fair Lawn Co-Operative Housin	
3.2	Past			Fatma Sultan Wife Of Mahomed
0.0			Jaffer Shushtri, Khanun Khadija	Sultan Shaushtary,
3.3	Status		Co-operative Housing Society	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE	
5.0	Townscape(Natural/Manmade)			ont, which is one of the major North-
D. I	Townscape(Natural/Mannade)		South arterial roads.	Unit, which is one of the major north-
5.2	Architectural Description		Planning: It is a large building in	modest Art Deco style with
			adequate light and ventilation.	
				projecting balconies on the façade
				vertical bands on the front façade.
				vindows on the front façade of the
			building with no chajjas. The building has rectangular balconies on	
				on the rear side as well. There is a
	· · · · ·		small service staircase opening	
5.3	Intrinsic			ts era. The various Art Deco style
				d lands created a cohesive image.
				r time represented the new face of
				ower, so did the Art Deco buildings
			and precincts symbolized the sh	in in expression to represent
			contemporary aspirations.	

5.4	Malas Olassifiantian	
	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine Drive Heritage Precinct
()		TODOODADUW
6.0		TOPOGRAPHY
6.1	Floors	G+5
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with granite cladding and a wooden railing
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Cement terrazzo Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	Entrance Foyer, porch steps with marble cladding on it.
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room, temporary sheds, water tank
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good

A16	FAIR LAWN	
10.0		TRANSFORMATION
10.1	Form	Additional box grills and the balconies on the sides are enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A16 FAIR LAWN

(a)

(b)





(C)

(d)





A 1 7			
A17	COURT VIEW	Common Dof no. A17	
		Common Ref no: A17	
	Card No.:		the second se
		Ward: Ward A CS No. 1536	
	A CONTRACT OF A	Plot Area : 1077.76	2
		B U Area : 3330	
	2015 100	Date : January, 2013	An to An toA
		Record by : Aneri S, Ad	
		Review by : Shraddha E	
			As above
	Call	Photo Ref : A17 COUR	
1.0			DENOMINATION
1.1	Name of Premises		Court View
1.2	Earlier Name		Not applicable
1.3	Built In 1930's		Extension Date(if any): Not Applicable
2.0			ACCESS ROADS
2.1	Main		Maharshi Karve road
2.2	Subsidiary		Not applicable
3.0			OWNERSHIP PATTERN
3.1	Present		Court View Co-Operative Housing Society Limited
3.2	Past		The Governor of Bombay, Jivatram Kundanmal
3.3	Statuc		Ramchandani
3.3	Status		Co-operative Housing Society
4.0			USE
4.1	Present		Residential
4.2	Past		Residential
4.3	Usage		Regular in residential use
	l		
5.0			SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manma	de)	Part of Maharshi Karve road front, which is one of the major
			North-South arterial roads.
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with
			adequate light and ventilation.
			Stylistic Classification: Rectangular balconies and recessed
			windows on the front façade of the building, the building
			shows a beautiful Art Deco style carving on the front façade.
			Original grills and gates are maintained as they were. The
			building shows balconies also on the side and rear façade of
			the building. Rectangular chajjas also become a feature of the building.
5.3	Intrinsic		Art Deco building representing its era. The various Art Deco
0.5	Intrinsic		style buildings on the newly reclaimed lands created a
			cohesive image. Like the Gothic buildings in their time
			represented the new face of the city and an expression of
			power, so did the Art Deco buildings and precincts
I	4		perior, so and the fire bood walkings and provinces

A17	COURT VIEW	
		symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under
		Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well wooden staircase with a wooden railing having a
		glass motif
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and
		painted
		Flooring: Cement terrazzo in the lobby
7.9	Interiors(Movable & Immovable)	Staircases: Granite Cladding Entrance Foyer and Porch steps with marble cladding
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates
7.10	Compound/Fence/Gale	are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room,
7.11	Curringer Oribuin space/out buildings/landscape	temporary sheds, water tank
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the
		houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Average(needs cleaning)
9.10	Overall Condition	Good

A17	COURT VIEW	
10.0		TRANSFORMATION
10.1	Form	Balconies are enclosed on almost all facades.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps- Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	IMPLEMENTATION	

A17 COURT VIEW





(b)



(C)



(d)



A18 EROS CINEMA				
		Comm	non Ref no: A18 (reviewed in	
		2013)		
		Card	No.: A-70	
			(Part): A	
CS No		CS No	b.: Not available	
Plot A		Plot A	rea: Not available	
	STOREMENT IN IN INCOME	B U A	rea: Not available	
Date:			January, 2006	
			d by: Gauri J, Deepti S	
- Dia	Review		w by: Neera Adarkar	
			above Ext: As above	
		Photo	Ref: A18 EROS CINEMA a-g	
1.0			DENOMINATION	
1.1	Name of Premises		Eros Cinema	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1938		Extension Date(if any): Not applicable	
2.0			ACCESS ROADS	
2.0	Main		Jamshetji Tata Road	
2.2	Subsidiary		Maharshi Karve Marg (Queen's Road)	
2.2				
3.0			OWNERSHIP PATTERN	
3.1	Present		Not available	
3.2	Past		Not available	
3.3	Status		Under Governor of Bombay	
4.0			USE	
4.0	Present		Entertainment and commercial	
4.2	Past		Entertainment and commercial	
4.3	Usage		Regular public use	
1.0				
5.0			SIGNIFICANCE & VALUE CLASSIFICATION	
5.1	Townscape(Natural/Manmade)		A landmark theatre building situated on the commanding junction of	
			Maharshi Karve Marg, Jamshetji Tata Road and Veer Nariman	
			Road opposite Churchgate Railway Terminal . Forms a part of Fort	
			Precinct.	
5.2	Architectural Description		The V shaped Art Deco structure represents an excellent example	
			of urban response to a prominent public square surrounded by the	
			public amenities like the Oval ground, the Churchgate Railway	
			station and the back bay Art Deco precinct. It incorporates the two	
			wings which unite and round off at the main entrance to the theatre. The corner rising up in stepped circular profile gives the	
			commanding character to the theatre. It is partially faced with Red	
			Agra sandstone and the same shed of red colour is used for the	
			finish of the mouldings and ornamental details while the rest of the	
			structure was painted in light cream. The visual interlocking of these	
			colours creates an illusion of height making the building seem	
			larger.	

A18	EROS CINEMA		
5.3	Intrinsic	This building was designed by Sohrabji Bhedwar and its foundations	
		were laid in 1935. The Art Deco movement had reached its pinnacle	
		in February, 1938 with the opening of a grand luxury cinema, the	
		Eros is the only non-residential building to be constructed on the	
		new plots fronting the Oval in the Back Bay Reclamation scheme.	
5.4	Value Classification	Existing Grade: NA Recommended Grade: IIA	
		A(arc), B(des), I(sce), C(seh)	
		Under Oval Precinct, part of Fort Precinct and also under Marine	
		Drive Heritage Precinct	
6.0		ΤΟΡΟΟΡΑΡΙΙΥ	
6.0 6.1	Floors	TOPOGRAPHY	
6. I	Floors	G + 6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry walls	
7.2	Floor	R.C.C. floor slab	
7.4	Stairs	Three marble staircases with chromium handrails laid to the	
7.1		auditorium and balcony	
7.5	Openings	Rectangular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof terrace	
7.7	Articulation	The building is partially faced with Red Agra sandstone and the	
		same shed of red colour is used for the finish of the mouldings and	
		ornamental details while the rest of the structure was painted in light	
		cream. The visual interlocking of these colours creates an illusion of	
		height making the building seem larger.	
7.8	Finishes	Internally and externally cement plastered and painted except for	
		the few parts on the façade which partially faced Red Agra	
		sandstone.	
7.9	Interiors(Movable & Immovable)	The interiors are imposing with a magnificent foyer of gleaming	
		white and jet black marble, relieved with streak of gold. There are	
		murals on the walls painted in soft tones symbolizing India with its	
		tropical vegetation, the dim outline of Taj Mahal and temples of	
7.10		south.	
7.10	Compound/Fence/Gate	Not provided	
7.11	Curtilege/ Unbuilt space/out	None	
	buildings/landscape		
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural ventilation	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Fire fighting sprinkler system	
8.7	Other (HVAC/BMC/Security Systems)	Central air-conditioning unit	
9.0		CONDITION	
9.1	Plinth	Good (No settlement or cracks observed)	

A18	EROS CINEMA				
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good (No sagging observed)			
9.4	Stairs	Good			
9.5	Openings	Good			
9.6	Roofing	Good (No leakage observed)			
9.7	Articulation & Finishes	Good			
9.8	Services	Good (Drainage pipes need no replacement)			
9.9	Outbuildings	Good			
9.10	Overall Condition	Good Maintenance level Good			
10.0		TRANSFORMATION			
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
11.0	DP REMARKS/PERCEIVED	Plot demarcated for Social Amenities in (DP			
	THREATS				
12.0	ADDITIONAL	Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai,			
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995			
	AVAILABLE/RECOMMENDATIONS				
	& SUGGESTIONS FOR				
	IMPLEMENTATION				

A18 EROS CINEMA





(C)



(e)



(g)



(b)



(d)

(f)





A19	CHHEDA SADAN			
		Commo	on Ref no: A19	
		Card N		a hope and and a set of the set
		Ward:		
		CS No.		
			ea : 1231.89	10 HI H H H
			ea : 3895.43	Land Contraction
	The second second		January, 2013	Au-A Au-A
			by : Aneri S, Adele Z	PLC PLC
	·	Review	y by : Shraddha B.	the state of the s
			above Ext: As above	
	and the second s		Ref : A19 CHEDA SADAN a-	
		e		
1.0		Ũ	DENOMINATION	
1.1	Name of Premises		Cheda Sadan	
1.2	Earlier Name		Al-Abad	
1.3	Built In 1940's		Extension Date(if any): Not	Applicable
2.0			ACCESS ROADS	
2.0	Main		Kum. Jethi.T.Sipahimalani N	Aaro
2.2	Subsidiary		Not applicable	larg
2.2				
3.0			OWNERSHIP PATTERI	N
3.1	Present		Kalyanji Meghji Chheda	
3.2	Past		The Governor of Bombay, N	ajina Ebrahim, Kapurchand
			Nemchand Mehta, Zavercha	
			Kevalchand Nemchand Meh	
			Morarji Meghji Chheda, Lakl	hamsi Meghji Chheda
3.3	Status		Tenanted	
4.0			USE	
4.1	Present		Mixed use (Satyam collectio	
			general stores in one of the	garages)
4.2	Past		Residential	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VAL	
5.1	Townscape(Natural/Manmade)		Part of Kum. Jethi.T.Sipahin	
5.2	Architectural Description			ig in modest Art Deco style with
			adequate light and ventilatio	
				ional corner balconies projecting
				ajjas on the front façade. Original
				ned on the sides of the building.
			Rectangular balconies proje	
			building.	
				shows small windows with few
				Il staircase, gates, name plates,
			etc still retained.	
5.3	Intrinsic			ng its era. The various Art Deco

A19	CHHEDA SADAN	
		style buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
0.1	110013	
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with granite cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Marble flooring in the lobby Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	Entrance Canopy, porch steps to the building, steps to the shops on the ground floor.
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room, temporary sheds, water tank, and The Satyam collection shop extends in the compound.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)

A19	CHHEDA SADAN	
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good(few shallow exterior cracks)
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Average(Tree growing on the compound wall, needs
		cleaning)
9.10	Overall Condition	Good
10.0		TRANSFORMATION
10.1	Form	Additional box grills, few balconies enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-
	NOTES/REFERENCES/DOCUMENTS	Mumbai,
	AVAILABLE/RECOMMENDATIONS &	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	SUGGESTIONS FOR IMPLEMENTATION	

A19 CHHEDA SADAN


(a)



(b)



(d)



(C)



A 2 0	SNEH SADAN	
	2013 Card War CS I Plot B U Date Recu Int: A	mon Ref no: A20 (reviewed in 3) 1 No.: A-10 d (Part): A No.: 1559 Area: 1201.5 sq.m. Area: 4757.94 sq.m. e: April, 2005 ord by: Gauri J, Keshav S iew by: Arun Kale As above Ext: As above to Ref: SNEH SADAN a-f
1.0		DENOMINATION
1.1	Name of Premises	Sneha Sadan
1.2	Earlier Name	Not applicable
1.3	Built In: Late 1950-59	Extension Date (if any): Not applicable
2.0		ACCESS ROADS
2.1	Main	Kum. Jethi.T.Sipahimalani Marg
2.2	Subsidiary	Not applicable
3.0		OWNERSHIP PATTERN
3.1	Present	Sneha Sadan Churchgate Co-Op Housing Society
3.2	Past	Governor of Bombay (Lesser)
3.3	Status	Ownership
4.0		USE
4.1	Present	Residential
4.2	Past	Residential
4.3	Usage	Regular residential use
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape (Natural/Manmade)	Part of the road front of Kum. Jethi.T.Sipahimalani Marg in the Back Bay Reclamation area.
5.2	Architectural Description	A modest Art Deco building with no articulation but, except the balconies with a small band of intricate concrete railings. Represents the streetscape. The projecting balconies are curved at all the corners of the building. One of the few simple Art Deco buildings where only couple of balconies is enclosed with aluminium sliding windows that destroy the Art Deco character.
5.3	Intrinsic	The Back Bay Reclamation was complete in 1929, after which tenanted residential buildings mostly in Art Deco style with a large foot print and G + 5 height were constructed on the organized plots. The various Art Deco style buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of

A 2 0	SNEH SADAN			
		power, so too the Art Deco buildings and precincts symbolized the		
		shift in expression to represent contemporary aspirations.		
5.4	Value Classification	Existing Grade: NA Recommended Grade: III		
		A(arc), B(des), G(grp), E		
6.0		TOPOGRAPHY		
6.1	Floors	G + 5		
7.0		CONSTRUCTION		
7.1	Plinth	Plastered masonry plinth		
7.2	Walls	Brick masonry wall		
7.3	Floor	R.C.C. floor slab		
7.4	Stairs	R.C.C. dog legged staircase		
7.5	Openings	Rectangular openings with wooden frames and glazed shutters		
7.6	Roofing	Flat roof with terrace		
7.7	Articulation	No articulation except curved balconies		
7.8	Finishes	Internally and externally cement plastered and painted		
7.9	Interiors(Movable & Immovable)	Entrance foyer		
7.10	Compound/Fence/Gate	Plastered brick walls		
7.11	Curtilege/ Unbuilt space/out	Marginal side open space		
	buildings/landscape			
8.0		SERVICES & UTILITIES		
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and sanitation)	MCGM		
8.6	Fire Precaution	Not provided		
8.7	Other (HVAC/BMC/Security Systems)	Window air-conditioning units at some places		
9.0		CONDITION		
9.1	Plinth	Good (No settlement or cracks observed)		
9.2	Walls	Good (No dampness or cracks observed)		
9.3	Floor	Good		
9.4	Stairs	Good		
9.5	Openings	Good		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Good		
9.8	Services	Good (Drainage pipes need no replacement)		
9.9	Outbuildings	Good		
9.10	Overall Condition	Good Maintenance level Good		
10.0		TRANSFORMATION		
10.1	Form	Sliding windows added later.		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		


A 2 0	SNEH SADAN		
11.0	DP REMARKS/PERCEIVED THREATS	Plot falls under Residential Zone in DP	
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai, Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995	


A20 SNEH SADAN



(c)

(e)





A 2 1				
AZI		Comm	on Ref no: A21	
		Card N		مرجع مرجع المرجع الم
			Ward A	
	Stand 2 - The state	CS No.		4 43
			ea :1274.25	B.B.
			ea : 2988	
	and the second second			Culy 1
			January, 2013	
			by : Aneri S, Adele Z	
			y by : Shraddha B. above Ext: As above	Ret Co
				-
1.0		Photo i	Ref : A21 LILY COURTa-f	
1.0	Name of Dramicas			
-	Name of Premises		Lily Court	
1.2	Earlier Name		Not applicable	
1.3	Built In :1950's		Extension Date(if any): Not A	Applicable
2.0				
2.0	Na in		ACCESS ROADS	1
2.1	Main		Kum. Jethi.T.Sipahimalani M	larg
2.2	Subsidiary		Not applicable	
2.0				
3.0	Descent		OWNERSHIP PATTERN	N
3.1	Present		Skyline Estates Pvt.Ltd.	
3.2	Past		The Governor of Bombay, Va	arjiwandas Motilal Saraiya,
				lal, Vinod Varjiwandas Saraya,
			Mathurdas Narayandas Maji	
2.2	3 Status		[Fco.Operative Housing Soc	
3.3			Co-operative Housing Societ	ty
1.0				
4.0	Durand		USE	
4.1	Present		Mixed use	
4.2	Past		Mixed use	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VAL	
5.1	Townscape(Natural/Manmade)		Part of Kum. Jethi.T.Sipahim	
5.2	Architectural Description			g in modest Art Deco style with
			adequate light and ventilation	
			interior windows of the buildi	
				uilding shows no balconies but
				tinuous chajja on them on the
			front façade. Balconies on th	
			Deco style carvings over the	entrance gate. Uld wooden
			chajjas retained.	
5.3	Intrinsic			ng its era. The various Art Deco
			style buildings on the newly	
			cohesive image. Like the Go	
				the city and an expression of
			power, so did the Art Deco b	ulidings and precincts

A 2 1	LILY COURT	
		symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Dog legged wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Cement terrazzo in the lobby. Staircases: Wooden polished
7.9	Interiors(Movable & Immovable)	·
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room, temporary sheds, and water tank.
0.0		
8.0	Lighting	SERVICES & UTILITIES
8.1	Lighting Ventilation	Natural and artificial, good natural lighting
8.2 8.3	Electricity	Natural and artificial, good natural lighting BEST
<u> </u>	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
		Cood
9.9 9.10	Outbuildings Overall Condition	Good Good

A 2 1	LILY COURT	
10.0		TRANSFORMATION
10.1	Form	Additional box grills, few balconies enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-
	NOTES/REFERENCES/DOCUMENTS	Mumbai,
	AVAILABLE/RECOMMENDATIONS &	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	SUGGESTIONS FOR IMPLEMENTATION	

A21 LILY COURT













(e)



A 2 2	FAIRFIELD			
		Common	Ref no: A22	
		Card No.:		and the second second
	and the second sec	Ward : W		
	The state of the second se	CS No. 1		
		Plot Area		žo z o k
		B U Area		
			. 3240 nuary, 2013	All Real
			y : Aneri S, Adele Z	La Pro
	The second s		y : Shraddha B.	1 5 5
2	ATTACK OF THE REAL PROPERTY OF	Int : As at		ALEL NO.13
	State Barrier Carlos E. C. and M.		f : A22 FAIRFIELD a-d	Provide and the
1.0			DENOMINATION	
1.1	Name of Premises		Fairfield	
1.2	Earlier Name		Not applicable	
1.3	Built In 1950's		Extension Date(if any): No	t Applicable
2.0			ACCESS ROADS	
2.1	Main		Kum. Jethi.T.Sipahimalani	Marg
2.2	Subsidiary]	Not applicable	
2.0				
3.0 3.1	Dracant		OWNERSHIP PATTER	
3.1	Present		Fair Field Co.Operative Ho	
3.Z	`Past			Bhanji Devji Khimji, Bai Ratanbai Govindram, Daulatram Chatrumal,
3.3	Status		Partly Private Partly Tenan	
5.5		I	Failiy Flivale Failiy Teliali	
4.0		1	USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0				LUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Kum. Jethi.T.Sipahi	
5.2	Architectural Description			ing in modest Art Deco style with
				on. It has a void where the
			interior windows of the buil	
			Stylistic Classification: The	
				on the corners on the front
				Deco style articulation at the
				g continuous chajja over the s which are round around the
5.3	Intrinsic			e side façade of the building. ting its era. The various Art Deco
0.0				y reclaimed lands created a
				Sothic buildings in their time
				of the city and an expression of
			power, so did the Art Deco	
			symbolized the shift in exp	
L	<u> </u>		Symbolized the Shirt in CAPI	

A 2 2	FAIRFIELD	
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with marble cladding with wooden
		railing
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and
		painted
		Flooring: Marble flooring in the lobby
		Staircases: Marble Cladding
7.9	Interiors(Movable & Immovable)	Entrance Canopy, Porch steps.
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates
		are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room,
/		temporary sheds, water tank, security office(additional),
		society office
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the
		houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good

A 2 2	FAIRFIELD	
10.0		TRANSFORMATION
10.1	Form	Additional box grills, few balconies enclosed, Additional security office.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps- Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A22 FAIRFIELD



(b)





(C)



A 2 3	PANKAJ MAHAL			
		Comm	non Ref no: A23	
-	and the second	Card N		
and the			Ward A	
Contraction of the	CS No			
. 20			rea : 1175.59	P P P
			rea : 3115	
120000			January, 2013	
	All and a second second second		d by : Aneri S, Adele Z	112 Lord
manual			w by : Shraddha B.	1 3 Long in I
10. 8			s above Ext: As above	1 °
1	Marit 1 1 1 1 400 de la contra de la		Ref : A23 PANKAJ MAHAL a-e	
1.0			DENOMINATION	
1.1	Name of Premises		Pankaj Mahal	
1.2	Earlier Name		Gupta Mahal	
1.3	Built In:1940's		Extension Date(if any): Not Appli	icable
2.0			ACCESS ROADS	
2.1	Main		Kum. Jethi.T.Sipahimalani Marg	
2.2	Subsidiary		Not applicable	
	1			
3.0			OWNERSHIP PATTERN	
3.1	Present		Anish Pankaj Gupta & Tarush Pankaj Gupta	
3.2	Past			gopal Kashiram Gupta, Smt.Swaran
				ta, Rajan Kamalgupta, Shatulgupta
3.3	Status		Co-operative Housing Society	
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Residential	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)		Part of Kum. Jethi.T.Sipahimalar	
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with	
			adequate light and ventilation. It	
			windows of the buildings open in	
			Stylistic Classification: The front	
			rectangular projecting balconies that curve around the edges. The	
			side façade shows balconies and small windows next to them. The	
			windows show few original chajja. The rear side of the building	
5.6	<u> </u>		shows an M.S. spiral staircase which is used for services.	
5.3	Intrinsic			s era. The various Art Deco style
				lands created a cohesive image.
				time represented the new face of
				wer, so did the Art Deco buildings
			and precincts symbolized the shi	itt in expression to represent
			contemporary aspirations.	


A 2 3	PANKAJ MAHAL		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well R.C.C. staircase with marble cladding	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
74	Deefing	Flat roof and terrace	
7.6 7.7	Roofing Articulation		
1.1	Articulation		
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Marble tiles in the lobby Staircases: Marble cladding	
7.9	Interiors(Movable & Immovable)	Entrance canopy	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M. gates painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.0 9.1	Plinth	Good	
9.1 9.2	Walls	Good	
9.2 9.3	Floor	Good	
9.3 9.4	Stairs	Good	
9.4 9.5	Openings	Good	
<u> </u>			
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	

A 2 3	PANKAJ MAHAL	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. chajjas , antennas, garage converted to
		shops
10.2	Structure	No transformation
10.3	Articulation & Finishes	Recently painted
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai,
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	AVAILABLE/RECOMMENDATIONS	
	& SUGGESTIONS FOR	
	IMPLEMENTATION	

A23 PANKAJ MAHAL



(b)



(C)







A 2 4	ROSHERA			
- AZ4	KO SIIL KA	Comm	non Ref no: A24	
		Conin Card I		L.D.s.
	an activ		Ward A	- F- 0
	and the second sec		. 1555	
	La Later		rea : 976.59	
		B U A		110 0 110 0 1100 0 0 100 0 0 0 100 0 0 0 100 0 0 0 100 0 0 0 100 0 0 0 100 0 0 0 100 0 0 0 100 0 0 0 100 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	The second second			No. Vest
	and the second support		January, 2013	Dil Front
	San a second second	Recor	d by : Aneri S, Adele Z	
			w by : Shraddha B. s above Ext: As above	1 11 1 1
		-		
	A STATE AND A		Ref : A24 ROSHERA SION a-f	
1.0		IVIAINS		
1.0 1.1	Name of Premises		Roshera	
1.1	Earlier Name			
1.2			Not applicable Extension Date(if any): Not App	liaabla
1.3	Built In 1930's		Extension Date(ii any): Not App	
2.0			ACCESS ROADS	
2.1	Main		Dinshaw Vatcha Road	
2.2	Subsidiary		Kum. Jethi.T.Sipahimalani Marc	ר – ר <u>ו</u>
2.2				
3.0			OWNERSHIP PATTERN	
3.1	Present		The Governor General Of India	
3.2	Past			kla Kumari D/O Ranzorsinghji & W/O
			Narpatsinghji	
3.3	Status		Central Government	
4.0				
4.0	Drecont		USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)		Part of Dinshaw Wachha road f	
5.2	Architectural Description		Planning: It is a large building in	
5.2	Architectural Description		adequate light and ventilation.	Thought Art Deed style with
				ding shows a curved corner along the
				iary road. The façade facing the main
				ngular chajja. The windows along the
			curved corner are small and sho	
				ad shows long rectangular balconies
				e of the building show small windows
				ilding shows a M.S. spiral staircase
			on the façade facing the subsid	
5.3	Intrinsic			its era. The various Art Deco style
				d lands created a cohesive image.
				r time represented the new face of
				ower, so did the Art Deco buildings

A 2 4	ROSHERA	
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Dog legged wooden staircase with a wooden railing
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Curved corner
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Cement terrazzo Staircases: Wooden polished
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S. gates painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, water tank, pump
	buildings/landscape	room
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Average (exterior walls need repairs and painting, show vegetation growth)
9.3	Floor	Average
9.4	Stairs	Average
9.5	Openings	Average
9.6	Roofing	Good
9.7	Articulation & Finishes	Average
9.8	Services	Average (Needs cleaning and repairs, compound wall tilted)
9.9	Outbuildings	Average(Shows cracks needs repairs)
9.9	Overall Condition	

A 2 4	ROSHERA	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. canopies and chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A24 ROSHERA







(e)







(d)



A 2 5	VASWANI MANSIONS			
NIC AKO	TASWANT WANSTONS	Comm	non Ref no: A25	
Contraction of the		Card N		0.00
			Ward A	CAND
). 1565	
			rea : 1903.86	Mun of N Ouro
			rea : 6363	
Strand.			January, 2013	PLOT No. 120 B.B.R
heer the				MH O O HIT
A ALL	Contract on Est		d by : Aneri S, Adele Z w by : Shraddha B.	and the second second
			s above Ext: As above	WACHA A A ON ON LAND
Lal	States of the states of the states of the		Ref : A25 VASWANI	uno ROAD
			SIONS a-e	
1.0		IVIAINS		
1.0 1.1	Name of Premises		Vaswani Mansions	
1.2 1.3	Earlier Name		Not applicable	nliachla
1.3	Built In:1940's		Extension Date(if any): Not App	
2.0			ACCESS ROADS	
2.1	Main		Dinshaw Wachha Road	
2.2	Subsidiary		Kum. Jethi.T.Sipahimalani Mar	g
0.0				
3.0			OWNERSHIP PATTERN	
3.1	Present		Sunita Roopchand Vaswani, Sheela Ramchand Vaswani, Mukesh Ramchand Vaswani, Vijaya Ramchand Vaswani	
2.2				
3.2	Past			abirprasad Hazarimal, Ramchand
			K.Vaswani, Rupchand K.Vaswa K.W.Waswani,	ani, Paravalidevi wd/O
2.2	Status		Tenanted	
3.3	Status		Tenanieu	
4.0			USE	
4.1	Present		Mixed use	
4.2	Past		Residential	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			road front, at the junction of Dinshaw
			Wachha and Kum. Jethi.T.Sipa	
5.2	Architectural Description		Planning: It is a large building in	n modest Art Deco style with
			adequate light and ventilation.	
				ding shows a rounded corner at the
			junction of the main and subsid	
				alconies. Rectangular projecting
				f the building. Long continuous
			chajjas over the balconies and	WILLOWS.
5.3	Intrinsic			its era. The various Art Deco style
				ed lands created a cohesive image.
			Like the Gothic buildings in the	ir time represented the new face of

A 2 5	VASWANI MANSIONS	
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with cement terrazzo cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded corner at the junction of the main and subsidiary road.
7.8	Finishes	Walls: Externally and internally cement plastered, painted
		Flooring: Marble flooring in the lobby
		Staircases: Cement terrazzo cladding.
7.9	Interiors(Movable & Immovable)	Entrance Canopy, porch steps to the building. Shop in the garage.
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S.
		gates (original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,
	buildings/landscape	temporary sheds, water tank.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good

A 2 5	VASWANI MANSIONS	
10.0		TRANSFORMATION
10.1	Form	Additional box grills, most of the balconies enclosed, additional gate dividing the compound of the building.
10.2	Structure	Few buildings completely enclosed.
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	& SUGGESTIONS FOR	

A25 VASWANI MANSIONS







(d)







A 2 6	PREM COURT			
A20		Commo	on Ref no: A26	
		Commo Card N		ANT A
			Ward A	an for the second
		CS No.		
			1304 ea 1832.78	" I many I
			ea: 5152	1 m the to the
				the section of the
			lanuary, 2013 by : Aneri S, Adele Z	in the second of
	BU DEST		by : Shraddha B.	1-7
		Int : As		
			Ref : A26 PREM COURT a-f	the states
1.0		1 11010 1	DENOMINATION	1
1.1	Name of Premises		Prem Court	
1.2	Earlier Name		Not applicable	
1.3	Built In 1940's		Extension Date(if any): Not A	oplicable
2.0			ACCESS ROADS	
2.1	Main		Jamshedji Tata road	
2.2	Subsidiary		Dinshaw Watcha Marg	
3.0			OWNERSHIP PATTERN	
3.1	Present		Her Highness Ram Saheba S	
			Wadhwan	
3.2	Past		The Governor of Bombay	
3.3	Status		Tenanted	
4.0			USE	
4.1	Present			e Samrat group on the ground
			floor of the building)	
4.2	Past		Residential	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALU	
5.1	Townscape(Natural/Manmade)			oad front, at the junction of
			Dinshaw Wachha and Jamsh	
5.2	Architectural Description			g in modest Art Deco style with
			adequate light and ventilation	
			Stylistic Classification: The b	
			along the junction of the mair	
			building shows bay windows	
			the chajjas continue in curved	
				wo spiral staircases made up of
			M.S.	
Г 2	Intrincia		Art Dooo hullalian assault	wite and The vertex Art Due
5.3	Intrinsic			g its era. The various Art Deco
			style buildings on the newly r	
			cohesive image. Like the Got	
L			represented the new face of	ine city and an expression of

A 2 6	PREM COURT	
- 112 0		power, so did the Art Deco buildings and precincts
		symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.1	Walls	
7.3	Floor	Brick masonry wall R.C.C. floor slab
7.3	Stairs	
7.4		Dog legged wooden staircase with a M.S. railing.
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded corner at the junction of the main and subsidiary
1.1	A dediction	road.
		1044.
7.8	Finishes	Walls: Externally and internally cement plastered and
		painted
		Flooring: Marble flooring in the lobby
		Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	Entrance Canopy, porch steps to the building, steps to the
1.7		shops on the ground floor. The outdoor seating and waiting
		area for Samrat restaurant. HVAC connections in the
		compound
		compound
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates
		are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room,
		temporary sheds, water tank, outdoor seating of samrat
		restaurant.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the
		houses)

A 2 6	PREM COURT	
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Very Good
10.0		TRANSFORMATION
10.1	Form	Additional box grills, Added canopy for the seating of samrat
		restaurant. External staircase for samrat restaurant.
10.2	Structure	No transformation
10.3	Articulation & Finishes	HVAC connections in the compound and additional wires on
		the wall
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-
	NOTES/REFERENCES/DOCUMENTS	Mumbai,
	AVAILABLE/RECOMMENDATIONS	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	& SUGGESTIONS FOR	
	IMPLEMENTATION	





(b)



(d)



(C)



(e)



A27 ORIENTAL HOUSE				
		ommon Ref no: A27		
NAME AND ADDRESS OF TAXABLE PARTY OF TAXABLE PARTY.		ard No.:		
Contraction of the second s		/ard : Ward A		
CS No		S No. 1562 & 1563		
		lot Area : 3614.58		
12222		U Area : 7652		
I I I I I		ate : January, 2013		
Canada and a second sec		ecord by : Aneri S, Adele Z		
		eview by : Shraddha B.		
		t: As above Ext: As above		
1200	the second se	hoto Ref : A27 ORIENTAL HOUSE		
	a			
1.0		DENOMINATION		
1.1	Name of Premises	Oriental House		
1.2	Earlier Name	Not applicable		
1.3	Built In : 1970's	Extension Date(if any): Not Applicable		
2.0		ACCESS ROADS		
2.1	Main	Dinshaw Wachha Road		
2.2	Subsidiary	Kum. Jethi.T.Sipahimalani Marg		
0.0				
3.0 3.1	Present	OWNERSHIP PATTERN		
3.1 3.2``	Present Past			
3.3	Status	Semi Government		
5.5				
4.0		USE		
4.1	Present	Commercial		
4.2	Past	Commercial		
4.3	Usage	Regular in commercial use		
5.0		SIGNIFICANCE & VALUE CLASSIFICATION		
5.1	Townscape(Natural/Manmade)	Part of Dinshaw Wachha road front		
5.2	Architectural Description	Planning: It is a large building in modest Art Deco style with		
		adequate light and ventilation.		
		Stylistic Classification: The building shows vertical fins on the front		
		façade, these fins enclose windows in them. The building shows a		
		ramp going to the parking on the second floor. The corner windows		
		outside the fins show small chajja over it. The interior lobby has an old ceiling pattern which is still maintained		
		on centry partern which is summaritanted		
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style		
		buildings on the newly reclaimed lands created a cohesive image.		
		Like the Gothic buildings in their time represented the new face of		
		the city and an expression of power, so did the Art Deco buildings		
		and precincts symbolized the shift in expression to represent		
		contemporary aspirations.		

A 2 7	ORIENTAL HOUSE		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
0.1			
6.0		TOPOGRAPHY	
6.1	Floors	G+7 (varied topography, is G and G+1 structure in a few places)	
0.1			
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well stone staircase with marble cladding and aluminium	
		railing	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
		5 1 5 5	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Marble flooring	
		Staircases: Marble flooring	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S.	
		gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out	Petrol pump, ramp to the parking	
	buildings/landscape		
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Average (Needs cleaning and repairs)	
9.9	Outbuildings	Average(Needs cleaning)	
9.10	Overall Condition	Good	

A 2 7	ORIENTAL HOUSE	
10.0		TRANSFORMATION
10.1	Form	Additional canopies in the compound. Glazed shutters on the ground
		floor
10.2	Structure	No transformation
10.3	Articulation & Finishes	No transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls partly under Residential and partly Commercial Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai,
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	AVAILABLE/RECOMMENDATIONS	
	& SUGGESTIONS FOR	
	IMPLEMENTATION	

A27 ORIENTAL HOUSE



(C)



(e)



(b)



(d)



A 2 8	RITZ HOTEL			
AZ0	-	Common Ref no: A28 (Reviewed in		
		2013)		
		Card No.: A-7e		
100-		Ward (Part): A-II		
1.1	CONTRACTOR OF THE OWNER OWNER OF THE OWNER	CS No.: 1 / 1561		
		Plot Area: 500 sg.m.		
		3 U Area: 1980 sq.m.		
1.2		Date: April, 2005		
		Record by: Gauri J, Anup S		
-		Review by: Arun Kale		
1 / I		nt: As above Ext: As above		
		Photo Ref: A28 RITZ HOTEL a-e		
1.0		DENOMINATION		
1.1	Name of Premises	Ritz Hotel		
1.2	Earlier Name	Not applicable		
1.3	Built In: 1930s	Extension Date(if any): Not applicable		
2.0		ACCESS ROADS		
2.1	Main	Jamshediji Tata Road		
2.2	Subsidiary	Kum. Jethi.T.Sipahimalani Marg		
3.0		OWNERSHIP PATTERN		
3.1	Present	Governor of Maharashtra (Lessor), Lessee – Esso Standard		
		Eastern Inc.		
3.2	Past	Governor of Maharashtra (Lessor), Lessee – Esso Standard		
		Eastern Inc.		
3.3	Status	Private (Ownership)		
4.0		USE		
4.1	Present	Commercial		
4.2	Past	Commercial		
4.3	Usage	Regular commercial use		
5.0		SIGNIFICANCE & VALUE CLASSIFICATION		
5.1	Townscape(Natural/Manmade)	Part of Jamshedji Tata Road front at the sharp corner of		
		Road No. 4 with a Petrol station, in Back Bay area.		
5.2	Architectural Description	The buildings on the Jamshedji Tata Road fall in the Back Bay		
		Reclamation area. Earlier strict guidelines were laid down		
		regarding the construction. A clear space of twenty feet all around		
		the building and a space of forty feet between any two buildings		
		was mandatory. This has often resulted in some monotony. This		
		Art deco building has prominent chajjas projecting on each floor on		
		the entire length of the facade highlighted in dark green.		
5.3	Intrinsic	The various Art Deco style buildings on the newly reclaimed lands		
		created a cohesive image. Like the Gothic buildings in their time		
		represented the new face of the city and an expression of power,		
		so too the Art Deco buildings and precincts symbolized the shift in		

A 2 8	RITZ HOTEL				
		expression to represent contemporary aspirations.			
5.4	Value Classification	Existing Grade: NA Recommended Grade: II A			
		A(arc), B(des), G(grp), E			
6.0		TOPOGRAPHY			
6.1	Floors	G + 6			
7.0		CONSTRUCTION			
7.1	Plinth	0.6 meter high plastered masonry plinth			
7.2	Walls	0.15 meter thick brick masonry wall			
7.3	Floor	R.C.C. floor slab			
7.4	Stairs	R.C.C. marble cladded staircase			
7.5	Openings	Rectangular openings with wooden frames and glazed shutters			
7.6	Roofing	Asbestos sheet roofing			
7.7	Articulation	Horizontal band at every floor and sill level			
7.8	Finishes	Internally and externally cement plastered and painted			
7.9	Interiors(Movable & Immovable)	Access denied			
7.10	Compound/Fence/Gate	Plastered Brick 1.5 meter high compound wall			
7.11	Curtilege/ Unbuilt space/out	Front open space moderately landscaped corner of the plot			
	buildings/landscape	occupied by a Petrol station.			
8.0		SERVICES & UTILITIES			
8.1	Lighting	Natural and artificial, fair natural lighting			
8.2	Ventilation	Natural and artificial, fair natural ventilation			
8.3	Electricity	BEST			
8.4	Water Supply	MCGM			
8.5	Drainage (Plumbing and sanitation)	MCGM			
8.6	Fire Precaution	Fire fighting system includes Hydrates, Sprinklers			
8.7	Other (HVAC/BMC/Security Systems)	Not provided			
9.0		CONDITION			
9.1	Plinth	Good (No settlement or cracks observed)			
9.2	Walls	Good (No dampness or cracks observed)			
9.3	Floor	Good			
9.4	Stairs	Good			
9.5	Openings	Good			
9.6	Roofing	Good (No leakage observed)			
9.7	Articulation & Finishes	Fair			
9.8	Services	Good (Drainage pipes need no replacement)			
9.9	Outbuildings	Good			
9.10	Overall Condition	Good Maintenance level Good			
10.0		TRANSFORMATION			
10.1	Form	No transformation			
10.2	Structure	No transformation			
10.3	Articulation & Finishes	No transformation			
10.0					

A 2 8	RITZ HOTEL
11.0	DP REMARKS/PERCEIVED THREATS
	Plot falls under Commercial Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS
	AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR
	IMPLEMENTATION
	History: Ritz Hotel and was designed by Gregson, Batley and King.
	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai,
	Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995







(b)







A 2 9	APEEJAY HOUSE			
		Comm	non Ref no: A29	Not Available
		Card N	No.:	1
		Ward	: Ward A	1
		CS No	o. 1570	7
		Plot A	rea : 2225.76	
		B U Ai	rea : 8440	1
	A REAL PROPERTY AND A REAL	Date :	January, 2013	7
	a st sit sit sit of a m	Recor	d by : Aneri S, Adele Z	
			w by : Shraddha B.	7
		Int : As	s above Ext: As above	7
		Photo e	Ref A29 APEEJAY HOUSE a-	
1.0		C	DENOMINATION	
1.1	Name of Premises		Apeejay House	
1.2	Earlier Name		Not applicable	
1.3	Built In 1970's		Extension Date(if any): Not Ap	plicable
2.0			ACCESS ROADS	
2.0	Main		Dinshaw Wachha road	
2.2	Subsidiary		Road no. 3	
2.2				
3.0			OWNERSHIP PATTERN	
3.1	Present		M/S.Steelcrete Private Ltd.	
3.2	Past		The Governor Of Bombay, Bai	Safiabai Mulla Adamji
3.3	Status		Tenanted	
4.0			USE	
4.1	Present		Commercial	
4.2	Past		Commercial	
4.3	Usage		Regular in commercial use	
5.0			SIGNIFICANCE & VALUI	E CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Dinshaw Wachha road	front
5.2	Architectural Description		Planning: It is a large building i	n modest Art Deco style with
			adequate light and ventilation.	
			5	lding shows no balconies. The front
			facade is flat with recessed wir	
				are set in those fins. The ground floor
F 0	Later de		shows marble cladding on the	
5.3	3 Intrinsic			its era. The various Art Deco style
				ed lands created a cohesive image.
				ir time represented the new face of ower, so did the Art Deco buildings
			and precincts symbolized the s	
			contemporary aspirations.	
5.4	Value Classification		Under Marine Drive Heritage P	Precinct

A 2 9	APEEJAY HOUSE		
6.0		TOPOGRAPHY	
6.1	Floors	G+7	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Access Denied	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
-	- T		
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Diagonal fins	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Access Denied	
		Staircases: Access Denied	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall and M.S. grill along the side	
	· ·	facing the main road.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,	
	buildings/landscape	temporary sheds, water tank, toilets, planters	
	Narran genarrae cap c		
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided	
-			
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	
10.0		TRANSFORMATION	
10.1	Form	No transformation	
10.2	Structure	No transformation	
10.3	Articulation & Finishes	No major transformation	
	i		

A 2 9	APEEJAY HOUSE	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP
10.0		
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A29 APEEJAY HOUSE

(a)



(b)



(d)





A 3 0	K.C. COLLEGE			
		Comm	non Ref no: A30	Not Available
		Card I		
			: Ward A	
			D. 1569	
		-	rea : 1958.21	
			rea : 6209	
			January, 2013	-
			d by : Aneri S, Adele Z	-
			w by : Shraddha B.	-
	West of the second second		s above Ext: As above	1
			Ref : A30 KC COLLEGE a-d	1
1.0		1	DENOMINATION	
1.1	Name of Premises		K.C.College	
1.2	Earlier Name		Not applicable	
1.3	Built In 1960's		Extension Date(if any): Not App	licable
				-
2.0			ACCESS ROADS	
2.1	Main		Dinshaw Wachha road	
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Hotchand Gopaldas Adwani, Lokumal Kishinchand, Kundandas	
			Rewachand, Khushiram Motirar	
3.2	Past		The Governor of Bombay, Mrs.	Ratan Hasmuklal Fozdar
3.3	Status		Under state government	
			<u> </u>	
4.0			USE	
4.1	Present		College	
4.2	Past		College	
4.3	Usage		Under a trust	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Dinshaw Wachha road fi	ront
5.2	Architectural Description		Planning: It is a large building in	modest Art Deco style with
			adequate light and ventilation.	-
			Stylistic Classification: Front façade shows recessed windows and	
			curved column like structures. T	
			show no chajjas. The side facad	des have long continuous chajjas.
L				
5.3	Intrinsic			ts era. The various Art Deco style
				d lands created a cohesive image.
				r time represented the new face of
				ower, so did the Art Deco buildings
			and precincts symbolized the sh	nitt in expression to represent
			contemporary aspirations.	
E 4	Value Classification		Lindor Morino Drive Listiano D	cocinct
5.4	Value Classification		Under Marine Drive Heritage Pr	ecincl

A 3 0	K.C. COLLEGE		
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
-			
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	L shaped stone staircase with granite cladding	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Ceramic tiles in the lobby	
		Staircases: Granite Cladding	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.	
		gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds, water fountain, open air canteen, Canopies, planters,	
	buildings/landscape	pots, steps on front and sides.	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	
10.0		TRANSFORMATION	
10.1	Form	Additional canopies on both sides of the building, open air canteen	
		in the compound at a higher level, water fountain, canteen on the left	
		side of the building, stone steps on the left side of the building.	
10.2	Structure	Open air canteen.	
10.3	Articulation & Finishes	No major transformation	

A 3 0	K.C. COLLEGE		
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot demarcated for Educational Amenities in DP	
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995	

A30 K.C. COLLEGE









(C)



A 3 1	H.R. COLLEGE			
11 30		Comm	non Ref no: A31	Not Available
33		Card N	No.:	
1.10		Ward	(Part) Ward (Part II): A II	-
1. A. S.		CS No	o. 1568	
18. °	at a		rea : 1800.18	
-			rea : 6057	
and the second			January, 2013	
			d by : Aneri S, Adele Z	_
- Contra Lan			w by : Shraddha B.	
			s above Ext: As above	-
1.0		Photo	Ref : A31 HR COLLEGE a-e	
1.0	Newson (December)		DENOMINATION	
1.1	Name of Premises		H.R. College of Commerce	
1.2	Earlier Name		Not applicable	nliachla
1.3	Built In: 1960's		Extension Date(if any): Not Ap	phicaple
2.0			ACCESS ROADS	
2.0	Main		Dinshaw Wachha road	
2.1	Subsidiary		Not applicable	
2.2				
3.0			OWNERSHIP PATTERN	
3.1	Present		Lakumal Kishinchand, Kundendas Rewachand, Khushiram	
			Motichand Kundani	
3.2	Past			tram Murlimal, Hotchad Gopaldas
			Advani	•
3.3	Status		Under a trust	
4.0			USE	
4.1	Present		College	
4.2	Past		College	
4.3	Usage		Regular in use as a college	
5.0			SIGNIFICANCE & VALU	
5.1 5.2	Townscape(Natural/Manmade)		Part of Dinshaw Wachha road	
5.Z	Architectural Description		Planning: It is a large building i	n modest Art Deco style with
			adequate light and ventilation.	cade shows recessed windows and
			Stylistic Classification: Front façade shows recessed windows and rectangular column like structures. The windows on the front façade	
			show no chajjas. The side facades have long continuous chajjas.	
				Original grills and gates maintained
			(painted).	5 5 5 5 <u>5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 </u>
5.3	Intrinsic			its era. The various Art Deco style
			buildings on the newly reclaim	ed lands created a cohesive image.
			Like the Gothic buildings in the	ir time represented the new face of
				ower, so did the Art Deco buildings
			and precincts symbolized the s	shift in expression to represent
			contemporary aspirations.	
5.4	Value Classification		Under Marine Drive Heritage P	recinct

A 3 1	H.R. COLLEGE	
AJI		
6.0		TOPOGRAPHY
6.1	Floors	G+5
0.1		
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	L shaped stone staircase with cement tarazzo on it
7.5	Openings	Regular openings with wooden frames and glazed shutters
1.5	openings	
7.6	Roofing	Flat roof and terrace
7.7	Articulation	
1.1		
7.8	Finishes	Walls: Externally and internally cement plastered and painted
7.0		Flooring: Ceramic tiles in the lobby
		Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.
		gates (original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, college canteen,
7.11	buildings/landscape	staircase to the open air canteen, open air canteen, Canopies.
	bullungshanascape	
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units)
-		· · · · · · · · · · · · · · · · · · ·
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good

A 3 1	H.R. COLLEGE	
10.0		TRANSFORMATION
10.1	Form	Additional A.C.P. chajjas and canopies, open air canteen, staircase
		to the canteen, canteen sheds at the back of the structure.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot demarcated for Educational Amenities in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A31 H.R. COLLEGE





(b)



(C)



(d)



A 3 2	MISTRY BHAWAN		
(e)		Common Ref no: A32	Not Available
(-)		Card No.:	
		Ward : Ward A	
		CS No. 1567	
		Plot Area :1645.49	
		B U Area : 5433.3146	
	· · · · ·	Date : January, 2013	
		Record by : Raveena Garg	
	and Artification and and and	Review by : Shraddha B.	
		Int : As above Ext: As above	
		Photo Ref : A32 MISTRY BHAWAN a-e	
1.0		DENOMINATION	
1.1	Name of Premises	Mistry Bhawan	
1.2	Earlier Name	Not applicable	
1.3	Built In 1960's	Extension Date(if any): Not Applicable	
2.0		ACCESS ROADS	
2.1	Main	Dinshaw Wachha road	
2.2	Subsidiary	Not applicable	
2.2			
3.0		OWNERSHIP PATTERN	
3.1	Present	M/S Gajria Electric Industrial Company Privat	a Limitod Dahim Karim
J. I	Tresent	Mistry, Fakirmahomed Karim Mistry , The Go	
		Grantor	vernor or bornbay -
3.2	Past	The Governor Of Bombay - Grantor	
3.3	Status	M/S Gajria Electric Industrial Company Privat	e l imited
0.0			
4.0		USE	
4.1	Present	Private Offices	
4.2	Past	Private Offices	
4.3	Usage	Private Offices	
5.0		SIGNIFICANCE & VALUE CLASSIFI	CATION
5.1	Townscape(Natural/Manmade)	Part of Dinshaw Wachha road front	
5.2	Architectural Description	Planning: It is a large building in modest Art D	Deco style with adequate
		light and ventilation.	
		Stylistic Classification: Front façade shows re	
		windows on the front façade and side facade	show no chajjas.
5.3	Intrinsic	Art Deco building representing its era. The va	rious Art Deco style
_		buildings on the newly reclaimed lands create	
		the Gothic buildings in their time represented	
		and an expression of power, so did the Art De	
		symbolized the shift in expression to represer	
		aspirations.	. ,
5.4	Value Classification	Under Marine Drive Heritage Precinct	

A 3 2	MISTRY BHAWAN		
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
0.1			
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Half landing staircase with marble cladding	
7.5	Openings	Regular openings with aluminium frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Recessed windows with projecting columns.	
1.1			
7.8	Finishes	Walls: Internally cement plastered and painted .External Walls (G+2) with Plywood cladding and rest cement plastered and painted. Flooring: Marble flooring in the lobby.	
		Staircases: Marble Cladding	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.	
7.10	Compound incerdate	gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds, water fountain, canopies, planters, pots, steps on front	
		and sides.	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units)	
017			
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	
,			
10.0		TRANSFORMATION	
10.1	Form	No transformation	
10.2	Structure	No transformation	
10.3	Articulation & Finishes	No major transformation	
-		· · · · · · · · · · · · · · · · · · ·	

A 3 2	MISTRY BHAWAN	
11.0	DPREMARKS/PERCEIVEDTHREATS	
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

(b)

A32 MISTRY BHAWAN







A 3 3	RAM MAHAL		
		Review by: A Int: As above above	2013) 7a A-II 5 03.86 sqm. 95.26 sqm. 005 5 auri J, Anup S run Kale
1.0		[DENOMINATION
1.1	Name of Premises		Ram Mahal
1.2	Earlier Name	1	Not applicable
1.3	Built In: 1946		Extension Date(if any): Not applicable
2.0			ACCESS ROADS
2.1	Main		Jamshediji Tata Road
2.2	Subsidiary		Dinshaw Wachha Road
3.0		(OWNERSHIP PATTERN
3.1	Present		Kotecha Investment Corp pvt. Ltd
3.2	Past	(\ 	Governor of Bombay (Lessor), Lessee – Ramchand K. Vaswani, Rupchand K. Vaswani, Sunita Rupchand Vaswani, Sheela Ramchand Vasvani, Mukesh Ramcahand Vaswani, Vijaya Ramchand Vaswani
3.3	Status		Tenanted
4.0			JSE
4.1	Present		Mixed Use
4.2	Past		Residential
4.3	Usage		Regular residential and commercial use
5.0			SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	1	Located on a rectangular corner plot at junction of Jamshedji Tata Road, which is one of the major North-South arterial roads and Dinshaw Wachha Road.
5.2	Architectural Description	(((((((((((((((((((One of the fine examples of Art Deco corner building having a circular central staircase block and rounded corners accentuated With linear curved chajjas on the facade. Unlike he other Art Deco buildings its corner has a visually nteresting concave form, a feature which sets it apart from he other Art deco buildings in its Vicinity.

A 3 3	RAM MAHAL	
5.3	Intrinsic	The various Art Deco style buildings on the newly reclaimed
		lands created a cohesive image. Like the Gothic buildings in
		their time represented the new face of the city and an
		expression of power, so too the Art Deco buildings and
		precincts symbolized the shift in expression to represent
5.4	Value Classification	contemporary aspirations. Existing Grade: NA Recommended Grade: III
J.4	Value Classification	A(arc), B(des), G(grp), E, I(sce)
6.0		TOPOGRAPHY
6.1	Floors	G + 6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry walls
7.3	Floor	R.C.C. floor slab
7.4	Stairs	R.C.C. winding staircase
7.5	Openings	Rectangular openings with wooden frames and glazed
		shutters
7.4	Roofing	Flat roof with terrace
7.6 7.7	Articulation	Circular central staircase, having glazing throughout chajjas
1.1	Anticulation	act as continuous floor bands around the building.
		act as continuous noor bands around the building.
7.8	Finishes	Internally and externally cement plastered and painted
7.9	Interiors(Movable & Immovable)	Decorative entrance foyer
7.10	Compound/Fence/Gate	Brick wall and M.S. fencing
7.11	Curtilege/ Unbuilt space/out	Paved marginal side open space
	buildings/landscape	
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural ventilation
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Window air-conditioning units at some places
9.0		CONDITION
9.1	Plinth	Good (No settlement or cracks observed)
9.2	Walls	Good (No dampness or cracks observed)
9.3	Floor	Good
9.4	Stairs	Good (Wooden members in good condition)
9.5	Openings	Good
9.6	Roofing	Good (No leakage observed)
9.7	Articulation & Finishes	Good

A 3 3	RAM MAHAL		
9.8	Services	Good (Drainage pipes need no replacement)	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	Maintenance level Good
10.0		TRANSFOR	MATION
10.1	Form	Sliding windov	vs and grills added later.
10.2	Structure	No transforma	tion
10.3	Articulation & Finishes	No transforma	tion
11.0	DP REMARKS/PERCEIVED THREATS	Plot falls under Residential Zone in DP	
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION		S. sheets, D.P. Sheets, Eicher City Maps – Mumbai, tra Bombay, The Cities Within Bombay 1995

A33 RAM MAHAL



(b)

(d)





Δ34	RAVINDRA MANSION			
Comm Card N Ward :		non Ref no: A34	1 x m	
				110000
		Ward :Ward A		
		CS No. 1630		In the of
			rea : 2027.6	Viter Var Marana
	PLT		rea : 7861	- Carling - 1 4
10.7			January, 2013	A HAND A I
	A CONTRACTOR OF THE REAL OF TH		d by : Aneri S, Adele Z	the first
- Andrews	A REAL PROPERTY OF		w by : Shraddha B.	A XX A
1.19			s above Ext: As above	1 10 1
E.			Ref : A34 RAVINDRA	N N
			SION a-f	
1.0	I		DENOMINATION	
1.1	Name of Premises		Ravindra Mansion	
1.2	Earlier Name		Not applicable	
1.3	Built In :1940's		Extension Date(if any): Not App	blicable
2.0			ACCESS ROADS	
2.1	Main		Dinshaw Vachha Road	
2.2	Subsidiary		J.Tata Road	
	1			
3.0			OWNERSHIP PATTERN	
3.1	Present		Vasantrao Vishnu Patil, Ravind	ra Vishnu Patil, Sudhir Vishnu Patil,
3.2	Past		The Governor of Bombay, Vish	nu Hari Patil
3.3	Status		Tenanted	
1.0				
4.0	Dresent		USE	
4.1	Present Past		Residential Residential	
4.2	Usage		Regular in residential use	
4.3			Regular in residential use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Dinshaw Vachha road fr	
5.2	Architectural Description		Planning: It is a large building ir	
	'		adequate light and ventilation. I	
			windows of the buildings open i	
			Stylistic Classification: The fron	t façade of the building shows
				d balconies that curve at one end,
				ell. The façade facing the subsidiary
				shows windows with chajja and
			balconies towards the right end	. Original nameplates, grills are
	<u> </u>		retained.	
5.3	Intrinsic			its era. The various Art Deco style
				d lands created a cohesive image.
				r time represented the new face of
				ower, so did the Art Deco buildings
			and precincts symbolized the sl	init in expression to represent
			contemporary aspirations.	

A 3 4	RAVINDRA MANSION		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Dog legged wooden staircase with wooden and aluminium railing	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Marble flooring in the lobby Staircases: Wooden Polished	
7.9	Interiors(Movable & Immovable)	Porch steps	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM MCGM	
8.5 8.6	Drainage (Plumbing and sanitation) Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units)	
9.0		CONDITION	
9.0 9.1	Plinth	Good(Lift lobby needs repairs)	
9.1	Walls	Good	
9.2 9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
0 (
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Average(Needs repairs and cleaning)	
9.10	Overall Condition	Good	

A 3 4	RAVINDRA MANSION	
10.0		TRANSFORMATION
10.1	Form	Balconies enclosed, Additional box grills, antennas on the façade of
		the building, garage doors changed
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai,
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	AVAILABLE/RECOMMENDATIONS	
	& SUGGESTIONS FOR	
	IMPLEMENTATION	

(b)

A34 RAVINDRA MANSION





(C)



(e)



A 3 5	YASHODHAN	
A 3 5		mon Ref no: A35 Not Available
	AND A NOT	
		No.:
		d: Ward A Io. Not Available
	FIUL	Area : Not Available Area: 10668
-		
and the		: January, 2013
100	Rect	ord by : Aneri S, Adele Z ew by : Shraddha B.
		As above Ext: As above
		o Ref : A35 YASHODHAN
		RTMENTS a-e
1.0	APA	
1.0	Name of Premises	Yashodhan
	Earlier Name	
1.2		Not applicable
1.3	Built In : 1960's	Extension Date(if any): Not Applicable
2.0		ACCESS ROADS
2.1	Main	Dinshaw Wachha Road
2.2	Subsidiary	Not Applicable
3.0		OWNERSHIP PATTERN
3.1	Present	State Government
3.2	Past	State Government
3.3	Status	Under the State Government
1.0		
4.0	Drecont	USE Residential
4.1	Present	
4.2	Past	Residential
4.3	Usage	Regular in residential use
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Part of Dinshaw Wachha road front, which is one of the major North-
-		South arterial roads.
5.2	Architectural Description	Planning: It is a large building in modest Art Deco style with
		adequate light and ventilation.
		Stylistic Classification: The building shows a concave corner on the
		left side. The front façade of the building shows long rectangular
		balconies with shallow chajja. The side facades show balconies and
		chajja. The building has multiple entries and staircases. The rear
		façade shows small windows with wooden chajja and rectangular
		balconies. Few windows show original grills.
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style
		buildings on the newly reclaimed lands created a cohesive image.
		Like the Gothic buildings in their time represented the new face of
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.

A 3 5	YASHODHAN			
5.4	Value Classification	Under Marine Drive Heritage Precinct		
6.0		TOPOGRAPHY		
6.1	Floors	G+6		
7.0		CONSTRUCTION		
7.1	Plinth	Plastered masonry plinth		
7.2	Walls	Brick masonry wall		
7.3	Floor	R.C.C. floor slab		
7.4	Stairs	Open well R.C.C. staircase with granite and marble cladding		
7.5	Openings	Regular openings with wooden frames and glazed shutters		
7.6	Roofing	Flat roof and terrace		
7.7	Articulation	Rounded balconies		
7.8	Finishes	Walls: Externally and internally cement plastered and painted		
		Flooring: Italian marble		
		Staircases: Granite Cladding		
7.9	Interiors(Movable & Immovable)	Entrance canopy		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.		
		gates painted.		
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,		
	buildings/landscape	temporary sheds, water tank		
8.0		SERVICES & UTILITIES		
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural lighting		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and sanitation)	MCGM		
8.6	Fire Precaution	Not provided		
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)		
9.0		CONDITION		
9.1	Plinth	Good		
9.2	Walls	Average(Needs repairs and painting)		
9.3	Floor	Good		
9.4	Stairs	Good		
9.5	Openings	Good		
9.6	Roofing	Good		
9.7	Articulation & Finishes	Good		
9.8	Services	Good		
9.9	Outbuildings	Good		
9.10	Overall Condition	Good		

A 3 5	YASHODHAN		
10.0		TRANSFORMATION	
10.1	Form	Additional box grills , balconies enclosed	
10.2	Structure	No transformation	
10.3	Articulation & Finishes	No major transformation	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP	
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995	

A35 YASHODHAN









(d)



A 3 6	CCI CHAMBERS			
Comm Card N			non Ref no: A36	Not Available
				1
			: Ward A	
CS No). 1645		
		rea : 3319.51		
	B U Ar		rea : 11543	
			January, 2013	
			d by : Aneri S, Adele Z	
	Revie		w by : Shraddha B.	
			s above Ext: As above	-
			Ref : A36 CCI CHAMBERS (a)	
			CCI CHAMBERS (d)	
1.0			DENOMINATION	
1.1	Name of Premises		CCI Chambers	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1950's		Extension Date(if any): Not Applicable	
2.0			ACCESS ROADS	
2.1	Main		Dinshaw Vachha road	
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		The Circket Club of India Ltd.	
3.2	Past		The Governor of Bombay	
3.3	Status		Under a trust	
4.0			USE	
4.1	Present		Residential(CCI guest rooms on the ground floor)	
4.2	Past		Residential	
4.3			Regular in residential use	
5.0			SIGNIFICANCE & VALUI	E CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Dinshaw Wachha road	front.
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with	
			adequate light and ventilation. It has voids where the interior	
			windows of the buildings open	into.
			Stylistic Classification: The bu	
			balconies on the front façade with project out towards the corners.	
				alconies. The windows show no
			chajja over them.	
5.3			Art Deco building representing its era. The various Art Deco style	
			buildings on the newly reclaimed lands created a cohesive image.	
			Like the Gothic buildings in their time represented the new face of	
			the city and an expression of power, so did the Art Deco buildings	
			and precincts symbolized the shift in expression to represent	
			contemporary aspirations.	
5.4	Value Classification L		Under Marine Drive Heritage P	

A 3 6	CCI CHAMBERS		
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well R.C.C. staircase with marble cladding	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Marble flooring in the lobby	
		Staircases: Marble cladding	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.	
		gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,	
	buildings/landscape	temporary sheds, water tank	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	fire extinguishers on the mid landings	
8.7	Other (HVAC/BMC/Security Systems)	Video surveillance in the compound, HVAC not provided	
		(independent air conditioning units)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	

A 3 6	CCI CHAMBERS	
10.0		TRANSFORMATION
10.1	Form	Additional grills, security rod for vehicles
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under commercial zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A36 CCI CHAMBERS







(C)



A 3 7	RAKHI MAHAL			
A 3 7		Comm	non Ref no: A37	
		Card I		
Con.			: Ward A	
). 1644	
1			rea : 1672.25	
	100 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		rea : 3384.57	
0			January, 2013	
			d by : Aneri S, Adele Z	
			w by : Shraddha B.	
			s above Ext: As above	
			Ref : A37 RAKHI MAHAL a-e	
1.0		FIIULU	DENOMINATION	
1.1	Name of Premises		Rakhi Mahal	
1.2	Earlier Name		Usha Kiran	
1.3	Built In: 1940's		Extension Date(if any): Not Applicable	
1.5			באנכווסטוד שמנכנוו מוזץ). זוטנ קיטווכמטוכ	
2.0	1		ACCESS ROADS	
2.0	Main		Dinshaw Wachha Road	
2.1	Subsidiary		Not applicable	
2.2	Subsidially			
3.0			OWNERSHIP PATTERN	
3.1	Present		Messrs Lotus Properties Private Limited	
3.2	Past		The Governor Of Bombay, Daddy Jehangir Billimoria &	
J.Z	Fasi		Capt.Shiwajirao N.Pawar & Nanubhai Kanthadbhai Jhaveri , Liant	
			General His Highness, Sir Jiwajirao M.Scindia Maharaja Of Gwalior	
			& Ahmedally Abdulhusein Kaka , Nomanbhoy Ahmedally Kaka ,	
			Safakathusein Ahmedally Kaka , Moizbhoy Ahmedally Kaka ,	
			Amtabai W/O Ahmedally Abdulhusein Kaka	
3.3	Status		Co-operating Housing Society	
5.5				
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
4.5				
5.0			SIGNIFICANCE & VALUE CLASSIFICATION	
5.1	Townscape(Natural/Manmade)		Part of Dinshaw Wachha road front.	
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with	
5.2			adequate light and ventilation. It has a void where the interior	
			windows of the buildings open into.	
			Stylistic Classification: The building has small projecting balconies	
			on the corners and windows have no chajja. The windows on the	
			side façade show curved chajja on them. The windows show	
			original grills and original gates. The balconies show original	
			carvings on them.	
5.3	Intrinsic		Art Deco building representing its era. The various Art Deco style	
0.0			buildings on the newly reclaimed lands created a cohesive image.	
			Like the Gothic buildings in their time represented the new face of	
I				

A 3 7	RAKHI MAHAL	
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well R.C.C. with marble cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Curved chajja
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Marble Cladding
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building
	buildings/landscape	
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Fire extinguishers
8.7	Other (HVAC/BMC/Security Systems)	HVAC not provided (independent air conditioning units in the
		houses)
9.0		CONDITION
9.0	Plinth	Good
9.2	Walls	Good (exterior walls need painting)
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.0	Articulation & Finishes	Good
9.7	Services	Good
9.8 9.9		
	Outbuildings Overall Condition	Average(Needs repairs and cleaning)
9.10		Good

A 3 7	RAKHI MAHAL	
10.0		TRANSFORMATION
10.1	Form	Additional box grills ,chajjas, balconies enclosed
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A37 RAKHI MAHA



(C)



(b)



(d)



A 3 8	MISTRY COURT			
		Comm	ion Ref no: A38	Not Available
		Card N		
	A CONTRACTOR OF		Ward A	
	10 the second of the	CS No	. Not available	
		Plot Ar	rea:	
		B U Ar	rea : 5571.3	
		Date :	January, 2013	
		Record	d by : Aneri S, Adele Z	
	TEL CONTRACTOR OF TEL CONTRACT	Review	v by : Shraddha B.	
	- LET		s above Ext: As above	
		Photo	Ref : A38 MISTRY COURT a-e	
1.0			DENOMINATION	
1.1	Name of Premises		Mistry Court	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date(if any): Not App	blicable
L				
2.0			ACCESS ROADS	
2.1	Main		Dinshaw Wachha road	
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Not available	
3.2	Past		Not available	
3.3	Status		Co-operative Housing Society	
1.0			USE	
4.0	Drocont		Mixed	
4.1	Present Past		Mixed	
4.2	Usage		Regular in mixed use	
4.5	Usaye		Regular III III. Red use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)		Part of Dinshaw Wachha road f	
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with	
0.2			adequate light and ventilation.	
			windows of the buildings open i	
			Stylistic Classification: The buil	
				ont façade and small rectangular
			balconies towards the corners	of the façade. The side façade shows
			rectangular balconies.	-
5.3	Intrinsic			its era. The various Art Deco style
				d lands created a cohesive image.
				r time represented the new face of
			, , , , , , , , , , , , , , , , , , ,	ower, so did the Art Deco buildings
			and precincts symbolized the s	hitt in expression to represent
			contemporary aspirations.	
E A	Value Classification		Under Marine Drive Heriters D	regipet
5.4	Value Classification		Under Marine Drive Heritage P	IECIIICI

A 3 8	MISTRY COURT		
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well R.C.C. staircase with granite cladding	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation		
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
l		Flooring: Granite flooring in the lobby	
		Staircases: Granite Cladding	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates	
		painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, water tank, pump	
	buildings/landscape	room, toilet	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Video surveillance, HVAC not provided (independent air	
		conditioning units)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good(exterior walls need painting)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Average(Shows cracks needs repairs)	
9.10	Overall Condition	Good	

A 3 8	MISTRY COURT	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. chajja, added toilet in the compound
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A38 MISTRY COURT



(b)



(d)





A 3 9	CRICKET CLUB	OF INDIA		
		Common Ref no: A3 2013) Card No.: A-8 Ward (Part): Ward A CS No.: 1554 Plot Area: 61190.84 B U Area: 80771.90 Date: April, 2005 Record by: Gauri J, Review by: Arun Ka Int: As above Photo Ref: A39 CCI	sq.m. sq.m. sq.m. Anup S le Ext: As above	
1.0			DENOMINATION	
1.1	Name of Premises		Cricket Club of India Ltd	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1937		Extension Date(if any): Not applicable	
2.0			ACCESS ROADS	
2.1	Main		Dinshaw Wachha Road	
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Governor of Bombay (Lessor), Cricket Club of India	
3.2	Past		(lessee) Governor of Bombay (Lessor), Cricket Club of India	
			(lessee)	
3.3	Status		Government	
4.0			USE	
4.1			Now the stadium hosts school sport meets & variety entertainment programs since the construction of Wankhede Stadium	
4.2	Past		Public	
4.3	Usage		Regular public use	
5.0			SIGNIFICANCE & VALUE CLASSIFICATION	
5.1	Townscape(Natural/Ma	nmade)	Located east of the Marine Drive in Back Bay area facing Dinshaw Wachha Road, adjoining Brabourne stadium.	

A 3 9	CRICKET CLUB OF INDIA	
5.2	Architectural Description	Low rise building in moderate Art Deco character. Rounded
	· · · · · · · · · · · · · · · · · · ·	balconies and curved corners, simple rectangular windows
		with
		chajjas compound wall and gate with Art Déco elements all
		painted in pastel shades of grey and white, its modest
		interior
		attribute on sophisticated class identity of 1940s.
5.3	Intrinsic	Designed by architects Gregson, Batley and King, the CCI
0.0		Complex
		including the 40,000 capacity, Brabourne stadium was
		inaugurated
		by the Governor Lord Brabourne. This was the prime
		Cricket
		Stadium till it lost its importance to Wankhede Stadium,
		built in the
		close vicinity in 1970s. The CCI Club is still one of the elite
		clubs of
		the city. The various Art Deco style buildings on the newly
		reclaimed lands created a cohesive image. Like the Gothic
		buildings
		in their time represented the new face of the city and an
		expression
		of power, so too the Art Deco buildings and precincts
		symbolized
		the shift in expression to represent contemporary
		aspirations.
5.4	Value Classification	Existing Grade: NA Recommended Grade: II B
		A(arc), A(cul), B(des), E
		TODOODADUW
6.0		TOPOGRAPHY
6.1	Floors	G + 3
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry walls
7.3	Floor	R.C.C. floor slab
7.3	Stairs	Access denied
7.4	Openings	Rectangular openings with wooden frames and glazed
1.5	openings	shutters
7.6	Roofing	Flat roof with terrace
7.7	Articulation	It has minimal articulation on the façade except for the
1.1		rounded
		edges of the building and the facades painted in pastel
		shades.
7.8	Finishes	Sand faced externally and internally cement plastered and
7.0		painted
7.9	Interiors(Movable&Immovable)	Entrance foyer
7.10	Compound/Fence/Gate	Plastered brick wall with M.S. fencing
7.10	Curtilege/ Unbuilt space/out	Open space for stadium in the center
7.11	ournicyc/ onbuilt space/out	Open space for stadium in the center

CRICKET CLUB OF INDIA			
	1		
	SERVICES	& UTILITIES	
Liahtina			ahtina
			ontildion
		at 30 meters	
			ome places
	CONDITION	N	
Plinth			served)
		d	
		-	
		kage observed)	
	Good (Drainage pipes need no replacement)		
Overall Condition	Good	Maintenance level	Good
Form			nter
DP REMARKS/PERCEIVED THREATS	Plot demarcated as Open Spaces in DP		s in DP
	History Crog	con Ration and King	n who also drow the plane
ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	History: Gregson, Batley and King, who also drew the pla for the Cricket Club of India and the Brabourne Stadiu The magnificent cricket stadium, inaugurated in December 1937 by the Governor Lord Brabourne, could accommoda 40000 people, and was in the coming decade, to becor synonymous with the game of cricket in the city. Documents: C.S. sheets, D.P. Sheets, Eicher City Maps Mumbai, Dwivedi, Mehrotra Bombay, The Cities With Bombay 1995		the Brabourne Stadium. inaugurated in December, burne, could accommodate oming decade, to become cket in the city. heets, Eicher City Maps -
	Form Form Structure Articulation & Finishes DP REMARKS/PERCEIVED THREATS ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR	buildings/landscape SERVICES Lighting Natural and a Ventilation Natural and a Electricity BEST Water Supply MCGM Drainage (Plumbing and sanitation) MCGM Fire Precaution Fire hydrants Other (HVAC/BMC/Security Systems) Window air-co Plinth Good (No sett Walls Good (No sett Walls Good (No sett Valls Good (No leal Articulation & Finishes Good Openings Good Roofing Good (No leal Articulation & Finishes Good Outbuildings Good Overall Condition Good Structure No transforma Articulation & Finishes No transforma AVAILABLE/RECOMMENDATIONS History: Greg; &	buildings/landscape SERVICES & UTILITIES Lighting Natural and artificial, fair natural in Natural and artificial, fair natural in Natural and artificial, fair natural in Second Sec



CRICKET CLUB OF INDIA

(a)







A 4 0	MOTI MAHAL			
		Common Ref no: A40		
	and the second second	(Reviewed in 2013)		
7.43	AND	Card No.: A-7c		
IIII TO	THE REAL PROPERTY AND ADDRESS OF	Ward (Part): A-II	1631	
	THE OWNER WATER TO AN	CS No.: 1631	MOTI MAHAL	
		Plot Area: 2136.3 sq.r	$\overline{\mathbf{n}}$	
		B U Area: 1424.2 sq.r		
		Date: April, 2005		
in a star		Record by: Gauri J, A	nun 🕷	
		S	nup "Hellin Harrow Bar	
		Review by: Arun Kale	14 ROA	
Δ			Ext:	
		As above		
		Photo Ref: A40 MOTI		
		MAHAL a-f		
1.0		DENOMINAT	ION	
1.1	Name of Premises	Moti Mahal		
1.2	Earlier Name	Not applicable		
1.3	Built In: 1940-1949		if any): Not available	
		,	//	
2.0		ACCESS RO	ADS	
2.1	Main	Jamshedji Tata		
2.2	Subsidiary		Dinshaw Wachha Road	
3.0		OWNERSHIP	PATTERN	
3.1	Present	Bombay Fire & (General Insurance Company	
3.2	Past	Gopalbhai Bhair	uratan Damani, Bhimaldevi Premratan	
		Damani,		
			tan Damani, South India Insurance Company	
3.3	Status	Tenanted		
4.0		USE		
4.1	Present	Residential, Cor	nmercial	
4.2	Past	Residential		
4.3	Usage	Regular resident	tial and commercial use	
5.0	-		CE & VALUE CLASSIFICATION	
5.1	Townscape(Natural/Manmade)		portant junction facing the round island at	
		Jamshedji		
			ch is one of the major North-South arterial	
		roads	a bha Daoid 's Daois Dao Daoisean atlan	
<u>г</u> о	Architectural Description		achha Road in Back Bay Reclamation.	
5.2	Architectural Description		is architecturally no so valuable Art Deco	
		building is	tion accumulation of the corners facing the	
		traffic	tion occupying one of the corners facing the	
			like vertical bands spanning from first floor to	
			like vertical bands spanning from first floor to he projecting curved balconies are its claim	
			The projecting curved balconies are its cialin	

A 4 0	MOTI MAHAL	
		to Art
		Deco.
5.3	Intrinsic	The various Art Deco style buildings on the newly reclaimed
		lands created a cohesive image. Like the Gothic buildings in
		their time represented the new face of the city and an
		expression of power, so too the Art Deco buildings and
		precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Existing Grade: NA Recommended Grade: III
		A(arc), B(des), G(grp), E
6.0		TOPOGRAPHY
6.1	Floors	G + 7
0.1		
7.0		CONSTRUCTION
7.1	Plinth	0.3 meters plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	R.C.C. staircase around lift well
7.5	Openings	Rectangular openings with wooden frames and glazed
		shutters
7.6	Roofing	Flat roof with terrace
7.7	Articulation	Small rectangular balconies rounded at ends, vertical
		projecting
7.0		bands on façade
7.8 7.9	Finishes	Internally and externally cement plastered and painted
7.10	Interiors(Movable & Immovable) Compound/Fence/Gate	Entrance foyer Prick piers, with M.S. foncing
7.10	Curtilege/ Unbuilt space/out	Brick piers, with M.S fencing Front open space moderately landscaped with lowers and
7.11	buildings/landscape	plasters
	bullulitys/latuscape	plasters
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural ventilation
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided
9.0		CONDITION
9.1	Plinth	Fair (No settlement or cracks observed but needs
		maintenance)
9.2	Walls	Fair
9.3	Floor	Fair

A 4 0	MOTI MAHAL	
9.4	Stairs	Fair (Needs maintenance)
9.5	Openings	Fair
9.6	Roofing	Fair (No leakage observed)
9.7	Articulation & Finishes	Fair
9.8	Services	Fair (Drainage pipes need maintenance)
9.9	Outbuildings	Fair
9.10	Overall Condition	Fair Maintenance level Fair
10.0		TRANSFORMATION
10.1	Form	No transformation
10.2	Structure	Top two floors added later.
10.3	Articulation & Finishes	No transformation
11.0	DP REMARKS/PERCEIVED	Plot falls under Residential Zone in DP
	THREATS	
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps -
	NOTES/REFERENCES/DOCUMENTS	Mumbai,
	AVAILABLE/RECOMMENDATIONS	Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995
	& SUGGESTIONS FOR	
	IMPLEMENTATION	

(b)

A 4 0 MOTI MAHAL







122.5

(c)





(e)



Λ/1	LOTUS COURT			
A 4 1		Comm	non Ref no: A41	
	10.50	Conin Card N		-
			: Ward A	KIC Vin 2
(† 1977) 1977 - 1977 1977 - 1977	A Contraction of the second), 1632	-
Tel.	and the spinster of the			
			rea : 1958.21	1/0
ing A			rea: 4599	- AL - A A A
			January, 2013	
			d by : Aneri S, Adele Z	
1			w by : Shraddha B.	· ····································
			s above Ext: As above	-
1.0		Photo	Ref : A41 LOTUS COURTa-d	
1.0	Nome of Dramines		DENOMINATION	
1.1	Name of Premises		Lotus Court	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1950's		Extension Date(if any): Not App	licable
2.0				
2.0			ACCESS ROADS	
2.1	Main		J. Tata Road	
2.2	Subsidiary		Not Applicable	
2.0				
3.0	Descent		OWNERSHIP PATTERN	
3.1	Present		Lotus Court (Private)Ltd.	
3.2	Past			alal Premjee, Harishchandra Alias
			Harish, Jethalal Premjee, Pravir	nchandra Jethalal Premjee,
2.2			Manharlal Jethalal Premjee	
3.3	Status		Co-operative housing society	
4.0				
4.0	Present		USE	
4.1			Mixed	
4.2	Past		Mixed	
4.3	Usage		Regular in mixed use	
F 0				
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of J. Tata road front.	
5.2	Architectural Description		Planning: It is a large building in	i modest Art Deco style with
			adequate light and ventilation.	food of the building obout long
				façade of the building shows long des show small curved balconies
E D			and windows with no chajjas ov	
5.3	Intrinsic			ts era. The various Art Deco style
				d lands created a cohesive image. r time represented the new face of
				wer, so did the Art Deco buildings
			and precincts symbolized the sh	
			contemporary aspirations.	Int in copiession to represent
5.4	Value Classification		Under Marine Drive Heritage Pr	ecinct
U. T				oomot
	<u> </u>		1	

A 4 1	LOTUS COURT	
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Access Denied
7.5	Openings	Regular openings with wooden frames and glazed shutters
		5 1 5 5
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Access Denied
		Staircases: Access Denied
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.
		gates painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, water tank, pump
	buildings/landscape	room, security office, entrance to the bank on the ground floor,
		planters on the ground floor.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Video surveillance
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good

A 4 1	LOTUS COURT	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. chajjas , security cabin, Additional canopy on the ground floor.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

(b)

A41 LOTUS COURT

(a)







Δ 4 2	NATIONAL INSURANCE BU	ווח וו	NG	
		ion Ref no: A42		
	Card N			· To have at a
		Ward A	1 Million	
CS No.				
		rea : 1651.53	13/ 20 22	
tion of the second s			rea: 4956	KK Vin Martin
			January, 2013	and him a to
			d by : Aneri S, Adele Z	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			w by : Shraddha B.	and the state of the second se
TA SHOW	A DE LE		s above Ext: As above	A A A
ilis itiihanna			Ref : A42 NATIONAL	max Str D. X
			RANCE a-e	
1.0		moon	DENOMINATION	
1.1	Name of Premises		National Insurance Building	
1.2	Earlier Name		Royal Insurance Building	
1.3	Built In : 1940's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		J. Tata Road	
2.2	Subsidiary		Not Applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		The Royal Insurance Company	Limited
3.2	Past		The Governor Of Bombay, Mrs.	
3.3	Status		Tenanted	,
4.0			USE	
4.1	Present		Commercial	
4.2	Past		Commercial	
4.3	Usage		Regular in Commercial use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of J. Tata road front.	
5.2	Architectural Description		Planning: It is a large building in	modest Art Deco style with
			adequate light and ventilation.	
			Stylistic Classification: The front	
				windows with no chajjas. The side
				nall windows with chajjas over them.
				s trapezoidal. The rear façade is
	Intrincio		similar to the front façade.	to any The verieus Art Dass study
5.3	Intrinsic			ts era. The various Art Deco style d lands created a cohesive image.
				r time represented the new face of
				wer, so did the Art Deco buildings
			and precincts symbolized the sh	
			contemporary aspirations.	
L			1	

A 4 2	NATIONAL INSURANCE BUIL	DING	
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well stone staircase with cement terrazzo tiling	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Black marble flooring in the lobby	
		Staircases: Cement terrazzo (marble on the ground floor)	
7.9	Interiors(Movable & Immovable)	Entrance Canopy and porch steps	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S.	
		gates painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room, Planters	
	buildings/landscape	5	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good(Needs cleaning)	
9.10	Overall Condition	Good	

A 4 2	NATIONAL INSURANCE BUILDI	NG
10.0		TRANSFORMATION
10.1	Form	Additional grills , A.C.P. chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A42 NATIONAL INSURANCE BUILDING

(a)



(C)



(b)



(d)



A 4 3	KHETAN BHAVAN	
A45		Common Ref no: A43 (Reviewed in 2013)Card No.: A-7bWard: Ward ACS No. 1634Plot Area : 1678.1B U Area : 6292.87Date : April, 2005Record by : Gauri J, Ojas PReview by : Arun KaleInt : As aboveExt: As abovePhoto Ref : A43 KHETAN BHAVAN a-g
1.0		DENOMINATION
1.1	Name of Premises	Khetan Bhavan
1.2	Earlier Name	Not applicable
1.3	Built In:1930's	Extension Date(if any): Not Applicable
2.0		ACCESS ROADS
2.1	Main	Jamshedji. Tata Road
2.2	Subsidiary	Jamshedji Tata Cross Road
3.0		OWNERSHIP PATTERN
3.1	Present	Omkar Premises Co-Operative Society Limited
3.2	Past	The Governor Of Bombay, Karimjee, Properties Ltd., Messrs.Khetau Estate Ltd.
3.3	Status	Co-operative Housing Society
4.0		USE
4.1	Present	Mixed
4.2	Past	Mixed
4.3	Usage	Regular in mixed use
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Part of Jamshedji Tata road front.
5.2	Architectural Description	Planning: It is a large building in modest Art Deco style with adequate light and ventilation. It has voids where the interior windows of the buildings open into. Stylistic Classification: The left corner of the building is trapezoidal. The building shows curved balconies from that corner. The other balconies are rectangular and they project out (mostly enclosed).
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts

A 4 3	KHETAN BHAVAN		
		symbolized the shift in expression to represent contemporary aspirations.	
5.4	Value Classification	Existing Grade: NA A(arc), B(des), G(grp), E	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0			
7.0	Dlinth	CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
	Walls	Brick masonry wall R.C.C. floor slab	
7.3 7.4	Floor Stairs	Dog legged stone staircase with marble cladding(commercial)	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.6 7.7	Articulation	Trapezoidal corner, curved balconies	
7.8	Finishes Fin		
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, water tank	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	

A 4 3	KHETAN BHAVAN	
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good(Needs cleaning)
9.10	Overall Condition	Good
10.0		TRANSFORMATION
10.1	Form	Additional grills , A.C.P. chajjas , balconies enclosed
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-
	NOTES/REFERENCES/DOCUMENTS	Mumbai, Dwivedi, Mehrotra Bombay, The Cities within
	AVAILABLE/RECOMMENDATIONS	Bombay 1995
	& SUGGESTIONS FOR	
	IMPLEMENTATION	

A43 KHETAN BHAVAN













A 4 5	Δ STORIA HOTEL	
		Common Ref no: A45
1		(Reviewed in 2013)
21.15		Card No.: A-7d
		Ward (Part): A-II
	2 2 2 2 2 1 m m m m i 1 1 1 2 2	CS No.: 1637
42		Plot Area: 2992.50 sq.m.
		B U Area: 13466.25 sq.m.
		Date: April, 2005
en.	The glolarie Shalet	Record by: Gauri J, Ojas P
P		Review by: Arun Kale
		Int: As above Ext:
		As above LAL
		Photo Ref: A45 ASTORIA
		HOTEL a-g
		HOTEL day
1.0		
1.0	News of Desmisse	DENOMINATION
1.1	Name of Premises	Astoria Hotel
1.2	Earlier Name	Not applicable
1.3	Built In: 1950-1959	Extension Date(if any): Not applicable
2.0		ACCESS ROADS
2.0	Main	
		Jamshedji Tata Road
2.2	Subsidiary	Not applicable
3.0		OWNERSHIP PATTERN
3.1	Present	Khupchand Daulatram, Parasram Daulatram
3.2	Past	Governor of Bombay, Kishanchand Gulabram, Lacchmibai
0.1		Shevakram, Lokumal Kishanchand, Murli Tehliram Chellaram,
		Pishutehliram Chellaram, Wasiamull Bhagumal, Lachmandas
		Shevakram, Hotchand Advani, Navindhibhai Advani, Shobhraj
		Jhumatmal, Valiram Gheruma, Kakibai Dwarkadas.
3.3	Status	Ownership
4.0		USE
4.1	Present	Hotel (Public)
4.2	Past	Hotel (Public)
4.3	Usage	Hotel (Regular public use)
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Located on Jamshedji Tata Road, which is one of the major North-
		South arterial roads. This area falls under Back Bay Reclamation
		which was completed in 1929.
5.2	Architectural Description	This well proportioned symmetrical building on the Jamshedji Tata
		road is part of the Back Bay Reclamation area. In simple Art deco
		style cladded in Porebunder stone with minimum articulation on the
		facade enhances its public character. The facade has verticality
		with recessed openings. The only projecting balcony on the top
		floor creates interest on the otherwise stark facade.

A 4 5	ASTORIA HOTEL			
5.3	Intrinsic	The various Art Deco style buildings on the newly reclaimed lands		
		created a cohesive image. Like the Gothic buildings in their time		
		represented the new face of the city and an expression of power, so too the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations.		
5.4	Value Classification	Existing Grade: NA Recommended Grade: II A		
		A(arc), B(des), G(grp), E		
6.0		TOPOGRAPHY		
6.1	Floors	G + 5		
•••				
7.0		CONSTRUCTION		
7.1	Plinth	Plastered masonry plinth		
7.2	Walls	0.15 meter thick brick wall		
7.3	Floor	R.C.C. floor slab		
7.4	Stairs	Dog legged, R.C.C. staircase with wooden railing		
7.5	Openings	Rectangular openings with wooden frames and glazed shutters		
7.6	Roofing	Flat roof with terrace		
7.7	Articulation	Stone pilasters projecting on the façade		
7.8	Finishes	Malad stone cladding. Internally cement plastered and painted.		
7.9	Interiors(Movable & Immovable)	Decorative entrance foyer		
7.10	Compound/Fence/Gate	Brick piers at intervals		
7.11	Curtilege/ Unbuilt space/out	Marginal side open space		
	buildings/landscape			
8.0		SERVICES & UTILITIES		
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural ventilation		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and sanitation)	MCGM		
8.6	Fire Precaution	Not provided		
8.7	Other (HVAC/BMC/Security Systems)	Window air-conditioning units at some places		
9.0		CONDITION		
9.0	Plinth			
9.1	Walls	Good (No settlement or cracks observed) Good (No dampness or cracks observed)		
9.3	Floor	Good (No dampness of cracks observed)		
9.4	Stairs	Good		
9.5	Openings	Good		
9.6	Roofing	Good (No leakage observed)		
9.7	Articulation & Finishes	Good		
9.8	Services	Good (Drainage pipes need no replacement)		
9.9	Outbuildings	Good		
9.10	Overall Condition	Good Maintenance level Good		
7.10				
	1	<u>I</u>		

A 4 5	ASTORIA HOTEL			
10.0		TRANSFORMATION		
10.1	Form	No transformation		
10.2	Structure	No transformation		
10.3	Articulation & Finishes	No transformation		
11.0				
	DP REMARKS/PERCEIVED	Plot falls under Commercial Zone in DP		
	THREATS			
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai,		
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995		
	AVAILABLE/RECOMMENDATIONS			
	& SUGGESTIONS FOR			
	IMPLEMENTATION			

A45 ASTORIA HOTEL









(e)



(d)



Δ16	INDUSTRIAL ASSURANCE	BIIII	DING	
A40	INDUSTRIAL ASSURANCE		non Ref no: A61	de la companya de la
Card Ward CS No Plot A				a Tom Canada a la la la
			d (Part) Ward (Part II): A II	
			rea: 2992.5	m man mar
			ea: 12157.8287	hand D Cany my 11 -
			January, 2013	Link Kill
Recor			d by : Aneri S, Adele Z	HIS & X
			w by : Shraddha B.	2 2
			s above Ext: As above	2 1 at 12
Photo			Ref : A46 INDUSTRIAL	2.23.
			RANCE a-q	The the stand of the
1.0	-	INSUR		
1.0	Name of Premises		Industrial Assurance Building	
1.1	Earlier Name		Not applicable	
1.2	Built In: 1940's		Extension Date(if any): Not Applicable	
1.5			LAIGHSIUH DAIG(II AHY). NULAPPIICADIG	
2.0			ACCESS ROADS	
2.0	Main		J. Tata Road	
2.2	Subsidiary		Veer Nariman Road	
2.2				
3.0			OWNERSHIP PATTERN	
3.1	Present		The Industrial & Prudential Assurance Company Ltd.	
3.2	Past		The Governor Of Bombay	
3.3	Status		Partly Tenanted part Co-operative Housing Society	
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Mixed	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of J. Tata road front.	
5.2	5.2 Architectural Description		Planning: It is a large building in modest Art Deco style with	
			adequate light and ventilation. It has a void where the interior	
			windows of the buildings open in	
			Stylistic Classification: The building shows a curved corner along the junction of the main and subsidiary road. The building is divided into	
			commercial and residential wing (originally). The building is divided into commercial and residential wing (originally). The building shows large R.C.C. canopies on the facades facing the main and subsidiary roads. The commercial wing shows a grand entrance with a large spiral staircase in the lobby in marble. The Residential wing shows rectangular and curved balconies. Original grills in few windows, old	
			nameplates are still maintained. The windows on the façade facing	
			the main road are recessed. The windows on the side façade of the	
			building have rectangular balconies that project out.	
5.3	Intrinsic			ts era. The various Art Deco style
				d lands created a cohesive image.

A 4 6	INDUSTRIAL ASSURANCE BU	JILDING	
		Like the Gothic buildings in their time represented the new face of	
		the city and an expression of power, so did the Art Deco buildings	
		and precincts symbolized the shift in expression to represent	
		contemporary aspirations.	
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine	
		Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
7.0		CONSTRUCTION	
7.0	Plinth	Plastered masonry plinth	
7.1	Walls	Brick masonry wall	
7.2	Floor	R.C.C. floor slab	
7.3	Stairs		
7.4	Sidiis	staircase(residential)	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Curved corner and balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Ceramic tiles in the lobby	
		Staircases: Granite Cladding	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S.	
		gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, water tank, Porch	
	buildings/landscape	steps of the shops	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Individual units provided	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Average(Shows cracks needs repairs)	
9.10	Overall Condition	Good	

A 4 6	INDUSTRIAL ASSURANCE BUIL	DING
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. and chajjas,
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A46 INDUSTRIAL ASSURANCE BUILDING







(d)



(C)



(e)





A 4 7	REHMAT MANZIL			
			non Ref no: A47	The second
Ca		Card N		701 5
		Ward : Ward A		and the second of the second o
Sec. ve-	A CONTRACTOR OF A CONTRACTOR O). 1/1554	A Contraction of To
1 1 N			rea : 1605.54	for all in the for
· ·		B U Ar	rea : 4830	free with and
2. 30	AND DO ALLOW AND DESCRIPTION	Date :	January, 2013	Arm of Reference on One
E State	A A A A A A A A A A A A A A A A A A A	Recor	d by : Aneri S, Adele Z	HALO PLOY HOZOZA BBR OM
	ADDR	Review	w by : Shraddha B.	and a land
AS I	A PARTICIPAL PROPERTY		s above Ext: As above	A Come one one one
		Photo	Ref : A47 REHMAT MANZIL a-	
		h		
1.0	Nome of Dramines		DENOMINATION	
1.1	Name of Premises Earlier Name		Rehmat Manzil	
1.2			Not applicable	licabla
1.3	Built In: 1940's		Extension Date(if any): Not App	
2.0			ACCESS ROADS	
2.1	Main		Veer Nariman road	
2.2	Subsidiary		Not Applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Noorbanoo Hooseinally Vishram	
3.2	Past		Bai Rehmatbai Wd/O Jairazbho	y Peerbhoy, Hassanally
			Q.Jairazbhoy, Ashrafali Q.Jairaz	zbhoy
3.3	Status		Tenanted	
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Mixed	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Veer Nariman road front	
5.2	Architectural Description		Planning: It is a large building in	
			adequate light and ventilation. It	
			windows of the buildings open ir	
			Stylistic Classification: The fron	5
				ular balconies towards the corners.
				vindows with long continuous chajjas
			and balconies on the corners. O mailboxes are maintained.	nginai grills, namepiates and
5.3	Intrinsic			ts era. The various Art Deco style
5.5				d lands created a cohesive image.
				time represented the new face of
				wer, so did the Art Deco buildings
			and precincts symbolized the sh	
			contemporary aspirations.	

A 4 7	REHMAT MANZIL		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
5.4			
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
0.1			
7.0		CONSTRUCTION	
7.0	Plinth	Plastered masonry plinth	
7.1	Walls	Brick masonry wall	
7.2	Floor	R.C.C. floor slab	
7.4	Stairs	R.C.C. spiral staircase with cement terrazzo with a wooden handrail	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation		
1.1	Anculation		
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
7.0	1 11131103	Flooring: Cement terrazzo	
		Staircases: Cement terrazzo	
7.9	Interiors(Movable & Immovable)	Entrance canopy and porch steps	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates	
7.10		painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, water tank	
/.11	buildings/landscape	Tarking sheus at the real side of the building, water tark	
	bullungshandscape		
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good(exterior walls need painting)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good(Needs painting)	
9.8	Services	Good	
9.9	Outbuildings	Average(Needs cleaning and repairs)	
9.10	Overall Condition	Good	

A 4 7	REHMAT MANZIL	
10.0		TRANSFORMATION
10.1	Form	Additional grills, A.C.P. chajjas , enclosed balconies, garages
		converted to shops.
10.2	Structure	No transformation
10.3	Articulation & Finishes	(The building is under repairs)
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai,
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	AVAILABLE/RECOMMENDATIONS	
	& SUGGESTIONS FOR	
	IMPLEMENTATION	

A47 REHMAT MANZIL





(b)



(C)



(e)









(g)





A 4 8	VULCAN INSURANCE			
		Comm	non Ref no: A48	
	19	Card		The second second
			:Ward A	and - for the second of the
). 2/1554	2ª / Re-
			rea : 1605.54	
			rea :4809	17534
			January, 2013	The time to the
			d by : Aneri S, Adele Z	ma g
			w by : Shraddha B.	Pe [ma
			s above Ext: As above	L J L
			Ref : A48 VULCAN	
			RANCE a-e	
1.0		INSUF		
1.0	Name of Premises		Vulcan Insurance	
1.1	Earlier Name		Not applicable	
1.2	Built In:1930's		Extension Date(if any): Not Appli	laabla
1.3	Built 11: 1930 S			
2.0			ACCESS ROADS	
2.1	Main		Veer Nariman Road	
2.2	Subsidiary		Not Applicable	
2.2				
3.0			OWNERSHIP PATTERN	
3.1	Present		The Vulcan Insurance Co.Ltd.	
3.2	Past			akirmahomed Currimbhoy Lalljee
				Iljee Sajun, The Vulcan Insurance
			Company Limited., The English I	Electric Company Limited.
3.3	Status		Semi Government	
4.0				
4.0	Dressent		USE	
4.1	Present		Commercial	
4.2	Past		Commercial	
4.3	Usage		Regular in commercial use	
F 0				
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Veer Nariman road front.	madaat Art Daga atula with
5.2	Architectural Description		Planning: It is a large building in	modest Art Deco style with
			adequate light and ventilation.	foodo of the huilding is optically
			Stylistic Classification: The front	
				ndows recessed inside them. The
				windows with no chajjas. The rear
				windows recessed in the fins with
5.3	Intrinsic		triangular chajjas. The right façad Art Deco building representing its	
5.3				
				lands created a cohesive image.
				time represented the new face of
				ver, so did the Art Deco buildings
			and precincts symbolized the shi	it in expression to represent
L			contemporary aspirations.	

A 4 8	VULCAN INSURANCE		
A 4 0	VULCAN INSURANCE		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well stone staircase with Kota	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation		
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Black marble flooring Staircases: Kota Stones	
7.9	Interiors(Movable & Immovable)	Entrance canopy and porch steps	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with, Gates are M.S. gates	
7.10		painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, Planters	
	buildings/landscape		
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Average(exterior walls need repairs and painting)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Average(Needs cleaning and repairs)	
9.10	Overall Condition	Good	

A 4 8	VULCAN INSURANCE	
10.0		TRANSFORMATION
10.1	Form	Additional grills for A.C. units
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A48 VULCAN INSURANCE



(b)



(C)





ΛΛΟ	MAYFAIR			
A 4 7		Comm	non Ref no: A49	1 1 1 1 - Considering
		Control Control		The fit-bener 11
			:Ward A	1 1ª mil mand - 4
			b. 3/1554	
1.2	A LEAD - A BALLE & CONTRACT OF		rea : 1605.54	
	All All and a second	_	rea: 4458	
			January, 2013	
2	The second secon		d by : Aneri S, Adele Z	PLAT
(j)			w by : Shraddha B.	PLET HO ZOZO BAR. ONH 9
			s above Ext: As above	for the second s
	PIDE LUANCATION	_	Ref : A49 MAYFAIR a-e	
1.0		1 11010	DENOMINATION	
1.1	Name of Premises		Mayfair	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1930's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Veer Nariman Road	
2.2	Subsidiary		Not Applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Sarla Wife of Kumudchandra Cl	heda
3.2	Past		The Governor of Bombay, The	
J.Z	1 431		Tehmina Wife Of Kaikhushroo H	
				K.C.Chheda & Co., Kumudchandra
			Champshi Chheda	
3.3	Status		Tenanted	
0.0				
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Residential	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			nt, which is one of the major North-
F 0	Architectural Description		South arterial roads.	medeet Art Deee et de with
5.2	Architectural Description		Planning: It is a large building in	
			adequate light and ventilation. If	
			windows of the buildings open in	
			Stylistic Classification: The front	dows with chajjas towards the corner.
				shows windows with long continuous
				he rear. The rear façade is similar to
				e staircase made of M.S. is seen on
			the rear side of the building.	
5.3	Intrinsic			ts era. The various Art Deco style
0.0				d lands created a cohesive image.
				r time represented the new face of

A 4 9	MAYFAIR	
Λτ/		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with marble cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring
7.0		Staircases: Marble Cladding
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates
		painted.
7 1 1		Deally a shead of the second day of the head of the second sector back as well.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, water tank, pump
	buildings/landscape	room
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	HVAC system for the restaurant on the ground floor and
		independent air conditioning units for the houses
		· · · · · · · · · · · · · · · · · · ·
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good(exterior walls need painting)
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Average(Needs cleaning)
9.10	Overall Condition	Good

A 4 9	MAYFAIR	
10.0		TRANSFORMATION
10.1	Form	Additional grills, balconies enclosed
10.2	Structure	No transformation(Under Repairs)
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995





(b)



(C)



(d)



A 5 0	STADIUM HOUSE		
- 7,50		Common Ref no: A50	t
State States		Card No.:	during
102 A		Ward : Ward A	m Straign (range . v) sail 12
N. CO		CS No. 4/1554	L'aller Fr
		Plot Area : 3286.81	A PARTE
		B U Area :	sinan line -
		Date : January, 2013	" \
		Record by : Aneri S, Adele Z	
-	Management and a Resource of Statement of St	Review by : Shraddha B.	al la
		Int : As above Ext: As above	
		Photo Ref : A50 STADIUM HOUSE a f	12.7 -16
1.0		DENOMINATION	- L
1.1	Name of Premises	Stadium House	
1.2	Earlier Name	Not applicable	
1.3	Built In: 1930's	Extension Date(if any): Not Ap	oplicable
2.0		ACCESS ROADS	
2.0	Main	Veer Nariman road	
2.2	Subsidiary	Not Applicable	
2.2			
3.0		OWNERSHIP PATTERN	
3.1	Present	Cricket Club of India Ltd.	
3.2	Past	Cricket Club of India Ltd.	
3.3	Status	Tenant	
4.0		USE	
4.1	Present	Commercial	
4.2	Past	Commercial	
4.3	Usage	Regular in commercial use	
5.0		SIGNIFICANCE & VALU	F CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Part of Veer Nariman road fro	
5.2	Architectural Description	Planning: It is a large building	
0.2		adequate light and ventilation.	
			nt façade of the building shows
			ajja over them. The building has
		varying topography and multip	ble gates. The rear façade of the
			with chajja over them. The building
			e front façade, a modest G+1 storey.
		0	naving no chajja. The ground floor
			age, nameplate still maintained. The
5.3	Intrinsic	colonnade has cylindrical colu	imns. g its era. The various Art Deco style
0.0			ned lands created a cohesive image.
			eir time represented the new face of
			power, so did the Art Deco buildings
			shift in expression to represent

A 5 0	STADIUM HOUSE	
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	Under Renovation not known
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with granite cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
		······································
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S
		gates (original) painted.
		gatoo (original) paintou
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,
/	buildings/landscape	temporary sheds, water tank
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units)
0.7		
9.0		CONDITION
<u>9.0</u> 9.1	Plinth	Good
9.1 9.2	Walls	Good
<u>9.2</u> 9.3	Floor	Good
<u>9.3</u> 9.4	Stairs	Good
9.4 9.5		Good
	Openings Desting	
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings Overall Condition	Good Good(under repairs)
9.10		

A 5 0	STADIUM HOUSE	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. canopies and chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995





A 5 1	RIVIERA			
I C A	RIVIERA	Comm	on Ref no: A51	
	Card N			
Ward:V			11 11 mather	
		. 1760	A SIL	
			ot Area : 1675.59	
			rea : 4590	all of more to fit
Contraction of the second			January, 2013	man a lines a fri
			d by : Aneri S, Adele Z	1 1 mar / / //
		Review	v by : Shraddha B.	A A A
- E			s above Ext: As above	
-		Photo	Ref : A51 RIVIERA a-f	the second secon
1.0			DENOMINATION	
1.1	Name of Premises		Riviera	
1.2	Earlier Name		Not applicable	
1.3	Built In:1940's		Extension Date(if any): Not App	blicable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose	Road
2.2	Subsidiary		Madam Cama Road	
3.0			OWNERSHIP PATTERN	
3.1	Present		New Riviera Co-Operative Housing Society Ltd. The Governor Of Bombay, Rawal Sangram Singhji, Rani Roopraj	
3.2	Past		5	vai Sangram Singnji, Rani Roopraj
3.3	Ctotuc		Laxmi	
3.3	Status		Central Government	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra	
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with	
			adequate light and ventilation. I	
			windows of the buildings open i	into.
				ding shows a rounded corner along
			the junction of the main and subsidiary road. The front façade shows	
			curved balconies projecting out and the windows have long	
			continuous chajja over them. The balconies on the side and rear	
				ws on the rear façade are recessed
			with no chajjas.	now a curved well around the
			The ground floor apartments show a curved wall around the entrance to the apartment. A typical feature of a spiral service	
			staircase at the rear side of the	
5.3	Intrinsic			its era. The various Art Deco style
0.0				ed lands created a cohesive image.
				ir time represented the new face of

Interview Interview 5.4 Value Classification Under Marine Drive Heritage Precinct 5.4 Value Classification Under Marine Drive Heritage Precinct 6.0 TOPOGRAPHY 6.1 Floors G+5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Open well wooden staircase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded comer and curved balconies 7.8 Flinishes Walls: Externally and internally cement plastered and painted(Ur renovation) 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound/wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out BetST 8.1 Lighting Natural and aritificial, good natural lighting <t< th=""><th>A 5 1</th><th>RIVIERA</th><th></th></t<>	A 5 1	RIVIERA	
and precincts symbolized the shift in expression to represent contemporary aspirations. 5.4 Value Classification Under Marine Drive Heritage Precinct 6.0 TOPOGRAPHY 6.1 Floors G-5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C. floor slab 7.4 Stairs Open well wooden staircase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovalion) Flooring: Marble flooring in the lobby Staircases: Wooden polished 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtlege/ Unbuilt space/out balteriate. Parking sheds at the rear side of the building. 8.1 Lighting Natural and artificial, good natural lighting <			the city and an expression of power, so did the Art Deco buildings
contemporary aspirations. 5.4 Value Classification Under Marine Drive Heritage Precinct 6.0 TOPOGRAPHY 6.1 Floors G+5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C. floor slab 7.4 Stairs Open well wooden staircase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and Internally cement plastered and painted(Ur renovation) Flooring: Marbie flooring in the lobby Staircases: Wooden polished Staircases: Wooden polished 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landiscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES			
5.4 Value Classification Under Marine Drive Heritage Precinct 6.0 TOPOGRAPHY 6.1 Floors G+5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Open well wooden staircase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded comer and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out building. Parking sheds at the rear side of the building. buildings/landscape SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Not provided 8.3 Drainage (Plumbing and sanitation) MCGM 8.4 Water Supply McGM 8.5 Drainage (Plumbing and sanitation) <td></td> <td></td> <td></td>			
Interiors Image: Construction 6.0 File 7.0 CONSTRUCTION 7.1 Plinth 7.2 Walls 7.3 Floor 7.4 Stairs 7.5 Open ingli wooden staircase 7.6 Roofing 7.7 Articulation 7.8 Finishes 8 Finishes 9 Interiors(Movable & Immovable) 9 Interiors(Movable & Immovable) 9 Interiors(Movable & Immovable) 7.1 Compound/Fence/Gate 7.10 Compound/Fence/Gate 7.11 Curtilege/ Unbuilt space/out buildings/landscape 7.11 Curtilege/ Unbuilt space/out building 7.11	5.4	Value Classification	Under Marine Drive Heritage Precinct
6.1 Floors G+5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Open well wooden staircase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovalion) Flooring: Marble flooring in the lobby Staircases: Wooden polished 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtileg/ Unbuilt space/out building. Parking sheds at the rear side of the building. buildings/landscape Exervices & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST			<u> </u>
7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C. floor slab 7.4 Stairs Open well wooden frames and glazed shutters 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) Flooring: Marble flooring in the lobby Staircases: Wooden polished Staircases: Wooden polished 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES Electricity 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4	6.0		TOPOGRAPHY
7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Open well wooden staircase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) Flooring: Marble flooring in the lobby Staircases: Wooden polished Staircases: Wooden polished 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out Parking sheds at the rear side of the building. 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) Mot good 8.6	6.1	Floors	G+5
7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Open well wooden staicase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) Flooring: Marble flooring in the lobby Staircases: Wooden polished Staircases: Wooden polished 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out Parking sheds at the rear side of the building. 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) Mot provided 8.6			
7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Open well wooden staircase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) Flooring: Marble flooring in the lobby Staircases: Wooden polished 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES 8.1 8.1 Lighting Natural and artificial, good natural lighting 8.2 Veniliation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution	7.0		CONSTRUCTION
7.3 Floor R.C.C. floor slab 7.4 Stairs Open well wooden staircase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out building. Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES Statural and artificial, good natural lighting 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) McGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided <t< td=""><td>7.1</td><td>Plinth</td><td></td></t<>	7.1	Plinth	
7.4 Stairs Open well wooden staircase 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) Flooring: Marble flooring in the lobby Staircases: Wooden polished 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES Entrance canopy and entrance porch steps 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided	7.2	Walls	Brick masonry wall
7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 9.0 CONDITION Parking 9.1 Plinth Good 9.2 Walls Good 9.4 Stairs Good 9.5 Openings <td>7.3</td> <td>Floor</td> <td>R.C.C. floor slab</td>	7.3	Floor	R.C.C. floor slab
7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Waler Supply MCGM 8.5 Drinage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.1 Plinth Good 9.2 Walls Good 9.3 Floor Good 9.4 Stairs Good 9.5 Openings Good 9.6 Roofing Good	7.4	Stairs	Open well wooden staircase
7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.1 Plinth Good 9.2 Walls Good 9.3 Floor Good 9.4 Stairs Good 9.5 Openings Good 9.7 Articulation & Finishes Good <td>7.5</td> <td>Openings</td> <td>Regular openings with wooden frames and glazed shutters</td>	7.5	Openings	Regular openings with wooden frames and glazed shutters
7.7 Articulation Rounded corner and curved balconies 7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.1 Plinth Good 9.2 Walls Good 9.3 Floor Good 9.4 Stairs Good 9.5 Openings Good 9.7 Articulation & Finishes Good <td></td> <td></td> <td></td>			
7.8 Finishes Walls: Externally and internally cement plastered and painted(Ur renovation) 7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.0 CONDITION Good 9.1 Plinth Good 9.2 Walls Good 9.3 Floor Good 9.4 Stairs Good 9.5 Openings Good 9.6 Roofing Good 9.7 Articulat			
renovation) Flooring: Marble flooring in the lobby Staircases: Wooden polished7.9Interiors(Movable & Immovable)Entrance canopy and entrance porch steps7.10Compound/Fence/GateCompound wall is plastered brick wall. Original M.S. gates.7.11Curtilege/ Unbuilt space/out buildings/landscapeParking sheds at the rear side of the building.8.0SERVICES & UTILITIES8.1LightingNatural and artificial, good natural lighting8.2VentilationNatural and artificial, good natural lighting8.3ElectricityBEST8.4Water SupplyMCGM8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood			
Flooring: Marble flooring in the lobby Staircases: Wooden polished7.9Interiors(Movable & Immovable)Entrance canopy and entrance porch steps7.10Compound/Fence/GateCompound wall is plastered brick wall. Original M.S. gates.7.11Curtilege/ Unbuilt space/out buildings/landscapeParking sheds at the rear side of the building.8.0SERVICES & UTILITIES8.1LightingNatural and artificial, good natural lighting8.2VentilationNatural and artificial, good natural lighting8.3ElectricityBEST8.4Water SupplyMCGM8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.19.1PlinthGood9.2WaltsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood	7.8	Finishes	
7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.0 CONDITION Parking Good 9.1 Plinth Good 9.2 Walls Good 9.3 Floor Good 9.4 Stairs Good 9.5 Openings Good 9.4 Stairs Good 9.5 Openings Good 9.6 Rofing Good 9.7			
7.9 Interiors(Movable & Immovable) Entrance canopy and entrance porch steps 7.10 Compound/Fence/Gate Compound wall is plastered brick wall. Original M.S. gates. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.0 CONDITION 9.1 9.1 Plinth Good 9.2 Walls Good 9.3 Floor Good 9.4 Stairs Good 9.5 Openings Good 9.4 Stairs Good 9.5 Openings Good 9.6 Roofing Good 9.7 </td <td></td> <td></td> <td></td>			
7.10Compound/Fence/GateCompound wall is plastered brick wall. Original M.S. gates.7.11Curtilege/ Unbuilt space/out buildings/landscapeParking sheds at the rear side of the building.8.0Parking sheds at the rear side of the building.8.0SERVICES & UTILITIES8.1LightingNatural and artificial, good natural lighting8.2VentilationNatural and artificial, good natural lighting8.3ElectricityBEST8.4Water SupplyMCGM8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.19.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood			Staircases: Wooden polished
7.10Compound/Fence/GateCompound wall is plastered brick wall. Original M.S. gates.7.11Curtilege/ Unbuilt space/out buildings/landscapeParking sheds at the rear side of the building.8.0Parking sheds at the rear side of the building.8.0SERVICES & UTILITIES8.1LightingNatural and artificial, good natural lighting8.2VentilationNatural and artificial, good natural lighting8.3ElectricityBEST8.4Water SupplyMCGM8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.19.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood	7.0	Interiors (Mayable & Immoyable)	Entrance canony and entrance nerch stone
7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building. 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.0 CONDITION 9.1 Plinth Good 9.2 Walls Good 9.3 Floor Good 9.4 Stairs Good 9.5 Openings Good 9.4 Stairs Good 9.5 Openings Good 9.6 Roofing Good 9.7 Articulation & Finishes Good			
buildings/landscapeConstruction8.0SERVICES & UTILITIES8.1LightingNatural and artificial, good natural lighting8.2VentilationNatural and artificial, good natural lighting8.3ElectricityBEST8.4Water SupplyMCGM8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood		•	
8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.0 CONDITION 9.1 Plinth Good 9.2 Walls Good 9.3 Floor Good 9.4 Stairs Good 9.5 Openings Good 9.6 Roofing Good 9.7 Articulation & Finishes Good	7.11		Parking sheds at the rear side of the building.
8.1LightingNatural and artificial, good natural lighting8.2VentilationNatural and artificial, good natural lighting8.3ElectricityBEST8.4Water SupplyMCGM8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood		buildings/landscape	
8.1LightingNatural and artificial, good natural lighting8.2VentilationNatural and artificial, good natural lighting8.3ElectricityBEST8.4Water SupplyMCGM8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood	0.0		
8.2VentilationNatural and artificial, good natural lighting8.3ElectricityBEST8.4Water SupplyMCGM8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood		Lighting	
8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.0 CONDITION 9.1 Plinth Good 9.2 Walls Good 9.3 Floor Good 9.4 Stairs Good 9.5 Openings Good 9.6 Roofing Good 9.7 Articulation & Finishes Good			
8.4Water SupplyMCGM8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0			
8.5Drainage (Plumbing and sanitation)MCGM8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0			
8.6Fire PrecautionNot provided8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood			
8.7Other (HVAC/BMC/Security Systems)Not provided9.0CONDITION9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood			
9.0CONDITION9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood			
9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood	0.1		
9.1PlinthGood9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood	9.0		CONDITION
9.2WallsGood9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood		Plinth	
9.3FloorGood9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood			
9.4StairsGood9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood			
9.5OpeningsGood9.6RoofingGood9.7Articulation & FinishesGood			
9.6 Roofing Good 9.7 Articulation & Finishes Good			
9.7 Articulation & Finishes Good			
9.9 Outbuildings Good			
9.10 Overall Condition Good			

A 5 1	RIVIERA	
10.0		TRANSFORMATION
10.1	Form	No transformation
10.2	Structure	No transformation
10.3	Articulation & Finishes	(Under renovation)
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A51 RIVIERA









(b)




(d)



A 5 2	SHALIMAR APARTMENTS			
A J Z		Comm	non Ref no: A52	12 1 1 1 1 1 1 1 1 1
NH.			Ward A	- Added the second
25			D. : 1759	Nor and
			rea : 1693.15	+ Mild Man port
1	AND THE CENT		rea : 4926	hope the the first of the
0	A ROZENSE AND		January, 2013	the second second
	THE PERSON AND AND AND AND AND AND AND AND AND AN		d by : Aneri S, Adele Z	A HANNEL IN
in name	Children - marses and bloor mer same		w by : Shraddha B.	- A A A A
			s above Ext: As above	of the set of the
K has	Still I I I I I I I I I I I I I I I I I I		Ref : A52 SHALIMAR a –f	A DESTRUCTION
1.0			DENOMINATION	
1.1	Name of Premises		Shalimar apartments	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date(if any): Not Ap	plicable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose	Road
2.2	Subsidiary		Babubhai M. Chinai Marg	
3.0			OWNERSHIP PATTERN	
3.1	Present		Rikhiram Tulsiram Arora, Rame	eshkumar Tulsiram Arora
3.2	Past		The Governor of [Bombay] Mal	harashtra, Nathumal Shorimal,
			Tulsiram Nathumal Rangwala	
3.3	Status		Tenanted	
4.0			USE	
4.1	Present			ne subsidiary road taken over by
			Srinivas Motors)	
4.2	Past		Residential	
4.3	Usage		Regular in mixed used	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandr	
5.2	Architectural Description		Planning: It is a large building i	in modest art Deco style with
			adequate light and ventilation.	Iding is hovegonal around the junction
				Iding is hexagonal around the junction
			of the main and subsidiary road. The front façade shows no balconies but long continuous chajjas over the windows. The	
				ular balconies on the side and rear
				hajjas over the windows on these
			facades.	
5.3	Intrinsic			its era. The various Art Deco style
0.0				ed lands created a cohesive image.
				ir time represented the new face of
				ower, so did the Art Deco buildings
			and precincts symbolized the s	
			contemporary aspirations.	

A 5 2	SHALIMAR APARTMENTS		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Dog legged wooden staircase with M.S. railing on the ground floor and original wooden railing from first floor onwards.	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Hexagonal corner	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Ceramic tiles in the lobby Staircases: Wooden Polished	
7.9	Interiors(Movable & Immovable)	Entrance canopy	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room, temporary sheds, and water tank. Ramp for Srinivas motors and parking for the shop.	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
0.7			
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Fair(exterior walls need painting and repairs)	
9.3	Floor	Good	
9.4	Stairs	Poor(Shaky, needs structural repairs and polishing)	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Poor(Needs painting)	
9.8	Services	Fair (Needs cleaning and repairs)	
9.9	Outbuildings	Poor(Needs cleaning and repairs)	
9.10	Overall Condition	Fair	

SHALIMAR APARTMENTS	
	TRANSFORMATION
Form	Additional box grills , A.C.P. canopies and chajjas , Balconies enclosed
Structure	No transformation
Articulation & Finishes	No major transformation
DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	Form Structure Articulation & Finishes DPREMARKS/PERCEIVEDTHREATS ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR



A 5 3	SHANTI KUTEER			
-A33	SHANTI KOTLEK	Commo	n Ref no: A53	Maport & VI
Bar		Card No		and the state of t
		Ward :V		- Ce
205		CS No.		support of an fil
THE PARTY			ea : 1658.87	E Martine The
16 TA		B U Are		Har I June / T
			anuary, 2013	
and de			by : Aneri S, Adele Z	- 1
			by : Shraddha B.	Harry //
		Int : As		
			Ref : A53 SHANTI KUTEER	and the
		a-f		
1.0			DENOMINATION	
1.1	Name of Premises		Shanti Kuteer	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1950's		Extension Date(if any): Not A	Applicable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bo	se Road
2.2	Subsidiary		Babubhai M. Chinai Marg	
2.0				N
3.0	Drocont		OWNERSHIP PATTER	
3.1 3.2	Present Past		Ramnarain Sons Private Ltd Subtadevi Ramnarayan, Rar	
J.Z	FdSI		Dadhekrishna Damnarayan	& Madan Mohan Ramnarain
			Ruia & Sushilkimar Ramnara	avan Ruia
3.3	Status		Co-operative Housing Socie	2
0.0				. <u>,</u>
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VAL	
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Char	
5.2	Architectural Description			g in modest Art Deco style with
			adequate light and ventilatio	
			interior windows of the buildi	
				building shows a rounded corner
				n and the subsidiary road. The
				es projecting out. The windows
				s over them. The balconies and the side and the rear facades
5.3	Intrinsic			the side and the rear facades. ng its era. The various Art Deco
0.5			style buildings on the newly	
			cohesive image. Like the Go	
				the city and an expression of
			power, so did the Art Deco b	
L	4			

A 5 3	SHANTI KUTEER	
7100		symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with granite cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters Flat roof and terrace
7.6 7.7	Roofing Articulation	
7.7	Finishes	Rounded balconies           Walls: Externally and internally cement plastered and
1.0	FILISHES	painted
		Flooring: Marble flooring
		Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates
///0		are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room,
		temporary sheds, water tank
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Video surveillance( independent air conditioning units in the
		houses)
0.0		
9.0	Dlinth	CONDITION
9.1 9.2	Plinth Walls	Good
		Good
9.3 9.4	Floor Stairs	Good Good
9.4 9.5		Good
9.5	Openings Roofing	Good
9.0 9.7	Articulation & Finishes	Good
9.7	Services	Good
9.0	Outbuildings	Good
9.10	Overall Condition	Good
7.10		

A 5 3	SHANTI KUTEER	
10.0		TRANSFORMATION
10.1	Form	Railing changed, Additional box grills
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps- Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

### A53 SHANTI KUTEER



(C)



(b)



(d)







A53-iv

A 5 4	OCEANA			
A 3 4		Comm	on Ref no: A54	
1/200	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			our francisco and the
MOV-APRIL THE MEDICAL STREET		Card N	Ward A	
		CS No.		A.
			ea : 1482.44	1 f of more and 5.1
			ea : 3870	log of what start of
Same S			January, 2013	AL "HI
15 22			I by : Aneri S, Adele Z	the l.
			<i>i</i> by : Shraddha B.	
S and			above Ext: As above	stand to F
mmi			Ref : A54 OCEANA a-d	Mane. Callet
1.0			DENOMINATION	
1.1	Name of Premises		Oceana	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1939		Extension Date(if any): Not Appl	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose F	Road
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Rohini Kundanlal Gupta, Mohini Kundanlal Gupta	
3.2	Past		The Governor Of Bombay, Kunc	Ianlal Laxmichand Gupta, Sita
			Kundanlal Gupta,	
3.3	3 Status		Tenanted	
1.0				
4.0 4.1	Present		USE Residential	
4.1	Past		Residential	
4.2			Regular in residential use	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			Bose road front, which is one of the
0.1			major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with	
0.2			adequate light and ventilation. It	
			windows of the buildings open ir	
				ling shows recessed balconies on
				es on the side façade and polygonal
			balconies on the rear façade. The building shows a spiral service	
			staircase on the rear façade.	
5.3	5.3 Intrinsic			s era. The various Art Deco style
				d lands created a cohesive image.
				time represented the new face of
				wer, so did the Art Deco buildings
			and precincts symbolized the sh	in in expression to represent
<b>Б</b> 4	Value Classification		contemporary aspirations.	acinct
5.4	Value Classification		Under Marine Drive Heritage Pre	CITICI

A 5 4	OCEANA	
-734		
6.0		TOPOGRAPHY
6.1	Floors	G+5
0.1		
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
		·····g······ g·······g·······
7.6	Roofing	Flat roof and terrace
7.7	Articulation	
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Wooden polished
		·
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.
		gates (original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room, planters
	buildings/landscape	
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good(exterior walls need painting)
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
0 (	Desfine	Coord
9.6	Roofing	Good
9.7	Articulation & Finishes	Average(Needs painting)
9.8	Services	Good
9.9	Outbuildings	Average(Shows cracks needs reapairs)
9.10	Overall Condition	Good

A 5 4	OCEANA	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

# A54 OCEANA



(b)



(C)



A 5 5	HOTEL MARINE PLAZA		
		Comm	ion Ref no: A55
		Card N	No.:
			Ward A
			0. 1642
			rea: 1752.53
			rea : 5820
	Date :		January, 2013
			d by : Aneri S, Adele Z
			w by : Shraddha B.
maine			s above Ext: As above
			Ref : A55 HOTEL MARINE
		PLAZ	
1.0			DENOMINATION
1.0	Name of Premises		Hotel Marine Plaza
1.2	Earlier Name		Chambers De Luxe Hotel
1.3	Built In : 1940's		Extension Date(if any): Not Applicable
2.0			ACCESS ROADS
2.1	Main		Netaji Subhash Chandra Bose Road
2.2	Subsidiary		Dinshaw Watcha road
2.2			
3.0			OWNERSHIP PATTERN
3.1	Present		Dr.Latif R.Patel and Dr.Rahim H.Muljiani
3.2	Past		The Governor Of Bombay, Ahmed Habib, Mahomedalli Habib,
0.2			Dawood Habib, Gulamalli Habib, Yusufbhai Cassum Mitha, Ebrahim
			Navrozali, Rajabali P.Ebrahim, Salimbhai Haji Mahomed, Rasool
			Abdulla Raqoonwalla, Ashraf Dharamsey, Habibbhai Huseinali
			Cassam Mitha, Esmail Abdulkarim Panjoo, Rajabali P.Ebrahim,
			Rasul A.Rangoonwala, Habibbhai Huseinally Cassam Mitha,
			Habibbhai Cassam Chinwala, Fazal A.Fazalbhoy, Hoosainali
			G.Merchantm, Mrs.Zarina E.Currimbhoy, Mrs.Goolbanu M.Hashaw
			Premji, Masumali Jafferali Merchant, Hajir Husain Vazirali, Noorally
			Sherally Merchant, Sultan Alladin Nathani, Mohamedali Gulamali
			Karmali, Ahmedali M.Merchant, Smt.Rukaya S.Dossal
3.3	Status		Private
4.0			USE
4.1	Present		Commercial
4.2	Past		Commercial
4.3	Usage		Regular in commercial use
5.0			SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra Bose road front.
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with
			adequate light and ventilation.
			Stylistic Classification: The building is curved along the junction of
			the main and subsidiary road. The building shows glass cladding all
			over it. The interiors of the building are still retained. The building

A 5 5	HOTEL MARINE PLAZA		
		shows plain articulation on the façade facing the main road.	
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations.	
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.1	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Access Denied	
7.5	Openings	Access Denied	
7.6	Roofing	Access Denied	
7.7	Articulation	Curved corner	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Access Denied Staircases: Access Denied	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Provided	
8.7	Other (HVAC/BMC/Security Systems)	HVAC provided	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	

A 5 5	HOTEL MARINE PLAZA		
10.0		TRANSFORMATION	
10.1	Form	No transformation	
10.2	Structure	No transformation	
10.3	Articulation & Finishes	No transformation	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP	
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995	





(C)





A 5 6	ST.JAMES COURT			
- 730		Comm	non Ref no: A56	
(iii)	Card			I may contract
			: Ward A	and a second
111				All start
Plot A		rea : 2316.9	full the state of the	
		B U A		1041 /044
			January, 2013	Aler No 20
			d by : Aneri S, Adele Z	CAN DE BBR OWN
			w by : Shraddha B.	and
HIRING	CHILDREE TO A THE PROPERTY OF		s above Ext: As above	0 MM 44 0 MM
			Ref : A56 ST.JAMES COURT	and the second second
		a-f	Rei . ASO ST.JAIVIES COURT	2
1.0		a-1	DENOMINATION	
1.0	Name of Premises		St. James Court	
1.1	Earlier Name		Not applicable	
1.2	Built In : 1940's		Extension Date(if any): Not Appl	licablo
1.3	Dunit III . 1740 S		LATCHSION DATE(II ANY). NOT APPI	แบลมเซ
2.0			ACCESS ROADS	
2.0	Main		Netaji Subhash Chandra Bose F	Soad
2.2	Subsidiary		Dinshaw Watcha Road	
2.2				
3.0			OWNERSHIP PATTERN	
3.1	Present		Brijbehari Lachhmandas Nayer & Jagdishmohan Lachhmandas	
0.1			Nayer	
3.2	Past		The Governor Of Bombay, Kanh	navalal Lachhmandas Naver.
			Kahanchand Lachhmandas Nay	
			Nayer, Janakraj Lachhamandas	
3.3	Status		Tenanted	<u> </u>
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Residential	
4.3	Usage		Regular in mixed use	
			-	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra Bose road front, which is one of the	
			major North-South arterial roads	5.
5.2	Architectural Description		Planning: It is a large building in	modest Art Deco style with
			adequate light and ventilation. It	
			windows of the buildings open in	
				orner along the main and subsidiary
			roads. The building shows curve	
				rectangular carved feature is seen
				atures like curved chajja are seen on
			the façade. Original grills are ma	
			round corner and polygonal balc	
5.3	Intrinsic			ts era. The various Art Deco style
			buildings on the newly reclaimed	d lands created a cohesive image.


A 5 6	ST.JAMES COURT	
		Like the Gothic buildings in their time represented the new face of
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
<b>F</b> 4		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with cement terrazzo with aluminum nosing strip on it
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Polygonal balconies over a rounded corner.
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble in the lobby
		Staircases: Cement terrazzo
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall ; Gates are M.S. gates
		(original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,
	buildings/landscape	temporary sheds, water tank
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
_		
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good

ST.JAMES COURT		
	TRANSFORMATION	
Form	Additional box grills , A.C.P. chajjas , balconies enclosed	
Structure	No transformation	
Articulation & Finishes		
DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP	
ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995	
	Form Structure Articulation & Finishes DPREMARKS/PERCEIVEDTHREATS ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR	

# A56 ST.JAMES COURT








(e)







A57 FRAN			
		non Ref no: A57	
14	Card		
		:Ward A	
		p. 1640	
		rea : 1853.69	
Sector of the se		rea: 5154	
		: January, 2013	
		d by : Aneri S, Adele Z	
and the second	Revie	w by : Shraddha B.	
the states		s above Ext: As above	
		Ref : A57 FRAMROZE COURT	
	a-f		
1.0		DENOMINATION	
	of Premises	Framroz Court	
1.2 Earlier	Name	Earl's Court	
1.3 Built In:	1940's	Extension Date(if any): Not Applicable	
2.0			
2.0		ACCESS ROADS	
2.1 Main		Netaji Subhash Chandra Bose road	
2.2 Subsidi	ary	Not applicable	
3.0		OWNERSHIP PATTERN	
3.1 Present	ł	Advani & Watumal	
3.2 Past	l	The Governor Of Bombay, His Highness Maharaval, Shri	
J.Z FASI		Natwarsinhji Fatehsinhji Of Chhotta Udepur, Phirozshaw Maneckji	
		Framroz, The Central Bank Executor & Trustee Company Ltd, Miss	
		Roda Framroz, Mr.Dara Nadershaw Sabawala, Bomanji Kavasji	
		Boman-Behram, Dr.Aspi Framroze Colwalla, Dr.(Miss) Nelie	
		Rustomji, Nomble Jamshed Nusserwanji Guzder, Erach Byramsha	
		Desai, Manekji Bejonji Hodiwalla	
3.3 Status		Tenanted	
4.0		USE	
4.1 Present	t	Residential	
4.2 Past		Residential	
4.3 Usage		Regular in residential use	
5.0		SIGNIFICANCE & VALUE CLASSIFICATION	
	cape(Natural/Manmade)	Part of Netaji Subhash Chandra Bose road front, which is one of the	
		major North-South arterial roads.	
5.2 Archited	ctural Description	Planning: It is a large building in modest Art Deco style with	
		adequate light and ventilation. It has a void where the interior	
		windows of the buildings open into.	
		Stylistic Classification: The building shows small curved balconies	
		on the front façade, Other features like polygonal balconies and	
		curved chajja are seen on the side facades. On the right side of the	
		building above the entrance canopy rectangular panels with typical	
		Art Deco carvings are seen. The original nameplates and grills are	

A 5 7	FRAMROZ COURT		
1107		retained. The rear façade shows large curved balconies	
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations.	
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well stone staircase with granite cladding	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Marble flooring in the lobby Staircases: Granite Cladding	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room, temporary sheds, water tank	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided	
9.0		CONDITION	
9.0 9.1	Plinth	Good	
9.1 9.2	Walls	Good Good Good Good Good Good Good Good	
9.2	Floor	Good Good	
9.3 9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.0	Articulation & Finishes	Good	
9.8	Services	Good	
9.0 9.9	Outbuildings	Good	
7.7	Toumululitys	0000	

FRAMROZ COURT	
Overall Condition	Good
	TRANSFORMATION
Form	Additional box grills , chajjas, balconies enclosed
Structure	No transformation
Articulation & Finishes	
DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	Form Structure Articulation & Finishes DPREMARKS/PERCEIVEDTHREATS ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR

# A57 FRAMROZ COURT



(b)



(d)





(e)

(C)



A 5 8	SEA GREEN HOTEL			
- 7.50		Commo	on Ref no: A58	1 Andre 1
	11 Martin Contraction	Card No		mo om
	Es al	Ward : V		for state one
		CS No.		1/00/ 00/17
1			ea : 1682.28	NI Brid
4			ea : 4992	Infrance Transit vi 15
-			a . 4992 Ianuary, 2013	I mal Plor No 204 0 /offi
			by : Aneri S, Adele Z	Sea Green and
20.7			by : Shraddha B.	- In long
			above Ext: As above	and for the former of the
4			Ref : A58 SEAGREEN a-f	
1.0			DENOMINATION	
1.1	Name of Premises		Sea Green Hotel	
1.2	Earlier Name		Not applicable	
1.3	Built In 1947, (1930's)		Extension Date(if any): Not	Applicable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bos	se road
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	J
3.1	Present		Pesi K.Sidhwa	
3.2	Past			estonji Fallirji Sidhwa, Pallonji
				nji Sidhwa, Kaikhushru Pallonji
			Sidhwa, Pilloo W/O Kaikhush	
			Kaikhushroo Sidhwa, Pilloo K	K.Sidhwa, Soonita K.Sidhwa
3.3	Status		Private	
4.0			USE	
4.1	Present		Commercial	
4.2	Past		Commercial	
4.3	Usage		Regular in Commercial use	
5.0			SIGNIFICANCE & VAL	UE CLASSIFICATION
5.1	Townscape(Natural/Manmade)			indra Bose road front, which is
			one of the major North-South	
5.2	Architectural Description			g in modest Art Deco style with
			adequate light and ventilation	
			interior windows of the building	
			Small rectangular balconies	
			building. Long continuous ch	
			Original grills and gates are s	
5.3	Intrinsic			ng its era. The various Art Deco
			style buildings on the newly r	
			cohesive image. Like the Go	
				the city and an expression of
			power, so did the Art Deco b	
			symbolized the shift in expre	ssion to represent

A 5 8	SEA GREEN HOTEL		
100		contemporary aspirations.	
5.4	Value Classification	Under Marine Drive Heritage Precinct	
0.1			
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation		
1.1			
7.8	Finishes	Walls: Externally and internally cement plastered and	
7.0		painted	
		Flooring: Ceramic tiles in the lobby	
		Staircases: Wooden polised	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room,	
		temporary sheds, water tank	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	HVAC for the hotel rooms.	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	

A 5 8	SEA GREEN HOTEL	
10.0		TRANSFORMATION
10.1	Form	No transformation
10.2	Structure	No transformation
10.3	Articulation & Finishes	Recently painted
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps- Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

# A58 SEA GREEN HOTEL



(b)



(d)



(e)

SEA CREEN

केडएबस Fec



A 5 9	SOONA MAHAL			
		Comm	non Ref no: A59	
Card Ward CS N Plot A				and the second s
				la station and
				ALM MAIN OF
				of from for
			rea : 1769.24	In I star 19 #
in the second	A DEC MAN		rea: 5572	/ / / / / / / / / / / / / / / / / / /
1.2.2	AND AND AND AND AND A REAL PROPERTY AND		January, 2013	1 9 Less for
			d by : Aneri S, Adele Z	Merna 200 - B
			w by : Shraddha B.	the way and
	THE REPORT OF A PARTY	-	s above Ext: As above	toring the second
The deal		Photo	Ref: A59 SOONA MAHAL a-e	m en 11
1.0			DENOMINATION	
1.1	Name of Premises		Soona Mahal	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	oad
2.2	Subsidiary		Veer Nariman Road	
3.0			OWNERSHIP PATTERN	
3.1	Present		Soona Mahal Cooperative Housing Society Limited	
3.2	Past			arashtra, Sorabji Cowasji Sidhwa,
0.2				zonji Cowasji Sidhwa, Framroze
			Cowasji Sidhwa, Kaikhusroo Co	
				a, Executors Executrix & Trustees of
			The Last Will Of Cowasji Fakirji	
3.3	Status		Co-operative Housing Society	
			·	
4.0			USE	
4.1	Present		Mixed use	
4.2	Past		Residential	
4.3	Usage		Regular in mixed use	
1.0				
5.0	+		SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
5.1	10Wilsedpe(Natara/Malimade)		major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in	
0.2	Alemeetalar Description		adequate light and ventilation. It	
			windows of the buildings open in	
				ling shows a rounded corner along
				subsidiary road. There are recessed
				cade of the building. The building
				hajjas and nameplates. The rear
			façade of the building shows rec	
			Concrete spiral service staircase	
			building.	
5.3	Intrinsic			ts era. The various Art Deco style
0.0	manific		, at Dood building representing it	is oral the validas Art Deco style

A 5 9	SOONA MAHAL	
1107		buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary appirations
5.4	Value Classification	contemporary aspirations. Under Marine Drive Heritage Precinct
0.4		
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded corner
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Marble flooring in the lobby Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall Gates are M.S. gates (original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, meter room, temporary sheds, and water tank. HVAC for the restaurant, plants (pots) in the compound.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)HVAC for the restaurant
9.0		CONDITION
9.0	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Needs cleaning

A 5 9	SOONA MAHAL	
9.10	Overall Condition	Good
10.0 10.1	Form	TRANSFORMATION Additional box grills , A.C.P. canopies and chajjas , enclosed balconies.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

#### A 5 9 SOONA MAHA





(C)



A 6 0	SUNDER MAHAL	
7.00		mmon Ref no: A60
		rd No:
		ard: Ward A
		S No. 1687
A		ot Area : 1398.0
		J Area : 4144
- Artes		te : January, 2013
1 Cont		cord by : Aneri S, Adele Z
		view by : Shraddha B.
ALC: NOT A		: As above Ext: As above
0.0		oto Ref : A60 SUNDER MAHAL a-e
1.0		DENOMINATION
1.1	Name of Premises	Sunder mahal
1.2	Earlier Name	Not applicable
1.3	Built In: 1930's	Extension Date(if any): Not Applicable
2.0		ACCESS ROADS
2.1	Main	Netaji Subhash Chandra Bose road
2.2	Subsidiary	Veer Nariman road
3.0		OWNERSHIP PATTERN
3.0	Dracant	Shri Nari W.Dalamal
3.1	Present	
3.2	Past	The Governor Of Bombay, Tekchand Charandass Verma, Kaushalyadevi Tekchand Verma, Wadhumal Dalamal, Smt.Bhagwati
		W.Dalamal, Smt.Chandra S.Dalamal, Shri Sunder W.Dalamal, Shri
		Ghanshyam W.Dalamal
3.3	Status	Tenanted
5.5		
4.0		USE
4.1	Present	Mixed use
4.2	Past	Mixed use( Iran Air, Etihad airlines, Baskin robins)
4.3	Usage	Regular in mixed use
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Part of Netaji Subhash Chandra Bose road front, which is one of the
		major North-South arterial roads
5.2	Architectural Description	Planning: It is a large building in modest Art Deco style with
		adequate light and ventilation.
		Stylistic Classification: The building is curved along the junction of
		the main and subsidiary road. The façade of the building is flat
		facing the main road with shallow long continuous chajjas. The
		building has three gates right now.
		Original grills and compound wall maintained in few places. The rear
		façade and the façade on the left side of the building show small
		rectangular balconies.
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style
		buildings on the newly reclaimed lands created a cohesive image.
		Like the Gothic buildings in their time represented the new face of

A 6 0	SUNDER MAHAL	
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
( )		TOROCRADUV
6.0 6.1	Floors	TOPOGRAPHY G+6
0. I	Floors	G+0
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with granite cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Access Denied
		Staircases: Stone staircase with marble cladding
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall, New gates on the left side of
		the building.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,
	buildings/landscape	temporary sheds, water tank, Planters outside Iran air, seating for
		baskin robins, Steps leading towards the shops along the subsidiary road.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Average(Compound wall needs painting)
9.10	Overall Condition	Good
-		

SUNDER MAHAL		
	TRANSFORMATION	
Form	Additional box grills, Balconies enclosed, Additional canopies in the compound, Additional Steps for the shops, Compound wall broken down and opened for the seating and public entrance. Additional entrances and gates for different entries.	
Structure	No transformation	
Articulation & Finishes	No major transformation	
DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP	
ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995	
	Form Structure Articulation & Finishes DPREMARKS/PERCEIVEDTHREATS ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR	

# A60 SUNDER MAHAL





(C)







Δ61	PODAR HOUSE			
	TODAR HOUSE	Comm	non Ref no: A61	
		Card N		10
		Ward :Ward A		1 Para Pan and Pa
		CS No. 1688		OND IN THE
1				5 will all the
		Plot Area: 1281.77 B U Area: 3192		tinge a om
				Port No. to Bas
18			January, 2013	B " Our Mansion of
			d by : Aneri S, Adele Z	China Ind
			w by : Shraddha B.	if the the
1	Iller Bar All Hilling		s above Ext: As above	
1.0		Photo	Ref : A61 PODAR HOUSE a-e	
1.0	Nome of Dramiana		DENOMINATION	
	Name of Premises		Podar House	
1.2	Earlier Name		Podar Mansion	P 1.1.
1.3	Built In: 1940's		Extension Date(if any): Not App	nicadie
2.0	+			
2.0	Mala		ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	⁷ 080
2.2	Subsidiary		Sitaram Devra Marg (A road)	
0.0				
3.0			OWNERSHIP PATTERN	
3.1	Present		Podar Trading Company Private Limited	
3.2	Past		The Governor Of Bombay, Mes	srs.Podar Sons Pv.Ltd.]
3.3	Status		Tenanted	
1.0			1105	
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Mixed	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
5.0			major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in	
			adequate light and ventilation.	
			windows of the buildings open in	
				ding shows a rounded corner at the
				ary road, Balconies curve along the
				nain road. The structure has small
				hajjas on the curved corner of the
				building shows rectangular and
5.2			curved balconies which project	
5.3	Intrinsic			ts era. The various Art Deco style
				d lands created a cohesive image. r time represented the new face of
			the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent	
			contemporary aspirations.	
I				

A 6 1	PODAR HOUSE	
5.4	Value Classification	Under Marine Drive Heritage Precinct
0.1		
6.0		TOPOGRAPHY
6.1	Floors	G+6
011		
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with marble staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
	e por mige	
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Marble cladding
		5
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.
		gates (original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,
	buildings/landscape	temporary sheds, water tank
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good( needs cleaning)
9.10	Overall Condition	Good

A 6 1	PODAR HOUSE	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , Enclosed balconies, Grills for the A.C. units.
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

(b)

# A61 PODAR HOUSE

(a)



(d)



(C)



A / 0		
A 6 2	JYOTI SADAN	Common Define: A/2
		Common Ref no: A62
		Card No.:
		Ward: Ward A
	A CONTRACTOR OF	CS No. 1704
-		Plot Area : 1443.98
ST.		B U Area :
		Date : January, 2013
		Record by : Aneri S, Adele Z
1	THE R P P P P P P P P P P P P P P P P P P	Review by : Shraddha B.
Contraction of the	The state of the second second	Int : As above Ext: As above
-	the second second	Photo Ref : A62 JYOTI SADAN a-e
1.0		DENOMINATION
1.1	Name of Premises	Jyoti Sadan
1.2	Earlier Name	Not applicable
1.3	Built In: 1940's	Extension Date(if any): Not Applicable
2.0		ACCESS ROADS
2.1	Main	Netaji Subhash Chandra Bose road
2.2	Subsidiary	Sitaram Devra Marg (A road)
	,	
3.0		OWNERSHIP PATTERN
3.1	Present	J-M/S Bubna Trading Company Limited
3.2	Past	The Governor of Bombay, Gordhandas Kalidas, Nagardas Kalidas,
		Pranlalo Kalidas
3.3	Status	Tenanted
4.0		USE
4.1	Present	Mixed
4.2	Past	Mixed
4.3	Usage	Regular in mixed use
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Part of Netaji Subhash Chandra Bose road front, which is one of the
0.1		major North-South arterial roads.
5.2	Architectural Description	Planning: It is a large building in modest Art Deco style with
0.2		adequate light and ventilation.
		Stylistic Classification: The building corner curved along the junction
		of the main and subsidiary road. Projecting balconies on the façade
		facing the front road (most of them enclosed). The windows on the
		curved corner are small and show original chajjas over them.
		Balconies are seen on the left façade of the building.
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style
		buildings on the newly reclaimed lands created a cohesive image.
		Like the Gothic buildings in their time represented the new face of
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
L		1

A 6 2	JYOTI SADAN	
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5(additional apartment on the terrace level)
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with granite cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded corner
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Granite flooring in the lobby
		Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall, Gates are M.S. gates
		painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,
	buildings/landscape	temporary sheds, water tank, Steps leading to the shops on the
		ground floor.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good(exterior walls need painting)
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Average (Needs cleaning and repairs)
9.10	Overall Condition	Good

A 6 2	JYOTI SADAN	
10.0		TRANSFORMATION
10.1	Form	Additional box grills, Most of the balconies taken in completely and
		enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai,
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	AVAILABLE/RECOMMENDATIONS	
	& SUGGESTIONS FOR	
	IMPLEMENTATION	


A62 JYOTI SADAN



(b)



(C)



(d)



A 4 2				
A 6 3	INTERCONTINENTAL	Comm	$pon Dof no: \Lambda 62$	
		Comm Card N	non Ref no: A63	o ^{Aw}
				The second of th
			: Ward A	MH OM OM
			). 1705	
			rea : Not Available	The In I P
	Sold Land		rea : Not Available	Bonna Via
			January, 2013	Plot No 27 d BR
		Recor	d by : Aneri S, Adele Z	
			w by : Shraddha B.	A THE OTHER OTHER
			s above Ext: As above	-f
	(000ED)		Ref : A 63	
1.0		INTER	RCONTINENTAL a-d	
1.0			DENOMINATION	
1.1	Name of Premises		Intercontinental	
1.2	Earlier Name		Bombay Club	
1.3	Built In : 1990's		Extension Date(if any): Not App	blicable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	oad
2.2	Subsidiary		Pt. Shobhnath Mishra Marg	
			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
3.0			OWNERSHIP PATTERN	
3.1	Present		Not Available	
3.2	Past		Not Available	
3.3	Status		Not Available	
4.0			USE	
4.1	Present		Commercial	
4.2	Past		Commercial	
4.3	Usage		Regular in commercial use	
1.0				
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra major North-South road	Bose road front, which is one of the
5.2	Architectural Description		Planning: It is a large building in	modest Art Deco style with
0.2			adequate light and ventilation.	modest Art Dece style with
				ling is curved along the junction of
			the main and subsidiary road. The	
			constructed again but it follows t	
				facing the roads show glass cladding
				les facing the roads and along the
			curved corner are seen.	<u>.</u>
5.3	Intrinsic		The building complements the A	rt Deco buildings in the area.

A 6 3	INTERCONTINENTAL			
5.4	Value Classification	Under Marine Drive Heritage Precinct		
0.1				
6.0		TOPOGRAPHY		
6.1	Floors	G+7		
0.1				
7.0		CONSTRUCTION		
7.1	Plinth	Plastered masonry plinth		
7.2	Walls	Brick masonry wall		
7.3	Floor	R.C.C. floor slab		
7.4	Stairs	Access Denied		
7.5	Openings	Access Denied		
7.6	Roofing	Access Denied		
7.7	Articulation	Access Denied		
7.8	Finishes	Walls: Externally and internally cement plastered and painted		
		Flooring:		
		Staircases:		
7.9	Interiors(Movable & Immovable)	Entrance Foyer		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall		
7.11	Curtilege/ Unbuilt space/out			
	buildings/landscape			
8.0		SERVICES & UTILITIES		
8.1	Lighting	Natural and artificial, good natural lighting		
8.2	Ventilation	Natural and artificial, good natural lighting		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing and sanitation)	MCGM		
8.6	Fire Precaution	Provided		
8.7	Other (HVAC/BMC/Security Systems)	HVAC provided		
9.0		CONDITION		
9.1	Plinth	Good		
9.2	Walls	Good		
9.3	Floor	Good		
9.4	Stairs	Good		
9.5	Openings	Good		
9.6	Roofing	Good		
9.7	Articulation & Finishes	Good		
9.8	Services	Good		
9.9	Outbuildings	Good		
9.10	Overall Condition	Good		

A 6 3	INTERCONTINENTAL		
10.0		TRANSFORMATION	
10.1	Form	No transformation	
10.2	Structure	No transformation	
10.3	Articulation & Finishes	No transformation	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP	
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995	

A63 INTERCONTINENTAL





(C)



A 6 4	CHATEAU MARINE			
		Comp	non Ref no: A64	
		Conmon Remo. Add		- Burner
		Ward: Ward A CS No. 1717		A A
		Plot Area : 1501.68 B U Area: 4278		The Trans O
				Chateav Marine
D			January, 2013	1717 OMW 11
T STATES		Recor	d by : Aneri S, Adele Z	1 1 mar 13
			w by : Shraddha B.	
			s above Ext: As above	
nin Th			Ref : A64 CHATEAU MARINE	
		а-е		
1.0 1.1	Name of Premises		DENOMINATION Chotogy Maring	
			Chateau Marine	
1.2	Earlier Name		Not applicable	
1.3	Built In:1940's		Extension Date(if any): Not Applicable	
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose road	
2.2	Subsidiary		Pt. Shobhnath Mishra Marg	
2.2				
3.0			OWNERSHIP PATTERN	
3.1	Present		Satvashiladevi Shivramraje Bhosle	
3.2	3.2 Past		The Governor Of Bombay, His Highness Maharaja Sir Pratapsingh	
		Gaekwar Maharaja Of Baroda G.C.I.E.L.L.D.), His Highness		
			Maharaja Fatehsingh Gaekwar Of Baroda, Shantadevi Pratapsingh	
			Gaekawar, Dr.Mrunalinidevi Anandrao Paur, Pramilaraje	
			Shivrajkumar Kacher	
3.3	Status 1		Tenanted	
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Mixed	
4.3	Usage		Regular in mixed use	
5.0				
5.0	Townscone (Notural/Manmada)		SIGNIFICANCE & VALUE CLASSIFICATION Part of Netaji Subhash Chandra Bose road front, which is one of the	
5.1	1 Townscape(Natural/Manmade)		major North-South arterial roads.	
5.2	Architectural Description		Planning: It is a large building in	
			adequate light and ventilation. It has a void where the interior	
			windows of the buildings open in	
				ling has a curve the corner along the
				sidiary road. The front façade of the
			building shows rectangular balco	
				d of the façade. The building shows a
			carved feature on the mid landir	
			balconies are seen on the left si	
			balconies are seen on the rear f	
L	1			· , · · · · · · · · · · · · · · · · · ·

A64 CHATEAU MARINE 5.3 Intrinsic Art Deco building representing its era. The various Art Deco buildings on the newly reclaimed lands created a cohesive Like the Gothic buildings in their time represented the new the city and an expression of power, so did the Art Deco buildings on the newly reclaimed lands created a cohesive Like the Gothic buildings of the shift in expression to represe contemporary aspirations. 5.4 Value Classification Under Marine Drive Heritage Precinct 6.0 TOPOGRAPHY 6.1 Floors G+5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings Requilar openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring. Marble flooring in the lobby Staircases. Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound/Fence/Gate 7.1 Curtilege/ Unbuilt space/out building sheds at the rear side of the building,		
the city and an expression of power, so did the Art Deco bu and precincts symbolized the shift in expression to represe contemporary aspirations. 5.4 Value Classification Under Marine Drive Heritage Precinct 6.0 TOPOGRAPHY 6.1 Floors 7.0 CONSTRUCTION 7.1 Plinth 7.2 Walls 8.1 Brick masonry wall 7.3 Floor 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings 7.6 Roofing 7.7 Articulation 7.8 Finishes 7.9 Interiors(Movable & Immovable) 7.10 Compound/Fence/Gate 7.9 Interiors(Movable & Immovable) 7.10 Compound/Fence/Gate 7.11 Curtilege/ Unbuilt space/out buildings/landscape tank 8.0 SERVICES & UTILITIES 8.1 Lighting 8.2 Ventilation 8.3 Electricity BEST 8.4	image.	
and precincts symbolized the shift in expression to represe contemporary aspirations. 5.4 Value Classification Under Marine Drive Heritage Precinct 6.0 TOPOGRAPHY 6.1 Floors 7.0 CONSTRUCTION 7.1 Plinth 7.2 Walls 8.0 Brick masonry wall 7.3 Floor 7.4 Stairs 0.0 Dog legged stone staircase with mosaic tiles 7.5 Openings 7.6 Roofing 7.7 Articulation 7.8 Finishes 7.9 Interiors(Movable & Immovable) 7.10 Compound//Fence/Gate 7.9 Interiors(Movable & Immovable) 7.10 Compound//Fence/Gate 7.9 Interiors(Movable & Immovable) 7.11 Curtilege/ Unbuilt space/out buildings/landscape tank 8.0 SERVICES & UTILITIES 8.1 Lighting 8.2 Ventilation 8.3 Electricity 8.4 Water Supply 8.5		
5.4 Value Classification Under Marine Drive Heritage Precinct 6.0 TOPOGRAPHY 6.1 Floors G+5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supp		
5.4 Value Classification Under Marine Drive Heritage Precinct 6.0 TOPOGRAPHY 6.1 Floors G+5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) T 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill: Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting <	m	
6.0 TOPOGRAPHY 6.1 Floors 7.0 CONSTRUCTION 7.1 Plinth 7.2 Walls Brick masonry wall 7.3 7.3 Floor 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings 7.6 Roofing 7.7 Articulation 7.8 Finishes 7.9 Interiors(Movable & Immovable) 7.9 Interiors(Movable & Immovable) 7.10 Compound/Fence/Gate 20mpound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.		
6.1 Floors G+5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound/Fence/Gate 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCG		
6.1 Floors G+5 7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound/Fence/Gate 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCG		
7.0 CONSTRUCTION 7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire P		
7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound/Fence/Gate 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8		
7.1 Plinth Plastered masonry plinth 7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound/Fence/Gate 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8		
7.2 Walls Brick masonry wall 7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (indep		
7.3 Floor R.C.C. floor slab 7.4 Stairs Dog legged stone staircase with mosaic tiles 7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound/Fence/Gate gates (original) painted. 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not		
7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound/Fence/Gate 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the hou 9.0 CONDITION Conditioning units in the hou <td></td>		
7.5 Openings Regular openings with wooden frames and glazed shutters 7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound/Fence/Gate 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the hot 9.0 CONDITION Conditioning units in the hot		
7.6 Roofing Flat roof and terrace 7.7 Articulation Rounded corner 7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound/Fence/Gate 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the hou 9.0 CONDITION	5	
7.8 Finishes Walls: Externally and internally cement plastered and paint Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) Compound Wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the hou 9.0 CONDITION		
Flooring: Marble flooring in the lobby Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.0 CONDITION		
Staircases: Mosaic tiles. 7.9 Interiors(Movable & Immovable) 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the house 9.0 CONDITION	ted	
7.9 Interiors(Movable & Immovable) 7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the hout of the systems) 9.0 CONDITION		
7.10 Compound/Fence/Gate Compound wall is plastered brick wall with M.S. grill; Gates gates (original) painted. 7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.7 Other (HVAC/BMC/Security Systems) Not provided 9.0 CONDITION		
7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the hout of the ho		
7.11 Curtilege/ Unbuilt space/out buildings/landscape Parking sheds at the rear side of the building, meter room, tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the hout and artificioning units in the	s are M.S.	
buildings/landscape tank 8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the houted for the precision of t		
8.0 SERVICES & UTILITIES 8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the houted (independe	water	
8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the houted (independent air conditioning units in thouted (independent air conditioning units		
8.1 Lighting Natural and artificial, good natural lighting 8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the houted (independent air conditioning units in thouted (independent air conditioning units		
8.2 Ventilation Natural and artificial, good natural lighting 8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the hout of the security Systems) 9.0 CONDITION		
8.3 Electricity BEST 8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the houted (independent air conditioni		
8.4 Water Supply MCGM 8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the houted (independe		
8.5 Drainage (Plumbing and sanitation) MCGM 8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the houted (independent air conditioning units in thouted (independent air condit)) <td></td>		
8.6 Fire Precaution Not provided 8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the houted (independent air conditioning units air conditing (independent air conditing (independent air condit		
8.7 Other (HVAC/BMC/Security Systems) Not provided (independent air conditioning units in the houted of the system) 9.0 CONDITION		
9.0 CONDITION		
	1923/	
9.2 Walls Good(exterior walls need painting)		
9.3 Floor Good		
9.4 Stairs Good (need cleaning)		
9.5 Openings Fair (Shutters of few windows are broken)		
9.6 Roofing Good		
9.7 Articulation & Finishes Good		
9.8 Services Good		
9.9 Outbuildings Average (needs cleaning and repairs)		
9.10 Overall Condition Fair		

CHATEAU MARINE		
	TRANSFORMATION	
Form	Additional box grills , chajjas , balconies are enclosed	
Structure	No transformation	
Articulation & Finishes		
DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP	
ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995	
	Form Structure Articulation & Finishes DPREMARKS/PERCEIVEDTHREATS ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR	

(b)

(d)

A64 CHATEAU MARINE

(a)







A64-iv

A 6 5	SHIV SADAN	Comm	an Def nei A/E	
22.31.11			non Ref no: A65	
hint		Card N		Comments of the
NHILL P			Ward A	OTH I
	THE REPORT OF THE PARTY AND THE PARTY	CS No. 1718		115
			rea : 1519.23	11 D. LA
			rea : 4038	1716
			January, 2013	Plot No 42 B ER Shiv Saday
		Recor	d by : Aneri S, Adele Z	Shir Sadan
	Terra Andread (VAL) Spaces and	Review	w by : Shraddha B.	2 Dem martin
THE REAL PROPERTY	an and the second of the second s	Int : As	s above Ext: As above	-h
		Photo	Ref : A65 SHIV SADAN a-f	
1.0		-	DENOMINATION	
1.1	Name of Premises		Shiv Sadan	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1930's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose	road
2.2	Subsidiary		M. Shukla Nirzar Marg	
			in onand mild indig	
3.0	_		OWNERSHIP PATTERN	
3.1	Present		Lachhmandas Tulsidas Nayar	
3.2			The Governor of Bombay	
	3.3 Status		Tenanted	
0.0			Tendrited	
4.0			USE	
4.1	Present		Mixed	
4.2	2 Past		Mixed	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
-			major North-South arterial road	
5.2	Architectural Description		Planning: It is a large building ir	
-			adequate light and ventilation. I	
			windows of the buildings open i	
			0 1	ding shows a hexagonal corner along
			the junction of the main and sub	
				curved balconies are seen at the rear
			-	Driginal grills, gates and features are
			still maintained.	5 5 7 5
5.3	Intrinsic			its era. The various Art Deco style
				d lands created a cohesive image.
				r time represented the new face of
				ower, so did the Art Deco buildings
			and precincts symbolized the sl	
			contemporary aspirations.	1 1 1 1
L	•		•	

A 6 5	SHIV SADAN		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
5.7			
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
0.1			
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well stone staircase with marble cladding	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
1.5	openings	Regular openings with wooden names and glazed shatters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Hexagonal corner	
1.1		Texagonal conter	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Cement terrazzo in the lobby	
		Staircases: Granite Cladding	
		g	
7.9	Interiors(Movable & Immovable)	Entrance canopy	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S.	
		gates (original) painted.	
		5 (5) 1	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room, water	
,	buildings/landscape	tank	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Average(shows leakage in a few places in the interiors)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Average(Shows members rusted in few openings)	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Fair(Needs painting)	
9.8	Services	Fair	
9.9	Outbuildings	Average(Shows cracks needs repairs)	
9.10	Overall Condition	Fair	

A 6 5	SHIV SADAN	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , balconies enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A65 SHIV SADAN



(b)





(C)



(e)



A 6 6	GANGA VIHAR			
		Comm	on Ref no: A66	
		Card N		frank the
			Ward A	tring 1
		CS No		
			rea : 1552.68	
	A CANA		rea : 4140	
			January, 2013	Plot N' - KIL
	The second s		d by : Aneri S, Adele Z	Gange Vihat
tin 1		Review	v by : Shraddha B.	
Ling			s above Ext: As above	11 maria
1991 - 1 - 1994			Ref : A66 GANGA VIHAR a-f	OMM Bernard
1.0			DENOMINATION	
1.1	Name of Premises		Ganga Vihar	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1950's		Extension Date(if any): Not Appl	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	oad
2.2	Subsidiary		C road	
3.0			OWNERSHIP PATTERN	
3.1	Present		Pushpadevi Gangadhar Makhar	
3.2	Past			ourgeshwari Wife of Mr.Gangadhar
			Chaturbhuj, Gangadhar Chaturb	bhuj
3.3	Status		Tenanted	
4.0			USE	
4.0	Present		Residential(shop in the garage)	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
1.0				
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)			Bose road front, which is one of the
			major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in	
			adequate light and ventilation. It	
			windows of the buildings open ir	nto.
				er along the junction of the main
				ne front façade of the building shows
				ue as chajjas over the windows next
				facing the subsidiary road are similar
				de. Polygonal balconies on the left
			side faced of the building. The re	
5.2				riginal grills on most of the windows.
5.3	Intrinsic			ts era. The various Art Deco style
				d lands created a cohesive image. time represented the new face of
				wer, so did the Art Deco buildings
L			the city and all expression of po	wei, so uiu ine Art Deco bullulliys

A66	GANGA VIHAR		
		and precincts symbolized the shift in expression to represent	
		contemporary aspirations.	
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+5(a room on the terrace)	
		· · · · ·	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Hexagonal corner	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Marble flooring in the lobby Staircases: Wooden polished	
7.9	Interiors(Movable & Immovable)	Entrance canopy and porch steps	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building(one converted into a shop, water tank	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good(needs painting)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good(needs painting)	
9.10	Overall Condition	Good	
-			

A 6 6	GANGA VIHAR	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , chajjas, balconies enclosed
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995


(b)

A 6 6 GANGA VIHAR

(a)

(C)





۸ <i>(</i> ٦				
A 6 7	FIRDAUS	Comm	on Dof nov A47	
Republic	and the second		on Ref no: A67	-
10	A A A A A A A A A A A A A A A A A A A	Card N		The second secon
2 minus	ALL TRACT		: Ward A	
18 M			0. 1732	
A. 1			rea : 1552.68	
8 - 4			rea : 3685	Firdeus
2			January, 2013	
			d by : Aneri S, Adele Z	1. Jan Martin Still
-			w by : Shraddha B.	
			s above Ext: As above	
		Photo	Ref : A67 FIRDAUS a-g	
1.0			DENOMINATION	
1.1	Name of Premises		Firdaus	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	oad
2.2	Subsidiary		V. Mankad road(D road)	
3.0			OWNERSHIP PATTERN	
3.1	Present		Pushpadevi Gangadhar Makhar	ia
3.2	Past		The Governor of Bombay, Bai D	Ourgeshwari Wife of Mr.Gangadhar
			Chaturbhuj, Gangadhar Chaturb	phuj
3.3	Status		Tenanted	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra	a Bose road front, which is one of the
5.2	Architectural Description			
			balconies.	
5.3	Intrinsic			ts era. The various Art Deco style
				time represented the new face of
				wer, so did the Art Deco buildings
			and precincts symbolized the sh	
			contemporary aspirations.	
5.2	Architectural Description		major North-South arterial roads Planning: It is a large building in adequate light and ventilation. It windows of the buildings open in Stylistic Classification: The front balconies. The apartment on the façade shows small balconies a with small chajjas over them. Th balconies. Art Deco building representing i buildings on the newly reclaimed Like the Gothic buildings in their the city and an expression of po and precincts symbolized the sh	s. i modest Art Deco style with t has a void where the interior hto. t façade of the building shows small e terrace has a sloping roof. The right nd the left façade has small windows he rear façade shows rectangular ts era. The various Art Deco style d lands created a cohesive image. r time represented the new face of ower, so did the Art Deco buildings

A 6 7	FIRDAUS		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
J. <del>4</del>			
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
0.1			
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.2	Floor	R.C.C. floor slab	
7.4	Stairs	Dog legged wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
1.5	operings		
7.6	Roofing	Sloping roof over the terrace apartment and terrace	
7.7	Articulation	Sloping roof over the apartment	
1.1			
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
7.0		Flooring: Marble flooring in the lobby	
		Staircases: Wooden polished	
7.9	Interiors(Movable & Immovable)	Entance canopy	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates	
		(original) painted.	
		(	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,	
7.11	buildings/landscape	temporary sheds, water tank	
	bunungshanascape		
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
_			
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good(exterior walls need painting)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
	1 J ⁻		
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good (needs cleaning and painting)	
9.10	Overall Condition	Good	
-			

A 6 7	FIRDAUS	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , enclosed balconies, parking shed given for
		laundry shop, additional security cabin,
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai,
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	AVAILABLE/RECOMMENDATIONS	
	& SUGGESTIONS FOR	
	IMPLEMENTATION	

# A67 FIRDAUS





(C)







(b)



(d)



(f)



A67-iv

A 6 8	KRISHNA MAHAL			
		Comm	on Ref no: A68	Not Available
		Card N	lo.:	
		Ward :	Ward A	
	NAME AND ADDRESS OF TAXABLE PARTY.	CS No	.: 1739	
			rea : 2227.44	
and the second			ea : 6048	
			January, 2013	
			d by : Aneri S, Adele Z	
			v by : Shraddha B.	
			s above Ext: As above	
-		Photo	Ref : A68 KRISHNA MAHAL a-	
		е		
1.0			DENOMINATION	•
1.1	Name of Premises		Krishna Mahal	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1950's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	road
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		M/S Reshma Estates Pvt.Ltd.	
3.2	Past		The Governor of Bombay, Lady	Krishnabai Bisesardas Daga W/O
				aga, Shri Navjivan Investors Private
			Ltd., M/S Cloth And Yarn Sales	Corporation Private Limited.
3.3	Status		Tenanted	
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Mixed	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
			major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in	n modest Art Deco style with
			adequate light and ventilation.	
				ding shows curved balconies on the
				balcony continue as the chajja over
				y, the right façade of the building is
				eft façade of the building shows
			0	oden chajjas over them. Circular
				orner of the building, the slab of
				ajja over the windows. The building
				back used for service. Along the main
5.2	Intrincic		staircase there is a glass feature	
5.3	Intrinsic		Art Deco building representing r	ts era. The various Art Deco style

5.4 6.0 6.1	KRISHNA MAHAL Value Classification Floors	buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations. Under Marine Drive Heritage Precinct TOPOGRAPHY
6.0 6.1		Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations. Under Marine Drive Heritage Precinct
6.0 6.1		and precincts symbolized the shift in expression to represent contemporary aspirations. Under Marine Drive Heritage Precinct
6.0 6.1		contemporary aspirations. Under Marine Drive Heritage Precinct
6.0 6.1		Under Marine Drive Heritage Precinct
6.0 6.1		
6.1	Floors	ΤΟΡΟGRAPHY
6.1	Floors	
	FIUUIS	G+7
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Spiral stone staircase with granite cladding
	Openings	Regular openings with wooden frames and glazed shutters
	Roofing	Flat roof and terrace
	Articulation	Rounded balconies
	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Granite flooring in the lobby
		Staircases: Granite Cladding
7.9	Interiors(Movable & Immovable)	
	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.
		gates (original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, meter room,
	buildings/landscape	temporary sheds, water tank, Extra parking shed, HVAC plant
8.0		SERVICES & UTILITIES
	Lighting	Natural and artificial, good natural lighting
	Ventilation	Natural and artificial, good natural lighting
	Electricity	BEST
	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
	Fire Precaution	Riser system
8.7	Other (HVAC/BMC/Security Systems)	HVAC for the building
9.0		CONDITION
	Plinth	Good
	Walls	Good(exterior walls need painting)
	Floor	Good
	Stairs	Good
	Openings	Good
	Roofing	Good
	Articulation & Finishes	Good
	Services	Good
	Outbuildings	Good (Need cleaning and painting)
	Overall Condition	Good Good
7.10		

A 6 8	KRISHNA MAHAL	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , Balconies enclosed, additional parking spaces, additional chajjas
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

#### A 6 8 KRISHNA MAHA

(a)





(C)





(e)



A69	KEVAL MAHAL			
29-12		Common Re	ef no: A69	Not Available
Ť			A	
-			)	
			882.95	
	32.5	B U Area : 5		
		Date : Janua		
			Aneri S, Adele Z	
			Shraddha B.	
		Int : As abov		
		Photo Ref :	A69 KEVAL MAHAL a	
1.0			DENOMINATION	1
1.1	Name of Premises		Keval Mahal	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date(if any): No	ot Applicable
				- The means a
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra	Bose road
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTE	RN
3.1	Present		The Governor of Bombay	
3.2	Past			lehta & His Wife, Bai Kamlabai
0.2			(Lessees)	
3.3	Status		Tenanted	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VA	LUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Cl	handra Bose road front, which is one
			of the major North-South	
5.2	Architectural Description			ilding in modest Art Deco style with
			adequate light and ventila	ition.
5.3	Intrinsic		Art Deco building represe	nting its era. The various Art Deco
				ly reclaimed lands created a
				Gothic buildings in their time
			represented the new face	of the city and an expression of
			power, so did the Art Dec	o buildings and precincts symbolized
				epresent contemporary aspirations.
			Carved feature along the	staircase of the building.
5.4	Value Classification		Under Marine Drive Herita	age Precinct
6.0			TOPOGRAPHY	
6.1	Floors		G+5	

A 6 9	KEVAL MAHAL	
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Access Denied
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: under renovation
-		Flooring: Access Denied
		Staircases: Access Denied
7.9	Interiors(Movable & Immovable)	Access Denied
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates
		(original) painted.
7.11	Curtilege/ Unbuilt space/out buildings/ landscape	Parking sheds on the rear side of the building.
		¥¥¥
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided
9.0		CONDITION
9.1	Plinth	under renovation
9.2	Walls	under renovation
9.3	Floor	Access Denied
9.4	Stairs	Access Denied
9.5	Openings	Good
9.6	Roofing	Access Denied
9.7	Articulation & Finishes	Access Denied
9.8	Services	Good
9.9	Outbuildings	Access Denied
9.10	Overall Condition	Average
10.0		TRANSFORMATION
10.1	Form	No transformation
10.2	Structure	No transformation
10.3	Articulation & Finishes	Under renovation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/ REFERENCES/	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-
	DOCUMENTS	Mumbai,
	AVAILABLE/RECOMMENDATIONS &	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	SUGGESTIONS FOR IMPLEMENTATION	

A 7 0	KAPUR MAHAL			
	30	Comm	non Ref no: A70	Not Available
		Card N	No.:	
		Ward	: Ward A	
		CS No	o. 1741	
		Plot A	rea : 1887.13	
	MARKET AND ADDRESS TO A DOLLAR OF ADDRESS OF		rea : 6034	
			January, 2013	
			d by : Aneri S, Adele Z	
ST.			w by : Shraddha B.	
			s above Ext: As above	
1114141			Ref : A70 KAPUR MAHAL a-e	
1.0			DENOMINATION	
1.1	Name of Premises		Kapur Mahal	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	road
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Ameeta Dharamjit Singh	
3.2	Past		The Governor of Bombay, Kapu	rchand Nemchand Mehta] [And His
			Wife, Bai Nandgauri, Virajlal Ka	purchand Mehta, Harshad
			Kapurchand Mehta, Anilkant Ka	
			Kapurchand Mehta, Shrimati Mi	
			Vasant Shah, Nirmala Subodh I	
				lal Ratilal Maniar, Paresh Manharlal
			Maniar	
3.3	Status		Tenanted	
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Mixed	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	
5.0	Townscape(Natural/Manmade)			a Bose road front, which is one of the
5.1	i ownscape(ivatural/ivialiliaue)		major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in	
5.2			adequate light and ventilation.	
			windows of the buildings open in	
				t façade shows recessed balconies,
				alconies projecting out. The rear
			façade shows balconies as well	
5.3	Intrinsic			ts era. The various Art Deco style
0.0				d lands created a cohesive image.
				r time represented the new face of
1				

A 7 0	KAPUR MAHAL		
		the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations. Carved feature along the staircase of the building.	
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
7.0		CONSTRUCTION	
7.0	Plinth	Plastered masonry plinth	
7.1	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Dog legged wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Marble tiles in the lobby Staircases: Wooden polished	
7.9	Interiors(Movable & Immovable)	Entrance canopy	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, water tank	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Average(exterior walls need painting)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Average	
9.10	Overall Condition	Good	

A 7 0	KAPUR MAHAL	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. chajjas, balconies enclosed
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

(d)

## A70 KAPUR MAHAL













A71	ZAVER MAHAL			
		Comm	non Ref no: A71	Not Available
		Card N		
			:Ward A	
			).: 1742	
			rea : 1886.3	
			rea : 5730	
CAN DO			January, 2013	
P. Con			d by : Aneri S, Adele Z	
	CONTRACTOR OF THE ADDRESS OF THE OWNER.		w by : Shraddha B.	
inn.	The formation of the second second second		s above Ext: As above	
	ANY DESCRIPTION DESCRIPTION	-	Ref : A71 ZAVER MAHAL a-f	
1.0			DENOMINATION	
1.1	Name of Premises		Zaver Mahal	
1.2	Earlier Name		Not applicable	
1.3	Built In:1940's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	oad
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Darshana Harish Mehta	
3.2	Past			erchand Nemchand Mehta, Bai
				Mehta, Gunilal Vasantrai Mehta
3.3	Status		Tenanted	
1.0			USE	
4.0	Present		Mixed	
	Past		Mixed	
4.2 4.3			Regular in mixed use	
4.3	Usage			
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
5.1			major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in	
0.2			adequate light and ventilation. It	
			windows of the buildings open in	
				ling is divided into two wings. The
				along the left side. The side facades
			of the building shows a glass fea	ature along the staircase of the
			building. The front façade of the	building shows curved balconies
			and the slab of the balcony exte	
			windows next to the balcony. Th	
			balconies; curved balconies are	-
5.3	Intrinsic			ts era. The various Art Deco style
				d lands created a cohesive image.
				time represented the new face of
			the city and an expression of po	wer, so did the Art Deco buildings

A71	ZAVER MAHAL		
		and precincts symbolized the shift in expression to represent	
		contemporary aspirations.	
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
-			
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Dog legged wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
	- T		
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies and rounded corner	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Marble flooring in the lobby	
		Staircases: Wooden polished	
		·	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall, Gates are M.S. gates	
		(original) painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, water tank	
	buildings/landscape		
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	

A 7 1	ZAVER MAHAL	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , enclosed balconies
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

## A71 ZAVER MAHAL









(d)



(e)



Δ72	SONAWALA BUILDING			
	JONAWAEA DOLEDING	Comm	non Ref no: A72	Not available
-		Card I		
Wer /			: Ward A	-
cel.			. : 1743	-
			rea : 1910.54	-
			rea : 7035	-
			January, 2013	-
5/			d by : Aneri S, Adele Z	-
100			w by : Shraddha B.	-
			s above Ext: As above	-
STAF			Ref : A72 SONAWALA	-
1	A REAL PROPERTY AND A REAL		DING a-e	
1.0		BUILL	DENOMINATION	
1.0	Nome of Dromises			
1.1 1.2	Name of Premises Earlier Name		Sonawala Building	
			Not applicable	liaabla
1.3	Built In: 1950's		Extension Date(if any): Not App	лісаріе
2.0			ACCESS ROADS	
2.0	Main		Netaji Subhash Chandra Bose	road
2.1	Subsidiary		Not applicable	1080
2.2				
3.0	-		OWNERSHIP PATTERN	
3.1	Present		Ayesha Homi Laher	
3.2	Past			dhandas Purshottamdas Sonawala &
				tlal Gordhandas Sonawala, Harilal
			Gordhandas Sonawala, Sarita I	Harilal Sonawala
3.3	Status		Tenanted	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
<b>_</b>			major North-South arterial road	
5.2	Architectural Description		Planning: It is a large building in	n modest Art Deco style with
			adequate light and ventilation.	
				ding shows a curved corner on the
				uilding has curved balconies along
				e building has curved balconies, the
				become the chajja over the windows
				façade shoes rectangular balconies
				he corners. The side facades have
				ich project out. The rear facades
			show similar balconies. The wir	
5.3	Intrinsic			its era. The various Art Deco style
			pullulings on the newly reclaime	d lands created a cohesive image.

A72	SONAWALA BUILDING	
		Like the Gothic buildings in their time represented the new face of
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
F 4	Value Classification	contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+6(6 th floor looks like an addition)
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Dog legged wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Curved corner and balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Wooden polished
7.9	Interiors(Movable & Immovable)	Entrance canopy
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall in the front and with M.S. grill
-	· · · · · · · · · · · · · · · · · · ·	on the sides. Gates are M.S. gates painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, syntax tanks, and
	buildings/landscape	planters in the front of the building.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
0.7		
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good(needs cleaning)
9.10	Overall Condition	Good

SONAWALA BUILDING	
	TRANSFORMATION
Form	Enclosed balconies, Garage shutters changed.
Structure	No transformation
Articulation & Finishes	Painting going on
DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone on Proposed Development Plan. (D.P.)
ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	Form Structure Articulation & Finishes DPREMARKS/PERCEIVEDTHREATS ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR

## A72 SONAWALA BUILDING

(a)



(b)



(d)



(C)



A 7 3	НЕМРКАВНА		
- <del> </del>		Common Ref no: A73	Not Available
	Internet and the second second	Card No.:	
		Ward :Ward A	
	In I Commenter of the second	CS No. 1744	
San 7		Plot Area : Not Available	
Princip		B U Area : 6920	
-	A Real Property and and and	Date : January, 2013	
A STATIST		Record by : Aneri S, Adele Z	
CHELI		Review by : Shraddha B.	
Mule 1		Int : As above Ext: As above	
E		Photo Ref : A73 HEMPRABHA a-e	2
1.0		DENOMINATION	
1.1	Name of Premises	Hemprabha	
1.2	Earlier Name	Not applicable	
1.3	Built In: 1950's	Extension Date(if any): No	t Applicable
		`,	
2.0		ACCESS ROADS	
2.1	Main	Netaji Subhash Chandra B	ose road
2.2	Subsidiary	Not applicable	
3.0		OWNERSHIP PATTER	RN
3.1	Present	Not Available	
3.2	Past	Not Available	
3.3	Status	Co-operative Housing Soc	iety
4.0		USE	
4.1	Present	Residential	
4.2	Past	Residential	
4.3	Usage	Regular in residential use	
5.0			LUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)		andra Bose road front, which is one of the
<b>F</b> 0	And the shared Descent of	major North-South arterial	
5.2	Architectural Description		ing in modest Art Deco style with
			ion. It has a void where the interior
		windows of the buildings o	
			building shows a curved corner on the building has curved balconies along
			of the building has curved balconies, the
			Iconies become the chajja over the
			nies. The front façade shoes rectangular
			urving around the corners. The side
		1, 2, 0	gular balconies which project out. The
			o of the balcony continuing as chajjas over
			ades show similar balconies. The window
		grills are original.	
5.3	Intrinsic		ting its era. The various Art Deco style
			aimed lands created a cohesive image.

A 7 3	HEMPRABHA		
		Like the Gothic buildings in their time represented the new face of	
		the city and an expression of power, so did the Art Deco buildings	
		and precincts symbolized the shift in expression to represent	
		contemporary aspirations.	
5.4	Value Classification	Under Marine Drive Heritage Precinct	
( )		TODOODADUW	
6.0		TOPOGRAPHY	
6.1	Floors	G+7(the 6 th and 7 th floor look like an addition)	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Dog legged wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
1.0		Flooring: Granite flooring	
		Staircases: Wooden polished	
7.9	Interiors(Movable & Immovable)		
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.	
		gates painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, water tank, pump	
/	buildings/landscape	room, planters.	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Individual A.C. units, video surveillance.	
0.0			
9.0	Dlinth	CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Average(Needs cleaning and repairs)	
9.10	Overall Condition	Good	

	TRANSFORMATION
Form	Additional box grills , A.C.P. chajjas , enclosed balconies, pipe lines from the canopy to the planters.
Structure	No transformation
Articulation & Finishes	
DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	Structure Articulation & Finishes DPREMARKS/PERCEIVEDTHREATS ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR

# A73 HEMPRABHA





(C)



(d)



A74	AL-JABREYA COURT			
\$		Comm	non Ref no: A74	
		Card I	No.:	mo om N
		Ward	: Ward A	Al-Jaireya Cost
		CS No	D. 1745	PLOTNO 40 BER []
		Plot A	rea : 1892.99	
		BUA	rea : 4772.46	
-S- 14			January, 2013	
			d by : Aneri S, Adele Z	4
			w by : Shraddha B.	
			s above Ext: As above	ANO NO L
		Photo	Ref : A75 MATRUCHAYA a-f	
1.0			DENOMINATION	
1.1	Name of Premises		Al-Jabreya Court	
1.2	Earlier Name		Not applicable	
1.3	Built In : 1950's		Extension Date(if any): Not App	blicable
2.0				
2.0 2.1	N 4 - i		ACCESS ROADS	no o d
2.1	Main		Netaji Subhash Chandra Bose	1020
2.2	Subsidiary		Not Applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Shaikh Jabbar Abdulla Al-Saba	h
3.1	Past			sor), Chandulal Mohanlal, Hechand
J.Z	Fast		Mohanlal, Bhogilal Mohanlal, Ta	
				kh Abdulla Al.Jabar Al-Sabah of
			Kuwait (Lessee)	
3.3	Status		Tenanted	
0.0	- Cranac			
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
	V		<u> </u>	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra	a Bose road front, which is one of the
			major North-South arterial road	
5.2	Architectural Description		Planning: It is a large building ir	n modest Art Deco style with
			adequate light and ventilation.	
				ding shows curved balconies on both
				front façade shows rectangular
			balconies projecting out the sla	
				lls and the original name plaque
5.2			remains.	its era. The various Art Deco style
5.3	Intrinsic			ed lands created a cohesive image.
				ir time represented the new face of
				ower, so did the Art Deco buildings
			and precincts symbolized the sl	
l	-			

A 7 4	AL-JABREYA COURT		
- <del>/</del> / 4		contemporary aspirations.	
5.4	Value Classification	Under Marine Drive Heritage Precinct	
J.4			
6.0		TOPOGRAPHY	
6.1	Floors	G+5	
0.1	1 1001 3		
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.2	Floor	R.C.C. floor slab	
7.4	Stairs	Access Denied	
7.4	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.0	Articulation	Rounded balconies	
1.1	ALICUIDIT	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Access Denied	
		Staircases: Access Denied	
7.9	Interiors(Movable & Immovable)	Access Denied	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall	
7.11	Curtilege/ Unbuilt space/out	None	
	buildings/landscape		
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Access Denied	
9.4	Stairs	Access Denied	
9.5	Openings	Good	
9.6	Roofing	Good	
9.0	Articulation & Finishes	Good	
9.7	Services	Good	
9.0	Outbuildings	Access Denied	
9.9	Overall Condition	Good	
9.IU			
10.0		TRANSFORMATION	
10.0	Form	Balconies enclosed, AC units on road facing side.	
10.1	Structure	No transformation	
10.2	Articulation & Finishes	No major transformation	
10.5			

A 7 4	AL-JABREYA COURT	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A 7 5	MATRUCHHAYA	Comm	non Define: A7E	
			non Ref no: A75	-j#
	THE REPORT OF THE PARTY OF THE	Card N		E
1 1			: Ward A	The second s
Real Provention	THE REAL PROPERTY AND		0. 1746 & 1/1746	-
			Irea : 1893.82	
A DECEMBER OF THE OWNER OWNER OF THE OWNER OWNE	A DESCRIPTION OF THE OWNER OWNER OF THE OWNER OWNER OF THE OWNER OWNE		rea :5481.7	
	States of the same of the same		: January, 2013	
			rd by : Aneri S, Adele Z	
			w by : Shraddha B.	a
HIPHT			s above Ext: As above	-+
1.0	Ι	Photo	Ref : A75 MATRUCHAYA a-f	
1.0			DENOMINATION	
1.1	Name of Premises		Matruchhaya	
1.2	Earlier Name		Tulsi Vihar	
1.3	Built In : 1950's		Extension Date(if any): Not Applicable	
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose road	
2.2	Subsidiary		Not Applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Rupa Bhogilal Shah	
3.2	Past		The Governor of Bombay, Tulsidas Chhaganlal Shah, Kamlabai	
			Tulsidas Shah, Shri Pritamlal Mohanlal Daftary, Smt.Kusumben	
			Pritamlal Daftary, Matruchhaya Building Condominium, Taraben	
			K.Shah, Indumati Ahsok Kumar Shukla, Gurdeep Singh Bajaj,	off
			Hardesh Kaur Bajaj, Navnitbhai H.Parekh, Purvi Shashikant Shro	011,
			Purvi Chandrakant Shah, Surendra Tulsidas Shah, Purnima	
			M.Patani, Mukesh C.Patani, Sumanben J.Ghandhi, Arvind C.Ghandhi, Hansaben A.Ghandhi, Kokilaben C.Ghandhi, Narend	dra
				JIA
			Laxmikant Parekh, Usha Dilip Mehta, Surendrabhai T.Shah, Ranjanben C.Kothari, Kamlbhai C.Kothari, Nandraj C.Kothari,	
			Hemlata B.Shilpi, Ajit B.Shilpi, Gordhandas D.Bhagat, Pushpabe	n
			G.Bhagat, Vithalbhai H.Patel, Sanjaybhai V.Patel, Omprakash	511
			B.Kejriwal, Radheshayam B.Kejriwal, Nathmal B.Kejriwal,	
			Ghewarchand H.Bokaria, Pavan Ghewarchand Bokaria, Ansibai	
			H.Bokaria, Yashwantrai Dularai Dave, Vijaya Yashwantrai Dave,	
			Neela Natwarlal Desai, Yeshwant Manibhai Desai, Lal Manibhai	
			Desai, Vijaybhai H.Pandya, Pushpaben V.Pandya, Venkateshwa	
			Subra Moni., M/S.Bawa Praduman Sing & Sons., Surendrakuma	
			Babulal Bubna, Sampatkumar Babulal Bubna, Santoshkumar	
			Babulal Bubna, Vasant Kishore, Amerchand, Nitin Narotamdas	
			Shah, Pravinchandra Hiralal Doshi, Indumati Pravinchandra Dos	shi,
			Harsha Alias Haridarshna Wd/O Narendra L.Parekh, Smruti Alias	
			Hina Nayan Mirani, Chhaya Narendra Parekh, Bina Nikhil Merch	
			Pritamlal Mohanlal Daftary, Smt.Kusumben Pritamlal Daftary,	
			Ramchandra Bharatan, Sridhar Bharatan, Pankaj Talwar	
3.3	Status		Co-operative Housing Society	

A 7 5	MATRUCHHAYA	
4.0		USE
4.1	Present	Residential
4.2	Past	Residential
4.3	Usage	Regular in residential use
т.5		
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Part of Netaji Subhash Chandra Bose road front, which is one of the
		major North-South arterial roads.
5.2	Architectural Description	Planning: It is a large building in modest Art Deco style with
		adequate light and ventilation. It has a void where the interior
		windows of the buildings open into.
		Stylistic Classification: The building shows curved balconies on both
		corners at the front façade. The front façade shows rectangular
		balconies projecting out the slab of the balconies becomes the
		chajja for the windows. The corner small windows have independent
		chajjas. The side facades have small rectangular balconies which project out. The rear facades show balconies similar to the front
		facade. The window grills are original. The chajjas, window grills,
		name plates and some of the garage doors are original.
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style
0.0		buildings on the newly reclaimed lands created a cohesive image.
		Like the Gothic buildings in their time represented the new face of
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
( 0		
6.0 6.1	Floors	TOPOGRAPHY G+7
0.1	FIDUIS	6+7
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Dog legged wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
7.0		Flooring: Marble flooring
		Staircases: Wooden polished
7.9	Interiors(Movable & Immovable)	Entrance canopy
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill, Gates are M.S.
		gates painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, temporary sheds,
	buildings/landscape	planters

A 7 5	MATRUCHHAYA	
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Average(Shows cracks needs repairs)
9.10	Overall Condition	Good
10.0		TRANSFORMATION
10.1	Form	Additional grills , balconies enclosed
10.2	Structure	No transformation
10.3	Articulation & Finishes	Recently painted
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

# A75 MATRUCHHAYA





(C)







(d)



(e)




A76	GIRI KUNJ			
A / 0	GIRI KUNJ	Comm	non Ref no: A76	1
		Conin Card N		
			: Ward A	10 9
			. waiu A ).: 1747	Sh Ti
			rea : 1892.99	A LOTHO T BEAL
	A AN ADDRESS OF A			
	All and a second		rea:5611.2	·
7			January, 2013	an key
36			d by : Aneri S, Adele Z w by : Shraddha B.	11 the de
1			s above Ext: As above	12
16		-	Ref : A76 GIRIKUNJ a-e	An and
1.0		THOLO	DENOMINATION	
1.1	Name of Premises		Giri Kunj	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date(if any): Not App	olicable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose	road
2.2	Subsidiary		Not applicable	
3.0			OWNERSHIP PATTERN	
3.1	Present		Mayuri Hiralal Girdharlal	
3.2	Past		The Governor of Bombay, Cha	ndanbai Girdharlal, Dhirajlal
			Girdharlal, Hiralal Girdharlal, Ki	iritilal Girdharlal, Hemant Hiralal
			Girdharlal, Rajiv Hiralal Girdhar	rlal, Prabhaben Hiralal Girdharlal
3.3	Status			
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Mixed	
4.3	Usage		Regular in mixed use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
5.0			major North-South arterial road	
5.2	Architectural Description		Planning: It is a large building in	
			adequate light and ventilation.	
			windows of the buildings open	
				ding shows curved balconies on both
				e front façade shows rectangular ajjas of the balconies becomes the
				rner small windows have independent
				small rectangular balconies which
				how balconies similar to the front
				original. Name plates are original
5.3	Intrinsic			its era. The various Art Deco style
0.0				ed lands created a cohesive image.
				ir time represented the new face of

A76	GIRI KUNJ	
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+7
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Dog legged wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Wooden polished
7.9	Interiors(Movable & Immovable)	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates painted.
7.11	Curtilege/ Unbuilt space/out	Temporary sheds, Elevated parking sheds at the rear of the building
	buildings/landscape	
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Average(needs cleaning)
9.10	Overall Condition	Good

A 7 6	GIRI KUNJ	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. chajjas, balconies enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	Under renovation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

# A76 GIRI KUNJ



(b)





(d)



Δ77	BHARATIYA BHAVAN		
	DIAKATITA DITAVAN	Comm	non Ref no: A77
		Card N	1 d Ba
	Carried Constant		: Ward A
- KE			
1A			o. 1748 & 1/1748 rea : 562.71
N. 6 1.44	CA CA		
			rea : 5471.9
			January, 2013
		Recor	d by : Aneri S, Adele Z
			w by : Shraddha B.
monite	CONTRACTOR OF THE OWNER		s above Ext: As above
			Ref : A77 BHARATIYA
1.0		BHAV	AN a-d
1.0	Nome of Dramians		DENOMINATION Describes Description
1.1	Name of Premises		Bharatiya Bhavan
1.2	Earlier Name		Not applicable
1.3	Built In: 1940's		Extension Date(if any): Not Applicable
2.0			ACCESS ROADS
2.0	Main		Netaji Subhash Chandra Bose road
2.1	Subsidiary		Not applicable
2.2			
3.0			OWNERSHIP PATTERN
3.1	Present		Dr.Kirtilal M.Bhansali
3.2	Past		the Governor of Bombay, Tarabai Jivanlal Parekh, Dhirajlal Jivanlal
0.2			Parekh, Keshavlal Bhikabahi, Manubhai Lalbhai Gajrawala,
			Rasilaben Moholal, Chandulal Vardhman Shah
3.3	Status		Co-operative Housing Society
			Jeres
4.0			USE
4.1	Present		Residential
4.2	Past		Residential
4.3	Usage		Regular in residential use
5.0			SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra Bose road front, which is one of the
			major North-South arterial roads.
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with
			adequate light and ventilation.
			Stylistic Classification: The building shows curved balconies on both
			corners at the front façade. The front façade shows rectangular
			balconies projecting out the chajja of the balconies becomes the
			chajja for the windows. The corner small windows have independent
			chajjas. The side facades have small rectangular balconies which
			project out. The rear facades show rectangular balconies which
			project out, the windows on the rear façade show no chajjas. The
			window grills are original. Name plates are original
5.3	Intrinsic		Art Deco building representing its era. The various Art Deco style
			buildings on the newly reclaimed lands created a cohesive image.

A77	BHARATIYA BHAVAN	
		Like the Gothic buildings in their time represented the new face of
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	
5.4		
6.0		TOPOGRAPHY
6.1	Floors	G+6(6 th floor looks like an additional floor)
0.1		
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Dog legged wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
7.0	1 11131163	Flooring: Granite flooring in the lobby
		Staircases: Wooden polished
7.9	Interiors(Movable & Immovable)	Entrance canopy
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S.
7.10	Compound/Fence/Gale	gates (original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, temporary sheds,
	buildings/landscape	Water tank (not underground), pump room.
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
		BEST
8.3 8.4	Electricity Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
	Fire Precaution	
8.6		Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
7.J	Openings	
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Average(Needs cleaning and repairs)
9.10	Overall Condition	Good
7.10		

A77	BHARATIYA BHAVAN	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. chajjas , balconies enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

# A77 BHARATIYA BHAVAN







(C)



A 7 8	AL-SABAH COURT		
-710		Comm	non Ref no: A78
		Card	
5			Mand A
	H HI 100 11 11 11		. 1749
	The second secon		rea : 1892.99
			rea: 5589.5
			January, 2013
			d by : Aneri S, Adele Z
		Review	w by : Shraddha B.
			s above Ext: As above
1111(111			Ref : A78 AL-SABAH COURT
		a-e	
1.0			DENOMINATION
1.1	Name of Premises		Al-Sabah Court
1.2	Earlier Name		Not applicable
1.3	Built In: 1940's		Extension Date(if any): Not Applicable
2.0			ACCESS ROADS
2.0	Main		Netaji Subhash Chandra Bose road
2.2	Subsidiary		Not applicable
	Culoradary		
3.0			OWNERSHIP PATTERN
3.1	Present		
3.2	Past		The Governor of Bombay, Kantilal Ishwarlal, Bai Shakuntala Kantilal
3.3	Status		His Highness The Shaikh Of Kuwait Shaikh Abdulla Al-Salim Al-
			Sabah
4.0			USE
4.1	Present		Residential
4.2	Past		Residential
4.3	Usage		Regular in residential use
5.0			SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra Bose road front, which is one of the
			major North-South arterial roads.
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with
			adequate light and ventilation.
			Stylistic Classification: The building shows curved balconies on both
			corners at the front façade. The front façade shows rectangular
			balconies projecting out the chajja of the balconies becomes the
			chajja for the windows. The corner small windows have independent
			chajjas. The side facades have small rectangular balconies which
			project out. The rear facades show rectangular balconies which project out, the windows on the rear facade show no chajjas. The
			window grills are original. Name plates are original
5.3	Intrinsic		Art Deco building representing its era. The various Art Deco style
			buildings on the newly reclaimed lands created a cohesive image.
			Like the Gothic buildings in their time represented the new face of
	1		

A 7 8	AL-SABAH COURT	
-770		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent
		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+5
-		
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Dog legged wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Wooden polished
7.9	Interiors(Movable & Immovable)	Entrance canopy
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall, Gates are M.S. gates painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building , water tank, planters
	buildings/landscape	· · ··································
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
		Cood
9.9 9.10	Outbuildings Overall Condition	Good

A 7 8	AL-SABAH COURT	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. chajjas , balconies enclosed
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

# A78 AL-SABAH COURT

(a)





(d)





A79	SEKSARIA	
R/7	JENJANIA	Common Ref no: A79
		(Reviewed in 2013)
		Card No.: A-19a
		Ward (Part): A-I
		CS No.: 1750
		Plot Area: 1919.74
	HILL A LEAD IN THE MAN AND A LEAD IN THE AND A LEAD AND	sq.m.
		B U Area: 8869.19
		sq.m.
		Date: April, 2005
		Record by: Gauri J,
		Anup S 5 Cover
		Review by: Arun Kale
		Ext: As above
		Photo Ref: A79 SEKSARIA a-f
1.0		DENOMINATION
1.0	Name of Premises	Sekseria
1.1	Earlier Name	Not applicable
1.2	Built In: Late 1930s to 40s	Extension Date(if any): Not applicable
1.0		
2.0		ACCESS ROADS
2.1	Main	Netaji Subhash Chandra Road (Marine Drive)
2.2	Subsidiary	Not applicable
3.0		OWNERSHIP PATTERN
3.1	Present	Bai Bhagwantibai Shivprasad Vaid
3.2	Past	Basantbhai Govindram, Kudilal Govindram, Shaikh Sariyabai
	-	Anaribai, Sitaram Podar
3.3	Status	Tenanted
4.0		
4.0	Procent	USE
4.1	Present Dest	Residential Residential
4.2 4.3	Past Usage	Regular residential use
4.3	Usaye	
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Located on a corner plot facing Netaji Subhash Chandra
		Road,
		which is one of the major North-South arterial roads.
5.2	Architectural Description	Follows the typology of Art Deco corner building. The
		Chamfered
		corner façade enclosing the staircase block with glass
		windows is
		highlighted by vertical plaster bands rising through first to fifth
		floor.
		The balconies with rounded corners emerge from the

A 7 9	SEKSARIA	
		Chamfered
		façade and continue on both the sides façade. The parapet
		walls of
		balconies have their plaster bands and light wooden / metal
		railing.
		However the balconies which are enclosed destroy the Art
		Deco
		character.
5.3	Intrinsic	Owned by Marwaris, a wealthy business community. The
		various
		Art Deco style buildings on the newly reclaimed lands created
		a
		cohesive image. Like the Gothic buildings in their time
		represented
		the new face of the city and an expression of power, so too
		the Art
		Deco buildings and precincts symbolized the shift in
		expression to
		represent contemporary aspirations.
5.4	Value Classification	Existing Grade: NA Recommended Grade: III
		A(arc), B(des), G(grp), E
( )		
6.0		TOPOGRAPHY
6.1	Floors	G + 6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry walls
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Openwell R.C.C. marble cladded staircase
7.5	Openings	Rectangular openings with wooden frames and glazed
-		shutters
7.6	Roofing	Flat roof with terrace
7.7	Articulation	The Chamfered corner façade enclosing the staircase block
		with
		glass windows is highlighted by vertical plaster bands rising
		through first to fifth floor. The balconies with rounded corners
		emerge from the Chamfered façade and continue on both the
		sides
		façade.
7.8	Finishes	Internally and externally cement plastered and painted
7.9	Interiors(Movable & Immovable)	Entrance foyer
7.10	Compound/Fence/Gate	Plastered brick wall
7.11	Curtilege/ Unbuilt space/out	Marginal side open space
	buildings/landscape	
0.0		
8.0	Lighting	SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural ventilation

A79	SEKSARIA	
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided
9.0		CONDITION
9.1	Plinth	Good (No settlement or cracks observed)
9.2	Walls	Good (No dampness or cracks observed)
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good (No leakage observed)
9.7	Articulation & Finishes	Good
9.8	Services	Good (Drainage pipes need no replacement)
9.9	Outbuildings	Good
9.10	Overall Condition	Good Maintenance level Good
10.0		
10.0		TRANSFORMATION
10.1	Form	Balconies enclosed on many floors.
10.2	Structure	Sliding windows, aluminium chajjas added.
10.3	Articulation & Finishes	Railings changed or / and filled up with masonry.
11.0	DP REMARKS/PERCEIVED THREATS	Plot falls under Residential Zone in DP
12.0		Desumentes C.C. sheets D.D. Cheste Fisher City Marro
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps – Mumbai, Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995









(d)



(e)



A79-iv

A 8 0	BHARAT MAHAL			
	DITARAT MAITAL	Comm	ion Ref no: A80	CHI CHI
Dec.		Card N	31 1 5	
			: Ward C	and a li
TREAT THE T			0. 1769	Mahala.
TAN JAIN			rea : 1756.7	So the second second
-FIN 40			rea : 5323.5	THE IN
			January, 2013	
			d by : Aneri S, Adele Z	1100
		Review	v by : Shraddha B.	The state of the s
			s above Ext: As above	and the second second
		Photo	Ref : A80 BHARAT MAHAL a-e	Contraction of the second s
1.0			DENOMINATION	
1.1	Name of Premises		Bharat Mahal	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date(if any): Not Applicable	
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose road	
2.2	Subsidiary		Patan Jain Mandal Marg	
3.0			OWNERSHIP PATTERN	
3.1	Present		The Akhil Bharat Co-Operative Housing Society	
3.2	Past		Governor of Bombay, Jayantilal Nathalal, Kantil	ai nathalai
3.3	Status		Co-operative Housing Society	
4.0			USE	
4.0	Present		Mixed	
4.1	Past		Mixed	
4.3	Usage		Regular in mixed use	
5				
5.0			SIGNIFICANCE & VALUE CLASSIFIC	ATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra Bose road from	
			major North-South arterial roads.	
5.2	Architectural Description		Planning: It is a large building in modest Art Dec	co style with
			adequate light and ventilation. It has voids wher	
			windows of the buildings open into.	
			Stylistic Classification: The building shows a cu	
			junction of the main and subsidiary road. The fr	
			continuous balconies. The façade facing the sul	
			long balconies. The other side façade shows cu	rved balconies. The
E 2	Intrincia		balconies show small chajjas over them.	ue Art Deec style
5.3	Intrinsic		Art Deco building representing its era. The vario	
			buildings on the newly reclaimed lands created Like the Gothic buildings in their time represented	
			the city and an expression of power, so did the	
			and precincts symbolized the shift in expression	
			contemporary aspirations.	
5.4	Value Classification		Under Marine Drive Heritage Precinct	
· · · · · · · · · · · · · · · · · · ·	<u> </u>			

A 8 0	BHARAT MAHAL	
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Dog legged stone staircase with ceramic tile cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Curved corner
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Marble flooring in the lobby Staircases: Ceramic tile
7.9	Interiors(Movable & Immovable)	Entrance canopy
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates painted.
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, temporary sheds, Water tank
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
7.0		
9.9	Outbuildings	Average(Needs cleaning and repairs)

A 8 0	BHARAT MAHAL	
10.0		TRANSFORMATION
10.1	Form	New grills, A.C.P. chajjas, balconies enclosed. Parking shed
		converted to a storage space
10.2	Structure	No transformation
10.3	Articulation & Finishes	No major transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Commercial Zone in DP
12.0	ADDITIONAL	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai,
	NOTES/REFERENCES/DOCUMENTS	Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995
	AVAILABLE/RECOMMENDATIONS	
	& SUGGESTIONS FOR	
	IMPLEMENTATION	

# A80 BHARAT MAHAL

(a)









(d)



A 8 1	SHRI NIKETAN	
7.01	onki kikerak	Common Ref no: A81
		Card No.:
80		Ward: Ward C
		CS No. 1/1769
A - A		Plot Area : 1690.64
Son Park	THE THE THE AVER	B U Area : 4151
		Date : January, 2013
and the second		Record by : Aneri S, Adele Z
		Review by : Shraddha B.
		Int : As above Ext: As above
		Photo Ref : A81 SHRI NIKETAN a-d
1.0		DENOMINATION
1.1	Name of Premises	Shri Niketan
1.2	Earlier Name	Not applicable
1.3	Built In:1950's	Extension Date(if any): Not Applicable
2.0		ACCESS ROADS
2.1	Main	Netaji Subhash Chandra Bose road
2.2	Subsidiary	Not applicable
3.0		OWNERSHIP PATTERN
3.1	Present	Shreeniwas Co-Operative Hosuing Society Limited
3.2	Past	The Governor Of Bombay, Nanalal Haridas
3.3	Status	Co-operative Housing Society
4.0		USE
4.1	Present	Residential
4.2	Past	Residential
4.3	Usage	Regular in residential use
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.0	Townscape(Natural/Manmade)	Part of Netaji Subhash Chandra Bose road front, which is one of the
5.1	Townscape(Natural/Manmade)	major North-South arterial roads.
5.2	Architectural Description	Planning: It is a large building in modest Art Deco style with
5.2	Architectural Description	adequate light and ventilation. It has voids where the interior
		windows of the buildings open into.
		Stylistic Classification: The front façade of the building shows curved
		balconies which project out. The small windows next to the
		balconies show original chajjas over them. The side façade show
		small windows with original chajja. The rear façade show no
		balconies only windows with some original chajjas and some new
		chajjas. The building shows few old grills maintained in the
		windows.
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style
		buildings on the newly reclaimed lands created a cohesive image.
		Like the Gothic buildings in their time represented the new face of
		the city and an expression of power, so did the Art Deco buildings
		and precincts symbolized the shift in expression to represent

A 8 1	SHRI NIKETAN	
7.01		contemporary aspirations.
5.4	Value Classification	Under Marine Drive Heritage Precinct
0.1		
6.0		TOPOGRAPHY
6.1	Floors	G+6
0.1		
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase with marble cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Marble cladding
7.9	Interiors(Movable & Immovable)	Entrance canopy
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with; Gates are M.S. gates
		(original) painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, Water tank, pump
	buildings/landscape	room, planters
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good

A 8 1	SHRI NIKETAN	
10.0		TRANSFORMATION
10.1	Form	New grills, A.C.P. chajjas , balconies enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

# A81 SHRI NIKETAN

(a)







(C)



A 8 2	GOBIND MAHAL			
		Comm	non Ref no: A82	
		Card N		
6			: Ward C	
1			). 2/1769	
			rea : 1581.94	with maked first t
			rea : 4298	with as a for the
and the			January, 2013	M Martin Alex 1
			d by : Aneri S, Adele Z	11 - Toma at
			w by : Shraddha B.	1 hoto
	THE PROPERTY OF A DESCRIPTION OF A DESCR		5	
Enne?			s above Ext: As above Ref : A82 GOBIND MAHAL a-f	Tilhetan
1.0			DENOMINATION	•
1.1	Name of Premises		Gobind Mahal	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date (if any): Not App	blicable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	oad
2.2	Subsidiary		G Road	
3.0			OWNERSHIP PATTERN	
3.1	Present		Mrs.Sheila K.Sippy	
3.2	Past			ecklal Ujamani, Laxmibai Manecklal,
0.2			Ramchand Hashmatrai Hiranan	
			Hiranandani	
3.3	Status		Co-operative Housing Society	
0.0				
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Mixed	
4.2	Usage		Regular in Mixed use	
4.5	Usaye			
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
5.1			major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in	
J.Z	Architectural Description		adequate light and ventilation.	modest Art Deco style with
				ling shows a curved corner along the
				sidiary road. The front façade shows
				now all enclosed). The side façade
			shows rectangular projecting ba	
5.3	Intrinsic			ts era. The various Art Deco style
5.5				d lands created a cohesive image.
				r time represented the new face of
				wer, so did the Art Deco buildings
			and precincts symbolized the sh	
			contemporary aspirations.	
L	<u> </u>		1	

A 8 2	GOBIND MAHAL		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
0.1			
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Dog legged stone staircase with yellow marble	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
		·····g	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Curved corner	
7.8	Finishes	Walls: Externally and internally cement plastered and painted	
		Flooring: Marble flooring in the lobby	
		Staircases: yellow marble/ceramic tiles	
7.9	Interiors(Movable & Immovable)	Entrance canopy	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall, Gates are M.S. gates	
		painted.	
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, temporary sheds,	
	buildings/landscape	Water tank (not underground), pump room.	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Video surveillance (independent air conditioning units in the	
		houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	

nclosed. Parking shed
er City Maps-Mumbai, n Bombay 1995

# A82 GOBIND MAHAL











(d)



(e)



A 8 3	PARIJAT			
AUJ	ГАЛІЗАТ	Comm	non Ref no: A83	
		Card N		1 to to to to
	the second second		Ward C	A Land Land
1 - 3		-	). 1778	
100	A DESCRIPTION AND		rea : 1612.88	pantiar ag a 1 [1]
-		-	rea : 4566.1	and
			January, 2013	
			d by : Aneri S, Adele Z	110
ation			w by : Shraddha B.	
10			s above Ext: As above	A
	18 - Contraction of the		Ref : A83 PARIJAT a-e	
1.0			DENOMINATION	
1.1	Name of Premises		Parijat	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1940's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	road
2.2	Subsidiary		G Road	
3.0	-		OWNERSHIP PATTERN	
3.1	Present		TIMBLO BROTHERS PVT.LTD	
3.2	Past		GOVERNOR OF BOMBAY, JA	
			JAGJWAN SHETH, VASANT J	AGJIWANDS MULJI, BHARAT
3.3	Status		BUILDERS LTD. Co-operative Housing Society	
3.3	Status			
4.0			USE	
4.1	Present		Mixed	
4.2	Past		Mixed	
4.3	Usage		Regular in Mixed use	
5.0			SIGNIFICANCE & VALUE	CLASSIFICATION
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
			major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in	
			adequate light and ventilation. It	
			windows of the buildings open in	
				ding shows a curved corner along the
				iary road. The windows from the first
				he ground floor. The windows show
				le show similar windows and chajja.
5.3	Intrinsic		0 1 0	ts era. The various Art Deco style
				d lands created a cohesive image.
				r time represented the new face of
				ower, so did the Art Deco buildings
			and precincts symbolized the sh	int in expression to represent
			contemporary aspirations.	

A 8 3	PARIJAT	
5.4	Value Classification	Under Marine Drive Heritage Precinct
0.1		
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well wooden staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
		·····g-······g-······g-·······
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Wooden polished
7.9	Interiors(Movable & Immovable)	Entrance canopy
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S.
		gates painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, Water tank ,pump
	buildings/landscape	room, Steps to the shops on the ground floor, planters
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Video surveillance (independent air conditioning units in the
		houses)
9.0	DPut	CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good

A 8 3	PARIJAT	
10.0		TRANSFORMATION
10.1	Form	Additional grills , A.C.P. chajjas ,
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995









(b)



(d)



A 8 4	SHANTI NIKETAN		
		Comm	non Ref no: A84
all a	Y	Card N	
-			: Ward C
11 11			D.: 1/1778
To prove			rea : 1556.86
			rea : 4713.4
23 0	1000		January, 2013
			d by : Aneri S, Adele Z
and the second			w by : Shraddha B.
a in			s above Ext: As above
INF			Ref : A84 SHANTI NIKETAN a-
		e	
1.0		0	DENOMINATION
1.1	Name of Premises		Shanti Niketan
1.2	Earlier Name		Not applicable
1.3	Built In:1940's		Extension Date(if any): Not Applicable
2.0			ACCESS ROADS
2.0	Main		Netaji Subhash Chandra Bose road
-			Not applicable
2.2	Subsidiary		
3.0			OWNERSHIP PATTERN
3.1	Present		Shri Shantiniketan Co-Operative Housing Society Ltd.
3.2	Past		The Governor of Bombay, Nanalal Haridas, Tribhuvandas Haridas,
			Shantilal Mangaldas, Mahendra Shantilal, Apurva Shantilal
3.3	Status		Co-operative Housing Society
1.0			USE
4.0	Dresent		
4.1	Present		Mixed
4.2	Past		Mixed
4.3	Usage		Regular in mixed use
5.0			SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)		Part of Netaji Subhash Chandra Bose road front, which is one of the
			major North-South arterial roads.
5.2	Architectural Description		Planning: It is a large building in modest Art Deco style with
	·····		adequate light and ventilation.
			Stylistic Classification: The balconies on the front façade of the
			building are curved along the centre. The balconies project out. The
			side façade show small rectangular balconies projecting out. The
			balconies show shallow chajjas over them.
5.3	Intrinsic		Art Deco building representing its era. The various Art Deco style
			buildings on the newly reclaimed lands created a cohesive image.
			Like the Gothic buildings in their time represented the new face of
			the city and an expression of power, so did the Art Deco buildings
			and precincts symbolized the shift in expression to represent
			contemporary aspirations.

A 8 4	SHANTI NIKETAN		
5.4	Value Classification	Under Marine Drive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Dog legged wooden staircase	
7.5	Openings	Regular openings with wooden frames and glazed shutters	
7.6	Roofing	Flat roof and terrace	
7.7	Articulation	Rounded balconies	
7.8	Finishes	Walls: Externally and internally cement plastered and painted Flooring: Granite flooring in the lobby Staircases: Wooden polished	
7.9	Interiors(Movable & Immovable)	Entrance canopy	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall with M.S. grill; Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building, temporary sheds, Water tank (not underground), pump room.	
8.0		SERVICES & UTILITIES	
8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural lighting	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)	
9.0		CONDITION	
9.1	Plinth	Good	
9.2	Walls	Good	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Good	
9.9	Outbuildings	Average(Needs cleaning and repairs)	
9.10	Overall Condition	Good	

A 8 4	SHANTI NIKETAN	
10.0		TRANSFORMATION
10.1	Form	Additional box grills , A.C.P. chajjas , balconies enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

(b)

# A84 SHANTI NIKETAN



(C)





(d)



A 8 5	MEGHDOOT			
- 705		Comm	non Ref no: A85	minute the second second
* 1 g	the the main	Card N		
1.1			:Ward C	1 the and
1			). 2/1778	
			rea : 1804.36	matter and a
			rea : 5383	met the atte
金融 小	THE REPORT OF THE REPORT OF THE		January, 2013	111 12 -11
			d by : Aneri S, Adele Z	ill the tr
in the second			w by : Shraddha B.	1 1 L - D'
	the second se		s above Ext: As above	an il and a
	The a summer and a summer and the		Ref : A85 MEGHDOOT a-e	1 the Count
1.0			DENOMINATION	<u> </u>
1.1	Name of Premises		Bharatiya Bhavan	
1.2	Earlier Name		Not applicable	
1.3	Built In: 1950's		Extension Date(if any): Not App	licable
2.0			ACCESS ROADS	
2.1	Main		Netaji Subhash Chandra Bose r	road
2.2	Subsidiary		Shamaldas Gandhi Road	
3.0			OWNERSHIP PATTERN	
3.1	Present		The Meghdoot Co-Operative Ho	ousing Society Limited
3.2	Past		The Governor Of Bombay, The	Sonawala Co.Ltd.
3.3	Status		Co-operative Housing Society	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0			SIGNIFICANCE & VALUE	
5.1	Townscape(Natural/Manmade)			a Bose road front, which is one of the
			major North-South arterial roads	
5.2	Architectural Description		Planning: It is a large building in	modest Art Deco style with
			adequate light and ventilation.	
				ling shows a polygonal corner along
				osidiary road. The other corner of the
				s. The side facades of the building
				project out. The curved balconies
			the windows.	e. Original grills are maintained on
5.3	Intrinsic			ts era. The various Art Deco style
5.5				d lands created a cohesive image.
			0	r time represented the new face of
				wer, so did the Art Deco buildings
			and precincts symbolized the sh	
			contemporary aspirations.	
L	i		1	

A 8 5	MEGHDOOT	
5.4	Value Classification	Under Marine Drive Heritage Precinct
0.1		
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Dog legged stone staircase with marble cladding
7.5	Openings	Regular openings with wooden frames and glazed shutters
	- p	·····g
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Rounded balconies
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Marble flooring in the lobby
		Staircases: Marble cladding
7.9	Interiors(Movable & Immovable)	Entrance canopy
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates
		painted.
7.11	Curtilege/ Unbuilt space/out	Parking sheds at the rear side of the building, Water tank ,pump
	buildings/landscape	room, planters
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good
9.9	Outbuildings	Good
9.10	Overall Condition	Good

A 8 5	MEGHDOOT	
10.0		TRANSFORMATION
10.1	Form	Additional grills , A.C.P. chajjas , balconies enclosed.
10.2	Structure	No transformation
10.3	Articulation & Finishes	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

# A85 MEGHDOOT

(a)



(C)



(b)



(d)



A86 Hon	g Kong Bank Building		175
	- <u></u>	Common Ref No: 175	
		Card No: 233	
		Ward (Part): A (Part II)	
		CS No: 151, 152 (Fort Division)	
		Plot Area: 1794.41 sq m.	
		B U Area: 91947.15 sq m.	7 J. THE
	Party H H H H	Date: 19/01/2005	L ROA
		Recorded by: Zankhana Prajapati	
			CAN WHITE CONTRACTOR
		Reviewed by: UDRI	
1		Int: Zankhana Prajapati, Sonal Modak	HAT HAT
		Ext: Zankhana Prajapati, Sonal	
		Modak	
		Photo Ref: 175_Hongkong Bank	Location Plan
		Building.	
4.5		Reviewed in 2013	
1.0		Denomination	
1.1	Name of Premises	Hong Kong Bank Building	
1.2	Earlier Name	Mercantile bank Building	
1.3	Built in:	Indeterminable	Extension Date: -
2.0		Access	
2.1	Main	Mahatma Gandhi Road.	
2.2	Subsidiary	Mahamaho Padhya Dr. Kane Road.	
3.0		Ownership pattern	
3.1	Present	Private	
3.2	Past	Private – The Secretary of State for	or India & others, The Merchantile
		Bank of India Ltd.	
3.3	Status	Owner/tenant	
4.0		Use	
4.1	Present	Bank and MSEB offices	
4.2	Past	Indeterminable	
4.3	Usage	Daily.	
5.0		Significance & Value Classification	on
5.1	Townscape (manmade)	The building is on the corner plo	
		Mahamaho Padhya Dr. Kane Road	
		The main access is from the Maha	
		access from the corner of the buildir	5
		It is one of the buildings in the Flora	
		at the ground floor in the Art-Deco S	
5.2	Architectural Description	Planning	
		The building is trapezoidal with the I	
		The building is ground plus seven-si	
		Entrance of the building is from Ma	
		end of the building, which leads to c	
		Toilets are beside the staircase and	
		The bank occupies most floors a	and only lew spaces have been
		occupied by the MSEB.	
		Features	

A86 Hone	g Kong Bank Building			175
5.3	Intrinsic	Building has a plain façade with minimal orna laid on the corner facing Flora Fountain, the Ground floor has an arcade, marked with sixth floor level, with continuous windows intercepted by huge circular columns; fifth horizontal band and sixth and seventh floor terrace. Besides this, the building has a l statues at entrance and an old decorative lan <b>Style</b> Building displays characteristics of the Art-De	building is clad in ma cornice band at first from first to fourth floor is defined as or are recessed with huge entrance door, np.	arble. and floor one part
5.4	Value Classification	A(arc), B(per), B (des), B (uu), E, F, G(grp),	Recommended	II
5.4	Value Classification	I(sce)	grade	A.
			grade	73.
6.0		Topography		
6.1	Floors	G + 7		
0.1				
7.0		Construction		
7.1	Plinth	Medium height plinth clad with granite.		
7.2	Walls	Load bearing wall clad with marble.		
7.3	Floor	Not visible due to false ceiling.		
7.4	Stairs	Three staircases are present.		
		The main staircase is C-shaped RCC and escapes- doglegged RCC. Has a parapet wall as divider between the flic		e fire
7.5	Openings	Rectangular door openings with heavy pan door. All windows are huge rectangular opening floors.		
7.6	Roofing	Flat terrace, with cable net, dish net, AC ur chimney.	nits, water tanks, blov	Ners,
7.7	Articulation	Circular column with decorative capital and lie	on statues at entranc	e.
7.8	Finishes	External walls are clad in marble.		
		Internal walls are plastered and painted. Flooring is varied - in some portions, marble,	granite and vitrified ti	iles.
7.9	Interiors (Movable & Immovable)	Movable - Immovable		
7.10	Compound/ Fence/ Gate	Building sits on the entire plot. No fencing is seen. Entrance door forms the entry gate.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape			
8.0		Services & Utilities		
8.1	Lighting	Supplemented by electric light fixtures.		
8.2	Ventilation	Central AC system.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing &	MCGM		
0.0	Sanitation)			

A86 Hong	g Kong Bank Building		175
8.6	Fire Precaution	Integrated fire precaution system with smoke detector	ors, sprinkler
		system, alarm system and fire extinguisher.	·
8.7	Other (HVAC/BMS/Security	Remote Accessing System and Central AC	
	Systems)		
9.0		Condition	
9.1	Plinth	Good - Well maintained.	
9.2	Walls	Good - External wall has some hoardings.	
9.3	Floor	Good - Well maintained.	
9.4	Stairs	Good - Well maintained.	
9.5	Openings	Good - Well maintained.	
9.6	Roofing	Good - At some area dampness was seen due to AC un	nits and water
7.0	Rooming	tank.	
9.7	Articulation & Finishes	Fair - Externally the building is in good condition, at c	ertain places
2		plaster and paint was peeling off.	pidooc
9.8	Services	Good - Well maintained.	
9.9	Out Buildings	-	
9.10	Overall Conditions	Good Maintenance Goo	bc
		level:	
10.0		Transformation	
1010	Form	No visible changes	
	Structure	No visible changes	
	Articulation & Finishes	No visible changes	
		, , , , , , , , , , , , , , , , , , ,	
11.0		DP Remarks/ Perceived Threats.	
		Plot falls under commercial zone in DP	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		-	
		References:	
		INTACH (1990) Preliminary unedited listing of Unprotecte	
		Monuments, Buildings and Structures listed for Conserval	
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) 7/	he Cities
		Within, Bombay : Eminence Designs Pvt. Ltd.	
		RAHUL MEHROTRA, GUNTER NEST and SANDHYA SA	
		(1994) The Fort Precinct in Bombay – Conserving an Ima	ge Centre, 2
		Vols, Bombay. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD	Vieual
		dictionary of Architecture, Division of International Thoms	
		Inc.	
		SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fa</i>	ort Malks
		Bombay : Eminence Designs Pvt. Ltd.	πι νναικο,
		bombay . Eminence Designs I VI. Elu.	

# A86 Hong Kong Bank Building















175

A87 Ban	k of India building	173		
	at or mana somating	Common Ref No: 173		
		Card No: 231		
		Ward (Part): A (Part II)		
		CS No: 153, 154 (Fort)         Plot Area: 2,219.90 sq m.         B U Area: 91947.15 sq m.         Date: 02/02/2005         Recorded by: Sonal Modak         Reviewed by: UDRI         Int: Sonal Modak, Zankhana		
	a man and and and and and a man a man	Pill Area: 01047 15 cg m		
	I MAILE IN THE THE MENTING			
TENET	The last starting and the second second	Date: 02/02/2005		
THE IN IN		Recorded by: Sonal Modak		
*****		Reviewed by: UDRI		
* # #				
The The Ma	and the second	Prajapati		
100 M		Internal photography permission		
S = at				
A State		Ext Sonal Modak Zankhanal		
		Prajapati Location Plan		
		Photo Ref: 173_Bank of India Bldg.		
		Reviewed in 2013		
1.0		Denomination		
1.1	Name of Premises	Bank of India building		
1.2	Earlier Name	Bank of India building		
1.3	Built in:	1942 Extension 1952 - fourth and fifth floors		
	2 3	Date: were added.		
-				
2.0		Access		
2.1	Main	Mahatma Gandhi Road - Pedestrian		
2.2	Subsidiary	Dr. Kane Road - Pedestrian		
2.2				
3.0		Ownership pattern		
3.0	Present	Private – Bank of India		
3.1				
	Past	Private – Bank of India, The Secretary of State for India & others.		
3.3	Status	Owner		
4.0		Use		
4.1	Present	Institutional - Bank		
4.2	Past	Institutional - Bank		
4.3	Usage	Daily		
5.0		Significance & Value Classification		
5.1	Townscape (Manmade)	The building stands on Mahatma Gandhi Road facing east.		
		It has a central main access from an arcade at ground level.		
		It has a massive rectangular front elevation with a central void forming		
		a small terrace at first floor level, defined by tall tapering octagonal		
		columns on either side spanning the height from the first floor to third		
		floor.		
5.2	Architectural Description	Planning		
		It has a wedge shaped, roughly rectangular plan with central access		
		from eastern side through an arcade.		
		Different floors cater to the various departments of the bank.		
		Parking, electric substation and AHU are located in the basement.		
		Staircases and service areas are located on rear (western) side of the		
		building.		
6		The building has symmetrical front (eastern) façade with an arcade on		
L	I	The samaling has symmotrical none (castern) laçade with an areade on		

A87 Bank	c of India building	173
	5	ground floor level. A central entrance bay defined by recessed,
		corbelled arches.
		Above is a high ceiling terrace at first floor level having two massive,
		three storey high circular columns resting on projecting cornices
		supported by two stone brackets.
		Central bay extends a floor higher.
		Features
		Corbelled pendant bracketed cornices above rectangular window
		opening at topmost floor level.
		Recessed, corbelled arches, at the central arched opening.
		Style
		It displays no specific style. Has influence of art deco, classical and
		vernacular styles of architecture.
5.3	Intrinsic	-
5.4	Value Classification	A(arc), B (per), B (des), B (uu), E, Recommended II A.
0.1		F, G(grp) grade
		giado
6.0		Topography
6.1	Floors	G + 5 with basement
0.1	110013	
7.0		Construction
7.0	Plinth	High plinth in grey ashlar masonry to accommodate ventilators for
7.1	FIIIIUI	basement.
7.2	Walls	
1.Z	vvalis	Thick load bearing external walls. Internal non-structural brick walls
7.0		with RCC columns to support RCC floors.
7.3 7.4	Floor	RCC slabs with deep RCC beams.
7.4	Stairs	Five staircases totally.
		Two of them open well RCC staircases on north and south end of the
		building.
7.5		Other two doglegged RCC staircases in the rear part of the building.
7.5	Openings	On either side of the central bay are rectangular windows at all floor
		levels recessed within the six engaged columns, which has a broad
7 (	Deefing	projecting cornice like the <i>chhajja</i> above.
7.6	Roofing	Partly sloping hipped roof with timber trusses. Overhangs supported
		by wooden brackets.
		Partly slightly sloping RCC slab at fourth floor level.
7.7	Articulation	Corbelled pendant brackets supporting projecting cornices.
7.8	Finishes	Exposed grey ashlar masonry externally on eastern facade. Western
		façade is clad with glass mosaic tiles. Internally walls are plastered
		and painted. Marble mosaic dado in stairwells. Flooring is of marble
7.0		mosaic tiles in most of the areas.
7.9	Interiors (Movable &	Movable
	Immovable)	·
		Immovable
		-
7.10		<b>T</b> I 1 111
7.10	Compound/ Fence/ Gate	The building covers the entire plot.
7.11	Curtilage/ Unbuilt space/ Out	Cooling towers at terrace level. Water storage tanks for fire fighting
	Buildings/ Landscape	equipment. Basement houses parking, BEST substation and Air
		Handling Unit of central AC system.
8.0		Services & Utilities
8.1	Lighting	Inadequate daylight available therefore almost completely dependent

A87 Banl	k of India building	173	
	<b>y</b>	on artificial lighting.	
8.2	Ventilation	Inadequate ventilation therefore almost completely dependent on forced ventilation.	
8.3	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5		MCGM	
8.6	Fire Precaution	-	
8.7	Other (HVAC/BMS/Security Systems)	-	
9.0		Condition	
9.1	Plinth	Fair – covered with planter boxes and all the ventilators are closed.	
9.2	Walls	Fair – Minor cracks are observed.	
9.3	Floor	Good – No evident damages seen, well maintained.	
9.4	Stairs	Good – No evident damages seen, well maintained.	
9.5	Openings	Good – No evident damages seen, well maintained.	
9.6	Roofing	Fair – Wooden members deteriorating in some parts. Reinforcement exposed in few areas of the RCC slab.	
9.7	Articulation & Finishes	Fair - Plaster peeling off in some areas due to dampness.	
9.8	Services	Good – Well maintained	
9.9	Out Buildings	-	
9.10	Overall Conditions	Good Maintenance Good level	
10.0		Transformation	
	Form	No visible changes	
	Structure	No visible changes	
	Articulation & Finishes	No visible changes	
11.0		DP Remarks/ Perceived Threats	
		Plot falls under Commercial Zone in DP	
12.0		Additional Notes/ References/ Documents available	
		Additional Notes:	
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.	

# A87 Bank of India building

Inninninnit











A 8 8	REGAL CINEMA		
		Common Ref no: A88 (Reviewed in 2013) Card No.: A-71 Ward (Part): A-III CS No.: Not available Plot Area: Not available B U Area: Not available Date: January, 2006 Record by: Gauri J, Deepti S Review by: Neera Adarkar Int: As above Ext: As above Photo Ref: A88 REGAL CINEMA a-h	
1.0		DENOMINATION	
1.1	Name of Premises	Regal Cinema	
1.2	Earlier Name	Not applicable	
1.3	Built In: 1933	Extension Date(if any): Not applicable	
2.0		ACCESS ROADS	
2.1	Main	Shahid Bhagatsing Marg (Colaba Causeway)	
2.2	Subsidiary	Chhatrapati Shivaji Maharaj Marg	
3.0		OWNERSHIP PATTERN	
3.1	Present	K. A. Kooka and F.H. Sidhwa.	
3.2	Past	Not available	
3.3	Status	Under Governor of Bombay	
4.0		USE	
4.1	Present	Entertainment and commercial	
4.2	Past	Entertainment and commercial	
4.3	Usage	Regular public use	
5.0		SIGNIFICANCE & VALUE CLASSIFICATION	
5.1	Townscape(Natural/Manmade)	Prominent junction on way to the Gateway of India and facing a large public space enclosed by heritage public buildings like the Old Secretariat, the Museum and the Royal Institute of Science (now also housing National gallery of Modern Art). Forms a part of Fort Precinct.	
5.2	Architectural Description	Regal Cinema a Art Deco style building responds sensitively like Eros Cinema (which was built after Regal) to the open space surrounded by very imposing Neo classical and Neo Gothic buildings. Its outer façade occupies the entire site to create continuity of the street edge as the building turns at the corner. The façade has simple features like stepped planes highlighted by Bas - Relief work.	
5.3	Intrinsic	Regal Cinema was formerly inaugurated by Governor of Bombay in 1933. The site for the Regal Cinema was occupied by old saluting	

A 8 8	REGAL CINEMA	
A00		battery and lay vacant for many years after government abandoned
		George Wittet's plan to include the battery as a part of an imposing
		ceremonial avenue. The plot was finally leased to K. A. Kooka and
		F.H. Sidhwa. (who also owned the Capitol Cinema)
5.4	Value Classification	Existing Grade: NA Recommended Grade: IIA
0.1		A(arc), B(des), I(sce), C(seh)
6.0		TOPOGRAPHY
6.1	Floors	G + 3
7.0		CONSTRUCTION
7.1	Plinth	Black Basalt stone plinth in coursed ashlar masonry
7.2	Walls	Brick masonry walls
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Openwell R.C.C. staircase
7.5	Openings	Rectangular openings with wooden frames and glazed shutters
7.6	Roofing	The auditorium has sloping roof and the rest of the structure has flat
	Ĭ	roof terrace
7.7	Articulation	The corner façade has vertical projections which give an identity to
		the theatre. Its outer façade occupies the entire site to create a
		continuity if the street edge as the building turns at the corner.
7.8	Finishes	Internally and externally cement plastered and painted
7.9	Interiors(Movable & Immovable)	The interiors are designed to create an impression of airiness,
		coolness and sized in harmony with the modern simplicity of
		exteriors.
7.10	Compound/Fence/Gate	Not provided
7.11	Curtilege/ Unbuilt space/out	None
	buildings/landscape	
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, good natural lighting
8.2	Ventilation	Natural and artificial, good natural ventilation
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Fire fighting sprinkler system
8.7	Other (HVAC/BMC/Security	Central air-conditioning unit
	Systems)	
9.0		CONDITION
9.1	Plinth	Good (No settlement or cracks observed)
9.2	Walls	Good (No dampness or cracks observed)
9.3	Floor	Good (No sagging observed)
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good (No leakage observed)
9.7	Articulation & Finishes	Good

A 8 8	REGAL CINEMA			
9.8	Services	Good (Drainage pipes need no replacement)		
9.9	Outbuildings	Good		
9.10	Overall Condition	Good	Maintenance level	Good
10.0		TRANSFO	RMATION	
10.1	Form	No transform	ation	
10.2	Structure	No transform	ation	
10.3	Articulation & Finishes	No transformation		
11.0		DP REMARKS/PERCEIVED THREATS Plot demarcated for Social Amenities in DP		
				1
12.0		ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION		
		Documents: C.S. Sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities Within Bombay 1995		

# A88 REGAL CINEMA
















A 8 9	FIRUZ-ARA	
A 8 9	CC 20 Ca W3 CS Plu B Da Re Re Int	
1.0		noto Ref :A89 FIRUZ-ARA a-e DENOMINATION
1.0	Name of Premises	Firuz-Ara
1.1	Earlier Name	Not applicable
1.2	Built In :1930's	Extension Date(if any): Not Applicable
1.0		
2.0		ACCESS ROADS
2.1	Main	Maharshi Karve Road (Queen's Road)
2.2	Subsidiary	Madam Cama road
3.0		OWNERSHIP PATTERN
3.1	Present	Lessee – Geeta Wife of Digambar, Pundalic Patkar and Digambar Pundalic Patkar
3.2	Past	Governor of Bombay (Lessor)
3.3	Status	Ownership
4.0		USE
4.1	Present	Residential, Commercial
4.2	Past	Residential, Commercial
4.3	Usage	Regular in residential and commercial use
5.0		SIGNIFICANCE & VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)	Located on corner plot at a junction of Maharshi Karve Marg, which is one of the major North-South arterial roads and Madam Kama Marg, which is one of the major East-West roads. It is a Corner Building facing the Oval Maidan diagonally. Forms a part of Fort Precinct.
5.2	Architectural Description	<ul> <li>Planning: It is a large building in modest Art Deco style with adequate light and ventilation</li> <li>Stylistic Classification: The Building is curved along the junction of the main and subsidiary road, the balconies facing the subsidiary road &amp; main road are large, and balconies facing the rear side are narrower.</li> <li>The front gate and most of the grills of the building are still the original Art Deco style grills.</li> </ul>

A 8 9	FIRUZ-ARA		
5.3	Intrinsic	Art Deco building representing its era. The various Art Deco style buildings on the newly reclaimed lands created a cohesive image. Like the Gothic buildings in their time represented the new face of the city and an expression of power, so did the Art Deco buildings and precincts symbolized the shift in expression to represent contemporary aspirations.	
5.4	Value Classification	A(arc), B(des), I(sce)Recommended Grade IIIUnder Oval Precinct, part of Fort Precinct and also under MarineDrive Heritage Precinct	
6.0		TOPOGRAPHY	
6.1	Floors	G+6	
7.0		CONSTRUCTION	
7.1	Plinth	Plastered masonry plinth	
7.2	Walls	Brick masonry wall	
7.3	Floor	R.C.C. floor slab	
7.4	Stairs	Open well wooden staircase with wooden railing.	
7.5	Openings	Regular openings with wooden frames and glazed shutters.	
7.6	Roofing	Flat roof with terrace	
7.7	Articulation	Curved corner Projecting balconies curved at the corner edges. The projecting balconies and the chajjas are enhanced by use of dark colours.	
7.8	Finishes	Walls : Externally and internally cement plastered and painted Flooring : Marble flooring in the lobby Staircases: Polished wooden staircase	
7.9	Interiors(Movable & Immovable)	Entrance Foyer	
7.10	Compound/Fence/Gate	Compound wall is plastered brick wall; Gates are M.S. gates (original) painted.	
7.11	Curtilege/ Unbuilt space/out buildings/landscape	Parking sheds at the rear side of the building	
0.0		SERVICES & UTILITIES	
8.0 8.1	Lighting	Natural and artificial, good natural lighting	
8.2	Ventilation	Natural and artificial, good natural ventilation	
<u>8.3</u>	Electricity	BEST	
8.4	Water Supply	MCGM	
8.5	Drainage (Plumbing and sanitation)	MCGM	
8.6	Fire Precaution	Not provided	
8.7	Other (HVAC/BMC/Security Systems)	Window air conditioning units	
9.0		CONDITION	
9.1	Plinth	Good (No settlement or cracks observed)	
9.2	Walls	Good (No dampness or cracks observed)	
9.3	Floor	Good	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good (External painting in progress)	

A 8 9	FIRUZ-ARA		
9.7	Articulation & Finishes	Good	
9.8	Services	Good (Drainage	e pipe needs no replacement)
9.9	Outbuildings	Good	
9.10	Overall Condition	Good	Maintenance Level Good
10.0		TRANSFORM	NATION
10.1	Form	No transformati	on
10.2	Structure	No transformati	on
10.3	Articulation & Finishes	No transformati	on
11.0	DP REMARKS/PERCEIVED THREATS	Plot falls under Residential Zone in DP	
12.0	ADDITIONAL NOTES/REFERENCES/DOCUME NTS AVAILABLE/RECOMMENDATIO NS & SUGGESTIONS FOR IMPLEMENTATION		S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, tra Bombay, the Cities within Bombay 1995











A 9 0	NARIMAN			
		Comm	on Ref no: A90	Not Available
(e)			lo.: Not available	
			Ward A	
		Di	.: Not available	
			ea : 1453.67	
	Plate And a second second		ea : 4657.51	_
	a ber and the state of the state		March, 2013	_
			by : Raveena Garg	_
			v by : Shraddha B.	_
			s above Ext: As above	
			Ref : A90 NARIMAN a-e	
		-		
1.0			DENOMINATION	
1.1	Name of Premises		Nariman	
1.2	Earlier Name		Not applicable	
1.3	Built In : 1940's		Extension Date(if any): No	ot Applicable
2.0			ACCESS ROADS	
2.1	Main		Maharshi Karve Road	
2.2	Subsidiary		Not applicable	
3.0			<b>OWNERSHIP PATTE</b>	RN
3.1	Present		Not available	
3.2	Past		Not available	
3.3	Status		Trust	
4.0			USE	
4.1	Present		Residential	
4.2	Past		Residential	
4.3	Usage		Regular in residential use	
5.0				LUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)			road front, which is one of the major
			North-South arterial roads	
5.2	Architectural Description			ling in modest Art Deco style with
			adequate light and ventila	
				conies are cantilevered and project
				f the grills of the building are still the
				s. Vertical and horizontal bands
				ad facing side of the building. Right -
			0	en on the edge of the road facing
			side.	
				d project out towards the left rear
			edge of the building.	
5.3	Intrinsic			nting its era. The various Art Deco
				ly reclaimed lands created a cohesive
			image. Like the Gothic bu	ildings in their time represented the

A 9 0	NARIMAN	
		new face of the city and an expression of power, so did the Art
		Deco buildings and precincts symbolized the shift in expression
		to represent contemporary aspirations.
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under
		Marine Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Vertical and horizontal moldings
7.8	Finishes	Walls: Externally and internally cement plastered and painted
		Flooring: Granite flooring in the lobby
		Staircases: Cement Terrazzo staircase
7.9	Interiors(Movable & Immovable)	None
7.10	Compound/Fence/Gate	No Compound Wall or Gates are provided
7.44		
7.11	Curtilege/ Unbuilt space/out	None
	buildings/landscape	
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, poor natural lighting
8.2	Ventilation	Natural and artificial, poor natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
0.7		
9.0		CONDITION
9.1	Plinth	Good (Plastering and painting in progress)
9.2	Walls	Good
9.3	Floor	Good (Needs cleaning and polishing)
9.4	Stairs	Good (no structural damage but needs cleaning and polishing)
9.5	Openings	Good (Some of the initial wooden frames replaces with
		aluminum sliding windows)
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good (Drainage pipe needs no replacement)
9.9	Outbuildings	Good
9.10	Overall Condition	Good (Plastering and painting in progress)

A 9 0	NARIMAN	
10.0		TRANSFORMATION
10.1	Form	No transformation
10.2	Structure	Extended windows in balconies
10.3	Articulation & Finishes	No transformation
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps- Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A 9 0 N A R I M A (a)

(b)



(C)

(d)





Δ91	SITA KIINI		
		Common Ref no: A91	Not Available
		Card No.: Not available	
16 3		Ward : Ward A	-
Sec. 45	and the state of the	CS No.: Not available	-
		Plot Area : 1420.28	
	the area light at the second	B U Area : 3770.107	_
	A PART - A PART	Date : March, 2013	
		Record by : Raveena Garg	
and a state	And the second second second second	Review by : Shraddha B.	
		Int : As above Ext: As above	
		Photo Ref :A91 SITA KUNJ a-e	
1.0	0	DENOMINATION	
1.1	Name of Premises	Sita Kunj	
1.2	Earlier Name	Not applicable	
1.3	Built In : 1930's	Extension Date(if any	v): Not Applicable
2.0		ACCESS ROADS	
2.1	Main	Maharshi Karve Roa	d
2.2	Subsidiary	Not applicable	
3.0		OWNERSHIP PA	TTERN
3.1	Present	Not available	
3.2	Past	Not available	
3.3	Status	Tenant	
4.0		USE	
4.0	Present	Residential	
4.2	Past	Residential	
4.3	Usage	Regular in residentia	luse
5.0		SIGNIFICANCE &	VALUE CLASSIFICATION
5.1	Townscape(Natural/Manmade)		arve road front, which is one of the major
		North-South arterial r	roads.
5.2	Architectural Description		e building in modest Art Deco style with
		adequate light and ve	
			n: Balconies are cantilevered and project out,
			of the grills of the building are still the original
			Vertical and horizontal bands (moldings)
			ing side of the building. Right -angled corner edges of the road facing side.
			ed and project out towards the left rear edge
		of the building.	and project out towards the left rear edge
5.3	Intrinsic		resenting its era. The various Art Deco style
		buildings on the new	ly reclaimed lands created a cohesive image.
			ings in their time represented the new face of
			ssion of power, so did the Art Deco buildings
			lized the shift in expression to represent
		contemporary aspira	lions.

A91	SITA KUNJ	
5.4	Value Classification	Under Oval Precinct, part of Fort Precinct and also under Marine
		Drive Heritage Precinct
6.0		TOPOGRAPHY
6.1	Floors	G+6
7.0		CONSTRUCTION
7.1	Plinth	Plastered masonry plinth
7.2	Walls	Brick masonry wall
7.3	Floor	R.C.C. floor slab
7.4	Stairs	Open well stone staircase
7.5	Openings	Regular openings with wooden frames and glazed shutters
7.6	Roofing	Flat roof and terrace
7.7	Articulation	Vertical and horizontal moldings
7.8	Finishes	Walls: Externally and internally cement plastered and painted
-		Flooring: Granite flooring in the lobby
		Staircases: Cement Terrazzo staircase
7.9	Interiors(Movable & Immovable)	None
7.10	Compound/Fence/Gate	No Compound Wall or Gates are provided
7.11	Curtilege/ Unbuilt space/out buildings/landscape	None
,		
8.0		SERVICES & UTILITIES
8.1	Lighting	Natural and artificial, poor natural lighting
8.2	Ventilation	Natural and artificial, poor natural lighting
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing and sanitation)	MCGM
8.6	Fire Precaution	Not provided
8.7	Other (HVAC/BMC/Security Systems)	Not provided (independent air conditioning units in the houses)
9.0		CONDITION
9.1	Plinth	Good (Needs plastering and painting)
9.2	Walls	Good (Needs plastering and painting)
9.3	Floor	Good (Needs cleaning and polishing)
9.4	Stairs	Good (no structural damage but needs cleaning and polishing)
9.5	Openings	Good (Some of the initial wooden frames replaces with aluminum
	- r	sliding windows)
9.6	Roofing	Good
9.7	Articulation & Finishes	Good (Needs plastering and painting)
9.8	Services	Good (Rusting in pipes, needs replacement)
9.9	Outbuildings	Good
9.10	Overall Condition	Good (Needs plastering and painting)
20		
10.0		TRANSFORMATION
10.1	Form	No transformation
10.2	Structure	Extended windows in balconies
10.3	Articulation & Finishes	No transformation

A 9 1	SITA KUNJ	
11.0	DPREMARKS/PERCEIVEDTHREATS	Plot falls under Residential Zone in DP
12.0	ADDITIONAL NOTES/REFERENCES/DOCUMENTS AVAILABLE/RECOMMENDATIONS & SUGGESTIONS FOR IMPLEMENTATION	Documents: C.S. sheets, D.P. Sheets, Eicher City Maps-Mumbai, Dwivedi, Mehrotra Bombay, The Cities within Bombay 1995

A 9 1	SITA KUNJ	
	(a)	(b)



(c)



(d)



N1 Stan	dard Chartered Bank building	(Grindlay's Bank)	172	
		Common Ref No: 172		
		Card No: 230		
		Ward (Part): A (Part II)		
The second second				
		CS No: 155 (Fort)	MAHATMA GANDHI RO	
A State of the second second	The state of the s	Plot Area: 1775.09 sq m.		
*		B U Area: -	NR A. MA	
1		Date: 11/02/2005		
and sail		Recorded by: Arun Wadhwa		
The second		Reviewed by: UDRI		
1		Int: Sonal Modak, Arun Wadhwa		
	20%	Internal photography permission	A D	
		denied		
	The second se	Ext: Sonal Modak, Arun Wadhwa	UNIVERSITY ROAD	
1 01		Photo Ref: 172_Grindlays Bank	for the second s	
			Location Plan	
		Building	Location Pian	
4.0		Reviewed in 2013		
1.0		Denomination		
1.1	Name of Premises	Standard Chartered Bank building		
1.2	Earlier Name	Grindlays Bank Building		
1.3	Built in:	1865	Extension -	
			Date	
			1	
2.0		Access		
2.1	Main	Mahatma Gandhi Road – Pedestria	n	
2.2	Subsidiary		11	
Z.Z	Subsidialy	University Road – Pedestrian Dr. Kane Road – Vehicular and Pedestrian		
		DI. Kane Roau – Venicular and Peo	Jestnan	
3.0	-	Ownership pattern		
3.1	Present	Standard Chartered Bank – Owner		
3.2	Past	Grindlays Bank – Owner		
3.3	Status	Owner.		
4.0		Use		
4.1	Present	Institutional – Bank		
4.2	Past	Institutional – Bank		
4.3	Usage	Daily		
т.Ј	- OSugo			
5.0		Significance & Value Classification	<b>n</b>	
5.0		Significance & Value Classificatio		
5.1	Townscape (Manmade)	The building is located on a corne		
			natma Gandhi Road on the eastern	
		5	und level. There are two subsidiary	
		entrances one from University Road on southern side and other one		
		from Dr. Kane Road on western sid		
		The West and South entries are res	served for staff.	
5.2	Architectural Description	Planning		
		Rectangular plan with an arcade on the east side through which the		
		building is accessed.		
		Ground floor serves as a grand bar	king lobby	
			staircase lead to offices on upper	
			eads to the parking in basement.	
		Services and toilet facilities are pl	aceu aluny me slues & rear. A.C.	
		plant is located in the basement.		

N1 Stand	V1 Standard Chartered Bank building (Grindlay's Bank) 172				
<u>N1 Stand</u>	lard Chartered Bank building ((	<ul> <li>Floor layout seems complicated due to internal subdivisions for functional and security concerns.</li> <li>Features</li> <li>Symmetrical main façade with central pediment.</li> <li>Yellow stone ashlar masonry with quoins, rusticated masonry. The front façade has an impressive large, plain pediment supported on six fluted circular Corinthian columns spanning first and second floor height with two square engaged columns at ends. Ground floor has rectangular simple openings and upper floors have semicircular arched openings. Ground floor has semicircular arched arcade with decorative band above.</li> <li>The side façade has Corinthian pilasters with predominantly semicircular arched, balustrade openings.</li> <li>The building has two prominent cornice bands, one at the pediment level and the second above arches. The interiors have fluted tall Corinthian columns.</li> <li>Style</li> <li>Influence of Neo-Classical and Baroque styles.</li> </ul>			
F 0	la tata a ta				
5.3 5.4	Intrinsic Value Classification	A(arc), B (per), B (des), B (uu), E, Recommended II A. F, G(grp) grade			
6.0		Topography			
6.1	Floors	G + 3			
7.0		Construction			
7.1	Plinth	Medium plinth in grey stone about 2 ft. in height.			
7.2	Walls	Load bearing rubble stone masonry walls & cast Iron pillars.			
7.2	Floor	Indeterminable due to false ceiling.			
7.4	Stairs	Totally three staircases. Main staircase is located near the north-east corner is open well timber staircase having lift shaft in the central open well. One straight flight RCC staircase along northern side in front part of the building. Separate doglegged timber staircase for staff is located along the southern side having direct entry from road.			
7.5	Openings	Arched external openings with wooden framed glazed panel shutters, some full door height also with separate ventilator panels. Ground floor arcade on front has semicircular arches with rustication.			
7.6	Roofing	Indeterminable			
7.7	Articulation	Corinthian column capitals. Square fluted engaged columns and fluted circular columns on front façade. Decorative keystones.			
7.8	Finishes	Yellow stone dressed ashlar on all façades with quoins, rusticated masonry and painted features. Original Minton floor tiles have been replaced with varied floor finishes ranging from Granite, marble & ceramic tiles. Plastered/ painted internal wall surfaces.			
7.9	Interiors (Movable 8 Immovable)	Movable - Immovable -			
7.10	Compound/ Fence/ Gate	Building itself forms the boundary along the road fronts on three sides, except north side with an adjacent bank building.			

N1 Standa	ard Chartered Bank building (G	rindlay's Bank) 172		
7.11	Curtilage/ Unbuilt space/ Out			
	Buildings/ Landscape			
8.0		Services & Utilities		
8.1	Lighting	Largely relies on artificial light.		
8.2	Ventilation	Centrally air-conditioned.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	Smoke detectors & Fire extinguishers.		
8.7	Other (HVAC/BMS/Security Systems)	Centrally with an. A.C plant. Electronic door locking devices. A/V monitoring of specific areas.		
9.0		Condition		
9.1	Plinth	Good - Except some plant growth & plumbing interventions externally.		
9.2	Walls	Good - Except service areas.		
9.3	Floor	Undetermined due to false ceilings.		
9.4	Stairs	Good - Except minor cracks & wear tear.		
9.5	Openings	Good - Except modifications made to door & window shutters.		
9.6	Roofing	Indeterminable		
9.7	Articulation & Finishes	Good - Façade restoration carried out. Very well maintained internal finishes.		
9.8	Services	Good - Well maintained		
9.9	Out Buildings	-		
9.10	Overall Conditions	Good Maintenance Good level		
10.0		Transformation		
10.0	Form	-		
	Structure	_		
	Articulation & Finishes	Signage strip runs continuously at first floor level affecting the stone		
		clad façade. White wash to arches and ornamental features. Gold color applied over internal column capitals.		
11.0		DP Remarks/ Perceived Threats		
11.0		Plot falls under Commercial Zone in DP		
12.0		Additional Notes/ References/ Documents available		
12.0		Additional Notes:		
		<b><u>References:</u></b> INTACH (1990) <i>Preliminary unedited listing of Unprotected</i> <i>Monuments, Buildings and Structures listed for Conservation.</i> FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual</i> <i>dictionary of Architecture</i> , Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i> , Bombay: Eminence Designs Pvt. Ltd.		

# N1 Standard Chartered Bank building (Grindlay's Bank)





(e)





(d)



(f)



172

V2 Army	and Navy Building		16		
	<u> </u>	Common Ref No: 167	י וב		
		Card No: 225			
		Ward (Part): A (Part III)	A. S. D'MELLO ROAD		
		CS No: 146			
		Plot Area: 1861.21			
2					
Concession of		B U Area: -			
A hour base		Date: 10/11/2004	GA		
		Recorded by: Arun Wadhwa	AND HIROAD		
		Reviewed by: UDRI			
		Int: Arun Wadhwa, Zankhana			
1000	A DESCRIPTION OF THE PARTY OF T	Prajapati			
		Ext: Arun Wadhwa, Zankhana	\$*11		
and the second	The second se	Prajapati	Location plan		
		Photo Ref.: 167_Army and Navy	-		
		building			
		9	-		
1.0		Reviewed in 2013			
1.0		Denomination			
1.1	Name of Premises	Army and Navy Building			
1.2	Earlier Name	Army and Navy Store.			
1.3	Built in:	Commenced 1897, Completed	Extension Date: -		
		1904.			
2.0		Access			
2.1	Main		r and podestrian		
		Mahatma Gandhi Road – Vehicular and pedestrian			
2.2	Subsidiary	A. S. D' Mello Road. – Service enti	ſ <u>ÿ</u> .		
2.0		Our enchie nettern			
3.0		Ownership pattern			
3.1	Present	Private, owned by Tata Sons.			
3.2	Past	Private, Army Navy store			
3.3	Status	Ownership with multi tenanted pre	mises.		
4.0		Use			
4.1	Present	Departmental store on ground floo	r. several private offices and		
		Department of Fisheries located or			
4.2	Past	Exclusive Departmental store sellir			
			ig navar merchandise.		
4.3	Usage	Daily.			
<b>F</b> 0					
5.0		Significance & Value Classificat			
5.1	Townscape (Manmade)		buildings facing Kala Ghoda square		
		Accessed from east side front façade and also subsidiary entry from			
		west side narrow lane. Conceived	as a unifying street façade and		
			ntinuous pedestrian arcade with adjoining buildings in the prominen		
		intersection of Kala Ghoda.			
5.2	Architectural Description	Planning			
		0	ot leaving marginal open space wit		
		David Sassoon Library to the south			
		North. Probably conceived as oper			
		structure is supported on a steel co			
		The building originally had a centra			
		during major renovation work in 19			
		stretches up to the street line with projecting porch. Staircases are pla			

N2 Army	and Navy Building	167		
		<ul> <li>of the building. The rear side has two entries at either end meant to serve as service as well as subsidiary access. The top floor cantilevers out beyond the building line on the rear side and is supported on decorative brackets.</li> <li>Features</li> <li>Symmetrical stone dressed front façade with rich ornamental features and topped by a distinct pediment feature. Projecting central bay Various decorative elements like arched openings, cornice bands, columns, pilasters, and stone balustrades.</li> <li>Style</li> <li>Neo Classical with rich ornamentation on the front facade.</li> </ul>		
5.3	Intrinsic	Amongst the earliest buildings to have an RCC slab construction resting on steel girders. Amongst the earliest to have a basement. Structural column - girder detail seems an innovative construction technique.		
5.4	Value Classification	A(arc), B(per), B (des), E, F, I(sce)		
6.0		Topography		
6.1	Floors	G + 3 upper floors with partial mezzanine to the rear side on the first and second floors. Mezzanines have been added. Presence of an elevated overhead water tank at a considerable height from the terrace level		
7.0		Construction		
7.1	Plinth	The plinth rises unto two feet, constructed in dressed buff basalt. The two side facades are constructed in rough black basalt. A large portion of the building has a basement.		
7.2	Walls	<ul> <li>External load bearing brick walls with local sandstone ashlar masonry and lime plastered internally.</li> <li>The front façade is in dressed buff basalt and light colored, porbander stone forming the projecting features and ornamentation.</li> <li>The side and rear walls are in black basalt with light colored porbander stone for projecting features.</li> </ul>		
7.3	Floor	The floors are constructed in RCC, one of the earliest examples of this type of construction, supported on steel girders. The girders rest on round plain cast iron columns.		
7.4	Stairs	Both the staircases are open well, constructed in stone slab supported (cantilevered) from the load bearing walls. Wooden members strengthen it from below. The side to the open well has wooden handrail and decorative iron railing.		
7.5	Openings	-		
7.6	Roofing	Series of pitched roof supported on teakwood trusses and covered with mangalore tiles. The central portion has an asbestos cement sheet roof being a later addition.		
7.7	Articulation	The detailing has been sculpted on stone and finished with plaster		
7.8	Finishes	Dressed buff basalt and soft porbander stone as projecting features form the exterior finishing to the front façade. Two sides and rear façade are in black basalt along with plastered surfaces. Internally the surfaces are plastered and painted. Extensive modifications have led to various different kind of paint and texture finishes.		

	and Navy Building	16		
7.9	Interiors (Movable &	Movable:		
	Immovable)	-		
		Immovable: Multiple decorative cast iron objects e.g. spiral staircase		
		brackets, etc.		
7.10	Compound/ Fence/ Gate	External wall of the building forms the compound on the front and rea		
		side.		
		The sides along the north and south have low stone compound with		
		iron railing above.		
7.11	Curtilage/ Unbuilt space/ Out	-		
	Buildings/ Landscape			
8.0		Services & Utilities		
8.1	Lighting	Large door and window openings provide ample daylight, certain		
		portion of corridor and staircase seems inadequately lit, supplemente		
		with electric lighting.		
8.2	Ventilation	Natural ventilation through large windows, forced ventilation using air		
		conditioners. Internal passages are inadequately lit.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing &	MCGM		
0.0	Sanitation)			
8.6	Fire Precaution	Absence of integrated fire fighting system though individual tenanted		
0.0	The Treedulion	offices have installed smoke detectors, fire alarms, etc.		
8.7	Other (HVAC/BMS/Security	Presence of central air-conditioning system for the departmental store		
0.7	Systems)	at the ground floor. Several offices have installed window and split uni		
	Systems)	air-conditioners. Absence of integrated security system for the whole		
		building. Installation of the air conditioning plant on the terrace of the		
		first floor.		
9.0		Condition		
9.1	Plinth	Good		
9.1	Walls	Good		
9.3	Floor	Good- The floor seems to be stable in most places.		
9.4	Stairs	Good		
9.5	Openings	Good		
9.6	Roofing	Good		
9.7	Articulation & Finishes	Good		
9.8	Services	Good		
9.9	Out Buildings	Good		
9.10	Overall Conditions	Good Maintenance level: Good		
10.0		Transformation		
	Form	No change		
	Structure	Mezzanine floors have been added. The building originally had a		
		central courtyard, which was closed during major renovation work in		
		1950's		
	Articulation & Finishes	Detailing has been insensitively painted.		
11 0		DP Remarks/ Perceived Threats		
11.0		DP Remarks/ Perceived Threats Plot demarcated as commercial zone and Government Offices		

N2 Army and Navy Building	167
12.0	Additional Notes/ References/ Documents available
	Additional Notes:         The Army and Navy Stores was designed by a local firm, Gostling and Morris, Architect and Civil Engineers         References:         INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.         RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT (1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2 Vols, Bombay.         FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc.         SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.         Conservation report on Army & Navy building, Bombay, Vikas Dilawari

### N2 Army and Navy Building







(e)









(d)



(f)






n and the second s		
n		
n		
'n		
In		
in		
Mahatma Gandhi Road and Karmaveer Bhaurao Patil Marg - vehicular and pedestrian		
oads, with		
aurao Patil		
Itheast		
utheast		
n scale on		
n scale on fferent		
n scale on		
n scale on fferent on the south		
n scale on fferent		
n scale on fferent on the south		
n scale on fferent on the south in entrance		
n scale on fferent on the south in entrance spacious		
n scale on fferent on the south in entrance spacious I court.		
n scale on fferent on the south in entrance spacious		

N3 Institu	Ite of Science	155				
		Subsidiary entrances from the west and east side lead to the				
		secondary staircases.				
		Long annex wing has been added to the north side connected from the				
		west end. Also an addition has been carried out from the central				
		staircase wing housing the Library. Small ancillary structures are				
		present in the internal open space.				
		Features				
		Grand entrance bay has slightly recessed colonnaded central portion				
		marked by projecting balcony above with circular ionic columns rising				
		two floors high surmounted by distinct frieze band and decorative relief				
		feature.				
		Front side stone facade has rusticated semicircular arch verandahs on				
		the ground floor and rectangular openings on the two upper floors with				
		infill relief panels and stone <i>jali</i> ventilator and parapet. Terrace parapet				
		is distinctly treated as stone baluster parapet making the entire edge light in appearance.				
		<ul> <li>Projecting stone balconies supported on large brackets and decorative parapet feature. Distinct keystone feature surmounting the semicircular arch openings.</li> <li>Style</li> <li>The building displays features of the Renaissance Revival style of</li> </ul>				
		architecture				
5.3	Intrinsic	-				
5.4	Value Classification	A (arc), B (per), B(des), B(uu), E, F, G (grp), Recommended I				
		l(sce) grade				
6.0		Topography				
6.1	Floors	G+3.				
7.0		Construction				
7.1	Plinth	High plinth height dressed in rough buff stone				
7.2	Walls	Load bearing rubble masonry stonewalls.				
7.3	Floor	RCC slab resting on load bearing walls.				
7.4	Stairs	Three staircases – central grand curvilinear C-shaped stone staircase				
		with large open atrium under the domed space with lift installed in the				
		open shaft at the end of East wing.				
		Regular double flight stone stair with semi circular mid-landing in the				
		west wing.				
7.5	Openings	Semicircular arch openings on ground floor verandahs and rectangular				
		on two upper floors.				
		Segmental arch window openings on the rear facades. Wooden				
		paneled door and wooden glazed panel window shutters with separate				
		ventilator openings in the arch portions.				
7.6	Roofing	Flat RCC slab over long curvilinear wings and large dome over the				
		central staircase block.				
7.7	Articulation	Central portion emphasised with high circular columns, frieze band,				
		stone jali, decorative relief feature, prominent keystone on semicircular				
		arches, semicircular arch verandahs on the ground floor, projecting				
		stone balconies supported on large brackets.				
7.8	Finishes	Buff colored Kurla stone dressed ashlar course external wall surfaces				
		and plaster painted internal finishing. Ceramic tile floor finishes.				
		Polished wooden door and window shutters.				

N3 Institu	ute of Science	155
7.9	Interiors (Movable &	
	Immovable)	<b>Immovable</b> Standing Marble statue of Baron Sydenham, Governor of Bombay in the central foyer of main staircase. Wooden folding
		benches in the stepped lecture halls on the second floor.
7.10	Compound/ Fence/ Gate	Original small stone post and chained fence now replaced with iron frame and chain link.
7.11	Curtilage/ Unbuilt space/ Out	Numerous small structures located in the central open space including
	Buildings/ Landscape	a G+1 Radioactive Research Centre and single storied sloping roof
		canteen, staff union office and pump room structures.
8.0		Services & Utilities
8.1	Lighting	Adequate natural light in passages and service areas supplemented
		by artificial light.
8.2	Ventilation	Adequate natural ventilation supplemented by artificial ventilation
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Fire extinguishers and dry riser arrangement.
8.7	Other (HVAC/BMS/Security	Window and Split air conditioning units
	Systems)	
9.0		Condition
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Fair
9.4	Stairs	Fair
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Fair
9.9	Out Buildings	Fair
9.10	Overall Conditions	Good Maintenance level: Good
10.0		Transformation
10.0		Transformation
	Form	Annex building has been added along the north side
	Structure	-
	Articulation & Finishes	Cement pointing has been carried out on stone dressed facades.
11.0		DP Remarks/ Perceived Threats
		Plot falls under Educational Amenities in DP
12.0		Additional Notae/ Deferences/ Decuments augitable
12.0		Additional Notes/ References/ Documents available Additional Notes:
		George Wittet, consulting Architect to the Government of India designed the institute in Renaissance revival style along with Prince of Wales Museum.
		Foundation stone was laid in 1911, was opened only in 1920 due to the outbreak of World War I in 1914.
		Building has a height of 50 feet with a total frontage of 400 yards. References:
		INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.

N3 Institute of Science	155
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual</i> <i>dictionary of Architecture</i> , Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks</i> , Bombay : Eminence Designs Pvt. Ltd.

### N3 Institute of Science













(f)



N4 Sir C	awasji Jahangir Hall- NGMA				156	
		Common Ref No: 156	ESSERE C		T	
		Card No: 214	KOAD		DEL.	
		Ward (Part): A (Part III)	TILIVA	Tain A		
		CS No: Indeterminable	NURAO	WON TUSROO		
			THE REAL	MUNK	BASH WAL	
		Plot Area: Indeterminable	·	ATUA C	AC HON	
3	मध्यितायुत्ते का कता मध्यति पुष्ठ सरकायमञ्च अर्थयोग पहिलक होत	B U Area: -	KAR	4HAM	ant /	
	The second se	Date: 10/11/2004	MADANCA	<b>O</b> c, <b>C</b>	APHID BH	
No. A DUTIT		Recorded by: Zankhana Prajapati	121000	ROAD Roo .	91	
		Reviewed by: UDRI	The second	1 3		
1. 日前		Int: Arun Wadhwa, Zankhana		wased monthly	10	
	LET.	Prajapati		Lean Marine State		
		Ext: Arun Wadhwa, Zankhana	WATMAL	Ha S	APPEN IN	
		Prajapati	Lar AC	A STAND	18	
		Photo Ref.: 156_Cowasji Jehangir	-	Location Plan		
		Hall				
			4			
		Reviewed in 2013				
1.0		Denomination				
1.1	Name of Premises	National Gallery of Modern Art				
1.2	Earlier Name	Sir Cawasji Jahangir Hall				
1.3	Built in:	Foundation stone laid in 1911, com	pletion in	Extension	-	
		1917				
		opened in 1920 during World War				
				ł		
2.0		Access				
2.1	Main	Junction of Mahatma Gandhi Road	and Madan	n Cama Road		
2.2	Subsidiary					
Z.Z		-				
2.0		Ourporchin a attaine				
3.0		Ownership pattern				
3.1	Present	Government of Maharashtra				
3.2	Past	Government of Bombay				
3.3	Status	Owner				
4.0		Use				
4.1	Present	Art Gallery and Lecture Hall				
4.2	Past	Public hall for Theatre, Performance	e. Lecture	etc.		
4.3	Usage	Daily				
т.Ј						
5.0		Significance & Value Classificati	on			
5.0		Significance & Value Classificati			الاعلان ر	
5.1	Townscape (Manmade)	Prominent corner building located a				
		wings on the Madam Cama Road,				
		The building is placed along a row				
		Madam Cama Road and is surrounded with buildings of different				
		styles and periods including the YWCA, St. Annes School on the south				
		and Wellington fountain to the east.				
		The curvilinear building form is a site response, with its main entrance				
		from south side of Madam Cama Road.				
		It forms the vertex to the two wings of the Institute of Science.				
		The curved building with its dominating entrance dome forms an				
		important landmark in the urban sc				
5.2	Architectural Description	Planning	upc.			
J.Z			an ovtondo	d norch at the		
		The building is circular in plan with intersection facing the Wellington facing the Well		u porch at the		
		In a second the second the Wellington to	מוביוחות			

N4 Sir Ca	wasji Jahangir Hall- NGMA		156
		The circular built space has a continuous verandal staircases on both sides beyond which Institute of continues. The present renovation to turn it into a museum ha galleries on split-levels with a central void. The portion below the topmost gallery is designed with an inbuilt projector room. The space below the shallow dome forms a large of Central air conditioning unit, store and offices are p gallery on the rear side. <b>Features</b> The front has a large magnificent opening framed I stone piers with a pair of ionic columns supporting Semi-circular arched openings with ornate keyston ground floor verandah. Double storied colonnades upper portion, with horizontal lintel stone openings balusters and projecting cornice bands. The front porch with double colonnaded front and s arched openings on the two sides. The two projecting blocks enclosing staircases are stone masonry punctuated with large openings and a projecting bafor supported on highly ornate brackets. <b>Style</b> The building displays features of the Renaissance architecture	Science building is semi circular as a lecture hall circular gallery. blaced below the by two large ornate entablature. ie all around the punctuate the and carved side piers support well composed in alcony at the first
5.3	Intrinsic	This was the first cultural hall dedicated to the peop	ple of Bombay
5.4	Value Classification	A(arc), A(his), A(cul), B(per), B (des), B (uu), D(bio), E, F, G(grp), I(sce)	Recommended I grade:
6.0		Topography	
6.1	Floors	G+3	
7.0		Construction	
7.1	Plinth	The plinth is very low, constructed in buff basalt in	
7.2	Walls	The walls are stone load bearing masonry, includir The verandah walls are in shallow dressed courses	S.
7.3	Floor	The original flooring in verandahs and lobbies is su arches. The renovated art gallery has ribbed floors support columns and shear walls.	
7.4	Stairs	Two Staircases. Both the staircases are open well, stone slab supported (cantilevered) from the side le with a wooden handrail and decorative cast-iron ra	bad bearing walls
7.5	Openings	Ground floor verandah has semicircular arched op have flat stone lintels. The curvilinear verandah wa teakwood doors and windows. The projecting staircase block has openable glaze Small circular fixed glass panels at the upper part of	enings, upper levels Il has openings with d paneled windows. of the shallow dome.
7.6	Roofing	Circular shallow dome in concrete, central portion accommodate openings for light. The surrounding verandah and staircase slab has terrace.	raised to

N4 Sir Ca	wasji Jahangir Hall- NGMA	156	
7.7	Articulation	Ornate key stone detail of the semicircular arched opening.	
		Cantilevered projecting balcony supported on ornate stone brackets at	
		the staircase entry.	
		The overlapping stone courses spanning the horizontal lintel opening	
		indicate sound construction technique.	
7.8	Finishes	External building facade and verandahs are dressed in buff basalt,	
		internally the surfaces are plastered and finished in Plaster of Paris.	
		Gypsum board panels used within the galleries.	
		Verandah and lobby areas have marble flooring whereas the	
7.0		renovated galleries have wooden flooring.	
7.9	Interiors (Movable &	Movable	
	Immovable)		
		Immovable	
		Marble statue of Sir Cowasji Jehangir at the entrance lobby.	
7.10	Compound/ Fence/ Gate	Originally very low stone verticals with iron chain connectors served as	
		compound fence. Presently a stone wall with high iron railing is built in	
		between the original stone verticals.	
		High iron gates with decorative motif atop on both sides of the porch.	
7.11	Curtilage/ Unbuilt space/ Out	Underground water tank and an electrical transformer in the open	
	Buildings/ Landscape	space to the south of the entry.	
		Plant and shrub growth around the entrance porch.	
		• • • • • • • • • • • • • • • • • • •	
8.0		Services & Utilities	
8.1	Lighting	Artificial lighting throughout the building as it serves as an enclosed	
0.0		gallery space.	
8.2	Ventilation	Large central air conditioning system for the gallery spaces.	
8.3 8.4	Electricity Water Supply	BEST MCGM	
8.5	Drainage (Plumbing &	MCGM	
	Sanitation)		
8.6	Fire Precaution	Smoke detector and fire alarm system with fire fighting equipment has	
07		been installed.	
8.7	Other (HVAC/BMS/Security	Audio-visual camera surveillance system, private and state security	
	Systems)	guards Large central air conditioning plant	
1			
9.0		Condition	
9.1	Plinth	Good- organic growth and weathering has deteriorated the stone	
		COURSES.	
9.2	Walls	good - rainwater seepage has led to deterioration of stone masonry in	
		the staircase block.	
		The interior is modified with gypsum board panel for exhibition.	
9.3	Floor	Fair - original upper floor dismantled and redesigned	
9.4	Stairs	Good	
9.5	Openings	Good	
9.6	Roofing	Good	
9.7	Articulation & Finishes	Good	
9.8	Services	Fair	
9.9	Out Buildings	-	
9.10	Overall Conditions	Good Maintenance Good	
		level	

N4 Sir Ca	ir Cawasji Jahangir Hall- NGMA 156		
10.0		Transformation	
	Form	-	
	Structure	The whole internal space has been transformed by constructing split level galleries supported on additional columns and shear walls.	
	Articulation & Finishes	-	
11.0		DP Remarks/ Perceived Threats	
		Plot demarcated for Social Amenities in DP	
12.0		Additional Notes/ References/ Documents available	
		<ul> <li><u>Additional Notes:</u> <ul> <li>The Hall is nearly a hundred feet in diameter. With a seating capacity of 1200, the original Hall was the venue for art shows, lectures and musical performances for several years. The interiors were entirely redesigned in 1996 by Delhi architect, Romi Khosla, to accommodate the Bombay branch of the National Gallery of Modern Art.</li> <li><u>References:</u></li></ul></li></ul>	



























l1 Westerr	n Railway Headquarters				163
		Common Ref No: 163	Harris B.		100
		Card No: 221	TEL	TO TA	
	~ ]	Ward (Part): A (Part II)			
	1	CS No: 710, 1/710 (Fort division)	Z	T.C. S	
	finite .		Maharshi Karve Road	arine	
		Plot Area: 14656.28 sqm.	SHIK	Line	
- inte		B U Area: -	ane 7	S.	
Carente -		Date: 18/04/2005	Roa		
and the		Recorded by: Sonal Modak	E a	2	
	MANO - CONTRACTOR	Reviewed by:	9 (F		10
		Int: Permission denied		Veer Nariman	Road
		Ext: Sonal Modak	-19)	1	Sold .
Terra Conterna	ALL AND ALL ALL ALL ALL ALL ALL ALL ALL ALL AL	Photo Ref.: 163_Western Railway	P P	1	
		HQ a-j		ation Plan	
		Reviewed in 2013			
1.0		Denomination			
1.1	Name of Premises	Western Railway Headquarters			
1.2	Earlier Name	Bombay Baroda & Central India Rai	ilway Head Qua	arters	
1.3	Built in:	Commenced in May 1894, Complete		Extension	-
		1899	J	Date:	
2.0		Access			
2.1	Main	Maharshi Karve Road– vehicular an	nd nedestrian		
2.2	Subsidiary	Veer Nariman Road, V. Thackersey			
2.2			Mary		
3.0		Ownership pattern			
3.0 3.1	Drocopt	Central Government			
	Present				1
3.2	Past	BB – LC. 1 Railway Companies (off	icers) & others,	, The Municipa	1
2.2	Chatura	Corporation of Bombay & others			
3.3	Status	Owner			
4.0		Use			
4.1	Present	Railway Offices			
4.2	Past	Railway Offices			
4.3	Usage	Daily			
L					
5.0		Significance & value Classificatio			
5.1	Townscape (Manmade)	Prominent building located at the jui	nction of Maha	rshi Karve Roa	ad and
		Veer Nariman Road			
		Veer Nariman Road The building is a city landmark on a	n important and	d busy junctior	I,
				d busy junctior	١,
		The building is a city landmark on a	hgate area.		
		The building is a city landmark on a dominating the skyline of the Church	hgate area. buildings of dif	ferent styles a	nd
		The building is a city landmark on a dominating the skyline of the Church The building is juxtaposed between	hgate area. buildings of dif	ferent styles a	nd
		The building is a city landmark on a dominating the skyline of the Churcl The building is juxtaposed between periods of Architecture, forming an i	hgate area. buildings of dif mportant natur	ferent styles a re of the towns	nd cape
		The building is a city landmark on a dominating the skyline of the Church The building is juxtaposed between periods of Architecture, forming an i of the city.	hgate area. buildings of dif mportant natur	ferent styles a re of the towns	nd cape
		The building is a city landmark on a dominating the skyline of the Church The building is juxtaposed between periods of Architecture, forming an i of the city. The building overlooks Oval Maidan	hgate area. buildings of dif mportant natur i in front with, re	ferent styles a e of the towns ow of Art Decc	nd cape
		The building is a city landmark on an dominating the skyline of the Church The building is juxtaposed between periods of Architecture, forming an i of the city. The building overlooks Oval Maidan buildings and	hgate area. buildings of dif mportant natur i in front with, r University build	ferent styles a e of the towns ow of Art Decc	nd cape
		The building is a city landmark on an dominating the skyline of the Church The building is juxtaposed between periods of Architecture, forming an i of the city. The building overlooks Oval Maidan buildings and Victorian Neo-Gothic buildings like to building, High Court and on its eithe	hgate area. buildings of dif mportant natur in front with, r University build r side.	ferent styles a e of the towns ow of Art Decc ing, Secretaria	nd cape o it
		The building is a city landmark on an dominating the skyline of the Church The building is juxtaposed between periods of Architecture, forming an i of the city. The building overlooks Oval Maidan buildings and Victorian Neo-Gothic buildings like U	hgate area. buildings of dif mportant natur in front with, r University build r side. an old gate with	ferent styles a e of the towns ow of Art Decc ing, Secretaria	nd cape o it
5.2	Architectural Description	The building is a city landmark on an dominating the skyline of the Church The building is juxtaposed between periods of Architecture, forming an i of the city. The building overlooks Oval Maidan buildings and Victorian Neo-Gothic buildings like t building, High Court and on its eithe The structure stands on the site of a and is thus integral to the history of	hgate area. buildings of dif mportant natur in front with, r University build r side. an old gate with	ferent styles a e of the towns ow of Art Decc ing, Secretaria	nd cape o it
5.2	Architectural Description	The building is a city landmark on an dominating the skyline of the Church The building is juxtaposed between periods of Architecture, forming an i of the city. The building overlooks Oval Maidan buildings and Victorian Neo-Gothic buildings like t building, High Court and on its eithe The structure stands on the site of a	hgate area. buildings of dif mportant natur in front with, r University build r side. an old gate with	ferent styles a e of the towns ow of Art Decc ing, Secretaria	nd cape o it

11 Wester	rn Railway Headquarters	163
		The building is constructed in grey basalt stone with a central dome
		rising above. The unique central tower has been designed to be square from the base up to 100 feet in height, then becoming an octagon that gradually diminished into a smaller octagon culminating in a circular masonry dome.
		Multiple smaller domes form the skyline with finial like features at the top.
		<ul> <li>Window openings have semicircular and pointed arches in various sizes with ventilators above</li> <li>Narrow smaller acoupled arched openings with the arches supported on yellow stone circular column with corinthian capitals form one of the significant features of the facades.</li> <li>Continuous bands at each floor level, decorative bands, dentils, quatrefoil arched openings, lion carved in stone atop the gable ends, gable ends with large rose window are some of the integral features displayed on facades.</li> <li>The two porches on the western and southern facades provide additional strength and character to the building.</li> <li>Stevens placed the representation of 'Engineering' in Bath stone atop the central gable. The group comprised a lady accompanied by two children on either side, with her holding a locomotive engine in her right hand and supporting herself on a wheel to her left. Seven other carved figures in Porbunder stone of griffins holding the BB&amp;CI monogrammed shield were placed on the smaller gables.</li> <li>The central statue was commissioned from the studio of Roscoe Mullins of London together with two carved medallion portraits of Colonels French and Kennedy, the pioneers of the Company, which were placed in circular panels between the arches of the carriage porch on the west.</li> <li>Style</li> <li>The building shows evident influence of Indo Saracenic style of Architecture</li> </ul>
5.3	Intrinsic	
5.4	Value Classification	A(arc), A(his), B(per), B(des), B(uu), C(seh), E, F, Recommended I I(sce)
6.0		Topography
6.1	Floors	G+2 with central and side domes higher than the rest of the structure
7.0		Construction
7.1	Plinth	Medium plinth about two ft high in grey rough dressed ashlar masonry.
7.2	Walls	Indeterminable
7.3	Floor	Indeterminable
7.4	Stairs	Indeterminable
7.5	Openings	Arched openings with wooden frame partly glazed panels with wooden louvers at bottom.
7.6	Roofing	Timber truss with Mangalore roofing tiles.
7.7	Articulation	Corinthian column capitals, dentils, quatrefoil openings etc.
7.8	Finishes	Externally grey ashlar masonry. Internal finishes indeterminable.
7.9	Interiors (Movable & Immovable)	Movable - Immovable
L	I	

11 Weste	rn Railway Headquarters		163	
		-		
7.10	Compound/ Fence/ Gate	A stone compound wall with MS fencing atop.		
7.11	Curtilage/ Unbuilt space/ Out	Indeterminable.		
	Buildings/ Landscape			
8.0		Services & Utilities		
8.1	Lighting	Indeterminable		
8.2	Ventilation	Indeterminable		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM		
8.6	Fire Precaution	Indeterminable		
8.7	Other (HVAC/BMS/Security	Indeterminable		
	Systems)			
9.0		Condition		
9.1	Plinth	Good		
9.2	Walls	Indeterminable		
9.3	Floor	Indeterminable		
9.4	Stairs	Indeterminable		
9.5	Openings	Fair - At some places shutters have been replaced.		
9.6	Roofing	Indeterminable		
9.7	Articulation & Finishes	Good		
9.8	Services	Indeterminable		
9.9	Out Buildings	Indeterminable		
9.10	Overall Conditions	Good Maintenance Good		
10.0		Transformation		
10.0	Form	No visible changes from outside		
	Structure	No visible changes from outside		
	Articulation & Finishes	No visible changes from outside		
11.0		DP Remarks/ Perceived Threats		
		Plot falls under Government Offices		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes:		
		Frederick William Stevens designed the building on simple lir		
		the total effect determined by the outline and massing. The building,		
		with a length of 276 feet along the western façade and a centur		
		rising to 160 feet, has a facing of coursed blue basalt stone domes, mouldings, capitals, columns, cornices and		
		enrichments in Porbunder stone, white Kurla and Dhrangad		
		sandstone. Later, when these weathered badly, they were		
		with facsimiles in bronze, crafted by C Burns. The embelli		
		were prepared by Mr Gomez and students of the School of A		
		the supervision of the Principal, Mr Greenwood. The contra		
		the foundations were Gamajee Balajee and Company and t		
		the superstructure Jagooji Hanmantrao and Company. The	coloured	

I1 Western Railway Headquarters	163
	Maw's tiles, marble and coloured glasswork were executed by Sorabji Warden & Company while the contractors for the drainage and water supply and fittings were Richardson and Cruddas. The entire open ground both in front and behind the main building was laid out as a garden, separated from the road by ornamental railings and gates. The total cost of the building including drainage and water supply was exactly that estimated by Stevens – Rs 750,000. <u>References:</u> INTACH (1990) <i>Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation.</i> Eicher Goodearth Ltd. (2002) <i>City Map – Mumbai</i> , Mumbai. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual dictionary of Architecture</i> , Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>Fort Walks,</i> Bombay : Eminence Designs Pvt. Ltd. ABHA NARAIN LAMBAH <i>Through the Looking Glass – The Grade I Heritage of Mumbai</i> , Mumbai : Urban Design Research Institute, Jasubhai Media and Super Book House. RAHUL MEHROTRA and SHARADA DWIVEDI <i>Anchoring A City Line – The History Of The Western Subarban Railway And Its</i> <i>Headquarters In Bombay:</i> Eminence Designs Pvt. Ltd.

### I1 Western Railway Headquarters













163

### I1 Western Railway Headquarters





(i)



12 Chhati	ranati Shivaii Vastu Sangraha	laya (Prince of Wales Museum) 164
	rapati Shivaji vastu Sangrana	Common Ref No: 164
		Card No: 222
		Ward (Part): A (Part IV)
1		CS No: 33 (Fort Division)
		Plot Area: 24705.88 sq m.
J.C.		B U Area: -
		Date: 20/12/2004
	the state of	Recorded by: Zankhana Prajapati
Berthall .	and the second s	
2.4		Int: Zankhana Prajapati, Sonal
		Modak
		Ext: Zankhana Prajapati, Sonal
	and the second s	Modak
		Photo Ref: 164_Prince of Wales
		Museum.
		Reviewed in 2013
1.0		Denomination
1.1	Name of Premises	Chhatrapati Shivaji Vastu Sangrahalaya
1.2	Earlier Name	Prince of Wales Museum
1.3	Built in:	Foundation stone laid in 1905, designed in Extension Date: 1938
1.0		1909, constructed in 1914 and opened to
		public in 1922.
2.0		Access
2.0	Main	Mahatma Gandhi Road.
2.1	Subsidiary	
Z.Z		K. Dubhash Marg.
2.0		Qumarahin nattarn
3.0	Dressent	Ownership pattern
3.1	Present	State Government
3.2	Past	The Trustees of the Prince of Wales Museum of India and others.
3.3	Status	Owner/Tenant.
4.0		Use
4.1	Present	Museum
4.2	Past	During World War I, the building served as military hospital and since
		1922 is museum.
4.3	Usage	Daily.
5.0		Significance & Value Classification
5.1	Townscape (manmade)	The building is situated on the crescent shaped site in front of S.P.
		Mukherjee Chowk and the National Gallery of Modern Art with
		Mahatma Gandhi road forming the main access road.
		The main access to the building is from Mahatma Gandhi Road. The
		imposing presence of the building forms an important landmark of the
		city in the Indo-Saracenic style.
5.2	Architectural Description	Planning
		The building is situated on crescent site with the rectangular building
		at the rear with longer façade along the Mahatma Gandhi Road.
		The building is ground plus two storied high with the central dome
		giving an additional floor height to the volume of the building. The
		building is made up of Kurla and basalt stone.
		building is made up of Kurla and basalt stone. Entrance of the building is from the center of the main building through


2 Chhatrapati Shivaji Vastu Sangrahalaya (Prince of Wales Museum)       164         a porch, which leads to an entrance lobby which houses reception, museum shop and audio guidance area, adjacent to which is huge central atrium below the dome with projecting galeries on first floor and second floor level. On the left and right of the central atrium are the verandahs which house sculptural exhibits, flanked by Coomarswamy Hall and Indian Sculpture exhibition area respectively. From atrium main staircase leads to the first floor, behind which is the Indian Pre and Proto History section: toilets are at the left of the main staircase. At the end of right side verandah one enters the annex building, which has the enuseum library and Natural history section. On the first floor towards the left is the Miniature painting, decorative at, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor.         Features       II is a symmetrical building, with ends and center being emphasized by projecting out.         The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets of foral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corrers of the end bay. Ground floor has Mughal arch opening, with <i>jalis</i> the rest as projecting balcory supported on columns around the balcory's Mughal arch opening. The regular bays are separated by columns. On the ground floor has a composition of three Mughal arch vents are present with a corrice band to mark the floor i
central atrium below the dome with projecting galleries on first floor and second floor level. On the left and right of the central atrium are the verandahs which house sculptural exhibits, flanked by Coomarswamy Hall and Indian Sculpture exhibition area respectively. From atrium main staircase leads to the first floor, behind which is the Indian Pre and Proto History section; toilets are at the left of the main staircase. At the end of right side verandah one enters the annex building, which has the museum library and Natural history section. On the first floor towards the left is the Miniature painting, decorative art, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays: each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top: the parapet along the four minarets bear floral motif and openings with <i>jalls</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings. While he first floor has a projecting balcony supported on decoraris (dupan arch pering. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jall</i> ventilators below and <i>chaijas</i> above su
and second floor level. On the left and right of the central atrium are the verandahs which house sculptural exhibits, flanked by Coomarswamy Hall and Indian Sculpture exhibition area respectively. From atrium main staircase leads to the first floor, behind which is the Indian Pre and Proto History section; toilets are at the left of the main staircase. At the end of right side verandah one enters the annex building, which has the museum library and Natural history section. On the first floor towards the left is the Miniature painting, decorative art, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top: the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch opening. The regular bays are separated by colums. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chaijas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor fort which has trefoil Mughal arch high parapet with columns ending in noino shaped dome arising from lotus petals pillasters.
the verandahs which house sculptural exhibits, flanked by Coomarswamy Hall and Indian Sculpture exhibition area respectively. From atrium main staircase leads to the first floor, behind which is the Indian Pre and Proto History section; toilets are at the left of the main staircase. At the end of right side verandah one enters the annex building, which has the museum library and Natural history section. On the first floor towards the left is the Miniature painting, decorative art, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays: each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lolus leaf and having minarets on four corners of these domes at top: the parapet along the four minarets bear floral motif and openings with <i>Jalls</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch opening, while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>Jall</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by colums. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>Jall</i> ventilators below and <i>chaijas</i> above supported on in
Coomarswamy Hall and Indian Sculpture exhibition area respectively. From atrium main staircase leads to the first floor, behind which is the Indian Pre and Proto History section; toilets are at the left of the main staircase. At the end of right side verandah one enters the annex building, which has the museum library and Natural history section. On the first floor towards the left is the Miniature painting, decorative art, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jallis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets being. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jall</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which pari terrace is formed in second floor front which has trefoil
Coomarswamy Hall and Indian Sculpture exhibition area respectively. From atrium main staircase leads to the first floor, behind which is the Indian Pre and Proto History section; toilets are at the left of the main staircase. At the end of right side verandah one enters the annex building, which has the museum library and Natural history section. On the first floor towards the left is the Miniature painting, decorative art, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Mariime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays: each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jallis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets being. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jall</i> ventilators below and chajfas above supported on windows with jall ventilators below and chajfas above supported on windows with jall ventilators below and chajfas above supported on win
From atrium main staircase leads to the first floor, behind which is the Indian Pre and Proto History section: toilets are at the left of the main staircase. At the end of right side verandah one enters the annex building, which has the museum library and Natural history section. On the first floor towards the left is the Miniature painting, decorative art, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from totus leaf and having minarets on four corners of these domes at top: the parapet along the four minarets bear floral motif and openings with <i>jailis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jail</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jail</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor floor which has
staircase. At the end of right side verandah one enters the annex building, which has the museum library and Natural history section. On the first floor towards the left is the Miniature painting, decorative art, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch which parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
staircase. At the end of right side verandah one enters the annex building, which has the museum library and Natural history section. On the first floor towards the left is the Miniature painting, decorative art, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch which parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
<ul> <li>building, which has the museum library and Natural history section. On the first floor towards the left is the Minitature painting, decorative art, bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor.</li> <li>Features</li> <li>It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out.</li> <li>The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top: the parapet along the four minarets bear floral motif and openings with <i>jalis</i>. There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch opening.</li> <li>The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with <i>jali</i> ventilators below and to mark the floor differences. First floor has a composition of three Mughal arch vents are present with <i>jali</i> stapet suported on columns around the balocomy supported on intricately carved decorative Gujarat style stone brackets, above which part errace is formed in second floor front which has trefoil Mughal arch vents are present with <i>jali</i> stapet windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part errace is formed in second floor front which has trefoil Mughal arch vents are present with columns ending in onion shaped dome arising from lotus petals</li></ul>
the first floor towards the left is the Miniature painting, decorative art, bronze, and office area, behind starcase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
bronze, and office area, behind staircase is the exhibition area of painting, on right is exhibition gallery for Nepal and Tibet area, over the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays: each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch opening. The regular balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone bracket, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
the annex building there is the Maritime history section and Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
Premchand Roychand gallery. On second floor both left and right wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
wings have collections of European painting, with Far Eastern art behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays: each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top: the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
behind staircase and Arms and Armour exhibit above porch area. There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
There are two part terraces on second floor. <b>Features</b> It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
Features It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
It is a symmetrical building, with ends and center being emphasized by projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
projecting bays. The central bay is huge equivalent to four regular bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
bays; each side of central bay consists of six bays with the end bays projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
projecting out. The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
The end bays are emphasized by having onion shaped dome arising from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
from lotus leaf and having minarets on four corners of these domes at top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
top; the parapet along the four minarets bear floral motif and openings with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
with <i>jalis</i> . There are two small projecting terraces at the two corners of the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
the end bay. Ground floor has Mughal arch openings while the first floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
floor has a projecting balcony supported on decorative Gujarat style stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
stone brackets and having a backdrop of two minarets with <i>jali</i> parapet supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
supported on columns around the balcony's Mughal arch opening. The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
The regular bays are separated by columns. On the ground floor a huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
huge Mughal arch opening is present above which three trefoil Mughal arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
arch vents are present with a cornice band to mark the floor differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
differences. First floor has a composition of three Mughal arch windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
windows with <i>jali</i> ventilators below and <i>chajjas</i> above supported on intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
intricately carved decorative Gujarat style stone brackets, above which part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
part terrace is formed in second floor front which has trefoil Mughal arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
arch high parapet with columns ending in onion shaped dome arising from lotus petals pilasters.
from lotus petals pilasters.
entrance porch at the center which is formed of pendentive dome
topped by <i>amlaka</i> and <i>kalash</i> , supported on Mughal arch openings
and colonnette which is formed at the junction of two arches. Two
intricately carved minarets mark the front of the porch. Central bay is
further divided into three parts where the two flanking ones are
identical and center bay is more ornate. The two side bays are slightly
recessed from the central bay and are half the width of central bay. At
the ground floor one sees small Mughal arch openings within
rectangular buff stone frame; first floor has Rajput <i>jharokha</i> , second
floor has <i>jalis</i> within Mughal arch openings above which Venetian
dentil band is present and above which <i>chajjas</i> is supported on
intricately carved decorative Gujarat style stone brackets. Above this a
part terrace is formed in the third floor front side, which has high

I2 Chhatr	apati Shivaji Vastu Sangrah	nalaya (Prince of Wales Museum) 164
5.3		<ul> <li>parapet with columns ending in onion shaped domes arising from lotus petals pilasters. The center portion at ground floor has a pendentive-domed porch, first floor has a series of three Mughal arch openings and second floor has one huge Mughal arch opening. The entire central bay is recessed at third floor level and has a square base made of a series of Mughal arch openings over which the main central onion shaped dome arises from lotus petal. Surrounding the central dome there are series of minarets.</li> <li>The building uses different buff and blue basalt stone, Curla stone, limestone and gray stone. It has decorative column capitals inside and wooden galleries in central atrium. All the openings are largely Mughal arch openings but few at the rear are segmental arch openings.</li> <li>Style</li> <li>Building represents influences of the Indo Saracenic style.</li> <li>The acquisition in 1915 of the collections of Sir Purshottam Mavji, the magnificent gift in 1921 by Sir Ratan Tata, and in 1933 by Sir Dorab Tata, of their valuable art collections, formed the nucleus of the museum's art section. The transfer of sculptures and coins of the defunct Poona Museum, of the collection of the Bombay Branch of Royal Asiatic society, consisting of valuable sculptures and the Bombay Natural History Society, helped in setting up the archaeological and Natural history sections.</li> <li>Currently it houses elite collection of sculptures from Gupta period, Mirpurkhas, Buddhist images, Aihole, Pauni, Pitalkhora, beside that varied collection from Indus Valley Civilization, best collection of decorative art in jade, wood, ivory, metal and other medium, fascinating panorama of the religious and artistic world of Nepal – Tibet, varied typology of Indian weaponry of which the main attraction is of Allauddin Khilji's <i>Khanda</i> and Akbar's cuirass with shield, has a major section on Far Eastern Art which has an iron snake of rare workmanship made by renowned Armour maker, Muni Yoshi, is today</li> </ul>
5.4	Value Classification	collectors of European oil paintings.         A(arc), A(his), A(cul), B(per), B (des), B (uu),         Recommended         I         D(hia)         F         C(arc)         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I         I
		D(bio), E, F, G(grp), I(sce), J grade
6.0		Topography
6.1	Floors	G + 2
7.0		Construction
7.1	Plinth	High gray stone plinth with buff basalt stone edging for plinth
		protection.
7.2	Walls	External wall is load bearing made of stone, buff and blue basalt stone and Curla stone ashlars masonry. Inside the walls are plastered and painted, some walls were paneled by wooden planks to avoid seepage.
7.3	Floor	In some areas timber flooring is observed, but largely, it is in RCC supported over beams and finished with tiling.
7.4	Stairs	Six staircases are present. Main staircase is made up of two L-shaped with common mid landing,

2 Chhatrapati Shivaji Vastu Sangrahalaya (Prince of Wales Museum) 164			
		secondary staircase is a C-shaped staircase with open well, has an	
		elliptical staircase in annex building and spiral staircase for terrace.	
		Primarily all staircases are made of stone with wooden handrail and baluster.	
		The terrace spiral staircase is decorative in cast iron.	
		On second floor wooden railing has lamppost placed at regular	
		intervals.	
7.5	Openings	All doors, windows and openings are Mughal arched openings but few	
7.5	openings	are semicircular arched and rectangular openings.	
		Many ventilators are present above and below of window and door,	
		which are either done in <i>jali</i> work or glazed frame or mild steel grill.	
		The windows are double, triple and fourth leaf with ventilators above	
		and below the lintel and sill respectively.	
		All windows are glazed panels in wooden frame.	
7.6	Roofing	The roof is a composition of domes, flat terraces, vaults, minarets and	
		chatris. The dome is covered with ceramic mosaic chips, pendentive	
		vaulted arches support the domes and sloping roof above the side	
		wings.	
7.7	Articulation	All the features are in buff basalt stone especially carved stone	
		brackets, jalis, Rajput jharokas, onion shaped or bulbous dome arising	
		from lotus petals seen in all minarets, decorative cornice and corbels,	
		floral motif and decorative column capital.	
7.8	Finishes	External walls are in exposed stone ashlar masonry and many places	
		have alternate buff and blue basalt masonry specifically observed in	
		arches and certain areas in walls.	
		Internal walls are plastered and painted.	
		Flooring is varied from marble pattern flooring, wooden, china mosaic	
		on terrace, kotah and ceramic tiles.	
		Has false ceiling done in the entire exhibition and display area.	
7.9	Interiors (Movable &		
	Immovable)	Old furniture, panels, racks, display board, showcases, benches,	
		artifacts, prehistoric anthropological objects, weaponry, paintings,	
		statuary, bronze gallery, ivory carvings, and all the other exhibits.	
		Immovable	
7 4 0		Wooden columns and balusters, handrail, light fixtures.	
7.10	Compound/ Fence/ Gate	The compound wall comprises of a stone wall over which a stone	
		baluster and railing is present over which cast iron grill work is present.	
		Cast iron decorative entrance gate and side gates.	
7 1 1	Cutilogo/Uphuilt anago/ Out	Has carved stone gateposts.	
7.11	Curtilage/ Unbuilt space/ Out	Rear and side has open spaces.	
	Buildings/ Landscape	Many outbuildings are present like two small sheds used as storage, fountain, pump room, entrance office, ticket counter, substation,	
		guesthouse, residence building, Jehangir art gallery, Max Muller Bhavan, and chawl type houses.	
		The site has a well-planned landscape layout with huge garden with a	
		beautifully sculpted statue of King George V in naval uniform by George Wade fronting the museum. On the pedestal are bas-reliefs of	
		the foundation stone laying ceremony and the reading of the address	
		of welcome by members of the Municipal Corporation, weaponry,	
		statues, fountain and carved stone relief work. Presence of many old	
		trees which forms the main feature of the garden and site.	
		מככז שהוכוד וסודהז נהכי הומוד ובמנערב טו נהב עמו עבוד מווע זונב.	

12 Chhatrap	oati Shivaji Vastu Sangrahalay	a (Prince of Wales Museum) 164
8.0		Services & Utilities
8.1	Lighting	Adequate Natural light through door-window openings supplemented by electric light fixtures.
8.2	Ventilation	Adequate Natural ventilation through door-window openings supplemented by electric fans and air conditioning.
8.3	Electricity	BEST
8.4	Water Supply	MCGM
8.5	Drainage (Plumbing & Sanitation)	MCGM
8.6	Fire Precaution	Presence of fire extinguishers.
8.7	Other (HVAC/BMS/Security Systems)	Window AC units.
9.0		Condition
9.1	Plinth	Good
9.2	Walls	Good
9.3	Floor	Good
9.4	Stairs	Good
9.5	Openings	Good
9.6	Roofing	Good
9.7	Articulation & Finishes	Good
9.8	Services	Good - Regular maintenance is done, overall in good condition.
9.9	Out Buildings	
9.10	Overall Conditions	Good. Maintenance Good level:
10.0		Transformation
	Form	Addition of annex wing.
	Structure	Addition of I-section in ground floor to strengthen the structural system.
	Articulation & Finishes	Painted internal arches and domes.
11.0		DP Remarks/ Perceived Threats
		Plot falls under Social Amenities and Open space in DP
<u> </u>		
12.0		Additional Notes/ References/ Documents available
		Additional Notes: The seed of this museum were sown in 1892 resolution adopted by the government of India for promotion of trade and industries, but in 1894, Lord Harris had referred to this resolution in opening address at Bombay Fine Art Exhibition. The idea remained dormant till 1904; meanwhile a representative committee was set up for the purpose. Its principal recommendation was to set up museum with an educational bias combined with a public reading room and a library. The 'Crescent Site' was recommended as an ideal site for locating the Museum. The idea got impetus in 1905, when the people of Bombay decided to commemorate the visit of the Prince of Wales of England by setting up a Museum. During WWII the museum was threatened the safety of the museum exhibits, and thus the major collection had to be removed out of the museum and away of Bombay. Subsequently in 1946, the task of resetting the galleries was taken up.

12 Chhatrapati Shivaji Vastu Sangrahala	ya (Prince of Wales Museum) 164
	Designed by George Wittet in the Indo-Sarasenic style, the Museum is
	situated in a vast crescent-shaped compound with beautiful gardens.
	Yellow and blue basalt stone quarried in the Bombay region has been
	extensively but sensitively used in the building. The Prince of Wales
	laid the foundation stone in 1905 during his first visit to the city and the
	building was completed in 1914. During World War I the Museum was
	used as a military hospital and was formally opened by Lady Lloyd, the
	Governor's wife, only in 1923. The dome bears a striking resemblance
	to that of the Gol Gumbuz at Bijapur. Elements of traditional
	architecture have been blended extensively and aesthetically in the
	facade, including small bulbous cupolas on the towers, jalis used as
	infills for the Saracenic arches, Rajput style jharokas, brackets of
	Hindu temples and semi open veranda spaces incorporated in
	response to the climate. In short, the building is an assembly of
	elements from diverse sources. In 1936, an extension new wing
	designed by Gregson, Batley & King was added to house an amazing
	collection of exhibits of Natural History.
	The contents of the Museum form a crucial part of the city's cultural heritage. A large portion of the Art collection was a gift of Sir Ratan
	Tata, comprising paintings, Oriental arms, a unique collection of jade,
	china and porcelain, Indian silver and bronzes and other objets d'art.
	Sir Dorab Tata also presented to the Museum a collection of paintings,
	statuary and a collection of Mughal miniatures and several Maratha
	relics. The Museum also houses a fine collection of Rajput miniature
	paintings. A recent addition has been the collection of the legal
	luminary, Karl Khandalawala who was a Trustee of the Museum for
	several years. In the gardens can be seen a variety of Oriental bronze
	sculptures. There is a beautifully sculpted statue of King George V in
	naval uniform by George Wade fronting the museum. On the pedestal
	are bas-reliefs of the foundation stone laying ceremony and the
	reading of the address of welcome by members of the Municipal
	Corporation.
	References:
	INTACH (1990) Preliminary unedited listing of Unprotected
	Monuments, Buildings and Structures listed for Conservation.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) <i>The Cities Within</i> , Bombay : Eminence Designs Pvt. Ltd.
	RAHUL MEHROTRA, GUNTER NEST and SANDHYA SAVANT
	(1994) The Fort Precinct in Bombay – Conserving an Image Centre, 2
	Vols, Bombay.
	FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD <i>Visual</i>
	dictionary of Architecture, Division of International Thomson Publishing
	Inc.
	SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks,
	Bombay : Eminence Designs Pvt. Ltd.
	ABHA NARAIN LAMBAH Through the Looking Glass – The Grade I
	Heritage of Mumbai, Mumbai : Urban Design Research Institute,
	Jasubhai Media and Super Book House.
	SIR BANNISTER FLETCHER A History of Architecture, CBS
	publication and distributors.



12 Chhatrapati Shivaji Vastu Sangrahalaya (Prince of Wales Museum)

















# 12 Chhatrapati Shivaji Vastu Sangrahalaya (Prince of Wales Museum)



















164

13 Maiest	ic Aamdar Nivas (Majestic Ho	tel)		227
io majest	Common Ref No: 227			
1. 1		Card No: 318		1:23 Ber 2.
			I)	E She E
		Ward (Part): A (Part II		CI: PULLE
		CS No: 442 (Colaba c		The second secon
	The thread the	Plot Area: 2906.38sq	m.	The second second
4		B U Area: -		Here I Aller
-		Date: 30/12/04		S A I I TOTAL
		Recorded by: Prachi	Verchant	11.
-		Reviewed by: UDRI		SHAHID BHAGATSINGH ROAD
1		Int: Prachi Merchant,	Sonal Modak	AGATSINGH
1		Ext: Prachi Merchant, Sonal		ROAD
		Modak	Jonal	B. B. · Maria
1	- Andreases		ctic Hotal	Location Plan
2.15		Pholo Rel.: 227_Majestic Hotel		
1.0		Reviewed in 2013		L
1.0		Denomination		
1.1	Name of Premises	Majestic Aamdar		
		Nivas		
1.2	Earlier Name	Majestic Hotel		
1.3	Built in:	1875	Extension	1928 (Rooms added on the top
			Date:	floor)
			•	
2.0		Access		
2.1	Main		agat Singh M	larg and Nathalal Parekh Marg–
2.1		pedestrain	agat Unight M	
2.2	Subsidiary	Shahid Bhagat Singh	Marg and No	thalal Darokh Marg
2.2			iviary and iva	
2.0		Ourorohin rotter		
3.0	Descent	Ownership pattern		
3.1	Present	State Government		
3.2	Past	State Government		
3.3	Status	Owner - Tenant		
4.0		Use		
4.1	Present	MLA Hostel, Commer	cial – Shops,	Offices, Restaurants.
4.2	Past	MLA Hostel, Commer		
4.3	Usage	Daily		
5.0		Significance & value	Classificatio	n
5.0	Townscano (Manmado)			at the S.P.Mukherjee chowk at the
5.1	Townscape (Manmade)			
				arg and Nathlalal Parekh Marg.
				st side and the other shop and
		restaurant entrances a		
		The building form is a response to the corner site context.		
		The building is juxtaposed with other important buildings of different		
			styles and period, like Police Headquarters, Indian Mercantile	
		Mansion, Regal cinema, Prince of Wales museum and Cowasji		
		Jehangir Hall (NGMA)	).	-
5.2	Architectural Description	Planning		
			he 'V' shape f	rom the shape of the site, with its
		two wings aligned to the access roads, enclosing an internal court.		
				e sides; East, West and North side.
				an elaborate extended porch.
				d in the center, opening into an
			יווש מוד וטנמול	a in the center, opening line an

13 Majestic Aamdar Nivas (Majestic Hot	el) 227
13 Majestic Aamdar Nivas (Majestic Hot	atrium space with skylight above, and rear extended wings on either side. The atrium opens into terrace spaces in the front on the north side. The building is one single mass with taller and emphasized north side façade with tall minarets and central façade feature in front and side bays with decorative features. The ground floor houses some famous and old shops, and restaurants. The basement is occupied by storage area for 'Sahakari Bhandar'. The top floors are occupied by common triangular atrium space from the first floor, with extended terraces on each floor to the north side and double loaded corridors in the wings occupying offices, MLA rooms etc. The servants' quarters are added at the rear of the building in the service area. <b>Features</b> Prominent grey stone clad building with white bands defining floor levels and highly ornamented façade features. The North side entrance façade has an extended porch with Islamic arched openings with decorative intrados and <i>jali</i> work in the spandrels, supported on columns with decorative base and capitals. The porch has two octagonal minarets on either side with marginally projecting cornice bands, geometric pattern friezes. The porch has a terrace above with stone balustrade parapet. The other floors are setback overlooking the terrace of porch. The second and third floors have double height Islamic arched openings with triple arches within, <i>jali</i> work and turrets on either side, with terrace above. The topmost floor has its central portion has turrets on either side with fortified balustrade, flanked with two octagonal minarets on either side. The minarets are adorned with projecting corbel bands, geometric pattern friezes with star shaped opening, and chatris as watch towers on top. The side facades have a taller central wing with ground entrance with decorative arched opening with decorative intrados, projecting <i>Jharokhas</i> with brackets, with the bay ending into turrets and balustrade. The recessed lined with a row of pointed arched windows recessed marginally in
	decorative brackets. Lift well walls are adorned with decorative jali
5.3 Intrinsic	-
5.4 Value Classification	A(arc), B(per), B(des), B(uu), C(seh), E, Recommended II A F, I(sce) grade:
6.0	Topography

13 Majest	ic Aamdar Nivas (Majestic Hote	l) 227		
6.1	Floors	G+4 with basement and terrace, Ground floor servants quarter structure.		
7.0		Construction		
<b>7.0</b> 7.1	Plinth	Construction High (due to basement) plinth clad with grey stone and stone plinth protection band.		
7.2	Walls	Load bearing stone external walls and internal brick walls.		
7.3	Floor	Jack-arch construction with cast iron supporting columns.		
7.4	Stairs	Main open well wooden staircase on the east side, with wooden treads, risers and railing. Two lifts, one in the staircase lobby and other in the atrium space. RCC staircase from ground floor level to the basement.		
7.5	Openings	Porch arches and other main entrances have arched openings with decorative intrados. Internal doors have arched openings with paneled shutters with upper part as louvered, with ventilator above. Windows have arched openings with full height double glazed paneled shutters with ventilators. Passage openings are arched with decorative intrados.		
7.6	Roofing	Arch braced roof over the atrium with a skylight. The central portion has sloping Mangalore tile roof. The side wings and front portion has flat RCC terrace slab.		
7.7	Articulation	Bands, arches, minarets, <i>jharokhas</i> , cornice bands, decorative stone brackets, balustrade.		
7.8	Finishes	The walls are externally clad with grey stone and plastered and painted inside. Floors are finished with cement tiles.		
7.9	Interiors (Movable & Immovable)	Movable Wardrobes and dressing tables in rooms, tables, chairs, electric box covers. Immovable		
7.10	Compound/ Fence/ Gate	The building directly abuts the road. No compound wall and fence accept in the south side.		
7.11	Curtilage/ Unbuilt space/ Out Buildings/ Landscape	The west side of the building setback has been occupied by shops and restaurant with asbestos covering. Footpath in front of the east side and the porch is paved. The south side setback has unpaved areas, and has been occupied by garage and servants quarter.		
8.0		Services & Utilities		
8.1	Lighting	Adequate light through skylight, balconies, terraces and openings supplemented by artificial light.		
8.2	Ventilation	Adequate ventilation through balconies, terraces and openings supplemented by artificial ventilation.		
8.3	Electricity	BEST		
8.4	Water Supply	MCGM		
8.5	Drainage (Plumbing & Sanitation)	MCGM (original cast iron pipes observed)		
8.6	Fire Precaution	Extinguishers are installed at every floor level.		
8.7	Other (HVAC/BMS/Security Systems)	Individual tenants have installed window and split AC's. Manual security to the society.		
9.0		Condition		

13 Majest	ic Aamdar Nivas (Majestic H	otel) 227		
9.1	Plinth	Fair		
9.2	Walls	Fair		
9.3	Floor	Fair – Due to its deteriorating state, the floor have been strengthened with steel sections.		
0.4	Chalma	Tanks have been installed on the Terrace level.		
9.4	Stairs	Fair – The main wooden staircase is in a deteriorating condition.		
9.5	Openings	Fair– ACs installed in the openings, alterations in the openings		
9.6	Roofing	Fair – Tanks have been added on the terrace. Extensions have been made towards the east side.		
9.7	Articulation & Finishes	Floor finish has been altered and replaced by ceramic tiles.		
9.8	Services	Fair		
9.9	Out Buildings	Few buildings in the courtyard		
9.10	Overall Conditions	FairMaintenance levelFair		
10.0		Transformation		
10.0	Form			
	Structure	I-sections have been installed to strengthen the floor.		
	Siructure	Extensions to the blocks are made in the front and at the rear side.		
	Articulation & Finishes	Openings have been altered.		
11.0		DP Remarks/ Perceived Threats		
		Plot falls under Residential Zone in DP		
12.0		Additional Notes/ References/ Documents available		
		Additional Notes:		
		-		
		References: INTACH (1990) Preliminary unedited listing of Unprotected Monuments, Buildings and Structures listed for Conservation. FRANCIS D.K.CHING and VAN NOSTRAND REINHOLD Visual dictionary of Architecture, Division of International Thomson Publishing Inc. SHARADA DWIVEDI and RAHUL MEHROTRA (2001) Fort Walks, Bombay : Eminence Designs Pvt. Ltd.		

### 13 Majestic Aamdar Nivas (Majestic Hotel)













# 13 Majestic Aamdar Nivas (Majestic Hotel)















